Palm Beach County Fleet Management Asset Maintenance History

10203143 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: Problem:	1700130 install hitch ex	Meter: at/ underco	1 eat			In Date:	01/05/2017	Closed:	01/24/20)17
- Install Hitch	Ext				Parts Li	st				Qty
- Undercoat Chasis					Rubberi	zed Underc	oat			1.00
- Shop Suppli	es				Receive	r Extension				1.00
					Ball Mou	unt 3/4"				1.00
					Pin W/cl	ip 5/8 For H	litch			2.00
					Shop Su	ıpplies				1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	99.80	Total:	159.80	
Workorder: Problem:	1700806 1061 - Pre De	Meter: livery Insp	1 ection			In Date:	01/26/2017	Closed:	01/26/20)17
- Pre Delivery	Inspection									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1701828 overheating/ o	Meter: coolant lev	-			In Date:	02/21/2017	Closed:	03/09/20)17
- Test Eqpt H	ector Turf -repl	ace coolin	g fan relay wa	arranty	Parts Li	st				Qty
- Shop Suppli	es				Shop Su	ıpplies				1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1706448	Meter:	39			In Date:	06/29/2017	Closed:	07/10/20)17
Problem:	pm service									
- Pm					Parts Li	st				Qty
- Wash and Undercoat					d Oil Filter				1.00	
- Shop Suppli	es				Fuel Filt					1.00
					Napa Qt					3.00
						or Brake Clr	nr .			1.00
					Mobil 42					4.00
					Napagold Air Filter				1.00	
					Rubberized Undercoat					1.00
					\circ					
	Цали	o 6 00		Lobor	Shop Su		100 54	Totalı	460 E4	1.00
	Hour :	s 6.00		Labor:	Shop Su 360.00		100.54	Total:	460.54	1.00
Workorder: Problem:	Hour : 1801813 pm service	Meter:	110	Labor:	-		100.54	Total:	460.54	
	1801813		110	Labor:	-	Parts:				
Problem:	: 1801813 pm service		110	Labor:	360.00 Parts Li Napagol	Parts: In Date: st d Oil Filter)18
Problem: - pm service - repair tailgat - wash equipr	: 1801813 pm service te ment and rubbe	Meter:		Labor:	Parts Li Napagol 15-40 C	Parts: In Date: st Id Oil Filter Dil				Qty 1.00 3.00
Problem: - pm service - repair tailga	: 1801813 pm service te ment and rubbe	Meter:		Labor:	360.00 Parts Li Napagol	Parts: In Date: st Id Oil Filter Dil				018 Qty 1.00
Problem: - pm service - repair tailgat - wash equipr	: 1801813 pm service te ment and rubbe	Meter:		Labor:	Parts Li Napagol 15-40 C Fuel Filt Napagol	Parts: In Date: st Id Oil Filter Dil er Id Air Filter				Qty 1.00 3.00
Problem: - pm service - repair tailgat - wash equipr	: 1801813 pm service te ment and rubbe	Meter:		Labor:	Parts Li Napagol 15-40 C Fuel Filt Napagol Mobil 42	Parts: In Date: st d Oil Filter oil er d Air Filter 44 Fluid				O18 Qty 1.00 3.00 1.00 1.00 4.00
Problem: - pm service - repair tailgat - wash equipr	: 1801813 pm service te ment and rubbe	Meter:			Parts Li Napagol 15-40 C Fuel Filt Napagol	Parts: In Date: st Id Oil Filter Oil er Id Air Filter 24 Fluid upplies		Closed:		O18 Qty 1.00 3.00 1.00 1.00

Palm Beach County Fleet Management Asset Maintenance History

Workorder: 1809709 Meter: 207 Problem: pm service		In Date:	09/20/2018	Closed:	11/05/2018
- pm service		Parts List			Qty
- replace all 4 rotors and pads	Napa Qt 15w40	3.00			
- replace coolant pipes and service system	Napagold Oil Filter	1.00			
- repair parking brake cable. lube and adjust	Napa Fuel Filter	1.00			
- Shop Supplies		Napagold Air Filter	r		1.00
		Mobil 424 Fluid			4.00
		Brake Rotor			4.00
		Front Brake Pad Se	et		1.00
		Brake Shoe, Kit			1.00
		1gal Rtu Antifreeze)		1.00
		Tee, Coolant Fill			1.00
		Coolant Pipes		1.00	
		Shop Supplies			1.00
Hours 13.00 :	Labor:	871.00 Parts:	920.31	Total:	1,791.31
Workorder: 1904782 Meter: 258 Problem: pm service		In Date:	05/01/2019	Closed:	05/13/2019
- Pm Service		Parts List			Qty
- Wash and undercoating		Napa Qt 15w40			3.00
- Repl. parking brake unit		Napagold Oil Filter			1.00
- Repl. brake light switch; repair headlight switch		Napa Fuel Filter			1.00
- Shop Supplies		Napagold Air Filter	r		1.00
		Mobil 424 Fluid			4.00
		Carb-choke Clnr 13	3oz		2.00
		Caliper Mech Park		1.00	
		Brake Light Switch		1.00	
		Rubberized Under		2.00	
		Shop Supplies		1.00	
Hours 8.50	Labor:	569.50 Parts:	287.36	Total:	856.86
Workorder: 2004135 Meter: 258 Problem: Transition Prep Charge		In Date:	04/24/2020	Closed:	04/24/2020
- Transition Prep Charge					
Hours 2.00	Labor:	146.00 Parts:	0.00	Total:	146.00