10151822 2004 GMC SAFARI Mini Van, Cargo

		101	51822 2	004 GMC S	SAFARI	Mini Van, Ca	argo			
Workorder: Problem:	434029 WASH VEHIC	Meter: LE	0			In Date:	01/29/2004	Closed:	01/29/20	004
- Wash Vehic	le									
- Pre-delivery	Inspection									
	ate Keys For N	ew Vehicl	е							
·		s 4.10		Labor:	205.00	Parts:	0.00	Total:	205.00	
Workorder:	434637 VEHICLE TAG	Meter:	16 F			In Date:	02/07/2004	Closed:	02/07/20	004
			_							
- Tag Charge					Parts Li					Qty
					Tag Cha	•				1.00
	Hours :	s 0.00		Labor:	0.00	Parts:	51.85	Total:	51.85	
Workorder: Problem:	452460 P.M.SERVICE	Meter:	1083			In Date:	07/30/2004	Closed:	08/04/20	004
- Pm Service					Parts Li	ist				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					Ph3387	a Oil Filter L	.bf Ph47 Wix	51040		1.00
					10w30 N	Motor Oil				5.00
	Hours	3 2.00		Labor:	100.00	Parts:	9.83	Total:	109.83	
Workorder: Problem:	537457 P.M.SERVICE	Meter:	3549			In Date:	02/25/2005	Closed:	02/28/20	005
- Pm Service					Parts Li	ist				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					Ca7421	Air Filter Lb	of Af7863 Wix	46117		1.00
					Ph3387	a Oil Filter L	.bf Ph47 Wix	51040		1.00
					10w30 N	Motor Oil				5.00
					Nb-18 \	Wiper Blade	s 18" Anco 3	1-18		2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
	Hours :	3 2.00		Labor:	100.00	Parts:	27.68	Total:	127.68	
Workorder: Problem:	537608 NAIL IN R/FRO	Meter: ONT TIRE	3549			In Date:	02/28/2005	Closed:	03/07/20	005
- Tire Repair					Parts Li	ist				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
	Hours	s 1.00		Labor:	50.00	Parts:	2.00	Total:	52.00	
Workorder: Problem:	551050 003 WASH TIO	Meter: CKETS IS	0 SUED OUT	07/22/05		In Date:	07/22/2005	Closed:	07/27/20	005
- 003 Wash T	ickets Issued O	ut 07/22/	05							
222		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
					0.00	. 4.10.	3.00	· otali	5.55	

Workorder: 554139 Meter: 6030 Problem: P.M.SERVICE		In Date:	08/30/2005	Closed:	08/31/2005
- Pm		Parts List			Qt
- Rr Broken R Door Mirror Assy		Shop Supplies			1.00
- Shop Supplies		Ph3387a Oil Filter	Lbf Ph47 Wix s	51040	1.00
		10w30 Motor Oil			5.00
		Nb-18 Wiper Blade	es 18" Anco 3	1-18	2.00
		12476270 Passeng	ger Door Mirroi	r Glass	1.00
Hours 2.50 :	Labor:	125.00 Parts:	63.89	Total:	188.89
Workorder: 636669 Meter: 10364 Problem: P.M.SERVICE		In Date:	03/31/2006	Closed:	04/06/2006
- Pm Service		Parts List			Qt
- Transport & Pickup Vehicle At Dealer.(p/s Leakin	ng)	Shop Supplies			1.00
- Shop Supplies		Ca7421 Air Filter L	bf Af7863 Wix	46117	1.00
		Ph3387a Oil Filter	Lbf Ph47 Wix s	51040	1.00
		3481 Fuel Filter Fr	m G3727 Wix	33481	1.00
		10w30 Motor Oil			5.0
		Nb-18 Wiper Blade	es 18" Anco 3	1-18	2.00
		Used Firex Refurbe	ed Fire Extings	hers	1.00
Hours 3.00 :	Labor:	150.00 Parts:	51.66	Total:	201.66
Workorder: 642861 Meter: 11694		In Data:	07/24/2006	Closed:	00/40/2006
Problem: INSTALL BULKHEAD		In Date:	07/24/2006	Ciosea.	09/12/2006
	ıll Window	Parts List	07/24/2006	Cioseu.	09/12/2006 Qt
Problem: INSTALL BULKHEAD	ıll Window		07/24/2006	Ciosea.	
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta	ıll Window	Parts List		Ciosea.	Qt
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens.	ıll Window	Parts List Shop Supplies		Gioseu.	Qt ;
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens.	ıll Window	Parts List Shop Supplies 1/4x3x20 Alum Flat		Gioseu.	Qt y 1.00 2.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens.	III Window	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen		Gioseu.	Qt y 1.00 2.00 1.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens.	ıll Window	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen	t Bar 6063	Gioseu.	Qty 1.00 2.00 1.00 2.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens.		Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V	t Bar 6063		Qty 1.00 2.00 1.00 2.00 2.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies		Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V	t Bar 6063 W/ Shroud		Qty 1.00 2.00 1.00 2.00 2.00 2.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820		Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts:	t Bar 6063 W/ Shroud 603.38	Total:	Qty 1.00 2.00 1.00 2.00 2.00 2.00 1,078.38
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE.	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List	t Bar 6063 W/ Shroud 603.38	Total:	Qty 1.00 2.00 2.00 2.00 2.00 1,078.38
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE. - Pm Service - Check Ac Sys Performance.not Cold.check Press Add Freon.	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List	V/ Shroud 603.38 10/25/2006	Total:	Qt; 1.00 2.00 2.00 2.00 2.00 1,078.38
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE. - Pm Service - Check Ac Sys Performance.not Cold.check Press Add Freon Check Security Locks On Doors.r&r And Lube	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List Shop Supplies	t Bar 6063 W/ Shroud 603.38 10/25/2006 bf Af7863 Wix	Total: Closed:	Qty 1.00 2.00 2.00 2.00 2.00 1,078.38 10/31/2006
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE. - Pm Service - Check Ac Sys Performance.not Cold.check Press Add Freon. - Check Security Locks On Doors.r&r And Lube Locks.adjusts Catches.	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List Shop Supplies Ca7421 Air Filter Li	t Bar 6063 W/ Shroud 603.38 10/25/2006 bf Af7863 Wix	Total: Closed:	Qt; 1.00 2.00 2.00 2.00 2.00 1,078.38 10/31/2006 Qt; 1.00 1.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE. - Pm Service - Check Ac Sys Performance.not Cold.check Press Add Freon. - Check Security Locks On Doors.r&r And Lube Locks.adjusts Catches Nitrogen Fill All Tires.	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List Shop Supplies Ca7421 Air Filter L Ph3387a Oil Filter	t Bar 6063 W/ Shroud 603.38 10/25/2006 bf Af7863 Wix Lbf Ph47 Wix 8	Total: Closed: 46117 51040	Qty 1.00 2.00 1.00 2.00 2.00 1,078.38 10/31/2006 Qty 1.00 1.00 1.00
Problem: INSTALL BULKHEAD - Fab Plates.install Locks Side & Rear Doors Insta Screens. - Shop Supplies Hours 9.50 : Workorder: 647722 Meter: 12820 Problem: P.M. SERVICE.SEE NOTE. - Pm Service - Check Ac Sys Performance.not Cold.check Press Add Freon. - Check Security Locks On Doors.r&r And Lube Locks.adjusts Catches.	Labor:	Parts List Shop Supplies 1/4x3x20 Alum Flat 88013 Screen 88014 Screen 2000 Lock Assy 800 Lock Bracket V 475.00 Parts: In Date: Parts List Shop Supplies Ca7421 Air Filter L Ph3387a Oil Filter I 10w30 Motor Oil	t Bar 6063 W/ Shroud 603.38 10/25/2006 bf Af7863 Wix Lbf Ph47 Wix 8	Total: Closed: 46117 51040	Qt; 1.00 2.00 2.00 2.00 2.00 1,078.38 10/31/2006 Qt; 1.00 1.00 5.00

Workorder: 739141 Meter: 17547 Problem: P.M SERVICE,SEE NOTE		In Date:	05/29/2007	Closed:	05/31/2007
- Perform Pm Service Complete Also Replace The Fuel F	Filter Pa ı	rts List			Qty
With New.	L17	7026 Cleaner Th	rottle Plate (sn	nrt Blnd	1.00
- Perform Transmission Flush Complete.also Flush Coole	er& Sho	op Supplies			1.00
Torque Converter To Correct Fluid Condition.	Ca	7421 Air Filter L	bf Af7863 Wix	46117	1.00
 - Ac Evaporator Failed, leak Test-rr Ac Housing & Clean Same, repl The Ac Evaporator & Orificing Tube Filter 	Ph:	3387a Oil Filter	Lbf Ph47 Wix 5	51040	1.00
W/new,vacuum & Rechg Sys To Specs	348	81 Fuel Filter Fr	m G3727 Wix	33481	1.00
- Eng Idles Rough,ck Over & Found Corroded Distripbuto		n/atf Trans Fluid	Synthetic		12.00
Cap & Rotor.repl Distribulator Cap & Rotor,clean And Gap	o All 10v	w30 Motor Oil			5.00
Spark Plugs. Throttle Plote Sticking & Cummed Up perform Throttle	E8	A/c Oil R134a A	/c Oil (tsi)		1.00
- Throttle Plate Sticking & Gummed Up.perform Throttle Body Service Complete & Relearn All Eng Controls To	R1:	34a Refrigerant			3.00
Correct Problem.rechk - Ok.		-18 Wiper Blade	es 18" Anco 3°	1-18	2.00
- High Speed Balance All 4 Tires & Index The Right Rear	_	65 Ignition Roto			1.00
Correct Vibration In Body Over 45 Mph.	D3:	28a Dist Cap (ad	` '		1.00
- Perform Wheel Alignment Complete To Correct Left Pul	llina	-62111 Evaporat	*		1.00
Condition & Excessive Front Out Side Tire Wear.		-5754 Orifice Tul			1.00
- Shop Supplies Hours 17.25 La	bor: 948	8.75 Parts:	407.58	Total:	1,356.33
Workorder: 832299 Meter: 21603 Problem: P.M SERVICE		In Date:	01/04/2008	Closed:	01/14/2008
- Pm Service	Pai	rts List			Qty
- Check Battery And Charging Sys $\ensuremath{R}\xspace/\ensuremath{r}$ Defective Battery.	Sho	op Supplies			1.00
					1.00
- Mount,balance And Nitrofill 4 Tires.	Ca	7421 Air Filter L	bf Af7863 Wix	46117	1.00
- Inspect Head Lights,removed Left Head Light Fastening					
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. 	g Ph	7421 Air Filter L	Lbf Ph47 Wix 5	51040	1.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	g Ph: 100	.7421 Air Filter L 3387a Oil Filter	Lbf Ph47 Wix 5	51040	1.00 1.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	9 Ph: 100 100	.7421 Air Filter L 3387a Oil Filter l 020 Injector Clea	Lbf Ph47 Wix 5 aner Don't Reo	51040 rder	1.00 1.00 1.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	g Ph: 100 100 Nb	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3	51040 rder 1-18	1.00 1.00 1.00 5.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	g Phi 100 10v Nb- Use	7421 Air Filter L 3387a Oil Filter l 020 Injector Clea w30 Motor Oil -18 Wiper Blade	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ^o ed Fire Extings	51040 rder 1-18	1.00 1.00 1.00 5.00 2.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	9 Ph: 100 10v Nb- Use Gro	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ^o ed Fire Extings	51040 rder 1-18	1.00 1.00 1.00 5.00 2.00 1.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. 	9 Ph: 100 100 Nb: Use Gro Tire 687	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3' ed Fire Extings acd 78ps)	51040 rder 1-18 hers	1.00 1.00 1.00 5.00 2.00 1.00 4.00
 Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring. Complete Front End Alignment.test Drive. Shop Supplies 	9 Ph: 100 100 Nb: Use Gro Tire 687	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3' ed Fire Extings acd 78ps)	51040 rder 1-18 hers nor SI (don't	1.00 1.00 1.00 5.00 2.00 1.00 4.00
- Mount,balance And Nitrofill 4 Tires Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Workorder: 842920 Meter: 27120 Problem: P.M SERVICE	9 Ph: 100 10v Nb- Use Gro Tire 687 Re	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3° ed Fire Extings acd 78ps)	51040 rder 1-18 hers nor SI (don't	1.00 1.00 1.00 5.00 2.00 1.00 4.00
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 La : Workorder: 842920 Meter: 27120 Problem: P.M SERVICE	9 Ph: 100 10v Nb- Use Gro Tire 687 Re- bor: 525	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts:	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3° ed Fire Extings acd 78ps) 0r16 Silent Arn 716.88	51040 rder 1-18 hers nor SI (don't Total:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai: Workorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service	9 Phi 100 100 Nb- Use Gro Tire 687 Re- bor: 525	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts:	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3° ed Fire Extings acd 78ps) 0r16 Silent Arn 716.88	51040 rder 1-18 hers nor SI (don't Total:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 4.00 08/21/2008
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Workorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service - Rotate & High Speed Balance 4 Tires. Fill W/nitrogen.	Phi 100 100 Nb- Use Gro Tire 687 Re- bor: 525 Pai She	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies 3387a Oil Filter I	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ed Fire Extings acd 78ps) 0r16 Silent Arn 716.88 08/15/2008	51040 rder 1-18 hers nor SI (don't Total: Closed:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 1,241.88
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Norkorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service - Rotate & High Speed Balance 4 Tires. Fill W/nitrogen.	Phi 100 100 Nb- Use Gro Tire 687 Re- bor: 525 Pai She	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ed Fire Extings acd 78ps) 0r16 Silent Arn 716.88 08/15/2008	51040 rder 1-18 hers nor SI (don't Total: Closed:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 4.00 08/21/2008
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Norkorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service - Rotate & High Speed Balance 4 Tires. Fill W/nitrogen.	Phi 100 100 Nb- Use Gro Tire 687 Re- bor: 525 Pai Sho Phi 348	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies 3387a Oil Filter I	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ded Fire Extings acd 78ps) Or16 Silent Arn 716.88 O8/15/2008 Lbf Ph47 Wix 5 m G3727 Wix	51040 rder 1-18 hers nor SI (don't Total: Closed:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 4.00 1,241.88 08/21/2008 Qty 1.00 1.00
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Workorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service - Rotate & High Speed Balance 4 Tires. Fill W/nitrogen.	Phi 100 100 Nb- Use Gro Tire 687 Red bor: 525 Pai Sho Phi 348	7421 Air Filter L 3387a Oil Filter L 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies 3387a Oil Filter Fr	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ded Fire Extings acd 78ps) Or16 Silent Arn 716.88 O8/15/2008 Lbf Ph47 Wix 5 m G3727 Wix	51040 rder 1-18 hers nor SI (don't Total: Closed:	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 1,241.88 08/21/2008 Qty 1.00 1.00 1.00
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Workorder: 842920 Meter: 27120 Problem: P.M SERVICE - Pm Service - Rotate & High Speed Balance 4 Tires. Fill W/nitrogen.	Ph: 100 100 Nb: Use Gro Tire 687 Rec bor: 525 Pai Sho Ph: 348 61a 100	7421 Air Filter L 3387a Oil Filter I 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies 3387a Oil Filter I a P/steering Flui	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ded Fire Extings acd 78ps) Or16 Silent Arn 716.88 O8/15/2008 Lbf Ph47 Wix 5 m G3727 Wix d	51040 rder 1-18 hers nor SI (don't Total: Closed: 51040 33481	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 1,241.88 08/21/2008 Qty 1.00 1.00 1.00 1.00
- Inspect Head Lights,removed Left Head Light Fastening Ring. Repaired And Reinstalled Ring Complete Front End Alignment.test Drive Shop Supplies Hours 8.75 Lai : Workorder: 842920 Meter: 27120	Phi 100 100 Nb- Use Gro Tire 687 Red bor: 525 Pai Sho Phi 348 61a 100 Nb-	7421 Air Filter L 3387a Oil Filter L 020 Injector Clea w30 Motor Oil -18 Wiper Blade ed Firex Refurbe oup 78 Battery (a e Disposal Fee 7205170 215/70 ord 5.00 Parts: In Date: rts List op Supplies 3387a Oil Filter Fr a P/steering Flui w30 Motor Oil	Lbf Ph47 Wix 5 aner Don't Reo es 18" Anco 3 ed Fire Extings acd 78ps) 0r16 Silent Arn 716.88 08/15/2008 Lbf Ph47 Wix 5 m G3727 Wix d es 18" Anco 3 ed Fire Extings acd 78ps)	51040 rder 1-18 hers nor SI (don't Total: Closed: 51040 33481	1.00 1.00 1.00 5.00 2.00 1.00 4.00 4.00 4.00 1,241.88 08/21/2008 Qty 1.00 1.00 1.00 1.00 5.00

Workorder: 846054 Meter: 0 In Date: 10/22/2008 Closed: 10/22/2008 Problem: SISTERS TOWING & TRANSPORTATON TOW FROM SUMMIT LIB - Sisters Towing & Transportation Tow From Summit Library -Tow To Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 846059 28002 In Date: Meter: 10/22/2008 Closed: 10/24/2008 Problem: A/C FAN KEEPS RUNNING - Inspect & Test Blower Motor Circuit. Replace Blower **Parts List** Qty Resistor & Retest. Shop Supplies 1.00 - Charge Battery & Test.test Starting & Charging Systems. Blower Resistor 1.00 - Shop Supplies Labor: 150.00 Parts: 42.08 Total: 192.08 Hours 2.50 936297 Workorder: Meter: 30618 In Date: 04/09/2009 Closed: 04/16/2009 Problem: P.M. SERVICE. - Pm Service **Parts List** Qty - Replace Both Rear Axle Seals. Leaking. Service Rear 82194 Gray Silicone (permatex) 1.00 Differ- Ential. **Shop Supplies** 1.00 - Rotate & Hi Speed Balance 4 Tires.fill W/nitrogen. Rear Wheel Seal 2.00 - Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 09997 Brake Clean 1.00 12345841 Gear Oil Synthetic 75w-90 2.00 10w30 Motor Oil 5.00 Used Firex Refurbed Fire Extingshers 1.00 Hours 6.35 Labor: 381.00 Parts: 100.91 Total: 481.91 Workorder: 1000236 Meter: 33840 In Date: 01/06/2010 **Closed:** 01/14/2010 Problem: P.M service. - P.m service. **Parts List** Qty - Rotate & balance all four tires. **Shop Supplies** 1.00 - Shop Supplies 22514722 O-ring Seal Fuel Filter (acd 217-452) 2.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 Ca7421 Air Filter Lbf Af7863 Wix 46117 1.00 3481 Fuel Filter Frm G3727 Wix 33481 1.00 10w30 Motor Oil 5.00

Labor: 225.00

Hours 3.75

Nb-18 Wiper Blades 18" Anco 31-18

Parts: 43.65

2.00

Total: 268.65

Workorder: 1007254 Meter: 35701 Problem: P.M. Service.A/C inop.	In Date: 07/09/2010 Closed:	07/21/2010
- Perform pm service.	Parts List	Qty
- Pressure test and inspect cooling system.reverse flush and	Shop Supplies	1.00
renew coolant.	Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
- Rotate and balance all four tires.	10w30 Motor Oil	5.00
- Diagnose ac concern.leak check then vacume and	R134a Refrigerant	2.00
recharge system to specs with virgin freon and ac performance test.	Used Firex Refurbed Fire Extingshers	1.00
- Shop Supplies	Nb-18 Wiper Blades 18" Anco 31-18	2.00
onop ouppings	Prf116 Coolant Flush	1.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 7.25 Labor:	435.00 Parts: 85.13 Total:	520.13
Workorder: 1101874 Meter: 39206 Problem: Pm service.	In Date: 02/16/2011 Closed:	02/25/2011
Desferon and the control of the cont	David L'at	01
- Perform pm service.	Parts List	Qty
- Computer diagnose for misfire.test and replace failed	Shop Supplies	1.00
- Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00 1.00
- Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test.	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481	1.00 1.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean	1.00 1.00 1.00 1.00
- Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test.	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper	1.00 1.00 1.00 1.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper	1.00 1.00 1.00 1.00 1.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads	1.00 1.00 1.00 1.00 1.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. Rotate and balance all four tires. Fabricate and repair vacume canister hose to correct ac blend door opperation 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads 1401 Brake Fluid Brake Fluid	1.00 1.00 1.00 1.00 1.00 1.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. Rotate and balance all four tires. Fabricate and repair vacume canister hose to correct ac 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads 1401 Brake Fluid Brake Fluid 10w30 Motor Oil	1.00 1.00 1.00 1.00 1.00 1.00 1.00 5.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. Rotate and balance all four tires. Fabricate and repair vacume canister hose to correct ac blend door opperation 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads 1401 Brake Fluid Brake Fluid 10w30 Motor Oil D328a Dist Cap (acd)	1.00 1.00 1.00 1.00 1.00 1.00 1.00 5.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. Rotate and balance all four tires. Fabricate and repair vacume canister hose to correct ac blend door opperation 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads 1401 Brake Fluid Brake Fluid 10w30 Motor Oil D328a Dist Cap (acd) D465 Ignition Rotor (acd)	1.00 1.00 1.00 1.00 1.00 1.00 1.00 5.00 1.00
 Computer diagnose for misfire.test and replace failed distributor cap,rotor and ignition wires with new.perform major tune up and replace six spark plugs with new.clear codes and road test. Install new rear brake pads and resurface brake rotors.replace both failed rear brake calipers with new.perform brake fluid flush and bleed hydralic system. Rotate and balance all four tires. Fabricate and repair vacume canister hose to correct ac blend door opperation 	Shop Supplies Ph3387a Oil Filter Lbf Ph47 Wix 51040 3481 Fuel Filter Frm G3727 Wix 33481 09997 Brake Clean Rear Caliper Rear Caliper Rear Pads 1401 Brake Fluid Brake Fluid 10w30 Motor Oil D328a Dist Cap (acd)	1.00 1.00 1.00 1.00 1.00 1.00 1.00 5.00 1.00

Workorder: 1109138 Meter: 41402 Problem: P.M. Service.	In Date: 08/29/2011 Closed: 09/07/2011
- Perform pm service.	Parts List Qty
- Inspect and service transmission.replace filter and gasket	Shop Supplies 1.00
with new.flush and renew transmission fluid.	Serp Belt 1.00
- Inspect and replace failed serpentine belt with new.	Ft1217 Trans Filter Atp B-165 Wix Don't Use 1.00
- Fabricate and replace failed fire extinguisher bracket with new and secure.	Ca7421 Air Filter Lbf Af7863 Wix 46117 1.00
- Rotate and balance all four tires.	3481 Fuel Filter Frm G3727 Wix 33481 1.00
	22514722 O-ring Seal Fuel Filter (acd 217-452) 2.00
- Shop Supplies	Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00
	Syn/atf Trans Fluid Synthetic 12.00
	10w30 Motor Oil 5.00
	Custom5lb Bracket Firex Stock #340060300 1.00
	Used Firex Refurbed Fire Extingshers 1.00
	Nb-18 Wiper Blades 18" Anco 31-18 2.00
Hours 7.75 Labor :	: 465.00 Parts: 179.32 Total: 644.32
Workorder: 1203406 Meter: 45291	In Date: 04/10/2012 Closed: 04/30/2012
Problem: P.M. service and towed in for no start.	Jule : 0 1/10/2012
	Parts List Qty
Problem: P.M. service and towed in for no start.	
Problem: P.M. service and towed in for no start.- P.m. Service.	Parts List Qty
Problem: P.M. service and towed in for no start.- P.m. Service.- Test battery and charging system.replace bad battery.	Parts List Qty Shop Supplies 1.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires.	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00
 Problem: P.M. service and towed in for no start. P.m. Service. Test battery and charging system.replace bad battery. Replace and balance four tires. Complete wheel alignment. 	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment.	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Labor: Workorder: 1203435 Meter: 44962	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Labor: Workorder: 1203435 Meter: 44962 Problem: Transport for repair - Tow From: 3650 Summit Blvd	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Eabor Workorder: 1203435 Meter: 44962 Problem: Transport for repair - Tow From: 3650 Summit Blvd	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62 In Date: 04/11/2012 Closed: 04/11/2012
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Eabor Workorder: 1203435 Meter: 44962 Problem: Transport for repair - Tow From: 3650 Summit Blvd Hours 0.00 Eabor Workorder: 1208051 Meter: 47383 Problem: Left outside mirror glass fell off.	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62 In Date: 04/11/2012 Closed: 04/11/2012 : 0.00 Parts: 0.00 Total: 0.00
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Eabor Workorder: 1203435 Meter: 44962 Problem: Transport for repair - Tow From: 3650 Summit Blvd Hours 0.00 Eabor Workorder: 1208051 Meter: 47383 Problem: Left outside mirror glass fell off. - Replace glass in left side mirror.	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62 In Date: 04/11/2012 Closed: 04/11/2012 1000 Parts: 0.00 Total: 0.00 In Date: 08/24/2012 Closed: 08/29/2012 Parts List Qty
Problem: P.M. service and towed in for no start. - P.m. Service. - Test battery and charging system.replace bad battery. - Replace and balance four tires. - Complete wheel alignment. - Shop Supplies Hours 8.25 Eabor Workorder: 1203435 Meter: 44962 Problem: Transport for repair - Tow From: 3650 Summit Blvd Hours 0.00 Eabor Workorder: 1208051 Meter: 47383 Problem: Left outside mirror glass fell off.	Parts List Qty Shop Supplies 1.00 Ph3387a Oil Filter Lbf Ph47 Wix 51040 1.00 10w30 Motor Oil 5.00 Group 78 Battery (acd 78ps) 1.00 P215/70r16 Wrangler Sr-a 4.00 Tire Disposal Fee 4.00 495.00 Parts: 697.62 Total: 1,192.62 In Date: 04/11/2012 Closed: 04/11/2012 1000 Parts: 0.00 Total: 0.00 In Date: 08/24/2012 Closed: 08/29/2012 Parts List Qty

Parts List 10w30 Motor Oil Oil Filter G3727 Fuel Filter L 31-18 Wiper Blades Used Firex Refurbe Engine Seal 12oz Mkd785 Brake Pade 2232 Brake Fluid Q Shop Supplies 435.00 Parts:	s 18 d F s		Qty 5.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00
Oil Filter G3727 Fuel Filter L 31-18 Wiper Blades Used Firex Refurbe Engine Seal 12oz Mkd785 Brake Pads 2232 Brake Fluid Q Shop Supplies	s 18 d F s		5.00 1.00 1.00 2.00 1.00 1.00 1.00
G3727 Fuel Filter L 31-18 Wiper Blades Used Firex Refurbe Engine Seal 12oz Mkd785 Brake Pads 2232 Brake Fluid Q Shop Supplies	s 18 d F s		1.00 2.00 1.00 1.00 1.00
31-18 Wiper Blades Used Firex Refurbe Engine Seal 12oz Mkd785 Brake Pads 2232 Brake Fluid Q Shop Supplies	s 18 d F s		2.00 1.00 1.00 1.00 1.00
Used Firex Refurbe Engine Seal 12oz Mkd785 Brake Pada 2232 Brake Fluid Q Shop Supplies	d F s		1.00 1.00 1.00 1.00
Engine Seal 12oz Mkd785 Brake Pads 2232 Brake Fluid Q Shop Supplies	S		1.00 1.00 1.00
Mkd785 Brake Pade 2232 Brake Fluid Q Shop Supplies			1.00 1.00
2232 Brake Fluid Q Shop Supplies			1.00
Shop Supplies	uar		
			1 00
435.00 Parts:			1.00
	130.09	Total:	565.09
In Date:	06/21/2013	Closed:	07/10/2013
n.			
Parts List			Qty
10w30 Motor Oil			5.00
Napagold Oil Filter			1.00
Wiper Blade		2.00	
A C Compressor		1.00	
Rapid Seal Kit			1.00
R134a Lv Shop 1			3.00
mirror			1.00
Orifice Tube			1.00
E8 A-c Oil R134a A	-C		1.00
Shop Supplies			1.00
555.00 Parts:	459.53	Total:	1,014.53
In Date:	01/17/2014	Closed:	02/10/2014
Parts List			Qty
10w30 Motor Oil			5.00
		1.00	
. •	r		1.00
. •			1.00
. •			2.00
Washer Fl			1.00
	ished		1.00
			1.00
	59.54	Total:	284.54
	Parts List 10w30 Motor Oil Napagold Oil Filter Wiper Blade A C Compressor Rapid Seal Kit R134a Lv Shop 1 mirror Orifice Tube E8 A-c Oil R134a A Shop Supplies 555.00 Parts: In Date: Parts List 10w30 Motor Oil Napagold Oil Filter Napagold Fuel Filte Napagold Fuel Filte Napagold Air Filter Wiper Blade Washer Fl Used Fire X Refurb Shop Supplies	Parts List 10w30 Motor Oil Napagold Oil Filter Wiper Blade A C Compressor Rapid Seal Kit R134a Lv Shop 1 mirror Orifice Tube E8 A-c Oil R134a A-c Shop Supplies 555.00 Parts: 459.53 In Date: 01/17/2014 Parts List 10w30 Motor Oil Napagold Oil Filter Napagold Fuel Filter Napagold Filter Napagold Air Filter Wiper Blade Washer Fl Used Fire X Refurbished Shop Supplies	Parts List 10w30 Motor Oil Napagold Oil Filter Wiper Blade A C Compressor Rapid Seal Kit R134a Lv Shop 1 mirror Orifice Tube E8 A-c Oil R134a A-c Shop Supplies 555.00 Parts: 459.53 Total: In Date: 01/17/2014 Closed: Parts List 10w30 Motor Oil Napagold Oil Filter Napagold Fuel Filter Napagold Air Filter Wiper Blade Washer Fl Used Fire X Refurbished Shop Supplies

Problem:	1410246 p.m. SERVICE	Meter:	61290		ln	Date:	10/10/2014	Closed:	10/27/20)14
- Pm service.					Parts List					Qty
- Rotate and b	palance all four	tires.			10w30 Moto	or Oil				5.00
- Shop Suppli		00.			Napagold C					1.00
Chiop Cuppii					Wiper Blade					2.00
					Washer Flu		entr			1.00
					Shop Suppl		ond			1.00
	Hours	3.75		Labor:	225.00		28.85	Total:	253.85	1.00
Workorder: Problem:	1503906 Pm service.	Meter:	65170		In	Date:	04/15/2015	Closed:	04/29/20)15
- P.m. Service	e.				Parts List					Qty
- Test battery	and charging sy	ystem.rep	lace bad batte	ry.	Sensa-trac	Lt Truck	S			2.00
-	h ledaking front			•	10w30 Mot	or Oil				5.00
•	palance all four	_			Napagold C					1.00
- Shop Suppli	es				Wiper Blade					2.00
					Washer Flu		entr			1.00
					Napagold F	uel Filte	r			1.00
					Mac Wite L					1.00
					Group 78 B					1.00
					Shop Supp	•				1.00
	Hours	6.35		Labor:	381.00		227.62	Total:	608.62	
Workorder:	1511594	Meter:				D-1-	11/12/2015	011	11/23/20	115
Problem:		wicter.	69298		In	Date:	11/12/2013	Closed:	11/23/20	715
	Pm service.	weter.	69298			Date:	11/12/2013	Closed:	11/23/20	
- Pm service.	Pm service.		69298		Parts List		11/12/2013	Closea:	11/23/20	Qty
- Pm service Replace fad	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Moto	or Oil	11/12/2013	Closed:	11/23/20	Qty 5.00
Pm service.Replace fadeRotate and b	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Moto Napagold C	or Oil Dil Filter	11/12/2013	Closed:	11/23/20	Qty 5.00
- Pm service Replace fad	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Moto Napagold C Wiper Blade	or Oil Dil Filter e		Closed:	11/23/20	Qty 5.00 1.00 2.00
Pm service.Replace fadeRotate and b	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Moto Napagold C Wiper Blade Washer Flu	or Oil Dil Filter e		Closed:	11/23/20	Qty 5.00 1.00 2.00 1.00
Pm service.Replace fadeRotate and b	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug	or Oil Dil Filter e iid Conce	entr	Closed:	11/23/20	Qty 5.00 1.00 2.00 1.00
Pm service.Replace fadeRotate and b	Pm service. ed front asset n	umbers.	69298		Parts List 10w30 Moto Napagold C Wiper Blade Washer Flu Drain Plug Napagold A	or Oil Dil Filter e uid Conco	entr	Closed:	11/23/20	Qty 5.00 1.00 2.00 1.00 1.00
Pm service.Replace fadeRotate and b	Pm service. ed front asset n palance all four es	umbers.	69298	Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug	or Oil Dil Filter e aid Conco Air Filter lies	entr		294.88	Qty 5.00 1.00 2.00 1.00 1.00
- Pm service Replace fade - Rotate and the shop Suppli	Pm service. ed front asset no palance all four es Hours : 1605511	umbers. wheels.	73866	Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppl 255.00	or Oil Dil Filter e aid Conco Air Filter lies	entr			Qty 5.00 1.00 2.00 1.00 1.00 1.00
- Pm service Replace fade - Rotate and be - Shop Suppli	Pm service. ed front asset n calance all four es Hours : 1605511 P.M. Service.	umbers. wheels.		Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Supp 255.00	or Oil Dil Filter e uid Conco Air Filter lies Parts:	entr 39.88	Total:	294.88	Qty 5.00 1.00 2.00 1.00 1.00 1.00
- Pm service Replace fade - Rotate and b - Shop Suppli Workorder: Problem: - P.m. Service	Pm service. ed front asset n calance all four es Hours : 1605511 P.M. Service.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppi 255.00 In	or Oil Dil Filter e uid Conce hir Filter lies Parts: Date:	entr 39.88	Total:	294.88	Qty 5.00 1.00 2.00 1.00 1.00 1.00 016
- Pm service Replace fade - Rotate and be - Shop Supplie Workorder: Problem: - P.m. Service - Rotate and be	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Supp 255.00 In Parts List 10w30 Mote	or Oil Dil Filter e uid Conce hir Filter lies Parts: Date:	entr 39.88	Total:	294.88	Qty 5.00 1.00 1.00 1.00 1.00 1.00 016
- Pm service Replace fade - Rotate and b - Shop Suppli Workorder: Problem: - P.m. Service	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Moto Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppi 255.00 In Parts List 10w30 Moto Napagold C	or Oil Dil Filter e hid Conco hir Filter lies Parts: Date: or Oil Dil Filter	entr 39.88	Total:	294.88	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- Pm service Replace fade - Rotate and be - Shop Supplie Workorder: Problem: - P.m. Service - Rotate and be	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppl 255.00 In Parts List 10w30 Mote Napagold C 18" wiper b	or Oil Dil Filter e uid Conce Air Filter lies Parts: Date: or Oil Dil Filter blades	entr 39.88 05/27/2016	Total:	294.88	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- Pm service Replace fade - Rotate and be - Shop Supplie Workorder: Problem: - P.m. Service - Rotate and be	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Moto Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppi 255.00 In Parts List 10w30 Moto Napagold C 18" wiper b Napagold F	or Oil Dil Filter e hid Conco hir Filter lies Parts: Date: or Oil Dil Filter blades Fuel Filte	entr 39.88 05/27/2016	Total:	294.88	Qty 5.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1
- Pm service Replace fade - Rotate and be - Shop Supplie Workorder: Problem: - P.m. Service - Rotate and be	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Mote Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppl 255.00 In Parts List 10w30 Mote Napagold C 18" wiper b	or Oil Dil Filter e hid Conco hir Filter lies Parts: Date: or Oil Dil Filter blades Fuel Filte	entr 39.88 05/27/2016	Total:	294.88	Qty 5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
- Pm service Replace fade - Rotate and be - Shop Supplie Workorder: Problem: - P.m. Service - Rotate and be	Pm service. ed front asset no palance all four es Hours: 1605511 P.M. Service. es. palance all tires.	umbers. wheels. s 4.25 Meter:		Labor:	Parts List 10w30 Moto Napagold C Wiper Blade Washer Flu Drain Plug Napagold A Shop Suppi 255.00 In Parts List 10w30 Moto Napagold C 18" wiper b Napagold F	or Oil Dil Filter e lid Conce Air Filter lies Parts: Date: or Oil Dil Filter blades Fuel Filte (Refurbi	entr 39.88 05/27/2016	Total:	294.88	Qty 5.00 1.00 2.00 1.00 1.00 1.00

Workorder: 1607416 Meter: 75049 In Date: 07/20/2016 Closed: 08/18/2016 **Problem:** A/C only blows out defrost and steering/suspension feels loose/play. - A/c performance test.diagnose and repair broken vacuum **Parts List** Qty lines. 1.00 **Shop Supplies** - Inspect front end and steering components.test drive vehicle for loose steering unable to duplicate complain. - Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 92.00 Workorder: 1700521 Closed: 01/31/2017 Meter: 77918 In Date: 01/18/2017 Problem: P.M. service. - P.m. Service. **Parts List** Qty - Replace and balance four new tires. Napagold Oil Filter 1.00 - Complete wheel alignment.test drive. Napa Quart 5w30 5.00 - Replace broken transmission shifter cable.adjust. 2.00 18" wiper blades - Inspect and service rear differential. Washer Fluid Concentr 1.00 - Shop Supplies 215/70r16 Wrangler Sra Tire 4.00 1qt Syngear Oil 75-90 3.00 shifter cable 1.00 **Shop Supplies** 1.00 Tire Disposal Fee 4.00 Hours 10.25 Labor: 615.00 Parts: 681.96 Total: 1,296.96 Workorder: 1708279 Meter: 80923 In Date: 08/22/2017 **Closed:** 09/07/2017 Problem: P.M. service. - P.m. service. **Parts List** Qty - Broken engine and transmission mounts .r&r with new. Engine Oil Stop Leak 1.00 - Rear brakes new pads, new calipers, new rotors on both rear 10w30 Motor Oil 5.00 brakes.fluash and bleed system.test drive,ok. Mac Wite Lithium Gres 1.00 - Rotate and high speed balance all four tires. Napagold Oil Filter 1.00 - Shop Supplies Napagold Air Filter 1.00 Napagold Fuel Filter 1.00 Washer Fluid Concentr 1.00 18" wiper blades 12.00 2.00 Motor Mount **Transmission Mount** 1.00 Reman Brake Caliper 1.00 Reman Brake Caliper 1.00 B Fluid Dot 3-32oz 1.00 Non-chlor Brake Clnr 1.00 lube 1.00 Brake Rotor Only 2.00 **Shop Supplies** 1.00 Labor: 645.00 Hours 10.75 Parts: 440.00 Total: 1,085.00

Workorder: 1802393 Meter: 83874 Problem: PM Service		lı	n Date:	03/02/2018	Closed:	03/08/2018	
- P.m. service.		Parts List				Q	ty
- Remove and replace drive belt tensioner and se	erpentine	Napagold	Oil Filter			1.0	00
belt.		10w30 Mo	tor Oil			5.0	00
- Perform transmision service.flush trans fluid.		18" wiper	blades			2.0	00
- Balance and rotate all four wheels .nitrofill all.		Gas Cap N	lon-locki	ng		1.0	00
- Shop Supplies		Used Fire	X Refurb	ished		1.0	00
		Engine Oil	Stop Lea	ak		1.0	00
		Syn-atf Tra	ans Fluid	S		12.0	00
		Serpentine	Belt			1.0	00
		Belt Tension	oner Ass	y		1.0	00
		Shop Supp	olies			1.0	00
Hours 6.45 :	Labor:	387.00	Parts:	180.34	Total:	567.34	
Workorder: 1806800 Meter: 86229 Problem: A/C stuck on defrost.		lı	n Date:	07/02/2018	Closed:	07/05/2018	
- Diagnose A/c blend door . Repair vacuum servio	ce line to	Parts List				Q	ty
Hvac system .retest.	200 10	W W Vacu		na		3.0	-
- Shop Supplies		Shop Supp		.9		1.0	
Hours 1.50	Labor:		Parts:	3.31	Total:	93.31	
Workorder: 1810042 Meter: 87556 Problem: P.M. service and gauges and warn	ing light con		n Date: driving .	09/27/2018	Closed:	10/18/2018	
- P.m. service . Road test and computer diagnose		Parts List	_			Q	ty
could not dupicate at this time.	3-3	White She		p Lk			00
- Check battery and charging system . After fully of		Napagold		•		1.0	00
battery, battery failed load test. R&r defective battery bolts.	tery and	10w30 Mo				5.0	00
- Check and replace defective rear shocks .		Napagold	Fuel Filte	er		1.0	00
- Balance and rotate all four tires.		18" wiper				2.0	
							00
		Used Fire	X Refurb	ished		1.0	
- Shop Supplies				ished			00 00 00
		Battery Ca		ished		2.0	00
		Battery Ca Battery	ble Bolt			2.0	00 00 00
		Battery Ca	ble Bolt m Trk Sh	nock		2.0 1.0 2.0	00 00 00
		Battery Ca Battery Oespectru Chevy Gol	ble Bolt m Trk Sh d Bow S	nock wc		2.0 1.0 2.0 1.0	00 00 00 00
		Battery Ca Battery Oespectru	nble Bolt m Trk Sh d Bow So at Set Blk	nock wc		2.0 1.0 2.0 1.0	00 00 00 00

Workorder: Problem:	1904931 P.M. service	Meter:	88974			In Date:	05/06/2019	Closed:	05/13/2019
- P.m. service).				Parts Li	st			Qty
- Test and rep	place both hea	adlights bulk) .			d Oil Filter			1.00
	nigh speed ba	•		ofill all.	10w30 N				5.00
- Shop Suppli	• .				Washer	Fluid Conc	entr		1.00
					18" wipe	er blades			2.00
					Halogen	Sealed Be	ams		2.00
					Shop Su	pplies			1.00
	Hou :	ırs 4.75		Labor:	318.25	Parts:	41.58	Total:	359.83
Workorder: Problem:	1907734 A/C not cold	Meter: and ants .	89112			In Date:	07/25/2019	Closed:	08/07/2019
- A/c system	performance t	est.replace	leaking		Parts Li	st			Qt
evaporator,co	ndensor,accui			um and	Air Fresh	nener			1.00
recharge syste	-				A/c Orific	e Tube			1.00
- Shop Suppli	es				Fat Clute	h			1.00
					E8 A/c C	il Univ W E	Оуе		1.00
					A/c Gasl	ket Kit			1.00
					Freon L	Shop 2			2.00
					A/c Cond	denser			1.00
					A/c Accu	ımulator			1.00
					A/c Evap	orator			1.00
					Shop Su	pplies			1.00
	Hou :	ırs 5.50		Labor:	368.50	Parts:	756.89	Total:	1,125.39
Workorder: Problem:	1908797 Fumigate for	Meter: ant .	89131			In Date:	08/22/2019	Closed:	08/28/2019
- Spray and b	omb van for a								
	Ηοι :	ırs 0.50		Labor:	33.50	Parts:	0.00	Total:	33.50
Workorder: Problem:	1911280 P.M. service	Meter: and hank h	89155 as new tag .			In Date:	10/30/2019	Closed:	11/07/2019
- P.m. service).				Parts Li	st			Qt
- Rotate and I	oalance all fou	ır tires . Nitr	ofill all		10w30 N	lotor Oil			5.00
- Shop Suppli	es				Napagol	d Oil Filter			1.00
					18" wipe	er blades			2.00
					White Li	hium Grea	se		1.00
					Used Fir	e X Refurb	ished		1.00
					Napagol	d Fuel Filte	r		1.00
					Shop Su	pplies			1.00
					Chiop Co	PP00			1.0

Workorder: 2005773 Meter: 89312		d off O =	In Date:	06/10/2020	Closed:	07/15/202	20
Problem: PM Service, Dash gauges and lights turn	on an	a on. Gas	s gauge no	t working,			
- P.m. service.		Parts Li	st				Qty
- Computer diagnose fuel gauge . Perform test . Remove		Napagol	1.00				
tank to replace fuel pump/sender assembly and connecte Clear code and retest .	or .	10w30 M	lotor Oil		į	5.00	
- Computer diagnose air bag light , codes B0016 , B001	Ω	18" wipe	er blades			2	2.00
B0024 ,b1000 and U1301 . Access carpet to replace	Ο,	Washer	Fluid Conce	entr		1.00	
corroded air bag module .		Seal Fue	el			1.00	
- Replace both worn rear bump stops .		Fuel Pur		1.00 1.00			
- Rotate and high speed balance all four tires . Nitrofill a	all.	Module			1.00		
- Transport to and from dealer to reprogram and configu	ıre	Bumper	2.00				
pody control module and air bag module.		Program	Air Bag		1.0	1.00	
- Shop Supplies		Shop Supplies				1.00	1.00
Hours 12.25 La	abor:	894.25	Parts:	1,172.38	Total:	2,066.63	
Workorder: 2010811 Meter: 89334 Problem: Towed in for no start .			In Date:	10/27/2020	Closed:	11/02/202	20
- Charge battery fully . Test battery and charging system	n.	Parts Lis	st				Qty
R&r defective battery .		Battery				•	1.00
Hours 1.00 La	abor:	73.00	Parts:	127.97	Total:	200.97	
Workorder: 2010898 Meter: 89334			In Date:	10/29/2020	Closed:	10/29/202	20
Problem: Transition Prep Charge							
- Transition Prep Charge							
Hours 2.00 La	abor:	146.00	Parts:	0.00	Total:	146.00	