

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10180767    2010 FORD RANGER Pickup, Compact**

**Workorder:** 1002703    **Meter:** 0    **In Date:** 03/16/2010    **Closed:** 03/16/2010  
**Problem:** Pre Delivery Inspection

- Pre Delivery Inspection
- Wash Vehicle

Hours 2.50                      Labor: 150.00      Parts: 0.00                      Total: 150.00  
:

**Workorder:** 1004080    **Meter:** 953    **In Date:** 04/21/2010    **Closed:** 04/21/2010  
**Problem:** Nail in L/F tire

- Repair L/f tire.
- Shop Supplies

**Parts List**  
Shop Supplies                      Qty  
1.00

Hours 1.00                      Labor: 60.00      Parts: 2.00                      Total: 62.00  
:

**Workorder:** 1011037    **Meter:** 4406    **In Date:** 10/06/2010    **Closed:** 10/18/2010  
**Problem:** Pm service,also see notes on washer fluid.

- P.m. Service.
- Rotate and balance all tires.repair l/f tire.
- Shop Supplies

**Parts List**  
Shop Supplies                      Qty  
1.00  
Ph9566 Oil Filter Use Fram Ph3614                      1.00  
5w20 Engine Oil                      4.00

Hours 4.00                      Labor: 240.00      Parts: 13.11                      Total: 253.11  
:

**Workorder:** 1011408    **Meter:** 4408    **In Date:** 10/15/2010    **Closed:** 10/19/2010  
**Problem:** flash canceiver spot 216

- Flash Canceiver
- Shop Supplies

**Parts List**  
Shop Supplies                      Qty  
1.00

Hours 1.00                      Labor: 60.00      Parts: 2.00                      Total: 62.00  
:

**Workorder:** 1104434    **Meter:** 8504    **In Date:** 04/26/2011    **Closed:** 05/05/2011  
**Problem:** P.M. service and nails in tires.

- Perform pm service.
- Repair both rear tires flat.nitrogen fill and balance all four.
- Shop Supplies

**Parts List**  
Shop Supplies                      Qty  
1.00  
Ph9566 Oil Filter Use Fram Ph3614                      1.00  
5w20 Engine Oil                      5.00  
Nb-18 Wiper Blades 18" Anco 31-18                      2.00

Hours 4.00                      Labor: 240.00      Parts: 27.45                      Total: 267.45  
:

**Workorder:** 1105610    **Meter:** 8919    **In Date:** 05/27/2011    **Closed:** 05/31/2011  
**Problem:** Right front and left rear tires flat

- Repair two flat tires,right front and and left rear.nitrogen fill and balance both.re mount spare tire back to rack and secure.
- Shop Supplies

**Parts List**  
Shop Supplies                      Qty  
1.00

Hours 2.00                      Labor: 120.00      Parts: 2.00                      Total: 122.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1106856      **Meter:** 9305      **In Date:** 05/26/2011      **Closed:** 06/28/2011  
**Problem:** r/f flat--561.310.7515

- From: mosquito control

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1107448      **Meter:** 9446      **In Date:** 07/15/2011      **Closed:** 07/22/2011  
**Problem:** Pm service also check ac concern

- Perform pm service.  
- Install four new tires.nitrogen fill and balance all four  
- Perform wheel alignment complete.  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
1348 Oil Filter Frm Ph3614 Wix 51348	1.00
5w20 Engine Oil	5.00
Nb-18 Wiper Blades 18" Anco 31-18	2.00
183482418 P225/70r15 Wrangler Sr-a 100s	4.00
Tire Disposal Fee	4.00

Hours 6.50      Labor: 390.00      Parts: 496.46      Total: 886.46  
:

**Workorder:** 1110718      **Meter:** 11198      **In Date:** 10/06/2011      **Closed:** 10/06/2011  
**Problem:** Wiper blades failed and two flat tires see notes.

- Wiper blades damage due to paint over spray.clean paint off windshield and install new wiper blades.  
- Repair three flat tires.left front,left rear and right rear.nitrogen fill and balance all.  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
Nb-18 Wiper Blades 18" Anco 31-18	2.00

Hours 2.50      Labor: 150.00      Parts: 12.19      Total: 162.19  
:

**Workorder:** 1201683      **Meter:** 14714      **In Date:** 02/21/2012      **Closed:** 02/29/2012  
**Problem:** Pm service.Brake lamp inop and windshield washer fluid,see notes.

- Perform pm service.  
- Remove left tail lamp.test and replace failed brake light bulb with new.  
- Rotate and balance all four tires.  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00
1348 Oil Filter Frm Ph3614 Wix 51348	1.00
Ca8243 Air Filter Lbf Af1658 Wix 46253	1.00
3424 Fuel Filter Frm 3424 Wix 33424	1.00
5w20 Engine Oil	5.00
3157 Tail Light Bulbs	1.00

Hours 3.50      Labor: 210.00      Parts: 30.90      Total: 240.90  
:

**Workorder:** 1203754      **Meter:** 15669      **In Date:** 04/02/2012      **Closed:** 04/19/2012  
**Problem:** flat tire

- Tire Service C-rock Forest Hill Blvd. - flat tire

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1206532      **Meter:** 17474      **In Date:** 07/12/2012      **Closed:** 08/09/2012  
**Problem:** Check over ac vent output.Gear shift indicator.Fuel line safety recall campaign.

- Inspect for ac vents for air flow.clean ac recycle air screen and evaporator housing from debris.      **Parts List**      **Qty**  
Shop Supplies      1.00

- Transport vehicle to and from dealer for replacing failed gear shifter selector and indicator with new.also for fuel line recall.inspect and modify cover.

- Shop Supplies

Hours 2.75      Labor: 165.00      Parts: 2.00      Total: 167.00  
:

---

**Workorder:** 1208889      **Meter:** 17762      **In Date:** 09/17/2012      **Closed:** 09/18/2012  
**Problem:** No start

- Tow From: 8100 Forest Hill Blvd To: Lv Shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1208920      **Meter:** 17826      **In Date:** 09/19/2012      **Closed:** 09/26/2012  
**Problem:** P.M. Service.Towed in,no start.

- P.m. Service.      **Parts List**      **Qty**  
- Test battery and charging system.charge and retest battery,bad.replace defective battery.      Big G Degreaser Stock# 485180002      1.00  
Shop Supplies      1.00  
- Replace center brake light bulb.      1348 Oil Filter Frm Ph3614 Wix 51348      1.00  
- Repair one tire,rotate and balance all four.      5w20 Engine Oil      5.00  
- Shop Supplies      Wd40 Spray Lube Stock# 405540002      1.00  
Nb-18 Wiper Blades 18" Anco 31-18      2.00  
Group 59 Battery (mtc Bxt 59)      1.00

Hours 5.25      Labor: 315.00      Parts: 157.58      Total: 472.58  
:

---

**Workorder:** 1211315      **Meter:** 18651      **In Date:** 11/21/2012      **Closed:** 11/21/2012  
**Problem:** l/f flat tire

- Tire Service 4236 Lake worth rd - l/f flat tire

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1211316      **Meter:** 18651      **In Date:** 11/21/2012      **Closed:** 11/21/2012  
**Problem:** Service

- Tire Service 4236 Lake Worth Rd - Service

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1302555	<b>Meter:</b> 21427	<b>In Date:</b> 03/14/2013	<b>Closed:</b> 03/20/2013
<b>Problem:</b> P.M. service and towed in for left rear tire going flat.			
- P.m. Service.		<b>Parts List</b>	<b>Qty</b>
- Replace three tires,rotate and balance all four.		5w20 Engine Oil	5.00
- Complete wheel alignment.test drive.		Filter	1.00
- Shop Supplies		Napagold Fuel Filter	1.00
		Ca8243 Air Filter Lbf	1.00
		183482418 P225-70r15	3.00
		Shop Supplies	1.00
		Tire Disposal Fee	3.00
Hours 6.50	Labor: 390.00	Parts: 510.80	Total: 900.80
:			
<b>Workorder:</b> 1302572	<b>Meter:</b> 21339	<b>In Date:</b> 03/14/2013	<b>Closed:</b> 03/14/2013
<b>Problem:</b> Flat Tire / PM			
- Tow From: 8100 Forest hill blvd. To: Lv			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1305359	<b>Meter:</b> 23147	<b>In Date:</b> 05/31/2013	<b>Closed:</b> 06/05/2013
<b>Problem:</b> needs extra key			
- Make and program 1 extra key		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Ford Ignition Key Blank	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 28.61	Total: 88.61
:			
<b>Workorder:</b> 1306338	<b>Meter:</b> 23919	<b>In Date:</b> 06/25/2013	<b>Closed:</b> 06/27/2013
<b>Problem:</b> Left rear tire flat			
- Repair and balance left rear tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1306669	<b>Meter:</b> 24097	<b>In Date:</b> 07/03/2013	<b>Closed:</b> 07/05/2013
<b>Problem:</b> Towed in for right front tire flat.			
- Repair and balance right front tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1306700	<b>Meter:</b> 24053	<b>In Date:</b> 07/02/2013	<b>Closed:</b> 07/03/2013
<b>Problem:</b> Flat tire on F150			
- Tow From: 9045 Jog Rd, Boynton Beach To: Lv			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1400689      **Meter:** 29885      **In Date:** 01/22/2014      **Closed:** 02/19/2014  
**Problem:** PM, FLAT TIRE HAZARDS DONT WORK, DRIVER SIDE DOOR DRAWS IN WATER WHEN RAINING  
WASHER FLUID REFILL

	<b>Parts List</b>	<b>Qty</b>
- pm		
- ck strobe light not working perform pin point test and found bad switch remove panels and replace switch	Napa Quart 5w20	5.00
- ck hazard light not working verify concern ck and found bad flasher unit replace flasher unit	Napagold Oil Filter	1.00
- resurface front rotors svc calipers and replace pads	Napagold Fuel Filter	1.00
- replace both rear tires and rotate to the front	Wiper Blade	2.00
- replace shifter bushings shaft and plunger assembly	Toggle Switch	1.00
- Shop Supplies	Flasher Relay	1.00
	Disc Brake Pads	1.00
	Ceramic Brake Lube	1.00
	183482418 P225-70r15	2.00
	Shift indicator	1.00
	Spring	1.00
	Lever	1.00
	F3tz71278a Bushing Sh	2.00
	Gear Lunger	1.00
	Tube	1.00
	Pin	1.00
	Pin	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.00	Labor: 840.00	Parts: 648.68
:		Total: 1,488.68

**Workorder:** 1400954      **Meter:** 29580      **In Date:** 01/21/2014      **Closed:** 01/29/2014  
**Problem:** driver side flat

- Tow From: 9045 jog road delray To: sr shop delray	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

**Workorder:** 1401918      **Meter:** 30217      **In Date:** 02/27/2014      **Closed:** 02/28/2014  
**Problem:** need extra key

	<b>Parts List</b>	<b>Qty</b>
- Make and program 1 key		
- Shop Supplies	Ford Ignition Key Blank	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 28.61
:		Total: 88.61

**Workorder:** 1401921      **Meter:** 30355      **In Date:** 02/27/2014      **Closed:** 02/28/2014  
**Problem:** Left headlight inop and strobe lights inop.

	<b>Parts List</b>	<b>Qty</b>
- Replace left headlight bulb.		
- Check inop strobe lights.replace inline fuse holder.	Halogen Capsule	1.00
- Shop Supplies	Fuse Holder	1.00
	Shop Supplies	1.00
Hours 1.25	Labor: 75.00	Parts: 12.85
:		Total: 87.85

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1405783      **Meter:** 33078      **In Date:** 06/12/2014      **Closed:** 06/18/2014

**Problem:** leak driver rear tire, maybe a nail

- ck nail in l rear tire verify two rear tires need replaced mount balance add n2	<b>Parts List</b>	<b>Qty</b>
	183482418 P225-70r15	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.50	Labor: 90.00	Parts: 322.02
:		Total: 412.02

**Workorder:** 1408280      **Meter:** 35304      **In Date:** 08/20/2014      **Closed:** 09/15/2014

**Problem:** pm, shift link stuck nail in rear driver tire

- pm	<b>Parts List</b>	<b>Qty</b>
- ck shifter link stuck ck and found broken shifter indicator replace shifter indicator	Napagold Air Filter	1.00
	Bulb	1.00
- repair left rear brake light	Napa Quart 5w20	5.00
- repair left rear tire	Napagold Oil Filter	1.00
- clean inside cab before repair	Napagold Fuel Filter	1.00
- Shop Supplies	Accufit Conventional	2.00
	Napagold Air Filter	1.00
	Washer Fl	1.00
	Mac Wite Lithium Gres	1.00
	Shift indicator	1.00
	Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 99.28
:		Total: 444.28

**Workorder:** 1411266      **Meter:** 37182      **In Date:** 11/05/2014      **Closed:** 11/12/2014

**Problem:** Flat tire on Rear Driver side

- Tire Service Davis Rd N of Meleluca lane South of Lw Rd -  
Flat tire on Rear Driver side

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1501856      **Meter:** 40769      **In Date:** 02/20/2015      **Closed:** 02/27/2015

**Problem:** pm, driver tire leak, rear driver nail inside

- pm	<b>Parts List</b>	<b>Qty</b>
- verify needs two tires mount balance add n2 rotate to front	Napagold Oil Filter	1.00
- verify steering wheel needs cover install steering wheel cover	Napa Quart 5w20	5.00
	183482418 P225-70r15	2.00
- verify two holes in tire patch mount balance add n2	Stg Wheel Cov - Ford	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.00	Labor: 300.00	Parts: 359.22
:		Total: 659.22

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1502822	<b>Meter:</b> 41254	<b>In Date:</b> 03/18/2015	<b>Closed:</b> 03/27/2015
<b>Problem:</b> ck engine light on and off vehicle shakes at low speed, sputters on acceleration expecially when ...			
- ck engine light is on scan found po303 po316 perform pinpoint test and found bad coil pack and plugs replace spark plugs plug wires coil pack and clear codes	<b>Parts List</b>		<b>Qty</b>
	Spark Plug		4.00
	Coil Asy		1.00
- clean throttle plact and intake manifold	Wire Asy		1.00
- test drive before and after repair	Shop Supplies		1.00
- Shop Supplies			
Hours 7.00	Labor: 420.00	Parts: 164.63	Total: 584.63
:			

---

<b>Workorder:</b> 1506302	<b>Meter:</b> 43941	<b>In Date:</b> 06/23/2015	<b>Closed:</b> 06/25/2015
<b>Problem:</b> no start towed in			
- ck no start test battery bad ck charging sys replace battery	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Battery		1.00
	Shop Supplies		1.00
Hours 0.75	Labor: 45.00	Parts: 99.89	Total: 144.89
:			

---

<b>Workorder:</b> 1506432	<b>Meter:</b> 43941	<b>In Date:</b> 06/26/2015	<b>Closed:</b> 06/26/2015
<b>Problem:</b> won't start			
- Tow From: 9045 jog road boynton To: sr shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1506603	<b>Meter:</b> 44040	<b>In Date:</b> 07/01/2015	<b>Closed:</b> 07/08/2015
<b>Problem:</b> L/REAR TIRE FLAT			
- replace damage left rear tire	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	183482418 P225-70r15		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 156.10	Total: 216.10
:			

---

<b>Workorder:</b> 1508476	<b>Meter:</b> 45927	<b>In Date:</b> 08/24/2015	<b>Closed:</b> 09/08/2015
<b>Problem:</b> pm, lr tire flat, towed in			
- pm	<b>Parts List</b>		<b>Qty</b>
- needs front pads replace front brake pads tdurn rotors svc calipers	Napagold Fuel Filter		1.00
	Napagold Oil Filter		1.00
- verify bad front stablizer bushings replace front stablizer bushings	Napa Quart 5w20		5.00
	Wiper Blade		2.00
- replace 1 tire mount balance add n2	Disc Brake Pads		1.00
- replace rr tail light bulb	Ptex Anti-seize 16oz		1.00
- verify two tires have nails replace two different fires	Sway Bar Repair Kit		1.00
dismount patch mount balance add n2	183482418 P225-70r15		1.00
- Shop Supplies	Bulb		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 11.00	Labor: 660.00	Parts: 295.00	Total: 955.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1508527      **Meter:** 45673      **In Date:** 08/24/2015      **Closed:** 08/25/2015  
**Problem:** lr flat tire

- Tow From: 9045 jog road water utilities To: Sr Shop

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 1509933      **Meter:** 46949      **In Date:** 09/30/2015      **Closed:** 10/07/2015  
**Problem:** left rear tire

- verify two flat tires repair two tires front left and left rear      **Parts List**      **Qty**  
mount add n2      Shop Supplies      1.00  
- Shop Supplies

Hours 2.00      Labor: 120.00      Parts: 2.00      Total: 122.00  
:

---

**Workorder:** 1510437      **Meter:** 47248      **In Date:** 10/15/2015      **Closed:** 10/20/2015  
**Problem:** ROAD CALL/ TIRES FLAT

- travel to vehicle install spare to bring vehicle back to sr for      **Parts List**      **Qty**  
repair      183482418 P225-70r15      1.00  
- verify fr tire unable to repair replace tire      Shop Supplies      1.00  
- repair front left tire replace valve stem add n2      Tire Disposal Fee      1.00  
- Shop Supplies

Hours 3.00      Labor: 180.00      Parts: 157.75      Total: 337.75  
:

---

**Workorder:** 1510824      **Meter:** 47493      **In Date:** 10/26/2015      **Closed:** 10/28/2015  
**Problem:** Left front tire flat.Right head lamp inop.

- Replace and balance one tire due to sidewall damage.      **Parts List**      **Qty**  
- Replace defective right headlamp bulb.      183482418 P225-70r15      1.00  
- Shop Supplies      Halogen Capsule      1.00  
Shop Supplies      1.00  
Tire Disposal Fee      1.00

Hours 1.00      Labor: 60.00      Parts: 150.57      Total: 210.57  
:



**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1603025      **Meter:** 51776      **In Date:** 03/22/2016      **Closed:** 04/14/2016  
**Problem:** pm, front strobe, washer fluid, ac not blow that well, driver door not close properly

- Pm service.	<b>Parts List</b>	<b>Qty</b>
- Replace right front strobe light	Napagold Oil Filter	1.00
- Replace both lower ball joints.	Napa Quart 5w20	5.00
- Replace leaking windshield washer pump.replace steering wheel cover and brake pedal pad.	18" wiper blades	2.00
- Replace both rear tires and rotate to front.	Washer Fluid Concentr	1.00
- Check and found no reverse light.perform pinpoint test..found bad bulbs and bad safety neutral switch.replace both bulbs and safety neutral switch.	Vtx609c Led Strobe Cl	1.00
- C/s ac not blowing that well.check and found clogged evaporator core.clean evaporator core.	Pedal Pad	1.00
- Fill all tires with nitrogen.	Stg Wheel Cov - Ford	1.00
- Shop Supplies	183482418 P225-70r15	2.00
	Lamp	2.00
	Joint Assy	2.00
	Washer Pump	1.00
	Trans Senor/ns5576	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.75	Labor: 885.00	Parts: 691.91
:		Total: 1,576.91

**Workorder:** 1604260      **Meter:** 51800      **In Date:** 04/22/2016      **Closed:** 05/05/2016  
**Problem:** Driver door hinge loose.

- R&r left door and replace upper and lower hinges.adjust door.replace missing kick panel trim and scuff plate.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Panel	1.00
	molding plate	1.00
	screw and	8.00
	Hinge Asy	1.00
	Hinge Ass	1.00
	Mac Wite Lithium Gres	1.00
	Shop Supplies	1.00
Hours 2.50	Labor: 150.00	Parts: 216.01
:		Total: 366.01

**Workorder:** 1605999      **Meter:** 52663      **In Date:** 06/10/2016      **Closed:** 06/14/2016  
**Problem:** ROAD CALL, FLAT TIRE AT 9045 JOG ROAD.

- C/c flat tire.repair,mount and balance.add N2.	<b>Parts List</b>	<b>Qty</b>
- Travel to location.install spare tire so driver could bring vehicle to shop for repair.	Shop Supplies	1.00
- Shop Supplies		
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1606999      **Meter:** 53532      **In Date:** 07/12/2016      **Closed:** 07/28/2016  
**Problem:** Check brakes.Left rear tire flat

- C/c bad brakes.remove wheels.inspect brake system and replace defective brake vacume booster.	<b>Parts List</b>	<b>Qty</b>	
- Repair left rear tire.	Brake Booster	1.00	
- Test drive before and after repairs.	Shop Supplies	1.00	
- Shop Supplies			
Hours 4.25	Labor: 255.00	Parts: 203.29	Total: 458.29
:			

---

**Workorder:** 1608394      **Meter:** 54297      **In Date:** 08/15/2016      **Closed:** 08/17/2016  
**Problem:** Right front tire flat.

- Repair And Balance R/front Tire	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

---

**Workorder:** 1610853      **Meter:** 55680      **In Date:** 10/20/2016      **Closed:** 10/31/2016  
**Problem:** P.M. service and no start.

- P.m. Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00	
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	5.00	
- Replace right front upper control arm.	18" wiper blades	2.00	
- Replace front pads,calipers and rotors.flush and bleed system.	Washer Fluid Concentr	1.00	
- Complete wheel alignment.test drive.	Napagold Air Filter	1.00	
- Service transmission.flush and refill system.replace leaking dipstick tube seal.	Battery	1.00	
- Shop Supplies	Control Arm Assembly	1.00	
	Brake Rotor Hub	2.00	
	Napa Oil Seal	2.00	
	Non-chlor Brake Clnr	1.00	
	Fil Kit	1.00	
	Syn-atf Trans Fluid S	14.00	
	Reman Brake Caliper	1.00	
	Reman Brake Caliper	1.00	
	183482418 P225-70r15	2.00	
	dip stick seal	1.00	
	Rear Trans Seal	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 14.50	Labor: 870.00	Parts: 890.69	Total: 1,760.69
:			

---

**Workorder:** 1610968      **Meter:** 55570      **In Date:** 10/20/2016      **Closed:** 10/24/2016  
**Problem:** no start/ pm service

- Tow From: 9045 jog/ boynton bch To: 2601 vista			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1612383	<b>Meter:</b> 56166	<b>In Date:</b> 12/02/2016	<b>Closed:</b> 12/14/2016
<b>Problem:</b> Towed in left front tire flat.			
- Repair and balance left front tire.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1612548	<b>Meter:</b> 56012	<b>In Date:</b> 12/02/2016	<b>Closed:</b> 12/07/2016
<b>Problem:</b> Flat Tire (L/F)			
- Tow From: 4418 Venus Ave			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1701790	<b>Meter:</b> 57624	<b>In Date:</b> 02/21/2017	<b>Closed:</b> 02/28/2017
<b>Problem:</b> Gear shifter indicator not accurate.			
- Adjust Gear Shifter.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
<b>Workorder:</b> 1704153	<b>Meter:</b> 57645	<b>In Date:</b> 04/25/2017	<b>Closed:</b> 05/11/2017
<b>Problem:</b> P.M. service and towed in for no crank and recall 16S26.			
- P.m. Service.		<b>Parts List</b>	<b>Qty</b>
- Recharge battery and test charging system.replace defective alternator and serpentine belt.		5w20 Engine Oil	5.00
- Replace left front strobe light light bulb.		Napagold Oil Filter	1.00
- Service transmission.flush and refill system.		18" wiper blades	2.00
- Replace rear brake rotors,calipers and brake pads.flush and bleed system.		Washer Fluid Concentr	1.00
- Replace leaking pinnion seal.inspect and service rear differential.		Altenador Asm Motorcraft	1.00
- Replace both rear shocks.		V Belt	1.00
- R&r instrument cluster and rep[lace broken shift indicator.		Vtx609c Led Strobe Cl	1.00
- Shop Supplies		Syn-atf Trans Fluid S	11.00
		Screen Asy	1.00
		Rear Trans Seal	1.00
		brake pad	1.00
		Reman Brake Caliper	1.00
		Reman Brake Caliper	1.00
		B Fluid Dot 3-32oz	1.00
		Non-chlor Brake Clnr	1.00
		Real Brake Rotor	2.00
		Seal Asy	1.00
		Napa Gear 80w-90 Qt	3.00
		Friction Modifier	1.00
		Insulator Front Shocks	2.00
		Shock Abso	2.00
		Shift indicator	1.00
		Napagold Fuel Filter	1.00
		Shop Supplies	1.00
Hours 14.25	Labor: 855.00	Parts: 1,007.21	Total: 1,862.21
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1704163	<b>Meter:</b> 57624	<b>In Date:</b> 04/25/2017	<b>Closed:</b> 04/25/2017
<b>Problem:</b> No start			
- Tow From: 8100 Forest Hill Blvd To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1704603	<b>Meter:</b> 57624	<b>In Date:</b> 05/09/2017	<b>Closed:</b> 05/09/2017
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1708246	<b>Meter:</b> 58299	<b>In Date:</b> 08/21/2017	<b>Closed:</b> 08/23/2017
<b>Problem:</b> Towed in for no start.			
- Charge battery fully .test battery and charging system.perform draw test .found .112 amps draw from canceiver.send to Se shop for removal.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
<b>Workorder:</b> 1708251	<b>Meter:</b> 58299	<b>In Date:</b> 08/21/2017	<b>Closed:</b> 08/25/2017
<b>Problem:</b> canceiver problem			
- Test and remove canceiver issue fuel card			
	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
<b>Workorder:</b> 1708307	<b>Meter:</b> 58299	<b>In Date:</b> 08/22/2017	<b>Closed:</b> 08/23/2017
<b>Problem:</b> No Start			
- Tow From: Croc near cub hood up keys in it			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1708315	<b>Meter:</b> 58299	<b>In Date:</b> 08/23/2017	<b>Closed:</b> 08/23/2017
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1800537	<b>Meter:</b> 59666	<b>In Date:</b> 01/17/2018	<b>Closed:</b> 01/30/2018
<b>Problem:</b> P.M. service.			
- P.m. service.			
	<b>Parts List</b>		<b>Qty</b>
- R&r driver seat to be repaired.	5w20 Engine Oil		5.00
- Check strobe light system.repair broken wire to power switch for corner strbe lights.	Napagold Oil Filter		1.00
	18" wiper blades		2.00
- Rotate and high speed balance all four tires.	Seat R And R		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 5.00	Labor: 300.00	Parts: 294.91	Total: 594.91
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1806769      **Meter:** 60583      **In Date:** 07/02/2018      **Closed:** 07/18/2018  
**Problem:** P.M. Service.Recall.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- R&r right front marker light lens due to water intrusion .	Napagold Oil Filter	1.00
- Perform A/c performance test . Leak test . Replace high side line from condensor to evap ,accumulator and orifice tube . Evacuate and complete recharge to factory spec.	5w20 Engine Oil	5.00
	18" wiper blades	2.00
- Transport to and from dealer for recall 16s26 .	Freon Lv Shop 1	2.00
- Shop Supplies	Lamp Assy	1.00
	O Ring	3.00
	O-ring	3.00
	Orifice Tube Filter	1.00
	Accumulator	1.00
	Tube Asy	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 327.70
:		Total: 867.70

**Workorder:** 1807024      **Meter:** 60583      **In Date:** 07/11/2018      **Closed:** 07/18/2018  
**Problem:** replace rear cab glass

- set up repairs & reasett	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Workorder:** 1903024      **Meter:** 60740      **In Date:** 03/19/2019      **Closed:** 03/28/2019  
**Problem:** P.M. Service.

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Charge battery fully . Test battery and charging system . R&r failed battery .	Napagold Oil Filter	1.00
	5w20 Engine Oil	5.00
- Rotate and high speed balance all four tires . Nitrofill all.	18" wiper blades	2.00
- Shop Supplies	Battery	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 268.00	Parts: 153.30
:		Total: 421.30

**Workorder:** 1911561      **Meter:** 61674      **In Date:** 11/06/2019      **Closed:** 11/19/2019  
**Problem:** P.M. service and towed in for no start and stalling .

- P.m. service.	<b>Parts List</b>	<b>Qty</b>
- Charge battery . Test battery and charging system . Battery failed load test . R&r defective battery .	Napagold Oil Filter	1.00
	5w20 Engine Oil	5.00
- Test and replace left reverse light bulb .	18" wiper blades	2.00
- Computer diagnose Abs light , code B1318 no communication with Abs . Perform pinpoint test . R&r defective Abs module and Pmi module . Clear codes and retest .	B Fluid Dot 3-32oz	1.00
	Boxed Miniatures	1.00
	Battery	1.00
- Rotate and high speed balance all four tires . Nitrofill all.	Control Abs	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 7.00	Labor: 511.00	Parts: 786.45
:		Total: 1,297.45

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1911602      **Meter:** 61567      **In Date:** 11/06/2019      **Closed:** 11/07/2019  
**Problem:** Truck starts but when accelerated it stalls. Keys in cupholder - located in CROC parking lot N of gas, S of warehouse  
- Tow From: Croc 8100 Forest Hill To: Lv Shop - Vista  
Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

---

**Workorder:** 2004209      **Meter:** 61674      **In Date:** 04/28/2020      **Closed:** 04/28/2020  
**Problem:** Transition Prep Charge  
- Transition Prep Charge  
Hours 2.00      Labor: 146.00      Parts: 0.00      Total: 146.00  
: