10174408 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 842615 Meter: 0 In Date: 08/11/2008 Closed: 08/11/2008 Problem: PRE-DELIVERY INSPECTION - Pre-delivery Inspection Labor: 120.00 Parts: 0.00 Total: 120.00 Hours 2.00 Workorder: 843703 Meter: 356 In Date: 09/03/2008 Closed: 09/25/2008 Problem: INSTALL LADDER RACK. - Fabricate And Install Ladder Rack. **Parts List** Qty - Shop Supplies **Shop Supplies** 1.00 Ladder Rack 1.00 Labor: 240.00 Hours 4.00 Parts: 334.40 Total: 574.40 934079 Workorder: Meter: 2835 In Date: 02/17/2009 Closed: 02/25/2009 Problem: P.M.SERVICE - Pm Service **Parts List** Qty - Install New Decal **Shop Supplies** 1.00 1372 Oil Filter Frm Ph2 Wix 51372 - Shop Supplies 1.00 5w20 Engine Oil 7.00 Hours 3.00 Labor: 180.00 Parts: 38.68 Total: 218.68 Workorder: 944265 Meter: 6907 In Date: 10/07/2009 Closed: 10/09/2009 Problem: PM SERVICE - P.m.service **Parts List** Qty - Service And Test Fuel Tank, fuel Pump; r/r Filter **Shop Supplies** 1.00 - Service Latter Rack 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00 1259 Hydr Filter Lbf Frm P1653a Wix 51259 1.00 5w20 Engine Oil 7.00 Used Firex Refurbed Fire Extingshers 1.00 Hours 4.75 Labor: 285.00 Parts: 71.47 Total: 356.47 Workorder: 1001556 02/11/2010 Meter: 8774 In Date: **Closed:** 02/11/2010 Problem: 1 - Key(s) issued - 1 - Key(s) issued **Parts List** Qty **Duplicate Vehicle Keys** 1.00 Hours 0.20 Labor: 12.00 Parts: 3.00 Total: 15.00

Workorder: 1003280 Meter: 9817	In Date: 03/31/2010 Closed: 04/	/08/2010
<b>Problem:</b> P. M. SERVICE, & Wire up diesel fuel tank	Powdo Link	Otro
- P. M.	Parts List	Qty
- Wire aux fuel tank & service pump.	Shop Supplies Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00 1.00
<ul><li>Install "how's my driving" decal.</li><li>Rotate tire &amp; perform tire reset procedure.</li></ul>	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	1066 White Lithium (crc 05037)	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 7.75 Labor:	465.00 Parts: 76.39 Total: 541	
: : : : : : : : : : : : : : : : : : :	In Date: 09/30/2010 Closed: 10/	/13/2010
Problem: P. M. SERVICE	in Date. 09/30/2010 Closed. 10/	13/2010
- P. M.	Parts List	Qty
- Service & test fuel pump system. R&r filter.	Shop Supplies	1.00
- Service ladder rack, tighten, lube, etc.	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
- Nail in Rr tire. Dismount, patch, mount, balance, add 75	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
Psi of Nitrogen.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	5w20 Engine Oil	7.00
Hours 5.75 Labor:	345.00 Parts: 49.74 Total: 394	4.74
Workorder: 1103447 Meter: 16230 Problem: P.M.SERVICE	In Date: 03/30/2011 Closed: 03/	/31/2011
- P. M. Service.	Parts List	Qty
- Service fuel Aux tank. Replace filter.	Shop Supplies	1.00
- Verify, needs two tires. Mount, balance, add Nitro, & rotate	. 1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00
Hours 5.25 Labor:	Tire Disposal Fee 315.00 Parts: 440.32 Total: 755	
Hours 5.25 Labor: :  Workorder: 1104925 Meter: 17025 Problem: Service engine light is on	315.00 Parts: 440.32 Total: 755	
: Workorder: 1104925 Meter: 17025 Problem: Service engine light is on	315.00 Parts: 440.32 Total: 755  In Date: 05/10/2011 Closed: 05/	5.32 /20/2011
:  Workorder: 1104925 Meter: 17025  Problem: Service engine light is on  - C/s: Service engine light is on. Verify, scan for codes, Code # P0191-ff, perform pinpoint test on fuel system, found low	315.00 Parts: 440.32 Total: 755  In Date: 05/10/2011 Closed: 05/  Parts List Shop Supplies	5.32
:  Workorder: 1104925 Meter: 17025  Problem: Service engine light is on  - C/s: Service engine light is on. Verify, scan for codes, Code	315.00 Parts: 440.32 Total: 755  In Date: 05/10/2011 Closed: 05/  Parts List Shop Supplies	5.32 /20/2011 <b>Qty</b>
:  Workorder: 1104925 Meter: 17025  Problem: Service engine light is on  - C/s: Service engine light is on. Verify, scan for codes, Code # P0191-ff, perform pinpoint test on fuel system, found low fuel pressure, check, replace clogged fuel filter, clear codes &	315.00 Parts: 440.32 Total: 755  In Date: 05/10/2011 Closed: 05/  Parts List Shop Supplies	5.32 /20/2011 <b>Qty</b> 1.00

Workorder: Problem:	1109877 P. M. SERVIC	Meter:	19494			In Date:	09/15/2011	Closed:	09/20/20	011
- P. M. Servic		-			Parts Lis	<b>.</b>				Ott
- P. IVI. Service					Shop Su					<b>Qty</b> 1.00
		stata ta the	front		•		Dho Wiy F1	272		
•	h rear tires & ro		e iront.				n Ph2 Wix 513			1.00
	my driving dec	cai.			-		f Frm P1653a	WIX 51259		1.00
- Shop Suppli	es				5w20 En	_	5 47 M	0 5		7.00
							5r17 Wrangle	r Sr-a E		2.00
		5 50			Tire Disp		445.70	<b>.</b>	7.45.70	2.00
	Hour :	s 5.50		Labor:	330.00	Parts:	415.70	l otal:	745.70	
Workorder: Problem:	1110232 Check battery	<b>Meter:</b> , had to ju	19666 mp start			In Date:	09/26/2011	Closed:	09/26/20	011
	je & replace ba	d battery.	Aces code H	lca 0p,	Parts Lis	st				Qty
Dtc Code 845					Shop Su	pplies				1.00
- Shop Suppli	es				Group 65	Battery (n	ntc Bxt-65-850	0)		1.00
	Hour	s 0.75		Labor:	45.00	Parts:	130.75	Total:	175.75	
Workorder: Problem:	1200026 Flat tire, right	Meter: rear	21455			In Date:	01/03/2012	Closed:	01/12/20	012
- C/c: Right re	ar tire flat. Ver	ifv. flat tire	. Air up in pa	rkina lot	Parts Lis	st				Qty
to move to sho	p. Verify, unab	ole to repa			Shop Su					1.00
N2. Test drive	to clear Tpms	light.			•		5r17 Wrangle	r Sr-a F		1.00
- Shop Suppli	es				Tire Disp		or in wrangio	. 0. 4 2		1.00
	Hour	s 1.00		Labor:	-		204.68	Total:	264.68	1.00
Workorder:	1202386	Matari	20745			In Date:	02/00/2042	Classel	02/40/20	242
	P.M.SERVICE	Meter: E, A/C ON	22745 LY WORKS (	ON 3 AND	4.	iii Date.	03/08/2012	Closed:	03/19/20	J12
- pm service					Parts Lis	st				Qty
- sevice aus f	uel tank				Shop Su	pplies				1.00
	nly works on 3				1372 Oil	Filter Frm	n Ph2 Wix 513	372		1.00
pinpiint test an	d found bad bl	ower resis	tor replace re	esistor	G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
- Shop Suppli	es				1259 Hy	dr Filter Lbi	f Frm P1653a	Wix 51259		1.00
					5w20 En	gine Oil				8.00
						•	d Fire Extings	hers		1.00
							20" Blade			2.00
					A/c Resis	•				1.00
	Hour	s 6.00		Labor:	360.00		91.04	Total:	451.04	
Workorder:	1206069	Meter:	24363			In Date:	06/28/2012	Closed:	06/29/20	 012
Problem:	canceiver									
	ver-working into	ermitent re	emove cance	iver issue	Parts Lis	st				Qty
fuel card					Shop Su	pplies				1.00
- Shop Suppli	es				- '	•				
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1211831 P.M.SERVICE	Meter:	27626			In Date:	12/06/2012	Closed:	12/19/2	012
- pm					Parts Li	st				Qty
- Shop Suppli	es				Napa Q	uart 5w20				8.00
					Ph2 Oil	Filter Lbf Ph	า			1.00
					31-20 W	/iper Blades	3 20			2.00
					Ca1026	2 Air Filter N	Иt			1.00
					Shop Su	upplies				1.00
	Hours :	s 2.75		Labor:	165.00	Parts:	54.71	Total:	219.71	
Workorder: Problem:	1307692 pm	Meter:	32266			In Date:	08/01/2013	Closed:	08/27/2	013
- pm					Parts Li	st				Qty
- ck air bag lig	ght comes on in	termittent	ly scanand fo	und code	Napago	ld Oil Filter				1.00
	cm, u0073 30,				Napago	ld Fuel Filte	r			1.00
	rcm replace ro	•	•		Napa Q	uart 5w20				8.00
- test drive 50 coming on afte	miles to verify er repair	intermitte	ny air bag iigr	nt is not	31-20 W	/iper Blades	20			2.00
- Shop Suppli	•				Washer	FI				1.00
					Restrair	t Control M	od			1.00
					Shop St	upplies				1.00
	Hours :	s 8.75		Labor:	525.00	Parts:	311.35	Total:	836.35	
Workorder: Problem:	1311528 dead battery	Meter:	34206			In Date:	11/15/2013	Closed:	11/21/2	013
- ck jump star	t every morning	g recharge	battery ck ba	attery and	Parts Li	st				Qty
charging sys b	attery failed loa	ad test rr b	attery	-	Battery					1.00
- Shop Suppli	es				Shop St	upplies				1.00
	Hours :	s 0.75		Labor:	45.00	Parts:	121.61	Total:	166.61	
Workorder: Problem:	1406073 p.m.service	Meter:	38322			In Date:	06/19/2014	Closed:	06/26/2	014
- pm					Parts Li	st				Qty
	ault light flashir	ng reprogr	am tpms sen	sor	Napago	ld Oil Filter				1.00
correct all n2 l					Napa Q	uart 5w20				8.00
- Shop Suppli	es				Shop Su	upplies				1.00
						<b>-</b> .				

Labor: 225.00 Parts: 36.29

Total: 261.29

Hours 3.75

Workorder: 1501520 Problem: pm	Meter:	43129		I	n Date:	02/10/2015	Closed:	02/24/2015
- pm				Parts List	t			Qt
- repair 3rd brake light				Napagold	Oil Filter			1.00
- replace 4 tires				Napa Qua	rt 5w20			8.00
- fill all tires with nitroger	n and reprogra	m tpm		Napagold	Fuel Filte	r		1.00
- Shop Supplies				Wiper Bla	de			2.00
				Washer F	l			1.00
				Mac Wite	Lithium G	ires		1.00
				Napagold	Air Filter			1.00
				Used Fire	X Refurb	ished		1.00
				Lt245/75r	17 Hanko	ok Tire		4.00
				Flasher - I	Hazard			1.00
				Shop Sup	plies			1.00
				Tire Dispo	sal Fee			4.00
!	Hours 6.25		Labor:	375.00	Parts:	1,132.39	Total:	1,507.39
Workorder: 1506276 Problem: FRONT E	Meter: END DRIVER S	45908 SIDES NOISE		I	n Date:	06/23/2015	Closed:	06/25/2015
- remove cab and replace	e 6 body mour	nts / insulators	;	Parts List	t			Qt
- repair both head lights				Body Mou	ınt Kit			2.00
- Shop Supplies				Body Mou	ınt Kit			4.00
				Halogen L	.amp			2.00
				Shop Sup	plies			1.00
!	Hours 9.00		Labor:	540.00	Parts:	510.86	Total:	1,050.86
Workorder: 1508801 Problem: p.m.servi	Meter: ce/ needs stee	47656 ring wheel cov	/er	I	n Date:	09/02/2015	Closed:	09/14/2015
				Parts List	t			Qt
- pm								
<ul><li>pm</li><li>ck steering wheel cove</li></ul>	r			Stg Whee	I Cov - Fo	ord		1.00
F	er			Stg Whee Napagold		ord		1.00 1.00
- ck steering wheel cove	:r			-	Oil Filter	ord		
- ck steering wheel cove	er			Napagold	Oil Filter art 5w20	ord		1.00
- ck steering wheel cove	:r			Napagold Napa Qua	Oil Filter art 5w20 Vheel	ord		1.0 8.0

Workorder: Problem:	1601429 PM, AC FAN	<b>Meter:</b> 51727 I SWITCH ONLY WOI	RKS ON 3 -		n Date: JCK IN IG	02/10/2016 INITION	Closed:	03/29/2016
- pm				Parts List				Qty
-	ly works on 3	- 4 perform pinpoint to	est and	Napagold	Oil Filter			1.00
found bad blow	ver resistor re	eplace blower resistor		Napa Qua				8.00
<ul> <li>ck key stuck and key to vin</li> </ul>		and replace ign key c	ylinder lock	Napagold			1.00	
,		ug wire harness and f	emale	Washer Fl	uid Conce	entr		1.00
connector	oded trailer pr	ag wire riamess and r	Ciriaic	20" Wiper	Blade			2.00
- svc ladder ra	ack			Used Fire	X Refurb	ished		1.00
- Shop Suppli	es			resistor				1.00
				Ingition Lo	ck			1.00
				connector				1.00
				Female Co	onn Sock	et		1.00
				Term 24-2	2 Conn		10.00	
				Wire Term	16-14 BI	lt		10.00
				Step Dowr		tor		25.00
				14-16 Ga	Sldr Seal			50.00
				Shop Supp	olies			1.00
				Freight Ch	arge			1.00
	Hou :	urs 12.00	Labor:	720.00	Parts:	406.42	Total:	1,126.42
Workorder: Problem:	1602067 Install compu	<b>Meter:</b> 51064 uter stand.		lı	n Date:	02/29/2016	Closed:	03/02/2016
- Assemble a	nd install com	puter stand.		Parts List				Qty
- Shop Suppli		•						•
				Shop Supp	olies			1.00
	Hou :	urs 2.00	Labor:	Shop Supp 120.00	olies Parts:	2.00	Total:	1.00 122.00
Workorder: Problem:	1610711	Meter: 55960  Bad battery.Check lace		120.00		2.00	Total:	
	1610711	Meter: 55960		120.00	Parts:			122.00
<b>Problem:</b> - P.m.service	: 1610711 Pm service.E	Meter: 55960	dder rack bas	120.00 lı	Parts:	10/18/2016		122.00
Problem: - P.m.service - C/c Dead Bacharging Syst	: 1610711 Pm service.E attery, Test Ba	<b>Meter:</b> 55960 Bad battery.Check lace	dder rack bas	120.00 In Sec.	Parts:  n Date:  Air Filter	10/18/2016		122.00 10/28/2016 <b>Qty</b>
Problem: - P.m.service - C/c Dead Ba Charging Syst - C/c Ck Ladd	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery e. Service Ladder Race	dder rack bas	120.00 In se. Parts List Napagold	Parts:  n Date:  Air Filter Fuel Filte	10/18/2016		122.00 10/28/2016 <b>Qty</b> 1.00
Problem: - P.m.service - C/c Dead Ba Charging Syst - C/c Ck Ladd Metal Coat In	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base Rust Treatme	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery b. Service Ladder Race ant&paint.	dder rack bas ,check k,grind	120.00  In se.  Parts List Napagold Napagold	Parts:  n Date:  Air Filter Fuel Filter Oil Filter	10/18/2016		122.00 10/28/2016 <b>Qty</b> 1.00 1.00
Problem: - P.m.service - C/c Dead Ba Charging Syst - C/c Ck Ladd Metal Coat In	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base Rust Treatme	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery e. Service Ladder Race	dder rack bas ,check k,grind	I20.00  In se.  Parts List  Napagold  Napagold  Napagold	Parts:  n Date:  Air Filter Fuel Filte Oil Filter rt 5w20	10/18/2016		122.00 10/28/2016 <b>Qty</b> 1.00 1.00 1.00
Problem: - P.m.service - C/c Dead Baccharging Syst - C/c Ck Ladd Metal Coat In - C/c Trailer L	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base Rust Treatme ight Plug. Inst	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery e. Service Ladder Race ent&paint. tall Female Trailer Plu	dder rack bas ,check k,grind	I20.00  Parts List Napagold Napagold Napagold Napagold Napagold	Parts:  n Date:  Air Filter Fuel Filte Oil Filter rt 5w20	10/18/2016		122.00 10/28/2016 Qty 1.00 1.00 1.00 8.00
Problem: - P.m.service - C/c Dead Ba Charging Syst - C/c Ck Ladd Metal Coat In - C/c Trailer L Connector.	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base Rust Treatme ight Plug. Inst	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery e. Service Ladder Race ent&paint. tall Female Trailer Plu	dder rack bas ,check k,grind	I20.00  In Se.  Parts List Napagold Napagold Napagold Napagold Napa Qua 20" Wiper	Parts:  n Date:  Air Filter Fuel Filter Oil Filter rt 5w20 Blade	10/18/2016		122.00 10/28/2016
Problem:  - P.m.service  - C/c Dead Ba Charging Syst  - C/c Ck Ladd Metal Coat In  - C/c Trailer L Connector.  - Rotate And	: 1610711 Pm service.E attery, Test Ba em. ler Rack Base Rust Treatme ight Plug. Inst	Meter: 55960 Bad battery.Check lace attery Bad. R/r Battery e. Service Ladder Race ent&paint. tall Female Trailer Plu	dder rack bas ,check k,grind	I20.00  Parts List Napagold Napagold Napagold Napagold Napa Qua 20" Wiper Battery	Parts:  n Date:  Air Filter Fuel Filte Oil Filter rt 5w20 Blade	10/18/2016		122.00  10/28/2016  Qty 1.00 1.00 8.00 2.00 1.00

Workorder: Problem:	1701154 Driver window	Meter: Inop.	57746			In Date:	02/03/2017	Closed:	02/21/20	)17
	r driver window		ace driver dod	or window	Parts Li	st				Qty
· ·	window track/ru				Lf Windo	w Truck Ru	ın			1.00
<ul> <li>Had to jump and test batter</li> </ul>	start vehicle in y ok.	Wud parl	king lot.fully re	echarge	Regulato					1.00
- Shop Suppli	es				Shop Su	ipplies				1.00
	Hours :	3 2.75		Labor:	165.00	Parts:	281.77	Total:	446.77	
Workorder: Problem:	1704124 PM Service	Meter:	58940			In Date:	04/25/2017	Closed:	05/08/20	)17
- Pm Service					Parts Li	st				Qty
- Mount and b	alance two tires	s.rotate a	nd balance tw	o tires.	Napagol	d Oil Filter				1.00
- Shop Suppli	es				Napa Qu	uart 5w20				8.00
					22" Wipe	er Blade				2.00
					Washer	Fluid Conce	entr			1.00
					Used Fir	e X Refurbi	ished			1.00
					1796364	192 Lt245-7	5r17			2.00
					Shop Su	ıpplies				1.00
					Tire Disp	osal Fee				2.00
	Hours :	3 4.75		Labor:	285.00	Parts:	572.61	Total:	857.61	
Workorder:	1711892	Meter:	62467			In Date:	12/05/2017	Closed:	12/11/20	)17
Problem:	PM Service an	d excess	ive noises ove	er bumps.						
- Pm Service.					Parts Li	st				Qty
- Replace fror	nt and rear shoo	ks.			Napagol	d Oil Filter				1.00
- Replace two	rear tires then	rotate ne	w tires to the t	front.	Napa Qı	uart 5w20				8.00
- Repair utility	bed light.				22" Wipe	er Blade				2.00
- Service ladd	er rack.				Washer	Fluid Conce	entr			1.00
- Shop Suppli	es				Napagol	d Air Filter				1.00
					Napagol	d Fuel Filte	r			1.00
					Gas Gra	nde Fleet S	Shoc			2.00
					Gas Gra	nde Shock				2.00
					1796364	192 Lt245-7	5r17			2.00
					Bulb					2.00
					Shop Su	ıpplies				1.00
					Tire Disp	osal Fee				2.00
	Hours :	8.25		Labor:	495.00	Parts:	728.57	Total:	1,223.57	•
Workorder: Problem:	1804868 Right tail light i	Meter:	64814			In Date:	05/10/2018	Closed:	05/21/20	)18
- Test and rep	lace right tail la	mp bulb.ı	epair socket.	clean and	Parts Li	st				Qty
lube socket.					Boxed M	1iniatures				1.00
	Hours :	s 0.50		Labor:	30.00	Parts:	0.77	Total:	30.77	

	1806264 Pm Service	Meter: e.Install fuel ta	65272 Ink and pump	p in bed o		n Date:	06/19/2018	Closed:	06/29/2018
- Pm Service.				'	Parts List				Qt
- Repair left rea	ar reverse l	ight.			Napa Qua	rt 5w20			8.00
- Install auxilia		•	I		Napagold	Oil Filter			1.00
- Fabricate and	-			ınd	Washer Fl		entr		1.00
ground with fus	se for pump	)	·		22" Wiper	Blade			2.00
- Service ladde	er rack.				Napagold	Air Filter			1.00
- Shop Supplie	es				Napa Tran	s Filter			1.00
					Napagold	Fuel Filte	r		1.00
					Used Fire	X Refurb	ished		1.00
					Filter Kit				1.00
					Boxed Min	iatures			1.00
					Wire Term	16-14 BI	lt		10.00
					Atc-30 Fus	se			2.00
					Marine Ba	tt Fuse 1	25a		1.00
					Fuse Hold	er			1.00
					Shop Supp	olies			1.00
	Н	ours 18.75		Labor:	1,125.0	Parts:	174.05	Total:	1,299.05
	:				0				
	1808311	Meter: ENT OUT, NO	65804 D REVERSE			n Date:	08/14/2018	Closed:	09/28/2018
Problem: - C/s no revers	: 1808311 TRANS. W se.diagnose	Meter: ENT OUT, NO	O REVERSE ad				08/14/2018	Closed:	
Problem: - C/s no revers transmission.da	: 1808311 TRANS. W se.diagnose amage plan	Meter: ENT OUT, NO and found ba etary.replace	D REVERSE ad transmissior	า	lı		08/14/2018	Closed:	Qty
Problem: - C/s no revers	: 1808311 TRANS. W se.diagnose amage plan lines and ra	Meter: ENT OUT, No e and found ba etary.replace	D REVERSE ad transmissior	า	lı Parts List		08/14/2018	Closed:	<b>Qty</b> 20.00
Problem: - C/s no revers transmission.da assemblyflush	: 1808311 TRANS. W se.diagnose amage plan lines and ra .scan and c	Meter: ENT OUT, No e and found ba etary.replace	D REVERSE ad transmissior	า	Parts List Syn Atf Bu	ılk South	08/14/2018	Closed:	<b>Qty</b> 20.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.	: 1808311 TRANS. W se.diagnose amage plan lines and ra .scan and c ter repairs.	Meter: ENT OUT, No e and found ba etary.replace	D REVERSE ad transmissior	า	Parts List Syn Atf Bu Oil Cooler	ılk South	08/14/2018	Closed:	09/28/2018  Qty 20.00 1.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive after	: 1808311 TRANS. W se.diagnose amage plan lines and ra .scan and c ter repairs.	Meter: ENT OUT, No e and found ba etary.replace	D REVERSE ad transmissior	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy	ilk South  olies	08/14/2018		<b>Qty</b> 20.00 1.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft - Shop Supplie	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and cer repairs.	Meter: ENT OUT, NO e and found ba etary.replace adiator cooler elear codes.  burs 17.50  Meter:	D REVERSE ad transmissior	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0	ilk South  olies			Qty 20.00 1.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and cer repairs.	Meter: ENT OUT, NO e and found ba etary.replace adiator cooler elear codes.  burs 17.50  Meter:	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0	alk South  oblies Parts:	4,658.03	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive afters and supplied workorder:  Problem:	: 1808311 TRANS. W se.diagnose amage plan lines and ra.scan and correpairs. es Ho 1901466 PM Service	Meter: ENT OUT, NO e and found basetary.replace adiator cooler elear codes.  Durs 17.50  Meter:	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0	olles Parts:	4,658.03	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie  Workorder: Problem:  - Pm Service.	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and cer repairs. es Ho : 1901466 PM Service	Meter: ENT OUT, NO e and found ba etary.replace ediator cooler elear codes.  Durs 17.50  Meter: e.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In	olies Parts: n Date:	4,658.03	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie  Workorder: Problem:  - Pm Service.  - Replace both	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and correpairs. es Ho : 1901466 PM Service	Meter: ENT OUT, NO e and found batetary.replace adiator cooler clear codes.  Durs 17.50  Meter: e. mp bulbs. aux tank.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In Parts List Napagold	olles Parts:  Date:  Oil Filter rt 5w20	4,658.03 02/07/2019	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03 02/25/2019 Qty 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie  Workorder: Problem:  - Pm Service.  - Replace both  - Service aps f	: 1808311 TRANS. W se.diagnose amage plan lines and rascan and correpairs. es Ho : 1901466 PM Service or reverse larguel system are pedal page	Meter: ENT OUT, NO e and found batetary.replace adiator cooler clear codes.  Durs 17.50  Meter: e. mp bulbs. aux tank.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In Parts List Napagold Napa Qua	olles Parts:  Date:  Oil Filter rt 5w20 uid Conco	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 5,708.03 02/25/2019 Qty 1.00 8.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive afters afters and supplied.  Workorder: Problem:  - Pm Service.  - Replace bothers aps for the service aps for the service aps for the service.	: 1808311 TRANS. W se.diagnose amage plan lines and ra .scan and correpairs. es Ho 1901466 PM Service n reverse languel system se pedal page er rack.	Meter: ENT OUT, NO e and found ba etary.replace adiator cooler elear codes.  Durs 17.50  Meter: e. mp bulbs. aux tank. d.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In Parts List Napagold Napa Qua Washer Fl	olles Parts:  Date:  Oil Filter rt 5w20 uid Conc	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03  02/25/2019  Qty 1.00 8.00 1.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie  Workorder: Problem:  - Pm Service.  - Replace both  - Service aps f.  - Replace brak  - Service ladde	: 1808311 TRANS. W se.diagnose amage plan lines and rates and control of the repairs.  1901466 PM Service of reverse larger system are pedal pager rack.  rotate tires.	Meter: ENT OUT, NO and found batery.replace diator cooler elear codes.  Durs 17.50  Meter: a. mp bulbs. aux tank. d.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In Parts List Napagold Napa Qua Washer Fl Napagold	olies Parts:  Date:  Oil Filter rt 5w20 uid Conci	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03  02/25/2019  Qty 1.00 8.00 1.00 2.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive aft.  - Shop Supplie  Workorder: Problem:  - Pm Service.  - Replace both  - Service aps f.  - Replace brak  - Service ladde.  - Balance and	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and correpairs. es Ho 1901466 PM Service n reverse languel system are pedal page are rack. rotate tires. from radiati	Meter: ENT OUT, NO and found batery.replace diator cooler elear codes.  Durs 17.50  Meter: a. mp bulbs. aux tank. d.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In  Parts List Napagold Napa Qua Washer Fl Napagold Boxed Min	olies Parts:  Diles Parts:  Dil Filter rt 5w20 uid Conc Fuel Filte diatures as Filter	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03 02/25/2019 Qty 1.00 8.00 1.00 2.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive afters afters and several cooler.  - Test drive afters and several cooler.  - Shop Supplies  Workorder: Problem:  - Pm Service.  - Replace bothers applies and applies applies and applies and applies applies and applies applies and applies applies and applies applies applies and applies app	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and correpairs. es Ho 1901466 PM Service n reverse languel system are pedal page are rack. rotate tires. from radiati	Meter: ENT OUT, NO and found batery.replace diator cooler elear codes.  Durs 17.50  Meter: a. mp bulbs. aux tank. d.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0 In  Parts List Napagold Napa Qua Washer Fl Napagold Boxed Min Napa Tran	olies Parts:  Date:  Oil Filter rt 5w20 uid Conci Fuel Filte iiatures as Filter	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 5,708.03 02/25/2019 Qty 1.00 8.00 1.00
Problem:  - C/s no revers transmission.da assemblyflush lexternal cooler.  - Test drive afters afters and several cooler.  - Test drive afters and several cooler.  - Shop Supplies  Workorder: Problem:  - Pm Service.  - Replace bothers applies and applies applies and applies and applies applies and applies applies and applies applies and applies applies applies and applies app	: 1808311 TRANS. W se.diagnose amage plan lines and ra. scan and correpairs. es Ho 1901466 PM Service n reverse languel system are pedal page are rack. rotate tires. from radiati	Meter: ENT OUT, NO and found batery.replace diator cooler elear codes.  Durs 17.50  Meter: a. mp bulbs. aux tank. d.	D REVERSE ad transmissior for debris.rep	n place	Parts List Syn Atf Bu Oil Cooler Tram Assy Shop Supp 1,050.0 0  In  Parts List Napagold Napa Qua Washer Fl Napagold Boxed Min Napa Tran Pedal Pad	olles Parts:  Diles Parts:  Diles Parts:  Dil Filter rt 5w20 uid Conc Fuel Filte diatures dis Filter Blade	4,658.03 02/07/2019 entr	Total:	Qty 20.00 1.00 1.00 1.00 5,708.03  02/25/2019  Qty 1.00 8.00 1.00 2.00 1.00 1.00

Workorder: Problem:	1908022 PM Service.	Meter:	70395			In Date:	08/02/2019	Closed:	08/12/20	19
- Pm Service.					Parts Li	st				Qty
- Repair aux f	uel pump,repla	ace blown t	use.service	aux.fuel	22" Wip	er Blade				2.00
system.					Washer	Fluid Conce	entr			1.00
- Service ladd	er rack.				Napa Q	uart 5w20				8.00
- Rotate and b					Napago	ld Oil Filter				1.00
- Shop Suppli	es				Napago	ld Air Filter				1.00
					Wd40 S	pr				1.00
					Used Fi	re X Refurbi	ished			1.00
					Napa Tr	ans Filter				1.00
					Atc-30 F	use				5.00
					Shop Su	upplies				1.00
	Hour	s 7.50		Labor:	502.50	Parts:	88.74	Total:	591.24	
Workorder: Problem:	2000971 Rear tire flat.	Meter:	72904			In Date:	01/29/2020	Closed:	01/31/20	20
- Repair and b	palance right fr	ont tire.rep	lace Tpms	band and	Parts Li	st				Qty
sensor left rea	r wheel.		-		Tpms St	trap				1.00
- Shop Suppli	es				Tire Pre	ssure Sens	or			1.00
					Shop Su	upplies				1.00
	Hour	s 1.50		Labor:	109.50	Parts:	113.02	Total:	222.52	
Workorder: Problem:	2001618 PM Service.	Meter:	73574			In Date:	02/14/2020	Closed:	02/28/20	20
- Pm Service.					Parts Li	st				Qty
- Rotate and b	palance tires.				Napago	ld Oil Filter				1.00
- Shop Suppli	es				Napa Q	uart 5w20				8.00
					22" Wip	er Blade				2.00
					Washer	Fluid Conce	entr			1.00
					Shop Su	upplies				1.00
	Hour	s 3.50		Labor:	255.50		50.76	Total:	306.26	
Workorder: Problem:	2002694 Transition Pre	Meter: ep Charge	73779			In Date:	03/17/2020	Closed:	03/17/20	20
- Transition P	rep Charge									
	Hour	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00	