

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10172348 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid**

**Workorder:** 841168      **Meter:** 0      **In Date:** 07/10/2008      **Closed:** 07/10/2008  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 841207      **Meter:** 0      **In Date:** 07/10/2008      **Closed:** 07/10/2008  
**Problem:** 002 KEYS ISSUED OUT      07/10/08

- 002 Keys Issued Out      07/10/08

**Parts List**      **Qty**

Duplicate Vehicle Keys      2.00

Hours 0.40      Labor: 24.00      Parts: 6.00      Total: 30.00  
:

**Workorder:** 934225      **Meter:** 2068      **In Date:** 02/19/2009      **Closed:** 02/27/2009  
**Problem:** P.M.SERVICE

- Pm Service

**Parts List**      **Qty**

- Install New Decal

Shop Supplies      1.00

- Shop Supplies

Oil Filter      1.00

5w30 Oil      5.00

Hours 2.25      Labor: 135.00      Parts: 32.13      Total: 167.13  
:

**Workorder:** 945009      **Meter:** 4021      **In Date:** 10/26/2009      **Closed:** 10/28/2009  
**Problem:** need new key fob & key

- Program new key fob.

**Parts List**      **Qty**

- Shop Supplies

Shop Supplies      1.00

Key Fob Transmitter      1.00

Hours 1.00      Labor: 60.00      Parts: 68.00      Total: 128.00  
:

**Workorder:** 945365      **Meter:** 4210      **In Date:** 10/28/2009      **Closed:** 11/17/2009  
**Problem:** P.M. Service, Need an additional Key & Remote (Key has chip inside).

- P.m.service

**Parts List**      **Qty**

- Update Scanner With New Program For New  
Ign.key;program New Key&key Fabs

Shop Supplies      1.00

Ch9018 Oil Filter Acd Pf457g Wix 57082      1.00

- Shop Supplies

5w30 Oil      5.00

Hours 4.00      Labor: 240.00      Parts: 24.22      Total: 264.22  
:

**Workorder:** 945719      **Meter:** 4210      **In Date:** 11/05/2009      **Closed:** 11/10/2009  
**Problem:** Duplicate Key

- Order key and frob. cut key-key and frob need to be  
programed with vehicle sent to Sr shop

**Parts List**      **Qty**

- Shop Supplies

Shop Supplies      1.00

Ignition Key      1.00

Transmitter - Key      1.00

Hours 1.00      Labor: 60.00      Parts: 114.07      Total: 174.07  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1000376	<b>Meter:</b> 4666	<b>In Date:</b> 01/11/2010	<b>Closed:</b> 01/29/2010
<b>Problem:</b> CHECK ENGINE LIGHT IS ON			
- R&r w/blades.		<b>Parts List</b>	<b>Qty</b>
- Transport & pick up vehicle at dealer. (defective battery pack & service air bag light stays on)		Shop Supplies	1.00
- Shop Supplies		W/blade	1.00
		W/blade	1.00
Hours 2.25	Labor: 135.00	Parts: 43.66	Total: 178.66
:			
<b>Workorder:</b> 1005152	<b>Meter:</b> 5724	<b>In Date:</b> 05/18/2010	<b>Closed:</b> 05/21/2010
<b>Problem:</b> P. M. MAINT			
- P. M. Service		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
		5w30 Oil	5.00
Hours 2.00	Labor: 120.00	Parts: 20.68	Total: 140.68
:			
<b>Workorder:</b> 1009381	<b>Meter:</b> 6749	<b>In Date:</b> 08/30/2010	<b>Closed:</b> 10/13/2010
<b>Problem:</b> CHECK ENGINE LIGHT IS ON			
- Transport & pick up vehicle at dealer for recall (#10136 Hybrid battery).		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1013403	<b>Meter:</b> 7384	<b>In Date:</b> 12/06/2010	<b>Closed:</b> 12/14/2010
<b>Problem:</b> Check tire pressures, light on			
- C/c: Tpms on. Check all tires for damage. Correct nigtrogen levels.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
<b>Workorder:</b> 1013812	<b>Meter:</b> 7613	<b>In Date:</b> 12/16/2010	<b>Closed:</b> 12/22/2010
<b>Problem:</b> P. M. SERVICE			
- P. M. Service.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
		5w30 Oil	5.00
Hours 2.00	Labor: 120.00	Parts: 20.19	Total: 140.19
:			
<b>Workorder:</b> 1106770	<b>Meter:</b> 9004	<b>In Date:</b> 06/27/2011	<b>Closed:</b> 06/30/2011
<b>Problem:</b> P. M. SERVICE			
- P. M. Service.		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Shop Supplies	1.00
		Ch9018 Oil Filter Acd Pf457g Wix 57082	1.00
		5w30 Oil	5.00
Hours 2.00	Labor: 120.00	Parts: 23.00	Total: 143.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1112635	<b>Meter:</b> 10054	<b>In Date:</b> 11/30/2011	<b>Closed:</b> 12/09/2011
<b>Problem:</b> Steering wheel tight on cold start, & shimmeys			
- Test drive vehicle & was unable to verify concern.	<b>Parts List</b>		<b>Qty</b>
- Tire light was on, check & adjust air in all tires.	Shop Supplies		1.00
- R&r wiper blades.	Wiper Blade		1.00
- Shop Supplies	Wiper Blade		1.00
Hours 1.75	Labor: 105.00	Parts: 44.51	Total: 149.51
:			
<b>Workorder:</b> 1113351	<b>Meter:</b> 10054	<b>In Date:</b> 12/20/2011	<b>Closed:</b> 12/27/2011
<b>Problem:</b> P. M. SERVICE			
- P. M. Service.	<b>Parts List</b>		<b>Qty</b>
- Vehicle had dead battery. Recharge & check charging system. Charging system & battery are ok at this time.	Shop Supplies		1.00
- Shop Supplies	Ch9018 Oil Filter Acd Pf457g Wix 57082		1.00
	5w30 Oil		5.00
Hours 2.50	Labor: 150.00	Parts: 23.00	Total: 173.00
:			
<b>Workorder:</b> 1200241	<b>Meter:</b> 10206	<b>In Date:</b> 01/09/2012	<b>Closed:</b> 01/20/2012
<b>Problem:</b> Power steering problem			
- C/s: Power steering problem. Verified concern. Found bad module.	<b>Parts List</b>		<b>Qty</b>
- Transport & pick up vehicle at dealer. (defective P/s assist motor).	Shop Supplies		1.00
- Shop Supplies			
Hours 3.00	Labor: 180.00	Parts: 2.00	Total: 182.00
:			
<b>Workorder:</b> 1200651	<b>Meter:</b> 10157	<b>In Date:</b> 01/20/2012	<b>Closed:</b> 01/20/2012
<b>Problem:</b> 10 - Wash ticket(s) issued			
- 10 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1210089	<b>Meter:</b> 14722	<b>In Date:</b> 10/22/2012	<b>Closed:</b> 10/29/2012
<b>Problem:</b> pm, washer fluid			
- pm	<b>Parts List</b>		<b>Qty</b>
- repair right rear tire	Napa Quart 5w30		5.00
- Shop Supplies	Ch9018 Oil Filter Acd		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 26.14	Total: 206.14
:			
<b>Workorder:</b> 1301625	<b>Meter:</b> 15047	<b>In Date:</b> 02/14/2013	<b>Closed:</b> 02/22/2013
<b>Problem:</b> recall			
- transport and pick up vehicle at dealer for recall #12106	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1303984	<b>Meter:</b> 15794	<b>In Date:</b> 04/23/2013	<b>Closed:</b> 05/06/2013
<b>Problem:</b> pm, rr tire flat			
- pm		<b>Parts List</b>	<b>Qty</b>
- ck flat right rear tire unable to repair mount balance add n2 to new tire		Oil Filter	1.00
- Shop Supplies		Napa Quart 5w30	5.00
		P215 60r16 Uniroyal	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours 3.00	Labor: 180.00	Parts: 196.96	Total: 376.96
:			

---

<b>Workorder:</b> 1304019	<b>Meter:</b> 15543	<b>In Date:</b> 04/23/2013	<b>Closed:</b> 04/24/2013
<b>Problem:</b> rr flat			
- Tow From: 9045 jog road boynton To: sr shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

---

<b>Workorder:</b> 1312112	<b>Meter:</b> 17691	<b>In Date:</b> 12/04/2013	<b>Closed:</b> 12/17/2013
<b>Problem:</b> P.M.SERVICE			
- pm		<b>Parts List</b>	<b>Qty</b>
- verify lr tail light out disassemble trunk panel replace bulb reassemble		Napagold Oil Filter	2.00
- Shop Supplies		Napa Quart 5w30	10.00
		Washer FI	2.00
		Accufit Beam	2.00
		Wiper Blade - Accufit - Passenger's Side	2.00
		Bulb	2.00
		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 104.69	Total: 284.69
:			

---

<b>Workorder:</b> 1407792	<b>Meter:</b> 19665	<b>In Date:</b> 08/07/2014	<b>Closed:</b> 08/19/2014
<b>Problem:</b> pm, dead battery			
- pm		<b>Parts List</b>	<b>Qty</b>
- replace bad battery and ck charging sys		Napagold Oil Filter	1.00
- replace both rear tires and rotate to the front		Napa Quart 5w30	5.00
- right front side turn signal not working remove front bumper right front wheel well trace wire harness and found broken wire repair wire harness		Washer FI	1.00
- fill all tires with nitrogen		Accufit Beam	1.00
- Shop Supplies		Wiper Blade - Accufit - Passenger's Side	1.00
		Napagold Air Filter	1.00
		Battery	1.00
		738571571 P215-60r16	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 7.50	Labor: 450.00	Parts: 476.58	Total: 926.58
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1410547	<b>Meter:</b> 20210	<b>In Date:</b> 10/22/2014	<b>Closed:</b> 10/30/2014
<b>Problem:</b> RECALL			
- dealer to perform two safety recalls 14116 13036		<b>Parts List</b>	<b>Qty</b>
- transport to and from dealer for recall		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1502852	<b>Meter:</b> 21607	<b>In Date:</b> 03/19/2015	<b>Closed:</b> 03/27/2015
<b>Problem:</b> pm			
- pm		<b>Parts List</b>	<b>Qty</b>
- Shop Supplies		Napagold Oil Filter	1.00
		Napa Quart 5w30	5.00
		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 24.22	Total: 144.22
:			
<b>Workorder:</b> 1509453	<b>Meter:</b> 22841	<b>In Date:</b> 09/18/2015	<b>Closed:</b> 09/24/2015
<b>Problem:</b> pm			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Repair Key Fab		Napagold Oil Filter	1.00
- Shop Supplies		Napa Quart 5w30	5.00
		Washer Fluid Concentr	1.00
		Enr Elect Battery	1.00
		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 33.01	Total: 213.01
:			
<b>Workorder:</b> 1602158	<b>Meter:</b> 23476	<b>In Date:</b> 03/01/2016	<b>Closed:</b> 03/14/2016
<b>Problem:</b> Pm service.TPMS warning light on.Display on radio inop.Detail.			
- Pm service.		<b>Parts List</b>	<b>Qty</b>
- Diagnose radio display inop.intermittent.test circuits replace radio.		Dexos 5w30	5.00
		Napagold Oil Filter	1.00
- Diagnose low tire pressure lamp on.test and replace defective left front tire pressure sensor.replace two tires.rotate and balance all four.		Accufit Beam	1.00
		Wiper Blade - Accufit - Passenger's Side	1.00
- Fabricate and replace front and rear asset numbers.		Tire pressure sensor	1.00
- Shop Supplies		738571571 P215-60r16	2.00
		Radio	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 6.75	Labor: 405.00	Parts: 747.38	Total: 1,152.38
:			
<b>Workorder:</b> 1602609	<b>Meter:</b> 23358	<b>In Date:</b> 03/11/2016	<b>Closed:</b> 03/11/2016
<b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1700814      **Meter:** 25795      **In Date:** 01/26/2017      **Closed:** 02/13/2017  
**Problem:** p.m.service, dead battery

<ul style="list-style-type: none"> <li>- Pm Service.</li> <li>- Replace battery.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napa Syn 5w30 Qt</li> <li>Napagold Oil Filter</li> <li>Accufit Beam</li> <li>Wiper Blade - Accufit - Passenger's Side</li> <li>Washer Fluid Concentr</li> <li>Napagold Air Filter</li> <li>Battery</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>5.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 2.75	Labor: 165.00	Parts: 191.65	Total: 356.65
:			

**Workorder:** 1708756      **Meter:** 26524      **In Date:** 09/05/2017      **Closed:** 09/29/2017  
**Problem:** Pm Service.Driver seat adjuster broken.

<ul style="list-style-type: none"> <li>- Pm service</li> <li>- C/s driver seat broken.replace seat frame assembly and change over all parts from one to next..scan and clear codes for driver seat air bag.</li> <li>- Rotate and balance tires.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Oil Filter</li> <li>Napa Syn 5w30 Qt</li> <li>Accufit Beam</li> <li>Wiper Blade - Accufit - Passenger's Side</li> <li>Washer Fluid Concentr</li> <li>Seat Frame</li> <li>Panel</li> <li>Handle</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>5.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 7.75	Labor: 465.00	Parts: 889.90	Total: 1,354.90
:			

**Workorder:** 1803784      **Meter:** 27201      **In Date:** 04/11/2018      **Closed:** 04/23/2018  
**Problem:** PM Service.Has to go 9045 Jog Road to jump start vehicle and drive back to SR Shop for service.

<ul style="list-style-type: none"> <li>- Pm Service.</li> <li>- Remove the rear window shelf trim panel to access third brake light.replace third brake light assembly.</li> <li>- Recharge battery.check charging system.charging system and battery are ok at this time.</li> <li>- Had to go to 9045 Jog Road to jump start vehicle and drive back to Sr Shop for repairs and service.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Oil Filter</li> <li>Napa Syn 5w30 Qt</li> <li>Washer Fluid Concentr</li> <li>24in Exactfit-beam</li> <li>21in Exactfit-beam</li> <li>Ligth Asy</li> <li>Shop Supplies</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>5.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 6.50	Labor: 390.00	Parts: 262.67	Total: 652.67
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1810565      **Meter:** 28421      **In Date:** 10/15/2018      **Closed:** 10/22/2018  
**Problem:** PM Service.TPMS light on.

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Repair right rear tire.	Napa Syn 5w30 Qt	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
	Wd40 Spr	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 201.00	Parts: 46.11
:		Total: 247.11

**Workorder:** 1902206      **Meter:** 28590      **In Date:** 02/27/2019      **Closed:** 05/20/2019  
**Problem:** Dead battery.Had to go to 9045 Jog road to jump start vehicle and drive back to SR Shop

- Drive to Jog road to jump start vehicle and drive back vehicle to Sr Shop for repairs.	<b>Parts List</b>	<b>Qty</b>
- Diagnose for check engine light on.dismantle and replace bad hybrid #2 battery temperature sensors and harness.	Harness Bts	1.00
- Shop Supplies	Sensor Bat Temp	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 603.00	Parts: 474.11
:		Total: 1,077.11

**Workorder:** 1904964      **Meter:** 28590      **In Date:** 05/07/2019      **Closed:** 05/29/2019  
**Problem:** PM Service.

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Replace positive battery terminal harness.	Napa Syn 5w30 Qt	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	24in Exactfit-beam	1.00
	21in Exactfit-beam	1.00
	Washer Fluid Concentr	1.00
	Napagold Air Filter	1.00
	Bat Cable	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 268.00	Parts: 213.18
:		Total: 481.18

**Workorder:** 1907117      **Meter:** 28597      **In Date:** 07/10/2019      **Closed:** 07/31/2019  
**Problem:** Bad 12 volt battery.

- Test starting and charging system.battery failed loadtest after recharge..replace 12 volt battery.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 134.28
:		Total: 201.28

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1911787      **Meter:** 28597      **In Date:** 11/13/2019      **Closed:** 12/31/2019  
**Problem:** PM Service.Intermittent no start

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance four tires.	Napagold Oil Filter	1.00
- Clean and secure battery cables.fully recharge and test 12 volt battery.	Napa Syn 5w30 Qt	5.00
- Shop Supplies	21in Exactfit-beam	1.00
	24in Exactfit-beam	1.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 3.50	Labor: 255.50	Parts: 65.31
:		Total: 320.81

**Workorder:** 2005793      **Meter:** 28597      **In Date:** 06/11/2020      **Closed:** 07/17/2020  
**Problem:** PM Service

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Rotate and balance tires.	Napa Syn 5w30 Qt	5.00
- Shop Supplies	Napagold Oil Filter	1.00
	Washer Fluid Concentr	1.00
	Wd40 Spr	1.00
	Shop Supplies	1.00
Hours 2.75	Labor: 200.75	Parts: 47.61
:		Total: 248.36

**Workorder:** 2009438      **Meter:** 28597      **In Date:** 09/18/2020      **Closed:** 09/18/2020  
**Problem:** Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00