10180790 2010 FORD ESCAPE Suv, Mid Size, Hybrid Workorder: 1003126 Meter: In Date: 03/29/2010 Closed: 03/29/2010 **Problem:** Pre Delivery Inspection - Pre Delivery Inspection Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00 Workorder: 1003513 Meter: 8 In Date: 04/06/2010 Closed: 04/12/2010 Problem: cut & program 2 extra keys **Parts List** - cut 2 key blanks and program test ok Qty - Shop Supplies **Shop Supplies** 1.00 164-r0475 Ign Key 2010-earlier (don't Reorder) 2.00 Hours 1.00 Labor: 60.00 Parts: 44.90 Total: 104.90 1005150 770 Workorder: Meter: In Date: 05/18/2010 Closed: 05/21/2010 **Problem:** Check battery, will not start after sitting overnight. - Recharge battery & test charging system. Found defective **Parts List** Qty battery. Shop Supplies 1.00 - Transport & pick up vehicle at dealer. (defective battery). Shop Supplies Labor: 150.00 Hours 2.50 Parts: 2.00 Total: 152.00 Workorder: 1005698 Meter: 873 In Date: 06/01/2010 Closed: 06/28/2010 **Problem:** Dead Battery Transport & pick up vehicle at dealer. (battery dead after Parts List Qty car sits for 2 days). 1.00 Shop Supplies - Dealer warranty. (battery & charging system. Ok. No problem found). - Shop Supplies Labor: 120.00 Total: 122.00 Hours 2.00 Parts: 2.00 Workorder: 1010915 Meter: 2872 In Date: 10/04/2010 Closed: 10/13/2010 Problem: P. M. SERVICE - P. M. Parts List Qty - Rear brake drum service. Shop Supplies 1.00 - Tpms light on. Verify, nail in F/I tire. Dismount, patch, 1348 Oil Filter Frm Ph3614 Wix 51348 1.00 mount, balance, add 35 Psi of Nitrogen, rotate to right rear. 5w20 Engine Oil 5.00 - Shop Supplies Hours 4.00 Labor: 240.00 Parts: 28.78 Total: 268.78 Workorder: 1101142 Meter: 4642 In Date: 01/31/2011 Closed: 01/31/2011 Problem: Low tire pressure, & both power outlets 12v not working **Parts List** Qty Repair right front tire. - C/s: Both power outlets not working. Perform pinpoint test Shop Supplies 1.00

Shop Supplies

fuses.

Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 92.00

:

& found blown fuse for power point & cig lighter, replace both

Workorder: Problem:	1105870 P. M. SE		Meter:	7118			In Date:	06/02/2011	Closed:	06/10/2	011
- P. M. Servic	e:					Parts Li	st				Qty
- Rear brake	drum serv	ice.				Shop Su	upplies				1.00
- C/c: Check	12 volt out	tlets. \	/erify, fus	se blown	on outlets.	1348 Oi	Filter Frm	Ph3614 Wix	51348		1.00
R&r 20amp fu			•			09997 E	Brake Clear	1			1.00
- Shop Suppli	es					5w20 Er	ngine Oil				5.00
		Hours	3.50		Labor:	210.00	•	31.74	Total:	241.74	
Workorder: Problem:	1106458 reflash ca		Meter:	7250			In Date:	06/20/2011	Closed:	06/21/20	011
- Reflash Car	nceiver					Parts Li	ist				Qty
- Shop Suppli	es					Shop Su	upplies				1.00
		Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1200482 P. M. SE		Meter:	9816			In Date:	01/13/2012	Closed:	01/27/2	012
- P. M. Servic	e.					Parts Li	ist				Qty
- Service rear	· drum bra	kes.				Shop Su	upplies				1.00
- Shop Suppli	es					1348 Oi	51348		1.00		
,,,	Chop Gapphoo						5w20 Engine Oil				
		Hours	3.00		Labor:	180.00	_	22.88	Total:	202.88	5.00
Workorder: Problem:	1204651 WINDSH	· IIELD '	Meter:	11621 BAD			In Date:	05/16/2012	Closed:	05/16/2	012
- rr wiper blac						Parts Li	ist				Qty
,						Ww-204	6 Wiper Bla	de (motorcrat	ft)		2.00
		Hours :	0.25		Labor:		•	34.08	•	49.08	
Workorder: Problem:	1205363 low tire p		Meter:	12001			In Date:	06/07/2012	Closed:	06/12/2	012
- ck tire light of	on inspect	for de	bris corre	ect all n2	levels						
		Hours :	0.75		Labor:	45.00	Parts:	0.00	Total:	45.00	
Workorder: Problem:	1210683 pm		Meter:	13484			In Date:	11/01/2012	Closed:	11/08/2	012
- pm						Parts Li	st				Qty
- repair right f						Filter					1.00
to repair tire re	piace righ	nt tront	and left	rear tire	rotate new tire	Napa Q	uart 5w20				5.00
to the front		koc				Ca1017	0 Air Filter L	_b			1.00
	di rear hra					144 204	0 M/: DI-	do M			2.00
- clean and a	•					₩-204	6 Wiper Bla	ide ivi			2.00
- clean and ac	with nitrog						6 vviper віа 418 Р235-70				2.00
	with nitrog						418 P235-70				

Workorder: Problem:	1306239 pm	Meter:	16970			In Date:	06/21/2013	Closed:	06/28/20	013
- pm					Parts Lis	st				Qty
- svc rear bfra	ake drums				Napagolo	d Oil Filter				1.00
- Shop Suppli	- Shop Supplies									5.00
					Shop Sup	oplies				1.00
		Hours 3.00 :		Labor:	180.00	Parts:	23.75	Total:	203.75	
Workorder: Problem:	1310904 pm, ac no	Meter: ot cool when ho	19593 ot out			In Date:	10/31/2013	Closed:	11/14/20	013
- pm					Parts Lis	st				Qty
- rear brake d	lrum svc				Napagolo	d Oil Filter				1.00
		vaccume sys r	efill 2 lbs ur	nable to	Napa Qu	art 5w20				5.00
find leak at thi					Wiper Bla	ade				2.00
- Shop Suppli	es				Washer F	=1				1.00
					South Re	egion R134	а			2.00
					Shop Sup	oplies				1.00
		Hours 5.00		Labor:	300.00	Parts:	60.56	Total:	360.56	
test and found	l leking co	sys pressure te ndensor evacua arge sys and ck	ate remove		Condese Oil	r Ac				Qty 1.00
Chief Cappi					Shop Sup	oplies				1.00
		Hours 5.50 :		Labor:	330.00	Parts:	358.52	Total:	688.52	
Workorder: Problem:	1406066 pm	Meter:	23556			In Date:	06/19/2014	Closed:	06/26/20	014
- pm					Parts Lis	st				Qty
- rear brake d	lrum svc				Napagolo	d Oil Filter				
- Shop Suppli	es				Napa Qu	art 5w20				1.00
					Shop Su	onlies				1.00 5.00
						phico				
		Hours 3.00		Labor:	180.00	•	24.35	Total:	204.35	5.00
Workorder: Problem:	1409891	Hours 3.00: Meter: for no start.	26616	Labor:		•	24.35	Total:	204.35	5.00 1.00
Problem: - Test starting	1409891 Towed in	Meter: for no start. ging system.ba		Labor:		Parts:				5.00 1.00
Problem:	1409891 Towed in	Meter: for no start. ging system.ba		Labor:	180.00	Parts:				5.00 1.00
Problem: - Test starting	1409891 Towed in and charge defective	Meter: for no start. ging system.ba		Labor:	180.00	Parts: In Date:				5.00 1.00 014 Qty
Problem: - Test starting loadtest.replace	1409891 Towed in and charge defectives	Meter: for no start. ging system.ba		Labor:	Parts Lis Battery Shop Su	Parts: In Date: st oplies		Closed:		5.00 1.00 014 Qty 1.00

1409903 Workorder: 26592 In Date: 10/01/2014 Closed: 10/01/2014 Meter: Problem: No start - Tow From: 8100 Forest Hill To: Fleet Lv Shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1410916 Meter: 27407 In Date: 10/31/2014 Closed: 11/10/2014 **Problem:** recall, ck power outlet it short out a lot - transport and pick up at deler for recall **Parts List** Qty - dealer to reporgram the pscm and the ic module per recall **Shop Supplies** 1.00 14s05c - ck power outlet short out a lot ck all out let and unable to verify concern at this time - Shop Supplies Labor: 150.00 Parts: 2.00 Total: 152.00 Hours 2.50 1412005 Workorder: Meter: 27407 In Date: 12/01/2014 Closed: 12/29/2014 Problem: pm, engine light on **Parts List** - Pm Qty - Clean And Adj Rear Brakes Napagold Oil Filter 1.00 - Remove 3rd Brake Light, Light Bar And Repair Light Napa Quart 5w20 5.00 - Ck Engine Light Is On Scan Found Code U3003, U1015, Wiper Blade 2.00 C1018 Poa8d, B2172, U0155, U0131, P2450, u0154, U3003, Washer FI 1.00 Po562 Clear Codes And Clear Codes Rescan Fun No Napagold Air Filter 1.00 Problem At This Time **Brake Cleaner** 1.00 - Test Drive 87 Miles **Shop Supplies** 1.00 - Shop Supplies Hours 6.75 Labor: 405.00 Parts: 64.45 Total: 469.45 Workorder: 1505826 Meter: 29220 In Date: 06/11/2015 Closed: 06/17/2015 Problem: pm, ck engine light is on **Parts List** Qty - pm - clen and adj rear brakes Napagold Oil Filter 1.00 - replace 2 rear tires and rotate to the front Washer Fluid Concentr 1.00 - ck engine light is on scan found code p2450 oer form Napa Quart 5w20 5.00 pinpoint test trace evap hose clogged canister and bad vent **Brake Cleaner** 1.00 valve replace canister assembly clear codes test drive 183407418 P235-70r16 2.00 - fill all tires with nitrogen Vapor Cannister 1.00 - Shop Supplies Shop Supplies 1.00 Tire Disposal Fee 2.00

Labor: 645.00

Parts: 650.79

Total: 1,295.79

Hours 10.75

Workorder: Problem:	1512827 pm, dash dis	Meter: splay radio a	31548 ac out		lı	n Date:	12/18/2015	Closed:	01/22/2016
- pm					Parts List				Q
- ck dash disp	olay not workir	ng verify co	ncern perform	pinpoint	Napagold	Oil Filter			1.0
	test found and front control interface module fcim update and abs to the latest clibration repalce ficm an configure module								5.0
	nodule	Washer Fl	uid Conc	entr		1.0			
- clean and ad	•				Wiper Blad	de			2.0
- Shop Suppli	es				Display				1.0
					Shop Supp	olies			1.0
	Hou :	urs 8.00		Labor:	480.00	Parts:	540.95	Total:	1,020.95
Workorder: Problem:	1606060 Ac blows hot	Meter: t air.	33131		lı	n Date:	06/13/2016	Closed:	06/30/2016
- Charge syst				aporator	Parts List				Q
leak.evacuate console.evapt					Evaporato	r			1.0
lines.replace				e and	South Reg	ion R134	a		3.0
recharge syste	em.				Kit O				1.0
- Scan test,cle actuators.	ear all codes a	and recalibr	ate all ac dooi	r	Shop Supp	olies			1.0
- Test drive af	fter repairs.								
- Shop Suppli	es								
	Hou :	urs 15.75		Labor:	945.00	Parts:	823.88	Total:	1,768.88
Workorder: Problem:	1608615 Pm service	Meter:	33635		lı	n Date:	08/18/2016	Closed:	08/24/2016
- P.m.service					Parts List				Q
- Service Rea	ır Brakes				Napagold	Oil Filter			1.0
- Rotate And	Balance Tires	í			Napa Qua	rt 5w30			5.0
- Shop Suppli	es				Washer Fl	uid Conc	entr		1.0
					Mac Wite	Lithium G	res		1.0
					Brake Clea	aner			1.0
					Shop Supp	olies			1.0
	Hou :	urs 3.75		Labor:	225.00	Parts:	33.43	Total:	258.43
	1702989	Meter:	35586		lı	n Date:	03/24/2017	Closed:	03/31/2017
Workorder: Problem:	Pm Service								
	Pm Service				Parts List				Q
Problem:	Pm Service				Parts List Napagold				Q 1.0
Problem: - Pm Service.	Pm Service brakes.					Oil Filter			
Problem: - Pm Service Service rear	Pm Service brakes.				Napagold	Oil Filter rt 5w20	entr		1.0 5.0 1.0
Problem: - Pm Service Service rear - Rotate and b	Pm Service brakes.				Napagold Napa Qua Washer Fl Wiper Blad	Oil Filter rt 5w20 uid Conc de	entr		1.0 5.0 1.0 2.0
Problem: - Pm Service Service rear - Rotate and b	Pm Service brakes.				Napagold Napa Qua Washer Fl Wiper Blad Napagold	Oil Filter rt 5w20 uid Conc de Air Filter			1.0 5.0 1.0 2.0 1.0
Problem: - Pm Service Service rear - Rotate and b	Pm Service brakes.				Napagold Napa Qua Washer Fl Wiper Blac Napagold Non-chlor	Oil Filter rt 5w20 uid Conc de Air Filter Brake Cli			1.0 5.0 1.0 2.0 1.0
Problem: - Pm Service Service rear - Rotate and b	Pm Service brakes.				Napagold Napa Qua Washer Fl Wiper Blad Napagold	Oil Filter rt 5w20 uid Conc de Air Filter Brake Cli			1.0 5.0 1.0 2.0 1.0

Workorder: Problem:	170390 NAIL IN		Meter: AR TIRE	35811			In Date:	04/18/2017	Closed:	04/24/20)17
- Repair left re		nd bala	ince.			Parts Li					Qty 1.00
		Hours :	3 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	170681 Drive to		Meter: Ranch re	36470 pad to jump s	tart vehic	le.Dead b	In Date: pattery	07/12/2017	Closed:	07/17/20)17
- Test and repok.,	place ba	d 12 vol	t battery.	est charging	system	Parts Li Battery	ist				Qty 1.00
- Travel to 12 back vehicle to				jump start ar	nd drive	Shop Su	upplies				1.00
- Shop Suppl	ies										
		Hours :	2.25		Labor:	135.00	Parts:	122.12	Total:	257.12	
Workorder: Problem:	170950 PM Sei		Meter:	37229			In Date:	09/29/2017	Closed:	10/10/20)17
- Pm Service.						Parts Li	ist				Qty
- Service rear	r brakes.					Napago	ld Oil Filter				1.00
- Rotate and	balance	tires.				Napa Quart 5w20					5.00
- Shop Suppli	ies					Washer		1.00			
						Ww-204	l6 Wiper Bla	ide M			2.00
						Ww-120)2 Wiper Bla	ide M			1.00
						Non-chl	or Brake Clr	nr			1.00
						Napago	ld Oil Filter				1.00
						Shop St	upplies				1.00
		Hours	3.75		Labor:	225.00	Parts:	100.84	Total:	325.84	
Workorder: Problem:	171265 Left rea		Meter: at. Not rep	37608 pairable.			In Date:	12/22/2017	Closed:	12/28/20)17
- Replace and	d balance	e left rea	ar tire.put	back spare ti	re to	Parts Li	ist				Qty
vehicle.nitroge	en fill all	tires and	d relearn	Tpms.		1834074	418 P235-70	Or16			1.00
- Shop Suppl	ies					Shop St		1.00			
						Tire Dis	posal Fee				1.00
		Llouro	1.25		Labor:	75.00	Parts:	187.77	Total:	262.77	
		nouis	7 1.20								
Workorder: Problem:	171269 Spare I	: 3	Meter:	37608			In Date:	12/20/2017	Closed:	12/27/20)17
	Spare I	: 13 Mount	Meter:				In Date:	12/20/2017	Closed:	12/27/20)17

Workorder: Problem:	1803251 PM Service.	Meter:	38730		I	n Date:	03/28/2018	Closed:	04/12/20	018
- Pm Service.					Parts List	t				Qty
- Service rear					Napagold					1.00
- Shop Suppli	es				Napa Qua					5.00
					Washer F		entr			1.00
					Non-chlor	Brake Clr	nr			1.00
					Shop Sup	plies				1.00
	Hour :	s 3.00		Labor:	180.00	Parts:	29.90	Total:	209.90	
Workorder: Problem:	1808316 Left front tire f	Meter:	39569		I	n Date:	08/14/2018	Closed:	08/27/20	018
- Repair and I	palance left froi	nt tire.			Parts List	t				Qty
- Shop Suppli					Shop Sup	plies				1.00
		s 1.00		Labor:		Parts:	2.00	Total:	62.00	
Workorder: Problem:	1811010 PM Service a	Meter:	39569 attery.		I	n Date:	10/25/2018	Closed:	10/31/20	018
- Pm Service.					Parts List	t				Qty
- Service rear	brakes.				Napagold	Oil Filter				1.00
- Check and r	eplace bad bat	tery.napa	warranty pai	rt.	Washer F	luid Conce	entr			1.00
- Replace righ	nt front tire.				Non-chlor	Brake Clr	nr			1.00
- Clean debris	s from under ho	ood.			Battery					1.00
- Shop Suppli	es				Non-chlor	Brake Clr	nr			1.00
					Battery					1.00
					18340741	8 P235-70	Or16			1.00
					Napa Qua	art 5w20				5.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				1.00
	Hour :	s 5.75		Labor:	385.25	Parts:	517.60	Total:	902.85	
Workorder: Problem:	1901329 Will not start.h	Meter: Had to driv	39776 e to Hagen r	anch road		n Date: art vehicle	02/04/2019 and drive SU		02/11/20 p .	019
- Test battery	bad.replace ba	attery.ched	ck charging s	system.	Parts List	t				Qty
- Travel to Ha	gen ranch road	-		-	Battery					1.00
back to Sr Sho					Shop Sup	plies				1.00
- Shop Suppli	es									
					150.75				276.89	

Problem:	1904480 p.m.service	Meter:	39959		I	n Date:	04/25/2019	Closed:	05/06/2	019
- Pm Service.					Parts List					Qty
- Balance and		tires.			Napagold					1.00
- Rear brake	n and adjust.		Napa Qua					5.00		
- Clean debris	-		20in Exac					2.00		
- Shop Suppli	ies	·			12in Exac	tfit-rear				1.00
					Washer Fl	uid Conce	entr			1.00
					Napagold	Oil Filter				1.00
					Shop Sup	plies				1.00
	Ho	ours 4.50		Labor:	301.50	Parts:	68.90	Total:	370.40	
Workorder:	1907709	Meter:	40030		I	n Date:	07/25/2019	Closed:	07/25/2	019
Problem:	Had to jum	p start .								
- Jump start . system ,ok . P Needs to be d	Perform draw Iriven more o	test .o5 amp			33.50	Parts:	0.00	Total:	33.50	
Workorder: Problem:	1908201 wont fuel	Meter:	40078		I	n Date:	08/07/2019	Closed:	08/07/20	019
- test and rem	nove canceiv	er. issue fue	l card		Parts List					Qty
- Shop Suppli	ies				Shop Sup	plies				1.00
	Н	ours 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00	
Workorder:	1908859	Meter:	40299		I	n Date:	08/23/2019	Closed:	08/30/2	019
		Meter: door power w			I	n Date:	08/23/2019	Closed:	08/30/2	019
	Right rear	door power w			I Parts List		08/23/2019	Closed:	08/30/2	
Problem:	Right rear our window reg	door power w					08/23/2019	Closed:	08/30/20	Qty
- R/r right rea	Right rear our window reg	door power w			Parts List	egulator	08/23/2019	Closed:	08/30/20	Qty
Problem: - R/r right rea	Right rear our window regies	door power w		Labor:	Parts List	egulator			08/30/20	Qty
Problem: - R/r right rea - Shop Suppli Workorder:	Right rear our window regies	door power w gulator. ours 1.75 Meter:		Labor:	Parts List Windor Re Shop Sup 117.25	egulator plies				Qty 1.00 1.00
Problem: - R/r right rea - Shop Suppli Workorder:	Right rear of the	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25	egulator plies Parts: n Date:	97.61	Total:	214.86	Qty 1.00 1.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem:	Right rear of the	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25	egulator plies Parts: n Date:	97.61	Total:	214.86	Qty 1.00 1.00 019
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service.	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25	egulator plies Parts: n Date:	97.61	Total:	214.86	Qty 1.00 1.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold	egulator plies Parts: n Date: Oil Filter rt 5w20	97.61	Total:	214.86	Qty 1.00 1.00 019 Qty 1.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear - Rotate and	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold Napa Qua	egulator plies Parts: n Date: Oil Filter rt 5w20 tfit-rear	97.61	Total:	214.86	Qty 1.00 1.00 019 Qty 1.00 5.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear - Rotate and	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold Napa Qua 12in Exac	egulator plies Parts: n Date: Oil Filter rt 5w20 tfit-rear tfit-beam	97.61 10/23/2019	Total:	214.86	Qty 1.00 1.00 019 Qty 1.00 5.00 1.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear - Rotate and	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold Napa Qua 12in Exac 20in Exac	egulator plies Parts: n Date: Oil Filter rt 5w20 tfit-rear tfit-beam uid Conce	97.61 10/23/2019	Total:	214.86	Qty 1.00 1.00 019 Qty 1.00 5.00 1.00 2.00 1.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear - Rotate and	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold Napa Qua 12in Exac 20in Exac Washer Fl	egulator plies Parts: n Date: Oil Filter rt 5w20 tfit-rear tfit-beam uid Conce	97.61 10/23/2019 entr	Total:	214.86	Qty 1.00 1.00 019 019 1.00 5.00 1.00 2.00
Problem: - R/r right rea - Shop Suppli Workorder: Problem: - Pm Service Service rear - Rotate and	Right rear of the street of th	door power w gulator. ours 1.75 Meter:	rindow inop	Labor:	Parts List Windor Re Shop Sup 117.25 I Parts List Napagold Napa Qua 12in Exac 20in Exac Washer Fl Napagold	egulator plies Parts: n Date: Oil Filter rt 5w20 tfit-rear tfit-beam uid Conce Air Filter Brake Clr	97.61 10/23/2019 entr	Total:	214.86	Qty 1.00 1.00 019 1.00 5.00 1.00 2.00 1.00

Workorder: Problem:	2003719 PM Service.	Meter: Check TPM	41250 S and radio	inop.		In Date:	04/14/2020	Closed:	04/30/2020		
- Pm Service.					Parts Li	st			Qty		
- Diagnose ar	nd replace bad	d radio.			Napa Q	uart 5w20			5.00		
- Replace bot	- Replace both tailgate glass shocks								1.00		
- Replace left		sure sensor	.balance an	d rotate	Washer	Fluid Conce	entr		1.00		
all.reset Tpms		20in Exa	actfit-beam			2.00					
- Service rear		12in Exa	actfit-rear			1.00					
- Shop Suppli	- Shop Supplies						Wd40 Spr				
					Tpms12	Sensor Tire	e Pr		1.00		
					Non-chl	or Brake Clr	nr		1.00		
					Lift				1.00		
					Lift				1.00		
					Radio				1.00		
					Shop Su	upplies			1.00		
	Hou :	ırs 8.50		Labor:	620.50	Parts:	565.17	Total:	1,185.67		
Workorder: Problem:	2006345 Right front w	Meter: indow inop.	41450 Left rear tire	e flat.		In Date:	06/26/2020	Closed:	06/30/2020		
- Replace righ	nt front windov	v regulator	and motor.		Parts Li	st			Qty		
- Repaired lef	t rear tire.				Windor	Regulator			1.00		
- Shop Suppli	es				Shop Su	upplies			1.00		
	Hou :	ırs 3.00		Labor:	219.00	Parts:	151.23	Total:	370.23		
Workorder: Problem:	2008506 Transition Pr	Meter: ep Charge	41450			In Date:	08/26/2020	Closed:	08/26/2020		
- Transition P	rep Charge										
	Hou :	ırs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00		