

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 234363

**Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/05/2002	Hours	Description	
- Wash Vehicle	2.90		
- Pre-Delivery Inspection			
- Make Duplicate Keys For New Vehicle			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	145.00

**Workorder:** 234701

**Problem:** 001 WASH TICKET ISSUED OUT 02/05/02

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/05/2002	Hours	Description	
- 001 Wash Ticket Issued Out 02/05/02			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	7.14

**Workorder:** 235226

**Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/22/2002	Hours	Description	
- Wash Vehicle	5.90		
- Pre-Delivery Inspection			
- Make Duplicate Keys For New Vehicle			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	295.00

**Workorder:** 235340

**Problem:** 001 WASH TICKET ISSUED OUT 02/22/02

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/22/2002	Hours	Description	
- 001 Wash Ticket Issued Out 02/22/02			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	7.14

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

Workorder: 247896

Problem: PM SERVICE

Meter Reading: 2110	Labor	Parts	
In Date: 09/16/2002	Hours	Description	Quantity
- Pm Svc	7.00	L/F PH1218 FRM PH5 WIX 51060 OIL FILTER	1.00
- Service Rear Brakes		10W30 MOTOR OIL	6.00
- Transport To Dealer For Warranty Repair Of Oil Leaks		1066 WHITE LITHIUM (CRC 05037)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	19.74	<b>Labor Charge:</b>	350.00

Workorder: 337628

Problem: PM SERVICE

Meter Reading: 5335	Labor	Parts	
In Date: 04/01/2003	Hours	Description	Quantity
- Pm	5.00	L/F PH1218 FRM PH5 WIX 51060 OIL FILTER	1.00
- Service Rear Brakes		10W30 MOTOR OIL	6.00
- Shop Supplies		AF7996 AIR FILTER USE FRM CA9269	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	40.19	<b>Labor Charge:</b>	250.00

Workorder: 349544

Problem: PM

Meter Reading: 6902	Labor	Parts	
In Date: 10/08/2003	Hours	Description	Quantity
- Pm	5.00	10020 INJECTOR CLEANER DON'T REORDER	1.00
- Svc Rear Brakes		10W30 MOTOR OIL	6.00
- Shop Supplies		AF7996 AIR FILTER USE FRM CA9269	1.00
		L/F PH1218 FRM PH5 WIX 51060 OIL FILTER	1.00
		L/F G580 FRM G7333 WIX 33484 FUEL FILTER	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	34.24	<b>Labor Charge:</b>	250.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

Workorder: 442053

Problem: P.M SERVICE

Meter Reading: 8247	Labor	Parts	
In Date: 04/21/2004	Hours	Description	Quantity
- Pm	6.00	L/F G580 FRM G7333 WIX 33484 FUEL FILTER	1.00
- Rear Brake Svc		AF7996 AIR FILTER USE FRM CA9269	1.00
- Repair Rr Tire		L/F PH1218 FRM PH5 WIX 51060 OIL FILTER	1.00
- Shop Supplies		10W30 MOTOR OIL	6.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	31.54	<b>Labor Charge:</b>	300.00

Workorder: 460955

Problem: P.M SERVICE

Meter Reading: 10822	Labor	Parts	
In Date: 11/04/2004	Hours	Description	Quantity
- Pm	5.00	10W30 MOTOR OIL	6.00
- Rear Brake Svc		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		1401 BRAKE FLUID BRAKE FLUID	1.00
		SHOP SUPPLIES	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
		09997 BRAKE CLEAN	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b>	30.83	<b>Labor Charge:</b>	250.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 544335

**Problem:** PM SERVICE,RADIO NOISE W/ ENGINE RUNNING

Meter Reading: 12363 In Date: 05/09/2005	Close Date: 05/17/2005	Labor Hours	Description	Parts	Quantity
- Pm		<b>8.40</b>	AF7996 AIR FILTER USE FRM CA9269		1.00
- Test And Replace Battery Acid Leak At Positive Terminal			05046 BATTERY PROTECTOR (CRC)		1.00
- Repair Coroded Dwiring At Battery Replace Connectors			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Rewire			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Rear Brake Svc			05023 BATTERY CLEANER		1.00
- Replace Positive Battery Cable (Starter Assy Clean Acid			78-72 BATTERY GROUP 78		1.00
Crorsion From Battery & Alt) Clean Ac Lines Starter			15371966 BATTERY CABLE		1.00
Solenoid Remove Loose Wire			10020 INJECTOR CLEANER DON'T REORDER		1.00
- Shop Supplies			G7333 FUEL FILTER LBF G580 WIX 33484		1.00
			PH5 OIL FILTER LBF PH1218 WIX 51060		1.00
			10W30 MOTOR OIL		6.00
			SHOP SUPPLIES		1.00
	<b>Parts Charge:</b> 213.33	<b>Labor Charge:</b> 420.00			

**Workorder:** 556952

**Problem:** DOOR LOCK

Meter Reading: 13529 In Date: 10/18/2005	Close Date: 12/09/2005	Labor Hours	Description	Parts	Quantity
- Install Security Locks On Rear & Side Doors; Make Up		<b>6.50</b>	1/4X3X20 ALUM FLAT BAR 6063		2.00
- Backingfor Lock Hasps			SHOP SUPPLIES		1.00
- Shop Supplies			A2000KA LOCK		1.00
			A800 LOCK HASP		1.00
	<b>Parts Charge:</b> 99.68	<b>Labor Charge:</b> 325.00			

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 559634

**Problem:** P.M SERVICE,ROOF RACK LOOSE

Meter Reading: 14772	Labor	Parts	
In Date: 12/14/2005	Hours	Description	Quantity
- Pm Service	8.30	10W30 MOTOR OIL	6.00
- Flush Transmisson		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Service Rear Brakes		AF7996 AIR FILTER USE FRM CA9269	1.00
- Remove Ladder Rack, Weld Broken Crossbar And Reinstall		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Road Test		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		G7333 FUEL FILTER LBF G580 WIX 33484	1.00
		SHOP SUPPLIES	1.00
		09997 BRAKE CLEAN	1.00
		SYN/ATF TRANS FLUID SYNTHETIC	16.00
<b>Parts Charge:</b>	115.01	<b>Labor Charge:</b>	415.00

**Workorder:** 635929

**Problem:** INSTALL KNOCKBOX

Meter Reading: 15031	Labor	Parts	
In Date: 03/17/2006	Hours	Description	Quantity
- Install Key Box Fabricate Wiring	3.50	SHOP SUPPLIES	1.00
- Shop Supplies		784603 FUSEHOLDER STANDARD ET215	1.00
<b>Parts Charge:</b>	5.41	<b>Labor Charge:</b>	175.00

**Workorder:** 641273

**Problem:** P.M SERVICE

Meter Reading: 15283	Labor	Parts	
In Date: 06/22/2006	Hours	Description	Quantity
- Pm Service	3.50	10W30 MOTOR OIL	6.00
- Shop Supplies		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
<b>Parts Charge:</b>	38.27	<b>Labor Charge:</b>	175.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 649524

**Problem:** HESITATION & SPUTTERS ON ACC

Meter Reading: 16483	Labor	Parts	
In Date: 12/05/2006	Hours	Description	Quantity
- Scan Engine Specs & Follow Diagnostics For P0300;	5.50	DIST CAP D329A	1.00
- Flush Inj & Clean Throttle Body		DIST ROTOR D465	1.00
- Replace Cap & Rotor; Clean Distributor		SHOP SUPPLIES	1.00
- Road Test Several Times			
- Shop Supplies			
<b>Parts Charge:</b>	56.44	<b>Labor Charge:</b>	27.50

**Workorder:** 732325

**Problem:** P.M.SERVICE

Meter Reading: 16641	Labor	Parts	
In Date: 01/04/2007	Hours	Description	Quantity
- Pm Service	7.00	10W30 MOTOR OIL	6.00
- Fill Tires W/Nitrogen		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Rear Brake Service		291-12 WHEEL SEAL (NATIONAL 2081)	1.00
- Replace R/R Axle Seal		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Road Test		1066 WHITE LITHIUM (CRC 05037)	1.00
- Differential Service		85/140 GEAR OIL GEAR LUBE	3.00
- Shop Supplies		09997 BRAKE CLEAN	2.00
		G7333 FUEL FILTER LBF G580 WIX 33484	1.00
		SHOP SUPPLIES	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b>	66.44	<b>Labor Charge:</b>	55.00

**Workorder:** 741370

**Problem:** P.M.SERVICE/BATTERY?

Meter Reading: 17975	Labor	Parts	
In Date: 07/12/2007	Hours	Description	Quantity
- Pm Service	4.50	10W30 MOTOR OIL	6.00
- Charge, Test & Replace Battery; Jump Start In Parking Lot		G7333 FUEL FILTER LBF G580 WIX 33484	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Service Rear Brakes		10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		GROUP 78 BATTERY (ACD 78PS)	1.00
		SHOP SUPPLIES	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
<b>Parts Charge:</b>	122.32	<b>Labor Charge:</b>	55.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 832994

**Problem:** P.M.SERVICE

<b>Meter Reading:</b> 18795		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/18/2008	<b>Close Date:</b> 01/30/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service		<b>6.50</b>	10W30 MOTOR OIL	6.00
- Rear Brake Service			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Replace 4 Tires; Mount & Balance			744395900 245/75R16 245/75R16 WRANGLER HT	4.00
- Fill Tires W/Nitrogen			G7333 FUEL FILTER LBF G580 WIX 33484	1.00
- Shop Supplies			PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
			TIRE DISPOSAL FEE	4.00
			SHOP SUPPLIES	1.00
			10020 INJECTOR CLEANER DON'T REORDER	1.00
<b>Parts Charge:</b> 648.48		<b>Labor Charge:</b> 45.00		

**Workorder:** 835092

**Problem:** HESITATES ON TAKE OFF/PULLS TO ONE SIDE

<b>Meter Reading:</b> 19327		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/05/2008	<b>Close Date:</b> 03/14/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- C/S Hesitates; Test Drive To Verify; Comp Sys		<b>8.25</b>	DIST ROTOR	1.00
Analysis-Code Po300; Major Tune-Up; Service T/B Plate;			SPARK PLUGS	8.00
Clear Code; Test Drive			IGNITION WIRES	1.00
- Test Drive To Verify Vehicle Pulls To One Side; Rotate			DIST CAP	1.00
Tiresswap Ft Brake Pads; Replate Wheel Studs & Lug			WHEEL STUDS	4.00
Nuts; Test Drive Again			SHOP SUPPLIES	1.00
- Shop Supplies			LUG NUTS	5.00
			WHEEL STUD	1.00
<b>Parts Charge:</b> 306.53		<b>Labor Charge:</b> 165.00		

**Workorder:** 843461

**Problem:** P.M.SERVICE

<b>Meter Reading:</b> 20240		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/28/2008	<b>Close Date:</b> 09/08/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service		<b>4.75</b>	G7333 FUEL FILTER LBF G580 WIX 33484	1.00
- Rear Brake Service & Adjust			SHOP SUPPLIES	1.00
- Re-Tap 2 Damaged Lug Nuts & Studs			10W30 MOTOR OIL	7.00
- Shop Supplies			6573 AIR FILTER FRM CA9269 WIX 46573	1.00
			PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
			31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b> 47.68		<b>Labor Charge:</b> 60.00		

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 935386

**Problem:** P.M.SERVICE

Meter Reading: 21099	Labor	Parts	
In Date: 03/19/2009	Hours	Description	Quantity
- Pm Service	5.00	10W30 MOTOR OIL	7.00
- Rear Brake Service		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Install New Decal		SHOP SUPPLIES	1.00
- Service, Adjust, Lube & Tighten Bolts On Ladder Rack			
- Shop Supplies			
<b>Parts Charge:</b>	24.76	<b>Labor Charge:</b>	300.00

**Workorder:** 943421

**Problem:** P.M.SERVICE

Meter Reading: 21897	Labor	Parts	
In Date: 09/18/2009	Hours	Description	Quantity
- P.M.,Service	6.75	G7333 FUEL FILTER LBF G580 WIX 33484	1.00
- Service Rear Brakes,Test Drive		09997 BRAKE CLEAN	1.00
- Service Ladder Rack		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Verified Pulls To The Right;Rotate&Balance Front Tires		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
Correct Air Pressure&Test Drive		SHOP SUPPLIES	1.00
- Shop Supplies		10W30 MOTOR OIL	7.00
<b>Parts Charge:</b>	43.68	<b>Labor Charge:</b>	405.00

**Workorder:** 1002056

**Problem:** Sputters on occasion & feels like shutting off at times.

Meter Reading: 22359	Labor	Parts	
In Date: 02/26/2010	Hours	Description	Quantity
- Check Charging System. R&R Battery.	3.25	SHOP SUPPLIES	1.00
- C/S Sputter On Occasion, Verify. Test Drive, Scan For Codes & Perform Fuel System Test. Clean Fuel System.		GROUP 78 BATTERY (ACD 78PS)	1.00
- Shop Supplies			
<b>Parts Charge:</b>	99.99	<b>Labor Charge:</b>	195.00



2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1003050

**Problem:** P.M.SERVICE

Meter Reading: 22386 In Date: 03/25/2010	Close Date: 03/31/2010	Labor Hours	Description	Parts	Quantity
- P. M.		8.50	6573 AIR FILTER FRM CA9269 WIX 46573		1.00
- Rear Brake Service			G7333 FUEL FILTER LBF G580 WIX 33484		1.00
- R&R Belt.			10W30 MOTOR OIL		7.00
- Installed Driving Sticker.			PH5 OIL FILTER LBF PH1218 WIX 51060		1.00
- Repaired Socket Wiring To Frt Running Light.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- R&R Wheel Stud			SERPENTINE BELT		1.00
- Repaired Connections To Reisor For All Blower Speeds.			SHOP SUPPLIES		1.00
- Shop Supplies			09997 BRAKE CLEAN		1.00
<b>Parts Charge:</b> 89.55		<b>Labor Charge:</b> 510.00			

**Workorder:** 1003803

**Problem:** NO POWER AND HESITATES

Meter Reading: 22402 In Date: 04/13/2010	Close Date: 04/26/2010	Labor Hours	Description	Parts	Quantity
- C/S: Hesitates, Verify. Perform Pinpoint Test & Found Corrosion In Cap. Replace Cap & Rotor, Fuel Filter.		8.25	G7333 FUEL FILTER LBF G580 WIX 33484		1.00
			DIST. ROTER		1.00
- C/S: Hesitates, Scan For Codes, Perform Pinpoint Test & Found Bad Fuel Pump. Drain Fuel Tank, Replace Fuel Pump Assy & Test Drive.			FUEL PUMP ASSY.		1.00
			DIST. CAP		1.00
			SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b> 672.44		<b>Labor Charge:</b> 495.00			

**Workorder:** 1010537

**Problem:** P. M. SERVICE

Meter Reading: 23592 In Date: 09/24/2010	Close Date: 09/29/2010	Labor Hours	Description	Parts	Quantity
- P. M. Service.		4.75	31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Check Ladder Rack. Tighten All Fastening Bolts.			PH5 OIL FILTER LBF PH1218 WIX 51060		1.00
- Rear Brake Drum Service, Adjust Shoes.			L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC		1.00
- Shop Supplies			10W30 MOTOR OIL		7.00
			SHOP SUPPLIES		1.00
			09997 BRAKE CLEAN		1.00
<b>Parts Charge:</b> 52.54		<b>Labor Charge:</b> 285.00			

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1102916

**Problem:** P. M. SERVICE

Meter Reading: 24040 In Date: 03/17/2011	Close Date: 03/22/2011	Labor Hours	Parts Description	Quantity
- P. M. Service.		<b>6.75</b>	PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Clean & Adjust Rear Brakes.			SHOP SUPPLIES	1.00
- C/S: A/C Not Cool. Verify Concern. Evacuate, Charge, Add Uv Dye, Check For Leaks & Was Unable To Find Leak At This Time.			10W30 MOTOR OIL	7.00
			09997 BRAKE CLEAN	1.00
- Service Ladder Rack.			G7333 FUEL FILTER LBF G580 WIX 33484	1.00
			E8 A/C OIL R134A A/C OIL (TSI)	1.00
- Shop Supplies			R134A REFRIGERANT	3.00
<b>Parts Charge:</b>		53.36	<b>Labor Charge:</b> 405.00	

**Workorder:** 1104085

**Problem:** No power, sluggish

Meter Reading: 24067 In Date: 04/14/2011	Close Date: 04/20/2011	Labor Hours	Parts Description	Quantity
- C/S: No Power, Sluggish. Test Drive, Verify. Scan, Found Code # P0300, Perform Pinpoint Test & Found Bad Cap. Remove Engine Covers, Air Filter Housing & Replace Cap, Rotor, Wires, Plugs. Clear Codes..		<b>6.50</b>	SHOP SUPPLIES	1.00
			DIST. CAP	1.00
			IGN. WIRES	1.00
			DIST. ROTOR	1.00
- Shop Supplies			SPARK PLUGS	8.00
<b>Parts Charge:</b>		175.60	<b>Labor Charge:</b> 390.00	

**Workorder:** 1109848

**Problem:** P. M. SERVICE

Meter Reading: 25071 In Date: 09/14/2011	Close Date: 09/20/2011	Labor Hours	Parts Description	Quantity
- Performed P.M.		<b>9.25</b>	10W30 MOTOR OIL	7.00
- Rear Brake Service.			61A P/STEERING FLUID	1.00
- Rear Center Brake Out. R&R Bulb And Repair Socket.			31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Passenger Side Window Hard Operation. Removed Panel & Adjusted Track & Lubed Regulator & Reassembled.			6573 AIR FILTER FRM CA9269 WIX 46573	1.00
			USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
- Retightened Roof Rack.			PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
- Removed Pump Pressure Line. Removed Valve Assy, R&R O-Ring And Reassembled & Tested. Ok.			SHOP SUPPLIES	1.00
			09997 BRAKE CLEAN	1.00
- Shop Supplies				
<b>Parts Charge:</b>		62.71	<b>Labor Charge:</b> 555.00	

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1110409

**Problem:** PULLING TO THE RIGHT

Meter Reading: 25175	Labor	Parts	
In Date: 09/29/2011	Hours	Description	Quantity
- Balance & Rotate Tires. Test Drive With Driver.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	120.00

**Workorder:** 1202492

**Problem:** P M Service

Meter Reading: 27637	Labor	Parts	
In Date: 03/13/2012	Hours	Description	Quantity
- Pm Service	10.00	1401 BRAKE FLUID BRAKE FLUID	2.00
- Resurface Rear Drum, Replace Wheel Cylinder And Brake Shoes		REAR BRAKE SHOE	1.00
		REAR WHEEL CYLINDERS	2.00
- Adjust And Thighen Ladder Rack		SHOP SUPPLIES	1.00
- Shop Supplies		09997 BRAKE CLEAN	1.00
		PH5 OIL FILTER LBF PH1218 WIX 51060	1.00
		G7333 FUEL FILTER LBF G580 WIX 33484	1.00
		10W30 MOTOR OIL	7.00
<b>Parts Charge:</b>	325.71	<b>Labor Charge:</b>	600.00

**Workorder:** 1204214

**Problem:** replace spot mirrors

Meter Reading: 28834	Labor	Parts	
In Date: 05/03/2012	Hours	Description	Quantity
- Clean Both Rear View Mirror And Install 2 New Spot Mirrors	1.00	SHOP SUPPLIES	1.00
		7039D SPOT MIRROR VELVAC 723060	2.00
- Shop Supplies			
<b>Parts Charge:</b>	7.13	<b>Labor Charge:</b>	60.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1211440

**Problem:** pm, temp get high

Meter Reading: 32592	Labor	Parts	
In Date: 11/28/2012	Hours	Description	Quantity
- Pm	7.75	SHOP SUPPLIES	1.00
- Ck Tmp Gauge Rises Inspect Cooling Sys Pressure Test		H-DUTY A-FREEZE EXT-L	1.00
Drain Coolant Add New Coolant Test Drive		PH5 OIL FILTER LBF PH	1.00
- Service Rear Brake Drum System		31-22 WIPER BLADES 22	2.00
- Inspect Ladder Rack Tighten Bolts Lube		10W30 BULK SR	7.00
- Test Drive After Coolant Service For 1.0			
- Shop Supplies			
<b>Parts Charge:</b> 66.71		<b>Labor Charge:</b> 465.00	

**Workorder:** 1211917

**Problem:** VEHICLE HESITATES WHEN DRIVING

Meter Reading: 32669	Labor	Parts	
In Date: 12/10/2012	Hours	Description	Quantity
- Ck Veicle Hestates Test Drive Verify Concern Scan And Found Code Po300 Remove Enginte Covers Perform	4.00	D465 IGNITION ROTOR A	1.00
Pinpoin Test And Found Corrosion In Cap Replace Cap		SHOP SUPPLIES	1.00
Rotors Fuel Filter Clear Coeds And Test Drive		D329A IGN CAP ACD	1.00
- Shop Supplies		G7333 FUEL FILTER LBF	1.00
<b>Parts Charge:</b> 71.92		<b>Labor Charge:</b> 240.00	

**Workorder:** 1304468

**Problem:** low coolant

Meter Reading: 33398	Labor	Parts	
In Date: 05/06/2013	Hours	Description	Quantity
- Ck Low Coolant Ck And Found Rad Is Full Of Coolant But Over Flow Bottle Was Low Fill Bottle And Pressure Test Fund No Leak At This Time	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1307430

**Problem:** pm, truck sputters

Meter Reading: 33926	Labor	Parts	Quantity
In Date: 07/25/2013	Hours	Description	Quantity
- Pm	<b>14.25</b>	BRAKE CLEANER	1.00
- Clean And Adj Rear Brakes		SYN-ATF TRANS FLUID S	12.00
- Flush Transmission Replace Leaking Pand Gasket And		744395900 245-75R16	4.00
Test Drive		FT1203 TRANS FILTER L	1.00
- Replace 4 Tires		DISTRIBUTOR CAP	1.00
- Ck Truck Sputters Verify Concern Scan Found Code		SHOP SUPPLIES	1.00
Po300 Remove Engine Covers Perform Pinpoint Test And		D465 IGNITION ROTOR A	1.00
Found Corrosion In Cap Replace Cap Rotor Clear Codes		NAPAGOLD FUEL FILTER	1.00
And Test Drive		TIRE DISPOSAL FEE	4.00
- Svc Ladder Rack		PH5 OIL FILTER LBF PH	1.00
- Fill Tires With Nitrogen		WIPER BLADE	2.00
- Shop Supplies		10W30 BULK SR	7.00
		NAPAGOLD AIR FILTER	1.00
		SYN ATF BULK SOUTH	12.00
<b>Parts Charge:</b>	1,187.12	<b>Labor Charge:</b>	855.00

**Workorder:** 1401616

**Problem:** pm,

Meter Reading: 34702	Labor	Parts	Quantity
In Date: 02/19/2014	Hours	Description	Quantity
- Pm	<b>5.50</b>	SHOP SUPPLIES	1.00
- Svc Rear Brake Drums		GROUP 78 BATTERY	1.00
- Inspect Ladder Rack Tighten		NAPAGOLD FUEL FILTER	1.00
- Verify Battery Weak Recharge And Test Battery Replace		NAPAGOLD OIL FILTER	1.00
Battery Ck Charging Sys		10W30 BULK SR	7.00
- Shop Supplies			
<b>Parts Charge:</b>	129.36	<b>Labor Charge:</b>	330.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1402316

**Problem:** remove knox box froimt 10139383 and install in 10164706

Meter Reading: 34755	Labor	Parts	
In Date: 03/07/2014	Hours	Description	Quantity
- Remove Knox Box From 10139383 Fabricate Bracket And Install Know Box To Asset 10164706	3.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	180.00

**Workorder:** 1407234

**Problem:** temp gauge heating hight ck gauge

Meter Reading: 36715	Labor	Parts	
In Date: 07/23/2014	Hours	Description	Quantity
- C/S Ck Temp Gauge &Overheating. Veryfy Concern,Pressure Test System,Found Leaking Thermostat Housing.R&R Thermostat&Housing,Flush System.	5.50	PEAK GLOBAL Water Outlet SHOP SUPPLIES THERMOSTAT	2.00 1.00 1.00 1.00
- Test Drive Before&After Repair.			
- Shop Supplies			
<b>Parts Charge:</b>	55.58	<b>Labor Charge:</b>	330.00

**Workorder:** 1408016

**Problem:** pm

Meter Reading: 36715	Labor	Parts	
In Date: 08/13/2014	Hours	Description	Quantity
- Pm	4.75	BRAKE CLEANER	1.00
- Clean And Adj Rear Brakes		SHOP SUPPLIES	1.00
- Svc Ladder Rack		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		10W30 BULK SR	7.00
		NAPAGOLD AIR FILTER	1.00
		WASHER FL	1.00
		WIPER BLADE	2.00
<b>Parts Charge:</b>	50.51	<b>Labor Charge:</b>	285.00

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1503066

**Problem:** pm

<b>Meter Reading:</b> 38053		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/25/2015	<b>Close Date:</b> 03/31/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>5.75</b>	NAPAGOLD OIL FILTER		1.00
- Clean And Adj Rear Brakes			WASHER FL		1.00
- Svc Ladder Rack			DRAIN PLUG		1.00
- Repair Horn			WIPER BLADE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
			10W30 BULK SR		7.00
<b>Parts Charge:</b> 42.40		<b>Labor Charge:</b> 345.00			

**Workorder:** 1510080

**Problem:** pm

<b>Meter Reading:</b> 41735		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/05/2015	<b>Close Date:</b> 10/20/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Pm		<b>4.75</b>	WASHER FLUID CONCENTR		1.00
- Rear Brake Drum Svc			NAPAGOLD FUEL FILTER		1.00
- Ladder Rack Svc			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			10W30 BULK SR		7.00
<b>Parts Charge:</b> 35.49		<b>Labor Charge:</b> 285.00			

**Workorder:** 1512957

**Problem:** A/C STUCK ON HIGH/CHECK ENGINE LIGHT COMES ON

<b>Meter Reading:</b> 42722		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/23/2015	<b>Close Date:</b> 01/22/2016	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Ck Ac Stuck On High Perform Pin Point Test Fund Bad		<b>9.25</b>	PEAK GLOBAL		2.00
Blower Motor Resistor Replace Blower Motor Resistor			SHOP SUPPLIES		1.00
- Ck Engine Light On Can Found No Codes Test Drive			BLOWER MOTOR RESISTOR		1.00
Found Vehicl Over Heating Perform Cooling Sys Pressure			Radiator Cap		1.00
Test Found Leaking Intake Remove Alternator Ac					
Comperssor Power Steering Pump And Bracket Torque					
- Test Drive Before And After Repair					
- Shop Supplies					
<b>Parts Charge:</b> 70.07		<b>Labor Charge:</b> 555.00			

2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1604206

**Problem:** Pm service.

<b>Meter Reading:</b> 43846	<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 04/21/2016	<b>Hours</b>	<b>Description</b>
<b>Close Date:</b> 04/29/2016		<b>Quantity</b>
- Pm Service.	<b>4.75</b>	10W30 BULK SR 7.00
- Clean And Service Rear Brakes.		22" WIPER BLADE 2.00
- Service Ladder Rack.		NAPAGOLD AIR FILTER 1.00
- Shop Supplies		WASHER FLUID CONCENTR 1.00
		SHOP SUPPLIES 1.00
		BRAKE CLEANER 1.00
		NAPAGOLD OIL FILTER 1.00
<b>Parts Charge:</b> 48.30	<b>Labor Charge:</b> 285.00	

**Workorder:** 1606145

**Problem:** Bad battery.Has to jump start.

<b>Meter Reading:</b> 44678	<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 06/15/2016	<b>Hours</b>	<b>Description</b>
<b>Close Date:</b> 06/27/2016		<b>Quantity</b>
- Test Starting And Charging System.Battery Failed	<b>1.00</b>	SHOP SUPPLIES 1.00
- Loadtest After Recharge.Replace Defective Battery.		GROUP 78 BATTERY 1.00
- Shop Supplies		
<b>Parts Charge:</b> 100.79	<b>Labor Charge:</b> 60.00	



2/6/2017  
2:41:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139383 2002 GMC 3500 Van, 1 Ton, Cargo, No Glass

**Workorder:** 1610624

**Problem:** Pm Service.Right rear tire wobble.Fuel odor.

Meter Reading: 46820 In Date: 10/14/2016	Close Date: 11/14/2016	Labor Hours	Description	Parts	Quantity
- Pm Service		<b>19.00</b>	SHOP SUPPLIES		1.00
- Clean And Adjust Rear Brakes.Resurface Front Brake Rotors,Service Calipers And Replace Brake Pads.			TIRE DISPOSAL FEE		4.00
- Flush Cooling System.Replace Leaking Radiator,Thermostat And Gasket.			OIL COOLER HOSE		1.00
- Replace 4 Tires.			NAPAGOLD FUEL FILTER		1.00
- Replace Leaking Oil Cooler Hoses.			22" WIPER BLADE		2.00
- Service Ladder Rack.			WASHER FLUID CONCENTR		1.00
- Test Drive Before And After Repairs.			RADIADOR CAP A/C DELCO		1.00
- C/C Vehicle Has Fuel Odor.Check Over Vehicle And Was Unable To Verify Fuel Odor At This Time.			PEAK GLOBAL ANTIFRZ		2.00
- Fill All Tires With Nitrogen.			744395900 245-75R16		4.00
- Shop Supplies			THERMOSTAT		1.00
			OILCOOLER HOSE		1.00
			FRONT BRAKE PAD A/C DELCO		1.00
			NAPA RADIATOR		1.00
			RADIADOR		1.00
			10W30 BULK SR		7.00
			NON-CHLOR BRAKE CLNR		1.00
			NAPAGOLD OIL FILTER		1.00
	<b>Parts Charge:</b> 1,207.20	<b>Labor Charge:</b> 1,140.00			

**Workorder:** 1701011

**Problem:** Transition Prep Charge

Meter Reading: 48502 In Date: 01/31/2017	Close Date: 01/31/2017	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		<b>2.00</b>			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 120.00			

Total Parts Charges:	<b>6,555.05</b>	Total Labor Charges:	<b>13,612.50</b>	Total Comm. Charges:	<b>14.28</b>
----------------------	-----------------	----------------------	------------------	----------------------	--------------