First		55345 Palr	n Tran Connection v 2.2 ge 1 of 9	m WorkOrder: 513390 Invoice Number: 55345-				39044
Client Departme MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warra		55345M RGASPARD RGASPARD WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champic 1FDEE3FL1FDA027 40 1		i		
Reported Started Completed	Down Time	Chronology Jun 1, 2018 Jun 3, 2018 Jun 3, 2018	3	1:46 PM 12:50 PM System 1	eading         UOM           DH         DH           85,575         DH           85,725         DH			
Line Comment 10 COMPLAINT: CAUSE: CORRECTION:			WorkOrder Note	25				
Activity: 10 Activity Note: Reason for Repa Work Accomplis Part Failure:	Light Mediur	n Duty PMI ive Maintenance	Activity Comments	3				
Parts Issued	Part Number			Description		Qty.	Each	Extended
Lahar Baata								
Labor Poste	0	-			Hours	Ra	ite	Extended
	Owens,Arthur				1.00		0.00	0.00
				Activi Parts: Labor: Labor Hours: 1.00 Sublet Parts: Sublet Labor: Activity Sub Total	ity 10 Sul	o Tota	al	0.00 0.00 0.00 <u>0.00</u> <b>0.00</b>
Activity: 20 Activity Note: Reason for Repa Work Accomplis Part Failure:	PM A	ive Maintenance	Activity Comments					
Parts Issued			•					
Date	Part Number			Description		Qty.	Each	Extended
03-Jun-18	B329(F)	FILTE	R, OIL SAME AS LF3681			1.00	1.96	1.96

Firs		S C 7 Transit	5534	WorkOrder 5 Palm Tran Conn v 2.2 Page 2 of 9	nection		<b>1339044</b> 55345-51339044		
Client Depa MRC: WO Desc: PM A Requested Created By Class: Arrangeme Potential W	By: : nt:	R R W	5345M GASPARD GGASPARD /O nassigned o	Driver:	nt:	5450 Ford E350 Champior 1FDEE3FL1FDA0275 40 1	n Crusaders	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	55011
Labor Po	sted								
Date				Technician			Hours	Rate	Extended
03-Jun-18	Owens,Ar	thur					1.50	0.00	0.00
						Activit Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor: Activity Sub Total	y 20 Sub	Total	1.96 0.00 0.00 0.00 <b>1.96</b>
Part Failure Parts Iss Date	sued	Part Number		Activity Co		cription		Qty. Each	Extended
Labor Po	sted								
Date				Technician			Hours	Rate	Extended
03-Jun-18	Owens,Ar	thur					0.05	0.00	0.00
						Activit Parts: Labor: Labor Hours: 0.05 Sublet Parts: Sublet Labor: Activity Sub Total	y 30 Sub	Total	0.00 0.00 0.00 0.00 <b>0.00</b>
				L S	Parts: Labor: Labor Hou Sublet Parts Sublet Labo	:	044 Gran	d Total	1.96 0.00 0.00 <u>0.00</u> <b>1.96</b>
Recent Rep									
WorkOrder	Date Completed	Life Meter	Class			Description			
51339044	3-Jun-18	185,575	WO	PM A					
		185,265	WO	55345 SPARK PL	LIC CAS BLISS	FC			

First Base			WorkOrder 55345 Palm Tran Connection v 2.2 Page 3 of 9			WorkOrder: <b>51339044</b> Invoice Number: 55345-51339044					
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warranty:			55345M RGASPARD RGASPARD WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:		5450 Ford E350 Champion Crusaders 1FDEE3FL1FDA02752 40 1					
WorkOrder	Date Completed	Life Meter	Class			Descr	iption				
51259141	10-May-18	181,629	WO	PM A							
Scheduled I	Preventativ	e Maintena	ance		-	-					
Nest		PM	WorkOrd	er	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2		
Other Open	Repairs										
WorkOrder8	Date Reported	Life Meter	Class	Description							
51372014	24-May-18	184,168	WO	Transmission code PO 751							
51144053	28-Mar-18	172,949	WO	Front Brakes							
51079999	7-Mar-18	169,025	WO	Needs	4 rear tires						

# LH: 10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: AOWENS Performed on: 03-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		AOWENS	Jun 3, 2018 12:43:28 PM	No	
10,100	Safety Inspection	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		AOWENS	Jun 3, 2018 12:43:28 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,140	Check Service Brakes	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,160	FRA Check Instruments and Horns	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,170	Check Fast Idle	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,180	Check Starter Protection Circuit	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
10,190	Check Reverse Warning System	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,100	Check Parking Brake	Done		AOWENS	Jun 3, 2018 12:43:29 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,140	Road Test: Check for Proper Operation	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,150	Perform Brake Test	Done		AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,152	Decelerometer Results Test 1	FEET	N/a	AOWENS	Jun 3, 2018 12:43:30 PM	No	
11,154	Decelerometer Results Test 2	FEET	n/a	AOWENS	Jun 3, 2018 12:43:31 PM	No	
11,156	Decelerometer Results Test 3	FEET	n/a	AOWENS	Jun 3, 2018 12:43:31 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	AOWENS	Jun 3, 2018 12:43:31 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	AOWENS	Jun 3, 2018 12:43:31 PM	No	
11,170	FRA Check Door Operation	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,230	FRA Check Wiring Under Dash	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,240	FRA Check Interior Lights	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		AOWENS	Jun 3, 2018 12:43:31 PM	No	
20,260	Check Stop Request System	-	n/a	AOWENS	Jun 3, 2018 12:43:32 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	n/a	AOWENS	Jun 3, 2018 12:43:32 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		AOWENS	Jun 3, 2018 12:43:32 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		AOWENS	Jun 3, 2018 12:43:32 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		AOWENS	Jun 3, 2018 12:43:32 PM	No	
22,110	Check Emergency Hatches	Done		AOWENS	Jun 3, 2018 12:43:32 PM	No	
22,120	Check All Safety Equipment	Done		AOWENS	Jun 3, 2018 12:43:32 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,310	Check Passenger Doors	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,330	Check Wheelchair Lift Operation	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	n/a	AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,360	Check for Physical Damage and Decals	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		AOWENS	Jun 3, 2018 12:43:33 PM	No	
30,380	Check Exterior Compartment Doors	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
33,100	Check Lights and Reflectors	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,420	Check Hood	Done		AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		AOWENS	Jun 3, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					12:43:34 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	n/a	AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,442	Freeze Point	Degree Fahrenheit	n/a	AOWENS	Jun 3, 2018 12:43:34 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	n/a	AOWENS	Jun 3, 2018 12:43:35 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,130	FRA Check Exhaust System	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,140	FRA Check Intake System	Done		AOWENS	Jun 3, 2018 12:43:35 PM	No	
44,150	FRA Inspect Turbocharger	-	n/a	AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,180	FRA Check for Leaks	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,190	FRA Perform Battery Inspection	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
50,510	Check Entire Steering System	Done		AOWENS	Jun 3, 2018 12:43:36 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,610	FRA Check and Record Air Pressure	Done		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,620	Check Valve Stems and Caps	Done		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,630	Check and Record Tread Depth	Done		AOWENS	Jun 3, 2018 12:43:37 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,632	Tread Depth LF	6 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,650	Check Sidewall Wear	Done		AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,660	Inspect for Cuts and Tears	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
60,670	Check Dual Mating With Square	-	n/a	AOWENS	Jun 3, 2018 12:43:38 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		AOWENS	Jun 3, 2018 12:43:38 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,710	Check Vibration Damper	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,720	Check Engine and Transmission Mounts	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,730	FRA Check Starter	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,750	FRA Check Transmission for Leaks	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
70,770	FRA Check Exhaust System	Done		AOWENS	Jun 3, 2018 12:43:39 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		AOWENS	Jun 3, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					12:43:40 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,110	FRA Check Fuel Tank	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,120	Check Suspension Components	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,131	Brake Pad Thickness LF	7 Inch		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,132	Brake Pad Thickness RF	7 Inch		AOWENS	Jun 3, 2018 12:43:40 PM	No	
77,133	Brake Pad Thickness LR	4 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,134	Brake Pad Thickness RR	4 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,135	Brake Rotor LF	1.553 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,136	Brake Rotor RF	1.554 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,137	Brake Rotor LR	1.415 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,138	Brake Rotor RR	1.416 Inch		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,140	FRA Check Brake Hoses	Done		AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,150	Check King Pins	-	n/aa	AOWENS	Jun 3, 2018 12:43:41 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		AOWENS	Jun 3, 2018 12:43:41 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		AOWENS	Jun 3, 2018 12:43:41 PM	No	
80,810	Completion of PMI Report	Done		AOWENS	Jun 3, 2018 12:43:41 PM	No	
90,000	SECTION 9 Completion of PMI	Done		AOWENS	Jun 3, 2018 12:43:42 PM	No	
90,910	Vehicle Returned to predetermined location	Done		AOWENS	Jun 3, 2018 12:43:42 PM	No	

# LH: 20 Desc: PM A Task: PM A SERVICE Performed by: AOWENS Performed on: 03-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		AOWENS	Jun 3, 2018 12:04:40 PM	No	
101,000	FRA Change Oil Filters	Yes		AOWENS	Jun 3, 2018 12:04:40 PM	No	
102,000	FRA Drain Engine Oil	Yes		AOWENS	Jun 3, 2018 12:04:40 PM	No	
103,000	FRA Check Transmission Fluid	Done		AOWENS	Jun 3, 2018 12:04:40 PM	No	
104,000	Lubricate Chassis	Done		AOWENS	Jun 3, 2018 12:04:40 PM	No	
105,000	Replace or Clean A/C Filters	Done		AOWENS	Jun 3, 2018 12:04:40 PM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	AOWENS	Jun 3, 2018 12:04:40 PM	No	
108,000	Lube all pivoting Mechanisms	Done		AOWENS	Jun 3, 2018 12:04:40 PM	No	

### LH: 30 Desc: PRAMETER

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 3, 2018 12:03:21 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

		55345 Pa	<b>/orkOrder</b> Im Tran Connection v 2.2 Vage 1 of 9		WorkOrder: 51 e Number: 5		174398
Client Departn MRC:	nent:	55345M	Equipment:	5450			
WO Desc:				Ford E350 Cha	mpion Crusaders		
PM A Requested By:		CKARLENS	VIN: Status:	1FDEE3FL1FD/ 40	402752		
Created By:		CKARLENS	Priority:	1			
Class: Arrangement:		WO Unassigned	Driver: Phone:	<u>b</u>			
Potential Warr	anty:	No	ETA:				
		Chronology				1	
Reported Started		Jul 27, 20 Jul 27, 20		12:32 PM Met	er Reading UOM DH		
Completed		Jul 27, 20		11:23 PM Life	194,069 DH		
	Down Time	)			125 (1005   211		
Line	Comment		WorkOrder No	tes			
10 COMPLAINT:							
CAUSE: Serv							
	I: Performed and comple ed engine oil and replaced						
[							
Reason for Re Work Accompl Part Failure:	ished: A - PM Level	ive Maintenance A	Activity Commen	Its			
Date	Part Number			Description		Qty. Each	Extended
La sul constanti de la sul cons							Transfer 1
Labor Post	ed						
Date			Technician		Hours	Rate	Extended
27-Jul-18	Delva,Terry			2	0.43	0.00	0.00
				A Parts: Labor: Labor Hours: Sublet Parts: Sublet Labor: Activity Sub T		Total	0.00 0.00 0.00 0.00 <b>0.00</b>
Activity: 20 Activity Note: Reason for Rep Work Accompl Part Failure:	PM A	ive Maintenance					
			Activity Commen	ts			
Parts Issue	1	1					
Date	Part Number			Description		Qty. Each	Extended
27-Jul-18	B329(F)	FILT	ER, OIL SAME AS LF368	31		1.00 1.96	1.96

First	<sup>by</sup> First 7 Transit	55345 Pa	VorkOrder Im Tran Connection v 2.2 age 1 of 9	Wor Invoice N	kOrder: 517 umber: 55		728606
Client Departm MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warr		55345M AOWENS AOWENS WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champio 1FDEE3FL1FDA027 40 1			
Reported Started Completed		Chronology Oct 10, 20 Oct 10, 20 Oct 10, 20 Oct 11, 20	18	12.00 AN1 WO	eading UOM DH 07,718 DH		
	Down Time	8	WorkOrder Notes				
Line	Comment	1	workurger note:				
10 COMPLAINT:							
CAUSE:Servi							
CORRECTION Oil filter B32	N:Perform pmA Service 9 Qty1						
Engine oil 5v	v20 qty 7 Qts						
Reason for Re Work Accomp		m Duty PMI tive Maintenance					
Work Accomp Part Failure:	lished: A - PM Leve	tive Maintenance	Activity Comments				
Work Accomp Part Failure:	lished: A - PM Leve	tive Maintenance		Description		Oty, Each	1 Extended
Work Accompl Part Failure: Parts Issue Date	Part Number	tive Maintenance		Description		Qty. Each	h Extended
Work Accompl Part Failure: Parts Issue Date	Part Number	I A		Description	Hours	Qty. Each	h Extended
Work Accompl Part Failure: Parts Issue Date Labor Poste	Part Number	I A		Description	1		Extended
Work Accompl Part Failure: Parts Issue Date Labor Poste	Part Number	I A		Activit Parts: Labor: Labor Hours: 1.57 Sublet Parts: Sublet Labor:	Hours	Rate 0.00	Extended 0 0.00 0.00 0.00 0.00 0.00
Work Accompl Part Failure: Date Date Date 10-Oct-18	ed Gaspard,Ronald 999 TOTAL V PM A	/EHICLE		Activit Parts: Labor: Labor Hours: 1.57 Sublet Parts:	Hours	Rate 0.00	Extended 0 0.00 0.00 0.00 0.00 0.00
Work Accompl Part Failure: Parts Issue Date Labor Poste 10-Oct-18	ed Part Number ed Gaspard,Ronald 999 TOTAL V PM A pair: 08 - Prevent ished: A - PM Level	/EHICLE		Activit Parts: Labor: Labor Hours: 1.57 Sublet Parts: Sublet Labor:	Hours	Rate 0.00	Extended
Work Accompl Part Failure: Date Date Date 10-Oct-18	ed Part Number ed Gaspard,Ronald Gaspard,Ronald PM A pair: 08 - Prevent ished: A - PM Level	/EHICLE	Technician	Activit Parts: Labor: Labor Hours: 1.57 Sublet Parts: Sublet Labor:	Hours	Rate 0.00	Extended 0 0.00 0.00 0.00 0.00 0.00
Work Accompl Part Failure: Date Date Labor Poste Date 10-Oct-18	ed Part Number ed Gaspard,Ronald Gaspard,Ronald PM A pair: 08 - Prevent ished: A - PM Level	/EHICLE	Technician Activity Comments	Activit Parts: Labor: Labor Hours: 1.57 Sublet Parts: Sublet Labor:	Hours 1.57	Rate 0.00	Extended 0 0.00 0.00 0.00 0.00 0.00 0.00

Firs		55345 Pa	Im Tran Connection v 2.2 age 1 of 9	WorkOrder: <b>51802535</b> Invoice Number: 55345-51802535			
Client Depart MRC:	tment:	55345M	Equipment:	5450			
WO Desc:		555 1511	Equipmenti	Ford E350 Champion	Crusaders	5	
PM A			VIN:	1FDEE3FL1FDA02752			
Requested By	y:	RGASPARD	Status:	32			
Created By: Class:		RGASPARD WO	Priority: Driver:	1			
Arrangement	:	Unassigned	Phone:				
<b>Potential Wa</b>	rranty:	No	ETA:				
	Cl	ronology					
Reported		Nov 2, 2018	10:01 AM	Meter Reading UOM			
Started		Nov 4, 2018	7.47.84	WO DH			
Completed	Down Time	Nov 4, 2018	7:47 PM	Life 211,902 DH			
L	Down Hille		WorkOrder Notes				
Line		Comn					
10 COMPLAIN	T: PMA Service						
CALICE: Co	n in Due he Miles es						
CAUSE: Se	rvice Due by Mileage.						
Activity: <b>10</b> Activity Note Reason for R Work Accomp Part Failure:		lium Duty PMI entive Maintenance					
i ure i unurei			Activity Comments				
Parts Issu	od		Heavily comments				
Date	Part Numbe		2	- della	terra and	Oh: Fash	Constant of
Date	Part Numbe	a	De	scription		Qty. Each	Extended
Labor Pos	4						
	tea			A CONTRACTOR OF THE OWNER			
Date			Technician		Hours	Rate	Extended
04-Nov-18	Arthurs, Durvin				1.50	0.00	0.00
				Activity Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor: Activity Sub Total	10 Sul	b Total	0.00 0.00 0.00 0.00 <b>0.00</b>
III IIII							
Activity: 20 Activity Note Reason for Re Work Accomp Part Failure:	PM A	ntive Maintenance					
			Activity Comments				
Parts Issu	ed						

	<b>irst</b>	ev First 🎓 Transit	553	Work0 845 Palm Tra v 2.3 Page 1	n Connection 2	In	_	kOrder: 51		68636
MRC WO I PM A Requ Crea Class Arra	: Desc: uested By: ited By:		55345M DARTHUR DARTHUR WO Unassigne No	VI S Sta S Pri Dri	atus: ority: iver: one:		0 Champioi L1FDA0275	n Crusaders 2		
Star	orted ted ipleted	Down Time	Dec 2 Dec 2	28, 2018 28, 2018 28, 2018		12:58 PM 11:37 PM	WO Life 22	eading UOM DH 20,068 DH 20,222 DH		
Line		Comment		Wo	rkOrder Notes					
10	COMPLAINT: CAUSE: Servi CORRECTION Oil filter B329 Engine oil 5w	ce I:perform PmA Service 9 Qty1								
Activ Reas Wor	vity Note: son for Re	999 TOTAL Light Mediu pair: 08 - Prevent ished: A - PM Leve	m Duty PM tive Mainter	nance	ivity Comments					
Par	ts Issue	d								
	Date	Part Number			Des	scription			Qty. Each	Extended
Lab	or Poste	ed								
	Date			Technic	ian			Hours	Rate	Extended
2	28-Dec-18	Gaspard,Ronald						1.57	0.00	0.00
	ity: 20 vity Note:	<b>999 TOTAL</b> PM A	VEHICLE			Sublet Par Sublet Lat	ours: 1.57 ts:	y 10 Sub	o Total	0.00 0.00 0.00 <u>0.00</u> <b>0.00</b>
Rea: Wor	son for Re k Accompl	pair: 08 - Prevent ished: A - PM Leve		nance						
Part	Failure:	-								
Par	ts Issue	d		Act	ivity Comments					

First Base	55345 Pal	orkOrder m Tran Connection v 2.2 age 1 of 9	WorkOrder: <b>52031582</b> Invoice Number: 55345-52031582
Client Department: MRC: WO Desc: PM A Requested By: Created By:	55345M RGASPARD RGASPARD	Equipment: VIN: Status: Priority:	5450 Ford E350 Champion Crusaders 1FDEE3FL1FDA02752 40 1
Class: Arrangement: Potential Warranty:	WO Unassigned No	Driver: Phone: ETA:	<u>.</u>
Reported Started Completed	Chronology Jan 23, 2019 Jan 23, 2019 Jan 23, 2019	1:01 PN 10:59 PN	Life 223,996 DH
Down Time	3		System 224,168 DH
Line	Commen	WorkOrder Notes	
10 COMPLAINT: PMA Service		Men engitteet da ben a subscription autoria agus	ng basis (California) and an
CAUSE: Service Due by Mileage.			
CORRECTION: Change Oil& Filter Parts# B329 Qty (1) Oil 5W20QTY Qty (6.5) Qt	. Lube all Pivoting Points .	check Brakes. Replace . A/C	C Filter. Clean batteries.
Activity Note: Light Me		Activity Comments	escription Qty. Each Extended
Labor Posted			
Date		Technician	Hours Rate Extended
23-Jan-19 Arthurs, Durvin			1.50 0.00 0.00
			Activity 10 Sub TotalParts:0.00Labor:0.00Labor Hours: 1.500.00Sublet Parts:0.00Sublet Labor:0.00Activity Sub Total0.00
Activity Note: PM A	<b>AL VEHICLE</b> rentive Maintenance evel A		
Parts Issued		Activity Comments	
Date Part Num 23-Jan-19 B329(F)		D R, OIL. SAME AS LF3681	vescription Qty. Each Extended 1.00 1.96 1.96

•

.

.

<b>First</b> B		55345 Pa	VorkOrder alm Tran Connection v 2.2 Page 1 of 9	_		der: 5216		
Client Department.		•	age i or b	In	voice Numl	ber: 5534	5-5216	9338
Client Department: MRC:		55345M	Equipment:	5450				
WO Desc:		1007010	rdubiieur.		) Champion Cr	usaders		
PM A			VIN:		_1FDA02752	0300013		ŝ
Requested By:	i	RGASPARD	Status:	40				
Created By:		RGASPARD	Priority:	1				
Class:		WO	Driver:					
Arrangement:		Unassigned	Phone:					
Potential Warranty:		No	ETA:					
		Chronology						
Reported		Mar 5, 20		11:56 AM	Meter Readin	g UOM		
Started		Mar 5, 20			wo	DH		
Completed		Mar 5, 20	)19	10:07 PM	Life 232,01	4 DH		
	Down Time				L	<b>_</b> i		
	بنية محدث فراري المراجعة والمحدة والمراجع		WorkOrder Note	S				
Line	Comment							
10 COMPLAINT: PMA Se	ervice							
CAUCE, Descention 1	laintananan							
CAUSE: Preventive M	aintenance							
CORRECTION: Perfo	rmed and complete	d PMA Service						
ctivity Note: leason for Repair: Vork Accomplished		Duty PMI Maintenance	میکند (۱۹۹۱) (۱۹۹۱) وار میکند. میکند (۱۹۹۵) وار میکند (۱۹۹۵) و میکند (۱۹۹۵					
Activity Note: Reason for Repair: Vork Accomplished Part Failure: P <b>arts Issued</b>	Light Medium 08 - Preventiv : A - PM Level A -	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a				
Activity Note: Reason for Repair: Nork Accomplished Part Failure: Parts Issued	Light Medium 08 - Preventiv	Duty PMI Maintenance	Activity Comments	Description		Qty	e Each i E	Extenc
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date	Light Medium 08 - Preventiv : A - PM Level A -	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a		Qty	: Each E	xtenc
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date	Light Medium 08 - Preventiv : A - PM Level A -	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a	H			
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A -	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a	на н			Exten
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a	H	ours f	Rate E	Exten
Activity Note: Leason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a		iours I 1.00	Rate E 0.00	Exten
Activity Note: Leason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	e en alter en en en alter a son a	Activity 1	iours I 1.00	Rate E 0.00	Extend 0
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Description		iours I 1.00	Rate E 0.00	Extend 0 C
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Description Parts: Labor:		iours I 1.00	Rate E 0.00	Extend 0 C
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Description Parts: Labor:	Activity 1	iours I 1.00	Rate E 0.00	Extend 0 0 0 0
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Description Parts: Labor: Labor Hc	Activity 1 ours: 1.00	iours I 1.00	Rate E 0.00	Extend 0 C C C
ctivity Note: leason for Repair: Vork Accomplished art Failure: arts Issued Date Date Date	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	5xten 0 ( ( ( (
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date O5-Mar-19 AMRE	Light Medium 08 - Preventiv : A - PM Level A - Part Number	Duty PMI Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0 0
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRE O5-Mar-19 AMRE	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU	Duty PMI re Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0
Activity Note: Reason for Repair: Work Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI Costivity: 20	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU	HICLE	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extenc 0. 0 0 0 0 0
Activity Note: Reason for Repair: Work Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI Ctivity: 20	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU M A 08 - Preventive	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0 0
Activity Note: Reason for Repair: Work Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI Ctivity: 20	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU M A 08 - Preventive	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0 0
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI AM	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU M A 08 - Preventive	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0
Activity Note: Leason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI AM	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU M A 08 - Preventive	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0
Activity Note: Reason for Repair: Vork Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI AM	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU T TEEMAL, VISHNU M A 08 - Preventive	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00	Extend 0 0 0 0 0 0
Activity Note: Reason for Repair: Nork Accomplished Part Failure: Parts Issued Date Date 05-Mar-19 AMRI Contection Contection Date 05-Mar-19 AMRI Date 05-Mar-19 AMRI Contection	Light Medium 08 - Preventiv : A - PM Level A Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU 999 TOTAL VEI PM A 08 - Preventive : A - PM Level A	HICLE e Maintenance	Activity Comments	Parts: Labor: Labor Ho Sublet Part Sublet Lab <b>Activity S</b>	Activity 1 ours: 1.00 cs: or:	ours f 1.00 LO Sub To	Rate E 0.00 tal	Extenc 0 0 0 0 0 0
Abor Posted	Light Medium 08 - Preventiv : A - PM Level A - Part Number T TEEMAL, VISHNU T TEEMAL, VISHNU PM A 08 - Preventive A - PM Level A - Part Number	Duty PMI re Maintenance A HICLE e Maintenance	Activity Comments	Description Parts: Labor: Labor Ho Sublet Part Sublet Lab Activity S	Activity 1 ours: 1.00 cs: or:	iours I 1.00	Rate E 0.00 tal	Extenc 0. 0 0 0 0

FirstBas	Work 55345 Palm Tra v 2	an Connection			
hin the second s			Invoid	WorkOrder: 5222 Ce Number: 5534	
Client Department: MRC: WO Desc:	55345M	Equipment:	5450 Ford E350	Champion Crusaders	
PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	VAMRITTEEMAL VAMRITTEEMAL WO Unassigned No	VIN: Status: Priority: Driver: Phone: ETA:	1FDEE3FL1 40 1		
Reported Started	Chronology Mar 28, 2019		11:17 AM	ter Reading UOM	
Completed	Mar 28, 2019		6:46 PM Life		
		rkOrder Notes	<u></u>		
Line Comment 10 COMPLAINT: CAUSE: CORRECTION:	-				
Activity Note: Light	Ac	<b>tivity Comments</b> Di	ascription	Qt	2. Each Extended
Labor Posted Date	Techn	ician		Hours	Rate Extended
			A Parts: Labor: Labor Hours: Sublet Parts: Sublet Labor: Activity Sub		otal 0.00 0.00 0.00 0.00 0.00
Activity Note: PM A					
Date     Part N       29-Mar-19     B329(F)	umber	tivity Comments D SAME AS LF3681	escription	Qb 1.0	
Labor Posted					

F	irst		5534	WorkOrder 5 Palm Tran Connecti v 2.2 Page 1 of 9	 W	orkOrder: 5		372803
	nt Departme	ent:					JJJ-J2-J2-	572005
MRC WO D			55345M	Equipment:	5450 Ford E350 Cham	pion Crusader	S	
PM A <b>Requ</b>			RGASPARD RGASPARD	VIN: Status: Priority:	1FDEE3FL1FDA02 40 1		-	
Class Arra	s: ngement:		WO Unassigned	Driver: Phone:	1			
Pote	ntial Warra	nty:	No	ETA:				
Rep	orted		Chronology May 17,	2019	2:48 PM WO	eading UOM DH		
Star	ted					45,320 DH		
Com	pleted	Down Time	May 20,	2019		45,199 DH		
			-	WorkOrder N	lotes			
Line			Comment					
10	COMPLAINT: p							
	CAUSE: Preven	tive Maintenance						
	CORRECTION:	Perform pmA Service	lube all Pivoting	Points Cross Rotate Tires (	Completed			
Wor Part	Failure:	shed: A - PM Leve	ntive Maintena el A	Activity Comm	ents			
Par	ts Issued	-			Description			h Extended
	Dale	Part Number			Description		Qty. Eac	II Extended
Lab	or Poste	d		Technician		Hours	Rate	Extended
	Dute					Hours	Tute	Extended
					Parts: Labor: Labor Hours: 0.0 Sublet Parts:	i <b>vity 10 Su</b> 00	ıb Total	0.00 0.00 0.00
					Sublet Labor: Activity Sub Tot	 		0.00
Activ Reas Wor	ty: <b>20</b> vity Note: son for Repa k Accomplis Failure:	PM A	ntive Maintena	nce				
		-		Activity Comm	ents			
Par	ts Issued							
-	Date	Part Number			Description		Qty. Eac	
	20-May-19	B329(F)		FILTER, OIL SAME AS LF			1.00 1.9	0 1.90
Lab	or Poste	d						

First Base	) 55345 Pal	forkOrder Im Tran Connection v 2.2 age 1 of 9		Drder: <b>52444608</b> a <b>ber:</b> 55345-5244	4608
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M RRENE RRENE WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champion 0 1FDEE3FL1FDA02752 40 1	Crusaders	
Reported Started Completed	Chronology Jun 17, 20 Jun 17, 20 Jun 17, 20	)19	2:38 PM 7:04 PM	DH 170 DH	• . • • •
Down	lime	WorkOrder Notes	System 249,6	524 DH	
Line Commi 10 COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTEN, CORRECTION: PERFORM AND C REPLACED AIR FILTER REPLACED DRAIN PLUG	ANCE		· · ·		
Activity: 1.0 999 TO	TAL VEHICLE				
Activity Note: Light M	ledium Duty PMI eventive Maintenance	Activity Comments			
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: -	ledium Duty PMI eventive Maintenance	Activity Comments			
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: -	ledium Duty PMI eventive Maintenance Level A		escription	Qty, Each I	Extended
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun	ledium Duty PMI eventive Maintenance Level A		escription	Qty, Each I	Extended
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued	ledium Duty PMI eventive Maintenance Level A nber		escription		
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted	ledium Duty PMI eventive Maintenance Level A nber	D	escription		Extended
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted	ledium Duty PMI eventive Maintenance Level A nber	D		Hours Rate E	Extended 97.50
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted	ledium Duty PMI eventive Maintenance Level A nber	D	Activity Parts: Labor: Labor Hours: 1.50 Sublet Parts:	Hours Rate E 1.50 65.00	Extended 97.50 0.0 97.5 0.0
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted	ledium Duty PMI eventive Maintenance Level A nber	D	Activity Parts: Labor: Labor Hours: 1.50	Hours Rate E 1.50 65.00	Extended 97.50 0.0 97.5 0.0 0.0
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted Date 17-Jun-19 AMRIT TEEMALA AREASON for Repair: 08 - Pre Nork Accomplished: A - PM I	Iedium Duty PMI eventive Maintenance Level A nber vISHNU VISHNU	D	Activity Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor:	Hours Rate E 1.50 65.00	Extended 97.50 0.0 97.5 0.0 0.0
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted Date 17-Jun-19 AMRIT TEEMAL, Activity: 20 999 TO Activity Note: PM A	Iedium Duty PMI eventive Maintenance Level A nber vISHNU VISHNU	D	Activity Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor:	Hours Rate E 1.50 65.00	Extended Extended 97.50 0.00 97.50 0.00 <b>97.50</b>
Activity Note: Light M Reason for Repair: 08 - Pre Work Accomplished: A - PM I Part Failure: - Parts Issued Date Part Nun Labor Posted Date 17-Jun-19 AMRIT TEEMAL,A Activity: 20 999 Tor Activity Note: PM A Reason for Repair: 08 - Pre Work Accomplished: A - PM I	Iedium Duty PMI eventive Maintenance Level A nber vISHNU VISHNU	D	Activity Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor:	Hours Rate E 1.50 65.00	Extended 97.50 97.51 97.51 0.04 0.04

•

,

.

<b>First</b> Base	55345 Palm	<b>'kOrder</b> Tran Connection v 2.2		er: 52597684
a transit	Pag	e 1 of 9		er: 52345-52597684
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M DARTHURS DARTHURS WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champion Cru 1FDEE3FL1FDA02752 40 1	
Reported Started Completed Down Tim	Chronology Aug 7, 2019 Aug 7, 2019 Aug 8, 2019		11:37 AM Meter Reading WO 12:12 AM Life 257,739	uom Dh Dh
Line Comment		NorkOrder Note	<u>S</u>	
	<b>VEHICLE</b> um Duty PMI tive Maintenance el A	Activity Comments	Description	Qty. Each Extended
Labor Posted				
Date	Tec	nnician	Но	urs Rate Extended
07-Aug-19 Gaspard,Ronald				1.58 65.00 102.92
			Activity 10 Parts: Labor: Labor Hours: 1.58 Sublet Parts: Sublet Labor: Activity Sub Total	9 Sub Total 0.00 102.92 0.00 0.00 102.92
Activity: 20 999 TOTAL Activity Note: PM A Reason for Repair: 08 - Prevent Work Accomplished: A - PM Leve Part Failure: -	tive Maintenance			
D		Activity Comments		
Date         Part Number           07-Aug-19         B329(F)	FILTER, C	IL SAME AS LF3681	Description	Qty.         Each         Extended           1.00         1.96         1.96

•

First Base	55345 Palm	rkOrder Tran Connection v 2.2 e 1 of 9		ler: <b>52671134</b> er: 55345-52671134
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M RGASPARD RGASPARD WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champion Cru 1FDEE3FL1FDA02752 40 1	isaders
Reported Started Completed Down Time	Chronology Sep 9, 2019 Sep 9, 2019 Sep 10, 2019	,	3:57 PM Meter Reading WO 12:35 AM Life 262,135	DH
Line Comment 10 COMPLAINT: pmA CAUSE: Service		WorkOrder Notes		
CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Activity: 10	EHICLE			
Activity Note: Light Mediu	ive Maintenance	Activity Comments		
Parts Issued Date Part Number		1	Description	Qty. Each Extended
Date       09-Sep-19     Gaspard,Ronald	Te	chnician	Н	Durs         Rate         Extended           1.58         65.00         102.92
			Activity 1 Parts: Labor: Labor Hours: 1.58 Sublet Parts: Sublet Labor: Activity Sub Total	0 Sub Totai 0.00 102.92 0.00 0.00 102.92
Activity: 20 999 TOTAL V Activity Note: PM A Reason for Repair: 08 - Preventi Work Accomplished: A - PM Level Part Failure: -	ve Maintenance	Activity Comments		
Date     Part Number       09-Sep-19     B329(F)	FILTER,		Description	Qty.         Each         Extended           1.00         1.96         1.96

	55345 Palm	<b>kOrder</b> Tran Connection / 2.2 e 1 of 9	WorkOrder: <b>52865335</b> Invoice Number: 55345-52865335		
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M VAMRITTEEMAL VAMRITTEEMAL WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champion Crusaders 1FDEE3FL1FDA02752 40 1		
	Chronology Nov 1, 2019 Nov 1, 2019 Nov 2, 2019	4:05 PM 12:10 AM VorkOrder Notes	WODH		
Line         10       COMPLAINT: PMA Service         CAUSE: Service due by Mileage.         CORRECTION: Change Oil & Filte         Parts # B329 Qty (1)         Parts# PA4075 Qty (1)         Oil 5W20 Qty (6.5) Qt	Comment	eck brakes Clean batteries.	. Replace Air Filter.		
Activity Note:       Light Me         Reason for Repair:       08 - Prev         Work Accomplished:       A - PM Le         Part Failure:       -		Activity Comments			
Parts Issued       Date     Part Number       Labor Posted	Ner:	Desc	rription Qty. Each	Extended	
Date 01-Nov-19 Arthurs,Durvin	Ted	۲ ۲ ۲	Hours Rate 1.50 65.00 Activity 10 Sub Total Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor: Activity Sub Total	Extended 97.50 0.00 97.50 0.00 0.00 <b>97.50</b>	
Activity Note: PM A		Activity Comments			

.

'

First	" First " Transit	55345 Palm	r <b>kOrder</b> Tran Connection v 2.2 e 1 of 9	Invo		r: <b>52958721</b> r: 55345-529	58721
Client Departn MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement: Potential Warr		55345M DARTHURS DARTHURS WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 ( 1FDEE3FL1 40 1	Champion Crusa FDA02752	aders	
Reported Started Completed	Down Time		NorkOrder Note	8:11 AM	Meter Reading WO Life 275,508	uom Dh Dh	
CAUSE: PREV	Comment PMA SERVICE ENTIVE MAINTENANCE I: PERFORM AND COMPLI			₩₹	/		
Part Failure:	Light Mediur Dair: 08 - Preventi Ished: A - PM Level -	n Duty PMI ve Maintenance	Activity Comments				
Parts Issue Date	<b>d</b> Part Number			Description		Qty. Each	Extended
Date 02-Dec-19	ed Amrit Teemal, Vishni		hnikian		Hour	s Rate 1.50 65.00	Extended 97.50
				Parts: Labor: Labor Hour Sublet Parts: Sublet Labor Activity Sul	: :	Sub Total	0.00 97.50 0.00 0.00 <b>97.50</b>
Activity: <b>20</b> Activity Note: Reason for Rep Work Accompli Part Failure:	PM A	e Maintenance	Activity Comments				
Parts Issue Date	d Part:Number			Description		Qty. Each	Extended
02-Dec-19	B329(F)	FILTER, (	DIL SAME AS LF3681			1.00 1.96	1.96

. . . .

,

,

First Base	⊖ 55345 Palm	<b>kOrder</b> Tran Connection 2.2 2 1 of 9	WorkOrder: Invoice Number		9
Client Department: MRC: WO Desc:	55345M	Equipment:	5450 Ford E350 Champion Cru		
PM A Requested By: Created By: Class: Arrangement: Potential Warranty:	VAMRITTEEMAL VAMRITTEEMAL WO Unassigned No	VIN: Status: Priority: Driver: Phone: ETA:	1FDEE3FL1FDA02752 40 1		
C Reported Started Completed Down Time	hronology Jan 24, 2020 Jan 24, 2020 Jan 24, 2020	11:53 AM Mete WO 9:54 PM Life	r Reading UOM DH 283,632 DH		
	waarna	l VorkOrder Notes			
Line	1	Comment			
10 COMPLAINT: PMA Service					
CAUSE: Service due by Mileag	е.				1
CORRECTION: Change Oil & F Parts # B329 Qty (1) Oil 5W20 Qty (6.5) Qt	ilter . Lube all Pivoting Points. Cr	eck brakes . Clean batterie	es Rotate R/F To L/R outer & L/R O	uter to R/F.	
		Activity Comments	ription	Qly. Each Exten	ded
Labor Posted					
Date	Tecl	nician	Hours	Rate Exten	ded
24-Jan-20 Arthurs,Durvin					D.00
			Activity 10 S Parts: Labor: Labor Hours: 2.90 Sublet Parts: Sublet Labor: Activity Sub Total	( ( ( (	0.00 0.00 0.00 0.00 0.00
Activity Note: PM A					
		Activity Comments			
Parts Issued	e i segui i se principal per l'Arra di Mana	n dada ya ya daga da ku Manazarta	n he alfendes fillen johnen here: N		
Date Part Ni 24-Jan-20 B329(F)		Des DIL SAME AS LF3681	cription	Qty.         Each         Extension           1.00         1.96         1	ded 1.96

.

First	55345 Palm	r <b>kOrder</b> Tran Connection v 2.2 ge 1 of 9		er: <b>53214716</b> er: 55345-53214716
Client Department: MRC: WO Desc: PM A Requested By: Created By: Class: Arrangement:	55345M DARTHURS DARTHURS WO Unassigned	Equipment: VIN: Status: Priority: Driver: Phone:	5450 Ford E350 Champion Cru 1FDEE3FL1FDA02752 40 1	
Potential Warranty:	No	ETA:		
Reported Started Completed	Chronology Feb 20, 2020 Feb 20, 2020 Feb 20, 2020		Meter         Reading         UC           WO         D           7:07 PM         Life         287,932         D	
Down Ti		WorkOrder Note	I •IIIII	
Line 10 COMPLAINT: Perform PMA Servic CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter Parts # B329 Qty (1) Oil 5W20 Qty (6.5) Qt.		heck brakes. Clean batte	ries	
} <b>0.01120 207 (0.0) 2</b> 0				
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: -	999 TOTAL VEHICLE ty PMI entive Maintenance	Activity Comments		
Activity: <b>10</b> Activity Note: Light Du Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: -	ty PMI	Activity Comments		
Activity: 1.0 999/999/9 Activity Note: Light Du Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: -	ty PMI entive Maintenance		Description	Qty. Each Extended
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Numb	ty PMI entive Maintenance		Description	Oty. Each Extended
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Numb Labor Posted	ty PMI entive Maintenance ver			urs Rate Extended
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Numb Labor Posted	ty PMI entive Maintenance ver		Ho	urs Rate Extended 1.67 0.00 0.00
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Numb Labor Posted	ty PMI entive Maintenance ver		Ho Activity 10 Parts: Labor:	urs Rate Extended 1.67 0.00 0.00 • Sub Total 0.00
Activity: 10 999/999/9 Activity Note: Light Dui Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Numb Labor Posted	ty PMI entive Maintenance ver		Ho Activity 10 Parts:	urs Rate Extended 1.67 0.00 0.00 <b>Sub Total</b> 0.0 0.0 0.0 0.0 0.0 0.0 0.0
Activity: 10 999/999/ Activity Note: Light Dur Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Num: Labor Posted Date 20-Feb-20 Arthurs, Durvin Activity: 20 999 TOTA	ty PMI entive Maintenance per Te		Ho Activity 10 Parts: Labor: Labor Hours: 1.67 Sublet Parts: Sublet Labor:	urs Rate Extended 1.67 0.00 0.00 <b>Sub Total</b> 0.00 0.00 0.00 0.00 0.00 0.00 0.00
Activity: 10 999/999/ Activity Note: Light Dur Reason for Repair: 08 - Prev Work Accomplished: - Part Failure: - Parts Issued Date Part Num: Labor Posted Date 20-Feb-20 Arthurs, Durvin Activity: 20 999 TOTA Activity Note: PM A Reason for Repair: 08 - Preve Work Accomplished: A - PM Le	ty PMI entive Maintenance per Te		Ho Activity 10 Parts: Labor: Labor Hours: 1.67 Sublet Parts: Sublet Labor:	urs Rate Extended 1.67 0.00 0.00

First	55345 Pa	<b>/orkOrder</b> Im Tran Connection v 2.2 age 1 of 9	WorkOrder: 5	
Client Department: MRC: WO Desc: PM A	55345M	Equipment: VIN:	Invoice Number: 5 5450 Ford E350 Champion Crusader 1FDEE3FL1FDA02752	
Requested By: Created By: Class: Arrangement: Potential Warranty:	DARTHURS DARTHURS WO Unassigned No	Status: Priority: Driver: Phone: ETA:	40 1	
Reported Started Completed Dow	Chronology May 18, 2020 May 19, 2020 May 19, 2020	11:44 AM 10:26 AM		
Line 10 PM. Perform pmA service, Parts. Engine oil filter engine oil. SV	part # B329 qty 1	WorkOrder Note Comment and re torque tires (140 f/	S o), R&R engine oil and filter, road test, all ol	ay at this time.
Activity: 5 Activity Note: Reason for Repair: Work Accomplished: Part Failure:	9/999/999 TOTAL VEHICLE PERSONAL RISK ASSESSMEN SW - Shop Work Order 06 - Inspect 00 - No Failure			
Parts Issued	Part Number	Activity Comments	Description	Qty. Each Extended
Labor Posted		Technician	Hours	Rate Extended
			Activity 5 Sub Parts: Labor: Labor Hours: 0.00 Sublet Parts: Sublet Labor: Activity Sub Total	• Total 0.00 0.00 0.00 0.00 0.00
Activity: <b>10</b> Activity Note: Reason for Repair: Work Accomplished: Part Failure:	999/999/999 TOTAL VEHICLE Light Duty PMI 08 - Preventive Maintenance			
Parts Issued Date	Part Number	Activity Comments	Description	Oty. Each Extended

ł

	<b>irst</b>		5534	WorkOr <sup>15</sup> Palm Tran v 2.2 Page 1 o	Connection	Inv	WorkO voice Num		<b>5345-535</b>	75231
MRC WO 5534 Req Crea Class Arra	Desc: 45-LIGHT DUTY PM uested By: ated By:	4	55345M SPACE SPACE WO Unassig No	VI St Pr Di ned Pf	juipment: IN: atus: iority: river: none: FA:		50 Champion FL1FDA02752		rs	
Sta	oorted		Jul 7	7, 2020 7, 2020		9:33 AM	Meter Readi WO	ng UOM DH		
Con	npleted	Down Time	Jul 8	3, 2020 Work	Order Notes	12:22 AM	Life 300,8	01 DH		
Line 10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform Oil filter B329 Qty1 Engine oil 10w30 qty 7 Replaced marker light Replaced headlight bu	n PmA Service ' Qts Qty1								
Acti Rea Wo	ity: <b>5</b> 999 vity Note: son for Repair: rk Accomplished: t Failure:	/ <b>999/999 TOT</b> PERSONAL R SW - Shop W 06 - Inspect 00 - No Failui	ISK ASSES ork Order	SMENT	vity Comments					
Pai	rts Issued									
	Date	Part Number			De	escription			Qty. Each	Extended
Lat	oor Posted									
	Date			Technici	an			Hours	Rate	Extended
						Parts: Labor: Labor Ho Sublet Part Sublet Lab <b>Activity S</b>	or:	5 Sub	Total	0.00 0.00 0.00 <u>0.00</u> <b>0.00</b>
Acti Rea Wo	ity: <b>10</b> vity Note: son for Repair: rk Accomplished: t Failure:	299/999/999 Light Duty Pl 08 - Preventiv -	٩I	ance	it. Comments					
Par	rts Issued			Activ	vity Comments					
	Date	Part Number			De	escription			Qty. Each	Extended

	<b>irst</b>		55345 Pal	orkOrder m Tran Connec v 2.2 ge 1 of 12	tion	Work Invoice Nur	Order: 53 mber: 55	-	794414
MRC WO I 5534 Requ Crea Clas Arra	Desc: I5-LIGHT DUTY PM u <b>ested By:</b> I <b>ted By:</b>	A R F V U	SS345M RGASPARD RGASPARD VO Jnassigned Io	Equipme VIN: Status: Priority: Driver: Phone: ETA:	nt:	5450 Ford E350 Champio 1FDEE3FL1FDA0275 40 3		'S	
Sta	orted rted npleted Down	Chronology Oct 27, 20 Oct 27, 20 Oct 27, 20 Time	20	12:00 AM 6:31 PM	WO	Reading         UOM           DH           309,616         DH           309,765         DH			
Line				WorkOrder Comr					
10	COMPLAINT: Perform CAUSE: Service Due b CORRECTION: Change in Stock. Parts # B329 Qty (1) Oil 10W20 Qty (6.5) Q	y Mileage. e Oil & Filter. Lube all	Pivoting Points.	. Check brakes. Cle	an batterie	es. R/R hub bearing loose / P	inion Loose 8	seal Leakir	ngno Parts
Rea Wor	ity: <b>5</b> 999 vity Note: son for Repair: Accomplished: Failure:	<b>/999/999 TOTAL V</b> PERSONAL RISK SW - Shop Work 06 - Inspect 00 - No Failure	ASSESSMEN	IT Activity Com	ments				
Par	ts Issued								
	Date	Part Number			Des	scription		Qty. Eac	h Extended
Lab	oor Posted								
	Date			Technician			Hours	Rate	Extended
						Activity Parts: Labor: Labor Hours: 0.00 Sublet Parts: Sublet Labor: Activity Sub Total	y 5 Sub	Total	0.00 0.00 0.00 0.00 <b>0.00</b>
Acti Rea Wor	ity: <b>10</b> vity Note: son for Repair: 'k Accomplished: : Failure:	999/999/999 TOT/ Light Duty PMI 08 - Preventive M -		Activity Com	ments				
Par	ts Issued								
	Date	Part Number			Des	scription		Qty. Eac	h Extended

First	Base	5534	WorkOrder 5 Palm Tran Connection v 2.2 Page 1 of 9	Wor Invoice Nu	kOrder: 51		
<b>Client Depart</b>	ment:						10 10 100
MRC:		55345M	Equipment:	5450			
WO Desc: PM A			VIN:	Ford E350 Champio 1FDEE3FL1FDA0275			
Requested By	/=	TDELVA	Status:	40	2		
Created By:	-	TDELVA	Priority:	1			
Class:		WO	Driver:	-			
Arrangement		Unassigned					
Potential War	ranty:	No	ETA:				Berlin and Antonio and Mathematical Action (Science Science Sci Science Science Sci
	Chi	ronology		Meter Reading UOM			
Reported		Aug 22, 201		M WO DH			
Started Completed		Aug 23, 2018 Aug 23, 2018		Life 198,746 DH	1		
compieteu	Down Time	Aug 23, 2010	9.40 AI	System 198,746 DH	Sec. Salar		
			WorkOrder Note	I have been a second and the second s	• 		
Line		for an end of the	Comment		1		
10 COMPLAINT	Γ: PmA						
CALICE							
CAUSE: pre	ventive maintenance						
CORRECTIO							
CURRECTIC	Div: perform service lube	all Pivoting Point	s and Remove two rear tire by t	wo good used one completed			
Work Accomp Part Failure:	olished: - -						
Deute Issue			Activity Comments				
Parts Issue						1 1 1 1 1	
Date	Part Number			Description		Qty. Ea	ch Extended
Labor Deed							
Labor Post	ea						
Date			Technician		Hours	Rate	Extended
23-Aug-18	Pierre,Hubert J			1	8.00	0.	00 0.00
				Activit Parts: Labor:	y 10 Sut	Total	0.00 0.00
				Labor Hours: 8.00 Sublet Parts: Sublet Labor: Activity Sub Total			0.00 0.00 0.00 0.00
Activity: 20 Activity Note: Reason for Re Work Accomp	55345-PM	ntive Maintena	ince	Sublet Parts: Sublet Labor:			0.00 0.00
Activity Note: Reason for Re	55345-PM epair: 08 - Prever	A SERV ntive Maintena	10	Sublet Parts: Sublet Labor:			0.00 0.00
Activity Note: Reason for Re Work Accomp	55345-PM epair: 08 - Prever	A SERV ntive Maintena	Ince Activity Comments	Sublet Parts: Sublet Labor:			0.00 0.00
Activity Note: Reason for Re Work Accomp	55345-PM epair: 08 - Prever lished: A - PM Leve -	A SERV ntive Maintena	10	Sublet Parts: Sublet Labor:			0.00 0.00
Activity Note: Reason for Re Work Accomp Part Failure:	55345-PM epair: 08 - Prever lished: A - PM Leve -	A SERV ntive Maintena el A	10	Sublet Parts: Sublet Labor:		Qty. Ea	0.00 0.00

FirstB <sub>4</sub>	ase First 10 Transit	55345 Pa	<b>VorkOrder</b> alm Tran Connectic v 2.2 Page 1 of 9			rder: 513891	
Client Department:			-		voice Num	<b>ber:</b> 55345	-51389139
MRC: WO Desc: PM B		55345M	Equipment: VIN:		0 Champion Ci L1FDA02752	rusaders	
Requested By: Created By: Class: Arrangement: Potential Warranty:		AOWENS AOWENS WO Unassigned No	Status: Priority: Driver: Phone: ETA:	40 1			
Reported		Chronology		2 42 214	Meter Readir	Ig UOM	•
Started		Jun 29, 2		2:42 PM	WO Life 190,04	DH 18 DH	
Completed	Down Time	Jul 1, 2	U18	9:01 AM	System 190,35		
			WorkOrder N	otes			
Line         Comme           10         COMPLAINT: Perform							
CAUSE:preventive ma	intenance						
CORRECTION: Tech P Parts used Oil filter Qty:1	'erformed PM-B						
Oil Qty:6.5qts Air filter Qty:1 PA							
Air filter Qty:1 PA							
Air filter Qty:1 PA Activity: <b>10</b> Activity Note: Reason for Repair: Work Accomplished: Part Failure:	Light Mediun 08 - Preventiv	Duty PMI	e Activity Comme	ints			
Air filter Qty:1 PA Activity: <b>10</b> Activity Note: Reason for Repair: Work Accomplished: Part Failure: Parts Issued	Light Mediun 08 - Preventiv 06 - Inspect -	Duty PMI					
Air filter Qty:1 PA Activity: <b>10</b> Activity Note: Reason for Repair: Work Accomplished: Part Failure: Parts Issued Date	Light Mediun 08 - Preventiv	Duty PMI		ints Description		Qty.	Each Extended
Air filter Qty:1 PA Activity: <b>10</b> Activity Note: Reason for Repair: Work Accomplished: Part Failure: Parts Issued	Light Mediun 08 - Preventiv 06 - Inspect -	Duty PMI					Each Extended
Air filter Qty:1 PA Activity: 10 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Date Labor Posted	Light Mediun 08 - Preventiv 06 - Inspect -	Duty PMI	Activity Comme	Description Parts: Labor: Labor Ho	- ours: 0.00		ite Extended
Air filter Qty:1 PA Activity: 10 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Date Labor Posted	Light Mediun 08 - Preventiv 06 - Inspect -	Duty PMI	Activity Comme	Description Parts: Labor:	- ours: 0.00 ts:	Hours Ra	ite Extended
Air filter Qty:1 PA	Light Mediun 08 - Preventiv 06 - Inspect -	Duty PMI	Activity Comme	Description Parts: Labor: Labor: Labor Ho Sublet Par	ours: 0.00 ts: por:	Hours Ra	ite Extended
Air filter Qty:1 PA Activity: 10 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Date Labor Posted Date Activity: 20	Light Mediun 08 - Preventiv 06 - Inspect - Part Number Part Number 999 TOTAL VE PM B	Duty PMI ve Maintenance	Activity Comme	Description Parts: Labor: Labor Ho Sublet Par Sublet Lab	ours: 0.00 ts: por:	Hours Ra	ite Extended
Air filter Qty:1 PA Activity: 10 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Parts Issued Date Labor Posted Date	Light Mediun 08 - Preventiv 06 - Inspect - Part Number Part Number 999 TOTAL VE PM B 08 - Preventiv	Duty PMI ve Maintenance	Activity Comme	Description Parts: Labor: Labor Ho Sublet Par Sublet Lab	ours: 0.00 ts: por:	Hours Ra	ite Extended

First	First 🕫 Transit	5534	WorkOrder 5 Palm Tran Connection v 2.2 Page 2 of 9	WorkC Invoice Nun	Drder: <b>51</b>		89139
Client Departme MRC:	ent:	55345M	Equipment:	5450			
WO Desc: PM B Requested By: Created By: Class: Arrangement: Potential Warra	abu	AOWENS AOWENS WO Unassigned No	VIN: Status: Priority: Driver:	Ford E350 Champion ( 1FDEE3FL1FDA02752 40 1	Crusaders		
	1	NO			1	1	1
Date	Part Number			Description		Qty. Each	Extended
29-Jun-18 29-Jun-18	PA4075 B329(F)		FILTER, AIR, PAPER SAME AS A FILTER, OIL SAME AS LF3681	AF2559U		1.00 5.28 1.00 1.96	5,28
25-5011-18			FILTER, OIL SAME AS LESOSI			1.00 1.90	1.96
Labor Poste	d						
Date			Technician		Hours	Rate	Extended
					I		
					20 Sub	Total	
				Parts:			7.24
				Labor: Labor Hours: 0.00			0.00
				Sublet Parts:			0.00
			이 같은 것이 같은 것이 있는 것이 있었다. 같은 것은 것이 같은 것이 같은 것이 같이 있다.	Sublet Labor:			0.00
				Activity Sub Total			7.24
Activity: <b>30</b> Activity Note: Reason for Rep Work Accomplis Part Failure:	PRAMETER	ion, Routine	Activity Comments				
Parts Issued							3
Date	Part Number		[	Description		Qty. Each	Extended
						<u></u>	
Labor Poste	d						
Date			Technician		Hours	Rate	Extended
					30 Sub	Total	
	승객들은 감독을 통했다.			Parts:			0.00
				Labor: Labor Hours: 0.00			0.00
				Sublet Parts:			0,00
				Sublet Labor:			0.00
				Activity Sub Total			0.00
				WorkOrder 513891	39 Gran	d Total	
			Parts:				7.24
			Labor:				0.00
				ours: 0.00			0.00
			Sublet Pa Sublet Lal				0.00 0.00
				ler Grand Total		in an an andra	7,24
Recent Repair H	listory					in the first of the second	

Firs	<sup>by</sup> First	SO Transit	WorkOrder 55345 Palm Tran Connection v 2.2 Page 3 of 9			WorkOrder: <b>51389139</b> Invoice Number: 55345-51389139				
Client Depa MRC: WO Desc: PM B Requested I Created By: Class: Arrangemen Potential W	By: nt:		55345M Equipment: VIN: AOWENS Status: AOWENS Priority: WO Driver: Unassigned Phone: No ETA:		5450 Ford E350 Champion Crusaders 1FDEE3FL1FDA02752 40 1					
WorkOrder	Date Completed	Life Meter	Class			Desc	ription			
51389139	1-Jul-18	190,048	wo	PM B						
51339044	3-Jun-18	185,575	wo	PM A		and a first of the south source of the sourc				
51386017	1-Jun-18	185,265	wo	55345 5	SPARK PLUG GAS BU	SSES				
Scheduled I	Preventativ	e Mainten	ance						1	
Nest		PM	WorkO	rder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2	
<b>Other Open</b>	Repairs	( 원왕·문화)				일 2월 2월 2019 <sup>3</sup>				
WorkOrder8	Date Reported	Life Meter	Class			Desc	ription			
51372014	24-May-18	184,168	wo	Transm	ission code PO 751					

#### PH: Work Order: 51389139 Desc: PM B Equip: 5450 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL1FDA02752

# LH: 10 Desc: Light Mediun Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 01-JUL-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,100	Safety Inspection	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 29, 2018 4:48:32 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	Jul 1, 2018 9:00:42 AM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 29, 2018 4:48:33 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	Jun 29, 2018 4:48:34 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	Jun 29, 2018 4:48:34 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	Jun 29, 2018 4:48:34 PM	No	an i mana an any ini ini an an
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	Jun 29, 2018 4:48:34 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	Jun 29, 2018 4:48:35 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Jun 29, 2018 4:48:34 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:48:35 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	Jun 29, 2018 4:48:34 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 -
20,240	FRA Check Interior Lights	Done		CKARLENS	Jun 29, 2018 4:48:36 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 29, 2018 4:48:35 PM	No	
20,260	Check Stop Request System		na	CKARLENS	Jun 29, 2018 4:48:36 PM	No	
20,270	Check Fare Box Mounting (If Applicable)		na	CKARLENS	Jun 29, 2018 4:48:36 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 29, 2018 4:48:36 PM	No	antonia in tra
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 29, 2018 4:48:36 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	- provide per construction of spectra (spectra (
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	- , - , - , - , - , - , - , - , - , - ,
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	n a chairte a tha tha tha tha tha ann ann an
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	
30,340	FRA Check Destination Sign and Run Box	nen 2 an an 2 an 2 an 2 an 2 an 2 an 2 a	na	CKARLENS	Jun 29, 2018 4:48:38 PM	No	and and address and address of a set of
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 29, 2018 4:48:37 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	Jun 29, 2018 4:48:38 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 29, 2018 4:48:38 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	Jun 29, 2018 4:48:38 PM	No	, allan una martina de la constante de la const
30,390	FRA Check Fuel Tank Cap	Done	allan 1993	CKARLENS	Jun 29, 2018 4:48:38 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	Jun 29, 2018 4:48:38 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 29, 2018 4:48:38 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 29, 2018 4:52:13 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 29, 2018 4:52:13 PM	No	
40,420	Check Hood	Done		CKARLENS	Jun 29, 2018 4:52:13 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:52:14 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:52:14 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	10 <sup>-1</sup> 00 4-1 <sup>-1</sup> 00-1
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	Jun 29, 2018 4:52:15 PM	No	
44,140	FRA Check Intake System	Done	<b>1</b> 21 <b>*</b> . • • • • • • • • • • • • • • • • • •	CKARLENS	Jun 29, 2018 4:52:16 PM	No	1.000000000000000000000000000000000000
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	Jun 29, 2018 4:52:15 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	
44,180	, FRA Check for Leaks	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	n alan 11 - 1911 (11 )
44,190	FRA Perform Battery Inspection	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 29, 2018 4:52:16 PM	No	
50,510	Check Entire Steering System	Done	·	CKARLENS	Jun 29, 2018 4:52:16 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done	1	CKARLENS	Jun 29, 2018 4:52:16 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch	·	CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:52:17 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:52:10 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	Jun 29, 2018 4:52:17 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,631	Tread Depth RF	13 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,632	Tread Depth LF	13 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 29, 2018 4:55:25 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	Jun 29, 2018 4:55:26 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	Jun 29, 2018 4:55:26 PM	No	
60,670	Check Dual Mating With Square	Done	-	CKARLENS	Jun 29, 2018 4:55:26 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 29, 2018 4:55:26 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	Jun 29, 2018 4:55:27 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 29, 2018 4:55:28 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	Jun 29, 2018 4:55:28 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 29, 2018 4:55:28 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:55:28 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 29, 2018 4:55:28 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	Jun 29, 2018 4:55:29 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	Jun 29, 2018 4:55:29 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 29, 2018 4:55:29 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		CKARLENS	Jun 29, 2018 4:55:29 PM	No	al and all the second second second
77,132	Brake Pad Thickness RF	8 Inch	(m	CKARLENS	Jun 29, 2018 4:55:29 PM	No	, 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1 1997 - 199
77,133	Brake Pad Thickness LR	8 Inch		CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		CKARLENS	Jun 29, 2018 4:55:29 PM	No	
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,137	Brake Rotor LR	35.8 Inch	in the deal of the second second	CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	Jun 29, 2018 4:55:30 PM	No	
77,150	Check King Pins	-	na	CKARLENS	Jun 29, 2018 4:55:31 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 29, 2018 4:55:31 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 29, 2018 4:55:31 PM	No	· · · · · · · · · · · · · · · · · · ·
80,810	Completion of PMI Report	Done		CKARLENS	Jun 29, 2018 4:55:31 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	Jun 29, 2018 4:55:31 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	Jun 29, 2018 4:55:31 PM	No	

# LH: 20 Desc: PM B Task: PM B SERVICE Performed by: CKARLENS Performed on: 29-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 29, 2018 4:41:38 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Jun 29, 2018 4:41:38 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Jun 29, 2018 4:41:38 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Jun 29, 2018 4:41:38 PM	No	*** *** * * * * * * * * *
104,000	Lubricate Chassis	Done		CKARLENS	Jun 29, 2018 4:41:38 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Jun 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:41:38 PM		
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	Jun 29, 2018 4:41:38 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Jun 29, 2018 4:41:38 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Jun 29, 2018 4:41:39 PM	No	
201,000	Service Crankcase Breather	Done		CKARLENS	Jun 29, 2018 4:41:39 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Jun 29, 2018 4:41:40 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Jun 29, 2018 4:41:39 PM	No	s
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Jun 29, 2018 4:41:39 PM	No	Charles i sins no inconse

# LH: 30 Desc: PRAMETER Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 29-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 29, 2018 4:27:07 PM	No	nn inge ikanika na karat parti iaina karat na k
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

Activity Note: Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance Work Accomplished: 06 - Inspect Part Failure: - Activity Comments Parts Issued Date Part Number Description Qty, Each Extended Date Part Number Description Qty, Each Extended Comments Rate Extended 05-Dec-18 Arthurs,Durvin Comments Activity: 10 Sub Total Parts: 0.00 Labor: 0.00 Sublet Parts: 0.00 Sublet Parts: 0.00 Sublet Parts: 0.00 Sublet Parts: 0.00 Activity: Sub Total 0.00 Acti	Firs	by First 🕫 Transit		WorkOrder Palm Tran Connection v 2.2 Page 1 of 9	Wa Invoice N	rkOrder: 5 umber: 5		374960
Reported Started         Dec 5, 2018         10:50 AM Dec 5, 2018         In:45 PM           Unit         Down Time         WorkOrder Notes           WorkOrder Notes         System 216,337 DH           In         Completed         Comment           In         Comment         Comment           In         Completion         Comment           In         Comment         Comment           In         Completion         Comment           In         System 210 (1)         System 210 (2)           Parts B320 (2) (1)         Parts Insued         System 210 (2)           Parts Issued         System 210 (2)         System 210 (2)           Parts Issued         Date         Part Number         Decription           Int Failure:         -         Activity Comments         2.00 (0.00 (0.00 (2))           Parts Issued         International (2) (2) (2) (2) (2) (2) (2) (2) (2) (2)	MRC: WO Desc: PM B Requested B Created By: Class: Arrangement	<b>y:</b> t:	DARTHURS DARTHURS WO Unassigned	VIN: Status: Priority: Driver: Phone:	Ford E350 Champi 1FDEE3FL1FDA027 40		S	
Line       Comment         10       COMPLAINT: PMB Service         CAUSE: Service Due by Mileage.       CORRECTION: Change Oil8. Filter. Lube all Pivoting Points. Check brakes Clean batteries. Replace Air Filter. Parts B329 Qr (1)         On S W20 Qr (6.5) Qt       999 TOTAL VEHICLE         Activity Note:       Light Medium Duty PMI         Reason for Repair:       06 - Preventive Maintenance         Work Accomplished:       06 - Inspect         Part Failure:       -         Part S Issued	Started		Dec 5, 2018 Dec 5, 2018 Dec 5, 2018	11:45 P	M WO Life 216,126	DH DH		
10       COMPLAINT: PMB Service         CAUSE: Service Due by Mileage.       CORRECTION: Change Oil8, Filter. Lube all Prvoting Points. Check brakes Clean batteries. Replace Air Filter. Parts# B329 QV (1)         Parts# B329 QV (1)       Parts# May 200 (1)         Parts# B329 QV (1)       999 TOTAL VEHICLE         Activity: 10       Image Difference         Parts# B329 QV (1)       999 TOTAL VEHICLE         Activity Note:       Light Mediun Duty PMI         Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       06 - Inspect         Parts       Image Difference         Vork Accomplished:       06 - Inspect         Part Failure:       -         Activity Comments       Extended         Date       Part Number       Description         Date       Part Number       Description         Activity 10 Sub Total       0.00         05-Dec-18       Arthurs,Durvin       2.00       0.00         Activity Sub Total       0.00         Sublet Parts:       0.00       0.00         Activity Note:       PM B       Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       B - Preventive Maintenance       0.00         Activity Note:       PM B								
Activity Comments         Parts Issued         Date       Part Number       Description       Qty.       Each       Extended         Labor Posted         Date       Technician       Mours       Rate       Extended         Date       Technician       Hours       Rate       Extended         O5-Dec-18       Arthurs,Durvin       Colspan="4">Colspan="4"Colspa	Activity: 10 Activity Note Reason for R Work Accom	29 Qty (1) H075 Qty (1) Qty (6.5) Qt 999 TOTA :: Light Me epair: 08 - Prev	<b>AL VEHICLE</b> diun Duty PMI rentive Maintenanc		es. Replace Air Filter.			
Parts Issued       Description       Qty.       Each       Extended         Date       Part Number       Description       Qty.       Each       Extended         Date       Technician       Hours       Rate       Extended         05-Dec-18       Arthurs,Durvin       2.00       0.00       0.00         Activity ID Sub Total         Parts:       0.00       0.00         Labor Hours:       2.00       0.00       0.00         Labor:       0.00       Labor:       0.00         Labor:       0.00       Sublet Labor:       0.00         Sublet Labor:       0.00       0.00       0.00         Activity Sub Total       999 TOTAL VEHICLE       999 TOTAL VEHICLE       0.00         Activity Note:       PM B       Reason for Repair:       08 - Preventive Maintenance       Vork Accomplished: B - PM Level B       Vork Accomplished: B - PM Level B         Part Failure:       -       Activity Comments       U       U       U       U	Part Failure:	-						
Date       Part Number       Description       Qty.       Each       Extended         Labor Posted       Date       Technician       Hours       Rate       Extended         05-Dec-18       Arthurs,Durvin       2.00       0.00       0.00       0.00         Activity 10 Sub Total         Parts:       0.00         Labor:       2.00       0.00         Labor:       0.00       0.00         Labor:       0.00       0.00         Labor:       0.00       0.00         Sublet Datts:       0.00         Sublet Labor:       0.00         Activity Sub Total       0.00         Activity Sub Total         Parts:         Battivity Note:       PM B         Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       B - PM Level B         Part Failure:       -         Activity Comments       -				Activity Comments				
Date     Technician     Hours     Rate     Extended       05-Dec-18     Arthurs,Durvin     2.00     0.00     0.00       Activity 10 Sub Total       Parts:     0.00       Labor:     0.00       Labor:     0.00       Labor:     0.00       Sublet Parts:     0.00       Sublet Parts:     0.00       Sublet Parts:     0.00       Sublet Date:     999 TOTAL VEHICLE       Activity Note:     PM B       Reason for Repair:     08 - Preventive Maintenance       Work Accomplished:     B - PM Level B       Part Failure:     -	Entered and the second second					and the second		
Date       Technician       Hours       Rate       Extended         05-Dec-18       Arthurs,Durvin       2.00       0.00       0.00         Activity 10 Sub Total         Parts:       Parts:       0.00         Labor:       0.00       0.00         Labor:       0.00       0.00         Sublet Parts:       0.00       0.00         Sublet Parts:       0.00       0.00         Activity Sub Total       0.00         Activity Sub Total       0.00         Activity Note:       PM B         Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       B - PM Level B         Part Failure:       -         Activity Comments       4ctivity Comments			Jer	D	escription		Qty. Each	Extended
05-Dec-18       Arthurs,Durvin       2.00       0.00       0.00         Activity 10 Sub Total         Parts:       0.00         Labor:       0.00         Labor:       0.00         Labor Hours: 2.00       Sublet Parts:       0.00         Sublet Parts:       0.00         Sublet Parts:       0.00         Activity Sub Total       0.00         Activity Note:       PM B         Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       B - PM Level B         Part Failure:       -         Activity Comments	Contractor and and and and and			Technician		Hours	Rate	Extended
Parts: 0.00 Labor: 0.00 Labor Hours: 2.00 Sublet Parts: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00 Act	05-Dec-18	Arthurs, Durvin				2.00	0.00	A MICROSOFT CONTRACTOR
Activity Note:       PM B         Reason for Repair:       08 - Preventive Maintenance         Work Accomplished:       B - PM Level B         Part Failure:       -         Activity Comments					Parts: Labor: Labor Hours: 2.00 Sublet Parts: Sublet Labor:		b Total	0.00 0.00 0.00
	Reason for Re	PM B epair: 08 - Preve	entive Maintenance					
	Parts Issue	a d		Activity Comments				

<b>First</b> Base	) 55345 Palm T v	x <b>Order</b> ran Connection 2.2 1 of 9	WorkOrder: 52294981 Invoice Number: 55345-52294981
MRC: WO Desc: PM B Requested By: Created By: Class:	55345M VAMRITTEEMAL VAMRITTEEMAL WO	Equipment: VIN: Status: Priority: Driver:	5450 Ford E350 Champion Crusaders 1FDEE3FL1FDA02752 40 1
Arrangement: Potential Warranty:	WO Unassigned No	Driver: Phone: ETA:	
Reported Started Completed	Chronology Apr 24, 2019 Apr 24, 2019 Apr 25, 2019		5:57 PM Meter Reading UOM WO DH 12:41 AM Life 240,751 DH
Down			ł
Line Comment 10 COMPLAINT:pmB		orkOrder Notes	
CAUSE: Service CORRECTION:perform PmB Ser	áco -		
Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts			
		ctivity Comments	
Date Part Nun	iber	De	ascription Qty. Each Extende
Labor Posted           Date           24-Apr-19         Gaspard,Ronald	Techr	lcian	Hours Rate Extende 1.58 65.00 102.9
			Activity 10 Sub Total
			Parts: 0.0 Labor: 102.9 Labor Hours: 1.58
			Sublet Parts:0.0Sublet Labor:0.0Activity Sub Total102.9
Activity Note: PM B	AL VEHICLE ventive Maintenance evel B		
Parts Issued	A	ctivity Comments	
Date Part Nun 24-Apr-19 B329(F)		De L SAME AS LF3681	escription Qty. Each Extende

·

F	irst	Base	provide a second se	n Tran Connection v 2.2					
		First 🥟 Transit	Pa	ge 1 of 9	wo Invoice N	rkOrder: 52 umber: 5			74033
MRC	And a supervision of the supervi	ient:	55345M	Equipment:	5450				
	ested By: ted By:		RGASPARD RGASPARD WO	VIN: Status: Priority: Driver:	Ford E350 Champio 1FDEE3FL1FDA027 40 1		5		
	ngement: ntial Warr	anty:	Unassigned No	Phone: ETA:					
			Chronology				1		
Star	orted ted pleted		Oct 4, 2019 Oct 4, 2019 Oct 4, 2019	9	WO WO	Reading UOM DH 266,653 DH			
L		Down Time	)	WorkOrder Note					
Line		Comment		WORKOIGEI NOCE	2				
10	COMPLAINT:	PMB SERVICE							
	CAUSE: PREV	ENTIVE MAINTENANCE							
	CORRECTION	: PERFORM AND COMPLI	ETED PMB SERVICE						
Part	Accompli Failure:	ished: 06 - Inspect		Activity Comments	3				
Fart	Date	Part Number			Description		Qty.	Each	Extended
	Putt	- Gre Humber			Description		24.	Luch	Externed
Labo	or Poste	ed							
	Date		Т	echnician		Hours	R	ate	Extended
04	4-Oct-19	AMRIT TEEMAL, VISHN	IJ			1.50		65.00	97.50
					Activi Parts: Labor: Labor Hours: 1.50 Sublet Parts: Sublet Labor: Activity Sub Total		b Tot	al	0.00 97.50 0.00 0.00 <b>97.50</b>
Rease Work	ity Note: on for Rep	PM B PM B Pair: 08 - Preventi shed: B - PM Level	ve Maintenance						
Dent				Activity Comments					
Part	s Issue				Desertation		0	-	Data da L
0	Date 4-Oct-19	Part Number B329(F)		, OIL SAME AS LF3681	Description		Qty.	Each	Extended 1.96
L0	, 50, 15						1.00	1.50	1.50

First	55345	WorkOrder Palm Tran Connection v 2.2 Page 1 of 11		order: <b>5330698</b>	
Client Department: MRC: WO Desc: PM B Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M DARTHURS DARTHURS WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champion 0 1FDEE3FL1FDA02752 40 1	Crusaders	
Reported Started Completed Dow	Chronology Mar 23, 2020 Mar 23, 2020 Mar 23, 2020 Mar 23, 2020	11:07 AM 8:07 PM WorkOrder Not	MeterReadingUOMWODHLife292,043DH		
Line 10 COMPLAINT: Perform CAUSE: Service due b CORRECTION: Chang Parts# B329 Qty (1) Parts #65266 Qty (1)	y Mileage. e Oil & Filter. Lube all Pivoting Pol	Comment ints. Check Brakes Clean ba	tteries. Replace Oil drain plug. Swaj	o R/R inner tire.	
Activity Note: Reason for Repair: Work Accomplished: Part Failure:	999/999/999 TOTAL VEHICL Light Duty PMI 08 - Preventive Maintenan				
Date Date	Part Number		Description	Qiy. I	Each Extended
Date 23-Mar-20 Arthurs	;Durvin	Technician	Activity Parts: Labor: Labor Hours: 1.82 Sublet Parts: Sublet Labor: Activity Sub Total	Hours Rate	0.00 0.00
Activity: 20 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Parts Issued	999 TOTAL VEHICLE PM B 08 - Preventive Maintenand B - PM Level B -	ce Activity Comment	S. (1997)		

•••

•

First Client Departr	<sup>by</sup> First 7 Transit		WorkOrder Palm Tran Connectior v 2.2 Page 1 of 9			kOrder: 51			48955
MRC:		55345M	Equipment:	5450					
WO Desc:						n Crusaders			
PM C Requested By		DCARTER	VIN: Status:	1FDEE3F 40	L1FDA0275	52			
Created By:		DCARTER	Priority:	1					
Class:		WO	Driver:						
Arrangement: Potential War		Unassigned No	Phone: ETA:						
		Chronology	LIA.		1				
Reported		Sep 17	2018	1:00 PM	Meter R	eading UOM			
Started		Sep 17	2018		wo	DH			
Completed	Deurs Time	Sep 17	2018	8:58 PM	Life 20	03,193 DH			
Lawrence and the second	Down Time		WorkOrder No	tec					
Line Com 10 Lof topped o Preventive n Part# b329 Qty1									
Parts Issue Date	ed Part Number		Activity Commen	ts Description			Qty.	Each	Extended
17-Sep-18	65266	PL	JG, DRAIN, OIL, ENGINE				1.00	4.50	4.50
Labor Post	ed								
Date			Technician			Hours	Ra	ate	Extended
17-Sep-18	Owens,Arthur			and a second second second second second		2.50		0.00	0.00
				Parts: Labor: Labor Ho Sublet Par Sublet Lab <b>Activity S</b>	ours: 2.50 ts: 00r:	y 10 Sub	Tota	al	4.50 0.00 0.00 0.00 <b>4.50</b>
Activity: 20 Activity Note: Reason for Re Work Accompl Part Failure:	PM C	e Maintenanc	e Activity Comment	5			•		
Parts Issue	d								
Date	Part Number			Description			Qty.	Each	Extended
17-Sep-18	B329(F)	FIL	TER, OIL SAME AS LF368	1			1.00	1.96	1.96

<b>First</b> Base	55345 Palm	r <b>kOrder</b> Tran Connection v 2.2 e 1 of 9	In		rder: <b>5210</b> b <b>er:</b> 5534	6635	635
MRC: WO Desc: PM C Requested By: Created By: Class: Arrangement: Potential Warranty:	55345M DARTHURS DARTHURS WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:		0 Champion C L1FDA02752	Trusaders		
Reported Started Completed Down Time	Chronology Feb 13, 2019 Feb 13, 2019 Feb 13, 2019		1:50 PM 11:34 PM	Meter Readi WO Life 2227,9 System 228,1	DH 46 DH		
Down Time		U WorkOrder Notes		Joyatem [ 220,1	57 011		
10 PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 Qty1 Transmission fluid 10 Qts Gear Oil 80w90 qty 4 Qts							
Activity: 10 999 TOTAL V Activity Note: Light Mediu Reason for Repair: 05 - Inspect Work Accomplished: 06 - Inspect Part Failure: -	m Duty PMI ion, Routine	Activity Comments					
Parts Issued							
Date Part Number		D	escription		Qh	/. Each E	xtended
Labor Posted	Tec	hnician			Hours	Rate E	xtended
13-Feb-19 Gaspard,Ronald					1.58	0.00	0.00
			Parts: Labor: Labor Ho Sublet Par Sublet Lab <b>Activity S</b>	ours: 1.58 ts: or:	10 Sub To	tal	0.00 0.00 0.00 0.00 <b>0.00</b>
Activity: 20 Activity Note: PM C Reason for Repair: 08 - Preventi Work Accomplished: C - PM Level Part Failure:	ve Maintenance						
Parts Issued		Activity Comments					

<b>Firs</b>	Base	), 5 ,	55345 Palm <sup>-</sup> v	kOrder Tran Connection v 2.2 e 1 of 9		kOrder: 52 mber: 5	525121	
MRC: WO Desc: PM C Requested By Created By: Class: Arrangement: Potential War	<i>י</i> : :	55345M VAMRITT VAMRITT WO Unassigne No	EEMAL	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Champ 1FDEE3FL1FDA02 40 1		ers	
Reported Started Completed	[ [	<b>nology</b> Iul 12, 2019 Iul 12, 2019 Iul 13, 2019		10:24 AM Meter WO 12:04 AM Life System	Reading         UOM           DH         DH           253,609         DH           253,724         DH			
			V	NorkOrder Notes				
Parts#2002 Oil 5W20 Q ATF Fluid (S Gear Oil Qt	ety (6.5) Qt 9.0) Qt							
Activity: 10 Activity Note Reason for Re	<b>999 TO</b> Light Me	<b>TAL VEHICLE</b> edium Duty I pection, Rou						
Activity Note Reason for Re Work Accomp	<b>999 TO</b> Light Me	edium Duty I pection, Rou						
Activity Note Reason for Re Work Accomp Part Failure:	999 To Light Ma epair: 05 - Ins plished: 06 - Ins -	edium Duty I pection, Rou		Activity Comments				
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue	ed	edium Duty I pection, Rou pect						
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date	ed Part Nurr	edium Duty I pection, Rou pect			Description		Qty. Each	Extended
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date Labor Post	ed Part Nurr	edium Duty I pection, Rou pect	Itine	- 	Description	Hours		
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue	ed Part Nurr	edium Duty I pection, Rou pect	Itine		Description	Hours 3.50	Qty. Each Rate 65.00	Extended 227.50
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date Labor Post Date 12-Jul-19	ed Part Num	edium Duty I pection, Rou pect	Itine	- 			Rate 65.00	Extended
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date Labor Post Date 12-Jul-19	ed Part Num ted Arthurs, Durvin PM C	edium Duty I pection, Rou nber	Itine	- 	Activit Parts: Labor: Labor Hours: 3.50 Sublet Parts: Sublet Labor:	3.50	Rate 65.00	Extended 227.50 0.00 227.50 0.00 0.00 0.00
Activity Note Reason for Re Work Accomp Part Failure: Date Date 12-Jul-19	999 TOT:         Light Me         epair:       05 - Insp         plished:       06 - Insp         ed       Part Num         ted	edium Duty I pection, Rou nber	Itine	- 	Activit Parts: Labor: Labor Hours: 3.50 Sublet Parts: Sublet Labor:	3.50	Rate 65.00	Extended 227.50 0.00 227.50 0.00 0.00 0.00
Activity Note Reason for Re Work Accomp Part Failure: Date Date 12-Jul-19	ed Part Num sed Part Num ted Arthurs, Durvin PM C epair: 08 - Pre plished: C - PM L 	edium Duty I pection, Rou nber	Itine	chnician	Activit Parts: Labor: Labor Hours: 3.50 Sublet Parts: Sublet Labor: Activity Sub Total	3.50	Rate 65.00 • Total	Extended 227.50 0.00 227.50 0.00 0.00 227.50
Activity Note Reason for Re Work Accomp Part Failure: Date Date 12-Jul-19	999 TOT:         Light Me         epair:       05 - Insp         plished:       06 - Insp         ed       Part Num         ted	edium Duty I pection, Rou nber	Itenance	chnician	Activit Parts: Labor: Labor Hours: 3.50 Sublet Parts: Sublet Labor:	3.50 y 10 Sub	Rate 65.00	Extended 227.50 0.00 227.50 0.00 0.00 0.00

Firs	by First 🕼 Transit	55345 Pal	orkOrder Im Tran Connection v 2.2 ge 1 of 10	WorkOrder: 53055549 Invoice Number: 55345-53055549					
Client Depart MRC: WO Desc: PM C Requested By Created By: Class: Arrangement Potential Wa	<b>y:</b> ::	55345M RRENE RRENE WO Unassigned No	Equipment: VIN: Status: Priority: Driver: Phone: ETA:	5450 Ford E350 Chamı 1FDEE3FL1FDA02 40 1					
Reported Started Completed	Down Ti	Chronology Dec 30, 20 Dec 30, 20 Dec 30, 20 Dec 30, 20	019 019	3:13 PM 8:23 PM Life	Reading UOM DH 279,577 DH				
,	Comment CE MAINTENANCE AND COMPLETED PMC S	ERVICE	WorkOrder Notes						
		99 TOTAL VEHICLE							
Activity Note Reason for Re Work Accomp Part Failure:	: Light Duty epair: 08 - Preve plished: - -		Activity Comments						
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date	: Light Duty epair: 08 - Preve plished: - - ed Part Numbe	/ PMI Intive Maintenance		escription	1	Qty. Each	Extended		
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date	: Light Duty epair: 08 - Preve plished: - - ed Part Numbe	/ PMI Intive Maintenance		escription	Hours 0.02 0.72 0.45		Extended Extended 1.30 46.80 29.25		
Labor Post Date 30-Dec-19 30-Dec-19	: Light Duty epair: 08 - Preve olished: - - ed Part Numbe ted AMRIT TEEMAL,VISI	/ PMI Intive Maintenance	Đ		Hours 0.02 0.72 0.45 vity 10 Sub 7 9	Rate 65.00 65.00 65.00	Extended 1.30 46.80 29.25 0.00 77.35 0.00 0.00		
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date Labor Post Date 30-Dec-19 30-Dec-19 30-Dec-19 30-Dec-19 Activity: 20	Light Duty epair: 08 - Preve olished: - - ed Part Numbe ted AMRIT TEEMAL,VISI AMRIT TEEMAL,VISI AMRIT TEEMAL,VISI AMRIT TEEMAL,VISI	y PMI entive Maintenance	Đ	Acti Parts: Labor: Labor Hours: 1.1 Sublet Parts: Sublet Labor:	Hours 0.02 0.72 0.45 vity 10 Sub 7 9	Rate 65.00 65.00 65.00	Extended 1.30 46.80 29.25 0.00 77.35 0.00 0.00		
Activity Note Reason for Ro Work Accomp Part Failure: Parts Issue Date 30-Dec-19 30-Dec-19 30-Dec-19 30-Dec-19 30-Dec-19 Activity: 20	Light Duty epair: 08 - Preve olished: - - ed Part Numbe ted AMRIT TEEMAL,VISI AMRIT TEEMAL,VISI	y PMI entive Maintenance	Đ	Acti Parts: Labor: Labor Hours: 1.1 Sublet Parts: Sublet Labor:	Hours 0.02 0.72 0.45 vity 10 Sub 7 9	Rate 65.00 65.00 65.00	Extended 1.30 46.80		
Activity Note Reason for Re Work Accomp Part Failure: Parts Issue Date Labor Post Date 30-Dec-19 30-Dec-19 30-Dec-19 30-Dec-19 Activity: 20	Light Duty epair: 08 - Preve olished: - - ed Part Numbe ted AMRIT TEEMAL,VISI AMRIT TEEMAL,VISI	y PMI entive Maintenance	D Technician	Acti Parts: Labor: Labor Hours: 1.1 Sublet Parts: Sublet Labor:	Hours 0.02 0.72 0.45 vity 10 Sub 7 9	Rate 65.00 65.00 70tal	Extended 1.30 46.80 29.25 0.00 77.35 0.00 0.00		

<b>First</b>		WorkOrder 55345 Palm Tran Connection v 2.2 Page 1 of 12			WorkOrder: 53678929						
Client Department: MRC: WO Desc: 55345-LIGHT DUTY PMC Requested By: Created By: Class: Arrangement: Potential Warranty:		55345 RGASF RGASI WO Unassi No	PARD S PARD P PARD P Igned P	Equipment: /IN: Status: Priority: Driver: Phone: ETA:	5450 Ford E3!	ord E350 Champion Crusaders FDEE3FL1FDA02752 0					
Star	npleted	Down Time	Aug Aug	<b>299</b> 14, 2020 14, 2020 18, 2020		12:00 AM 4:24 PM	WO Life 30	ading 5,361 5,272	UOM DH DH DH		
Acti	Comment PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 10w30 qty 7 Transmission filter 200 Transmission fluid 100 Air filter PA4075 qty1 Gear Oil 80w90 qty 4 ity: 5 y999 vity Note: son for Repair:	)21 qty1 Qts	RISK ASSE	SSMENT							
Wor	* Accomplished: Failure:				ivity Comments						
Par	ts Issued										
	Date	Part Number			De	escription				Qty. Each	Extended
										I I	
Lab	oor Posted										
	Date			Technie	cian			Ho	urs	Rate	Extended
						Parts: Labor: Labor Ho Sublet Part Sublet Lab <b>Activity S</b>	or:	ty 5	Sub	Total	0.00 0.00 0.00 0.00 <b>0.00</b>
Acti Rea Wor	ity: <b>10</b> vity Note: son for Repair: k Accomplished: t Failure:	999/999/999 Light Duty F 08 - Prevent - -	PMI	nance	ivity Comments						
Par	Parts Issued										
	Date	Part Number			De	escription				Qty. Each	Extended