

55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: **51383171 Invoice Number:** 55345-51383171

Client Department:

MRC: 55345M **Equipment:** 5428

WO Desc: Ford E350 Champion Crusaders

PM A VIN: 1FDEE3FLXFDA06816

Requested By:RGASPARDStatus:40Created By:RGASPARDPriority:1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

	Chronology					
Reported	Jun 25, 2018	11:09 AM				
Started	Jun 25, 2018					
Completed	Jun 25, 2018	11:31 PM				
Down						

Meter	Reading	UOM
WO		DH
Life	183,851	DH
System	184,011	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PM A
	CAUSE: Service due
	CORRECTION: Performed and Completed PM A Changed engine oil and replaced engine oil filter Added 6qts engine oil

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Otv.	Each	Extended	ı
Date	i di ci i di ilibei	Beschpton	~c,.	Lacii	LACCITACA	1

Labor Posted

Date	Technician	Hours	Rate	Extended	
25-Jun-18	Delva,Terry	0.55	0.00	0.00	

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51383171 **Invoice Number:** 55345-51383171

Client Department:

MRC: **Equipment:** 5428 55345M

WO Desc: Ford E350 Champion Crusaders

1FDEE3FLXFDA06816 VIN: PM A

Requested By: RGASPARD Status: 40 **Created By: RGASPARD Priority:** 1

Class: WO **Driver: Arrangement:** Unassigned Phone: **Potential Warranty:** ETA: No

Date	Part Number	Description	Qty.	Each	Extended
25-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jun-18	Delva,Terry	1.00	0.00	0.00

Activity 20 Sub Total Parts: 1.96 0.00 Labor: Labor Hours: 1.00 0.00 Sublet Parts: Sublet Labor: 0.00 1.96

Activity Sub Total

Activity: 30

999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jun-18	Delva,Terry	1.00	0.00	0.00

Activ	ity 30 Sub Total
Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	ı
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Tota	0.00

	.,	9.00
	WorkOrder 51383171 Grand	Total
	Parts:	1.96
	Labor:	0.00
	Labor Hours: 2.55	
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	WorkOrder Grand Total	1.96
Recent Repair History		



55345 Palm Tran Connection v 2.2 Page 3 of 9



WorkOrder: **51383171 Invoice Number:** 55345-51383171

Client Department:

MRC: 55345M **Equipment:** 5428

WO Desc: Ford E350 Champion Crusaders

PM A VIN: 1FDEE3FLXFDA06816

Requested By:RGASPARDStatus:40Created By:RGASPARDPriority:1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51383171	25-Jun-18	183,851	WO	PM A
51314227	31-May-18	179,591	WO	PM C
51377155	29-May-18	179,061	WO	Driver said passerger rear tire inner flat

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life	Due Meter	Due Life	Due Meter
				Meter	Reading	Meter 2	Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51149047	29-Mar-18	170,559	WO	Replace front/rear brake pads

PH: Work Order: 51383171 Desc: PM A

Equip: 5428 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA06816

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 25-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,100	Safety Inspection	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,140	Check Service Brakes	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,160	FRA Check Instruments and Horns	Done		TDELVA	Jun 25, 2018 11:23:48 PM	No	
10,170	Check Fast Idle	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
10,180	Check Starter Protection Circuit	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
10,190	Check Reverse Warning System	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,100	Check Parking Brake	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,140	Road Test: Check for Proper Operation	Done		TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,150	Perform Brake Test	Done		TDELVA	Jun 25, 2018 11:23:49 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,170	FRA Check Door Operation	Done		TDELVA	Jun 25, 2018 11:23:50 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		TDELVA	Jun 25, 2018 11:23:50 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		TDELVA	Jun 25, 2018 11:23:50 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,230	FRA Check Wiring Under Dash	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,240	FRA Check Interior Lights	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,260	Check Stop Request System	-	NA	TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jun 25, 2018 11:23:51 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
22,110	Check Emergency Hatches	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
22,120	Check All Safety Equipment	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,310	Check Passenger Doors	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,330	Check Wheelchair Lift Operation	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,360	Check for Physical Damage and Decals	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
30,380	Check Exterior Compartment Doors	Done		TDELVA	Jun 25, 2018 11:23:52 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
33,100	Check Lights and Reflectors	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jun 25, 2018 11:23:53 PM	No	
40,420	Check Hood	Done		TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		TDELVA	Jun 25, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:23:54 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	TDELVA	Jun 25, 2018 11:23:53 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		TDELVA	Jun 25, 2018 11:23:54 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,130	FRA Check Exhaust System	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,140	FRA Check Intake System	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jun 25, 2018 11:23:55 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
44,180	FRA Check for Leaks	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
44,190	FRA Perform Battery Inspection	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
50,510	Check Entire Steering System	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
60,610	FRA Check and Record Air Pressure	Done		TDELVA	Jun 25, 2018 11:23:56 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,620	Check Valve Stems and Caps	Done		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,630	Check and Record Tread Depth	Done		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,631	Tread Depth RF	9 32nds of an inch		TDELVA	Jun 25, 2018 11:23:57 PM	No	
60,632	Tread Depth LF	9 32nds of an inch		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,633	Tread Depth RRO	11 32nds of an inch		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,634	Tread Depth RRI	10 32nds of an inch		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,635	Tread Depth LRI	10 32nds of an inch		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,650	Check Sidewall Wear	Done		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,660	Inspect for Cuts and Tears	Done		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,670	Check Dual Mating With Square	-	NA	TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jun 25, 2018 11:23:58 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,710	Check Vibration Damper	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,720	Check Engine and Transmission Mounts	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,730	FRA Check Starter	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,750	FRA Check Transmission for Leaks	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
70,770	FRA Check Exhaust System	Done		TDELVA	Jun 25, 2018 11:23:59 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		TDELVA	Jun 25, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:24:00 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,110	FRA Check Fuel Tank	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,120	Check Suspension Components	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,131	Brake Pad Thickness LF	6 Inch		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,132	Brake Pad Thickness RF	6 Inch		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,133	Brake Pad Thickness LR	4 Inch		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,134	Brake Pad Thickness RR	5 Inch		TDELVA	Jun 25, 2018 11:24:00 PM	No	
77,135	Brake Rotor LF	39.8 Inch		TDELVA	Jun 25, 2018 11:24:01 PM	No	
77,136	Brake Rotor RF	39.8 Inch		TDELVA	Jun 25, 2018 11:24:01 PM	No	
77,137	Brake Rotor LR	1.67 Inch		TDELVA	Jun 25, 2018 11:24:01 PM	No	
77,138	Brake Rotor RR	1.67 Inch		TDELVA	Jun 25, 2018 11:24:01 PM	No	
77,140	FRA Check Brake Hoses	Done		TDELVA	Jun 25, 2018 11:24:01 PM	No	
77,150	Check King Pins	-	NA	TDELVA	Jun 25, 2018 11:24:02 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jun 25, 2018 11:24:01 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		TDELVA	Jun 25, 2018 11:24:01 PM	No	
80,810	Completion of PMI Report	Done		TDELVA	Jun 25, 2018 11:24:02 PM	No	
90,000	SECTION 9 Completion of PMI	Done		TDELVA	Jun 25, 2018 11:24:02 PM	No	
90,910	Vehicle Returned to predetermined location	Done		TDELVA	Jun 25, 2018 11:24:02 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: TDELVA Performed on: 25-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	Jun 25, 2018 11:18:56 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	Jun 25, 2018 11:18:56 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	Jun 25, 2018 11:18:56 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	Jun 25, 2018 11:18:56 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	Jun 25, 2018 11:18:57 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	Jun 25, 2018 11:18:57 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	TDELVA	Jun 25, 2018 11:18:57 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	Jun 25, 2018 11:18:57 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 25-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 25, 2018 11:18:27 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection v 2.2 Page 1 of 9

WorkOrder: **51657345 Invoice Number:** 55345-51657345

Client Department:

MRC: WO Desc:

Requested By:

Created By:

Completed

10

PM A

55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

CVERGARA CVERGARA VIN: Status:

40

CVE WO

Down Time

Priority: Driver: 1

Class: Arrangement: Potential Warranty:

Unassigned No

Phone: ETA:

	Chronology
Reported	Sep 24,
Started	Sen 24

Sep 24, 2018 Sep 24, 2018 Sep 25, 2018 9:52 AM W

Meter Reading UOM WO DH Life 197,008 DH System 197,195 DH

WorkOrder Notes

Line Comment

COMPLAINT:PmA

CAUSE:Service

CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10
Activity Note:

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Sep-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 1.55

0.00

Sublet Parts: Sublet Labor: 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A Reason for Repair: 08 - P

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty.	Each	Extended
24-Sep-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51917791 **Invoice Number:** 55345-51917791

Client Department:

MRC: WO Desc:

Started

Completed

55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

PM A Requested By:

RGASPARD RGASPARD Status: **Priority:**

VIN:

40 1

Created By: Class: **Arrangement:**

WO Unassigned No

Chronology

Driver: Phone: ETA:

Reported

Potential Warranty:

Dec 14, 2018 Dec 14, 2018 Dec 14, 2018

1:43 PM Life 11:59 PM

Meter Reading UOM WO DH 209,355 DH System 209,499 DH

WorkOrder Notes

Line Comment

COMPLAINT: PMA

CAUSE:Service

CORRECTION: Perform PMA Service Oil filter B339 qty 1 Air filter PA4075 gty1 Engine oil 5W20Qty qty 7 Qts

Activity: 10

999 TOTAL VEHICLE

Down Time

Activity Note: Reason for Repair:

Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date

Part Number

Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Dec-18	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.57 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20 **Activity Note:** 999 TOTAL VEHICLE

Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

VIN:

Status:

Page 1 of 9



WorkOrder: 51998726 Invoice Number: 55345-51998726

Client Department:

MRC: WO Desc:

Reported

Completed

Started

PM A

Requested By: Created By: Class: **Arrangement:**

Potential Warranty:

RGASPARD

55345M

RGASPARD WO Unassigned

Priority: Driver: Phone: ETA:

1

Chronology Jan 15, 2019 10:07 AM Jan 15, 2019 Jan 16, 2019 12:06 AM

Equipment:

Down Time

Meter	Reading	UOM
WO		DH
Life	213,278	DH
System	213,463	DH

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

WorkOrder Notes

Line Comment

COMPLAINT:pmA 10

CAUSE:Service

CORRECTION: Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **Activity Note:**

Reason for Repair:

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Qty. Each Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Jan-19	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.58 Sublet Parts:

0.00

Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date	Part Number	Description	Qty. Each Exten		
15-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52166438
Invoice Number: 55345-52166438

Client Department:

MRC:

55345M

Equipment:

5428

WO Desc: PM A

CVERGARA

VIN: Status:

Phone:

ETA:

1FDEE3FLXFDA06816 40

Requested By: Created By: Class:

CVERGARA WO

Priority: Driver:

Arrangement: Potential Warranty:

Unassigned No 1

Chronology
Reported | Mar 13, 2019 | 9:46 AM

Started Completed Mar 13, 2019 Mar 14, 2019

12:09 AM

 WO
 DH

 Life
 221,688
 DH

 System
 221,857
 DH

Reading

UOM

Ford E350 Champion Crusaders

Meter

Down Time

WorkOrder Notes

Line Comment

10 COMPLAINT:pmA

CAUSE: Service

CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty7 Qts Drain plug oil 65266 Qty1

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number

Description

Otv. Ea

Each Extended

Labor Posted

	13-Mar-19	Gaspard,Ronald	1.60	0.00	0.00	
1	Date	Technician	Hours	Rate	Extended	

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 1.60 Sublet Parts: Sublet Labor:

0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52251294 Invoice Number: 55345-52251294

Client Department:

MRC: WO Desc:

55345M

Equipment:

5428

12:25 PM

12:14 AM

1

Ford E350 Champion Crusaders

PM A Requested By:

RGASPARD

VIN: Status:

1FDEE3FLXFDA06816 40

Created By: Class:

Reported

Completed

Started

Line

10

RGASPARD WO

Priority:

Arrangement: Potential Warranty:

Unassigned No

Chronology

Apr 11, 2019

Apr 11, 2019

Apr 12, 2019

Driver: Phone: ETA:

Meter	Reading	UOM	
VO		DH	
ife	225 853	DH	

Down Time

WorkOrder Notes

Comment

COMPLAINT: pmA

CAUSE: Service

CORRECTION: Perform pmA Service Oil filter B329 qty 1

Engine oil 5w20 qty7 Qts Replaced AC filter

Rotate tires and washed rims

Torque wheels 140 lbs second torque 140 lbs

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended

Labor Posted

Date	Technician	Hours	Rate E	xtended
11-Apr-19	Gaspard,Ronald	2.42	0.00	0.00

10 Sub Tota

MCHAILA TO	Jub	i Viai
Parts:		0.00
Labor:		0.00
Labor Hours: 2.42		
Sublet Parts:		0.00
Sublet Labor:		0.00
Activity Sub Total		0.00

Activity: 20

Reason for Repair:

999 TOTAL VEHICLE

Activity Note: PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-52438451

UOM

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders 1FDEE3FLXFDA06816

Meter

PM A Requested By:

RGASPARD RGASPARD Status: **Priority:** 40 1

Created By: Class:

WO

Driver:

Arrangement: **Potential Warranty:**

Unassigned No

Phone: ETA:

VIN:

X				34	8	7		3		r
Ô		į.	Š			Š		ŝ		l
•	>٠		į	5	C)	V	1		
- 4	-		٠.	,	3		٠.			5

Reported Started Completed Chronology Jun 17, 2019 Jun 17, 2019 Jun 18, 2019

12:06 AM

wo		DH
Life	234,787	DH
Cuctom	234 003	DН

Reading

WorkOrder Notes

Line Comme	

COMPLAINT:pmA

CAUSE: Service

CORRECTION: Perform pmA Service

Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10

999 TOTAL VEHICLE

Down Time

Activity Note: Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Nu	umber	Description	Qty. Each Extended
The brief of the first and the brief of the	and the contract of the contra		00 \$00 \$0.77 \$17 \$0 \$1 \$4 \$6 \$1 \$2 \$6 \$1 \$2 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1 \$1

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Jun-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts: Labor:

0.00 104.00

Labor Hours: 1.60 Sublet Parts:

0.00 0.00

Sublet Labor: **Activity Sub Total**

104,00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM A

08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Date Part	lumber Description	Qty. Each Extended
17-Jun-19 B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-52525458

UOM

DΗ

DH

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

PM A Requested By:

RGASPARD

40 1

Created By:

RGASPARD WO

Priority:

Class: Arrangement:

Reported

Completed

Started

Unassigned

Chronology

Jul 19, 2019

Jul 19, 2019

Jul 22, 2019

Driver: Phone:

Potential Warranty:

No

ETA:

VIN:

Status:

3:11 PM	Meter	Reading
	wo	
7:33 AM	Life	239,033

Down Time

WorkOrder Notes

line Commont	10	COMMEN
아들보는 어느가 못 하는데, 그리가 가게 하는데 하는데 하다.	une	Comment

CAUSE: Service

CORRECTION: Perform pmA Service Oil filter B329 gty1 Engine oil 5w20 qty 7qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part N	lumber	Descriptio	n	Qty	y. Each Extended

Labor Posted

-	Date	Technician	resembled to	Hours	Rate	Extended	
	19-Jul-19	Gaspard,Ronald		1.67	65.00	108.33	
		**	erang in recommanders in constructed contragation			a commence of the second	

Activity 10 Sub Total

Parts: Labor:

0.00 108.33

Labor Hours: 1.67 Sublet Parts:

0.00

Subjet Labor:

00.0 108.33

Activity Sub Total

Activity: 20 **Activity Note:**

999 TOTAL VEHICLE PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

19-Jul-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.	96 1.96
Date	Part Number	De	escription Qty. Ea	ch Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52704812 **Invoice Number: 55345-52704812**

Client Department:

MRC:

55345M

Equipment:

5428

WO Desc: PM A

10

VIN:

Ford E350 Champion Crusaders 1FDEE3FLXFDA06816

Meter

Requested By:

AOWENS AOWENS Status: **Priority:** 40 1

Created By: Class:

WO

Driver:

Arrangement: Potential Warranty:

Unassigned No

Phone: ETA:

Chronology Reported

Sep 24, 2019 Started Sep 24, 2019 Completed Sep 24, 2019 12:18 PM 8:52 PM

WO Life 247,629

Reading

MOU

DH

DH

Down Time

WorkOrder Notes

Line Comment

COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description	n Qty. Each Extended

Labor Posted

Date	Technician	н	ours	Rate E	extended
24-Sep-19	AMRIT TEEMAL, VISHNU		1.50	65.00	97.50

Activity 10 Sub Total

Parts: 0.00 Labor: 97.50 Labor Hours: 1.50 Sublet Parts: 0.00 Sublet Labor: 0.00

97.50

Activity Sub Total

Activity: 20 **Activity Note:**

Reason for Repair:

999 TOTAL VEHICLE

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Color and Artis	Date	Part Number	Description	Qty.	Each	Extended
į	24-Sep-19 B3	329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
1		A. S. C.			- Frank State	and the second of



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52829493 **Invoice Number: 55345-52829493**

Client Department:

MRC:

55345M

Equipment:

5428

WO Desc: PM A

Meter

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

MOU

Requested By: Created By:

VAMRITTEEMAL VAMRITTEEMAL Status:

40

Class: **Arrangement:** WO

Priority: Driver: Phone:

Potential Warranty:

Unassigned

ETA:

VIN:

No Chronology

Oct 23, 2019 Oct 24, 2019 Oct 24, 2019 5:09 PM

10:03 AM

Down Time

wo DH Life 252,004 DH System 252,004 DH

Reading

1

WorkOrder Notes

Line 10 PM.

Reported

Completed

Started

Comment

Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1 engine oil, 5W20 Qty 6 qts

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments

Parts Issued

Date Pa	Part Number	Description	Qty, Each Extended

Labor Posted

1	Date	Technician		Marka da	Extended	
	24-Oct-19	Rodriguez, Raul	1.60	65.00	104.00	ļ

Activity 10 Sub Total

Parts: 0.00 Labor: 104.00

Labor Hours: 1.60 Subjet Parts:

0.00 Sublet Labor: 0.00 104.00

Activity Sub Total

999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity: 20

Activity Comments

	Account on a construction of the second second second		للمراجع والمراجع والمستنين والمستران والمستران والمستران والمراجع والمتراث		برسيكين بترسره ويتريك ويكانون ويتناه بينا أأري	arrente de la companya de la company
1	24-Oct-19	B329(F)	FILTER, OIL	SAME AS LF3681	1.00 1.96	1.96
÷			f			
1	Date	Part Number		Description	Qty. Each E	xtended
	\$1000000000000000000000000000000000000					



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53042813 Invoice Number: 55345-53042813

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

MOU

1FDEE3FLXFDA06816

PM A Requested By:

DARTHURS

Status:

40

Reading

Created By: Class:

DARTHURS WO Unassigned

Priority: Driver:

1

Meter

Arrangement: Potential Warranty:

No

Phone: ETA:

VIN:

Completed	Jan 3, 2020 Jan 3, 2020	10:33 PM
Started	•	
Reported	Jan 3, 2020	1:09 PM
	Chronology	

wo DH Life 260,317 DH

WorkOrder Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage,

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brake. Clean / Check batteries. Replace drain plugs.

Comment

Parts # 65266 Qty (1) Parts # B329. Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Down Time

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended

Labor Posted

	Date	Technician	Hours	Rate	Extended	The same
	03-Jan-20	Arthurs, Durvin	2.13	0.00	0.00	
1 horn		Tarang and a specific and the second	المراجع والمراجع والمراجع والمراجع والمراجع			싵

Activity 10 Sub Total

0.00 Parts: Labor: 0.00 Labor Hours: 2.13 Sublet Parts: 0.00 Sublet Labor: 0.00 **Activity Sub Total** 0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair: PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-53148254

Client Department:

MRC:

55345M

Equipment:

5428

40

1

WO Desc:

Ford E350 Champion Crusaders 1FDEE3FLXFDA06816

PM A Requested By: Created By:

DARTHURS DARTHURS Status: **Priority:**

Class: **Arrangement:** WO

Unassigned

Driver: Phone:

Potential Warranty:

No

ETA:

VIN:

Reported	Feb 5, 2020	7:07 AM
Started	Feb 5, 2020	
Completed	Feb 5, 2020	12:48 PM

Chronology

Life	264,527	DH
wo		DH
	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	~~

Meter Reading LIOM

Down Time

WorkOrder Notes

1,000,000,000	
Line	Comment
	1
10	COMPLAINT:
1	CAUSE:
-	CORRECTION:
	CONRECTION:
20	PM.
20	F ¹⁷ ,
2	
1	Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.
Ì	, and the state of
1	Parks Facing all filters and # 2000 at 4
1	Parts. Engine oil filter part # 8329 qty 1
	engine oil, 5W20 Oty 6 gts
A	5 7

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

A	Date	Technician	Hours		Extended
	05-Feb-20	Rodriguez,Raul	1.93	0.00	0.00
2.79	engineering exemple and equipment on exemple of		alia accordinata a constitui a constitui della constitui di constitui	A. s. s. 41 . s. s. 41	

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.93 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 53356607 **Invoice Number: 55345-53356607**

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

Reading UOM

PM A Requested By: Created By:

RGASPARD RGASPARD Status: **Priority:** 40 1

Meter

Class: Arrangement:

WO Unassigned No

Driver: Phone:

Potential Warranty:

ETA:

VIN:

Down Tim		
Completed	Apr 28, 2020	4:18 PM
Started	Apr 26, 2020	
 Reported	Apr 24, 2020	11:28 AM
	hronology	

wo		DH
Life	272,769	DH
System	272,768	DH

WorkOrder Notes

Line 10

COMPLAINT: Perform PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube All Pivoting Points. Check Brakes. Clean Batteries. Replace A/C Filter. parts # B 329 Qty (1) Oil 10W20 Qty (6.5) Qt.

Comment

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure:

Activity Comments

Parts Issued

Dal	re .	Part Nu	nber			Descripti	on		Qty.	Each Ex	ended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Apr-20	Arthurs, Durvin	0.02	0.00	0.00
26-Apr-20	Arthurs, Durvin	1.63	0.00	0.00

Activity 10 Sub Total

Activity Sub Total	0.00
Sublet Labor:	0.00
Sublet Parts:	0.00
Labor Hours: 1.65	
Labor:	0.00
Parts:	0.00

Activity: 20

Reason for Repair:

999 TOTAL VEHICLE

Activity Note: PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53558557 **Invoice Number: 55345-53558557**

Client Department:

MRC: WO Desc:

55345-LIGHT DUTY PMA

Requested By: Created By:

Class: Arrangement:

Reported

Completed

Started

Potential Warranty:

55345M

NSTOLFO

NSTOLFO

Unassigned

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

40

3

No

WO

Driver: Phone: ETA:

Status:

Priority:

VIN:

Chronology

Jun 29, 2020 Jun 29, 2020 Jun 30, 2020

12:00 AM 12:29 AM

Meter Reading MOU wo DH Life 277,036 DH

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA
	CAUSE: Service
	CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 Qts

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date Part Number Description

Rate

Qty. Each Extended

Labor Posted

Date

Technician

Hours

Extended

Activity 5 Sub Total

Parts: Labor: Labor Hours: 0.00 Sublet Parts:

Sublet Labor:

0.00 0.00

0.00

0.00

Activity Sub Total

0.00

Activity: 10 **Activity Note:**

999/999/999 TOTAL VEHICLE

Light Duty PMI Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Each Extended

Labor Posted



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53787683 **Invoice Number:** 55345-53787683

UOM

Client Department:

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

5428

Ford E350 Champion Crusaders

55345-LIGHT DUTY PMA

DARTHURS

1FDEE3FLXFDA06816

Requested By: Created By: Class:

DARTHURS WO

Status: **Priority: Driver:**

40 3

Arrangement: Potential Warranty: Unassigned No

Sep 28, 2020

Sep 28, 2020

Sep 29, 2020

Chronology

Phone: ETA:

VIN:

	Meter
12:00 AM	WO

Ю Life 12:06 AM

DH 285,880 DH System 285,998 DH

Reading

Down Time

WorkOrder Notes

Line	Comment

10 COMPLAINT:PMA

CAUSE:Service

CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

65266 qty1

Replaced marker lights left and right qty2

Activity: 5

999/999/999 TOTAL VEHICLE

PERSONAL RISK ASSESSMENT **Activity Note:**

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Part Number Description Extended Date Qty. Each

Labor Posted

Technician Extended Date Hours Rate

Activity 5 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 10 **Activity Note:**

999/999/999 TOTAL VEHICLE

Light Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Part Number Each Extended Description



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53913638 **Invoice Number:** 55345-53913638

Client Department:

MRC: WO Desc:

Started

55345M

Equipment:

5428

Ford E350 Champion Crusaders

VIN:

1FDEE3FLXFDA06816

UOM

55345-LIGHT DUTY PMA **Requested By:**

RGASPARD RGASPARD Status: **Priority:**

Meter

40 3

Created By: Class: **Arrangement:**

WO Unassigned **Driver:** Phone: ETA:

Potential Warranty: No

Down Time

Chronology Reported Nov 17, 2020 12:00 AM Nov 18, 2020 Completed Nov 19, 2020 7:55 AM

WO DH Life 290,365 DH 290,365 DH System

Reading

WorkOrder Notes

Comment

Line 10 COMPLAINT: PMA Service CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries replace A/C Filter. Rotate both front to R/R Swap Both L/R

New On Front

Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt

Activity: 5

999/999/999 TOTAL VEHICLE

PERSONAL RISK ASSESSMENT **Activity Note:**

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Part Number Extended Date Description Qty. Each

Labor Posted

Technician Extended Date Hours Rate

Activity 5 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

Activity Sub Total

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Date Part Number	Description	Qty.	Each	Extended
------------------	-------------	------	------	----------



55345 Palm Tran Connection v 2.2

Page 1 of 9

VIN:



WorkOrder: 51540594 **Invoice Number: 55345-51540594**

MOU

DH

DH

DH

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

Meter

Reading

192,544

192,544

1FDEE3FLXFDA06816

PM B Requested By: Created By:

TDELVA TDELVA WO

Status: **Priority:** Driver:

40 1

Class: Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Completed	Aug 27, 2018	7:55 AM
Started	Aug 24, 2018	
Reported	Aug 23, 2018	1:20 PM
	Chronology	

1:20 PM	wo
7:55 AM	Life
	System
	7:55 AM

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:
20	PmB
	Preventive maintenance
	Perform service lube all Pivoting Points cross Rotate Tires completed

Down Time

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Qty. Eac	h Extended
	cedification and introduction and and

Labor Posted

24-Aug-18	Pierre,Hubert J	<u> </u>	6.00	0.00	0.00	Service and
Date	Technician		Hours	Rate E	ktended	

Activity 10 Sub Total

	LY WAD I VOOL
Parts:	0.00
Labor:	0.00
Labor Hours: 6.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52083143 Invoice Number: 55345-52083143

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

PM B Requested By:

RGASPARD RGASPARD Status:

32

Created By: Class:

Completed

RGAS WO Priority: Driver: 1

Arrangement:
Potential Warranty:

Unassigned No Phone:

ETA:

VIN:

Feb 12, 2019 Feb 13, 2019 7:35 AM 9:23 AM
 Meter
 Reading
 UOM

 WO
 DH

 Life
 217,629
 DH

Down Time

WorkOrder Notes

Line 10 COMPLAINT: pmB

CAUSE: Preventive Maintenance

CORRECTION: Perform Service lube all Pivoting Points cross rotate tires completed

Comment

Activity: 10 Activity Note:

999 TOTAL VEHICLE Light Mediun Duty PMI 08 - Preventive Maintenance

Reason for Repair: 08 - Preventi Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Qty. Each Extended

Labor Posted

Date	<u>Technician</u>	•	Hours	anna ann an ann an ann an an an an an an	xtended
12-Feb-19	Pierre, Hubert J	Ì	8.00	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00

Labor Hours: 8.00 Sublet Parts:

0.00

Subject Faires.
Subject Faires.

0.00

Activity Sub Total

0.00

Activity: 20 Activity Note:

999 TOTAL VEHICLE

Reason for Repair: (

PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments

ļ.,,,	12-Feb-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96	-
	12 8-6 10	D220(E)	TYL THE ON ALLES AND THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OW	· Fried Andread Street	ner) annihoner erenniger	material material and a second	
	Date	Par	t Number Description	Qty.	Each	Extended	



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52621844 **Invoice Number:** 55345-52621844

UOM

Client Department:

MRC: WO Desc:

PM B

55345M

Equipment:

5428

Ford E350 Champion Crusaders

Meter

1FDEE3FLXFDA06816

Requested By: Created By:

RRENE RRENE Status: Priority: 32 1

Class:

WO

Driver:

Phone:

Arrangement: Potential Warranty:

Unassigned No

ETA:

VIN:

	Chronology	
Reported	Aug 19, 2019	2:20 PM
Started	Aug 19, 2019	
Completed	Aug 19, 2019	9:35 PM

Reading WO DH Life 243,276 DH

Down Time

WorkOrder Notes

Line	Comment	
10	COMPLAINT: PMB SERVICE	
1		

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMB SERVICE

REPLACED AIR FILTER

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date	Part Num	ber	Description	Qty. Each Extended	

Labor Posted

Date	Technician	Н	ours	Rate E	xtended	
 19-Aug-19	AMRIT TEEMAL, VISHNU		1.50	65.00	97.50	
	and the state of t	era a servicia a sumprição agração, a campa a c	فالمحتدد فالتحصيحي ويصبيها	حديث فعده بتعلقت عدوهم ووووجا	an sampan sa sa anaf	. :

Activity 10 Sub Total

Parts: 0.00 Labor: 97.50 Labor Hours: 1.50 Sublet Parts: 0.00

Sublet Labor: **Activity Sub Total**

0.00 97.50

Activity: 20 999 TOTAL VEHICLE **Activity Note:** PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

Activity Comments

	Date	Part Number	Description	Qty.	Each	Extended	
	19-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96	ì
ç			\$ \$ ^ # 1000 #	www.are			į.



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51314227 Invoice Number: 55345-51314227

Meter

System

WO

Life

Reading

179,591

179,801

UOM

DH

DH

DH

Client Department:

MRC: 55345M **Equipment:** 5428

WO Desc: Ford E350 Champion Crusaders PM C VIN: 1FDE3FLXFDA06816

Requested By:DCARTERStatus:40Created By:DCARTERPriority:1

Class: WO Driver:
Arrangement: Unassigned Phone:
Potential Warranty: No ETA:

	Chronology	
Reported	May 30, 2018	2:25 PM
Started	May 31, 2018	
Completed	May 31, 2018	12:20 AM
Do		

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear oil 80w90 qty 4 Qts Drain plug oil F75Z-6730-BA qty1

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended	ı
------	-------------	-------------	------	------	----------	---

Labor Posted

Date	Technician	Hours	Rate	Extended
31-May-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51314227 Invoice Number: 55345-51314227

Client Department:

MRC: **Equipment:** 5428 55345M

WO Desc: Ford E350 Champion Crusaders 1FDEE3FLXFDA06816

VIN: PM C

Requested By: DCARTER Status: 40 **Created By: DCARTER Priority:** 1

Class: WO **Driver: Arrangement:** Unassigned Phone: **Potential Warranty:** ETA: No

Date	Part Number	Description	Qty.	Each	Extended
31-May-18	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.26	17.26
31-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
31-May-18	Gaspard,Ronald	2.00	0.00	0.00

Activity 20 Sub Total Parts: 19.22 Labor: 0.00 Labor Hours: 2.00 Sublet Parts: 0.00 Sublet Labor: 0.00 **Activity Sub Total** 19.22

Activity: 30 **Activity Note:**

999 TOTAL VEHICLE

PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

	Date	Part Number	Description	Qty.	Each	Extended	
--	------	-------------	-------------	------	------	----------	--

Labor Posted

Date	Technician	Hours	Rate	Extended	
31-May-18	Gaspard,Ronald	0.28	0.00	0.00	

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.28	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51314227 Grand Total	
Parts:	19.22
Labor:	0.00
Labor Hours: 3.83	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	19.22



55345 Palm Tran Connection v 2.2 Page 3 of 9



WorkOrder: 51314227 Invoice Number: 55345-51314227

Client Department:

MRC: 55345M **Equipment:** 5428

WO Desc: Ford E350 Champion Crusaders PM C VIN: 1FDEE3FLXFDA06816

Requested By:DCARTERStatus:40Created By:DCARTERPriority:1

WorkOrdor

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

Recent Rep	Recent Repair History										
WorkOrder	Date Completed	Life Meter	Class Description								
51314227	31-May-18	179,591	WO	PM C							
51377155	29-May-18	179,061	WO	Driver said passerger rear tire inner flat							
51323615	9-May-18	175,962	WO	Spark plug / alternator bracket / front Heater core hoses							

Scheduled Preventative Maintenance

Motor Donding Motor 2	INCSL		Due Date	Due Life	Due Meter	Due Life	Due Metel
Meter Reading Meter 2				Meter	Reading	Meter 2	Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51149047	29-Mar-18	170,559	WO	Replace front/rear brake pads

PH: Work Order: 51314227 Desc: PM C

Equip: 5428 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FLXFDA06816

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 30-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,100	Safety Inspection	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	May 30, 2018 11:53:24 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	May 30, 2018 11:53:25 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	May 30, 2018 11:53:26 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	RGASPARD	May 30, 2018 11:53:26 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	RGASPARD	May 30, 2018 11:53:26 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	RGASPARD	May 30, 2018 11:53:26 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 30, 2018 11:53:27 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 30, 2018 11:53:26 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	May 30, 2018 11:53:28 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	May 30, 2018 11:53:27 PM	No	
20,260	Check Stop Request System	-	na	RGASPARD	May 30, 2018 11:53:28 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 30, 2018 11:53:28 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 30, 2018 11:53:28 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 30, 2018 11:53:28 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	May 30, 2018 11:53:28 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 30, 2018 11:53:29 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	May 30, 2018 11:53:29 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 30, 2018 11:53:30 PM	No	
40,420	Check Hood	Done		RGASPARD	May 30, 2018 11:53:31 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	May 30, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:53:31 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 30, 2018 11:53:31 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 30, 2018 11:53:31 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	RGASPARD	May 30, 2018 11:53:31 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 30, 2018 11:53:31 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 30, 2018 11:53:31 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 30, 2018 11:53:32 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	May 30, 2018 11:53:32 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,150	FRA Inspect Turbocharger	-	na	RGASPARD	May 30, 2018 11:53:33 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	May 30, 2018 11:53:33 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:34 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:34 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 30, 2018 11:53:35 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	May 30, 2018 11:53:35 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	May 30, 2018 11:53:35 PM	No	
60,631	Tread Depth RF	10 32nds of an inch		RGASPARD	May 30, 2018 11:53:35 PM	No	
60,632	Tread Depth LF	11 32nds of an inch		RGASPARD	May 30, 2018 11:53:35 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,634	Tread Depth RRI	6 32nds of an inch		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,635	Tread Depth LRI	6 32nds of an inch		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,636	Tread Depth LRO	5 32nds of an inch		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 30, 2018 11:53:36 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	May 30, 2018 11:53:37 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 30, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:53:38 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 30, 2018 11:53:38 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,135	Brake Rotor LF	38 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,136	Brake Rotor RF	38 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,137	Brake Rotor LR	36 Inch		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,138	Brake Rotor RR	36 Inch		RGASPARD	May 30, 2018 11:53:40 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	May 30, 2018 11:53:39 PM	No	
77,150	Check King Pins	-	na	RGASPARD	May 30, 2018 11:53:40 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 30, 2018 11:53:40 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	May 30, 2018 11:53:40 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	May 30, 2018 11:53:40 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	May 30, 2018 11:53:40 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	May 30, 2018 11:53:40 PM	No	

LH: 20 Desc: PM C

Task: PM C SERVICE Performed by: RGASPARD Performed on: 30-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	May 30, 2018 11:55:28 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	May 30, 2018 11:55:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	May 30, 2018 11:55:28 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	May 30, 2018 11:55:28 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	May 30, 2018 11:55:29 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	May 30, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:55:29 PM		
107,000	FRA Change Primary Fuel Filter	-	na	RGASPARD	May 30, 2018 11:55:29 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	May 30, 2018 11:55:29 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	May 30, 2018 11:55:29 PM	No	
201,000	Service Crankcase Breather	Done		RGASPARD	May 30, 2018 11:55:29 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		RGASPARD	May 30, 2018 11:55:29 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		RGASPARD	May 30, 2018 11:55:30 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	May 30, 2018 11:55:30 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	May 30, 2018 11:55:30 PM	No	
301,000	Check and Lubricate Door Linkages	Done		RGASPARD	May 30, 2018 11:55:30 PM	No	
302,000	Check Toe-In and Record Reading	-	na	RGASPARD	May 30, 2018 11:55:30 PM	No	
302,001	Record Toe-In Reading	Inches, fraction- actual	na	RGASPARD	May 30, 2018 11:55:30 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	May 30, 2018 11:55:31 PM	No	
305,000	FRA Change Differential Fluid	Yes		RGASPARD	May 30, 2018 11:55:30 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 30, 2018 11:55:59 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection v 2.2

Page 1 of 9



Invoice Number: 55345-51830784

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

PM C Requested By:

RGASPARD RGASPARD Status:

VIN:

32 1

Created By: Class:

Completed

WO Unassigned **Priority: Driver:**

Phone:

Arrangement: Potential Warranty:

ETA:

Started	Nov 16, 3
Reported	Nov 16,
	Chronology

16, 2018 Nov 16, 2018 Nov 16, 2018 11:51 AM 11:34 PM

Meter	Reading	UOM
wo		DH
Life	205,228	DH

Down Time WorkOrder Notes

Comment Line 10 PMC Service

Perform PMC Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Gear Oil 80w90 gty 4 Qts

Activity: 10 **Activity Note:**

Reason for Repair:

999 TOTAL VEHICLE

Light Medium Duty PMI 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

	Date	Technician	Hours	Rate	Extended
	16-Nov-18	Gaspard,Ronald	1.57	0.00	0.00
4 500		тысыну тышке кылимик емету кеменулганда и инимика калышта и ишини икезу могу и карилиу ишини из улана улан калыктын из инимика и ишини из улан жайын из ишини иши	أتحصيف جويدينا ويتجرعون	والأخرية بترواء والمستوان والمحاجبة	oninggon en egong (

Activity 10 Sub Total

0.00 Parts: 0.00 Labor: Labor Hours: 1.57

Sublet Parts: Sublet Labor: **Activity Sub Total** 0.00 0.00

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note:

PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments

Date	Part Number	Description	Qty. Each Extended
16-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 52337168 **Invoice Number:** 55345-52337168

Client Department:

MRC: WO Desc: 55345M

Equipment:

5428

1

Ford E350 Champion Crusaders

Meter

PM C Requested By:

RGASPARD RGASPARD Status:

1FDEE3FLXFDA06816 40

Created By: Class:

Completed

WO

Priority: Driver:

Arrangement: **Potential Warranty:**

Unassigned No

Phone: ETA:

VIN:

Chronology Reported May 15, 2019 Started

May 16, 2019 May 17, 2019 12:00 AM 12:16 AM wo DH Life 230,570 DH 230,570 System DH

Reading

MOU

Down Time

WorkOrder Notes

Line	Comment
10	PMC
	Service
	Perform PMC service
	Oil filter B329 Qty1
	Engine oil 5w20 qty 7 Qts
	Transmission fluid 10 Qts
	Transmission filter 20021 Qty1

Gear Oil 80W90 qty 4 qts

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description

Each Extended

Labor Posted

	Date		Technician	(transfer the money be able to the engine engine or transfer by booking). As	1	lours		xtended	
- 1	16-May-19	Gaspard,Ronald			7	1.60	65.00	104.00	
	franciska sagaran, sanganaran	elis, ceres e en como en enconocione con en enconociones en	 	 	and the second of the second		and the second of the second of		

Activity 10 Sub Total

Parts:

Labor:

0.00 104.00

Labor Hours: 1.60

Sublet Parts: Sublet Labor: 0.00 0.00

Activity Sub Total

104.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: Reason for Repair:

PM C

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52928954 **Invoice Number:** 55345-52928954

Client Department:

MRC:

55345M

Equipment:

5428

WO Desc:

PM C

VIN:

Ford E350 Champion Crusaders 1FDEE3FLXFDA06816

Requested By:

RRENE **RRENE** WO

Status: Priority: 40 1

Created By: Class:

Completed

Driver: Phone:

Arrangement: Potential Warranty: Unassigned No

ETA:

Started	Nov 26, 2019	
Reported	Nov 26, 2019	1:35 PM
(Chronology	

Nov 26, 2019

10:52 PM

Reading UOM Meter WO DH Life 256,266 DΗ

Down Time

WorkOrder Notes

Comment

Line 10 Perform PMC Service. Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries. Replace A/C Filter. Drain & Fill Differential.

Parts # B329 Qty (1) Oil 5W20 Qty (6.5) Qt Gear Oil 80 W90 Qty (3) Qt

Activity: 10 **Activity Note:**

999 TOTAL VEHICLE

Light Medium Duty PMI 05 - Inspection, Routine

Reason for Repair: Work Accomplished: 06 - Inspect

Part Failure:

Activity Comments

Parts Issued

Date Part Number Description Oty, Each Extended

Labor Posted

1	فيصد ويواد سيمسي سيم وسميد من ويدو مع ويدو		ł.,		
į	26-Nov-19	Arthurs, Durvin	2.50	65.00	162.50
	Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts: Labor:

0.00 162.50

Labor Hours: 2.50

0.00

Sublet Parts: Subjet Labor:

0.00

Activity Sub Total

162.50

Activity: 20

999 TOTAL VEHICLE

Activity Note:

Reason for Repair:

PM C

08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

Activity Comments

5	Date	Part Number	Description	Qty, Each E	xtended
	26-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96
1.7				A CONTRACTOR OF THE PROPERTY O	4-27-27-27-4-4



55345 Palm Tran Connection v 2.2 Page 1 of 12



WorkOrder: 53658767 **Invoice Number:** 55345-53658767

Ford E350 Champion Crusaders

1FDEE3FLXFDA06816

Client Department:

MRC:

WO Desc:

55345-LIGHT DUTY PMC

Requested By: Created By: Class: **Arrangement:**

Potential Warranty:

VIN: Status:

Equipment:

Priority: Driver: Phone: ETA:

> UOM Meter Reading WO DH Life 281,381 DH

5428

40

3

Chronology

55345M

RGASPARD

RGASPARD

Unassigned

WO

No

12:00 AM Reported Aug 14, 2020 Started Aug 16, 2020 Completed Aug 16, 2020 7:27 PM

Down Time

WorkOrder Notes

ı	Line	Comment
	10	Perform PMC Service .Change Oil & Filter. Lube all Pivoting Points. Check Brakes. Clean batteries. Clean A/C Filter. Required L/R Hub Seal. Perform differential Service. Drain & Fill. Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt
	20	Gear Oil 80W90 Qty (3) Qt

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

SW - Shop Work Order Reason for Repair:

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended	
------	-------------	-------------	------	------	----------	--

Labor Posted

Date Technician Hours Rate Extended

Activity 5 Sub Total

Parts: 0.00 Labor: 0.00

Labor Hours: 0.00 Sublet Parts: 0.00 0.00 Sublet Labor:

0.00

Activity Sub Total

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:**

Activity Comments

Parts Issued

Date Part Number Description	Qty. Each Extended	i
------------------------------	--------------------	---

Labor Posted