



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51302160
Invoice Number: 55345-51302160

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

Ford E350 Champion Crusaders

PM A

VIN: 1FDEE3FL2FDA08396

Requested By: DARTHURS

Status: 40

Created By: DARTHURS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	May 24, 2018	1:16 PM
Started	May 24, 2018	
Completed	May 25, 2018	12:20 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	186,344	DH
System	186,514	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Rotate tires and washed rims Torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	Gaspard,Ronald	1.75	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.75	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51302160
Invoice Number: 55345-51302160

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
24-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	Gaspard,Ronald	1.07	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 1.07
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: **30** **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	Gaspard,Ronald	0.25	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.25
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51302160 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 3.07
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51302160
Invoice Number: 55345-51302160

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51302160	25-May-18	186,344	WO	PM A
51164142	28-Apr-18	182,362	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51302012	27-Apr-18	182,362	WO	ScheduledMotor Mount& Tires/ Sift Cables
51079947	6-Mar-18	174,112	WO	Front Tire/Front. Brakes.& Left head light Pig tail/ Front clearance Light.

PH: Work Order: 51302160 Desc: PM A

Equip: 5435 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA08396

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,100	Safety Inspection	Done		RGASPARD	May 24, 2018 10:43:48 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 24, 2018 10:43:48 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 24, 2018 10:43:48 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	May 24, 2018 10:43:49 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	May 24, 2018 10:43:50 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	RGASPARD	May 24, 2018 10:43:51 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	RGASPARD	May 24, 2018 10:43:50 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	RGASPARD	May 24, 2018 10:43:51 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 24, 2018 10:43:51 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 24, 2018 10:43:51 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	May 24, 2018 10:43:51 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	May 24, 2018 10:43:51 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 24, 2018 10:43:51 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	May 24, 2018 10:43:52 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	May 24, 2018 10:43:52 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	May 24, 2018 10:43:52 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	May 24, 2018 10:43:52 PM	No	
20,250	FRA Check Interior Electrical Panels	-	na	RGASPARD	May 24, 2018 10:43:52 PM	No	
20,260	Check Stop Request System	-	na	RGASPARD	May 24, 2018 10:43:52 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 24, 2018 10:43:52 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 24, 2018 10:43:52 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	May 24, 2018 10:43:53 PM	No	
30,320	Inspect Step-well and Hand Rails	-	na	RGASPARD	May 24, 2018 10:43:54 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 24, 2018 10:43:54 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	May 24, 2018 10:43:54 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	May 24, 2018 10:43:55 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 24, 2018 10:43:55 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 24, 2018 10:43:55 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 24, 2018 10:43:55 PM	No	
40,420	Check Hood	Done		RGASPARD	May 24, 2018 10:43:55 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	May 24, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:43:55 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 24, 2018 10:43:56 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 24, 2018 10:43:56 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	RGASPARD	May 24, 2018 10:43:56 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 24, 2018 10:43:56 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 24, 2018 10:43:56 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 24, 2018 10:43:56 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 24, 2018 10:43:56 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	May 24, 2018 10:43:56 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,150	FRA Inspect Turbocharger	-	na	RGASPARD	May 24, 2018 10:43:57 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 24, 2018 10:43:57 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	May 24, 2018 10:43:58 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:58 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:59 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	May 24, 2018 10:44:00 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	May 24, 2018 10:43:59 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		RGASPARD	May 24, 2018 10:44:00 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		RGASPARD	May 24, 2018 10:44:00 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		RGASPARD	May 24, 2018 10:44:00 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		RGASPARD	May 24, 2018 10:44:00 PM	No	
60,635	Tread Depth LRI	8 32nds of an inch		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 24, 2018 10:44:01 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 24, 2018 10:44:02 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 24, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:44:03 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	May 24, 2018 10:44:03 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,135	Brake Rotor LF	38 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,136	Brake Rotor RF	38 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,137	Brake Rotor LR	36 Inch		RGASPARD	May 24, 2018 10:44:05 PM	No	
77,138	Brake Rotor RR	36 Inch		RGASPARD	May 24, 2018 10:44:04 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	
77,150	Check King Pins	-	na	RGASPARD	May 24, 2018 10:44:05 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	May 24, 2018 10:44:05 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: RGASPARD Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	May 24, 2018 10:45:01 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	May 24, 2018 10:45:01 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	May 24, 2018 10:45:01 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	May 24, 2018 10:45:01 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	May 24, 2018 10:45:01 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	May 24, 2018 10:45:02 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	May 24, 2018 10:45:02 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	May 24, 2018 10:45:02 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 24, 2018 10:45:26 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2

Page 1 of 9

Client Department:

MRC:

WO Desc:

PM A

Requested By:

Created By:

Class:

Arrangement:

Potential Warranty:

55345M

Equipment:

5435

Ford E350 Champion Crusaders
1FDEE3FL2FDA08396

CKARLENS

CKARLENS

WO

Unassigned

No

VIN:

Status:

Priority:

Driver:

Phone:

ETA:

WorkOrder: 51541276

Invoice Number: 55345-51541276

Chronology			
Reported Started	Aug 22, 2018	12:12 PM	
Completed	Aug 22, 2018	9:32 PM	

Down Time

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A SERVICE
	CAUSE: MILAGE
	CORRECTION: PERFORM LOF TOP OFF ALL FLUIDS CHECK TIRES AND BRAKES
	PARTS# B 329 QTY 1

Meter	Reading	UOM
WO		DH
Life	198,930	DH
System	199,128	DH

Activity: 10

999 TOTAL VEHICLE

Light Medium Duty PMI

Activity Note: 08 - Preventive Maintenance

Reason for Repair: A - PM Level A

Work Accomplished:

Part Failure:

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Aug-18	Owens,Arthur	1.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20

999 TOTAL VEHICLE

PM A

Activity Note: 08 - Preventive Maintenance

Reason for Repair: A - PM Level A

Work Accomplished:

Part Failure:

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
22-Aug-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51740106
Invoice Number: 55345-51740106

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 1, 2018	1:04 PM
Started	Nov 1, 2018	
Completed	Nov 1, 2018	11:51 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	207,068	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty 1 Engine oil 5w20 qty 7 Qts Fixed right rear inside tire patched Torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Nov-18	Gaspard,Ronald	2.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51870026
Invoice Number: 55345-51870026

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 30, 2018	11:55 AM
Started	Nov 30, 2018	
Completed	Nov 30, 2018	11:55 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	211,007	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Nov-18	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
30-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52031515
Invoice Number: 55345-52031515

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 25, 2019	11:39 AM
Started	Jan 25, 2019	
Completed	Jan 25, 2019	11:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	219,273	DH
System	219,484	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter.lube all Pivoting Points. Check brakes . Clean batteries. Replace Air Filter. Swap Right rear inner tire with one 9 /32 tread depth. Replace one front clearance light. Parts #B329 Qty (1) Parts# PA 4075Qty (1) Oil 5W20QTY (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jan-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52264002****Invoice Number: 55345-52264002****Client Department:****MRC:** 55345M**Equipment:** 5435**WO Desc:**

PM A

Requested By:

RGASPARD

VIN:

Ford E350 Champion Crusaders

Created By:

RGASPARD

Status:

40

Class:

WO

Priority:

1

Arrangement:

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:**

Chronology		
Reported	Apr 12, 2019	12:20 PM
Started	Apr 13, 2019	
Completed	Apr 13, 2019	12:27 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	231,557	DH
System	231,729	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter B329 qty 1 Engine oil 5w20 qty 7 Qts Replaced AC filter

Activity: 10**999 TOTAL VEHICLE****Activity Note:** Light Medium Duty PMI**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
13-Apr-19	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:** PM A**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52340871
Invoice Number: 55345-52340871

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 13, 2019	12:00 AM
Started	May 13, 2019	
Completed	May 13, 2019	11:32 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	236,283	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
13-May-19	AMRIT TEEMAL,VISHNU	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
Labor: 65.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
13-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder: 52513275
Invoice Number: 55345-52513275

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 16, 2019	12:00 AM
Started		
Completed	Jul 17, 2019	7:05 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	245,128	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: preventive maintenance CORRECTION: Perform pmA Service Lube all Pivoting Points Cross Rotate Tires Completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments


Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Jul-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52607644
Invoice Number: 55345-52607644

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 15, 2019	1:48 PM
Started	Aug 15, 2019	
Completed	Aug 16, 2019	7:41 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	249,301	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service due CORRECTION: Performed and completed pmA Changed engine oil and replaced engine oil filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Aug-19	Delva, Terry	0.52	65.00	33.58

Activity 10 Sub Total

Parts: 0.00
Labor: 33.58
Labor Hours: 0.52
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 33.58

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Aug-19	65266	PLUG, DRAIN, OIL, ENGINE	1.00	4.35	4.35



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52814050
Invoice Number: 55345-52814050

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 18, 2019	8:28 AM
Started	Oct 18, 2019	
Completed	Oct 18, 2019	1:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	257,833	DH

WorkOrder Notes

Line	Comment
10	PM. Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time. Parts. Engine oil filter part # B329 qty 1 engine oil, 5W20 Qty 6 qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Oct-19	Rodriguez, Raul	1.67	65.00	108.33

Activity 10 Sub Total

Parts: 0.00
Labor: 108.33
Labor Hours: 1.67
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 108.33

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52909670
Invoice Number: 55345-52909670

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 18, 2019	12:00 AM
Started	Nov 18, 2019	
Completed	Nov 19, 2019	12:03 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	262,402	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Nov-19	Gaspard, Ronald	1.55	65.00	100.75

Activity 10 Sub Total

Parts: 0.00
Labor: 100.75
Labor Hours: 1.55
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 100.75

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53118606
Invoice Number: 55345-53118606

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No


Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 21, 2020	10:41 AM
Started	Jan 21, 2020	
Completed	Jan 21, 2020	11:50 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	270,985	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts Replaced exhaust hanger Qty1

Activity: 10  **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jan-20	Gaspard, Ronald	1.18	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.18
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20  **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53202427
Invoice Number: 55345-53202427

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 17, 2020	3:11 PM
Started	Feb 17, 2020	
Completed	Feb 17, 2020	11:46 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	275,349	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service due CORRECTION: Performed and completed pma Changed air intake filter

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Feb-20	Delva,Terry	2.73	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.73
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Feb-20	B329(F)	FILTER, OIL, SPIN-ON	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53390927
Invoice Number: 55345-53390927

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 18, 2020	11:43 AM
Started	May 18, 2020	
Completed	May 18, 2020	11:18 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	283,680	DH
System	283,680	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A service. CAUSE: Due by mileage. CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53884967
Invoice Number: 55345-53884967

Client Department:

MRC: 55345M

WO Desc:

55345-LIGHT DUTY PMA

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 5435

Ford E350 Champion Crusaders

VIN: 1FDEE3FL2FDA08396

Status: 40

Priority: 3

Driver:

Phone:

ETA:

Chronology		
Reported	Nov 12, 2020	12:00 AM
Started	Nov 12, 2020	
Completed	Nov 13, 2020	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	296,657	DH
System	296,801	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -


Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52114785****Invoice Number: 55345-52114785****Client Department:****MRC:** 55345M**WO Desc:**

PM A

Requested By:

DARTHURS

Created By:

DARTHURS

Class:

WO

Arrangement:

Unassigned

Potential Warranty:

No

Equipment:

5435

Ford E350 Champion Crusaders

VIN:

1FDEE3FL2FDA08396

Status:

40

Priority:

1

Driver:**Phone:****ETA:**

Chronology		
Reported	Feb 19, 2019	10:06 AM
Started	Feb 19, 2019	
Completed	Feb 19, 2019	11:01 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,453	DH
System	223,556	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Perform and completed PMA Service

Activity: 10**999 TOTAL VEHICLE****Activity Note:**

Light Medium Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Feb-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
19-Feb-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53560792
Invoice Number: 55345-53560792

Client Department:

MRC:	55345M	Equipment:	5435
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		VIN:	1FDEE3FL2FDA08396
Requested By:	RRENE	Status:	40
Created By:	RRENE	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Jul 23, 2020	1:12 PM
Started	Jul 23, 2020	
Completed	Jul 23, 2020	6:15 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	287,900	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Clean batteries. Parts # B329 Qty (1) Oil 10 W30 Qty (6.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51372124
Invoice Number: 55345-51372124

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

Ford E350 Champion Crusaders

PM B

VIN: 1FDEE3FL2FDA08396

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Jun 22, 2018	10:48 AM
Started	Jun 22, 2018	
Completed	Jun 22, 2018	11:53 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	190,473	DH
System	190,617	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE:Service CORRECTION:Perform pmB Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Rotate tires and washed rims Torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jun-18	Gaspard,Ronald	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51372124
Invoice Number: 55345-51372124

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
22-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jun-18	Gaspard,Ronald	1.13	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 1.13
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: 30  **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jun-18	Gaspard,Ronald	0.25	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.25
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51372124 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 3.38
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51372124
Invoice Number: 55345-51372124

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51372124	22-Jun-18	190,473	WO	PM B
51302160	25-May-18	186,344	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51302012	27-Apr-18	182,362	WO	ScheduledMotor Mount& Tires/ Sift Cables

PH: Work Order: 51372124 Desc: PM B

Equip: 5435 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA08396

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 22, 2018 11:37:16 PM	No	
10,100	Safety Inspection	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,140	Check Service Brakes	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,160	FRA Check Instruments and Horns	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,170	Check Fast Idle	Done		RGASPARD	Jun 22, 2018 11:37:18 PM	No	
10,180	Check Starter Protection Circuit	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
10,190	Check Reverse Warning System	Done		RGASPARD	Jun 22, 2018 11:37:17 PM	No	
11,100	Check Parking Brake	Done		RGASPARD	Jun 22, 2018 11:37:18 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 22, 2018 11:37:18 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 22, 2018 11:37:18 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RGASPARD	Jun 22, 2018 11:37:18 PM	No	
11,150	Perform Brake Test	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	RGASPARD	Jun 22, 2018 11:37:18 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,170	FRA Check Door Operation	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RGASPARD	Jun 22, 2018 11:37:19 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,240	FRA Check Interior Lights	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,260	Check Stop Request System	-	NA	RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 22, 2018 11:37:20 PM	No	
22,110	Check Emergency Hatches	Done		RGASPARD	Jun 22, 2018 11:37:21 PM	No	
22,120	Check All Safety Equipment	Done		RGASPARD	Jun 22, 2018 11:37:21 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 22, 2018 11:37:21 PM	No	
30,310	Check Passenger Doors	Done		RGASPARD	Jun 22, 2018 11:37:21 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 22, 2018 11:37:21 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Jun 22, 2018 11:37:21 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
30,360	Check for Physical Damage and Decals	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
30,380	Check Exterior Compartment Doors	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
33,100	Check Lights and Reflectors	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,420	Check Hood	Done		RGASPARD	Jun 22, 2018 11:37:22 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 22, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:37:23 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 22, 2018 11:37:23 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Jun 22, 2018 11:37:24 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Jun 22, 2018 11:37:24 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 22, 2018 11:37:24 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 22, 2018 11:37:24 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 22, 2018 11:37:25 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 22, 2018 11:37:24 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 22, 2018 11:37:24 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 22, 2018 11:37:24 PM	No	
44,130	FRA Check Exhaust System	Done		RGASPARD	Jun 22, 2018 11:37:25 PM	No	
44,140	FRA Check Intake System	Done		RGASPARD	Jun 22, 2018 11:37:25 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	RGASPARD	Jun 22, 2018 11:37:25 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 22, 2018 11:37:25 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
44,180	FRA Check for Leaks	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
44,190	FRA Perform Battery Inspection	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
50,510	Check Entire Steering System	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RGASPARD	Jun 22, 2018 11:37:26 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,620	Check Valve Stems and Caps	Done		RGASPARD	Jun 22, 2018 11:37:27 PM	No	
60,630	Check and Record Tread Depth	Done		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,635	Tread Depth LRI	11 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,636	Tread Depth LRO	10 32nds of an inch		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,650	Check Sidewall Wear	Done		RGASPARD	Jun 22, 2018 11:37:28 PM	No	
60,660	Inspect for Cuts and Tears	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
60,670	Check Dual Mating With Square	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
70,710	Check Vibration Damper	Done		RGASPARD	Jun 22, 2018 11:37:29 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,730	FRA Check Starter	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,770	FRA Check Exhaust System	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 22, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:37:30 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,110	FRA Check Fuel Tank	Done		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,120	Check Suspension Components	Done		RGASPARD	Jun 22, 2018 11:37:30 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,131	Brake Pad Thickness LF	6 Inch		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,132	Brake Pad Thickness RF	6 Inch		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,133	Brake Pad Thickness LR	7 Inch		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,134	Brake Pad Thickness RR	7 Inch		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
77,135	Brake Rotor LF	38 Inch		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,136	Brake Rotor RF	38 Inch		RGASPARD	Jun 22, 2018 11:37:31 PM	No	
77,137	Brake Rotor LR	36 Inch		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
77,138	Brake Rotor RR	36 Inch		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
77,140	FRA Check Brake Hoses	Done		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
77,150	Check King Pins	-	NA	RGASPARD	Jun 22, 2018 11:37:32 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
80,810	Completion of PMI Report	Done		RGASPARD	Jun 22, 2018 11:37:32 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RGASPARD	Jun 22, 2018 11:37:33 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RGASPARD	Jun 22, 2018 11:37:33 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: RGASPARD Performed on: 22-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 22, 2018 11:38:39 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Jun 22, 2018 11:38:39 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Jun 22, 2018 11:38:39 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Jun 22, 2018 11:38:39 PM	No	
104,000	Lubricate Chassis	-	NA	RGASPARD	Jun 22, 2018 11:38:40 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Jun 22, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:38:40 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jun 22, 2018 11:38:40 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Jun 22, 2018 11:38:40 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jun 22, 2018 11:38:40 PM	No	
201,000	Service Crankcase Breather	Done		RGASPARD	Jun 22, 2018 11:38:40 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		RGASPARD	Jun 22, 2018 11:38:41 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		RGASPARD	Jun 22, 2018 11:38:40 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jun 22, 2018 11:38:41 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 22, 2018 11:39:04 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51953537
Invoice Number: 55345-51953537

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

Ford E350 Champion Crusaders

PM B

VIN: 1FDEE3FL2FDA08396

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology			Meter	Reading	UOM
Reported	Dec 28, 2018	12:58 PM	WO		DH
Started	Dec 28, 2018		Life	215,131	DH
Completed	Dec 28, 2018	9:35 PM	System	215,270	DH
Down Time					

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service Due by Mileage. CORRECTION:Change Oil & Filter .lube allPivoting Points. Check brakes. Clean batteries.replace A/C Filter. Repair wire for Left side panel flasher. Light. Parts# B329 Qty (1) Oil 5W20QTY (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Mediun Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Dec-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
28-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52427112
Invoice Number: 55345-52427112

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 5435

Ford E350 Champion Crusaders

1FDEE3FL2FDA08396

VIN: 40

Status: 1

Driver:

Phone:

ETA:

Chronology

Reported	Jun 12, 2019	11:17 AM
Started	Jun 12, 2019	
Completed	Jun 13, 2019	12:09 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	240,602	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION:Perform pmB Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Jun-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts: 0.00
Labor: 104.00
Labor Hours: 1.60
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 104.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53014227
Invoice Number: 55345-53014227

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No


Equipment: 5435
Ford E350 Champion Crusaders
1FDEE3FL2FDA08396
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Dec 20, 2019	12:00 AM
Started	Dec 20, 2019	
Completed	Dec 21, 2019	12:32 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	266,911	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION: perform PMB service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10  **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Dec-19	Gaspard,Ronald	0.08	65.00	5.20
20-Dec-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts: 0.00
Labor: 109.20
Labor Hours: 1.68
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 109.20

Activity: 20  **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 12



WorkOrder: 53726420
Invoice Number: 55345-53726420

Client Department:

MRC:	55345M	Equipment:	5435
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		VIN:	1FDEE3FL2FDA08396
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Sep 17, 2020	12:00 AM
Started	Sep 18, 2020	
Completed	Sep 18, 2020	9:57 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	292,306	DH
System	292,306	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 51647656****Invoice Number: 55345-51647656****Client Department:****MRC:** 55345M**Equipment:** 5435**WO Desc:**

Ford E350 Champion Crusaders

PM C**VIN:** 1FDEE3FL2FDA08396**Requested By:**

AOWENS

Status: 40**Created By:**

AOWENS

Priority: 1**Class:**

WO

Driver:**Arrangement:**

Unassigned

Phone:**Potential Warranty:**

No

ETA:

Reported Started Completed	Chronology	
	Sep 20, 2018	11:53 AM
	Sep 20, 2018	
	Sep 21, 2018	12:01 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	202,961	DH
System	203,147	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear Oil 80w90 qty 4 Qts Replaced AC filter

Activity: 10**999 TOTAL VEHICLE****Activity Note:** Light Medium Duty PMI**Reason for Repair:** 05 - Inspection, Routine**Work Accomplished:** 06 - Inspect**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Sep-18	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:** PM C**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** C - PM Level C**Part Failure:** -**Activity Comments****Parts Issued**



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52185113
Invoice Number: 55345-52185113

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

PM C

Requested By: VAMRITTEEMAL

VIN: Ford E350 Champion Crusaders

Created By: VAMRITTEEMAL

Status: 40

Class: WO

Priority: 1

Arrangement: Unassigned

Driver:

Potential Warranty: No

Phone:

ETA:

Chronology

Reported	Mar 18, 2019	11:54 AM
Started	Mar 18, 2019	
Completed	Mar 18, 2019	11:51 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	227,458	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform pmc Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear oil 80w90 qty 4 Qts

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Mar-19	Gaspard, Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52695603
Invoice Number: 55345-52695603

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: DKNOTT
Created By: DKNOTT
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5435
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA08396
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Sep 18, 2019	12:44 PM
Started	Sep 19, 2019	
Completed	Sep 20, 2019	8:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	253,733	DH
System	253,733	DH

WorkOrder Notes

Line	Comment
10	Complaints: PMC Cause: Service Due Correction: Performed and completed PMC ***Right engine Mount recommended next PM

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Sep-19	Delva, Terry	1.55	65.00	100.75

Activity 10 Sub Total

Parts: 0.00
Labor: 100.75
Labor Hours: 1.55
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 100.75

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
19-Sep-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53293567
Invoice Number: 55345-53293567

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

Ford E350 Champion Crusaders

PM C

VIN: 1FDEE3FL2FDA08396

Requested By: TDELVA

Status: 40

Created By: TDELVA

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Mar 16, 2020	11:59 AM
Started	Mar 16, 2020	
Completed	Mar 17, 2020	12:38 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	279,488	DH
System	279,575	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter B329 qty1 Engine oil 10W30 qty 7 qts Replaced AC filter Gear oil 80W90 qty 4 qts Replaced right front head light bulb wty1

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Mar-20	Gaspard,Ronald	1.93	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.93	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 3



WorkOrder: 54082873
Invoice Number: 55345-54082873

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

Ford E350 Champion Crusaders

REAR AC SYSTEM

VIN: 1FDEE3FL2FDA08396

Requested By: CVERGARA

Status: 32

Created By: CVERGARA

Priority:

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Nov 24, 2020	2:47 PM
Started	Nov 24, 2020	
Completed	Nov 24, 2020	6:53 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	297,915	DH
System	297,994	DH

WorkOrder Notes

Line	Comment
10	Rear A/C blow hot air . Evacuate & Recharge. Add (5.0) Oz Oil & (6.5) Lb Freon. replace Orifice tube replace A/C Control Switch. Parts # 3411885 Qty (1) Parts # 04257712A Qty (1)

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **001 AIR CONDITIONING, HEATING AND VENTILATION**

Activity Note:

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
24-Nov-20	04257712A	DISPLAY, DASH, LED, A/C, G4500	1.00	296.85	296.85
24-Nov-20	3411885	TUBE, ORIFICE, A/C, FORD	1.00	0.75	0.75

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 3



WorkOrder: 54082873
Invoice Number: 55345-54082873

Client Department:

MRC: 55345M

Equipment: 5435

WO Desc:

REAR AC SYSTEM

Ford E350 Champion Crusaders

VIN: 1FDEE3FL2FDA08396

Requested By:

CVERGARA

Status:

32

Created By:

CVERGARA

Priority:

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Date	Technician	Hours	Rate	Extended
24-Nov-20	Arthurs,Durvin	2.73	0.00	0.00

Activity 20 Sub Total

Parts:	297.60
Labor:	0.00
Labor Hours: 2.73	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	297.60

WorkOrder 54082873 Grand Total

Parts:	297.60
Labor:	0.00
Labor Hours: 2.73	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	297.60

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
54082873	24-Nov-20	297,915	WO	REAR AC SYSTEM
54076467	22-Nov-20	297,569	WO	Byfold wont close
54050404	13-Nov-20	296,657	WO	FOLLOWUP--> Replace Front Brakes And Front Tire
53884967	13-Nov-20	296,657	WO	55345-LIGHT DUTY PMA
53983002	29-Oct-20	294,809	WO	55345 FIRE SUPPRESSION SYSTEM

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 54082873 Desc: REAR AC SYSTEM

Equip: 5435 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA08396

LH: 10 Desc:

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-NOV-20

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		DARTHURS	Nov 24, 2020 6:45:40 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 24, 2020 6:45:42 PM	No	
3	Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 24, 2020 6:45:46 PM	No	
4	Have you performed the proper LOTO?	Done		DARTHURS	Nov 24, 2020 6:45:51 PM	No	
5	Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 24, 2020 6:45:55 PM	No	
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 24, 2020 6:45:59 PM	No	
20	Miles	Miles (TDED SMI)				No	
30	Kilometers	Kilometre*				No	
40	Hours	Hour*				No	