



12/30/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10169731

6X4 JOHN DEERE GATOR ATV 6X4

Workorder: V15952

In Date: 06/24/2008
Close Date: 07/17/2008

Meter Reading:

Problem?

b INSPECTION AND REPAIRS AS NEEDED

Task performed:

- B-Inspection
- 1. Test drive; change oil/filter; replc air/fuel filters; replace brakes.
- 2. Fabricat/install gusset plates to roof support frame. j

Parts	Quantity
33262FUEL FILTER JOHN DEERE	1
42845AIR FILTER JOHN DEERE	1
46449AIR FILTER GENERATOR LAF8388 ONAN	1
PH3593A 51334 TORO 67-4330 FILTER	1

Workorder: V17048

In Date: 08/14/2008
Close Date: 08/29/2008

Meter Reading:

Problem?

the green gator needs a batter. tried to charge it and it started smoking. STA-72

Task performed:

- 1. Measured battery & terminal orientation to order battery.
- 2. Get all parts necessary to do rep at Pahokee/Belle Glade/Canal Point.
- 3. Drive to Stn72 from C/S.
- 4. R/R battery; cln cable terminals. j

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
U1BATTERY 295CCA U1-LHP	1

Workorder: V32975

In Date: 06/17/2010
Close Date: 07/14/2010

Meter Reading:

Problem?

red mule atv having problems starting Sta 72

Task performed:

- C/O fnd bad btry/wire burnt to grnd; need to go to shop for svc, btry & wire repair. j

Parts	Quantity
NO PARTS USED	



12/30/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10169731

6X4 JOHN DEERE GATOR ATV 6X4

Workorder: V36461

In Date: 11/15/2010

Meter Reading:

Close Date: 12/07/2010

Problem?

B inspection and repairs (outside agency-regan)

Task performed:

Parts

Quantity

Svc small engines: Batt 1, 3, 4 & 5 - Regan j

NO PARTS USED

Vendor?: REGAN

Workorder: V36583

In Date: 11/19/2010

Meter Reading:

Close Date: 12/22/2010

Problem?

parts only

Task performed:

Parts

Quantity

15W40QSYN OIL QT

3

PH3593A 51334 TORO 67-4330 FILTER

1

Workorder: V45107

In Date: 11/11/2011

Meter Reading:

Close Date: 11/23/2011

Problem?

Gator atv rear seat needs cushion replaced Sta 72

Task performed:

Parts

Quantity

travel to st 72 check out seat get pt #ect order new seat

VG11696SEAT GATOR

1

travel to john deere pick up parts travel to st 72 femove medand bed r&r seat a--hardware reinstall bed unit return to shop

Workorder: V45849

In Date: 12/13/2011

Meter Reading:

Close Date: 01/10/2012

Problem?

B INSPECTION REGAN

Task performed:

Parts

Quantity

B INSPECTION AL PACKER

NO PARTS USED

Vendor?: REGAN



12/30/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10169731

6X4 JOHN DEERE GATOR ATV 6X4

Workorder: V55166

In Date: 01/19/2013

Meter Reading:

Close Date: 01/31/2013

Problem?

Battery is dead

Task performed:

TRAVEL TO ST 74 R&R BATT IN CART WENT TO BATT SHOP FOR PART.

Parts

Quantity

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

1

U1 BATTERY 295CCA U1-LHP

1

Workorder: V56362

In Date: 03/12/2013

Meter Reading:

Close Date: 03/18/2013

Problem?

Install a small round light on roof of gator. Also, two small interior light strips on underside of roof for night time ops.

Task performed:

1. INSTALLED LIGHTS WILL RETURN WITH WIRING AND EMERGENCY LIGHTS.
2. TRAVEL TO 19 INSTALLED EMERGENCY LIGHTS AND WIRED ALL LIGHTS AND SWITCHES.

Parts

Quantity

35-306DS-175 PUSH PULL SWITCH 75 AMP

2

Workorder: V56507

In Date: 03/19/2013

Meter Reading:

Close Date: 03/21/2013

Problem?

B inspection

Task performed:

serviced by Regan's equipment

Parts

Quantity

NO PARTS USED

Vendor?: REGAN

Workorder: V56363

In Date: 03/12/2013

Meter Reading:

Close Date: 04/09/2013

Problem?

replace 4 indicator light covers that are missing.

Task performed:

1. TRAVEL TO 19 CHECKED VIN NUMBERS ON UNIT AND ORDERED PARTS.
2. TRAVEL TO 15 INSTALLED INDICATOR LIGHT COVER AND INSTALLED NEW SEAT.
3. SECURED WIRING FOR EMERGENCY LIGHTS.

Parts

Quantity

M127611 LABEL

1

VG11696 SEAT GATOR

1



12/30/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10169731

6X4 JOHN DEERE GATOR ATV 6X4

Workorder: V74226

In Date: 01/01/1900

Meter Reading:

Close Date: 06/16/2015

Problem?

REPLACE BATT ON GATOR

Task performed:

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1

U1BATTERY 295CCA U1-LHP

1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10169731) 2003 - GATOR HPX John Deere Hpx 4X4 Gator

10169731

CSHOP-2020-238

Date Opened: 1-15-2020 Date Finished 1-27-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

REPAIR SHOP EQUIPMENT

1 NBH; G FORCE TM BELT

Service Requests:

01/15/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
WILL NOT GO INTO ANY GEAR.

CSHOP-2020-818

Date Opened: 2-12-2020 Date Finished 2-12-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

REPAIR SHOP EQUIPMENT

Service Requests:

02/12/2020 OIL / 18: LEAKING / OVERHAUL
LOW ENGINE OIL, THE UNIT IS LEAKING OIL ONTO THE FLOOR.

CSHOP-2020-984

Comments: **WAITING FOR PURCHASE ORDER**

Date Opened: 2-19-2020 Date Finished 4-24-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? EVERGLADES FARM EQUIP CO INC