



12/23/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182241

R09RB50AF ATV UTILITY VEHICLE POLARIS

Workorder: V35396

In Date: 10/04/2010
Close Date: 10/25/2010

Meter Reading:

Problem?

PURCHASE WINDSHIELD FOR POLARIS FOR VOLLYS

Task performed:

Purchase windshield for Polaris for Vollys - Mad Dog Motorsports j
Vendor?: MAD DOG

Parts

Quantity

NO PARTS USED

Workorder: V55648

In Date: 02/08/2013
Close Date: 03/25/2013

Meter Reading: 30.90

Problem?

repair polaris - will not start

Task performed:

REPAIR POLARIS - WILL NOT START.

Vendor?: GREATER MOTORSPORT

Parts

Quantity

NO PARTS USED

Workorder: V50426

In Date: 06/26/2012
Close Date: 04/22/2013

Meter Reading:

Problem?

Battery Bad. Please replace. Part # ETX 30L CCA 400

Task performed:

Parts

Quantity

BATTERY EPA TAX	BATTERY EPA TAX \$1.50 PER BATTERY	1
PIX-30L-BS-FSBATTERY		1

Workorder: V59719

In Date: 08/10/2013
Close Date: 09/18/2013

Meter Reading: 40.00

Problem?

PM, change fluids, filters, plugs Check shifter for sticking or difficulty in shifting gears

Task performed:

1. DIAGNOSED DIFF LOCK PROBLEM TO ECM.
2. INSTALLED NEW ECM FOUND WIRING ISSUE SHORT IN HARNESS TRACED OUT FOUND PROBLEM REPAIRED TESTED OK.
3. CHANGED OIL FILTER PLUGS.

Parts

Quantity

NO PARTS USED



12/23/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182241

R09RB50AF ATV UTILITY VEHICLE POLARIS

Workorder: V64165

In Date: 02/12/2014

Meter Reading: 40.00

Close Date: 02/27/2014

Problem?

battery not holding charge, polaris

Task performed:

1. replace battery, clean all terminal ends that were corroded, check battery charger, ok
2. remove lite bar on roof, take another lite bar given to me by Kevin, and install new LED lites in bar and install on roof and rewire,

* lite bar taken off this unit will be installed on the new polaris

Parts	Quantity
51-30219-1045 MASTER SWITCH 175 AMP	1
5291FOG LIGHTS	1
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	2
64093-5FOG LIGHT KIT	2
8126482-2106 TOGGLE GUARD	5
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
PIX30LBSFSBATTERY POLARIS ATV	1

Workorder: V64734

In Date: 03/06/2014

Meter Reading: 40.00

Close Date: 03/10/2014

Problem?

install auto-eject, install rear loading lites, old polaris

Task performed:

1. install auto-eject, install wiring harness, install battery charger
2. install 2 rear loading lites, drill holes in clear plexi-glass covers, install 2 on-off switch's, run wiring from lites to battery, remove front windshield to get access to battery, install fuses, reinstall windshield, test ok

Parts	Quantity
091-20WP-120AUTO EJECT	1

Workorder: V62840

In Date: 12/19/2013

Meter Reading: 40.00

Close Date: 03/12/2014

Problem?

Replace lightbar

Task performed:

install on nnew polaris

Parts	Quantity
287950012 IN LIGHTBAR POLARIS	1
2879863HARNES POLARIS	1
FREIGHTSHIPPING CHARGES	1



12/23/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182241

R09RB50AF ATV UTILITY VEHICLE POLARIS

Workorder: V64868

In Date: 03/12/2014

Meter Reading: 40.00

Close Date: 03/12/2014

Problem?

install fire extinusher, old polaris

Task performed:

Parts

Quantity

1. remove center floor board and mount fire ext. bracket to floor board, reinstall floor

NO PARTS USED

Workorder: V74559

In Date: 04/09/2015

Meter Reading: 93.00

Close Date: 04/24/2015

Problem?

no start

Task performed:

Parts

Quantity

1. Fuel system inop. Cart at Fair Grounds. Fuel pump replaced.

42SFUEL PUMP

1

7052301LINE AND FILTER

1

7080402CLIPS

1

8350019-160FUEL LINE

1

Workorder: V75433

In Date: 05/29/2015

Meter Reading: 93.00

Close Date: 06/01/2015

Problem?

Polaris broken down at ampitheatre

Task performed:

Parts

Quantity

1. Travel time to and from coral sky ampatheather. Inspected Polaris cart. Determined clutch failure. Repair cannot be made on scene.

NO PARTS USED

Workorder: V74280

In Date: 03/30/2015

Meter Reading: 93.00

Close Date: 06/16/2015

Problem?

will not run, polaris

Task performed:

Parts

Quantity

check spark plug, check fuel system, found carb leaking gas on bottom of fuel bowel

3130532CARB PARTS

1

3131361CARB PARTS

1



12/23/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182241

R09RB50AF ATV UTILITY VEHICLE POLARIS

Workorder: V74012

In Date: 03/19/2015

Meter Reading: 93.00

Close Date: 07/07/2015

Problem?

will not idle, reserve polaris

Task performed:

check spark plug, check carb, found gas leaking under carb

Parts

Quantity

NO PARTS USED