		1017869	07 20 ⁻	10 ΤΟΥΟΤΑ Ρ	PRIUS Ca	ar, Mid-Size	, Hybrid			
Workorder: Problem:	944463 Pre Delivery Ir	Meter:	0			In Date:	10/13/2009	Closed:	10/13/20	009
- Pre Delivery	Inspection									
	Hour:	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1003266 P.M service, A	Meter: BS Recal	710 I, Detail.			In Date:	03/31/2010	Closed:	04/07/20	010
- P.m service					Parts L	ist				Qty
- To/from dea	ler for Abs reca	ull & displa	y panel fo	ogged over.	Shop Si	upplies				1.00
- Shop Suppli	- Shop Supplies				Ch1035	58 Oil Filter L	bf P980 Wix	57064		1.00
					75-540	0w/20 Moto	or Oil			5.00
	Hour:	s 4.00		Labor:	240.00	Parts:	42.17	Total:	282.17	
Workorder: Problem:	1003715 1 - Detail Vehi	Meter: cle Wash	710 Ticket(s)	Issued		In Date:	04/09/2010	Closed:	04/09/20	010
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	ied							
	Hour:	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1011044 P.M. service a	Meter: and cancei	1565 ver.			In Date:	10/06/2010	Closed:	10/18/20	010
- P.m. Service	Э.				Parts L	ist				Qty
- Shop Suppli	es				Shop Si	upplies				1.00
					Ch1035	58 Oil Filter L	bf P980 Wix	57064		1.00
					75-540	0w/20 Moto	or Oil			5.00
	Hour	s 2.00		Labor:	120.00	Parts:	42.17	Total:	162.17	
Workorder: Problem:	1104334 P.m. service.	Meter:	2138			In Date:	04/21/2011	Closed:	05/05/20)11
- Perform pm	service.				Parts L	ist				Qty
- Rotate and I	balance all four	tires.			Shop Si	upplies				1.00
	hicle to and fro				Ch1035	68 Oil Filter L	bf P980 Wix	57064		1.00
	ster lens with n	ew under	factory w	arranty.	75-540	0w/20 Moto	or Oil			4.00
- Shop Suppli	es				75-540	0w/20 Moto	or Oil			1.00
					Nb-18	Wiper Blade	s 18" Anco 3	1-18		1.00
					31-24 V	Niper Blade	s 24" Blade			1.00
	Hour	s 5.00		Labor:	300.00	Parts:	52.24	Total:	352.24	
	:									

Problem:	1202934 P.M. service.	Meter:	6264			In Date:	03/27/2012	Closed:	04/04/20)12
- P.m. Service	Э.				Parts Li	st				Qty
- Replace two	o tires,rotate an	d balance	all four.		Shop Su		1.00			
- Shop Suppli	es				Cf10285			1.00		
					Ch1035	8 Oil Filter L	bf P980 Wix	57064		1.00
					75-540	0w/20 Moto	or Oil			5.00
					Nb-18 \	Viper Blade	s 18" Anco 3	1-18		1.00
					31-24 V	Viper Blades	s 24" Blade			1.00
					7382745 89h	571 195/65r	15 Assurance	Fuel Max		2.00
					Tire Dis	oosal Fee				2.00
	Hour :	s 4.00		Labor:	240.00	Parts:	225.17	Total:	465.17	
Workorder: Problem:	1203147 0 - Wash ticke	Meter: et(s) issued	6088 I			In Date:	04/02/2012	Closed:	04/02/20)12
- 0 - Wash tic	ket(s) issued									
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1203149 1 - Detail Veh	Meter: icle Wash	6088 Ticket(s) Issue	ed		In Date:	04/02/2012	Closed:	04/02/20)12
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	ed							
	Hour	<u>~</u> 000		Lobor						
		3 0.00		Labor.	0.00	Parts:	0.00	Total:	0.00	
	: 1211287 Pm service ar	Meter:	10844 at tire.		0.00	Parts: In Date:	0.00	Total: Closed:	0.00)12
	Pm service ar	Meter:			0.00 Parts Li	In Date:)12 Qty
Problem: - P.m. Service	Pm service ar	Meter: nd check fla			Parts Li	In Date:	11/20/2012			
- P.m. Service - Rotate and I	Pm service ar e. balance all tires	Meter: nd check fla		Labor.	Parts Li	In Date: st 8 Oil Filter L	11/20/2012			Qty
Problem: - P.m. Service	Pm service ar e. balance all tires	Meter: nd check fla		Labor.	Parts Li Ch1035 0w-20 M	In Date: st 8 Oil Filter L	11/20/2012 _b			Qty 1.00
Problem: - P.m. Service - Rotate and B	Pm service ar e. balance all tires	Meter: nd check fla		Labor.	Parts Li Ch1035 0w-20 M	In Date: st 8 Oil Filter L lotor Oil 7030 Rear V	11/20/2012 _b			Qty 1.00 5.00
Problem: - P.m. Service - Rotate and B	Pm service ar e. balance all tires ies	Meter: nd check fla			Parts Li Ch1035 0w-20 M 8524247	In Date: st 8 Oil Filter L lotor Oil 7030 Rear V upplies	11/20/2012 _b	Closed:		Qty 1.00 5.00 1.00
Problem: - P.m. Service - Rotate and b - Shop Suppli Workorder:	Pm service ar e. balance all tires ies	Meter: nd check fla s. rs 3.00 Meter:	at tire. 10671	Labor:	Parts Li Ch1035 0w-20 M 8524247 Shop Su	In Date: st 8 Oil Filter L lotor Oil 7030 Rear V upplies	11/20/2012 .b Viper	Closed:	12/07/20	Qty 1.00 5.00 1.00
Problem: - P.m. Service - Rotate and t - Shop Suppli Workorder: Problem:	Pm service ar e. balance all tires ies Hour : 1211779	Meter: nd check fla s. s. s 3.00 Meter: icle Wash	10671 Ticket(s) Issue	Labor:	Parts Li Ch1035 0w-20 M 8524247 Shop Su	In Date: st 8 Oil Filter L lotor Oil 7030 Rear V upplies Parts:	11/20/2012 .b Viper 61.13	Closed: Total:	12/07/20 241.13	Qty 1.00 5.00 1.00

Workorder: Problem:	1305363 Pm servic	Meter: e.Request for	13774 installing co	omputer sta	nd.	In Date:	05/31/2013	Closed:	06/11/20	013
- P.m. Servic	e.				Parts Li	st				Qty
- Install costo	omer supplie	ed computer st	and.		Syn0w2	0				5.00
- Rotate and	balance all	tires.			Napago	ld Oil Filter				1.00
- Shop Suppl	lies				Wiper B					1.00
						Viper Blades	s 2			1.00
					Shop Su	-				1.00
	F	lours 4.50		Labor:	270.00	Parts:	46.04	Total:	316.04	
Workorder: Problem:	1305523 1 - Detail \	Meter: Vehicle Wash	13664 Ticket(s) Is	sued		In Date:	06/05/2013	Closed:	06/05/20	013
- 1 - Detail Ve	ehicle Wash	n Ticket(s) Issu	ied							
	F :	lours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1307938 Right rear	Meter: tire flat.	14326			In Date:	08/08/2013	Closed:	08/15/20	013
- Repair flat r	ight rear tire	e.nitrogen fill a	nd balance	same.	Parts Li	st				Qty
- Shop Suppl	lies				Shop Su	upplies				1.00
	F	lours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
	:									
Workorder: Problem:	1308701 Remote in	Meter:	14611			In Date:	08/28/2013	Closed:	08/30/20	013
Problem:	: 1308701 Remote in	Meter:			Parts Li	In Date:	08/28/2013	Closed:	08/30/20	013 Qty
Problem:	: 1308701 Remote in oor lock rem	Meter:				In Date:	08/28/2013	Closed:	08/30/20	
Problem: - Diagnose d	: 1308701 Remote in oor lock rem y with new.	Meter:			Battery	In Date:			08/30/20	Qty
Problem: - Diagnose d remote batter Workorder:	: 1308701 Remote in oor lock rem y with new. H : 1312811	Meter: op. note inop.test a	and replace	e failed Labor:	Battery 30.00	In Date: St Parts: In Date:				Qty 1.00
Problem: - Diagnose d remote batter Workorder:	: 1308701 Remote in oor lock rem y with new. H : 1312811 P.M. servi	Meter: op. note inop.test a lours 0.50 Meter:	and replace	e failed Labor:	Battery 30.00	In Date: St Parts: In Date: er.	6.18	Total:	36.18	Qty 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic	: 1308701 Remote in oor lock rem y with new. H : 1312811 P.M. servi e.	Meter: op. note inop.test a lours 0.50 Meter:	and replace 16491 r no start ar	e failed Labor: nd recall bra	Battery 30.00 ake boost Parts L i	In Date: St Parts: In Date: er.	6.18	Total:	36.18	Qty 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n	: 1308701 Remote in oor lock rem y with new. : H 1312811 P.M. servi e. o start conc	Meter: op. hote inop.test a lours 0.50 Meter: ce towed in fo	and replace 16491 r no start ar n point test	e failed Labor: nd recall bra	Battery 30.00 ake boost Parts L i Napago	In Date: St Parts: In Date: er.	6.18	Total:	36.18	Qty 1.00 014 Qty
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fu: - Recharge b	: 1308701 Remote in oor lock rem y with new. H : 1312811 P.M. servi e. o start conc se panel an attery and to	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load	and replace 16491 r no start ar n point test m 125amp.	e failed Labor: nd recall bra t.r&r fuse.	Battery 30.00 ake boost Parts L i Napago	In Date: St Parts: In Date: er. st Id Oil Filter uart 5w20	6.18	Total:	36.18	Qty 1.00 014 Qty 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fue - Recharge b battery and te	: 1308701 Remote in oor lock rem y with new. H : 1312811 P.M. servi e. o start conc se panel and est charging	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok.	and replace 16491 r no start ar n point test m 125amp.	e failed Labor: nd recall bra t.r&r fuse.	Battery 30.00 Ake boost Parts L i Napago Napa Q Cabin A	In Date: St Parts: In Date: er. st Id Oil Filter uart 5w20	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 Qty 1.00 5.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fus - Recharge b battery and te - Rotate and	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and battery and to est charging balance all	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok. tires.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 Ake boost Parts L i Napago Napa Q Cabin A	In Date: St Parts: Parts: In Date: er. St Id Oil Filter uart 5w20 ir Filter Viper Blades	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 Qty 1.00 5.00 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fus - Recharge b battery and te - Rotate and	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and attery and to est charging balance all ehicle to dea	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 ake boost Parts Li Napago Napa Q Cabin A 31-24 V Wiper B 125a Fu	In Date: St Parts: Parts: In Date: er. er. St Id Oil Filter uart 5w20 ir Filter Viper Blades lade	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 014 1.00 5.00 1.00 1.00 1.00 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fus - Recharge b battery and te - Rotate and - Transport v	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and set charging balance all ehicle to dea s.	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok. tires.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 Ake boost Parts Li Napago Napa Q Cabin A 31-24 V Wiper B	In Date: St Parts: Parts: In Date: er. er. St Id Oil Filter uart 5w20 ir Filter Viper Blades lade	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 Qty 1.00 5.00 1.00 1.00 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fue - Recharge b battery and te - Rotate and - Transport v update recalls	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and set charging balance all ehicle to dea s.	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok. tires.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 ake boost Parts Li Napago Napa Q Cabin A 31-24 V Wiper B 125a Fu	In Date: ast Parts: In Date: er. ast Id Oil Filter uart 5w20 ir Filter Viper Blades lade use	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 014 1.00 5.00 1.00 1.00 1.00 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fue - Recharge b battery and te - Rotate and - Transport v update recalls	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and set charging balance all ehicle to dea s.	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok. tires.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 Ake boost Parts Li Napago Napa Q Cabin A 31-24 V Wiper B 125a Fu Battery	In Date: St Parts: Parts: In Date: er. er. St Id Oil Filter uart 5w20 ir Filter Viper Blades lade lase 0	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 1.00 5.00 1.00 1.00 1.00 1.00 1.00
Problem: - Diagnose d remote batter Workorder: Problem: - P.m. Servic - Diagnose n underhood fue - Recharge b battery and te - Rotate and - Transport v update recalls	: 1308701 Remote in oor lock rem y with new. H 1312811 P.M. servi e. o start conc se panel and set charging balance all ehicle to dea s.	Meter: op. note inop.test a lours 0.50 Meter: ce towed in fo ern.perform pi d replace blow est,failed load system,ok. tires.	and replace 16491 r no start ar n point test n 125amp. test.replace	e failed Labor: nd recall bra t.r&r fuse. e defective	Battery 30.00 Ake boost Parts Li Napago Napa Q Cabin A 31-24 V Wiper B 125a Fu Battery Syn0w2	In Date: ast Parts: In Date: er. er. ast Id Oil Filter uart 5w20 ir Filter Viper Blades lade use 0 upplies	6.18 12/26/2013	Total:	36.18	Qty 1.00 014 014 1.00 5.00 1.00 1.00 1.00 1.00 5.00

Workorder: Problem:	1400005 No start/PM	Meter: Service	16374			In Date:	12/26/2013	Closed:	01/02/2014
- Tow From: 1	100 Australian	Ave (airpo	rt Hilton) 1	o: Lv Shop					
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1409004 Pm service.F	Meter: Request to d	19795 letail vehic	le.		In Date:	09/08/2014	Closed:	09/22/2014
- P.m. Service	Э.				Parts Li	ist			Qty
- Replace two	tires,rotate a	nd balance	all four.		738274	571 195-65r	15 A		2.00
- Complete wl	heel alignmen	t.test drive.			Syn0w2	0			5.00
- Shop Suppli	es				Napago	ld Oil Filter			1.00
					31-24 V	Viper Blades	s 2		1.00
					Wiper B	lade			1.00
					Rear Co	mposite Bla	ade		1.00
					Shop Su	upplies			1.00
					Tire Dis	posal Fee			2.00
	Hou	ırs 6.50		Labor:	390.00	Parts:	302.52	Total:	692.52
- 1 - Detail Ve				Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1500535 Towed in for	Meter: no start.Ha	21581 d to jump :	start.		In Date:	01/15/2015	Closed:	01/22/2015
- Recharge ba	attery.test batt	ery and cha	arging syst	em.good.					
-	Hou	ırs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00
Workorder: Problem:	1500590 No start	Meter:	21581			In Date:	01/13/2015	Closed:	01/15/2015
- Tow From: 1 To: Lv shop	100 Australian	Ave (airpo	rt Hilton) D	es Dept					
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
			04504			In Date:	01/27/2015	Cleased	01/07/0015
Workorder: Problem:	1500979 3 - Wash tick	Meter: (s) issued	21581 1			in Date.	01/21/2013	Closed:	01/27/2015
	3 - Wash tick					in Date.	01/27/2013	Closed:	01/27/2015

Problem:	1503091 Pm service	Meter: Anti skid wa	22328 rning light on.			In Date:	03/25/2015	Closed:	04/08/2015	
- Pm service.					Parts Lis	st			Q	
- Computer d	iagnose for tra	action contro	ol light on.code	Ð	Napagolo	1.0				
C0200,c0205	and C1290.cl	lear codes a	nd retest steel		Syn0w20	5.0				
angle sensor.t					31-24 W	1.0				
- Rotate and I		ur tires.			Wiper Bla	ade			1.0	
- Shop Suppli	les				Accufit R	ear			1.0	
					Mac Wite		1.0			
					Air Filter				1.0	
					Shop Sup	oplies			1.0	
	Ho :	urs 5.00		Labor:	300.00	Parts:	65.65	Total:	365.65	
Workorder: Problem:	1509855 Pm service.l	Meter: Detail.	23813			In Date:	09/29/2015	Closed:	10/13/2015	
- Pm service.					Parts Lis	st			Q	
Rotate and balance all four wheels.					Syn0w20 5					
Shop Supplies					Napagold Oil Filter					
					Wiper Bla	ade			1.0	
					Wiper Bla	ade			1.0	
					Accufit R	1.0				
					Washer F	Fluid Conce	entr		1.0	
					Shop Sup	oplies			1.(
	Ho	urs 3.00		Labor:	180.00	Parts:	58.40	Total:	238.40	
	:						10/09/2015	Closed:	10/09/2015	
			23719 Ticket(s) Issue	ed		In Date:	10/03/2013	Gioseu.	10/09/2013	
	1 - Detail Ve shicle Wash T	ehicle Wash Ticket(s) Issu	Ticket(s) Issue	ed Labor:						
Problem: - 1 - Detail Ve	1 - Detail Ve ehicle Wash T Ho :	ehicle Wash ⁻icket(s) Issu urs 0.00	Ticket(s) Issue		0.00	Parts:	0.00	Total:	0.00	
Problem: - 1 - Detail Ve Workorder:	1 - Detail Ve shicle Wash T	ehicle Wash ⁻ icket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00					
Problem: - 1 - Detail Ve Workorder: Problem:	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service	ehicle Wash ⁻ icket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00	Parts: In Date:	0.00	Total:	0.00	
Problem: - 1 - Detail Ve Workorder: Problem:	1 - Detail Ve ehicle Wash T Ho : 1604105 P.M. service e.	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00	Parts: In Date:	0.00	Total:	0.00 04/26/2016	
Problem: - 1 - Detail Ve Workorder: Problem: - P.m. Service	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service e. balance all tir	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00 Parts Lis	Parts: In Date:	0.00	Total:	0.00 04/26/2016 Q	
Problem: - 1 - Detail Ve Workorder: Problem: - P.m. Service - Rotate and I	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service e. balance all tir	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00 Parts Lis Syn0w20	Parts: In Date:	0.00	Total:	0.00 04/26/2016 Q: 5.0	
Problem: - 1 - Detail Ve Workorder: Problem: - P.m. Service - Rotate and I	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service e. balance all tir	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00 Parts Lis Syn0w20 Oil Filter	Parts: In Date: St ades 24"	0.00	Total:	0.00 04/26/2016 Q: 5.0 1.0	
Problem: - 1 - Detail Ve Workorder: Problem: - P.m. Service - Rotate and I	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service e. balance all tir	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00 Parts Lis Syn0w20 Oil Filter Wiper Bla	Parts: In Date: St ades 24"	0.00	Total:	0.00 04/26/2016 04/26/2016	
Problem: - 1 - Detail Ve Workorder: Problem: - P.m. Service - Rotate and I	1 - Detail Ve ehicle Wash T Hou : 1604105 P.M. service e. balance all tir	ehicle Wash Ficket(s) Issu urs 0.00 Meter:	Ticket(s) Issue		0.00 Parts Lis Syn0w20 Oil Filter Wiper Bla 18" wipe	Parts: In Date: St ades 24" er blades ear	0.00	Total:	0.00 04/26/2016 Q 5.0 1.0 1.0 1.0	

Workorder: Problem:	1611908 P.m. service a	Meter: nd feels li	27254 ke draging ar	nd recall.	I	n Date:	11/17/2016	Closed:	11/30/20	016
- P.m. Service).				Parts List					Qty
	e lower engine	cover.			Syn0w20					5.00
- Rotate and b	alance tires.				Napagold	Oil Filter				1.00
- Transport ve	hicle to dealer	for recall	#16v-487.(air	bag).	Wiper Blad					1.00
- Shop Suppli					18" wiper	blades				1.00
					Cabin Air	Cabin Air Filter				
					Shop Sup	olies				1.00
	Hours :	s 5.50		Labor:	330.00	Parts:	44.87	Total:	374.87	
Workorder: Problem:	1702659 Low remote ba	Meter: attery war	27733 ning on dash.		l	n Date:	03/15/2017	Closed:	03/30/20	017
- Test and rep	lace keyfob ba	tterv.			Parts List					Qty
· · · · · · · · · · · · · · ·						oin Cell				1.00
	Hours	s 0.50		Labor:	30.00	Parts:	5.43	Total:	35.43	
Workorder: Problem:	1706294 P.M. Service.	Meter:	28020		lı	n Date:	06/26/2017	Closed:	06/29/20	017
- P.m. Service).				Parts List					Qty
- Rotate and b					Syn0w20					5.00
- Shop Suppli	es				Napagold					1.00
					Wiper Blac					1.00
					18" wiper					1.00
					Accufit Re					1.00
					Washer Fl		entr			1.00
				Laban	Shop Sup		10.40	Tatal	000 40	1.00
	Hours :	s 3.00		Labor:	180.00	Parts:	49.40	i otai:	229.40	
Workorder: Problem:	1800554 P.M. service.	Meter:	28571		l	n Date:	01/17/2018	Closed:	01/29/20	018
- P.m. service					Parts List					Qty
	o front tires .rot	tated and	balanced all f	four tires	Syn0w20					5.00
nitrogen fill tire					Napagold Oil Filter					1.00
- Shop Suppli	es				Wiper Blac	des 24"				1.00
					18" wiper					1.00
					14in Exact					1.00
					73827457		15 A			2.00
					Shop Sup	olies				1.00
					Tire Dispo	sal Fee				2.00
					240.00					

	1807217 P.M. service.	Meter:	29245			In Date:	07/16/2018	Closed:	07/19/2018
- P.m. service.					Parts Li	st			Q
- Replace two t	ires .rotate a	ind balance	all four tires.		Napagol	d Oil Filter			1.0
- Shop Supplie	S				Syn0w2	C			5.0
					14in Exa	actfit-rear			1.0
					18" wipe	er blades			1.0
					Wiper Bl	ades 24"			1.0
					7382745	571 195-65r	15 A		2.0
					Shop Su				1.0
						oosal Fee			2.0
	Hou :	ırs 4.00		Labor:	240.00	Parts:	293.81	Total:	533.81
	1900713 P.M. service.	Meter:	29946			In Date:	01/17/2019	Closed:	01/29/2019
- P.m. service.					Parts Li	st			Q
- Load test batt	ery and rech	arge fully .	Battery will n	ot hold a	Napagol	d Oil Filter			1.0
charge . R&r ba	,				Syn0w2	C			5.0
	Rotate and balance all four tires. Nitrofill all.					ctfit-rear			1.0
- Shop Supplie	S				18" wipe	er blades			1.0
					Wiper Bl	ades 24"			1.0
					Washer	Fluid Conce	entr		1.0
					Cabin Ai	r Filter			1.0
					Agm Bat	•			1.0
					Shop Su				1.0
	Hou :	ırs 4.00		Labor:	268.00	Parts:	277.01	Total:	545.01
	1905079 3 - Wash tick	Meter: et(s) issued	31270 J			In Date:	05/09/2019	Closed:	05/09/2019
- 3 - Wash ticke	et(s) issued								
	Hou :	irs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	1907375 P.M. service.	Meter:	32716			In Date:	07/17/2019	Closed:	07/23/2019
- P.m. service.					Parts Li	st			Q
- R&r front and	rear faded a	isset numb	ers.		Napagol	d Oil Filter			1.0
- Rotate and ba	alance all fou	ır tires . Nitı	ofill all.		Syn0w2	C			4.0
- Shop Supplie	S				Washer	Fluid Conce	entr		1.0
					14in Exa	actfit-rear			1.0
					18" wipe	er blades			1.0
					Wiper Bl	ades 24"			1.0
					Cabin Ai	r Filter			1.0
					Shop Su	pplies			1.0
	Hou	irs 3.80		Labor:	254.60	Parts:	54.02	Total:	308.62

:

Workorder:	1911590	Meter:	33820			In Date:	11/07/2019	Closed:	11/19/2019	
	Inspect brake			ollision da	mage .					
- Computer so four tires to ins Inspect and m this time.	spect brakes a	and measur	e pads and r	otors .	Parts Li Shop St				Q 1.	
- Shop Suppli	es									
	Hou :	ırs 1.00		Labor:	73.00	Parts:	4.00	Total:	77.00	
Workorder: Problem:	1912975 Damage to fi	Meter: ront bumper	33820 , left front fei	nder & hoc	od	In Date:	11/15/2019	Closed:	12/18/2019	
- Damage to f	• •		ider & hood							
	Ηοι :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	2000844 P.M. Service	Meter:	33835			In Date:	01/27/2020	Closed:	02/04/2020	
- P.m. service					Parts L	st			Q	
- Resurface b					Napagold Oil Filter 1.0					
Replace brake test .	e pads . Flush	and bleed b	brake system	I. Road	Syn0w2	0			4.	
- Rotate and h	nigh speed ba	lance all for	ur tires . Nitro	ofill all.	14in Exactfitblade118" wiper blades1					
- Shop Suppli	•									
					•	lades 24"			1.	
						ake Pad			1.	
					Shop Su	••			1.	
	Hou :	ırs 6.00		Labor:	438.00	Parts:	119.89	Total:	557.89	
Workorder: Problem:	2007665 Transition Pr	Meter: ep Charge	33835			In Date:	08/04/2020	Closed:	08/04/2020	
- Transition P	ron Chargo									
Indition	rep Charge									