

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 334089                      **Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/04/2003	Hours	Description	Quantity
- Wash Vehicle	3.10		
- Pre-Delivery Inspection			
- Make Duplicate Keys For New Vehicle			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	155.00

**Workorder:** 334111                      **Problem:** LADDER RACK

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/05/2003	Hours	Description	Quantity
- Po-Install Ladder Rack.Do Not Install Per Benard He Will Useit On Another Truck.		LADDER RACK 1450	1.00
<b>Parts Charge:</b>	227.46	<b>Labor Charge:</b>	0.00

**Workorder:** 334184                      **Problem:** 001 WASH TICKET ISSUED OUT 02/04/03

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/04/2003	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 02/04/03			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	7.14

**Workorder:** 346236                      **Problem:** P.M SERVICE

Meter Reading: 2637	Labor	Parts	Quantity
In Date: 08/19/2003	Hours	Description	Quantity
- Pm	2.00	10W30 MOTOR OIL	6.00
- Shop Supplies		SHOP SUPPLIES	1.00
		51522 WIX / PH59 L/F OIL FILTER	1.00
<b>Parts Charge:</b>	10.80	<b>Labor Charge:</b>	100.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 435560

**Problem:** P.M SERVICE

Meter Reading: 5846	Labor	Parts	
In Date: 02/20/2004	Hours	Description	Quantity
- Pm	2.00	10020 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		L/F G481 WIX 33481 FUEL FILTER	1.00
		AF1519 AIR FILTER USE LAF1520 FRM CA8755A	1.00
		10W30 MOTOR OIL	6.00
		SHOP SUPPLIES	1.00
		51522 WIX / PH59 L/F OIL FILTER	1.00
<b>Parts Charge:</b>	31.87	<b>Labor Charge:</b>	100.00

**Workorder:** 443816

**Problem:** NAIL IN L/F TIRE

Meter Reading: 7117	Labor	Parts	
In Date: 05/06/2004	Hours	Description	Quantity
- Repair Lf Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	50.00

**Workorder:** 456642

**Problem:** P.M SERVICE

Meter Reading: 9336	Labor	Parts	
In Date: 09/16/2004	Hours	Description	Quantity
- Pm	2.00	10W30 MOTOR OIL	6.00
- Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		SHOP SUPPLIES	1.00
		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		AF1519 AIR FILTER USE LAF1520 FRM CA8755A	1.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
<b>Parts Charge:</b>	39.80	<b>Labor Charge:</b>	100.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 539740

**Problem:** PM SERVICE, TAIL GATE CABEL RECALL

Meter Reading: 12875		Labor		Parts	
In Date: 03/22/2005	Close Date: 03/23/2005	Hours	Description		Quantity
- Pm		4.00	1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
- Tail Gate Cable Safety Recall 04007 Performed @ Delray Shop			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
- Shop Supplies			AF1519 AIR FILTER USE LAF1520 FRM CA8755A		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			10W30 MOTOR OIL		6.00
<b>Parts Charge:</b> 51.60		<b>Labor Charge:</b>	200.00		

**Workorder:** 556294

**Problem:** P.M SERVICE,CHECK FRONT END

Meter Reading: 16302		Labor		Parts	
In Date: 10/04/2005	Close Date: 10/11/2005	Hours	Description		Quantity
- Pm Service		6.30	SYN/ATF TRANS FLUID SYNTHETIC		16.00
- Transmission Flush			SHOP SUPPLIES		1.00
- Sr Fleet To Maroone For Warranty Work			1066 WHITE LITHIUM (CRC 05037)		1.00
- Shop Supplies			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			10W30 MOTOR OIL		6.00
			AF1519 AIR FILTER USE LAF1520 FRM CA8755A		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
<b>Parts Charge:</b> 106.21		<b>Labor Charge:</b>	315.00		

**Workorder:** 635843

**Problem:** INSTALL KNOCKBOX

Meter Reading: 17455		Labor		Parts	
In Date: 03/16/2006	Close Date: 03/22/2006	Hours	Description		Quantity
- Knockbox Fabricate Wiring		3.50	80865 FUSEHOLDER IMPERIAL 80865		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 6.20		<b>Labor Charge:</b>	175.00		

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 637773

**Problem:** P.M SERVICE

<b>Meter Reading:</b> 17401		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/20/2006	<b>Close Date:</b> 04/24/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>2.00</b>	10W30 MOTOR OIL		6.00
- Shop Supplies			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 59.61		<b>Labor Charge:</b> 100.00			

**Workorder:** 644672

**Problem:** FLAT TIRE

<b>Meter Reading:</b> 19963		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/25/2006	<b>Close Date:</b> 09/13/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Repair L/R Tire; Put Spare Away		<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 50.00			

**Workorder:** 644835

**Problem:** TIRESOLES OF BROWARD INC

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/23/2006	<b>Close Date:</b> 08/31/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 54.00	

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 646346

**Problem:** P.M SERVICE,TIRES

<b>Meter Reading: 20807</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 09/28/2006</b>	<b>Close Date: 10/04/2006</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>4.75</b>	10W30 MOTOR OIL		6.00
- Replace 4 Tires			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Fill Tires W/Nitrogen			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
- Shop Supplies			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			5LB FIREX ABC STOCK# 340280001		1.00
			744395900 245/75R16 245/75R16 WRANGLER HT		4.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			SHOP SUPPLIES		1.00
			TIRE DISPOSAL FEE		4.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
<b>Parts Charge: 680.32</b>		<b>Labor Charge: 41.25</b>			

**Workorder:** 736668

**Problem:** P.M.SERVICE

<b>Meter Reading: 23927</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 04/04/2007</b>	<b>Close Date: 04/11/2007</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>2.00</b>	10W30 MOTOR OIL		6.00
- Shop Supplies			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			SHOP SUPPLIES		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
<b>Parts Charge: 36.30</b>		<b>Labor Charge: 110.00</b>			

**Workorder:** 745249

**Problem:** P.M.SERVICE

<b>Meter Reading: 26934</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 10/05/2007</b>	<b>Close Date: 10/11/2007</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>3.00</b>	10W30 MOTOR OIL		7.00
- Clean & Lube Steering Shaft			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
			10020 INJECTOR CLEANER DON'T REORDER		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
<b>Parts Charge: 38.95</b>		<b>Labor Charge: 60.00</b>			

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 834283

**Problem:** SISTERS TOWING & TRANSPORTATON TOW FROM CONGRESS A

Meter Reading: 0	Labor	Parts			
In Date: 02/15/2008	Hours	Description	Quantity		
- Sisters Towing & Transportaton Tow From Congress Ave West Side Of Rd. S O Jfk - Tow To					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	78.00

**Workorder:** 837154

**Problem:** P.M.SERVICE,CHECK TRANS.

Meter Reading: 29724	Labor	Parts	
In Date: 04/17/2008	Hours	Description	Quantity
- Pm Service			
- C/S Shifting Not Smooth; Test Drive; Scan For Dtc; Check Solenoids W/Scanner; Unable To Verify Complaint; Flush Transmission & Test			
- Shop Supplies			
<b>Parts Charge:</b>	114.94	<b>Labor Charge:</b>	150.00
		SHOP SUPPLIES	1.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
		10W30 MOTOR OIL	6.00
		SYN/ATF TRANS FLUID SYNTHETIC	16.00

**Workorder:** 838051

**Problem:** CEI GROUP

Meter Reading: 0	Labor	Parts			
In Date: 02/15/2008	Hours	Description	Quantity		
- Cei Group					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	7,115.08

**Workorder:** 838836

**Problem:** DEAD BATTERY

Meter Reading: 30220	Labor	Parts	
In Date: 05/21/2008	Hours	Description	Quantity
- Ck Battery-Bad Cell; Replace Battery; Ck Charging Sys;			
- Shop Supplies			
<b>Parts Charge:</b>	91.61	<b>Labor Charge:</b>	45.00
		SHOP SUPPLIES	1.00
		GROUP 78 BATTERY (ACD 78PS)	1.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 843458                      **Problem:** KNOX BOX INOP

Meter Reading: 31859	Labor	Parts	Quantity
In Date: 08/28/2008	Hours	Description	Quantity
- Remove Knox Box And Test Operation Unit	0.50		
Failed.Remove Key. Give Unit To Fd&O For Repair.			
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 30.00		

**Workorder:** 846896                      **Problem:** P.M.SERVICE

Meter Reading: 33345	Labor	Parts	Quantity
In Date: 11/07/2008	Hours	Description	Quantity
- Pm Service	9.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- R&R Pads; Turn Rotors; R&R Calipers		10W30 MOTOR OIL	6.00
- Emergency Brake Service		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repair Ground To Tag Light; R&R Backup Light Bulb;		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
R&R L/F Running Light Bulb		3157 TAIL LIGHT BULBS	1.00
- Road Test		1401 BRAKE FLUID BRAKE FLUID	2.00
- Shop Supplies		3156 WAGNER BULB	1.00
		85/140 GEAR OIL GEAR LUBE	3.00
		REAR PADS	1.00
		SHOP SUPPLIES	1.00
		CALIPER	1.00
		09997 BRAKE CLEAN	2.00
		CALIPER	1.00
<b>Parts Charge:</b> 475.28	<b>Labor Charge:</b> 30.00		

**Workorder:** 934542                      **Problem:** REINSTALL CUSTOMERS KNOX BOX

Meter Reading: 35255	Labor	Parts	Quantity
In Date: 02/27/2009	Hours	Description	Quantity
- Reinstall Knox Box	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 60.00		

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 939265

**Problem:** P.M.SERVICE

Meter Reading: 38003	Labor	Parts	
In Date: 06/19/2009	Hours	Description	Quantity
- Pm Service	4.75	10W30 MOTOR OIL	7.00
- R&R Daytime Running Light Bulb; R&R Backup Light Bulb		3157 TAIL LIGHT BULBS	1.00
- Engine Light On; Install Scanner - Code Po440; Ck For Leaks;Tighten Filler Cap		SHOP SUPPLIES	1.00
- Install New Decal		3156 WAGNER BULB	1.00
- Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
<b>Parts Charge:</b> 28.21		<b>Labor Charge:</b> 285.00	

**Workorder:** 946908

**Problem:** P. M. SERVICE, & A/C fan speed does not work on the # 1 speed.

Meter Reading: 41417	Labor	Parts	
In Date: 12/10/2009	Hours	Description	Quantity
- P. M.	5.25	SHOP SUPPLIES	1.00
- Service, Tighten, & Lubricate Ladder Rack.		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Remove Steering Shaft, Lube, Re-Install.		10W30 MOTOR OIL	6.00
- Verify, Needs Two Rear Tires. R/R Tires, Mount, Balance, Add N2, Rotate To Front.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		TIRE DISPOSAL FEE	2.00
		744395900 245/75R16 245/75R16 WRANGLER HT	2.00
<b>Parts Charge:</b> 406.15		<b>Labor Charge:</b> 630.00	



1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1005977

**Problem:** P. M., & check all lights (passenger side parking light is out)

Meter Reading: 45672	Labor	Parts	
In Date: 06/07/2010	Hours	Description	Quantity
- P. M. Service.	6.00	744395900 245/75R16 245/75R16 WRANGLER HT	2.00
- Verify, Two Rear Tires Need Replacement. R&R Two		SHOP SUPPLIES	1.00
Tires, Mount, Balance, Rotate To Front. Add Nitrogen.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- C/C: Light Out. Verify. Passenger Side Daytime Running		TIRE DISPOSAL FEE	2.00
Light Out. R&R Bulb.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Check Ladder Rack, Lube, Adjust.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Verify, Nail In F/R Tire. Dismount, Patch, Mount,		3157 TAIL LIGHT BULBS	1.00
Balance, Rotate To Driver'S Side Rear, Add Nitrogen.		10W30 MOTOR OIL	6.00
- Shop Supplies		31-22 WIPER BLADES 22" WIPER BLADE	2.00
<b>Parts Charge:</b> 419.45		<b>Labor Charge:</b> 360.00	

**Workorder:** 1013687

**Problem:** P. M., & front of vehicle shakes/vibrates at 45-50 mph

Meter Reading: 50563	Labor	Parts	
In Date: 12/13/2010	Hours	Description	Quantity
- P. M. Service.	6.00	3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Remove Steering Shaft, Lube & Reinstall.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Check Ladder Rack. Remove Slides, Lube, Reinstall,		10W30 MOTOR OIL	7.00
Adjust, & Tighten.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- C/C: Shakes At 45-50 Mph. Rotate Tires, Balance All,		SHOP SUPPLIES	1.00
Correct Nitro Levels, & Test Drive.			
- Shop Supplies			
<b>Parts Charge:</b> 42.46		<b>Labor Charge:</b> 360.00	

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1106112

**Problem:** P. M., passenger side front parking light not working, & install new toolbox

<b>Meter Reading: 53412</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/09/2011	<b>Close Date:</b> 06/29/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P. M. Service.	<b>4.50</b>	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Replace Right Front Running Light Bulb.		3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
-	Install New Tool Box.		10W30 MOTOR OIL	7.00	
-	Service Ladder Rack.		3157 TAIL LIGHT BULBS	1.00	
-	Shop Supplies		TOOL BOX	1.00	
			SHOP SUPPLIES	1.00	
			6678 AIR FILTER FRM CA8755A WIX 46678	1.00	
<b>Parts Charge:</b> 500.32		<b>Labor Charge:</b> 270.00			

**Workorder:** 1107919

**Problem:** CHECK CHARGING SYSTEM

<b>Meter Reading: 54068</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/28/2011	<b>Close Date:</b> 07/29/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	C/S: Check Battery & Electrical System. Check & Replace Bad Battery, Check Charging System, Check For Draw & Test Drive.	<b>1.00</b>	SHOP SUPPLIES	1.00	
-	Shop Supplies		GROUP 78 BATTERY (ACD 78PS)	1.00	
<b>Parts Charge:</b> 90.63		<b>Labor Charge:</b> 60.00			

**Workorder:** 1113290

**Problem:** P. M. SERVICE

<b>Meter Reading: 57727</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/19/2011	<b>Close Date:</b> 12/27/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P. M. Service	<b>4.00</b>	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Verify, Steering Sticking. Remove Steering Shaft, Lubricate, Reinstall, Grease Steering Points.		10W30 MOTOR OIL	7.00	
-	Service Ladder Rack.		SHOP SUPPLIES	1.00	
-	Shop Supplies				
<b>Parts Charge:</b> 24.51		<b>Labor Charge:</b> 240.00			

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1207137

**Problem:** pm, ck battery

Meter Reading: 57915	Labor	Parts	
In Date: 07/31/2012	Hours	Description	Quantity
- Pm	9.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Repaired Socket To Back Up Light		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Battery Failed Load Recharged Battery And Retest And Passed		10W30 MOTOR OIL	7.00
		SHOP SUPPLIES	1.00
- Tire Repaired Rr Tire		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repaired Wiring And Vacuum Lines In Engine Compartment From Animal Damages			
- Ck For Codes Present None At This Time			
- Tighened Ladder Rack			
- Shop Supplies			
<b>Parts Charge:</b>	39.30	<b>Labor Charge:</b>	555.00

**Workorder:** 1301007

**Problem:** pm, ac not working, window passenger side does not close

Meter Reading: 58943	Labor	Parts	
In Date: 01/29/2013	Hours	Description	Quantity
- Pm	8.00	SHOP SUPPLIES	1.00
- Replace Right Front Window Regulator		PH3675 OIL FILTER LBF	1.00
- Ck Ac Not Working Verify Concern Test Sys Pressure		10W30 BULK SR	7.00
Evacuate Add Leak Dectection Dye Recharge Perform		Window Regulator - Right Front	1.00
Leak Ck And Ws Unable To Find Leak At This Time		R134A REFRIGERANT	2.00
- Svc Ladder Rack		WINDOW REGULATOR	1.00
- Shop Supplies			
<b>Parts Charge:</b>	127.67	<b>Labor Charge:</b>	480.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1308324

**Problem:** pm

**Meter Reading:** 60887

**In Date:** 08/19/2013

**Close Date:** 08/27/2013

**Labor**

**Hours**

**Description**

**Parts**

**Quantity**

- Pm	<b>2.00</b>	10W30 BULK SR	7.00
- Shop Supplies		WASHER FL	1.00
		SHOP SUPPLIES	1.00
		PH3675 OIL FILTER LBF	1.00
		10W30 MOTOR OIL	7.00
		WIPER BLADE	2.00
		G3727 FUEL FILTER LBF	1.00
<b>Parts Charge:</b>	55.37	<b>Labor Charge:</b>	120.00

**Workorder:** 1405955

**Problem:** pm

**Meter Reading:** 63868

**In Date:** 06/17/2014

**Close Date:** 06/26/2014

**Labor**

**Hours**

**Description**

**Parts**

**Quantity**

- Pm	<b>2.00</b>	NAPAGOLD OIL FILTER	1.00
- Shop Supplies		10W30 BULK SR	7.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	27.21	<b>Labor Charge:</b>	120.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1501128

**Problem:** PM, CK ENGINE LIGH

Meter Reading: 66330	Labor	Parts	Quantity
In Date: 01/30/2015	Hours	Description	Quantity
- Pm	<b>23.00</b>	WIPER BLADE	2.00
- Repair Left And Right Turn Signal Park Light And Running Light		10W30 BULK SR	7.00
		RESISTOR	1.00
- Ck And Replace Bad Ac Blower Resistor		NAPAGOLD AIR FILTER	1.00
- Replace All 4 Tires		REMAN BRAKE CALIPER	1.00
- Resurface Front And Rear Rotors Rr Front And Rear Pads With Calipers Svc Emergency Brake Cable Test Drive After Repair		744395900 245-75R16	4.00
		NAPAGOLD FUEL FILTER	1.00
- Ck Engine Light Is On Scan Found Code Po442 Po446 Perform Pinpoint Test Trace All Evap Hose And Found Bad Vent Solenoid And Hose Replace Vent Solenoid Hose And Clear Codes		DISC BRAKE PADS	1.00
		VAPOR CAN VENT VALVE	1.00
- Fill All Tires With Nitrogen		JUMPER HARNESS (EVAP CANN)	1.00
- Test Drive After Repair		BULB	2.00
- Shop Supplies		WASHER FL	1.00
		NAPAGOLD OIL FILTER	1.00
		TIRE DISPOSAL FEE	4.00
		VENT SOLENOID	1.00
		BULB	2.00
		VENT HOSE	1.00
		BLOWER MOTOR RESISTOR	1.00
		SHOP SUPPLIES	1.00
		REMAN BRAKE CALIPER	1.00
		DISC BRAKE PADS	1.00
<b>Parts Charge:</b>	1,402.35	<b>Labor Charge:</b>	1,380.00

**Workorder:** 1507553

**Problem:** pm, trouble light

Meter Reading: 68286	Labor	Parts	Quantity
In Date: 07/29/2015	Hours	Description	Quantity
- Pm	<b>8.00</b>	GAS CAP NON-LOCKING	1.00
- Ck Engine Lign Is On Scan Foiund Code Po446 Perform Pinpoint Fund Bad Evap Canister And Gas Cap Replace Evap Canister Gas Cap And Clear Codes		CANISTER	1.00
- Replace Tail Gate Handle And Bezel		TAILGATE HANDLE	1.00
- Test Drive After Repair		10W30 BULK SR	7.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		SHOP SUPPLIES	1.00
		TAIL GATE HANDLE BEZEL	1.00
		USED FIRE X REFURBISHED	1.00
<b>Parts Charge:</b>	344.94	<b>Labor Charge:</b>	480.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1509857

**Problem:** bad battery

Meter Reading: 68921	Labor	Parts	
In Date: 09/29/2015	Hours	Description	Quantity
- Ck Dead Battery Test Battery Bad Replace Battery Ck	0.75	GROUP 78 BATTERY	1.00
Charging Sys		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	96.83	<b>Labor Charge:</b>	45.00

**Workorder:** 1600855

**Problem:** P.M.SERVICE. CHECK ENGINE LIGHT STAYS ON

Meter Reading: 70360	Labor	Parts	
In Date: 01/26/2016	Hours	Description	Quantity
- Pm	10.00	10W30 BULK SR	7.00
- Ck Engine Light In On Scan Code Po446 Po300 Perform		NAPAGOLD OIL FILTER	1.00
Pinpoint Test Found Bad Fuel Pump And Bad Fuel		NAPAGOLD FUEL FILTER	1.00
Pressue Sensor Replace Fuel Pump Assembly With		SHOP SUPPLIES	1.00
Pressrue Sensor Install New Wire Harness And Clear Cod		module kit	1.00
- Test Drive 65 Miles Before And After Repair		22" WIPER BLADE	2.00
- Remove And Lube Steering Shaft		WASHER FLUID CONCENTR	1.00
- Sensor Ladder Rack			
- Shop Supplies			
<b>Parts Charge:</b>	348.59	<b>Labor Charge:</b>	600.00

1/30/2017  
3:07:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139717 2003 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

**Workorder:** 1608692

**Problem:** PM Service

Meter Reading: 73178 In Date: 08/22/2016	Close Date: 09/09/2016	Labor Hours	Description	Parts	Quantity
- P.M.Service		<b>14.00</b>	10W30 BULK SR		7.00
- Repair Leaking Orings,Evacuate,Recharge, Add Dye. C/K For Leak.			USED FIRE X REFURBISHED SHOP SUPPLIES		1.00 1.00
- Replace Leaking Brake Lines From Hyd. Proportional Valve To Abs Pump,Flush&Bleed Brake System.			B FLUID DOT 3-32OZ 22" WIPER BLADE		1.00 2.00
- C/K Engine Light Was On, Scan & Found Code#Po449, Perform Pin Point Test & Found Bad Vent Solenoid. R/R Vent Solenoid &Clear Code.			VENT SOLENOID WASHER FLUID CONCENTR NON-CHLOR BRAKE CLNR		1.00 1.00 2.00
- Test Drive Before &After Repairs.			NAPAGOLD OIL FILTER E8 A/C OIL UNIV W DYE		1.00 1.00
- Service Ladder Rack.			BRAKE LINE MADE		2.00
- Shop Supplies			SOUTH REGION R134A JUMPER HARNESS (EVAP CANN)		3.00 1.00
<b>Parts Charge:</b>		440.05	<b>Labor Charge:</b>		840.00

**Workorder:** 1612778

**Problem:** remove knox box

Meter Reading: 74661 In Date: 12/14/2016	Close Date: 12/20/2016	Labor Hours	Description	Parts	Quantity
- Remove Knox Box		<b>1.00</b>	SHOP SUPPLIES		1.00
- Shop Supplies					
<b>Parts Charge:</b>		2.00	<b>Labor Charge:</b>		60.00

**Workorder:** 1612799

**Problem:** Transition Prep Charge

Meter Reading: 74516 In Date: 12/14/2016	Close Date: 12/14/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		<b>2.00</b>			
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		0.00

Total Parts Charges:	<b>6,372.99</b>	Total Labor Charges:	<b>8,756.25</b>	Total Comm. Charges:	<b>7,254.22</b>
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------