10198088 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)

**Workorder:** 1500494 **Meter:** 1 **In Date:** 01/14/2015 **Closed:** 01/14/2015

**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Workorder: 1501205 Meter: 1 In Date: 02/02/2015 Closed: 02/13/2015

Problem: BROKEN SPRING

provided by franks mower nc Shop Supplies 1.00

- Shop Supplies

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

**Workorder:** 1505887 **Meter:** 62 **In Date:** 06/12/2015 **Closed:** 06/19/2015

Problem: wont start up

- trace and repair damage wire harness for starting sys Parts List Qty

- Shop Supplies Shop Supplies 1.00

Hours 2.50 Labor: 150.00 Parts: 2.00 Total: 152.00

Workorder: 1600672 Meter: 184 In Date: 01/21/2016 Closed: 01/27/2016

Problem: svc and new shut

- pm- svc hyd system- svc hyd system- Napagold Air Filter1.00

- ck chute replace discharge chute Fuel Fil 1.00

- wash eq Napagold Fuel Filter 1.00

- Shop Supplies Napagold Oil Filter 1.00 15w40 Bulk South Reg 4.00

Napa Trans Filter 1.00

deck chutes 1.00
Shop Supplies 1.00

Hours 7.00 Labor: 420.00 Parts: 118.37 Total: 538.37

:

Workorder: 1700568 Meter: 184 Problem: pm/ no start/ right switch/ slow F&R	In Date: 01/19/2017 Closed: 01/31/201	7
- Pm	Parts List	Qty
- Service hyd sys diag slow forward and reverse tightn by	Napagold Oil Filter 1	1.00
pass valve	15-40 Oil 4	1.00
- Replace right side safety	Fuel Fil 1	1.00
- Replace drive belt and Pto Belt	Napagold Air Filter 1	1.00
- Shop Supplies	Non-chlor Brake Clnr 1	1.00
	Napa Trans Filter 1	1.00
	Aw68 Hydro Fluid Hydr	4.00
	Napa 20w50 Qt 3	3.00
	Switch 1	1.00
	Seat Switch 1	1.00
	Belt 1	1.00
	481460 Clutch Belt Sc	1.00
	Shop Supplies 1	1.00
Hours 8.50 Labor:	510.00 Parts: 214.48 Total: 724.48	
Workorder: 1702042 Meter: 426 Problem: P.M.SERVICE/ HYD. LEAK.	In Date: 02/28/2017 Closed: 03/30/201	7
- Need No Pm. Had Pm done in janby Se Shop	Parts List	Qty
- Replace all rollers on deck.	Spindle Cap	2.00
- Replace air filter cover.	Anti-scalp Wheel	1.00
- C/c hyd oil leak.found loose hose clamps on resevoir.repair	Carriage Bolt 4	1.00
and test run.	Lug Nut	4.00
- Wash equipment to diagnose hyd. leak.	Anti Scalp Wheel	3.00
- Shop Supplies	Roller Shaft 1	1.00
	Air Filter Cleaner Cap 1	1.00
	Shop Supplies 1	1.00
Hours 3.75 Labor:	225.00 Parts: 272.32 Total: 497.32	
Workorder: 1703716 Meter: 427 Problem: NEW BATTERY	In Date: 04/12/2017 Closed: 04/17/201	7
- C/c Battery.test battery bad.replace battery.check charging		Qty
system Shop Supplies	Battery 1	1.00
- Shon Supplies	Shop Supplies 1	1.00
- Onop Supplies	Shop Supplies	

Workorder: 1708539 Meter: 642 Problem: REAR TIRES,HYD.FAN AND COVER,ROLL B	In Date: 08/29/2017 Closed: AR PIN, DECK ROLLER PIN&ROLLERS.	09/21/2017
- C/c Rear tires.replace 2 rear tires.mount add N2.	Parts List	Qty
- C/c hyd fan cover cover.install new fan cover on R/h hyd.	24-1200-12b Turf M Carl	2.00
pump.	Turf Tread 24x12x12	2.00
<ul> <li>Replace front rollers and shaft.install new roll bar pin assembly.</li> </ul>	Fan Guard Shroud	1.00
- Shop Supplies	Anti Scalp Wheel	3.00
- Shop Supplies	Roller Shaft	1.00
	Rops Hinge Pin Asm	1.00
	Grease Cap	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	0.00
Hours 5.00 Labor:	300.00 Parts: 767.00 Total:	1,067.00
Workorder: 1803362 Meter: 761 Problem: PM Service Intermittent no stat.Check battery,s	In Date: 03/30/2018 Closed: starting and charging system.	04/30/2018
- Pm Service.	Parts List	Qty
- Service hydraulic system.	Napagold Air Filter	1.00
- Replace rollers,chute,cap,repair anti rotation arm on Pto.	Fuel Fil	1.00
- C/c no start.load test battery passed.check charging	Napagold Oil Filter	1.00
system.	15w40 Bulk South Reg	4.00
- Wash equipment.	Napa Trans Filter	1.00
- Shop Supplies	Napa 20w50 Qt	2.00
	deck chutes	1.00
	Lug Nut	3.00
	Anti-scalp Wheel	3.00
	Carriage Bolt	3.00
	Rain Cap	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 9.75 Labor:	585.00 Parts: 259.22 Total:	844.22
Workorder: 1808084 Meter: 849 Problem: FRONT RIM&TIRE REPLACED	In Date: 08/07/2018 Closed:	08/20/2018
- Verify tire and rim assembly bad.replace assemblysolid	Parts List	Qty
wheel.	S9278 Tire-wheel Assy	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 0.25 Labor:	15.00 Parts: 175.78 Total:	190.78

Workorder: Problem:	1809064 CHECK B	Meter: 894 OTH FRONT WHEELS	5	ı	n Date:	09/04/2018	Closed:	09/27/20	018
- C/c front tire	s.replace f	ront solid tires.replace	bearings and	Parts Lis	t				Qty
bolts.			S9278 Tir	e-wheel A	Assy			2.00	
		g.remove clutch spray o	out dust and	Wheel Spacer					4.00
debris from co		stall ,test run.		43583 Sle	eve Scag	3			2.00
- Shop Suppli	es			Nut					2.00
				04001167	Wheel B	olt N			2.00
				Shop Sup	plies				1.00
	H :	Hours 3.75	Labor:	225.00	Parts:	409.25	Total:	634.25	
Workorder: Problem:	1811219 Bad batte	<b>Meter:</b> 951 ry.Check Hydraulic flui	d leak.	I	n Date:	10/31/2018	Closed:	11/13/20	018
		attery.bad.replace batt	ery and check	Parts Lis	t				Qty
charging syste				Battery					1.00
<ul> <li>C/c check hy equipment for</li> </ul>		d 1 quart to hyd.reservo	oir.inspect	Aw68 Bul	k Sr				1.00
• •		gine. Engine oil low.ad	ld 5	15w40 Bu	Ik South	Reg			1.00
quarttighten				Shop Sup	plies				1.00
- Shop Suppli	es								
	H :	Hours 2.50	Labor:	167.50	Parts:	128.40	Total:	295.90	
Workorder: Problem:	1904181 PM Service	<b>Meter:</b> 1129 ce.Over heat.Smoking.	Loose fan.	I	n Date:	04/17/2019	Closed:	06/26/20	019
- Pm Service.				Parts Lis	t				Qty
		spect all and R/r hyd. fi	ilter.correct	Napagold Air Filter 1.					1.00
fluid level(oem) suction filter installed.				Fuel Fil					1.00
<ul> <li>C/c Radiator.verify bushing broken causing fan to damage radiator.r/r radiator,bushing, thermostat and gasket.flush engine Reasemble,add coolant,r/r coolant resevoir.</li> <li>Wash equipment.</li> <li>Shop Supplies</li> </ul>			Napagold		1.00				
			15w40 Bu		4.00				
			Napagold Oil Filter					1.00	
			Oil Filter					1.00	
				Napa Anti	freeze Ga	al			2.00
				Stay					1.00
				Thermost	at Gasket				1.00
				Thermost	at Assy				1.00
				Radiator					1.00
				Reservoir					1.00
				Rub Cush					1.00
				Shop Sup	plies				1.00
	H .	Hours 11.75	Labor:	787.25	Parts:	1,559.34	Total:	2,346.59	9

Workorder: 1907037 Meter: 1 Problem: Broken belt.	157	lı	n Date:	07/08/2019	Closed:	07/22/201	19
- C/c belt.replace rollers,chute,deck belt a	and tensioner,idlers	Parts List					Qty
etctest mow.		Cutter Dec	k Belt			•	1.00
- Wash equipment.		Bearing			2	2.00	
- Shop Supplies		Pulley			•	1.00	
		Anti-scalp	Wheel			4	4.00
		Roller Sha	ft			•	1.00
		Deck Whe	el			(	3.00
		Lug Nut				4	4.00
		Carriage B	olt			4	4.00
		deck chute	es			•	1.00
		Shop Supp	olies			•	1.00
Hours 4.00 :	Labor	: 268.00	Parts:	474.51	Total:	742.51	
Workorder: 1907811 Meter: 1 Problem: Hydraulic oil leak.	196	lı	n Date:	07/29/2019	Closed:	10/15/201	19
- Verify pump leaking found L/h pump da	Parts List					Qty	
pump.flush cooler,lines.change fluid and f		Non-chlor Brake Clnr					2.00
- Replace two rear tires.mount and add N	12.	Napa 20w	50 Qt		11	1.00	
- Wash equipment.	Oil Filter					2.00	
<ul> <li>Replace two front bearing kit.retap dammeter shaft.install new nuts.</li> </ul>	age inreads on	Hydraulic Pump					1.00
- Replace battery.check charging system	24x12.00-12/4 Turf Master					2.00	
- Shop Supplies		Caster Nut			2.00		
		43583 Sle	eve Scag	l		2	2.00
		Bearing Ki	t			2	2.00
		Battery				•	1.00
		Shop Supp	olies			•	1.00
		Tire Dispo	sal Fee			2	2.00
Hours 10.75 :	Labor	: 784.75	Parts:	1,404.89	Total:	2,189.64	
Workorder: 1910292 Meter: 1 Problem: HOLE IN RADIATOR	200	lı	n Date:	10/04/2019	Closed:	10/29/201	19
- C/c hole in radiator.verify lower bushing						Qty	
lodgged in radiator fins.r/r radiator and all	Rub Cushion				2	2.00	
- Shop Supplies		Rad Cushi				2	2.00
		Rub Cushi	on			•	1.00
		Radiator				•	1.00
		Shop Supp	olies				1.00
		Chop Cup					
		Freight Ch					1.00

- Replace Steering Relays And Circuit Breaker For Charging System. Test Run - Test Battery Good. Charging System Good Shop Supplies	//2019
- Test Battery Good. Charging System Good Shop Supplies  Relay Wid40 Spr Relay Switch Shop Supplies  Hours 2.50 Labor: 182.50 Parts: 98.92 Total: 281.4  Workorder: 2002228 Meter: 1307 In Date: 03/03/2020 Closed: 03/17.  - C/c Pto Belt.replace Pto belt and idler pulley.test mow Shop Supplies  Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9 Shop Supplies  Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9 Shop Supplies  - T. steering arm/ reshape, make fishplates, reweld arm back in place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Workorder: 2006361 Meter: 1417 Problem: PM Service. Oil leaks Pm Service Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurerir (pilinder head flound rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies - Transition Prep Charge - Transition Prep Charge - Transition Prep Charge	Qt
- Shop Supplies	1.0
Workorder: 2002228 Meter: 1307 In Date: 03/03/2020 Closed: 03/17.  Problem: PTO Belt C/c Pto Belt replace Pto belt and idler pulley.test mow Shop Supplies	1.0
Relay Switch Shop Supplies Hours 2.50 Labor: 182.50 Parts: 98.92 Total: 281.4:  Workorder: 2002228 Meter: 1307 In Date: 03/03/2020 Closed: 03/17.  Problem: PTO Belt.  - C/c Pto Belt replace Pto belt and idler pulley.test mow. Parts List - Shop Supplies Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9  Workorder: 2003348 Meter: 1307 In Date: 04/02/2020 Closed: 04/08.  Problem: right front steering arm broke/ see note - rt. steering arm/ reshape, make fishplates, reweld arm back Parts List n place - Shop Supplies Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5:  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Problem: PM Service. Oil leaks Pm Service - C/c leaking oil replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear siston and cylinder damage.not cost effective to repair.reassemble Shop Supplies Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25.  Problem: Transition Prep Charge - Transition Prep Charge	1.0
Hours 2.50	1.0
Hours 2.50   Labor: 182.50   Parts: 98.92   Total: 281.4    Workorder: 2002228   Meter: 1307   In Date: 03/03/2020   Closed: 03/17.	1.00
Workorder: 2002228 Meter: 1307 In Date: 03/03/2020 Closed: 03/17.  Problem: PTO Belt.  - C/c Pto Belt.replace Pto belt and idler pulley:test mow Shop Supplies  Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9  Workorder: 2003348 Meter: 1307 In Date: 04/02/2020 Closed: 04/08.  Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back in place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Problem: PM Service Oil leaks.  - Pm Service - Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressureric yolinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25.  Problem: Transition Prep Charge  - Transition Prep Charge	1.0
Problem: PTO Belt.  - C/c Pto Belt.replace Pto belt and idler pulley.test mow Shop Supplies  Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9  Workorder: 2003348 Meter: 1307 Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back n place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Parts List Napagold Air Filter Napagold Oil Filter	-2
- Shop Supplies  Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9  Workorder: 2003348 Meter: 1307 Problem: right front steering arm broke/ see note - rt. steering arm/ reshape, make fishplates, reweld arm back no place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5  Workorder: 2006361 Problem: PM Service.Oil leaks Pm Service - Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear oiston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge - Transition Prep Charge  481460 Clutch Belt Sc Idler Pulley Shop Supplies  146.00 Parts: 78.97  In Date: 04/02/2020 Closed: 04/08.  Parts List Napagold Air Filter Napagold Air Filter Napagold Air Filter Napagold Fuel Filter Fuel Fil 15w40 Bulk South Reg Napagold Oil Filter	/2020
Idler Pulley Shop Supplies   Hours 2.00   Labor: 146.00   Parts: 78.97   Total: 224.9	Qt
Hours 2.00 Labor: 146.00 Parts: 78.97 Total: 224.9  Workorder: 2003348 Meter: 1307 In Date: 04/02/2020 Closed: 04/08.  Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.5  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Problem: PM Service. Oil leaks.  - Pm Service Service Hyd System.replace filter.correct fluid level C/c leaking oil. replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear oilston and cylinder damage.not cost effective to repair. reassemble Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25.  Problem: Transition Prep Charge - Transition Prep Charge	1.0
Workorder: 2003348 Meter: 1307 In Date: 04/02/2020 Closed: 04/08.  Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back in place - Shop Supplies  - Shop Supplies  - Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.50  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28.  Problem: PM Service. Service Hyd System.replace filter.correct fluid level. C/C leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rearpiston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25.  Problem: Transition Prep Charge	1.0
Workorder: 2003348 Meter: 1307 In Date: 04/02/2020 Closed: 04/08. Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back in place - Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.50  Workorder: 2006361 Meter: 1417 In Date: 06/26/2020 Closed: 07/28. Problem: PM Service.Oil leaks.  - Pm Service Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25. Problem: Transition Prep Charge	1.0
Problem: right front steering arm broke/ see note  - rt. steering arm/ reshape, make fishplates, reweld arm back in place - Shop Supplies  - Hours 3.50 - Hours 3.50 - Problem: PM Service. Oil leaks.  - Pm Service - Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  - Shop Supplies  - Shop Supplies  - Hours 9.75 - Labor: 711.75 - Parts: 173.22  - Total: 884.9  Workorder: 2008460 - Transition Prep Charge  - Transition Prep Charge	7
Shop Supplies  Hours 3.50 Labor: 255.50 Parts: 4.00 Total: 259.50  Workorder: 2006361 Problem: PM Service.Oil leaks.  Pm Service Service Hyd System.replace filter.correct fluid level. C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear oiston and cylinder damage.not cost effective to repair.reassemble. Shop Supplies  Parts List Napagold Air Filter Napagold Filter Napagold Filter Napagold Filter Napagold Oil Filter Napagold Oil Filter Napa 20w50 Qt Oil Filter Valve Cover Breather Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  Transition Prep Charge	/2020
- Shop Supplies  Hours 3.50 Eabor: 255.50 Parts: 4.00 Total: 259.5i  Workorder: 2006361 Meter: 1417 Problem: PM Service.Oil leaks.  - Pm Service - Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  - Shop Supplies  Hours 9.75 Eabor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge	Qt
Hours 3.50 Hours 3.50 Hours 3.50 Hours 3.50 Hours 3.50 Hours 255.50 Hours 3.50 Hours 255.50 Hours 4.00 Hours 259.55  In Date: 06/26/2020 House: 07/28.  Parts List  Napagold Air Filter Napagold Air Filter Napagold Air Filter Napagold Fuel Filter Napagold Fuel Filter Fuel Fil Hours 9.75 Hours 9.75 Hours 9.75 Labor: 711.75 Hours 9.75 Hours 9.	1.0
Problem: PM Service.Oil leaks.  - Pm Service Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  - Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25/2020  - Transition Prep Charge	<b>60</b>
Problem: PM Service.Oil leaks.  - Pm Service Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear piston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  - Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22  Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25/2020  - Transition Prep Charge	3/2020
- Service Hyd System.replace filter.correct fluid level C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear oiston and cylinder damage.not cost effective to repair.reassemble Shop Supplies  - Shop Supplies  - Shop Supplies  - Shop Supplies  - Hours 9.75 - Labor: - Transition Prep Charge  - Transition Prep Charge  Napagold Air Filter Napagold	
- C/c leaking oil.replace crankcase vent diaphram.found excessive backpressurer/r cylinder head and found rear oiston and cylinder damage.not cost effective to repair.reassemble.  - Shop Supplies  - Shop Supplies  - Shop Supplies  - Hours 9.75  - Hours 9.75  - Transition Prep Charge  - Transition Prep Charge  - Napagold Air Filter Napagold Fuel Filter Fuel Fil	Qt
Packersive backpressurer/r cylinder head and found rear poiston and cylinder damage.not cost effective to repair.reassemble.  - Shop Supplies  - Hours 9.75 - Labor: 711.75  - Problem: Transition Prep Charge  - Transition Prep Charge  Napagold Fuel Filter  Fuel Fil  15w40 Bulk South Reg  Napagold Oil Filter  Napa 20w50 Qt  Oil Filter  Valve Cover Breather  Shop Supplies  - In Date: 08/25/2020 Closed: 08/25/2020  - Transition Prep Charge	1.0
biston and cylinder damage.not cost effective to repair.reassemble.  - Shop Supplies  Shop Supplies  Fuel Fil  15w40 Bulk South Reg  Napagold Oil Filter  Napa 20w50 Qt  Oil Filter  Valve Cover Breather  Shop Supplies  Hours 9.75  Labor: 711.75 Parts: 173.22 Total: 884.9  **Total: 884.9**  **Norkorder: 2008460 Meter: 1417  Problem: Transition Prep Charge  - Transition Prep Charge	1.0
Fuel Fil  15w40 Bulk South Reg Napagold Oil Filter Napa 20w50 Qt Oil Filter Valve Cover Breather Shop Supplies  Hours 9.75 Eabor: 711.75 Parts: 173.22 Total: 884.99  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge	1.0
Napagold Oil Filter Napa 20w50 Qt Oil Filter Valve Cover Breather Shop Supplies Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  - Transition Prep Charge	1.0
Napa 20w50 Qt Oil Filter Valve Cover Breather Shop Supplies Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  - Transition Prep Charge	4.0
Oil Filter Valve Cover Breather Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  In Date: 08/25/2020 Closed: 08/25/2020  In Date: 08/25/2020 Closed: 08/25/2020	1.00
Valve Cover Breather Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  - Transition Prep Charge	2.0
Shop Supplies  Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.99  Workorder: 2008460 Meter: 1417 Problem: Transition Prep Charge  In Date: 08/25/2020 Closed: 08/25/2020  Transition Prep Charge	1.00
Hours 9.75 Labor: 711.75 Parts: 173.22 Total: 884.9  Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25/ Problem: Transition Prep Charge  - Transition Prep Charge	1.00
: Workorder: 2008460 Meter: 1417 In Date: 08/25/2020 Closed: 08/25/2020 Problem: Transition Prep Charge  - Transition Prep Charge	1.00
Problem: Transition Prep Charge - Transition Prep Charge	1
· · ·	/2020
Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00	
·	0