Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 745411 Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0 Labor

In Date: 10/10/2007 Close Date: 10/10/2007 Hours Description Quantity

- Pre-Delivery Inspection 2.00

Parts Charge: 0.00 Labor Charge: 120.00

Workorder: 746863 Problem: INSTALL TOOL BOX

Meter Reading: 348 Labor Parts

 In Date: 11/06/2007
 Close Date: 11/07/2007
 Hours
 Description
 Quantity

 - Install Tool Box - Shop Supplies
 1.00
 TBSD72LP TOOL BOX (UNITED WELDING)
 1.00

 - SHOP SUPPLIES
 1.00

Parts Charge: 429.20 Labor Charge: 60.00

Workorder: 842521 Problem: P.M SERVICE

Meter Reading: 1571 Labor **Parts** Quantity In Date: 08/07/2008 Close Date: 08/11/2008 Hours Description Pm Service 2.75 1372 OIL FILTER FRM PH2 WIX 51372 1.00 Shop Supplies G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00 **5W20 ENGINE OIL** 7.00 31-20 WIPER BLADES 20" BLADE 2.00 SHOP SUPPLIES 1.00

Parts Charge: 47.00 Labor Charge: 165.00

Workorder: 842678 Problem: 001 DETAIL VEHICLE 08/07/08

Meter Reading: 0 Labor Parts

In Date: 08/07/2008 Close Date: 08/12/2008 Hours Description Quantity

- 001 Detail Vehicle 08/07/08

Parts Charge: 0.00 Labor Charge: 0.00 Commercial Charge: 90.00

Parts

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 844076 Problem: REMOVE COMPUTER STAND FROM OLD TRUCK AND INSALL IN NEW.

Meter Reading: 1594 Labor

In Date: 09/11/2008 Close Date: 09/16/2008 Hours Description Quantity
- Remove Computer Stand And Harness From 5.00 SHOP SUPPLIES 1.00

10129981, Reinstall In New Truck And Wire In Wiring

Harness.

Shop Supplies

Parts Charge: 2.00 Labor Charge: 300.00

Workorder: 845702 Problem: 002 KEYS ISSUED OUT 10/15/08

Meter Reading: 0 Labor Parts

 In Date: 10/15/2008
 Close Date: 10/15/2008
 Hours
 Description
 Quantity

 - 002 Keys Issued Out
 10/15/08
 0.40
 DUPLICATE VEHICLE KEYS
 2.00

Parts Charge: 6.00 Labor Charge: 24.00

Workorder: 845933 Problem: INSTALL STROBES LIGHTS.

Meter Reading: 2633 Labor Parts

In Date: 10/20/2008 Close Date: 11/06/2008 Hours Quantity Description Fabricate And Install Strobe Light Sys In Cab.Install Relay 9.00 **COIN HOLDERS** 1.00 STROBE STRIP Harness, Switches And Wiring. 1.00 Repair 1 Tire Mount Back On Left Rear. SHOP SUPPLIES 1.00 **UPLIFTER SWITCH** 1.00 Shop Supplies **RELAY KIT** 1.00 ABOVE VISOR STROBE 1.00

Parts Charge: 1,809.61 Labor Charge: 60.00

Parts

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 934122 Problem: P.M SERVICE

Meter Reading: 6655			Labor	Pa	rts
In Date: 02/18/2009	Close Date: 02/26/2	2009	Hours	Description	Quantity
- Pm Service			3.75	SHOP SUPPLIES	1.00
 Rotate And Hi Speed Bala 	nce All 4 Tires.			USED FIREX REFURBED FIRE EXTINGSH	IERS 1.00
Shop Supplies				5W20 ENGINE OIL	7.00
				1372 OIL FILTER FRM PH2 WIX 51372	1.00
				CA10262 AIR FILTER MTC FA1883 WIX 49	1.00
	Parts Charge:	40.43 I	Labor Charge:	225.00	

Workorder: 945424 Problem: P.M. Service

Meter Reading: 14274		Labor	Parts	
In Date: 10/29/2009	Close Date: 12/02/2009	Hours	Description	Quantity
- P.M Service.		12.25	FLOOR MAT SET	1.00
 Mount Two New Tires, Ro 	tate & Balance All Four Tires.		SHOP SUPPLIES	1.00
- Test Starting & Charging S	System, Charge & Test Battery,		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Failed Load Test, R&R Ba	ttery.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Remove Computer Stand.	Fire Extingusher & Items From		D3TZ2457B BRAKE PEDAL PAD	1.00
•	ace Floor Mat, Reinstall When		31-20 WIPER BLADES 20" BLADE	2.00
Done.	acci ioci mat, itomotan iiion		5W20 ENGINE OIL	7.00
- Alignment.			TR416 VALVE STEM	2.00
T-/[D [W	onty Floor Mot		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
	enty Floor Mat.		TIRE DISPOSAL FEE	2.00
- Shop Supplies			1372 OIL FILTER FRM PH2 WIX 51372	1.00
			179636492 LT245/75R17 WRANGLER SR-A E	2.00

Parts Charge: 629.17 Labor Charge: 675.00

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1007292 Problem: P.M. Service..Service light on.

	Meter Reading: 21191		Labor	Parts	
	In Date: 07/12/2010	Close Date: 07/26/2010	Hours	Description	Quantity
-	Perform Pm Service.		6.75	CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
-	Install Two New Tires To	The Fronts And Balance All Four.		TIRE DISPOSAL FEE	2.00
-	Drive Vehicle To And Fror	n Dealer For Replacing Trottle		179636492 LT245/75R17 WRANGLER SR-A E	2.00
	Position Sensor Under Wa	arranty Asper Tsb#10-01-06		SHOP SUPPLIES	1.00
_	Shop Supplies	•		5W20 ENGINE OIL	7.00
				TR416 VALVE STEM	2.00
				1372 OIL FILTER FRM PH2 WIX 51372	1.00
				31-20 WIPER BLADES 20" BLADE	2.00

Parts Charge: 407.50 Labor Charge: 345.00

Workorder: 1012430 Problem: Right rear tire flat.

	Meter Reading: 25778		Labor	Parts	
	In Date: 11/05/2010	Close Date: 11/15/2010	Hours	Description	Quantity
-	Install One New Tire To R	light Rear.Nitrogen Fill And	1.00	179636492 LT245/75R17 WRANGLER SR-A E	1.00
	Balance Same.			SHOP SUPPLIES	1.00
-	Shop Supplies				

Parts Charge: 186.69 Labor Charge: 60.00

Workorder: 1013931 Problem: P.M. service.

Meter Reading: 27188		Labor	Parts	
In Date: 12/17/2010	Close Date: 12/28/2010	Hours	Description	Quantity
- Perform Pm Service.		4.25	5W20 ENGINE OIL	7.00
 Fabricate And Replace Mis 	ssing Hitch Pindel Pin With		1372 OIL FILTER FRM PH2 WIX 51372	1.00
New.			G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
 Rotate And Balance All Fo 	ur Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies			2560 HITCH PIN/CLIP	1.00
			18410 PINTLE PIN	1.00
			3157NA AMBER BULB	1.00
			SHOP SUPPLIES	1.00

Parts Charge: 42.00 Labor Charge: 255.00

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1105826 Problem: P.M. service and check battery had to jump start.

Meter Reading: 33493		Labor	Parts	
In Date: 06/02/2011	Close Date: 06/09/2011	Hours	Description	Quantity
- P.M. Service.		5.00	SHOP SUPPLIES	1.00
- Test Battery And Charging	g System.Charge And Retest		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
Battery,Fail Load Test.Re	place Defective Battery.		31-20 WIPER BLADES 20" BLADE	2.00
- Replace Brake Light Bulb.			5W20 ENGINE OIL	7.00
Rotate And Balance All Ti			09997 BRAKE CLEAN	1.00
- Shop Supplies			05046 BATTERY PROTECTOR (CRC)	1.00
5op 5.5pp.100			GROUP 65 BATTERY (MTC BXT-65-850)	1.00
			1372 OIL FILTER FRM PH2 WIX 51372	1.00

Parts Charge: 171.32 Labor Charge: 300.00

Workorder: 1112133 Problem: P.M. service.

Meter Reading: 39939		Labor	Parts	
In Date: 11/14/2011	Close Date: 11/29/2011	Hours	Description	Quantity
 Perform Pm Service. 		7.25	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Install Two New Tires To	The Front Wheels.Nitrogen Fill		1372 OIL FILTER FRM PH2 WIX 51372	1.00
And Balance All Four.			TR416 VALVE STEM	2.00
- Perform Wheel Alignment	Complete.		TIRE DISPOSAL FEE	2.00
- Shop Supplies	·		09997 BRAKE CLEAN	1.00
			31-20 WIPER BLADES 20" BLADE	2.00
			179636492 LT245/75R17 WRANGLER SR-A E	2.00
			5W20 ENGINE OIL	7.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			SHOP SUPPLIES	1.00

Parts Charge: 430.61 Labor Charge: 435.00

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1211193 Problem: P.M. service.

Meter Reading: 54488			Labor		Parts	
In Date: 11/16/2012	Close Date:	12/10/2012	Hours	Description		Quantity
 P.M. Service. Replace And Balance Four Replace Left Brake Light B Resurfaced Front Brake Ropads. Service And Lube Ca 	ulb. otors,Replace Brak		11.50	PH2 OIL FILTER LBF PH FORD FUEL FILTER 5W20 ENGINE OIL 179636492 LT245-75R17 31-20 WIPER BLADES 20		1.00 1.00 7.00 2.00 2.00
And Test Drive Complete Wheel Alignmen - Shop Supplies	t.Test Drive.			BRAKE PADS 179636492 LT245-75R17 CA10262 AIR FILTER MT 3157 TAIL LIGHT BULBS		1.00 2.00 1.00 1.00
	Parts Charge:	1,124.60	Labor Charg	USED FIREX REFURBED F SHOP SUPPLIES e: 690.00		1.00 1.00

Workorder: 1311550 Problem: P.M. Service.Check noise on right turns.

Meter Reading: 66855		Labor	Р	arts
In Date: 11/15/2013	Close Date: 11/27/2013	Hours	Description	Quantity
P.M. Service.		10.25	SHOP SUPPLIES	1.00
Replace Center Brake Lig	ht Bulb.		WIPER BLADE	2.00
Resurface Rear Brake Ro	tors,Replace Rear Brake		BRAKE PAD	1.00
Pads.Service And Lube R	ear Calipers.Flush And Bleed		REFLEX TRUCK SHOCK	2.00
System.Test Drive.	•		USED FIRE X REFURBISHED	1.00
Replace Leaking Front An	d Rear Shocks.		NAPAGOLD FUEL FILTER	1.00
Rotate And Balance All Fo			BRAKE CLEANER	1.00
Shop Supplies	741 11100.		NAPAGOLD OIL FILTER	1.00
Onop Oupplies			5W20 ENGINE OIL	7.00
			REFLEX TRUCK SHOCK	2.00
			045.00	

Parts Charge: 381.28 Labor Charge: 615.00

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1407515 Problem: P.M. Service.Brakes noisy.Check lighter fuse.

Meter Reading: 74966		La	bor	Parts	
In Date: 07/31/2014	Close Date: 08/	19/2014 H d	urs	Description	Quantity
- Pm Service.Replace Lighte	er Fuse.	2	3.25 7	5W140 FORD AXLE LUBE	3.00
- Inspect For Brake Noise.R	eplace Front Brake P	ads,Two	F	PTEX ULTRA GREY 3OZ	1.00
Front Calipers And Two Fr	ont Brake Rotors.Cle	an And	ŀ	(A8A THROTTLE BODY- U	1.00
Repack Wheel Bearings.F			4	08 FUEL INJECTION CL	1.00
Drive.			1	IAPAGOLD OIL FILTER	1.00
Replace Open Right Head	lamp Seal Beam		F	PADS	1.00
 Perform Engine Tune Up.F 	•	luge Had	1	IAPAGOLD AIR FILTER	1.00
To Extract Two Broken Plu		lugs.i iau	1	IAPAGOLD FUEL FILTER	1.00
Preform Induction Cleaning		a Injectore	(Caliper w/ Hardware - Left Rear (Eclipse	1.00
			7	TRE DISPOSAL FEE	4.00
Replace Rear Pinnion Sea		nuai.	V	Vheel Seal - Front Wheel	2.00
Install Four Tires And Balla			F	PEDAL PAD	1.00
Perform Complete Wheel	Alignment.		(CALIPER	1.00
Shop Supplies			E	BRAKE CLEANER	1.00
				BRAKE FLUID QT	1.00
			F	USE	1.00
			(CALIPER	1.00
				W20 ENGINE OIL	7.00
				SPARK PLUG	8.00
				JSED FIRE X REFURBISHED	1.00
				IALOGEN LAMP	1.00
				RICTION MODIFIER	1.00
				CALIPER WASHER	4.00
				Caliper w/ Hardware - Right Rear (Eclips	1.00
				VIPER BLADE	2.00
				SEAL	1.00
				SHOP SUPPLIES	1.00
				DISC BRAKE ROTOR-HUB	2.00
				R416 VALVE STEM	4.00
				79636492 LT245-75R17	4.00
			5	068 PENTRATING OIL	1.00

Total Parts Charges:

8,419.67

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170971 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1505194	Probler	n: Pm servi	ce			
Meter Reading: 82621			Labor		Parts	
In Date: 05/22/2015	Close Date: 06/0	04/2015	Hours	Description		Quantity
- Pm Service.			9.75 NAP	AGOLD AIR FILTER		1.00
 Test And Replace Defect 	ive Battery.		WIP	ER BLADE		2.00
- Replace Two Body Moun	its And Two Tool Box Li	id Shocks.	BRA	KE CLEANER		1.00
- Perform Coolant Flush A	nd Refill Cooling Syster	n.	BAT	TERY		1.00
- Rotate And Balance All F	our Tires.		PEA	K GLOBAL		1.00
- Shop Supplies			SUP	PPORT		2.00
				P SUPPLIES		1.00
				AGOLD OIL FILTER		1.00
				0 ENGINE OIL		7.00
				OY MOUNT KIT		2.00
	Parts Charge:	360.62	Labor Charge:	585.00		
Workorder: 1608461	Probler	n: P.M. ser	vice and A/C not cold ar	nd check lights.		
		m: P.M. ser	vice and A/C not cold ar	nd check lights.	Parts	
Workorder: 1608461 Meter Reading: 93528 In Date: 08/16/2016		m: P.M. ser		nd check lights. Description	Parts	Quantity
Meter Reading: 93528	Close Date:		Labor Hours	Description	Parts	Quantity
Meter Reading: 93528		n: P.M. serv	Labor	-	Parts	Quantity
Meter Reading: 93528 In Date: 08/16/2016	Close Date:	0.00	Labor Hours	Description	Parts	Quantity
Meter Reading: 93528 In Date: 08/16/2016	Close Date: Parts Charge:	0.00	Labor Hours Labor Charge:	Description	Parts Parts	Quantity
Meter Reading: 93528 In Date: 08/16/2016 - Workorder: 1611100	Close Date: Parts Charge:	0.00 n: Transitio	Labor Hours Labor Charge:	Description		Quantity Quantity
Meter Reading: 93528 In Date: 08/16/2016 - Workorder: 1611100 Meter Reading: 93528	Close Date: Parts Charge: Probler	0.00 n: Transitio	Labor Hours Labor Charge: n Prep Charge Labor	Description 0.00		_

Total Labor Charges:

6,309.00

Total Comm. Charges:

90.00