

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 643014		Problem: PRE-DELIVERY INSPECTION		
Meter Reading: 0		Labor	Parts	
In Date: 07/26/2006	Close Date: 07/26/2006	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
	Parts Charge: 0.00	Labor Charge:	100.00	

Workorder: 644501		Problem: REMOVE LIGHT BAR FROM 10124782 INSTALL TO 10164695		
Meter Reading: 294		Labor	Parts	
In Date: 08/23/2006	Close Date: 08/29/2006	Hours	Description	Quantity
- Fabricate & Install 4 Corner Strobe Lights.Remove & Reinstaltop Strobe Light Assy.		15.00	SHOP SUPPLIES	1.00
			66BR CLEAR SILICONE	1.00
- Fabricate & Install 2 Tool Boxes On Bed.			SH3920C CLEAR OVAL STROBE ASSY	2.00
- Shop Supplies			S660CCCC STROBE KIT 4 HEAD KIT	1.00
			30055-30 30AMP CIRCUIT BREAKER	2.00
	Parts Charge: 422.96	Labor Charge:	250.00	

Workorder: 644706		Problem: MODIFY BASKET		
Meter Reading: 254		Labor	Parts	
In Date: 08/28/2006	Close Date: 09/26/2006	Hours	Description	Quantity
- Modify Alum Basket		6.00	3/16X1-1/2X20 ALUM ANGLE ARCHITECTUAL	6.00
- Shop Supplies			SHOP SUPPLIES	1.00
			3/4#.125 4X8 ALM FLT METL ALUM FLATEN EXPAND METAL	3.00
	Parts Charge: 20.17	Labor Charge:	300.00	

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 644713

Problem: NEEDS LIGHT BAR ASSY

Meter Reading: 294 In Date: 08/28/2006	Close Date: 01/19/2007	Labor Hours	Description	Parts	Quantity
- Custom Install Light Bar And Switch		16.75	4L547 1/4 " BIT		1.00
- Replace Broken Tag Light Assembly.			L14108LE54AA LIGHT BAR ASSEMBLY		1.00
- Pm Service			15/40 OIL		15.00
- Nitrogen Fill Tires.			26330 TAG LIGHT (TKR LITE)		1.00
- Shop Supplies			4L547 1/4 " BIT		2.00
			30055-50 CKT BREAKER 50 AMP		1.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			PCCS9R SWITCH CONTROL		1.00
			SHOP SUPPLIES		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
Parts Charge: 2,807.11		Labor Charge: 55.00			

Workorder: 732392

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0 In Date: 12/14/2006	Close Date: 01/04/2007	Labor Hours	Description	Parts	Quantity
- Tiresoles Of Broward Inc					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 157.80	

Workorder: 732393

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0 In Date: 12/15/2006	Close Date: 01/04/2007	Labor Hours	Description	Parts	Quantity
- Tiresoles Of Broward Inc					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 54.00	

Workorder: 732904

Problem: MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0 In Date: 01/17/2007	Close Date: 01/17/2007	Labor Hours	Description	Parts	Quantity
- Minor Weld Repair Or Machining.		4.00			
Parts Charge: 0.00		Labor Charge: 165.00			

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 740847

Problem: P.M SERVICE

Meter Reading: 6716	Labor	Parts	
In Date: 07/02/2007	Hours	Description	Quantity
- Pm Service	5.80	15/40 OIL	15.00
- R&R Rightrear Marker Light Assy		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Rotate And High Speed Balance Six Tires.		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
- Shop Supplies		10003 INJECTOR CLEANER DON'T REORDER	1.00
		15200R RED MARKER LIGHT RECTANGULAR	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	96.79	Labor Charge:	82.50

Workorder: 740942

Problem: FLAT IN LOT

Meter Reading: 14060	Labor	Parts	
In Date: 07/03/2007	Hours	Description	Quantity
-			
Parts Charge:	0.00	Labor Charge:	0.00

Workorder: 744864

Problem: CHECK TIRES

Meter Reading: 9018	Labor	Parts	
In Date: 10/01/2007	Hours	Description	Quantity
- Repair 2 Nail Holes In Left Rear Outer Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 832340

Problem: P.M. SERVICE.A/C ONLY BLOWS ON HIGH.

Meter Reading: 11473		Labor		Parts	
In Date: 01/07/2008	Close Date: 01/11/2008	Hours	Description		Quantity
- Pm Service		6.00	CA9516 AIR FILTER LBF LAF1646 WIX 42731		1.00
- A/C Blower Only Works On High Speed.Test			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Circuit,Replace Blower Resistor.Open Circuit.(In House			SHOP SUPPLIES		1.00
Warranty)			31-20 WIPER BLADES 20" BLADE		2.00
- Rotate And Highspeed Balance 6 Tires.Nitrogen Fill.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Shop Supplies			10003 INJECTOR CLEANER DON'T REORDER		1.00
			WD40 SPRAY LUBE STOCK# 405540002		1.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			4C2Z19A706AA A/C BLOWER RESISTOR		1.00
			15/40 OIL		15.00
Parts Charge:		170.19	Labor Charge:	90.00	

Workorder: 841670

Problem: P.M SERVICE

Meter Reading: 16133		Labor		Parts	
In Date: 07/18/2008	Close Date: 07/23/2008	Hours	Description		Quantity
- Pm Service		11.00	15/40 OIL		15.00
- Check Batteries And Charging Sys.R&R Defective			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
Batteries.			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
- Test And Repair Ground To Tag Light.R&R Center Marker			31-20 WIPER BLADES 20" BLADE		2.00
Light Bar.			GROUP 65 BATTERY (MTC BXT-65-850)		2.00
- Replace 2 Tires Mount On Front High Speed Balance All 6			TIRE DISPOSAL FEE		2.00
Tires.Nitro Fill Tires.			SYN/ATF TRANS FLUID SYNTHETIC		16.00
- Service Trans.Flush And Refill Trans.			748636189 245/75R17 WRG SLT ARMOUR E		2.00
- Shop Supplies			09997 BRAKE CLEAN		1.00
			15050R ID BAR RED MODEL 15 LED		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		860.55	Labor Charge:	90.00	

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 845361

Problem: CHECK REAR STROBES

Meter Reading: 18216	Labor	Parts	
In Date: 10/07/2008	Hours	Description	Quantity
- Fabricate & Install 2 Rear Lamps With Strobe Bulbs.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		S30HACP STROBE BULB FOR KIT S660CCCC	2.00
		60804C BACKUP LIGHT OVAL	2.00
Parts Charge:	104.83	Labor Charge:	60.00

Workorder: 847502

Problem: GUARANTEED BUMPER & SUPPLIERS

Meter Reading: 0	Labor	Parts	
In Date: 11/18/2008	Hours	Description	Quantity
- Guaranteed Bumper & Suppliers			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	564.00

Workorder: 848290

Problem: R/R OUTER TIRE FLAT

Meter Reading: 19322	Labor	Parts	
In Date: 12/17/2008	Hours	Description	Quantity
- Replace 4 Rear Tires.Hi Speed Balance And Nitrofill Tires	2.00	748636189 245/75R17 WRG SLT ARMOUR E	4.00
- Shop Supplies		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
Parts Charge:	808.00	Labor Charge:	120.00

Workorder: 933646

Problem: L/F TIRE FLAT

Meter Reading: 20369	Labor	Parts	
In Date: 02/06/2009	Hours	Description	Quantity
- Repair L/F Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 933707

Problem: P.M SERVICE,CHECK EMERGENCY LIGHTS

Meter Reading: 20415		Labor		Parts	
In Date: 02/06/2009	Close Date: 02/10/2009	Hours	Description	Quantity	
- Pm Service		5.00	S30HACP STROBE BULB FOR KIT S660CCCC		2.00
- Comp:Wig Wag Lights Inop.Diag And Replace 2 Rear			SHOP SUPPLIES		1.00
Strobe Bulbs And Wire In.			15/40 OIL		15.00
- Shop Supplies			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
Parts Charge: 192.79		Labor Charge: 300.00			

Workorder: 937009

Problem: CHECK AND REPAIR REAR STROBE LIGHTS SYSTEM.

Meter Reading: 22432		Labor		Parts	
In Date: 04/24/2009	Close Date: 04/29/2009	Hours	Description	Quantity	
- Ck Strobe Lamp Sys. 2 Rear & R/F Not Working.Diag		2.00	SHOP SUPPLIES		1.00
Circuits. Replace Strobe Bulbs. Fabricate Wiring As			S30HACP STROBE BULB FOR KIT S660CCCC		3.00
Needed.					
- Shop Supplies					
Parts Charge: 123.28		Labor Charge: 120.00			

Workorder: 940924

Problem: Light bar not working, R/R strobe not working.,

Meter Reading: 24695		Labor		Parts	
In Date: 07/17/2009	Close Date: 07/28/2009	Hours	Description	Quantity	
- Trace & Repair Open Power Circuit To Light Bar. Test		1.50	S30HAC STROBE BULB (USE S30HACP)		1.00
Strobe System & Replace R/R Strobe Bulb.			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 44.07		Labor Charge: 90.00			

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 942149

Problem: pm service

Meter Reading: 25313		Labor	Parts	
In Date: 08/17/2009	Close Date: 08/20/2009	Hours	Description	Quantity
- P.M.		8.00	L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00
- Repair Ground R/F Marker Light			CA9516 AIR FILTER LBF LAF1646 WIX 42731	1.00
- Check Engine Codes,			7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Road Test			85/140 GEAR OIL GEAR LUBE	2.00
- Replace In Side R/R Tire. Repaired Old Tire For Spare			TIRE DISPOSAL FEE	1.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE	2.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
			179636492 LT245/75R17 WRANGLER SR-A E	1.00
			SHOP SUPPLIES	1.00
			15/40 OIL	15.00
Parts Charge: 346.24		Labor Charge: 480.00		

Workorder: 943201

Problem: Wig wags

Meter Reading: 26107		Labor	Parts	
In Date: 09/14/2009	Close Date: 09/15/2009	Hours	Description	Quantity
- Repair Wiring Replace Bulb And Controler		3.50	SHOP SUPPLIES	1.00
- Clear Area Behind Seat To Access Strobe Control Box			SH3920C CLEAR OVAL STROBE ASSY	1.00
- Shop Supplies			CSP660 POWER SUPPLY (WHELEN)	1.00
Parts Charge: 232.28		Labor Charge: 210.00		

Workorder: 946702

Problem: Check strobe lights.

Meter Reading: 27851		Labor	Parts	
In Date: 12/04/2009	Close Date: 12/07/2009	Hours	Description	Quantity
- Test & Replace R/F & L/R Strobe Bulbs.		1.00	SHOP SUPPLIES	1.00
- Shop Supplies			S30HACP STROBE BULB FOR KIT S660CCCC	2.00
Parts Charge: 82.85		Labor Charge: 120.00		

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1000364

Problem: Had to jump start.

Meter Reading: 28732 In Date: 01/11/2010	Close Date: 01/12/2010	Labor Hours	Description	Parts	Quantity
- Test Starting & Charging System, Charge & Test Both Batteries, Replace Both Batteries.		1.50	SHOP SUPPLIES		1.00
- Shop Supplies			GROUP 65 BATTERY (MTC BXT-65-850)		2.00
Parts Charge:		259.49	Labor Charge:		90.00

Workorder: 1000872

Problem: Check strobes

Meter Reading: 28949 In Date: 01/22/2010	Close Date: 01/26/2010	Labor Hours	Description	Parts	Quantity
- Test Strobe Light Operation, Test & Replace L/R Strobe Lamp.		0.50	SH3920C CLEAR OVAL STROBE ASSY		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		61.93	Labor Charge:		30.00

Workorder: 1001784

Problem: R/F tire damaged

Meter Reading: 29463 In Date: 02/19/2010	Close Date: 02/19/2010	Labor Hours	Description	Parts	Quantity
- Both Front Tires Have Side Wall Damage. Mount, Balance & Nitro Fill Two New Front Tires.		1.50	TIRE DISPOSAL FEE		2.00
- Shop Supplies			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		374.71	Labor Charge:		90.00

Workorder: 1002598

Problem: pm service, also see notes on transmission,light bar and front end noise.

Meter Reading: 29887 In Date: 03/12/2010	Close Date: 03/17/2010	Labor Hours	Description	Parts	Quantity
- P.M Service.		6.00	CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
- Test & Repair Electrical Circuit To Front Center Led Lamps In Light Bar. Test & Replace Rear Center Clearance Lamp Assembly.			31-20 WIPER BLADES 20" BLADE		2.00
- Shop Supplies			15050R ID BAR RED MODEL 15 LED		1.00
			15/40 OIL		15.00
			SHOP SUPPLIES		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
Parts Charge:		121.96	Labor Charge:		360.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1005285 **Problem:** Check strobes, vibration & alignment.

Meter Reading: 31295	Labor	Parts	
In Date: 05/24/2010	Hours	Description	Quantity
- Inspect & Test Strobe System, Replace R/F Strobe Bulb, Replace L/R Strobe Bulb & Repair Wire Connector.	5.30	S30HACP STROBE BULB FOR KIT S660CCCC SHOP SUPPLIES	2.00 1.00
- Rotate & Balance All Six Tires.			
- Alignment.			
- Shop Supplies			
Parts Charge:	78.30	Labor Charge:	318.00

Workorder: 1008006 **Problem:** damage to lft frt fender & bumper

Meter Reading: 32183	Labor	Parts	
In Date: 07/13/2010	Hours	Description	Quantity
- Damage To Lft Frt Fender & Bumper			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	504.00

Workorder: 1008803 **Problem:** Repair the keg holder

Meter Reading: 32183	Labor	Parts	
In Date: 08/16/2010	Hours	Description	Quantity
- Weld / Fab Keg Holder	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1009051 **Problem:** Check engine light on also strobe light inop.

Meter Reading: 32424	Labor	Parts	
In Date: 08/20/2010	Hours	Description	Quantity
- Test And Replace Failed Strobe Light Controller With New.Also Fabricate And Repair Wiring Harness,	5.00	CSP660 POWER SUPPLY (WHELEN) EGR VALVE	1.00 1.00
- Computer Diagnose For Check Engine Light On.Test And Replace Failed Egr Valve With New.Clean Egr Port And Intake For Excessive Coking And Roadtest.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	407.26	Labor Charge:	300.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1010150

Problem: Right side turn signal inop.

Meter Reading: 32871		Labor		Parts	
In Date: 09/16/2010	Close Date: 09/20/2010	Hours	Description		Quantity
-	Remove Head Lamps And Replace Both Failed Fronts	0.75	SHOP SUPPLIES		1.00
	Turn Signal Lamp Bulbs With New.		4114K BULB (ACD)		2.00
-	Shop Supplies				
Parts Charge: 7.88		Labor Charge: 45.00			

Workorder: 1010866

Problem: Pm service also see notes on transmission concern.

Meter Reading: 33305		Labor		Parts	
In Date: 10/01/2010	Close Date: 10/06/2010	Hours	Description		Quantity
-	P.M. Service.	6.25	15/40 OIL		15.00
-	Replace Missing Pintle Pin On Hitch.		CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
-	Replace Rear Strobe Lamp Bulb.		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE		2.00
-	Shop Supplies		18410 PINTLE PIN		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
			S30HACP STROBE BULB FOR KIT S660CCCC		2.00
Parts Charge: 188.90		Labor Charge: 375.00			

Workorder: 1102486

Problem: Right front tire flat

Meter Reading: 36019		Labor		Parts	
In Date: 03/04/2011	Close Date: 03/10/2011	Hours	Description		Quantity
-	Repair Flat Right Front Tire.Nitrogen Fill And Balance Same.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1103567

Problem: P.M. Service.Check engine light.A/C not cold.

Meter Reading: 36570 In Date: 04/01/2011	Close Date: 04/14/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		13.00	15/40 OIL		15.00
- Fabricate And Replace Missing Hitch Pindel Pin With New.			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Computer Diagnose For Check Engine Light On.Remove Egr.Valve And Perform Egr Flush,Diesel Induction Service And Diesel Injectors Flush Services.Clear Codes And Road Test.			1066 WHITE LITHIUM (CRC 05037)		1.00
			18410 PINTLE PIN		1.00
			DPKQ7 EGR SERVICE KIT (BG PRODUCTS)		1.00
			SHOP SUPPLIES		1.00
- Install Three New Tires .Nitrogen Fill And Balance All Six.			KQ22932DF DIESEL INJECTION KIT (BG PRODUCTS)		1.00
- Remove And Install Bench Seat After Repairs.Transport Bench Seat To And From Central Auto Trim Shop For Repairing Damage Cushion And Leather.			179636492 LT245/75R17 WRANGLER SR-A E		3.00
			TIRE DISPOSAL FEE		3.00
			D3TZ2457B BRAKE PEDAL PAD		1.00
- Shop Supplies					
Parts Charge:		629.36	Labor Charge:		780.00
			Commercial Charge:		363.94

Workorder: 1106516

Problem: had to jump start this morning.

Meter Reading: 38141 In Date: 06/21/2011	Close Date: 06/22/2011	Labor Hours	Description	Parts	Quantity
- Test Batteries And Charging System.Replace One Defective Battery.		1.50	GROUP 65 BATTERY (MTC BXT-65-850)		1.00
			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		130.74	Labor Charge:		90.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1108552

Problem: A/C blows out defroster and check engine light and strobe lights inop.

Meter Reading: 39109 In Date: 08/12/2011	Close Date: 08/22/2011	Labor Hours	Description	Parts	Quantity
- Ac Performance And Leak Test.Repair Failed Vacume Line To Climate Control Head.Remove Blower Motor And Clean Clogged Evaporator Core Fins.Vacume And Recharge System To Specs.		6.50	R134A REFRIGERANT		1.00
			06133 3M ELECTRIC TAPE STOCK #832260101		1.00
			3C3Z9A343A SEAL KIT FUEL FILTER (FORD)		1.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
- Computer Diagnose For Check Engine Light On And No Power.Test And Replace Both Failed Fuel Filters With New And Clean Fuel Condition Module.Clear Codes With Scan Tool And Road Test.			SHOP SUPPLIES		1.00
- Diagnose Strobe Lights Inop.Pin Point Test,Repair,Insulate And Secure Damage Wiring Harness To Controller Due To Equipments Stored At Back Of Rear Seat.Had To Remove Rear Seat.					
- Shop Supplies					
	Parts Charge:	58.10	Labor Charge:	390.00	

Workorder: 1110477

Problem: Pm service

Meter Reading: 39866 In Date: 09/30/2011	Close Date: 10/06/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		6.25	19006Y MARKER LIGHT 4" RECT YELLOW LED		2.00
- Test And Replace Both Failed Left And Right Led Marker Lamp Assemblies With New.			SHOP SUPPLIES		1.00
			15/40 OIL		15.00
- Rotate And Balance All Six Tires.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Shop Supplies			CA9516 AIR FILTER LBF LAF1646 WIX 42731		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
	Parts Charge:	168.72	Labor Charge:	375.00	

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1211848

Problem: Pm service

Meter Reading: 42654		Labor	Parts	
In Date: 12/07/2012	Close Date: 12/19/2012	Hours	Description	Quantity
-	Perform Pm Service.Replace Cracked Air Filter With New.	14.50	CS9667A FUEL FILTER	1.00
-	Test And Replace Failed Right Front Strobe Lamp Bulb With New.		LOWER BALL JOINT	2.00
-	Inspect And Replace All Four Failed Left And Right Upper And Lower Ball Joints With New.		PM-22-A ADDITIVE DIES	1.00
-	Perform Wheel Alignment Complete.		NAPAGOLD OIL FILTER	1.00
-	Rotate And Balance All Six Tires.		SHOP SUPPLIES	1.00
-	Shop Supplies		31-20 WIPER BLADES 20	2.00
			05046 BATTERY PROTECT	1.00
			USED FIREX REFURBED F	1.00
			S30HACP STROBE BULB F	1.00
			15-40 OIL	15.00
			UPPER BALL JOINT	2.00
			AIR FILTER 6.0	1.00
Parts Charge: 451.45		Labor Charge: 870.00		

Workorder: 1301638

Problem: Missing fuel cap.Check engine light on.No power.

Meter Reading: 43438		Labor	Parts	
In Date: 02/15/2013	Close Date: 02/27/2013	Hours	Description	Quantity
-	Computer Diagnose For Check Engine Light On And No Power.Test And Replace Failed Egr Valve With New.	5.00	5C3Z9N622A INDICATOR	1.00
-	Clean Intake Ports.Replace Fuel Filters,Install Fuel Cap.Clear Codes With Scan Tool And Roadtest		FUEL CAP	1.00
-	Shop Supplies		EGR VALVE	1.00
			NAPAGOLD FUEL FILTER	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 325.59		Labor Charge: 300.00		

Workorder: 1302557

Problem: Right side turn signal inop and check gauges.

Meter Reading: 43741		Labor	Parts	
In Date: 03/14/2013	Close Date: 03/21/2013	Hours	Description	Quantity
-	Replacerright Front Signal Light Bulb And Socket.Replace Left Rear Strobe Bulb And Dome Light Bulb.	2.25	BULB	1.00
-	Check Gauges,Unable To Duplicate Problem.		SOCKET	1.00
-	Shop Supplies		S30HACP STROBE BULB F	1.00
			4114K BULB ACD	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 78.72		Labor Charge: 135.00		

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1310307

Problem: P.M. service and had to jump start in A/M.

Meter Reading: 45126		Labor		Parts	
In Date: 10/11/2013	Close Date: 10/22/2013	Hours	Description		Quantity
-	P.M. Service.	9.00	SHOP SUPPLIES		1.00
-	Test Batteries And Charging System.Replace Both Bad Batteries.		15-40 OIL		15.00
-	Replace Two Tires,Rotate And Balance All Six.		TIRE DISPOSAL FEE		2.00
-	Replace Left Rear Marker Lamp.		31-20 WIPER BLADES 20		2.00
-	Shop Supplies		BATTERY		2.00
			TR416 VALVE STEM		2.00
			NAPAGOLD OIL FILTER		1.00
			M C BASE MOUNT KIT		1.00
			179636492 LT245-75R17		2.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 848.30		Labor Charge: 540.00			

Workorder: 1404283

Problem: Pm service.

Meter Reading: 45845		Labor		Parts	
In Date: 05/02/2014	Close Date: 05/08/2014	Hours	Description		Quantity
-	Perform Pm Service.	5.50	SHOP SUPPLIES		1.00
-	Rotate And Balance All Six Tires.		15-40 OIL		15.00
-	Shop Supplies		WIPER BLADE		2.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
Parts Charge: 103.88		Labor Charge: 330.00			

Workorder: 1406072

Problem: Check all gauges on dash intermittent.

Meter Reading: 46328		Labor		Parts	
In Date: 06/19/2014	Close Date: 06/30/2014	Hours	Description		Quantity
-	Computer Diagnose For Cluster Gauges Intermittent.Test And Replace Failed Engine Oil Pressore Switch With New And Test Drive.	2.50	OIL PRESSURE SWITCH		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge: 35.10		Labor Charge: 150.00			

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1408737 **Problem:** tires

Meter Reading: 46695 **Labor**

In Date: 08/29/2014 **Hours** **Description** **Parts** **Quantity**

- Tire Service Summit And Kirk - Tires

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 215.66

Workorder: 1408738 **Problem:** service

Meter Reading: 46695 **Labor**

In Date: 08/29/2014 **Hours** **Description** **Parts** **Quantity**

- Tire Service Summit And Kirk - Service

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 46.40

Workorder: 1502046 **Problem:** Pm service.

Meter Reading: 47978 **Labor**

In Date: 02/26/2015 **Hours** **Description** **Parts** **Quantity**

- Pm Service. **13.00** NAPAGOLD OIL FILTER 1.00

- Pressure Test And Inspect Cooling System.Flush And WIPER BLADE 2.00

Renew Engine Coolant. NAPAGOLD FUEL FILTER 1.00

- Replace Front Brake Pads And Resurface Both Front PEAK GLOBAL 3.00

Brake Rotors.Bleed Brake System. USED FIRE X REFURBISHED 1.00

- Replace Two Tires.Rotate And Balance All Six. PADS 1.00

- Shop Supplies SHOP SUPPLIES 1.00

Parts Charge: 555.76 **Labor Charge:** 780.00 LT245/75R17 TIRES 2.00

15-40 OIL 15.00

Workorder: 1507009 **Problem:** L/R outter tire flat.

Meter Reading: 48899 **Labor**

In Date: 07/15/2015 **Hours** **Description** **Parts** **Quantity**

- Repair And Balance Left Rear Tire. **1.00** SHOP SUPPLIES 1.00

- Shop Supplies

Parts Charge: 2.00 **Labor Charge:** 60.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1510724

Problem: Pm service.

Meter Reading: 49153		Labor		Parts	
In Date: 10/23/2015	Close Date: 10/28/2015	Hours	Description	Quantity	
- Pm Service.		14.00	15-40 OIL	15.00	
- Service Transmission.Replace Filter.Flush And Refill System.			NAPAGOLD OIL FILTER	1.00	
			SHOP SUPPLIES	1.00	
- Resurface Rear Brake Rotors.Replace Both Rear Brake Calipers And Brake Pads.Flush And Bleed Brake System			NAPAGOLD FUEL FILTER	1.00	
			SYN-ATF TRANS FLUID S	24.00	
- Replace Both Defective Seal Beam Headlamps.			B FLUID DOT 3-32OZ	2.00	
- Rotate And Balance All Six Tires.			BRAKE CLEANER	2.00	
- Shop Supplies			REMAN BRAKE CALIPER	1.00	
			BRAKE PAD	1.00	
			BULB	2.00	
			PLATINUM FILTER KIT	1.00	
			HALOGEN LAMP	2.00	
			REMAN BRAKE CALIPER	1.00	
			WIPER BLADE	2.00	
Parts Charge: 538.28		Labor Charge:	840.00		

Workorder: 1511400

Problem: Turn signal lights inop.

Meter Reading: 49201		Labor		Parts	
In Date: 11/06/2015	Close Date: 11/09/2015	Hours	Description	Quantity	
- Test And Replace Defective Right Front Turnsignal Lamp Bulb.		0.50	SIGNAL STOP LAMP	1.00	
Parts Charge: 1.75		Labor Charge:	30.00		

Workorder: 1512553

Problem: Overheating.Body damage passenger side.

Meter Reading: 49637		Labor		Parts	
In Date: 12/11/2015	Close Date: 12/16/2015	Hours	Description	Quantity	
- Pressure Test And Inspect Cooling System.Replace Cracked Coolant Degas Reservoir And Defective Return Hose.Flush And Refill Coolant.		3.00	PEAK GLOBAL	3.00	
			COOLANT CAP	1.00	
			SHOP SUPPLIES	1.00	
- Shop Supplies			EXPANSION TANK	1.00	
			COOLANT TANK HOSE	1.00	
Parts Charge: 260.10		Labor Charge:	180.00		

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1603741

Problem: P.M. service and burning smell from front brakes.

Meter Reading: 49920			Labor	Parts	
In Date: 04/08/2016	Close Date: 04/19/2016		Hours	Description	Quantity
- P.M. Service.			11.50	SHOP SUPPLIES	1.00
- Resurface Front Brake Rotors,Replace Calipers And Pads.Flush And Bleed System.				NAPAGOLD AIR FILTER	1.00
- Replace Both Rear Bounce Stops.				B FLUID DOT 3-32OZ	1.00
- Replace Defective Power Outlet.				REMAN BRAKE CALIPER	1.00
- Rotate And Balance All Six Tires.				NAPAGOLD OIL FILTER	1.00
- Shop Supplies				NAPAGOLD FUEL FILTER	1.00
				RING	1.00
				3C3Z9A343A SEAL KIT	1.00
				SOKET PAWER OUTLET	1.00
				15-40 OIL	15.00
				USED FIRE X REFURBISHED	1.00
				REMAN BRAKE CALIPER	1.00
				RING	1.00
				20" WIPER BLADE	2.00
				SOCKET ASS	1.00
				REAL SUSPENSION BUMPSTOPS	2.00
	Parts Charge:	432.74	Labor Charge:	690.00	

Workorder: 1607629

Problem: Check engine light on and no power.

Meter Reading: 50401			Labor	Parts	
In Date: 07/26/2016	Close Date: 07/29/2016		Hours	Description	Quantity
- Diagnose Check Engine Light.P0404,P1335.Replace Egr Valve.Clear Codes.			7.00	NAPAGOLD OIL FILTER	1.00
- Service And Clean Induction System And Flush Injectors.				DIESEL EGR INDUCTION SERVICE KIT	1.00
- Shop Supplies				EGR VALVE	1.00
				SHOP SUPPLIES	1.00
				KQ22932DF DIESEL INJE	1.00
				15-40 OIL	15.00
	Parts Charge:	650.27	Labor Charge:	420.00	

2/1/2017
4:39:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164695 2006 FORD F350 Utility Truck, W/Crew Cab, Vise

Workorder: 1608298

Problem: Check for oil leak.

Meter Reading: 50401	Labor	Parts		
In Date: 08/11/2016	Hours		Description	Quantity
-				
Parts Charge:	0.00	Labor Charge:	0.00	

Workorder: 1611388

Problem: Transition Prep Charge

Meter Reading: 50401	Labor	Parts		
In Date: 11/03/2016	Hours		Description	Quantity
-			Transition Prep Charge	
	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	13,330.22	Total Labor Charges:	11,590.50	Total Comm. Charges:	2,960.26
-----------------------------	------------------	-----------------------------	------------------	-----------------------------	-----------------