

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 642873

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 07/24/2006	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 100.00		

Workorder: 736122

Problem: P.M SERVICE

Meter Reading: 5715	Labor	Parts	
In Date: 03/23/2007	Hours	Description	Quantity
- Perform Pm Service	5.50	15/40 OIL	15.00
- Nitrogen Fill All Tires.		SHOP SUPPLIES	1.00
- Tag Lamp Not Working.Test Circuit. Repair Bad Ground At Lampassy.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Shop Supplies			
Parts Charge: 47.86	Labor Charge: 27.50		

Workorder: 748212

Problem: P.M SERVICE

Meter Reading: 11933	Labor	Parts	
In Date: 12/06/2007	Hours	Description	Quantity
- Pm Service	4.50	10003 INJECTOR CLEANER DON'T REORDER	1.00
- Repair Open In Rr Marker Light And Replace Tag Light Bulb		15/40 OIL	15.00
- Shop Supplies		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
		SHOP SUPPLIES	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
Parts Charge: 100.65	Labor Charge: 30.00		

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 840338

Problem: P.M SERVICE,CHECK ENGINE LIGHT ON

Meter Reading: 16922	Labor	Parts	
In Date: 06/20/2008	Hours	Description	Quantity
- R&R Right Rear Burned Out Brake Bulb.	7.50	CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
- Pm Service		3157 TAIL LIGHT BULBS	1.00
- Diag Engine Light W/Ids Scan Tool.Code# P0404 & P1335 For Egr Sys.Send To Dealer For Repair.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- To/Fr Dealer For Warranty Egr Valve.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		CA9516 AIR FILTER LBF LAF1646 WIX 42731	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		15/40 OIL	15.00
Parts Charge:	148.86	Labor Charge:	60.00

Workorder: 933299

Problem: P.M SERVICE

Meter Reading: 22350	Labor	Parts	
In Date: 01/29/2009	Hours	Description	Quantity
- Pm Service	7.50	15/40 OIL	15.00
- Transmission Service.Flush And Refill Sys.		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
- Test Charging Sys. Replace Both Batteries.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Replace Missing Trailer Hitch Pintle Pin.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC	16.00
		GROUP 65 BATTERY (MTC BXT-65-850)	2.00
		SHOP SUPPLIES	1.00
		18410 PINTLE PIN	1.00
Parts Charge:	440.52	Labor Charge:	450.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 942129

Problem: P.M service.

Meter Reading: 27196	Labor	Parts	
In Date: 08/14/2009	Hours	Description	Quantity
- P.M Service.	5.50	CA9516 AIR FILTER LBF LAF1646 WIX 42731	1.00
- Rotate & Balance All Six Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		WD40 SPRAY LUBE STOCK# 405540002	1.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		SHOP SUPPLIES	1.00
		15/40 OIL	15.00
		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
Parts Charge:	144.17	Labor Charge:	330.00

Workorder: 1002016

Problem: P.M. Service.

Meter Reading: 31873	Labor	Parts	
In Date: 02/25/2010	Hours	Description	Quantity
- P.M Service.	6.00	15/40 OIL	15.00
- Pressure Test & Inspect Cooling System, Flush & Renew Coolant.		3C3Z9A343A SEAL KIT FUEL FILTER (FORD)	1.00
- Shop Supplies		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		05046 BATTERY PROTECTOR (CRC)	1.00
		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	3.00
Parts Charge:	164.61	Labor Charge:	360.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1009312

Problem: P.M. service.

Meter Reading: 36608	Labor	Parts	
In Date: 08/26/2010	Hours	Description	Quantity
- P.M. Service.	9.50	179636492 LT245/75R17 WRANGLER SR-A E	6.00
- Replace And Balance Six Tires.		15/40 OIL	15.00
- Complete Front End Alignment.		TIRE DISPOSAL FEE	6.00
- Shop Supplies		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
		SHOP SUPPLIES	1.00
		TR416 VALVE STEM	6.00
Parts Charge:	1,208.71	Labor Charge:	570.00

Workorder: 1101750

Problem: PM service also see notes on has to jump start in am.

Meter Reading: 40570	Labor	Parts	
In Date: 02/15/2011	Hours	Description	Quantity
- Perform Pm Service.	7.50	CS9667A FUEL FILTER LBF L4604F WIX 33899	1.00
- Test Starting And Charging System.Both Batteries Failed		CA9516 AIR FILTER LBF LAF1646 WIX 42731	1.00
Load Test After Recharge.Replace Both Failed Batteries		15/40 OIL	15.00
With New.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Rotate And Balance All Six Tires.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Shop Supplies		7090BLK FRT FLOOR MATS (RUBBER QUEEN)	1.00
		SHOP SUPPLIES	1.00
		GROUP 65 BATTERY (MTC BXT-65-850)	2.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge:	441.98	Labor Charge:	450.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1109845 **Problem:** Pm service and check radio concern.

Meter Reading: 45972		Labor		Parts	
In Date: 09/14/2011	Close Date: 09/28/2011	Hours	Description	Quantity	
-	Perform Pm Service.	7.75	15/40 OIL		15.00
-	Test And Replace Failed Left Side And Right Side Led Marker Lamp Assemblies With New.		CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
-	Test And Replace Failed Am/Fm Radio With New.		RADIO		1.00
-	Rotate And Balance All Six Tires.		19006R MARKER LIGHT 4" RECTANGULAR RED LED		1.00
-	Shop Supplies		19006Y MARKER LIGHT 4" RECT YELLOW LED		1.00
			SHOP SUPPLIES		1.00
			D3TZ2457B BRAKE PEDAL PAD		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
Parts Charge:		389.21	Labor Charge:	465.00	

Workorder: 1201489 **Problem:** brakes are locked up

Meter Reading: 48803		Labor		Parts	
In Date: 02/14/2012	Close Date: 02/14/2012	Hours	Description	Quantity	
-	Tow From: 825 Ave P. Riviera Bch N. Co Complex To: Lv Shop				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 134.77

Workorder: 1201490 **Problem:** Towed in brake binding.

Meter Reading: 49140		Labor		Parts	
In Date: 02/14/2012	Close Date: 02/29/2012	Hours	Description	Quantity	
-	Check Brakes For Overheating Complaint.Replace Both Front Calipers And Right Front Brake Hose.Resurface Both Front Rotors.Service And Lube Caliper Slides.Flush And Bleed System And Test Drive.	5.00	EOAZ2149B COPPER WASHER (FORD)		4.00
-	Shop Supplies		2232 BRAKE FLUID QUART		1.00
			CALIPER ASSY		1.00
			BRAKE CALIPER		1.00
			09997 BRAKE CLEAN		1.00
			RIGHT BRAKE LINE HOSE		1.00
			SHOP SUPPLIES		1.00
			PADS		1.00
Parts Charge:		498.75	Labor Charge:	300.00	

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1204683

Problem: Pm service.

Meter Reading: 51220 In Date: 05/17/2012	Close Date: 05/29/2012	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		9.50	7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Diagnose Clearance Lamps Around Utility Box			15/40 OIL		15.00
Inop.Fabricate And Repair Harness Along Frame			09997 BRAKE CLEAN		1.00
Rail.Replace Two Amber And One Red Clearance Lamps With New.			19006R MARKER LIGHT 4" RECTANGULAR RED LED		1.00
			SHOP SUPPLIES		1.00
- Diagnose Vehicle For Long Crank Before Engine Starts.Remove Leaking Fuel Filter Housing Above Engine And Reseal With New Seal Kit.			31-20 WIPER BLADES 20" BLADE		2.00
			CS9667A FUEL FILTER LBF L4604F WIX 33899		1.00
			19006Y MARKER LIGHT 4" RECT YELLOW LED		2.00
- Rotate And Balance All Six Tires.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Shop Supplies			FUEL FILTER HOUSING O-RING KIT		1.00
Parts Charge:		195.72	Labor Charge:		570.00

Workorder: 1207852

Problem: Check engine light on.

Meter Reading: 53360 In Date: 08/17/2012	Close Date: 08/24/2012	Labor Hours	Description	Parts	Quantity
- Diagnose Check Engine Light.Replace Binding Egr Valve.Clear Codes And Perform Function Test.		7.00	EGR VALVE		1.00
			15/40 OIL		15.00
- Perform Egr Port And Intercooler Passage Cleaning.Clean And Flush Intake And Test Drive.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			DPKQ7 EGR SERVICE KIT (BG PRODUCTS)		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		473.89	Labor Charge:		420.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1300482

Problem: Pm service.

Meter Reading: 57080		Labor		Parts	
In Date: 01/14/2013	Close Date: 01/24/2013	Hours	Description		Quantity
-	Perform Pm Service.	5.50	SHOP SUPPLIES		1.00
-	Rotate And Balance All Six Tires.		OIL FILTER		1.00
-	Shop Supplies		31-20 WIPER BLADES 20		2.00
			15-40 OIL		15.00
			61A P-STEERING FLUID		1.00
			PM-22-A ADDITIVE DIES		1.00
			FIRE EXTINGUISHER		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 213.98		Labor Charge: 330.00			

Workorder: 1303101

Problem: Truck pulls to the right,

Meter Reading: 58889		Labor		Parts	
In Date: 03/29/2013	Close Date: 04/15/2013	Hours	Description		Quantity
-	Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance Both.	8.25	SHOP SUPPLIES		1.00
			TIRE DISPOSAL FEE		2.00
-	Inspect Front End And Replace Failed Steering Damper And Both Right Side Upper And Lower Tie Rods With New.Repair Oil Cooler Leak And Install New Filter.		SEAL		1.00
			END ASY		1.00
			FILTER		1.00
-	Perform Wheel Alignment Complete.Fabricate And Install New Cams To Upper Ball Joints To Adjust Caster And Camber Angles.		DAMPNER		1.00
			CONNECTOR		2.00
			END SPIN		1.00
-	Shop Supplies		179636492 LT245-75R17		2.00
			SEAL		2.00
			CASTER-CAMBER BUSHING		2.00
Parts Charge: 978.21		Labor Charge: 495.00			

Workorder: 1304310

Problem: breakdown

Meter Reading: 59229		Labor		Parts	
In Date: 05/01/2013	Close Date: 05/01/2013	Hours	Description		Quantity
-	Tow From: 825 Ave P Riviera To: Lv Shop				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 134.77	

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1304315

Problem: Towed in check engine light on.

Meter Reading: 59534 In Date: 05/01/2013	Close Date: 07/19/2013	Labor Hours	Description	Parts	Quantity
-	Computer Diagnose For Abs Warning Light Flashing.Test And Replace Failed Rear Abs Wheel Speed Sensor With New.	16.50	TURBO ASSEMBLY		1.00
			15-40 OIL		15.00
			NAPAGOLD FUEL FILTER		1.00
-	Computer Diagnose For Check Engine Light On.Test And Replace Failed Turbo Assembly,Map Sensor And Airflow Meter With New.Reprogram Pcm To Latest Calibration.		NAPAGOLD AIR FILTER		1.00
			TURBO CLAMP		1.00
			BRAKE CLEANER		2.00
-	Perform Pm Service Complete.		USED FIRE X REFURBISHED		1.00
-	Pressure Test And Inspect Cooling System.Reverse Flush And Renew Engine Coolant.		NAPAGOLD OIL FILTER		1.00
			TURBO ACTUATOR		1.00
-	Test Starting And Charging System.Both Batteries Failed Loadtest After Recharge.Replace Both Failed Batteries With New.		DIPSTICK		1.00
			BATTERY		2.00
			PEAK GLOBAL		2.00
-	Rotate And Balance All Six Tires.		NAPAGOLD AIR FILTER		1.00
			SENSOR		1.00
-	Shop Supplies		SENSOR		1.00
			SENSOR		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		2,738.24	Labor Charge:		990.00

Workorder: 1310570

Problem: Check over alignment,truck pulls to left.

Meter Reading: 62270 In Date: 10/22/2013	Close Date: 11/08/2013	Labor Hours	Description	Parts	Quantity
-	Replace And Balance Four New Tires.Check Alignment.	3.00	179636492 LT245-75R17		4.00
-	Shop Supplies		TIRE DISPOSAL FEE		4.00
			SHOP SUPPLIES		1.00
Parts Charge:		982.76	Labor Charge:		180.00

Workorder: 1400551

Problem: Wiper blades failed.

Meter Reading: 64193 In Date: 01/16/2014	Close Date: 01/21/2014	Labor Hours	Description	Parts	Quantity
-	Inspect And Replace Both Failed Windshield Wiper Blades With New.	0.50	WIPER BLADE		2.00
Parts Charge:		8.49	Labor Charge:		30.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1400809

Problem: Pm service

Meter Reading: 64502	Labor	Parts	
In Date: 01/24/2014	Hours	Description	Quantity
- P.M. Service.	6.50	15-40 OIL	15.00
- Replace Right Tail Lamp.		NAPAGOLD OIL FILTER	1.00
- Lubricate And Adjust Right Side Door On Utility Bed.		LED SUP MDL 44 42 DIO	1.00
- Rotate And Balance All Six Tires.		FUEL FILTER FORD ONLY	1.00
- Shop Supplies		FUEL FILTER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	196.92	Labor Charge:	390.00

Workorder: 1408081

Problem: P.M. Service..

Meter Reading: 70010	Labor	Parts	
In Date: 08/14/2014	Hours	Description	Quantity
- Pm Service.	5.50	NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Six Tires.		15-40 OIL	15.00
- Shop Supplies		WIPER BLADE	2.00
		FUEL FILTER	1.00
		FUEL FILTER FORD ONLY	1.00
		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	165.32	Labor Charge:	330.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1501803

Problem: Pm service.Heater inop.

Meter Reading: 75855 In Date: 02/19/2015	Close Date: 03/18/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		7.75	HEAT AND AC ACTUATOR		1.00
- Computer Diagnose For Heater Inop.Pinpoint Test And Replace Defective Temperarure Control Blend Door Actuator.			LED SUP MDL 44 42 DIO		1.00
			3C3Z9A343A SEAL KIT		1.00
			FUEL LINE HOSE		2.00
- Test And Replace Defective Left Rear Turnsignal Lamp Bulb And One Clearance Lamp Bulb On Top Of Cab.			HOSE CLAMP		2.00
			SHOP SUPPLIES		1.00
- Rotate And Balance All Six Tires.			15-40 OIL		15.00
			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			WIPER BLADE		2.00
			FUEL FILTER		1.00
Parts Charge:		266.66	Labor Charge:		465.00

Workorder: 1510899

Problem: Pm service.

Meter Reading: 82628 In Date: 10/28/2015	Close Date: 11/16/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		17.00	BATTERY		2.00
- Test Starting And Charging System.Both Batteries Failed Loadtest After Recharge.Replace Both Defective Batteries.			L / REAL CALIPER		1.00
			179636492 LT245-75R17		6.00
			B FLUID DOT 3-32OZ		1.00
- Replace And Balance All Six Tires.			TIRE DISPOSAL FEE		6.00
			BRAKE CLEANER		1.00
- Resurface Both Rear Brake Rotors.Replace Rear Brake Pads And Two Rear Calipers.Flush And Bleed Brake System.			CASTER-CAMBER BUSHING		1.00
			USED FIRE X REFURBISHED		1.00
			BRAKE PAD		1.00
- Complete Front End Alignment Also Replace Right Side Camber/Caster Adjusting Bushing.			SHOP SUPPLIES		1.00
			TR416 VALVE STEM		6.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			15-40 OIL		15.00
			R / REAL CALIPER		1.00
			FUEL FILTER		1.00
			WIPER BLADE		2.00
Parts Charge:		2,243.10	Labor Charge:		1,020.00

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1602543

Problem: Check engine light on.Battery light on and off .Rust hole in bed.

Meter Reading: 85871	Labor	Parts	
In Date: 03/10/2016	Hours	Description	Quantity
- Diagnose Battery Light On.R&R Defective Alternator And Retest.Had To Fully Charge And Test Both Batteries.	7.00	GLOW PLUG ALTERNATOR	1.00 1.00
- Computer Diagnose Check Engine Light On.Code P0675.R&R Defective #5 Glow Plug.Retest And Clear Codes.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 327.53		Labor Charge: 420.00	

Workorder: 1607016

Problem: P.M. service.

Meter Reading: 89231	Labor	Parts	
In Date: 07/12/2016	Hours	Description	Quantity
- P.M. Service.	14.70	JOINT ASM	1.00
- Rotate And Balance All Six Tires.		BALL JOINT	1.00
- Diagnose Check Engine Light.P0611.Replace Ficm And Reprogram.Clear Codes And Test Drive.		LEFT AXLE SEAL KIT SEAL	1.00 1.00
- Replace Left Upper And Lower Ball Joints..		15-40 OIL	15.00
- Complete Wheel Alignment.Test Drive.		20" WIPER BLADE	2.00
- Shop Supplies		USED FIRE X REFURBISHED SHOP SUPPLIES FUEL FILTER INJECTOR MODULE WASHER FLUID CONCENTR LEFT AXLE OUT SEAL NAPAGOLD OIL FILTER	1.00 1.00 1.00 1.00 1.00 1.00 1.00
Parts Charge: 1,251.36		Labor Charge: 882.00	

1/30/2017
4:09:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164696 2006 FORD F350 Utility Body, 1 Ton, 4X4, W/Crew Cab

Workorder: 1609180

Problem: Radiator leaking

Meter Reading: 90396		Labor		Parts	
In Date: 09/01/2016	Close Date: 09/19/2016	Hours	Description	Quantity	
-	Pressure Test Cooling System.Replace Leaking Radiator,Thermostat And Pressure Cap.Flush And Refill System.	5.50	RADIATOR		1.00
			COOLANT FORD GOLD		4.00
			RAD CAP		1.00
-	Shop Supplies		THERMOSTAT ASSY		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 449.48		Labor Charge: 330.00			

Workorder: 1610836

Problem: Transition Prep Charge

Meter Reading: 90947		Labor		Parts	
In Date: 10/20/2016	Close Date: 10/20/2016	Hours	Description	Quantity	
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	14,076.98	Total Labor Charges:	9,994.50	Total Comm. Charges:	269.54
----------------------	------------------	----------------------	-----------------	----------------------	---------------