

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1006710 **Problem:** reflash canceiver

Meter Reading: 369	Labor	Parts	
In Date: 06/25/2010	Hours	Description	
- Flash Canceiver And Program	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1006711 **Problem:** Pre Delivery Inspection

Meter Reading: 0	Labor	Parts	
In Date: 06/25/2010	Hours	Description	
- Pre Delivery Inspection	4.00		
Parts Charge:	0.00	Labor Charge:	240.00

Workorder: 1012987 **Problem:** P.M. SERVICE

Meter Reading: 6449	Labor	Parts	
In Date: 11/22/2010	Hours	Description	
- P. M.	7.75	FUEL FILTER	1.00
- Repaired Ground & Reanchored Triple Light Assy In Rear.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Unsiezed & Lubed Vise.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Retightened Body Hold Downs.		15/40 OIL	15.00
- Tire Repair.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Installed Driving Decal.		1066 WHITE LITHIUM (CRC 05037)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	162.48	Labor Charge:	465.00

Workorder: 1013219 **Problem:** ANTI-FREEZE LEAK FRONT OF ENGINE BY LOWER RAD.HOSE

Meter Reading: 6451	Labor	Parts	
In Date: 11/30/2010	Hours	Description	
- Transport & Pick Up Vehicle At Dealer (Anti Freeze Leak, Front Of Engine By Lower Radiator Hose).	2.00	SHOP SUPPLIES	1.00
- Dealer To Repair Leaking Coolant By Lower Radiator Hose.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1102367

Problem: Nail in front tire passenger side

Meter Reading: 10103 In Date: 03/02/2011	Close Date: 03/14/2011	Labor Hours	Description	Parts	Quantity
- Repair Right Front Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1104018

Problem: P. M. SERVICE

Meter Reading: 11673 In Date: 04/13/2011	Close Date: 04/20/2011	Labor Hours	Description	Parts	Quantity
- Performed Service.		7.50	CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
- Repaired Ground For Rear Light Assy.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Unsiezed & Lubed Vise.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Retightened Body Hold Downs.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Tire Repair.			SHOP SUPPLIES		1.00
- Shop Supplies			15/40 OIL		16.00
			3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
Parts Charge: 102.34		Labor Charge: 450.00			

Workorder: 1108565

Problem: P. M. SERVICE

Meter Reading: 16898 In Date: 08/15/2011	Close Date: 08/26/2011	Labor Hours	Description	Parts	Quantity
- Performed P.M.		8.75	7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Dealer To Replace Both Defective Batteries.			15/40 OIL		16.00
- Retightened Body Hold Downs.			3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
- Unsiezed & Lube Vise.			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
- Removed Tag Light & Repaired Wiring & Grounds.			SHOP SUPPLIES		1.00
- Installed Driving Decal.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Transport & Pick Up Vehicle At Dealer. (Defective Batteries).					
- Shop Supplies					
Parts Charge: 132.63		Labor Charge: 525.00			

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1200413

Problem: P. M. SERVICE

Meter Reading: 23104	Labor	Parts	
In Date: 01/12/2012	Hours	Description	Quantity
- P. M. Service.	12.00	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Repaired Ground For Rear Light Assy.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Disassembled Light Bar Assy & Reinstalled Light Assy In Socket. Reassembled Above.		TIRE DISPOSAL FEE	6.00
- Batt Failed Load, Retested & Recharged Batts. Passed.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Unsiezed & Lubed Vise.		15/40 OIL	16.00
- R&R And Balanced 6 Tires.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Retightened Body Hold Downs.		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	6.00
Parts Charge: 1,363.86		Labor Charge: 720.00	

Workorder: 1204545

Problem: pm service

Meter Reading: 28546	Labor	Parts	
In Date: 05/14/2012	Hours	Description	Quantity
- Pm Service	14.50	09997 BRAKE CLEAN	1.00
- Rr Light Assembly In Rear Repaired Wiring In Cabinet For Back Up		1401 BRAKE FLUID BRAKE FLUID	2.00
- Disassemble Light Assemblies Reaired Socket To Bulb Reassemble Light		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Ck Rear Brake Noise Verified Concern Rear Pad Coming Apart Rr Rear Pads		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Unsiezed And Lubed Vise		SHOP SUPPLIES	1.00
- Tightened Body Hold Downs		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Tire Repair R/S Rear Tire		REAR BRAKE PAD	1.00
- Shop Supplies		44202R TAIL LIGHT 4" RED 42 LED	1.00
		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
		15/40 OIL	16.00
Parts Charge: 275.07		Labor Charge: 870.00	

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1207894

Problem: pm

Meter Reading: 34478	Labor	Parts	
In Date: 08/20/2012	Hours	Description	Quantity
- Performed Service	9.50	CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Repaired Running Lights Ground		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Disassembled Light Bar Repaired Connection To Take Down Light		15/40 OIL SHOP SUPPLIES	16.00 1.00
- Unsiezed And Lubed Vise		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Tightened Body Hold Downs		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Tire Repair R R Tire		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Recharged And Retested Batts And Passed			
- Shop Supplies			
Parts Charge: 147.35		Labor Charge: 570.00	

Workorder: 1209451

Problem: truck shut off and wrench light come on in the dash

Meter Reading: 36255	Labor	Parts	
In Date: 10/02/2012	Hours	Description	Quantity
- Transport And Pick Up Vehicle At Dealer Defective Fuel Injector #6	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 120.00	

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1211820

Problem: pm, also keeps shutting off

Meter Reading: 40156	Labor	Parts	
In Date: 12/06/2012	Hours	Description	Quantity
- Pm	11.00	NAPAGOLD FUEL FILTER	1.00
- Repaired Connection To Rear Light Assy		NAPAGOLD AIR FILTER	1.00
- Repaired Connection To Alley Light Reassemble Box		OIL FILTER	1.00
- Unsiezed And Lubed Vise		31-22 WIPER BLADES 22	2.00
- Tightened Hold Downs		SHOP SUPPLIES	1.00
- R Rear Tire Repair		15w40 BULK SOUTH REG	16.00
- Transport And Pick Up Vehicle At Dealer For Warrenty Repairs			
- Dealer To Replace High And Low Fuel Pressure Line			
- Dealer To Replace Defective Ps Wheel			
- Shop Supplies			
Parts Charge: 164.77		Labor Charge: 660.00	

Workorder: 1303274

Problem: P.M.SERVICE

Meter Reading: 44966	Labor	Parts	
In Date: 04/04/2013	Hours	Description	Quantity
- Pm	10.50	SHOP SUPPLIES	1.00
- Repaired Center Stop Light Repaired Grounds For Running Light		NAPAGOLD OIL FILTER	1.00
- Repaired Light In Light Bar And Removed 4 Defective Strobe Packs For Warrantly		FUEL FILTER	1.00
- Repaired Lr Tire		AIR FILTER	1.00
- Tightened Hold Downs		31-22 WIPER BLADES 22	2.00
- Unsiezed And Lubed Vise		15w40 BULK SOUTH REG	16.00
- Transport And Pickup Vehicle At Dealer Dealer To Teplace Defective Radiator And Rad Hoses			
- Shop Supplies			
Parts Charge: 158.83		Labor Charge: 630.00	

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1307366

Problem: install lights

Meter Reading: 46138	Labor	Parts	Quantity
In Date: 07/23/2013	Hours	Description	Quantity
- Installed Several Lights And Connectors Inlight Bar And Reassemble Light	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1400413

Problem: pm

Meter Reading: 50531	Labor	Parts	Quantity
In Date: 01/14/2014	Hours	Description	Quantity
- Pm	11.00	15w40 BULK SOUTH REG	16.00
- Rr Clip Light And Rr Tail Light Assy Repaired Ground To Connector Triple Light Assy		WIPER BLADE	2.00
- Disassembled Light Bar Assy Repaired Wiring To Take Down Light		NAPAGOLD OIL FILTER	1.00
- Unsized And Lubed Vise		LED SUP MDL 44 42 DIO	1.00
- Batt Failed Load Test Recharged Batt Retested Failed Again Rr Both Batteies		FUEL FILTER FORD ONLY	1.00
- Removed Cross Member Straigtened On Press And Reinstalled		BATTERY	2.00
- Shop Supplies		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
		NAPAGOLD AIR FILTER	1.00
Parts Charge:	502.64	Labor Charge:	660.00

Workorder: 1405216

Problem: wiper blades

Meter Reading: 54110	Labor	Parts	Quantity
In Date: 05/29/2014	Hours	Description	Quantity
- Rr Wipers	0.25	WIPER BLADE	2.00
Parts Charge:	8.49	Labor Charge:	15.00

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1407213

Problem: pm

Meter Reading: 55584	Labor	Parts
In Date: 07/22/2014	Hours	Quantity
Close Date: 07/30/2014	Description	
- Pm Frame Rusted Badly	20.00	SHOP SUPPLIES 1.00
- Rr Two Marker Lights Repaired Tag Light		BRAKE PADS 1.00
- Replace Body Bolt Frame Is Severly Rusted		GROMMET MOUNT KIT 2.00
- Removed Shock And Straightened Mount Reinstalled		179636492 LT245-75R17 6.00
Shock		NAPAGOLD AIR FILTER 1.00
- Disassembled Light Repaired Connection To Take Down		FUEL FILTER FORD ONLY 1.00
Light		WIPER BLADE 2.00
- Rr And Balanced 6 Tires		NAPAGOLD OIL FILTER 1.00
- Rr Frt Brakes And Road Tested		1401 BRAKE FLUID BRA 2.00
- Unsiezed And Lubed Vise		TIRE DISPOSAL FEE 6.00
- Shop Supplies		BRAKE CLEANER 1.00
		15w40 BULK SOUTH REG 16.00
Parts Charge:	1,874.15	Labor Charge: 1,200.00

Workorder: 1411644

Problem: DEAD BATTERY

Meter Reading: 57097	Labor	Parts
In Date: 11/18/2014	Hours	Quantity
Close Date: 11/19/2014	Description	
- Jump Start Vehicle From Wud Parking Lot Recharge And	2.00	SHOP SUPPLIES 1.00
Test Batteries Both Batteries Are Bad Replace Both		
Batteries Under Warrancy		
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 120.00

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1500196

Problem: PM

Meter Reading: 57804	Labor	Parts
In Date: 01/07/2015	Hours	Quantity
Close Date: 01/22/2015	Description	
- Pm Frame Is Ruttred Badly	11.00	15w40 BULK SOUTH REG 16.00
- Repaired Open In Cabinet For Running Light And Rr On Light		SHOP SUPPLIES 1.00
		NAPAGOLD AIR FILTER 1.00
- Unsiezed And Lubed Vise		M C LAMP 1.00
- Tire Repair 4 Rear		WIPER BLADE 2.00
- Repaired Wiring For Back Up Alarm		USED FIRE X REFURBISHED 1.00
- Tightened Cab Mounts		FUEL FILTER FORD ONLY 1.00
- Repaired Wiring To One Strobe Light And Remove Two Strobe Packs And Replaced		NAPAGOLD OIL FILTER 1.00
- Shop Supplies		
Parts Charge: 206.89	Labor Charge: 660.00	

Workorder: 1504242

Problem: Light bar

Meter Reading: 59950	Labor	Parts
In Date: 04/24/2015	Hours	Quantity
Close Date: 07/06/2015	Description	
- Remove Damaged Light Bar Replace Bracket, Seal Holes	3.00	SHOP SUPPLIES 1.00
- Shop Supplies		LIGHT BAR MOUNTING BRACKET 1.00
Parts Charge: 736.25	Labor Charge: 180.00	

Workorder: 1508311

Problem: PM

Meter Reading: 61561	Labor	Parts
In Date: 08/19/2015	Hours	Quantity
Close Date: 08/25/2015	Description	
- Pm Frame Is Badly Rusted	9.00	NAPAGOLD AIR FILTER 1.00
- Repaired Wiring In Back Cabinet For Lights		FUEL FILTER FORD ONLY 1.00
- Disassembled Light Bar And Repaired Connections To Alley Light		WIPER BLADE 2.00
		15w40 BULK SOUTH REG 16.00
- Unsiezed And Lubed Vise		SHOP SUPPLIES 1.00
- Reattached Frt Spoiler		NAPAGOLD OIL FILTER 1.00
- Repaired Rr Tire		
- Shop Supplies		
Parts Charge: 187.97	Labor Charge: 540.00	

1/30/2017
4:15:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180749 2010 FORD F350 Utility Body, 1 Ton

Workorder: 1601796

Problem: pm

Meter Reading: 65709		Labor		Parts	
In Date: 02/22/2016	Close Date: 02/29/2016	Hours	Description	Quantity	
- Pm Utility Body Damaged On Ps Side Frt Frame Rusted Badly		9.50	SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
- Rr Two Light Assemblies Repaired Open To Marker Light			15w40 BULK SOUTH REG		16.00
- Repaired Connection At Switch			USED FIRE X REFURBISHED		1.00
- Repaired R Inner Tire And Frt Ds Tires			FUEL FILTER FORD ONLY		1.00
- Straightened Shock Bracket			LED SUP MDL 44 42 DIO		1.00
- Shop Supplies			22" WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FLUID CONCENTR		1.00
			M C LAMP		1.00
Parts Charge: 271.51		Labor Charge: 570.00			

Workorder: 1609011

Problem: P.M.SERVICE

Meter Reading: 70014		Labor		Parts	
In Date: 08/30/2016	Close Date: 09/09/2016	Hours	Description	Quantity	
- P.M.Service		5.00	SHOP SUPPLIES		1.00
- Repair Tail Gate.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			15w40 BULK SOUTH REG		16.00
			22" WIPER BLADE		2.00
			FUEL FILTER FORD ONLY		1.00
			WASHER FLUID CONCENTR		1.00
Parts Charge: 151.36		Labor Charge: 300.00			

Workorder: 1611133

Problem: Transition Prep Charge

Meter Reading: 70454		Labor		Parts	
In Date: 10/27/2016	Close Date: 10/27/2016	Hours	Description	Quantity	
- Transition Prep Charge		2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	6,458.59	Total Labor Charges:	9,765.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------