10199137 2015 MENZI MUCK M540 Excavator, Walking, All Terrain

Workorder: 1600601 Meter: 10 In Date: 01/20/2016 Closed: 01/29/2016 Problem: Check In **Parts List** - Check In Qty - Weld assets 5% Moly Reg'd 20.00 **Shop Supplies** 1.00 - Test run - To Cresthaven 2xs - Adjust Presures - Shop Supplies Hours 16.00 Labor: 960.00 Parts: 98.60 Total: 1,058.60 Workorder: 1600614 Meter: 10 In Date: 01/20/2016 Closed: 01/20/2016 Problem: 1062 - Make & Apply Decals. Check Fluids, Belts and Operation - Make & Apply Decals. Check Fluids, Belts and Operation Hours 1.00 Labor: 60.00 Parts: 0.00 Total: 60.00 Workorder: 1600729 Meter: 10 In Date: 01/22/2016 Closed: 01/25/2016 Problem: Greese fittings - add fittings on power tilt for grease **Parts List** Qty - to berkley ditch Shop Supplies 1.00 - Shop Supplies Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00 Workorder: 1601466 Meter: 88 In Date: 02/11/2016 Closed: 02/25/2016 Problem: Greese **Parts List** - Greese Qty - Fill with Hyd. oil 2xs 5% Moly Req'd 40.00 - Repair lines to mower deck. Check and adjust system Aw68 Hydro Fluid Hydr 108.00 presures **Shop Supplies** 1.00 - To Purdy Lane 3xs - Shop Supplies Labor: 600.00 Hours 10.00 Parts: 441.44 Total: 1,041.44 Workorder: 1601981 02/25/2016 Closed: 03/31/2016 Meter: 118 In Date: Problem: PM

:

Workorder: Problem:	1602025 Greese t		Meter:	118			In Date:	02/26/2016	Closed:	03/04/2016
- Repair lube	line					Parts Lis	st			Qty
- To Canal 9						Shop Sup				1.00
- Shop Suppli	ies						•			
		Hours :	5.00		Labor:	300.00	Parts:	2.00	Total:	302.00
Workorder: Problem:	1602291 Greeser		Meter:	121			In Date:	03/04/2016	Closed:	03/08/2016
- Remove pin	to clean	out pas	sage wa	y for greese		Parts Lis	st			Qty
- To Cannal 9)					Shop Sup	oplies			1.00
- Shop Suppl	ies									
		Hours :	4.00		Labor:	240.00	Parts:	2.00	Total:	242.00
Workorder: Problem:	1602527 Greese	7	Meter:	227			In Date:	03/10/2016	Closed:	03/31/2016
- Greese						Parts Lis	st			Qty
- Repair hyd.	leak on R	r leg a	nd top off	oil. Repair gre	eeseing	Aw68 Hy	dro Fluid H	lydr		4.00
system						5% Moly	Req'd			20.00
- To Eoc ditch						1cart Pal	ladium 2 G	irs		20.00
- Shop Suppl	ies					Shop Sup	oplies			1.00
		Hours	14.50		Labor:	870.00	Parts:	206.12	Total:	1,076.12
Workorder: Problem:	1603553 Greese	3	Meter:	249			In Date:	04/05/2016	Closed:	04/14/2016
- Replace gre	ase fitting	s and	adjust gre	easer		Parts Lis	st			Qty
- To Hermosa	a Ditch 2x	S				Washer F	Fluid Conce	entr		2.00
- Shop Suppli	ies					5% Moly	Req'd			40.00
						Shop Sup	oplies			1.00
		Hours	4.50		Labor:	270.00	Parts:	198.65	Total:	468.65
Workorder: Problem:	1604152 Power ti		Meter:	249			In Date:	04/20/2016	Closed:	05/12/2016
- order power	tilt. greas	se				Parts Lis	st			Qty
-	-					powertilt				1.00
 Shop Suppli 										
- Shop Suppl						5% Moly	Req'd			20.00
- Shop Suppl						5% Moly 5% Scha	Req'd ffer Ultra S	Supreme		20.00 20.00
- Snop Suppl						5% Scha	ffer Ultra S	Supreme		
- Snop Suppl						-	ffer Ultra S oplies	Supreme		20.00

Workorder: 160515 Problem: Greese		Meter:	249			In Date:	05/18/2016	Closed:	06/16/2016
- Greese					Parts Lis	st			Qty
- To Barkly ditch					5% Scha	ıffer Ultra S	Supreme		60.00
- Check for leak and c	lean co	olers			Shop Su	pplies			1.00
- Shop Supplies					·				
	Hours :	2.00		Labor:	120.00	Parts:	443.00	Total:	563.00
Workorder: 160661 Problem: AC	5	Meter:	249			In Date:	06/29/2016	Closed:	07/13/2016
- check Ac send to she	ор				Parts Lis	st			Qty
- to old Eoc ditch					Shop Su	pplies			1.00
- Shop Supplies					•				
	Hours :	2.00		Labor:	120.00	Parts:	2.00	Total:	122.00
Workorder: 160706 Problem: AC	8	Meter:	249			In Date:	07/13/2016	Closed:	07/28/2016
- check Ac					Parts Lis	st			Qty
- water pump					m5 wate	r pump			1.00
- to eoc 4 times					water pu	mp gasket			1.00
- belt					Distilled	Water 1gal			3.00
- Shop Supplies					Peak Glo	obal Antifrz			2.00
					Ultra Sup	oreme 238	Moly Grease		20.00
					m5 serpe	entine belt			1.00
					Shop Su	pplies			1.00
					Freight C	Charge			1.00
					Freight C	Charge			1.00
	Hours :	9.00		Labor:	540.00	Parts:	2,590.81	Total:	3,130.81
Workorder: 160788 Problem: Greese		Meter:	249			In Date:	08/02/2016	Closed:	08/10/2016
- Greese					Parts Lis	st			Qty
- Shop Supplies					Ultra Sur	oreme 238	Moly Grease		20.00
					Shop Su		,		1.00
	Hours	0.50		Labor:	-		143.00	Total:	173.00
Workorder: 160821 Problem: Greese		Meter:	249			In Date:	08/10/2016	Closed:	08/19/2016
- Greese					Parts Lis	st			Qty
- Shop Supplies					Ultra Sur	oreme 238	Moly Grease		40.00
• •					Shop Su				1.00
	Hours	0.00		Labor:	-		284.00	Total:	284.00

Workorder: Problem:	1608990 Greese		Meter:	249				In Da	ate:	08/30/2016	Closed:	08/31/2	016
- Greese							Parts L	_ist					Qty
- Shop Suppli	es						Ultra S	upreme	238	Moly Grease			20.00
							Non-ch	lor Bral	ke Clr	nr			2.00
							Shop S	Supplies	;				1.00
		Hours :	0.00			Labor:	0.00	P	Parts:	148.61	Total:	148.61	
Workorder: Problem:	1609102 Blades lo		Meter:	249				In Da	ate:	08/31/2016	Closed:	09/13/2	016
- Freed up bla	ades, Repl	ace bla	ades with	n new			Parts I	_ist					Qty
- To Hermosa	ditch						Mower	Blade					3.00
- Shop Suppli	es						Blade \	<i>N</i> asher					3.00
							Blade F	Roll Pin					3.00
							Mower	Blade					3.00
							Blade E	3olt					3.00
							Blade I	Nut					3.00
							Blade \	<i>N</i> asher					3.00
							Blade F	Roll Pin					3.00
							Shop S	Supplies	5				1.00
		Hours :	6.00			Labor:	360.00	P	Parts:	659.41	Total:	1,019.4	1
Workorder: Problem:	1609337 Greese		Meter:	249				In Da	ate:	09/08/2016	Closed:	09/13/2	016
- Greese							Parts I	_ist					Qty
- Replace blo	cked gree	se line					Ultra S	upreme	238	Moly Grease			20.00
- To Collins D - Shop Suppli	itch							Supplies		,			1.00
- Griop Guppii		Hours :	6.00			Labor:	360.00	P	Parts:	143.00	Total:	503.00	
Workorder: Problem:	1609600 Greese f		Meter:	249				In Da	ate:	09/14/2016	Closed:	10/13/2	016
- grease line l		install	quick co	uplers.	repair	grease	Parts I	_ist					Qty
system to boo							hose m	nade ma	ako				1.00
- clean radiate	or						Ultra S	upreme	238	Moly Grease			40.00
- to mako							Shop S	Supplies	;				1.00
- to collins dite													
- install couple		wer de	ck										
- Shop Suppli	es												
		Hours	13.00			Labor:	780.00	P	arts:	1,604.23	Total:	2,384.2	3
		:											

Workorder: 161077 Problem: grease		eter:	800			In Date:	10/19/2016	Closed:	10/28/2016
- Greese					Parts Li	st			Qty
- Shop Supplies							Moly Grease		20.00
5op 5pp5					Shop Su		,		1.00
	Hours 0.	50		Labor:	•		143.00	Total:	173.00
Workorder: 161130	: 12 M	eter:	800			In Date:	11/02/2016	Closed:	11/09/2016
Problem: Greese		ctor.	000			iii Date.	11/02/2010	Oloscu.	11/03/2010
- Greese					Parts Li	st			Qty
- Shop Supplies					Ultra Su	preme 238	Moly Grease		20.00
					Shop Su	ıpplies			1.00
	Hours 0.	00		Labor:	0.00	Parts:	143.00	Total:	143.00
Workorder: 161158 Problem: hatch	32 M	eter:	968			In Date:	11/09/2016	Closed:	11/15/2016
- add oil. add hyd flui	d				Parts Li	st			Qty
- repair rear hatch					Napa Qt	: 15w40			2.00
- wash and blow out a	all coolers a	and air	filters		Aw68 H	ydro Fluid H	lydr		8.00
to cresthaven ditchShop Supplies					Shop Su	ıpplies			1.00
	Hours 5.	50		Labor:	330.00	Parts:	27.77	Total:	357.77
Workorder: 161184 Problem: PM	12 M	eter:	968			In Date:	11/16/2016	Closed:	12/07/2016
- pm					Parts Li	st			Qty
- wash cab					Wiper B	lade			1.00
- test run					Ultra Su	preme 238	Moly Grease		22.00
- Shop Supplies					Big G D	egreaser 1 (Gal		1.00
						Fluid Conce			1.00
					15-40 C)il			14.00
					M5 Filte	r Kit			1.00
					Aw68 H	ydro Fluid H	lydr		20.00
						Gear Oil Ge			12.00
						or Brake Clr			4.00
					Shop Su				1.00
	Hours 9.	50		Labor:	570.00		2,709.05	Total:	3,279.05
Workorder: 161257 Problem: Greese		eter:	968			In Date:	12/07/2016	Closed:	12/09/2016
- Greese					Parts Li	st			Qty
- Shop Supplies							Moly Grease		20.00
Strop Supplies					Shop Su				1.00
	Hours 0.	50		Labor:	30.00	Parts:	143.00	Total:	173.00

Workorder: Problem:	1612728 Hyd Lea		Meter:	996			In Date:	12/13/2016	Closed:	12/13/2016
- Ck Hyd leak	and four	nd none				Parts L	ist			Qty
- To Cresthav						Shop St	upplies			1.00
- Shop Suppli	es									
		Hours :	2.00		Labor:	120.00	Parts:	2.00	Total:	122.00
Workorder: Problem:	1612989 grease	9	Meter:	996			In Date:	12/21/2016	Closed:	12/29/2016
- Greese						Parts L	ist			Qty
- Shop Suppli	es					Ultra Su	preme 238	Moly Grease		20.00
						Shop St	upplies			1.00
		Hours :	0.00		Labor:	0.00	Parts:	143.00	Total:	143.00
Workorder: Problem:	1700263 Greese	3	Meter:	996			In Date:	01/10/2017	Closed:	01/12/2017
- Greese						Parts L	ist			Qty
- Shop Suppli	es					Ultra Su	preme 238	Moly Grease		20.00
						Air Fres	hener			2.00
						Washer	Fluid Conce	entr		2.00
						Shop St				1.00
		Hours :	0.00		Labor:	0.00	Parts:	153.44	Total:	153.44
Workorder: Problem:	1700407 Power ti		Meter: egs	996			In Date:	01/12/2017	Closed:	02/06/2017
- joy stick						Parts L	ist			Qty
- grease						Joy Stic	k			1.00
- Shop Suppli	es					Coupler	•			1.00
						Ultra Su	preme 238	Moly Grease		40.00
						Shop St	upplies			1.00
						Freight	Charge			1.00
		Hours :	2.00		Labor:	120.00	Parts:	6,744.40	Total:	6,864.40
Workorder: Problem:	1701304 Power T		Meter: e	996			In Date:	02/08/2017	Closed:	02/09/2017
- Ck boom & p	oower tilt					Parts L	ist			Qty
- To Sunny La	ane					Shop St	upplies			1.00
- Shop Suppli	es									
		Hours :	1.50		Labor:	90.00	Parts:	2.00	Total:	92.00

Frobleiii.	1701626 Pin Reta		Meter:	1354			In Date:	02/15/2017	Closed:	02/16/2017
- To Neva St.		sent to	shop for	bad bearrings		Parts Li Shop Su				Qty 1.00
- Shop Suppli	162	Hours :	2.00		Labor:	120.00	Parts:	2.00	Total:	122.00
Workorder: Problem:	1701780 Coupler		Meter:	1354			In Date:	02/17/2017	Closed:	03/16/2017
- R&r coupler	on lube l	line to n	nower			Parts Li	st			Qty
- To Acme Da	airy Rd					Ultra Su	preme 238	Moly Grease		20.00
- To Mako Ho	se					jack fem	ale fitting			2.00
- Shop Suppli	ies					jack mal	e fitting			2.00
						Shop Su	ıpplies			1.00
		Hours :	3.00		Labor:	180.00	Parts:	233.30	Total:	413.30
Workorder: Problem:	170286 Greese	7	Meter:	1354			In Date:	03/22/2017	Closed:	03/29/2017
- Greese						Parts Li	st			Qty
- Shop Suppli	ies					Ultra Su	preme 238	Moly Grease		20.00
						Shop Su	•	·		1.00
		Hours	0.00		Labor:			143.00	Total:	143.00
Workorder:	170316	1	Meter:	1207						
Problem:			wietei.	1397			In Date:	03/30/2017	Closed:	05/11/2017
	Joystick		weter.	1397		Parts Li		03/30/2017	Closed:	05/11/2017 Qty
Problem:	Joystick stick					Parts Li	st	03/30/2017	Closed:	
Problem: - replace joy s - to kelly dr. to - R&r mowers	Joystick stick c crestha spindle a	ven. to	barkley d ly. replac		r and		st spindle	03/30/2017	Closed:	Qty
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp	Joystick stick c crestha spindle a oorts to re	ven. to ssemble	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Bo	st spindle Blade olt	03/30/2017	Closed:	Qty 1.00 3.00 3.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades	Joystick stick crestha spindle a corts to replace	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade B Blade N	st spindle Blade olt ut	03/30/2017	Closed:	Qty 1.00 3.00 3.00 3.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Bo Blade N Blade R	st spindle Blade olt ut oll Pin	03/30/2017	Closed:	Qty 1.00 3.00 3.00 3.00 3.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade B Blade N Blade R Blade W	st spindle Blade olt ut oll Pin		Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade B Blade N Blade R Blade W Ultra Su	st spindle Blade olt ut oll Pin asher preme 238	03/30/2017 Moly Grease	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 60.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	Mower B Blade Blade N Blade R Blade W Ultra Su Air Fresh	st spindle Blade olt ut oll Pin asher preme 238	Moly Grease	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 60.00 2.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fresl Washer	st spindle Blade olt ut oll Pin /asher preme 238 hener Fluid Cond	Moly Grease	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 60.00 2.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade B Blade N Blade R Blade W Ultra Su Air Fresl Washer kimball h	st spindle Blade olt ut oll Pin asher preme 238 hener Fluid Cond	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 60.00 2.00 2.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade B Blade N Blade R Blade W Ultra Su Air Fresl Washer kimball h	st spindle Blade olt ut oll Pin asher preme 238 hener Fluid Conc nardware	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 2.00 2.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fresi Washer kimball h Ptex Thi sprocket	st spindle Blade olt ut oll Pin asher preme 238 hener Fluid Cond nardware d Lck Red	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 60.00 2.00 1.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fresi Washer kimball h Ptex Thi sprocket	st spindle Blade olt ut oll Pin /asher preme 238 hener Fluid Conconardware rd Lck Red t	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 2.00 2.00 1.00 1.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fres Washer kimball h Ptex The sprocker roller che Joy Stick	st spindle splade olt ut oll Pin asher preme 238 hener Fluid Conc hardware d Lck Red t ain	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 60.00 2.00 1.00 1.00 1.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fresl Washer kimball h Ptex Thi sprocket roller cha Joy Stick Shop Su	st spindle slade olt ut oll Pin /asher preme 238 hener Fluid Conco hardware rd Lck Red t ain k	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 2.00 2.00 1.00 1.00 1.00 1.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower somewhat Mower Educate Blade Blade North Blade Robbins Blade Work Ultra Sur Air Fresh Washer kimball Moshocket Freight Controller Children Sur Stop Sur Freight Controller Children Sur Stop Sur Freight Controller Children Sur	st spindle slade olt ut oll Pin asher preme 238 hener Fluid Conc hardware d Lck Red t ain k upplies Charge	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 60.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - replace joy s - to kelly dr. to - R&r mower s fabricate supp - order blades - replace grea	Joystick stick coresthat spindle a corts to rest. replace ase fitting	ven. to ssemble pair dece	barkley d ly. replac ck	litch	r and	mower s Mower E Blade Be Blade N Blade R Blade W Ultra Su Air Fresl Washer kimball h Ptex Thi sprocket roller cha Joy Stick Shop Su	st spindle slade olt ut oll Pin 'asher preme 238 hener Fluid Conce hardware od Lck Red t ain k upplies Charge	Moly Grease eentr	Closed:	Qty 1.00 3.00 3.00 3.00 3.00 3.00 2.00 2.00 1.00 1.00 1.00 1.00 1.00

Workorder: 1704630 Meter: 1550 Problem: remove wire from mower head	In Date: 05/09/2017 Closed:	05/31/2017
- Remove chain link fence from mower. Work with Menzi on	Parts List	Qty
recalls	Aw68 Hydro Fluid Hydr	40.00
- To Perdy Lane ditch 3xs, and to Canal 9	Ultra Supreme 238 Moly Grease	20.00
- Reinstall turbo hose	Key	3.00
- Repair greese lines @ boom. Repair hyd. leak @ rear pump hose connection, R&r cooler, top off oil	Shop Supplies Freight Charge	1.00 1.00
- To Mako	3 3 4 5 4 5	
- Shop Supplies		
Hours 17.50 Labor:	1,050.0 Parts: 403.05 Total: 0	1,453.05
Workorder: 1705366 Meter: 1650 Problem: PM	In Date: 05/31/2017 Closed:	07/12/2017
- pm	Parts List	Qty
- R&r broken bolts from hyd filter housing	M5 Filter Kit	1.00
- repair hyd fitting. repair greaser. repair brake	15-40 Oil	14.00
- to lyons ditch 5 times	Wiper Blade	1.00
- test run many times	Washer Fluid Concentr	1.00
- clean coolers	85-140 Gear Oil Gear	20.00
- replace blades	Ultra Supreme 238 Moly Grease	30.00
- deck motor replace. repair power tilt leak	Big G Degreaser 1 Gal	1.00
- to mako	Service Aw68	20.00
- tighten anvil bolts. repair greaser lines	21/2 gal simple green	1.00
- to lyons	menzi mower deck motor	1.00
- Shop Supplies	Non-chlor Brake Clnr	6.00
	Aw68 Hydro Fluid Hydr	9.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 42.00 Labor:	2,520.0 Parts: 3,799.68 Total: 0	6,319.68
Workorder: 1706856 Meter: 1650 Problem: grease	In Date: 07/13/2017 Closed:	07/17/2017
- grease	Parts List	Qty
- Shop Supplies	Ultra Supreme 238 Moly Grease	20.00
	Shop Supplies	1.00
Hours 0.50 Labor:	30.00 Parts: 143.00 Total:	173.00

Workorder: Problem:	1707033 blades	Meter:	1650		In I	Date:	07/19/2017	Closed:	08/07/2017
- blades					Parts List				Qty
- Shop Suppli	es				Mower Blade	е			3.00
					Blade Bolt				3.00
					Blade Nut				3.00
					Blade Roll P	in			3.00
					Blade Wash	er			3.00
					Freight				1.00
					Shop Suppli	es			1.00
	Hou	urs 2.50		Labor:	150.00	Parts:	439.54	Total:	589.54
Workorder: Problem:	1707336 hyd leak	Meter:	1741		In I	Date:	07/26/2017	Closed:	08/01/2017
- replace hose	e in boom				Parts List				Qty
- to lyons and	linton				hose made				1.00
- to mako					Wd40 Spr				1.00
- check freon	in Ac				Ultra Supren	ne 238	Moly Grease		20.00
- Shop Suppli	es				Shop Suppli	es			1.00
	Hou	urs 10.50		Labor:	630.00	Parts:	775.54	Total:	1,405.54
Workorder: Problem:	1707823 grease	Meter:	1741		In I	Date:	08/10/2017	Closed:	08/16/2017
- grease					Parts List				Qty
- top off oil					Ultra Supren	ne 238	Moly Grease		20.00
- to eoc ditch					Aw68 Hydro	Fluid F	Hydr		16.00
- Shop Suppli	es				Shop Suppli	es			1.00
	Hou	ırs 2.00		Labor:	120.00	Parts:	179.48	Total:	299.48

:

- repair hyd leak top of										
	f hyd o	oil. replace	e 3 hyd hos	es in leg	Parts Lis	st				Qty
- to Eoc ditch 2xs. to g	•	•	•	J	hose mad	de				1.00
- to mako	•				hose mal	ΚΟ				1.00
- test run					Aw68 Hy	dro Fluid H	lydr			30.00
- R&r door 2xs					Ultra Sup	reme 238	Moly Grease			40.00
- replace joy stick					F/I Hose		•			2.00
- replace relief valve or	n powe	er tilt. repl	ace hyd ho	ses at	1cart Pall	ladium 2 G	irs			2.00
grapple					Non-chlo	r Brake Clr	nr			2.00
- to mako					hose mad	de mako				1.00
- to community ditch.	to rode	o drive			Ultra Sup	reme 238	Moly Grease			20.00
- add hyd oil					Cross Po	rt Relief Va	alve			1.00
- Shop Supplies					door glas	ss				1.00
					cooling s	ystem seal	tabs			2.00
					hose					1.00
					Joy Stick					1.00
					hose mad	de				1.00
					Aw68 Hy	dro Fluid H	łydr			28.00
					Shop Sup	oplies				1.00
					Freight C	harge				1.00
					Freight C	harge				1.00
					Freight C	harge				1.00
					Freight C	harge				1.00
	Hours :	51.50		Labor:	3,090.0 0	Parts:	9,580.50	Total:	12,670.	50
Workorder: 170894 Problem: replace		Meter: lass	1741			In Date:	09/18/2017	Closed:	09/25/2	017
- Set up repairs for rep	lacing	glass			Parts Lis	st				Qty
- Shop Supplies					Shop Sup	oplies				1.00
	Hours :	3 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: 1710774 Problem: install d		Meter: e	1822			In Date:	10/31/2017	Closed:	11/02/2	017
- Install case drains										
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: 1710830 Problem: Greese		Meter:	1822			In Date:	11/01/2017	Closed:	11/07/2	017
- replace grease fitting					Parts Lis	st				Qty
					hose mad	de mako				1.00
 to mosquito control 					Chan Cui	anlina				1.00
to mosquito controlto mako					Shop Sup	opiles				1.00
·					Shop Sup	oplies				1.00

Workorder: Problem:	171106 Greese	5 Meter:	1822			In Date:	11/08/2017	Closed:	11/13/2017
- grease					Parts Lis	st			Qty
- Shop Suppli	es				Ultra Sup	reme 238	Moly Grease		20.00
					Shop Sup	oplies			1.00
		Hours 0.50		Labor:	30.00	Parts:	143.00	Total:	173.00
Workorder: Problem:	171133 Repair		1822			In Date:	11/16/2017	Closed:	11/27/2017
- repair left jo	ystick				Parts Lis	st			Qty
- to gun club o					Shop Sup	oplies			1.00
- Shop Suppli									
		Hours 3.00 :		Labor:	180.00	Parts:	2.00	Total:	182.00
Workorder: Problem:	171199 Greese	6 Meter:	1822			In Date:	12/07/2017	Closed:	12/08/2017
- Greese					Parts Lis	st			Qty
- Shop Suppli	es				Ultra Sup	reme 238	Moly Grease		20.00
					Shop Sup				1.00
		Hours 0.00		Labor:	0.00	Parts:	143.00	Total:	143.00
Workorder: Problem:	171221 replace	1 Meter: missing plug	2032			In Date:	12/13/2017	Closed:	01/11/2018
- Replace rub	ber hous	sina plua			Parts Lis	st			Qty
- Replace retu						dro Fluid H	Hydr		120.00
- To Collins D					fitting fror		,		1.00
- To Mako 2xs	S				hose mad	de			1.00
- Repair leaki	ng hoses	and greese lii	nes in leg. Free	ed up	Cable Tie)			1.00
frozen pins.					Cable Tie)			1.00
Walked machi					Non-chlo	r Brake Cl	nr		5.00
- Replaced ra	-	kers			hose mad	de mako			1.00
- Shop Suppli	es				Speaker				2.00
					plugs				1.00
					Ultra Sup	reme 238	Moly Grease		20.00
					Shop Sup	oplies			1.00
					Freight C	harge			1.00
		Hours 45.00 :		Labor:	2,700.0 0	Parts:	2,252.54	Total:	4,952.54

Problem:	1800356 Coolant		Meter:	2054		I	n Date:	01/10/2018	Closed:	01/19/2018
- check coola	nt found l	low. tes	st for leak	s. replace 2 ra	adiator	Parts List				Qty
hoses and fill s	system					hose make	0			1.00
- to wabasso	and cher	okee				1gal Rtu A	ntifreeze			8.00
- pm						Hose Clar	np			4.00
- repair grease	e lines					15-40 Oil				14.00
- test run						M5 Filter k	Cit			1.00
- Shop Suppli	es					Aw68 Hyd	lro Fluid H	lydr		10.00
						85-140 G	ear Oil Ge	ear		20.00
						Ultra Supr	eme 238	Moly Grease		30.00
						Non-chlor	Brake Clr	nr		2.00
						Wiper Blad	de			1.00
						Shop Sup	plies			1.00
		Hours :	17.50		Labor:	1,050.0 0		2,824.88	Total:	3,874.88
Workorder: Problem:	1801554 Greese	4	Meter:	2054		I	n Date:	02/09/2018	Closed:	02/13/2018
- Greese						Parts List	:			Qty
- Shop Suppli	es					Ultra Supr	eme 238	Moly Grease		20.00
,,,						Shop Sup		,		1.00
		Hours :	0.50		Labor:			143.00	Total:	173.00
Workorder: Problem:	1802042 grease	2	Meter:	2242		I	n Date:	02/23/2018	Closed:	03/28/2018
- grease										
9.0000						Parts List	:			Qty
=	e lirrors, ı	replace	joystick (caps and tighte	en bolts	Parts List Joystick B		red)		Qty 24.00
- horn, replace				caps and tighte			uttons - (r	red)		-
- horn, replace	ack. fla m	ango.to	upland.			Joystick B	uttons - (r der	red)		24.00
- horn, replace - north dog tra	ack. fla m e line at l	ango.to	upland.			Joystick B mirror hold rear veiw	uttons - (r der mirror	red) Moly Grease		24.00 1.00
horn, replacenorth dog trarepair grease	ack. fla m e line at l nctions	ango.to	upland.			Joystick B mirror hold rear veiw I Ultra Supr	uttons - (r der mirror eme 238	,		24.00 1.00 2.00
horn, replacenorth dog trarepair greasecheck leg fue	ack. fla m e line at l nctions	ango.to	upland.			Joystick B mirror hold rear veiw I Ultra Supr	uttons - (r der mirror eme 238 eme 238	Moly Grease		24.00 1.00 2.00 20.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako 	ack. fla me line at le netions and bria	ango.to boom tip in way	upland.		obee	Joystick B mirror hold rear veiw r Ultra Supr Ultra Supr	uttons - (r der mirror eme 238 eme 238	Moly Grease		24.00 1.00 2.00 20.00 40.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow 	ack. fla me line at lenctions and briatorians with the second price and briatorians were steering to the second price and steering the second price and second price at least 100 meteorians and 100 meteor	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe	uttons - (r der mirror eme 238 eme 238	Moly Grease Moly Grease		24.00 1.00 2.00 20.00 40.00 2.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn	uttons - (r der mirror eme 238 eme 238 ener	Moly Grease Moly Grease		24.00 1.00 2.00 20.00 40.00 2.00 1.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako	Moly Grease Moly Grease entr		24.00 1.00 2.00 20.00 40.00 2.00 1.00 2.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako lro Fluid H	Moly Grease Moly Grease entr		24.00 1.00 2.00 20.00 40.00 2.00 1.00 2.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd	uttons - (r der mirror eme 238 emer 238 ener luid Conce e Mako lro Fluid F	Moly Grease Moly Grease entr		24.00 1.00 2.00 20.00 40.00 2.00 1.00 20.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd Shop Sup	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako lro Fluid H plies narge	Moly Grease Moly Grease entr		24.00 1.00 2.00 20.00 40.00 2.00 1.00 20.00 1.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee	Joystick B mirror hold rear veiw in Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd Shop Sup Freight Ch	uttons - (r der mirror eme 238 emer luid Conce e Mako lro Fluid F plies narge	Moly Grease Moly Grease entr		24.00 1.00 2.00 20.00 40.00 2.00 1.00 20.00 1.00 2.00
 horn, replace north dog tra repair grease check leg fue to belvedere to mako replace blow covers and fill 	ack. fla me e line at le nctions e and bria wn steerinoil	ango.to boom tip in way	upland.	to old okeecho	obee &r	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd Shop Sup Freight Ch	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako lro Fluid H plies narge narge	Moly Grease Moly Grease entr	Total:	24.00 1.00 2.00 20.00 40.00 2.00 1.00 20.00 1.00 2.00 1.00 2.00 1.00
- horn, replace - north dog tra - repair grease - check leg fue - to belvedere - to mako - replace blow covers and fill - Shop Suppli	ack. fla me e line at lanctions e and brian oil es	Hours	upland.	to old okeecho	obee &r	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd Shop Sup Freight Ch Freight Ch Freight Ch 1,650.0 0	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako lro Fluid H plies narge narge	Moly Grease Moly Grease entr	Total:	24.00 1.00 2.00 20.00 40.00 2.00 1.00 20.00 1.00 2.00 1.00 1.00 1.00
- horn, replace - north dog tra - repair grease - check leg fue - to belvedere - to mako - replace blow covers and fill - Shop Suppli	ack. fla me e line at lanctions e and brian oil es	Hours	upland. s on men 27.50	to old okeecho	obee &r	Joystick B mirror hold rear veiw I Ultra Supr Ultra Supr Air Freshe horn Washer Fl Hose Mak Aw68 Hyd Shop Sup Freight Ch Freight Ch Freight Ch 1,650.0 0	uttons - (r der mirror eme 238 eme 238 ener luid Conce e Mako lro Fluid H plies harge harge harge	Moly Grease Moly Grease entr Hydr 2,130.68		24.00 1.00 2.00 40.00 2.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 3,780.68

Workorder: 1803645 Meter: 2387 Problem: Greese	In Date: 04/06/2018 Closed: 05/23/2018
- Grease	Parts List Qty
- To Skee's Rd. 4xs To Canal 9 3xs	Wd40 Spr 1.00
- Repair grease line, Replace grease pump assembly for	Cable Tie 1.00
mowing deck. Replace hyd hoses on boom	Cable Tie 1.00
- Replace blades	Cable Tie 1.00
- Rebuild mower deck assembly. Replace motor, spindle	mower spindle 1.00
assembly, Blade bar, and blades	menzi reman deck motor 1.00
- Rebuil Power tilt	Ultra Supreme 238 Moly Grease 41.00
- To Mako 4xs	Cable Tie 1.00
- Repair grease line to boom	Mower Blade 3.00
- Repair side of deck, Reweld new panels	Blade Bolt 3.00
- To Haven - Wood Ditch	Blade Nut 3.00
- Shop Supplies	Blade Roll Pin 3.00
	Blade Washer 3.00
	Plug 6.00
	Brass Pipe Valve 1.00
	Female Socket 1.00
	Hose Made Mako 1.00
	Hose Made Mako 1.00
	Lincoln Pump 24v 1.00
	1"x6' cam strap 2.00
	30 175 Nat Cable Tie 1.00
	50 inch disc 1.00
	Ptex Thrd Lck Red Lg 1.00
	sprocket 1.00
	roller chain 1.00
	Hose Made Mako 1.00
	Ultra Supreme 238 Moly Grease 20.00
	Shop Supplies 1.00
	Freight Charge 1.00
	Freight Charge 1.00
	Freight Charge 1.00
Hours 100.00 Lab	or: 6,000.0 Parts: 11,413.41 Total: 17,413.41
Workorder: 1804671 Meter: 2242 Problem: LR tire	In Date: 05/03/2018 Closed: 05/07/2018
- tire	
	or: 0.00 Parts: 0.00 Total: 0.00

Workorder: Problem:	1805231 Greese	Meter:	2491			In Date:	05/22/2018	Closed:	06/18/2018
- grease					Parts Lis	st			Qty
- pm					Ultra Sup	oreme 238	Moly Grease		20.00
- wash and re	move beach	sand				Fluid Conc	•		2.00
- drill holes in	wheel motor	covers			85-140 (Gear Oil G	ear		24.00
- flush hub oil	replace dama	aged fill plug	js –		15-40 O	il			14.00
- replace belt	and tensione	r			Washer I	Fluid Conc	entr		1.00
- replace mirr	ors and brack	et			Wiper Bla	ade			1.00
- test run					M5 Filter	Kit			1.00
- Shop Suppli	es				198562	Fire 550/80)r23		1.00
					Shop Su	pplies			1.00
					Tire Disp	osal Fee			1.00
	Hou :	urs 19.50		Labor:	1,170.0 0	Parts:	7,308.40	Total:	8,478.40
Workorder: Problem:	1806273 Mount Minzi	Meter: tire	2491			In Date:	06/19/2018	Closed:	06/20/2018
- mount tire									
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1806305 Power Tilt	Meter:	2526			In Date:	06/20/2018	Closed:	06/22/2018
- Slip Tape					Parts Lis	st			Qty
- Install Powe	r tilt				Bucket P	in			1.00
- To Purdy Ln					Aw68 Hy	dro Fluid H	Hydr		20.00
- Shop Suppli	es				Shop Su	pplies			1.00
	Hou :	urs 4.00		Labor:	240.00	Parts:	603.77	Total:	843.77
Workorder: Problem:	1806580 Belt	Meter:	2555			In Date:	06/27/2018	Closed:	07/19/2018
- replace belt	and pulley				Parts Lis	st			Qty
- to purdy and	I military. to e	eoc ditch			Tensione	er Pulley			1.00
- test run					Gasket A	dhesive			1.00
- R&r main at	tachment hos	e on boom			m5 serpe	entine belt			1.00
- grease					Ultra Sup	oreme 238	Moly Grease		20.00
- to mako					Aw68 Hy	dro Fluid H	Hydr		10.00
- Shop Suppli	es				Hose Ma	de Mako			1.00
					Shop Su	pplies			1.00
					Freight C	harge			1.00
					Freight C	harge			1.00
	Hou								

Workorder: 1807543 Problem: hyd leak	Meter:	2620		In Date:	07/24/2018	Closed:	09/14/2018
- Repair grease lines			Parts L	.ist			Qty
- Clean and wash coolers			Drier				1.00
- To Eoc ditch 2xs			A/c Cor	mp 7h15 Em	n 24v Menzi		1.00
- Weld and repair door latcl			Hose M	lade Mako			1.00
assemblies. Repair grease	•	·	Hyd Fil	ter			1.00
 Ac repair/ replace hoses, and recharge 	compressor	, dryer,condenser,	Door H	older			1.00
- Wash Machine			Freon H	He Shop			4.00
- Replace cracked intake he	nse renlace	split intercooler has	Conder	nsor			1.00
- To Maco 4xs	osc, replace	spin intercooler not	Pressu	re Regulato	r		1.00
- Shop Supplies			Tubor H	Hose M5			1.00
опор опррпоз			Moly G	rease 40bl E	Bucket		1.00
			Grease	Pump			1.00
			Hose M	1ade Mako			1.00
			Hose M	1ade Mako			1.00
			Hose M	lade Mako			1.00
			Hose M	lade Mako			1.00
			Ultra S	upreme 238	Moly Grease		60.00
			Washe	r Fluid Cond	entr		3.00
			White N	∕lp Grs Cart			6.00
			3/4 Qui	ck Conn Fe	male		6.00
			3/4 Qui	ck Conn Ma	ale		6.00
			198562	? Tire 550/80)r23		1.00
			Washe	r Fluid Tank			1.00
			Shop S	upplies			1.00
			Tire Dis	sposal Fee			1.00
			Freight	Charge			1.00
			Freight	Charge			2.00
			Freight	Charge			1.00
Hou :	ırs 51.00	Labo	or: 3,060.0 0) Parts:	14,586.48	Total:	17,646.48
Workorder: 1808500 Problem: R&R tire	Meter:	2555		In Date:	08/17/2018	Closed:	08/23/2018
- Replace tire							
Hou :	ırs 0.00	Labo	or: 0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	1809692 Greese/ Joystic	Meter:	2746			In Date:	09/20/2018	Closed:	10/03/2018
- grease					Parts L	ist			Qty
- replace left l	nand joy stick				cover				1.00
- to collins dite	ch 2xs				Clip				4.00
- replace side	door adjust hing	ge and la	tch		Bolt		4.00		
- Shop Suppli	es				Ultra Su	preme 238	Moly Grease		40.00
					Storeag	e Box			1.00
					joystick				1.00
					Shop St	upplies			1.00
					Freight	Charge			1.00
					Freight	Charge			1.00
					Freight	Charge			1.00
					Freight	Charge			1.00
	Hours :	6.50		Labor:	435.50	Parts:	12,231.07	Total:	12,666.57
Workorder: Problem:	1810097 Install RF tire	Meter:	2620			In Date:	09/28/2018	Closed:	
-	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1810603 tire repair	Meter:	2746			In Date:	10/15/2018	Closed:	10/16/2018
- Repair tire									
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: 1810637 Meter: 2838 Problem: Joystick sticking		In Date	: 10/16/2018	Closed:	12/03/2018
- replace joystick		Parts List			Qty
- replace sending unit and connectors		Joy Stick			2.00
- to wabasso & cherokee 2xs. to west gate. 2xs		Fuel Indicator			1.00
- test run		Big G Degreaser	1.00		
- repair grease lines. replace greaser pum assembly	/	rear veiw mirror	2.00		
- pm		Hose Made Mak)		1.00
- replace turbo		lincoln pump ass			1.00
- replace mirror bracket		Lincoln Pump 24			1.00
- to mako 2xs		Non-chlor Brake			6.00
- steam pressure wash		85-140 Gear Oil			20.00
- Shop Supplies		Aw68 Hydro Flui			15.00
Chief Cappiles		15-40 Oil	y a.		14.00
		M5 Filter Kit			1.00
		Wiper Blade			1.00
		198562 Tire 550	80r23		1.00
		16.5 Oz Aero Kro			1.00
		Ultra Supreme 2			10.00
		m5 turbo	oo mony chouse		1.00
		Mirror Holder			1.00
		Hose Made Make)		1.00
		Shop Supplies			1.00
		Tire Disposal Fe	Э		1.00
		Freight Charge			1.00
		Freight Charge			1.00
		Freight Charge			1.00
		Freight Charge			1.00
		Freight Charge			1.00
		Freight Charge			1.00
Hours 78.00 :	Labor:	-	ts: 34,760.06	Total:	39,986.06
Workorder: 1811227 Meter: 2746 Problem: Flat repair		In Date	: 10/31/2018	Closed:	11/01/2018
- Flat repair Hours 0.00	Labor:	0.00 Par	ts: 0.00	Total:	0.00
Workorder: 1812313 Meter: 2926 Problem: controls inop		In Date	: 12/03/2018	Closed:	12/06/2018
- Disasembled joystick and repaired		Parts List			Qty
- Replaced relief valve in power tilt		Cross Port Relief	Valve		1.00
- To Congress & Belv. Rd		Shop Supplies			1.00
- Test run - Shop Supplies					
- Shop Supplies Hours 9.50	Lobor	636.50 Par	ts: 412.20	Total	1 049 70
: :	Lauui.	030.30 Par	io. 412.2U	i Otal:	1,048.70

Workorder: Problem:	1812466 Codes	Meter:	2945			In Date:	12/07/2018	Closed:	12/13/2018
- coolant leak	. replace radiat	or hoses a	and lift cab	to access	Parts Li	st			Qty
	and fl mango				1gal Rtu	Antifreeze			6.00
- to mako	J				•	c Antifeerze	Э		6.00
- test run					Hose Ma	ade Mako			1.00
- Shop Suppli	es				Shop Su	pplies			1.00
		s 11.50		Labor:	770.50		630.99	Total:	1,401.49
Workorder: Problem:	1812871 LF Menzi tire	Meter:	2945			In Date:	12/18/2018	Closed:	12/20/2018
- Lf tire									
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1812949 Blown line	Meter:	2985			In Date:	12/20/2018	Closed:	12/31/2018
- Pulled panel	ls in boom and	replaced	3 hoses		Parts Li	st			Qty
- To Old Oke	echobee 2xs				Hyd Hos	ses Made			1.00
- To Mako					Aw68 Hy	ydro Fluid H	lydr		16.00
- Repair grees	se lines				Shop Su	ıpplies			1.00
- Test run									
- Shop Suppli	es								
	Hour :	s 17.50		Labor:	1,172.5 0	Parts:	987.05	Total:	2,159.55
Workorder: Problem:	1900073 Mount tire	Meter:	2985			In Date:	01/02/2019	Closed:	01/10/2019
- Mount tire									
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1900461 RF leg has hy	Meter: d leak	2995			In Date:	01/11/2019	Closed:	02/01/2019
- Bypass blow	vn line and unlo	ck wheel	to move wl	nile in ditch	Parts Li	st			Qty
- Ski Rd. 2xs					Aw68 Hy	ydro Fluid H	łydr		258.00
- To Mako 4xs	S				Hose Ma	ade Mako			1.00
- Rehose Rs I	leg at shop				Valve St	em 17/8			1.00
- Clean mach		Service		20.00					
- Test run					Big G De	egreaser 1	Gal		2.00
- Shop Suppli	es				Hose Ma	ade Mako			1.00
					30 175 N	Nat Cable T	ie		1.00
					Cable Ti	е			1.00
					Hose Ma	ade Mako			1.00
					Shop Su	ıpplies			1.00

Workorder: Problem:	1900685 RF tire		Meter:	2985			In Date:	01/16/2019	Closed:	01/17/2019
- Rf tire										
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1901115 Hyd leak		Meter:	3031			In Date:	01/30/2019	Closed:	02/08/2019
- Repaired fitt coupler	ing at pow	er tilt.	Replace	d hose a	and quik	Parts L		I. I.		Qty
- To Jog & Tp	3xs to Ha	venwo	ood Ditch				lydro Fluid H lade Mako	iyar		35.00
- To Mako							lade Mako Hose M5			1.00 1.00
- Greese							Connect Fem	a la		9.00
- Pulled code:	s 1031 Sp	n 141	Fmi				Connect Male			9.00
- Shop Suppli	-					Deliver		,		1.00
						•	•	Moly Grease		20.00
							r Fluid Conce	•		2.00
							Tire 550/80			1.00
						Shop S		123		1.00
						-	sposal Fee			1.00
							Charge			1.00
		Hours	12.00		l ahor:	804.00	_	13,039.03	Total·	13,843.03
		: 10ui 5	12.00		Labor.	004.00	rans.	13,039.03	TOtal.	13,043.03
Workorder: Problem:	1901773 Greese		Meter:	3080			In Date:	02/14/2019	Closed:	03/01/2019
- Greese						Parts L	.ist			Qty
- Replace turk	oo intake h	nose				Moly G	rease 40bl B	ucket		1.00
- To Cresthav	en Ditch 3	Bxs				Hose M	lade Mako			1.00
- To Mako						Hose M	lade Mako			1.00
- Tested wirrii	ng for joys	ticks				Ultra Sı	upreme 238	Moly Grease		20.00
- Repaired wi	rring in be	lly of m	nachine			Washei	r Fluid Conce	entr		2.00
- Shop Suppli	es					Shop S	upplies			1.00
		Hours :	17.00		Labor:	1,139.0 0	Parts:	862.77	Total:	2,001.77
Workorder: Problem:	1902051 wiring rep	oair	Meter:	3031			In Date:	02/25/2019	Closed:	02/27/2019
- Menzi repaii	rs									
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1902298 Tire		Meter:	3080			In Date:	03/01/2019	Closed:	03/07/2019
- tire						Parts L	.ist			Qty
- Shop Suppli	es						Tire 550/80	r23		1.00
- 1. — II- II- II-						Shop S				1.00
							sposal Fee			1.00
		Hours	0.00		Labor:		-	4,754.24	Total:	4,754.24

Workorder: Problem:	1902312	Meter:	3080			In Date:	03/01/2019	Closed:	03/05/2019
	i iv uie								
- Rf tire	Houi	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1902564 Blown Hyd lin	Meter:	3139			In Date:	03/07/2019	Closed:	04/04/2019
- Rehose Rr I	eg/ Top off oil				Parts L	.ist			Qty
- Pm					Aw68 F	Hydro Fluid H	Hydr		65.00
- Service finns	al drives				Hose M	lade Mako			1.00
- To Sherwoo	d Forest				Hose M	lade Mako			1.00
- Wash mach	ine				Funnel				1.00
- Replace was	sher res.				Wiper E	Blade			1.00
- Test Run					M5 Filte	er Kit			1.00
- Shop Suppli	es				Non-ch	lor Brake Cli	nr		8.00
					Washe	r Fluid Conc	entr		1.00
					Big G D	Degreaser 1	Gal		2.00
					Napa C	t 15w40			2.00
					Prem B	lue 15w40 1	Gal		3.00
					85-140	Gear Oil Ge	ear		16.00
					Washe	r Fluid Tank			1.00
					Plug				16.00
					Shop S	upplies			1.00
					Freight	Charge			1.00
					Freight	Charge			1.00
	Hour :	rs 47.50		Labor:	3,182.5 0	Parts:	4,927.78	Total:	8,110.28
Workorder: Problem:	1902608 Mount tire	Meter:	3080			In Date:	03/08/2019	Closed:	03/11/2019
- mount tire									
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1902643	Meter:	3080			In Date:	03/07/2019	Closed:	03/11/2019
Problem:	Emergency T	Ire Service	:						
- Tire Service Tire Service	22438 Sw 7th	street,boo	a Raton - E	mergency					
	Hour	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: 1903683 Problem: Greese	Ме	ter:	3237			In Date:	04/04/2019	Closed:	05/28/20)19
- Greese					Parts Li	st				Qty
- Trade out power tilts a	nd replace	e hos	es and relief v	alve	Moly Gre			1.00		
- To Belvedere Eoc Ditc	h 3xs, and	d to o	ld Eoc 2xs		New Pig					2.00
- Add 60 quarts of Hyd.	oil				Cabl/tie					1.00
- Added Pig Mats to leg	for transp	ort			Cross Po			1.00		
- To Mako					Simple C	Green Clea	ner			2.00
- Disasembled Lr leg and	d replaced	d all v	vheel hoses		Non-chlo	or Brake Cli	nr			6.00
- Replaced exstention cy	/l. and cle	aned	oil		M5 Tele	scope Cylir	nder			1.00
- Repaired cracks in par	el on boo	m for	hoses		Ultra Su	preme 238	Moly Grease		(60.00
- Repaired Rf cover bolt	s and thre	eads			Air Fresh	nener				2.00
- Shop Supplies					Hose Ma	ade Mako				1.00
					Aw68 Hy	ydro Fluid H	Hydr		(60.00
					Scissor-	full Metal			1.00	
					Non-chlo	or Brake Cli			4.00	
					Hose Ma	ade Mako			1.00	
					Shop Su	ıpplies				1.00
					Freight (Charge				1.00
					Freight (Charge				1.00
H :	Hours 61.	50		Labor:	4,120.5 0	Parts:	14,726.59	Total:	18,847.0	9
Workorder: 1906008 Problem: Power Til		ter:	3237			In Date:	06/07/2019	Closed:	06/28/20)19
- Replace joy stick					Parts Li	st				Qty
- To Belvedere Ditch					Ultra Su	preme 238	Moly Grease		2	20.00
- To Sunny Lane						Fluid Conc	•			1.00
- To Mako					Hose Ma	ade Mako				1.00
- Replace turbo hoses					Joy Stick	<				1.00
- Shop Supplies					Shop Su					1.00
oner cappings					Freight (1.00
 	Hours 7.5	0		Labor:	502.50	•	7,036.55	Total:	7,539.05	
Workorder: 1906952 Problem: Blades	Ме	ter:	3290			In Date:	07/03/2019	Closed:	07/10/20)19
- Hot work, Torched apa	rt blades	and i	nstalled new		Parts Li	st				Qty
- To Haverhill & Belvede					Menzi B	lade Kit				1.00
- Shop Supplies	•				Shop Su					1.00
	Hours 9.0	0		Labor:	603.00		311.31	Total:	914.31	
Workorder: 1908528 Problem: 5 gal. gre		ter:	3290			In Date:	08/14/2019	Closed:	08/16/20)19
- Greese 5 Gal.					Parts Li	st				Qty
- Shop Supplies						ease 40bl E	Bucket			1.00
55p 3app50					Shop Su					1.00
ŀ	Hours 0.0	0		Labor:			280.86	Total:	280.86	00

Workorder: 1908617 Meter: 3504 Problem: Hose		In Date: 08/16/2019 Clo	sed: 10/23/2019
- Rehose boom		Parts List	Qty
- Repin and bushing bucket and power tilt		Hyd Boom Hose	1.00
- To Summit and to Westgate		Hyd Boom Hose	2.00
- Repair clogged and broken greese lines		Hyd Boom Hose	2.00
- Clean work area		Hyd Boom Hose	2.00
- Test run		Hyd Boom Hose	2.00
- Repair side cover		Hose Made Mako	1.00
- Repair hyd. leak under rotation		Aw68 Hydro Fluid Hydr	36.00
- Shop Supplies		1gal Rtu Antifreeze	6.00
		Non-chlor Brake Clnr	12.00
		Grease Nipple	10.00
		scaper	1.00
		199581 Bushing	4.00
		Bucket Pin	2.00
		Pin	2.00
		Spacer	1.00
		Spacer	2.00
		Arm Brace	2.00
		Bushing	4.00
		Snap Ring	2.00
		Ultra Supreme 238 Moly Grease	10.00
		spacer	1.00
		Pin Clip	2.00
		Shop Supplies	1.00
		Freight Charge	1.00
Hours 68.50 :	Labor:	5,000.5 Parts: 14,923.26 0	Total: 19,923.76

Workorder: Problem:	1910582 PM	Meter:	3559			In Date:	10/15/2019	Closed:	10/28/2019
- pm					Parts Li	st			Qty
- svc final driv	ves .				M5 Filte	r Kit			1.00
- replace 3 lig	ht bulbs				15-40 C	14.00			
- add grease.	repair jack han	dle holde	drill and tap n	iew	Wiper B		1.00		
hardware					85-140	16.00			
- replace bush	nings pins and p	oivot arms	on boom		Non-chlo	or Brake Clr	nr		2.00
- test run					Aw68 H	ydro Fluid H		6.00	
- Shop Suppli	es				Scraper				1.00
					Chuck				1.00
					Adapter				1.00
					24v 886	Bulb			4.00
					Simple (Green Clear	ner		1.00
					Ultra Su	preme 238	Moly Grease		8.00
					Service	/ Parts			1.00
					Shop Su	upplies			1.00
	Hours :	s 34.00		Labor:	2,482.0 0	Parts:	5,373.52	Total:	7,855.52
Workorder: Problem:	1910597 Repairs by Me	Meter: enzi	3290			In Date:	10/15/2019	Closed:	10/17/2019
- Repairs by N	Menzi								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1911160 wont move	Meter:	3559			In Date:	10/28/2019	Closed:	11/01/2019
- Traced out a	and replace con	trol box			Parts Li	st			Qty
- Shop Suppli	-				Service	And Parts			1.00
					Shop Su	upplies			1.00
	Hours :	s 8.00		Labor:	584.00	Parts:	10,198.01	Total:	10,782.01
Workorder: Problem:	1911336 Repairs by Mir	Meter: nzi USA	3559			In Date:	10/31/2019	Closed:	11/05/2019
- Repairs by N	Menzi								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1912262 Pressure Was	Meter: h	3559			In Date:	11/27/2019	Closed:	12/05/2019
- Wash machi	ine				Parts Li	st			Qty
- Shop Suppli	- Shop Supplies				Shop Supplies				1.00
		s 6.00		Labor:	438.00	Parts:	4.00	Total:	442.00

Workorder: Problem:	1912959 check engine li	Meter:	3559			In Date:	12/18/2019	Closed:	12/18/2019
	ngine light By M								
rtopan Git o	Hours :			Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2001719 Swivel leaking	Meter:	3694			In Date:	02/19/2020	Closed:	02/28/2020
- Swap power	· tilt				Parts L	.ist			Qty
- Atlantic and	Military				Ultra S	upreme 238	Moly Grease		1.00
- Rehose Rigl	nt Front leg				Aw68 H	lydro Fluid H	Hydr		12.00
- To Mako					Encore	5gal Bl Buc	ket		2.00
- Repair grees	se lines				Non-ch	lor Brake Cl	nr		2.00
- Shop Suppli	es				Hose M	lade Mako			1.00
					Aw68 H	lydro Fluid H	Hydr		32.00
					Shop S	upplies			1.00
	Hours :	26.00		Labor:	1,898.0 0) Parts:	425.64	Total:	2,323.64
Workorder: Problem:	2002082 Washer Fluid	Meter:	3745			In Date:	02/28/2020	Closed:	04/22/2020
- Washer fluid	I				Parts L	.ist			Qty
- Wash Mach	ine				Washe	r Fluid Conc	entr		2.00
- Rehose boo	m				Aw68 H	lydro Fluid I	Hydr		15.00
- Test run					Wiper E	Blade			1.00
- Pm					M5 Filte	er Kit			1.00
- Replace bel	t and tensioner				Non-ch	lor Brake Cl	nr		12.00
- Exstract dra	ain plugs and re	placed oil			Paint				3.00
- Shop Suppli	es				15-40	Oil			14.00
					85-140	Gear Oil G	ear		16.00
					m5 ser	pentine belt			1.00
					Belt Te	nsioner			1.00
					Shop S	upplies			1.00
	Hours :	30.00		Labor:	2,190.0 0) Parts:	3,922.74	Total:	6,112.74
Workorder: Problem:	2004039 Turbo Hose	Meter:	3770			In Date:	04/22/2020	Closed:	04/28/2020
- Replace bro	ken turbo pipe				Parts L	.ist			Qty
- To 45th 2xs					Hose C	lamp			5.00
- Manual rege- Shop Suppli					Shop S	upplies			1.00
2ab Gabbii	Hours	8.00		Labor:	584.00	Parts:	48.78	Total:	632.78

Workorder: Problem:	2004317 Power tilt		Meter:	3770			In Date:	04/30/2020	Closed:	05/29/2020
- rebuild 2 po	wer tilt unit	s. ins	stall powe	er tilt and	fab tool	Parts Li	st			Qty
- tire						198562	Tire 550/80)r23		1.00
- to carribean	ditch					Power T	ilt Bearing	Kit		4.00
- Shop Suppli	ies					Power T	ilt Seal Kit			4.00
						Non-chlo	r Brake Cl	nr		12.00
						White M	p Grs Cart			2.00
						Px Blue	Threadlock	er		1.00
						Permate	х			1.00
						Air Fresh	nener			2.00
						Washer	Fluid Conc	entr		2.00
						Hose Ma	ade Mako			1.00
						Ultra Su	oreme 238	Moly Grease		20.00
						Shop Su	pplies			1.00
						Tire Disp	osal Fee			1.00
						Freight 0	Charge			1.00
						Freight 0	Charge			1.00
	l :	Hours	46.00		Labor:	3,358.0 0	Parts:	8,386.14	Total:	11,744.14
Workorder: Problem:	2004487 RF Flat		Meter:	3770			In Date:	05/05/2020	Closed:	05/05/2020
- Tire Service	45th - Rf F	Flat								
	l :	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2004858 Mount tire)	Meter:	3770			In Date:	05/13/2020	Closed:	05/13/2020
- Tire Service	He - Mour	nt tire								
	l	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2005543 No Reger	1	Meter:	3914			In Date:	06/03/2020	Closed:	06/16/2020
- Tried to reg	en and got	Menz	zi out as i	t would n	ot regen	Parts Li	st			Qty
- Add hyd. oil	_				J	Aw68 Hy	/dro Fluid H	Hydr		1.00
- To Northlak		abana	Ditch 2x	S		Door Ho		,		1.00
- Replace do						Shop Su				1.00
- Pulled code		18 Fn	ni14			Freight 0				1.00
- Replace turl	•			er		3 / -	J -			
- To Cabana		•	,							
- Shop Suppli	-									
Is Is Is Is Is		Hours	14.00		Labor:	1,022.0 0	Parts:	296.89	Total:	1,318.89

Workorder: Problem:	2006092 Greese	Meter:	3914			In Date:	06/19/2020	Closed:	06/26/2020
- Greese					Parts L		Qty		
- Washer fluid/ Airfresh					Ultra Su	preme 238	Moly Grease		20.00
- Shop Suppli		Bayside Breeze 3 Pack				2.00			
		Washer	Fluid Conc	entr		2.00			
					Shop St	upplies		1.00	
		Hours 0.00		Labor:	0.00	Parts:	156.55	Total:	156.55
Workorder: Problem:	2006171 repair	Meter:	3914			In Date:	06/22/2020	Closed:	
-	ı			Labas	0.00	Danta	0.00	T-1-1	0.00
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2006172 repair by	Meter: Menzi DPF	3914			In Date:	06/22/2020	Closed:	06/24/2020
- Repairs by N	Menzi								
	!	Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2006343 Greese fi	Meter:	3914			In Date:	06/26/2020	Closed:	07/08/2020
- Repair greese lines and fittings					Parts L		Qty		
Palm BeachShop Suppli					Shop Su	upplies			1.00
		Hours 5.00		Labor:	365.00	Parts:	4.00	Total:	369.00
Workorder: Problem:	2006701 Hyd Leak	Meter:	4017			In Date:	07/08/2020	Closed:	07/17/2020
- hyd leak at leg. replace 2 hoses and add oil				Parts List				Qty	
- to plantation ditch 2xs					Aw68 Hydro Fluid Hydr				25.00
- to mako					Hose Made Mako				1.00
- Shop Supplies					Shop Supplies				1.00
]	Hours 13.00		Labor:	949.00	Parts:	240.73	Total:	1,189.73

Workorder: Problem:	2007198 Greese	Meter:	4020			In Date:	07/23/2020	Closed:	08/12/2020		
- fill greaser					Parts Li		Qty				
- replace grease lid					Washer	Fluid Conc	entr		4.00		
rehose leg repair grease linesto outfall ditchto mako					Ultra Su	preme 238	Moly Grease		20.00 1.00		
					Air Fres	•	•				
					Lid Blac	k			1.00		
- Shop Supplies					Aw68 H	60.00					
						ade Mako	•		1.00		
					Hose M	ade Mako			1.00		
					Shop Su	upplies			1.00		
					Freight (1.00		
	Ho :	urs 28.50		Labor:	2,080.5 0	-	1,341.65	Total:	3,422.15		
Workorder: Problem:	2008263 Turbo Hose	Meter:	4020			In Date:	08/18/2020	Closed:	09/09/2020		
- Replaced in	er cooler cou	plers			Parts Li	st			Qty		
- Test run						Hose Made Mako					
- To Mako					5 Gal Bu	3.00					
- To Westgate	e Ditch				Ultra Su	20.00					
- Greese						Shop Supplies					
- Shop Suppli	es				Freight	1.00					
	Ho :	urs 6.00		Labor:	438.00	Parts:	9,183.02	Total:	9,621.02		
Workorder: Problem:	2009062 PM	Meter:	4165			In Date:	09/09/2020	Closed:	09/22/2020		
- pm					Parts Li	st			Qty		
- svc final drives					M5 Filte	1.00					
- no start. batteries failed. replace batteries and hold downs					15-40 C	14.00					
- open belly and clean. top fluid					Wiper B	1.00					
- test run					85-140	16.00					
- Shop Supplies					Battery	2.00					
					•	preme 238	Moly Grease		10.00		
						ydro Fluid H	-		30.00		
						or Brake Cl	•		4.00		
					Shop Su	upplies		1.00			
				Freight (1.00				
	Ho	urs 19.50		Labor:	1,423.5 0	•	3,049.87	Total:	4,473.37		
Workorder: Problem:	2009481 reseal swive	Meter: el by Menzi	4020		<u> </u>	In Date:	09/21/2020	Closed:	09/29/2020		
- Reseal swiv	el										
	Ho :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00		

Workorder: Problem:	2010123 Greeser	Meter:	4165		l	In Date:	10/07/2020	Closed:	10/24/2020)	
- replace greaser						Parts List					
 repair mower grease line to florida mango. to austrailian ditch to mako 2xs remoce charge pipe. replace couplers 					Hose Mad	de Mako				Qty .00	
					10mm nyl	on tube			50.	.00	
					Hose Mad		1.00				
					Shop Supplies					.00	
- Shop Suppl	ies										
	Ho:	urs 9.00		Labor:	657.00	Parts:	435.19	Total:	1,092.19		
Workorder:	2011874	Meter:	4165			In Date:	12/01/2020	Closed:	12/07/2020)	
Problem:	Dist.1 Paul,	Menzi will n	ot start , it	is in Roads y	/ard						
- test run					Parts Lis	t			C	Qty	
- to rds yard 12/1					Shop Supplies					.00	
- Shop Suppl											
	Ho:	urs 1.00		Labor:	73.00	Parts:	4.00	Total:	77.00		
Workorder: Problem:	2012501 Repair Mow	Meter: er	4165			In Date:	12/16/2020	Closed:	02/03/2021		
- Mower deck	Parts Lis	t			C	Qty					
spindle holes			_		3/4 Drill B	1.	.00				
- pull codes fi			2 find dtc li	ist . coolant	7/8 Drill B	it			1.	.00	
- add coolant	stop engine warn ignored					Hose Made Mako					
- test run					mower sp	1.	.00				
- to ditch					Shop Sup	plies			1.	.00	
- Hydraulic lir Couplers.	ne couplers da	amaged and	leaking. R	&r	Freight Cl	narge			1.	.00	
- To Mako 2x											
- Test run											
- Wash mowi	ng deck and o	degrease.									
- Shop Suppl	ies										
	Hor :	urs 48.50		Labor:	3,540.5 0	Parts:	4,485.81	Total:	8,026.31		
Workorder:	2012642	Meter:	4165		1	In Date:	12/18/2020	Closed:			
Problem:	Dist.1 Paul,	machine is	giving a co	de an a alarr	ns it is in t	he roads y	ard				
-	Ho	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00		
	:										
Workorder: Problem:	2103691 Storm Wate	Meter: r, Cody mac	4165 hine has a	rip in the tur		In Date: is at E.O.0	03/31/2021 C Ditch North	Closed: end.	03/31/2021		
- replace inte	rcooler hose i	nearest turb	o with mari	ne exhaust	Parts Lis	t			C	Qty	
nose					Shop Sup	1.	.00				
to and from	New Eoc ditc	h 3/31									
		11 0/0 1									
- Shop Suppl	ies	urs 2.50			182.50	Parts:			186.50		

In Date: 04/02/2021 04/06/2021 Workorder: 2103777 4165 Closed: Meter: Problem: nEED A CASE OF Need a case of grease. Menzi operator Jon will be stopping by this morning Fr 4-2-21 Tha **Parts List** Onsite Fueling, Lube Qty Washer Fluid Concentr 2.00 - Eoc ditch Ultra Supreme 238 Moly Grease - Check Loose pin, and resecure. 20.00 - Shop Supplies **Shop Supplies** 1.00 Labor: 182.50 Hours 2.50 Parts: 148.90 Total: 331.40 2103997 4165 In Date: Workorder: Meter: 04/09/2021 Closed: 04/12/2021 Problem: Storm water Cody, machine needs hyd. fluid location is gun Club Ditch west of Military Trail. - top off hyd oil **Parts List** Qty - to eoc ditch **Shop Supplies** 1.00 - test run - Shop Supplies Hours 2.50 Labor: 182.50 Parts: 4.00 Total: 186.50 Workorder: 2104106 Meter: 4165 In Date: 04/13/2021 Closed: 04/14/2021 Problem: Storm Water, Cody, needs a box of grease - Operator requests grease tubes. **Parts List** Qty - Shop Supplies Ultra Supreme 238 Moly Grease 20.00 **Shop Supplies** 1.00 Hours 0.50 Labor: 36.50 Parts: 145.00 Total: 181.50 2104781 4165 Workorder: Meter: In Date: 04/28/2021 Closed: 05/18/2021 Problem: order key for surplus - Make Duplicate Keys **Parts List** Qty Key 1.00 Freight Charge 1.00 Labor: 0.00 Hours 0.00 Parts: 49.89 Total: 49.89 Workorder: 2104912 Meter: 4165 In Date: 05/03/2021 Closed: 05/03/2021 **Problem:** Transition Prep Charge - Transition Prep Charge

Labor: 146.00

Parts: 0.00

Total: 146.00

Hours 2.00