

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 148503

**Problem:** ADD OIL

Meter Reading: 14 In Date: 12/14/2001	Close Date: 12/18/2001	Labor Hours	Description	Parts	Quantity
- Add Atf		1.50	SHOP SUPPLIES		1.00
- Take To Cmc.			ATFD TRANS FLUID MERCON V		2.00
- Shop Supplies					
<b>Parts Charge:</b> 5.53		<b>Labor Charge:</b> 75.00			

**Workorder:** 149934

**Problem:** CHARGE FOR VEHICLE TAG

Meter Reading: 15 In Date: 11/07/2001	Close Date: 11/07/2001	Labor Hours	Description	Parts	Quantity
- Charge For New Tag			TAG FEE		1.00
<b>Parts Charge:</b> 51.85		<b>Labor Charge:</b> 0.00			

**Workorder:** 150540

**Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0 In Date: 11/21/2001	Close Date: 11/21/2001	Labor Hours	Description	Parts	Quantity
- Pre-Delivery Inspection		11.00			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 550.00			

**Workorder:** 150792

**Problem:** 008 KEYS ISSUED OUT 11/28/01

Meter Reading: 0 In Date: 11/28/2001	Close Date: 11/28/2001	Labor Hours	Description	Parts	Quantity
- 008 Keys Issued Out	11/28/01	1.60	DUPLICATE VEHICLE KEYS		8.00
<b>Parts Charge:</b> 24.00		<b>Labor Charge:</b> 80.00			

**Workorder:** 233403

**Problem:** 002 KEYS ISSUED OUT 01/23/02

Meter Reading: 0 In Date: 01/23/2002	Close Date: 01/23/2002	Labor Hours	Description	Parts	Quantity
- 002 Keys Issued Out	01/23/02	0.40	DUPLICATE VEHICLE KEYS		2.00
<b>Parts Charge:</b> 6.00		<b>Labor Charge:</b> 20.00			

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 233576

**Problem:** FAB NEW HITCH MOUNT

Meter Reading: 328	Labor	Parts	Quantity
In Date: 01/25/2002	Hours	Description	Quantity
- Fab New Dual Hitch Mount.	<b>31.50</b>	T-235 GRAY PRIMER	2.00
- R&R Tail Lights & Trailer Plug-Wiper Back Into The Sys.		T-1 BLACK PAINT GLOSS	3.00
- Welding Supplies		BOLT,1A-3103 3/4"X3-3/4"	2.00
		GREASE NLGI 2	1.00
		1/2X5X20 STEEL FLAT BAR	3.00
		1/2 4X8 SHEET STEEL	14.00
		1/2X2X20 STEEL FLAT BAR	4.00
		5/8X2-1/2X12 CR FLAT BAR	3.00
		3/8X3X20 STEEL ANGLE	3.00
		006063(30 TON) PINTLE HOOK-SWIVEL	1.00
		SHOP SUPPLIES	1.00
		3/16X3X3X20 ANGLE	1.00
<b>Parts Charge:</b>	539.03	<b>Labor Charge:</b>	1,575.00

**Workorder:** 235509

**Problem:** WILL NOT START

Meter Reading: 335	Labor	Parts	Quantity
In Date: 02/27/2002	Hours	Description	Quantity
- Jumpstart & Test Charging Sys; Charge Battery; Rewire Radio	<b>2.50</b>	SHOP SUPPLIES	1.00
- Fleet Mgmt To Wud 2030 And Back			
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	125.00

**Workorder:** 237221

**Problem:** 004 KEYS ISSUED OUT 03/27/02

Meter Reading: 0	Labor	Parts	Quantity
In Date: 03/27/2002	Hours	Description	Quantity
- 004 Keys Issued Out	<b>0.80</b>	DUPLICATE VEHICLE KEYS	4.00
<b>Parts Charge:</b>	12.00	<b>Labor Charge:</b>	40.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 238336                      **Problem:** 006 KEYS ISSUED OUT                      04/11/02

Meter Reading: 0		Labor		Parts	
In Date: 04/11/2002	Close Date: 04/11/2002	Hours	Description		Quantity
- 006 Keys Issued Out	04/11/02	1.20	DUPLICATE VEHICLE KEYS		6.00
	<b>Parts Charge:</b> 18.00	<b>Labor Charge:</b> 60.00			

**Workorder:** 238403                      **Problem:** 005 KEYS ISSUED OUT                      04/11/02

Meter Reading: 0		Labor		Parts	
In Date: 04/11/2002	Close Date: 04/11/2002	Hours	Description		Quantity
- 005 Keys Issued Out	04/11/02	1.00	DUPLICATE VEHICLE KEYS		5.00
	<b>Parts Charge:</b> 15.00	<b>Labor Charge:</b> 50.00			

**Workorder:** 245045                      **Problem:** PM SERVICE

Meter Reading: 610		Labor		Parts	
In Date: 07/31/2002	Close Date: 08/23/2002	Hours	Description		Quantity
- Performance Service		25.50	NB-18 WIPER BLADES 18" ANCO 31-18		2.00
- R&R Wipers.			30055-20 CKT BREAKER 20 AMP		1.00
- Ordered Plug.Repaired Wiring For 6 Prang Plug & Installed New 7 Progn's Plug & Wired.Installed Brake Box & Charge Lead.			S-12-10 10AMP CIRC BRKR		1.00
			4047 BRAKE CONTROLLER (USE 5100)		1.00
			PLUG 5418		1.00
- Removed Fuel From Tank.& Flushed Tanks.			SHOP SUPPLIES		1.00
- Installed Scanner.Performed Sys Performance Test.			15/40 OIL		21.00
- Take To Dealer.			L/F LFP815FN WIX 33118 FUEL FILTER		1.00
- Test Run			L/F LFP3191 FRM PH49A WIX 51791 OIL FILTER		1.00
- Warranty Drive From Gmc			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
- Shop Supplies			CA7139 AIR FILTER LBF LAF1878 WIX 46433		1.00
	<b>Parts Charge:</b> 172.22	<b>Labor Charge:</b> 1,275.00			

**Workorder:** 335479                      **Problem:** 001 KEY ISSUED OUT                      02/28/03

Meter Reading: 0		Labor		Parts	
In Date: 02/28/2003	Close Date: 02/28/2003	Hours	Description		Quantity
- 001 Key Issued Out	02/28/03	0.20	DUPLICATE VEHICLE KEYS		1.00
	<b>Parts Charge:</b> 3.00	<b>Labor Charge:</b> 10.00			

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 342803

**Problem:** PM SERVICE

<b>Meter Reading: 2428</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 06/19/2003</b>	<b>Close Date: 06/27/2003</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm		<b>8.00</b>	1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Test Run			MUD FLAP 24X36 SPLASH GUARD (SPL4-3)	1.00
- Shop Supplies			CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
			L/F LFP3191 FRM PH49A WIX 51791 OIL FILTER	1.00
			15/40 OIL	21.00
			SHOP SUPPLIES	1.00
			L/F LFP815FN WIX 33118 FUEL FILTER	1.00
	<b>Parts Charge: 81.22</b>	<b>Labor Charge: 400.00</b>		

**Workorder:** 350901

**Problem:** REPAIR PTO LEVERS AND MUD FLAP

<b>Meter Reading: 3179</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 10/30/2003</b>	<b>Close Date: 10/31/2003</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Repair Pto Ctrl(Came Apart)Make Bushing		<b>4.30</b>	MUD FLAP 24X36 SPLASH GUARD (SPL4-3)	1.00
Tofit.Reposition Cble @ Pto Bond Out Bracket For Clearance.			SHOP SUPPLIES	1.00
- Rr Mud Flap Missing (Replace)				
- Shop Supplies				
	<b>Parts Charge: 19.44</b>	<b>Labor Charge: 215.00</b>		

**Workorder:** 352960

**Problem:** REPLACE FUEL FILTERS

<b>Meter Reading: 3179</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 12/08/2003</b>	<b>Close Date: 12/22/2003</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service		<b>8.00</b>	L/F LFP3191 FRM PH49A WIX 51791 OIL FILTER	1.00
- Test Run			1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Shop Supplies			NB-18 WIPER BLADES 18" ANCO 31-18	2.00
			SHOP SUPPLIES	1.00
			15/40 OIL	21.00
			L/F LFP815FN WIX 33118 FUEL FILTER	1.00
	<b>Parts Charge: 48.26</b>	<b>Labor Charge: 400.00</b>		

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 434041

**Problem:** STALLING

Meter Reading: 3208	Labor	Parts	
In Date: 01/30/2004	Hours	Description	Quantity
- Install Laptop,Ck For All Codes.Performed Balance Test.Injector Test,Standard Test,Wiggle Test And Check.	<b>8.00</b>	SHOP SUPPLIES	1.00
- Removed Seat Assembly And Repair Locking Mechanism,Reinstalled		15/40 OIL	2.00
- Adjusted Engine Oil Level.		A77313 IGN KEY CASE	1.00
- Rd Tested.			
- Took To Gmc.			
- Fm Gmc			
- Shop Supplies			
<b>Parts Charge:</b> 7.76		<b>Labor Charge:</b> 400.00	

**Workorder:** 439635

**Problem:** ENGINE LOW POWER

Meter Reading: 3255	Labor	Parts	
In Date: 03/30/2004	Hours	Description	Quantity
- Or-Repair/Warranty At Gmc.			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 1,145.11

**Workorder:** 450074

**Problem:** PM SERVICE

Meter Reading: 4031	Labor	Parts	
In Date: 07/07/2004	Hours	Description	Quantity
- Pm Service	<b>10.50</b>	15/40 OIL	21.00
- Steam Wash		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Test Run		CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
- Shop Supplies		10205R MARKER LIGHT 2.5" RED GROTE 45812	2.00
		SHOP SUPPLIES	1.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
<b>Parts Charge:</b> 73.84		<b>Labor Charge:</b> 525.00	

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

Workorder: 536222

Problem: PM SERVICE AND LIST

Meter Reading: 6054	Labor	Parts	
In Date: 02/15/2005	Hours	Description	Quantity
- Pm Service	11.00	15/40 OIL	21.00
- Brake Box And Body Up 3 Switch		CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
- Steamwash		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
- Test Run		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Shop Supplies		61A P/STEERING FLUID	1.00
		AIR FRESHENER	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		SHOP SUPPLIES	1.00
		4047 BRAKE CONTROLLER (USE 5100)	1.00
		B90 SWITCH BODY UP SWITCH	1.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		6Y648 GRAPHITE LUBE (IMPERIAL 6590)	1.00
<b>Parts Charge:</b>	207.79	<b>Labor Charge:</b>	550.00

Workorder: 544377

Problem: REPLACE MUD FLAP

Meter Reading: 6996	Labor	Parts	
In Date: 05/10/2005	Hours	Description	Quantity
- Replace Mud Flap	1.00	MUD FLAP 24X36 SPLASH GUARD (SPL4-3)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	20.93	<b>Labor Charge:</b>	50.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 555583

**Problem:** PM SERVICE

Meter Reading: 8494	Labor	Parts	
In Date: 09/22/2005	Hours	Description	Quantity
- Pm Service	8.00	15/40 OIL	21.00
- Test Run.		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- Shop Supplies		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
		6Y648 GRAPHITE LUBE (IMPERIAL 6590)	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		AIR FRESHENER	1.00
		10205Y MARKER LIGHT 2.5" YELLOW GROTE 45813	2.00
		18410 PINTLE PIN	1.00
		66060 LOCK PIN 3/8"X2-1/2"	1.00
		SHOP SUPPLIES	1.00
		18410 PINTLE PIN	1.00
		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
		CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
<b>Parts Charge:</b>	103.49	<b>Labor Charge:</b>	400.00

**Workorder:** 555819

**Problem:** MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0	Labor	Parts	
In Date: 09/27/2005	Hours	Description	Quantity
- Minor Weld Repair Or Machining.	0.50		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	25.00

**Workorder:** 639648

**Problem:** TARP ASSY

Meter Reading: 10492	Labor	Parts	
In Date: 05/22/2006	Hours	Description	Quantity
- Repair Tarp Assy And Flap	3.00	MUD FLAP 24X30 SPLASH GUARD(SPL66490730)	1.00
- Acle Cap Gasket Replaced		CHAIN 40RIV1	10.00
- Shop Supplies		SHOP SUPPLIES	1.00
		441 CRANK ASSY	1.00
		G2013 BOWASSEMBLY #1344 & #1346 = G2013	1.00
<b>Parts Charge:</b>	443.26	<b>Labor Charge:</b>	25.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

<b>Workorder:</b> 641935		<b>Problem:</b> TIRESOLES OF BROWARD INC			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/06/2006	<b>Close Date:</b> 07/06/2006	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	793.78
<b>Workorder:</b> 641936		<b>Problem:</b> TIRESOLES OF BROWARD INC			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/06/2006	<b>Close Date:</b> 07/06/2006	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	72.00
<b>Workorder:</b> 734834		<b>Problem:</b> TIRESOLES OF BROWARD INC			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/27/2007	<b>Close Date:</b> 02/28/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	288.00
<b>Workorder:</b> 734835		<b>Problem:</b> TIRESOLES OF BROWARD INC			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/23/2007	<b>Close Date:</b> 02/28/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tiresoles Of Broward Inc					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	2,454.53
<b>Workorder:</b> 740082		<b>Problem:</b> 001 KEY ISSUED OUT		06/14/07	
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/14/2007	<b>Close Date:</b> 06/14/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- 001 Key Issued Out					
	06/14/07	<b>0.20</b>	DUPLICATE VEHICLE KEYS		1.00
<b>Parts Charge:</b>	3.00	<b>Labor Charge:</b>	0.00		



1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 742907

**Problem:** CONTROL FOR DUMP BODY AND PM SERVICE

Meter Reading: 14090		Labor	Parts	
In Date: 08/21/2007	Close Date: 11/15/2007	Hours	Description	Quantity
- Pm Service		29.00	15/40 OIL	21.00
- Repair Wiring To Marker Light			CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
- Repl Hyd.Pump @ Control Valve Assy.Manually Bleed			PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
Down Dump Bed & Brought To Shop.R&R 3Xs.Refillsys			1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
And Bleed.			P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
- Replace Belts			NB-18 WIPER BLADES 18" ANCO 31-18	2.00
- 441 And Back			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Test Run			10205Y MARKER LIGHT 2.5" YELLOW GROTE 45813	1.00
- Shop Supplies			AW68 HYDRO FLUID HYDRAULIC OIL 68	40.00
			AW68 HYDRO FLUID HYDRAULIC OIL 68	30.00
			036-6775 W/P BELT GMC/CAT ENGINES	1.00
			09997 BRAKE CLEAN	2.00
			K070855 SERP BELT	1.00
			SHOP SUPPLIES	1.00
	<b>Parts Charge:</b> 277.63	<b>Labor Charge:</b> 60.00	<b>Commercial Charge:</b> 6.36	

**Workorder:** 833917

**Problem:** REPAIR PULL OFF CABLE

Meter Reading: 15150		Labor	Parts	
In Date: 02/08/2008	Close Date: 02/19/2008	Hours	Description	Quantity
- Repair Pull Off Cable For Dump Bed.Parts No Charge.		6.00	4645 TARP 7.5X18 FINISHED SIZE DONOVAN	1.00
- Remove & Replace Tarp.			SHOP SUPPLIES	1.00
- Adjust Pull Cable For Dump Pto Stop.Not Going Up High				
Enough Legthen Cable & Re-Test.				
- Test Run				
- Shop Supplies				
	<b>Parts Charge:</b> 95.75	<b>Labor Charge:</b> 60.00		

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

Workorder: 841565

Problem: PM SERVICE

Meter Reading: 16073 In Date: 07/17/2008	Close Date: 07/30/2008	Labor Hours	Description	Parts	Quantity
- Pm Service		<b>24.00</b>	61A P/STEERING FLUID		2.00
- Transmission Service Drain Sys. Replace Filters Fill & Ck Trans-Ok.			H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)		4.00
			036-6775 W/P BELT GMC/CAT ENGINES		1.00
- P/Steering Service-Drain Fluid-Refill-Test Ck Sys For Leak-None .			K070855 SERP BELT		1.00
			K070855 SERP BELT		-1.00
- Cooling Sys Serv. Drain Cooling Flush			K070735HD SERP BELT		1.00
Sys.W/Water-Refill-Pressure Test Sys-Found Lk From Bottom Hose-Secure Leak-Retest Sys.-Ok.			GROUP 31 STUD BATTERY (ACD 31-900CT)		2.00
			SHOP SUPPLIES		1.00
- Replace Belts-(Remove Harmonic Balancer To Replace The Water Pump Belt.Install All Parts.Tighten To Spec.) Test-Ok.			15/40 OIL		21.00
			CA7139 AIR FILTER LBF LAF1878 WIX 46433		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		19.00
			29526898 TRANS FILTER FRM C9031 WIX 57740XE		1.00
- Repair Hyd Leak-Bleed Air From Cylinder-Tested Ok. (Remove Cylinder Hoses & Reseal & Thread Seal Tape Reinstall & Tighten).			H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)		2.00
			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
			NB-18 WIPER BLADES 18" ANCO 31-18		2.00
- Deflate Tire & Refill W/Nitrogen			P1146G FUEL FILTER LBF LFP815FN WIX 33118		1.00
- Test Drove Vehicle - Ok			PH49A OIL FILTER LBF LFP3191 WIX 51791		1.00
- Remove & Replace Batts. Test Batt Found One Bad-Replace Both Batteries-Retest-Ok.			AIR FRESHENER		1.00
- Shop Supplies					
<b>Parts Charge:</b>		707.00	<b>Labor Charge:</b>		60.00

Workorder: 846148

Problem: 001 KEY ISSUED OUT 10/24/08

Meter Reading: 0 In Date: 10/24/2008	Close Date: 10/24/2008	Labor Hours	Description	Parts	Quantity
- 001 Key Issued Out	10/24/08	<b>0.20</b>	DUPLICATE VEHICLE KEYS		1.00
<b>Parts Charge:</b>		3.00	<b>Labor Charge:</b>		12.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 848685

**Problem:** PM SERVICE AND LIST

<b>Meter Reading:</b> 17656		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/31/2008	<b>Close Date:</b> 01/15/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	<b>9.00</b>	PH49A OIL FILTER LBF LFP3191 WIX 51791		1.00
-	Replace Pass Turn Signal Bulb.		1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
-	Reinstall Tarp Spring.		P1146G FUEL FILTER LBF LFP815FN WIX 33118		1.00
-	Test Run.		CA7139 AIR FILTER LBF LAF1878 WIX 46433		1.00
-	Shop Supplies		1066 WHITE LITHIUM (CRC 05037)		1.00
			AIR FRESHENER		1.00
			SHOP SUPPLIES		1.00
			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
			15/40 OIL		21.00
			NB-18 WIPER BLADES 18" ANCO 31-18		2.00
<b>Parts Charge:</b>		131.78	<b>Labor Charge:</b>	60.00	

**Workorder:** 932559

**Problem:** TIRESOLES OF BROWARD INC

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/06/2009	<b>Close Date:</b> 01/09/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Tiresoles Of Broward Inc				
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 48.00

**Workorder:** 935547

**Problem:** TIRESOLES OF BROWARD INC

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/04/2009	<b>Close Date:</b> 03/24/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Tiresoles Of Broward Inc				
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 66.00

**Workorder:** 941925

**Problem:** Pintel hitch pins

<b>Meter Reading:</b> 19730		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/11/2009	<b>Close Date:</b> 08/11/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pins		18410 PINTLE PIN		13.00
-	Shop Supplies		SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		27.74	<b>Labor Charge:</b>	0.00	

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 941995

**Problem:** pm service and list

Meter Reading: 19881	Labor	Parts	Quantity
In Date: 08/12/2009	Hours	Description	Quantity
- P.M.	<b>23.50</b>	SHOP SUPPLIES	1.00
- Replace Mud Flaps		PINTLE HOOK 6063	1.00
- Replace 30 Ton Hitch		3/16X1-1/2X20 ALUM ANGLE ARCHITECTUAL	2.00
- Repair Glove Box Door		10250R MARKER LIGHT 2.5" RED LED	1.00
- Repair Air Leaks At Dash And Remove Compressor Head		1/4X4X20 ALUM FLAT BAR 6063	3.00
To Find And Repair Leak At Check Valve		18410 PINTLE PIN	1.00
- Repair Rear Lights Bulbs		10700 GROMMET 2.5" MARKER LIGHT	1.00
- Weld Cracks In Bed		MUD FLAP 24X30 SPLASH GUARD(SPL66490730)	2.00
- Test Run		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		BOLT 1A-3103	2.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
		LOCKING NUT 2K-0337	2.00
		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		93745 ADAPTER PLUG PLUG LED MARKER LIGHT	1.00
		15/40 OIL	21.00
		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
	<b>Parts Charge:</b> 487.23	<b>Labor Charge:</b> 1,410.00	

**Workorder:** 1000799

**Problem:** 2 - Key(s) issued

Meter Reading: 19883	Labor	Parts	Quantity
In Date: 01/21/2010	Hours	Description	Quantity
- 2 - Key(S) Issued	<b>0.40</b>	DUPLICATE VEHICLE KEYS	2.00
	<b>Parts Charge:</b> 6.00	<b>Labor Charge:</b> 24.00	

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1001191

**Problem:** lights and check brakes

Meter Reading: 20297	Labor	Parts	
In Date: 02/02/2010	Hours	Description	Quantity
- Replace Left Head Light	1.80	H6054 SEALED BEAM	1.00
- Brake Inspection -Ok-		SHOP SUPPLIES	1.00
- Test Run, Brake Check			
- Shop Supplies			
<b>Parts Charge:</b>	9.03	<b>Labor Charge:</b>	108.00

**Workorder:** 1002050

**Problem:** pm service

Meter Reading: 20349	Labor	Parts	
In Date: 02/26/2010	Hours	Description	Quantity
- Pm Service	10.00	15/40 OIL	21.00
- Test Run		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
- Move Tag To Rear		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- Weld Tag Bracket And Wire Light		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Replace Leaking Air Brake Fitting		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
- Shop Supplies		43022 TAG BRACKET (GROTE)	1.00
		SHOP SUPPLIES	1.00
		26330 TAG LIGHT (TKR LITE)	1.00
<b>Parts Charge:</b>	85.60	<b>Labor Charge:</b>	600.00

**Workorder:** 1007627

**Problem:** repair lights and len

Meter Reading: 20695	Labor	Parts	
In Date: 07/20/2010	Hours	Description	Quantity
- Repair Tail Light	0.50		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	30.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

<b>Workorder:</b> 1010965		<b>Problem:</b> pm service	
<b>Meter Reading:</b> 20911		<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 10/05/2010	<b>Close Date:</b> 10/08/2010	<b>Hours</b>	<b>Description</b>
			<b>Quantity</b>
		<b>11.00</b>	
- Pm Service			53630 TAIL LIGHT LED RIGHT HAND (GROTE) 1.00
- Replace Right Side Tail Light			P1146G FUEL FILTER LBF LFP815FN WIX 33118 1.00
- Add Nitrogen To All Tires			USED FIREX REFURBED FIRE EXTINGUISHERS 1.00
- Road Test			PH49A OIL FILTER LBF LFP3191 WIX 51791 1.00
- Shop Supplies			1R0751 FUEL FILTER FRM P8264 WIX 33626 1.00
			SHOP SUPPLIES 1.00
			15/40 OIL 21.00
			NB-18 WIPER BLADES 18" ANCO 31-18 2.00
<b>Parts Charge:</b>	174.42	<b>Labor Charge:</b>	660.00
<b>Workorder:</b> 1013138		<b>Problem:</b> Air leak	
<b>Meter Reading:</b> 20980		<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 11/29/2010	<b>Close Date:</b> 12/03/2010	<b>Hours</b>	<b>Description</b>
			<b>Quantity</b>
		<b>5.50</b>	
- Replace Pp1 Valve , Park Switch And Low Pressure Switch			PARK BRAKE SWITCH (2 PRONG) 1.00
			06133 3M ELECTRIC TAPE STOCK #832260101 1.00
- Fm To Crock			PARK BRAKE VALVE 1.00
- To Shop For Parts			SHOP SUPPLIES 1.00
- Shop Supplies			56521 THREAD SEALANT HI TEMP THREAD SEALANT 1.00
			19210986 SWITCH LOW AIR PRESS 3 PRONG 1.00
<b>Parts Charge:</b>	242.33	<b>Labor Charge:</b>	330.00
<b>Workorder:</b> 1102993		<b>Problem:</b> Flat Tire	
<b>Meter Reading:</b> 21159		<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 03/21/2011	<b>Close Date:</b> 03/23/2011	<b>Hours</b>	<b>Description</b>
			<b>Quantity</b>
- Repair Flat Tire Boulevard			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	71.10

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1104834

**Problem:** No Start

<b>Meter Reading:</b> 21321	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/05/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Jump Start And Replace Batteries	<b>4.00</b>	SHOP SUPPLIES	1.00
- Crock 2Xs		GROUP 31 STUD BATTERY (ACD 31-900CT)	2.00
- Shop Supplies			
<b>Parts Charge:</b>	277.22	<b>Labor Charge:</b>	240.00

**Workorder:** 1104952

**Problem:** pm service check ac

<b>Meter Reading:</b> 21330	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/10/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P.M. Service	<b>16.00</b>	CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
- Repair Tarp		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- Repair Bed Cylinder Leak / R&R Pull Valve Cable And Knob		SHOP SUPPLIES	1.00
- Repair A/C Found No Leaks		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
- Test Drive		15/40 OIL	21.00
- Shop Supplies		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
		AIR FRESHENER	1.00
<b>Parts Charge:</b>	104.77	<b>Labor Charge:</b>	960.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1107262

**Problem:** Belts

Meter Reading: 21567 In Date: 07/11/2011	Close Date: 07/15/2011	Labor Hours	Description	Parts	Quantity
- Replace Belts And Tensioner		<b>9.00</b>	A/C OIL		1.00
- Replace Compressor,Dryer,Orfice Tube,Accumulator ,High And Lower Switch Evac And Recharge			A/C COMPRESSOR		1.00
			7E-3999 TENSIONER BELT		1.00
- Test Run			SERPETINE BELT		1.00
- Shop Supplies			SWITCH		1.00
			ORFICE TUBE		1.00
			A/C DRYER		1.00
			ACCUMULATOR		1.00
			036-6775 W/P BELT GMC/CAT ENGINES		1.00
			R134A REFRIGERANT		4.00
			SWITCH		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 1,378.44		<b>Labor Charge:</b> 540.00			

**Workorder:** 1107267

**Problem:** Fan Belt Issues

Meter Reading: 21487 In Date: 07/08/2011	Close Date: 07/11/2011	Labor Hours	Description	Parts	Quantity
- From: 8100 Forest Hill Blvd/C-Rock To: He Shop					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 174.00	

**Workorder:** 1110656

**Problem:** air leak at dash

Meter Reading: 22061 In Date: 10/05/2011	Close Date: 10/12/2011	Labor Hours	Description	Parts	Quantity
- R&R Cluster To Repair Air Leak		<b>3.50</b>	SHOP SUPPLIES		1.00
- To Mako Hose					
- Shop Supplies					
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 210.00		<b>Commercial Charge:</b> 16.78	



1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

Workorder: 1111479

Problem: P.M.

Meter Reading: 22063	Labor	Parts	
In Date: 10/28/2011	Hours	Description	Quantity
- P.M.	13.50	PINTLE PIN	2.00
- Remove Bed Pins To Take Grease Install Safety Pin		SHOP SUPPLIES	1.00
- Repair Hitch Safety Locks		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Add Oil		15/40 OIL	21.00
- Replace Dash Switch		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC	5.00
		3006875 PIN ASSEMBLY (BUYERS)	1.00
		B90 SWITCH BODY UP SWITCH	1.00
		P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		18410 PINTLE PIN	1.00
<b>Parts Charge:</b>	171.50	<b>Labor Charge:</b>	810.00

Workorder: 1205700

Problem: pm service

Meter Reading: 22458	Labor	Parts	
In Date: 06/15/2012	Hours	Description	Quantity
- Pm Service	9.50	P1146G FUEL FILTER LBF LFP815FN WIX 33118	1.00
- Replace Safety Chain On Both Trailer Hitches		CA7139 AIR FILTER LBF LAF1878 WIX 46433	1.00
- Replace Tag Light Assy.		NB-18 WIPER BLADES 18" ANCO 31-18	2.00
- Test Drive		SHOP SUPPLIES	1.00
- Shop Supplies		26330 TAG LIGHT (TKR LITE)	1.00
		18410 PINTLE PIN	1.00
		3006875 PIN ASSEMBLY (BUYERS)	1.00
		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
		15/40 OIL	21.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
<b>Parts Charge:</b>	153.60	<b>Labor Charge:</b>	570.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1208513

**Problem:** Tarp

<b>Meter Reading: 22879</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 09/07/2012</b>	<b>Close Date: 09/20/2012</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Replace Complete Tarp Assy.	<b>4.50</b>	COMPLETE TARP ASSY	1.00
-	Replace Two Tail Light Assy.		TARP	1.00
-	Shop Supplies		SHOP SUPPLIES	1.00
			53640 TAIL LIGHT LED LEFT HAND (GROTE)	1.00
			53630 TAIL LIGHT LED RIGHT HAND (GROTE)	1.00
<b>Parts Charge:</b> 1,104.92		<b>Labor Charge:</b> 270.00		

**Workorder:** 1300274

**Problem:** pm service

<b>Meter Reading: 23209</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 01/08/2013</b>	<b>Close Date: 01/22/2013</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	P.M.	<b>8.50</b>	P1146G FUEL FILTER LB	1.00
-	Repair Lights		SHOP SUPPLIES	1.00
-	Test Drive		FUEL FILTER 1R0751	1.00
-	Shop Supplies		15-40 OIL	21.00
			PH49A OIL FILTER LBF	1.00
			WIPER BLADE	2.00
<b>Parts Charge:</b> 106.26		<b>Labor Charge:</b> 510.00		

**Workorder:** 1300617

**Problem:** boulevard replace front tires

<b>Meter Reading: 22963</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 01/16/2013</b>	<b>Close Date: 01/17/2013</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Replace Front Tires			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 1,612.00

**Workorder:** 1306634

**Problem:** Dead Battery

<b>Meter Reading: 23703</b>		<b>Labor</b>	<b>Parts</b>	
<b>In Date: 07/02/2013</b>	<b>Close Date: 07/09/2013</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	To Crock 2Xs	<b>4.00</b>	GROUP 31 STUD	2.00
-	Try To Jumpstart, Replaced Batteries		SHOP SUPPLIES	1.00
-	Shop Supplies			
<b>Parts Charge:</b> 304.76		<b>Labor Charge:</b> 240.00		

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1405632

**Problem:** Tailgate

Meter Reading: 24834	Labor	Parts	Quantity
In Date: 06/06/2014	Hours	Description	Quantity
- Pm	<b>38.50</b>	BODY UP SWITCH	1.00
- Replace Tag Light And Fabricate Sheild To Protect		STEERING COLUNM	1.00
- Replace Air Drier		15-40 OIL	21.00
- Replace Tailgate Control Canister And Adjust		NAPAGOLD AIR FILTER	1.00
- Steering Column Broken. Replace Column And Accessories		LICENSE LAMP	1.00
- Replace Blower Motor		NAPAGOLD FUEL FILTER	1.00
- Replace Body Upswitch		LED M C LAMP	1.00
- Replace Marker And Harness		GROMMET	1.00
- Unable To Dump Bed. Force Entry To Release Tailgate To Roebuck And Jog		BLOWER MOTOR	1.00
- Test Run		LED M C ADAPER PLUG	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		NAPAGOLD FUEL FILTER	1.00
		CARTRIDGE AD9	1.00
		VINYL ELECTRICAL TAPE	1.00
		SPRING BRAKE-MAXI	1.00
		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
		WIPER BLADE	2.00
<b>Parts Charge:</b>	2,417.99	<b>Labor Charge:</b>	2,310.00

**Workorder:** 1408406

**Problem:** Lights

Meter Reading: 25295	Labor	Parts	Quantity
In Date: 08/22/2014	Hours	Description	Quantity
- Rr Turn Signal Inop. Found Open In Turn Signal Circuit At Steering Column Connector. Repair Connector And Test	<b>3.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	180.00

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1504635

**Problem:** wont run

<b>Meter Reading:</b> 26167	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/06/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Replace Fuel Filters And Bleed System	<b>4.50</b>	NAPAGOLD FUEL FILTER	1.00
- To Croc		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	14.85	<b>Labor Charge:</b>	270.00

**Workorder:** 1504709

**Problem:** replace four rear recaps

<b>Meter Reading:</b> 26167	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/08/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- 4 Tires		11R225RC TIRE RECAPPED	4.00
- Shop Supplies		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	740.44	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	226.40

**Workorder:** 1606450

**Problem:** Tires

<b>Meter Reading:</b> 27320	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 06/24/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Tires			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	1,988.80

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

**Workorder:** 1606500

**Problem:** pintle pin/trailer plug

Meter Reading: 27400	Labor	Parts		
In Date: 06/27/2016	Hours	Description	Quantity	
- Pm	<b>13.00</b>	NAPAGOLD FUEL FILTER	1.00	
- R&R Trailer Plug		18" wiper blades	2.00	
- Replace Pindle Pin		USED FIRE X REFURBISHED	1.00	
- Replace Drive Belts		NAPAGOLD AIR FILTER	1.00	
- R&R Tag Light Assembly		PINTLE PIN W/CLIP	1.00	
- Road Test		DRIVE BELT	1.00	
- Shop Supplies		belt	1.00	
		FAB/LOOM	1.00	
		LICENSE LAMP	1.00	
		LICENSE PLATE BRKT	1.00	
		3006875 PIN ASSEMBLY	1.00	
		trailer plug	1.00	
		NAPAGOLD OIL FILTER	1.00	
		WASHER FLUID CONCENTR	1.00	
		15-40 OIL	21.00	
		DRY PTFE LUBE	1.00	
		NAPAGOLD FUEL FILTER	1.00	
		SHOP SUPPLIES	1.00	
	<b>Parts Charge:</b> 260.23	<b>Labor Charge:</b> 780.00		

**Workorder:** 1610451

**Problem:** LFIO tires

Meter Reading: 27487	Labor	Parts		
In Date: 10/11/2016	Hours	Description	Quantity	
- Lfio Tires				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 968.62	

**Workorder:** 1612719

**Problem:** Transition Prep Charge

Meter Reading: 27750	Labor	Parts		
In Date: 12/13/2016	Hours	Description	Quantity	
- Transition Prep Charge	<b>2.00</b>			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00		

1/30/2017  
4:16:02PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10133045 2002 GMC C8500 Dump Truck, Tandem, 12 Yard

Total Parts Charges: **11,144.11**

Total Labor Charges: **18,154.00**

Total Comm. Charges: **9,931.48**