

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021 System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code	Cause-Reason
PV1401	1100	INTERIOR CLEAN			4	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		SCHEDULED SERVICE
1912438	1	07/07/2019	668	interior clean		
1906878	1	04/11/2019	658	INTERIOR CLEAN---COMPLETED		OPERATOR COMPLAINT
1900611	1	01/11/2019	835	INTERIOR CLEAN----COMPLETED		SCHEDULED SERVICE
1911547	1	06/25/2019	865	INTERIOR CLEAN---COMPLETED		SCHEDULED SERVICE
PV1401	1204	FAN MOTOR REPL			1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		OPERATOR COMPLAINT
1912527	4	07/15/2019	849	REPLCD RADIATOR FAN		
PV1401	1209	COOLING SYS PROBES/SENSOR			1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		OPERATOR COMPLAINT
1814766	6	11/28/2018	823	R/R COOLANT SENSOR		
PV1401	1300	AIR COND\HEATING SYSTEM			8	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		OPERATOR COMPLAINT
1913013	7	10/29/2019	809	RECOVER FREON		
1913013	8	10/29/2019	809	VAcuum a/c system		OPERATOR COMPLAINT
1913013	9	10/29/2019	809	RECHARGED A/C SYSTEM 2.53 POUNDS OF FREON		OPERATOR COMPLAINT
1913013	11	10/29/2019	809	Ran a/c for 2.50 hours a/c is cold -ok the time		OPERATOR COMPLAINT
2119758	2	08/03/2021	833	RECOVER REFRIGERANT		OPERATOR COMPLAINT
2119758	3	08/03/2021	833	VACUM SYSTEM		OPERATOR COMPLAINT
2119758	4	08/03/2021	833	RECHARGE A/C A/C WITH CORRECT PRESSURES		OPERATOR COMPLAINT
2119758	5	08/03/2021	833	REPAIR VEHICLE DOOR		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: 1100 to 9700

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	1301	TROUBLESHOOT AC SYSTEM	Total Line Count for System Code 1301 :		14
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2119758	1	08/03/2021	833	INSTALL A/C GUAGES-CK PRESSURES - SYSTEM OVERFILLEED	OPERATOR COMPLAINT
1913013	1	10/29/2019	849	T/S A/C SYSTEM RECOVERED FREON AND REFILLED -NEEDS FURTHER DIAG	OPERATOR COMPLAINT
1913013	4	10/29/2019	809	T/S A/C SYSTEM A/C COMPRESSOR I S DEFECTIVE NEEDS A/C COMPRESSOR EXPANSION VALVE A	OPERATOR COMPLAINT
1911648	1	07/01/2019	783	T/S A/C SYSTEM - REMOVED CABIN FILER /CLOGGED PRESSURES TOO HIGH -WIP	OPERATOR COMPLAINT
1911648	2	07/01/2019	783	A/C 134 NA MACHINE ADJ STYARTED T/S A/C NOTICED BIG LEAK	OPERATOR COMPLAINT
1807984	1	05/01/2018	783	TROUBLESHOOT AC SYSTEM---NEEDS BLOWER MOTOR-POO (PART ON ORDER)	OPERATOR COMPLAINT
2015573	2	08/17/2020	853	TROUBLESHOOT AC SYSTEM--NEEDS COOLING FAN & MODULE--ONLY WORKING @LOW SPEED	NORMAL WEAR
2015573	4	08/17/2020	833	RE-CIRCULATIONG ACTUATOR NEEDS T/B REPLC--WONT NORMALIZE	OPERATOR COMPLAINT
1912527	1	07/15/2019	849	TROUBLESHOOT AC SYSTEM---NEED TO REPLC FRONT/REAR EXPANSION VALVE	OPERATOR COMPLAINT
1814766	7	11/28/2018	823	TROUBLESHOOT AC---has electrical issue--FAN WORKING @LOW SPEED--NEEDS 2 COOLANT FAN--	OPERATOR COMPLAINT
1814766	1	11/28/2018	746	TROUBLESHOOT AC SYSTEM---CK SYSTEM	OPERATOR COMPLAINT
1814766	14	11/28/2018	783	RECOVER, VAC, RECHATGE--PRESSURE HIGH--NEED TO REPLC FAN	OPERATOR COMPLAINT
1814766	15	11/28/2018	783	VAN HAS A RECALL#r62--FREE REPAIR	OPERATOR COMPLAINT
1814355	1	07/10/2018	783	TROUBLESHOOT AC SYSTEM--DRIVER SAID ITS FINE	OPERATOR COMPLAINT
PV1401	1303	AC COMPRESSOR REPL	Total Line Count for System Code 1303 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1913013	5	10/29/2019	809	RR A/C COMPRESSOR ADD OIL TO A/C COMPRESSOR	OPERATOR COMPLAINT
PV1401	1307	BLOWER MOTOR REPL	Total Line Count for System Code 1307 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1807984	6	05/01/2018	783	installed fan motor	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: **PV1401** to **PV1401**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	1309	A/C LINES/HOSES REPAIR	Total Line Count for System Code 1309 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1911648	6	07/01/2019	783	RECLAIM AND RECHARGE CHECK FFOR LEAKS -NOT BLOWING COOL	
PV1401	1313	A/C ELEC.COMPONENTS REPAI	Total Line Count for System Code 1313 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>NORMAL WEAR</u>
2015573	3	08/17/2020	853	REPLCD FAM SPEED RESISTOR & PROGRAM FAN CONTROL	
PV1401	1314	A/C ELEC COMPONENTS REPL.	Total Line Count for System Code 1314 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1814766	9	11/28/2018	823	INSTALL (2) RELAY & (1) FAN RESISTOR	
1814766	5	11/28/2018	746	CK AC SYTEM--COOLANT TEMP SENSOR ON ORDER	<u>OPERATOR COMPLAINT</u>
PV1401	1315	EXPANSION VALVE REPL	Total Line Count for System Code 1315 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1912527	3	07/15/2019	849	INSTALLED AC DRY ER & EXPANSION VALVE	
PV1401	1316	A/C DRIER REPL	Total Line Count for System Code 1316 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1913013	6	10/29/2019	809	RR A/C DRIER	
PV1401	1318	A/C SYSTEM RE-CHARGE	Total Line Count for System Code 1318 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1814766	12	11/28/2018	823	AC SYSTEM RECHARGE	
PV1401	1329	DRIVER BOOSTER FAN REPAIR	Total Line Count for System Code 1329 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1807984	10	05/01/2018	783	RESET AC ---BY DEFAULTING OFF SETTINGS & DISCONNECT BATTERY	
PV1401	1334	A/C SYSTEM EVACUATION	Total Line Count for System Code 1334 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1814766	10	11/28/2018	823	EVACUATE SYSTEM	
PV1401	1335	A/C SYSTEM VACUUM	Total Line Count for System Code 1335 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1814766	11	11/28/2018	823	VACUUM AC SYSTEM	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021 System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	1400	ELECTRICAL SYSTEM	Total Line Count for System Code 1400 :		5
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1702486	7	03/27/2017	746	BATTERY ON ORDER--CHARGE BATTERY	NORMAL WEAR
2113898	2	06/06/2021	833	AFTER CHARGING, VEHICLE STARTED	OPERATOR COMPLAINT
1601655	2	02/05/2016	823	repair wires-repair/secure trim molds	OPERATOR COMPLAINT
1912480	1	07/09/2019	849	STROBE LIGHTS NOT WORKING-CKD FUSE/WIRES--FOUND (1)BLOWN FUSE AND (1)MISSING FUSE	SCHEDULED SERVICE
1508723	3	07/14/2015	751	CHANGE BATTERY-NEEDS BATTERY TERMINAL-POO	OPERATOR COMPLAINT
PV1401	1401	TROUBLESHOOT ELECTRICAL S	Total Line Count for System Code 1401 :		11
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1508723	2	07/14/2015	751	TROUBLESHOOT ELECTRICAL	OPERATOR COMPLAINT
1508723	6	07/14/2015	746	REPLC BATTERY CONNECTOR	OPERATOR COMPLAINT
2001413	2	05/01/2020	809	t/s electrical	OPERATOR COMPLAINT
2003848	1	03/09/2020	849	TROUBLESHOOT ELECTRICALS----BATTERY DEAD--JUMP START--CHARGE BATTERY	OPERATOR COMPLAINT
1806649	1	04/06/2018	783	TROUBLESHOOT ELECTRICALS----TRACED TO BAD WIRING @RELAY BOX--FOUND (2) BLOWN FUSE	OPERATOR COMPLAINT
1601655	1	02/05/2016	823	TROUBLESHOOT ELECTRICALS-FOR STROKE LIGHT	OPERATOR COMPLAINT
1807984	4	05/01/2018	783	TROUBLESHOOT ---NEEDS TO BEL LOOKED AT BY ESS	OPERATOR COMPLAINT
1912120	1	07/02/2019	783	T/S ELECTRICAL -CHECKED FUSES -GOOD	OPERATOR COMPLAINT
1814766	18	11/28/2018	783	CKD FOR BATTERY DRAIN--OK	OPERATOR COMPLAINT
1814766	3	11/28/2018	746	TROUBLESHOOT AC --CK SYSTEM--POO---WIP..	OPERATOR COMPLAINT
1802580	5	03/12/2018	795	TROUBLESHOOT ELECTRICAL SYSTEM--BATTERY BAD--CHARGING SYS OK	SCHEDULED SERVICE
PV1401	1403	ALTERNATOR BELT REPL	Total Line Count for System Code 1403 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1508723	7	07/14/2015	770	REPLC BLOWN FUSE, CHARGED BATTERIES	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: **PV1401** to **PV1401**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	1407	BATTERIES CHECK	Total Line Count for System Code 1407 :		5
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1702486	4	03/27/2017	823	CHARGING BATTERY--CK CHARGING SYSTEM--RECHARGE OVERNIGHT	OPERATOR COMPLAINT
1702486	4	03/27/2017	746	CHARGING BATTERY--CK CHARGING SYSTEM--RECHARGE OVERNIGHT	OPERATOR COMPLAINT
1612180	2	09/03/2016	746	BATTERY CHARGE	OPERATOR COMPLAINT
1814766	21	11/28/2018	783	BAD BATTERY---POO	OPERATOR COMPLAINT
1702486	8	03/27/2017	798	BATTERY CHECK	NORMAL WEAR
PV1401	1408	BATTERIES REPLACE	Total Line Count for System Code 1408 :		7
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1814766	22	11/28/2018	783	INSTALLED NEW BATTERY	OPERATOR COMPLAINT
1921161	2	11/14/2019	756	REPLCD BATTERY & TEST CHARGING SYSTEM	NORMAL WEAR
1612180	4	09/03/2016	746	BATTERY REPLACED -NOT IN STOCK ON ORDER	OPERATOR COMPLAINT
1612180	5	09/03/2016	679	R/R BATTERY -TEST OK	OPERATOR COMPLAINT
1802580	6	03/12/2018	796	R/R BATTERY--TESTED CHARGING SYS--OK	SCHEDULED SERVICE
1702486	9	03/27/2017	798	R/R BATTERY CHECK -CHARGING SYSTEM--OK	NORMAL WEAR
1508723	4	07/14/2015	746	REPLC BATTERY	OPERATOR COMPLAINT
PV1401	1409	EXTERIOR LIGHTING	Total Line Count for System Code 1409 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2001413	1	05/01/2020	809	EXTERIOR LIGHTING	OPERATOR COMPLAINT
1907273	1	04/18/2019	753	EXTERIOR LIGHTING RR LEFT SIDE SIGNAL LIGHT	SCHEDULED SERVICE
2126168	2	10/14/2021	833	R&R L/FRONT BLINKER BULB	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: **PV1401** to **PV1401**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	1413	ELEC.SYS.SWITCHES-BREAKER	Total Line Count for System Code 1413 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1913013	2	10/29/2019	849	DRIVERS WINDOW SWICH IS BAD -NEEDS NEW MASTER WINDOW SWICH	OPERATOR COMPLAINT
1913013	10	10/29/2019	809	rr driver switch control	OPERATOR COMPLAINT
1701846	1	02/03/2017	796	ELEC.SWITCHES--BREAKER--SWITCHED RELAY--NOT THE PROBLEM--FOUND FUSE BLOWN FOR CIK	OPERATOR COMPLAINT
PV1401	1417	WIRING HARNESSES	Total Line Count for System Code 1417 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1912120	2	07/02/2019	753	RR FUSES -CLEANED AND ELECTRIC GREASE SOCKETS	OPERATOR COMPLAINT
1807984	9	05/01/2018	783	REPLCD DRIVER SEAT & COMPUTER PLATFORM WIRING & MOUNT	OPERATOR COMPLAINT
1806649	2	04/06/2018	783	REPAIRED HARNESS, FUSES--REPLC BAD BATTERY & TERMINAL CLAMPS	OPERATOR COMPLAINT
PV1401	1425	CANCEIVER REPAIR/REPLACE	Total Line Count for System Code 1425 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1416122	1	11/30/2014	751	CANCEIVER REPAIR /REPLACE	SCHEDULED SERVICE
1416122	1	11/30/2014	799	CANCEIVER REPAIR /REPLACE	SCHEDULED SERVICE
PV1401	2300	SUSPENSION SYSTEM	Total Line Count for System Code 2300 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2107125	1	03/31/2021	833	REPLACED TRANS	OPERATOR COMPLAINT
PV1401	2307	TORQUE RODS REPL	Total Line Count for System Code 2307 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1814766	19	11/28/2018	783	VAN SWAYS @HIGH SPEED--FOUND BROKEN SWAY BAR BRACKET @REAR	OPERATOR COMPLAINT
PV1401	2310	RADIUS RODS REPLACE	Total Line Count for System Code 2310 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1814766	20	11/28/2018	783	INSTALLED REAR AXLE BRACKET	OPERATOR COMPLAINT
PV1401	2500	BODY	Total Line Count for System Code 2500 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1900362	6	01/10/2019	746	ENGINE COVER ASSY OUTSIDE, SIDE PASSENGERS	SCHEDULED SERVICE
2126168	3	10/14/2021	833	R&R W/BLADES	OPERATOR COMPLAINT
1709018	1	05/25/2017	746	BODY -FUSE BOX BODY REPLACED	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: **PV1401** to **PV1401**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PV1401	2505	WIPERS				3		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>OPERATOR COMPLAINT</u>
2008261	1	05/11/2020	800	WIPRS RR WIPER BLADES				
1910905	2	06/13/2019	746	FRONT WIPER BLADES REPLCD				SCHEDULED SERVICE
1721530	2	11/30/2017	746	REPLCD WIPER BLADES				SCHEDULED SERVICE
PV1401	2510	MIRRORS				1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>OPERATOR COMPLAINT</u>
1507208	1	05/11/2015	731	MIRRORS-				
PV1401	2513	INTERIOR PANELS				1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1900362	7	01/10/2019	746	REPAIR INSIDE DRIVER PANEL BOTTOM				
PV1401	2600	BRAKES				1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1802580	3	03/12/2018	746	ADDED BRAKE FLUID				
PV1401	2603	FRONT RELINE				1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1900362	5	01/10/2019	746	REPLCD FRONT BRAKE PADS & ROTORS				
PV1401	2700	AIR SYSTEM				1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1616894	2	12/02/2016	746	REPLC AIR FILTER				
PV1401	2800	ENGINE				6		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>OPERATOR COMPLAINT</u>
2021247	1	10/26/2020	849	ENGINE---CHARGED BATTERY---NO ISSUES				
2009303	1	05/26/2020	849	ENGINE--RAN VAN --NO FUME SMELL--NO EXH LEAK-NPF				OPERATOR COMPLAINT
1707911	2	05/10/2017	619	WIP-NO OIL IN FILTER PART ON ORDER				SCHEDULED SERVICE
2126168	4	10/14/2021	833	SCAN FOR CODES-WORN CAMSHAFT				OPERATOR COMPLAINT
1913013	3	10/29/2019	809	BATTERY IS DEAD JUMP START VEHICLE				OPERATOR COMPLAINT
1810314	4	06/06/2018	746	RIGHT FRONT LIGHT REPALCE				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021 System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	2801	TROUBLESHOOT ENGINE	Total Line Count for System Code 2801 :		6
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1900008	1	01/09/2019	783	TROUBLESHOOT ENGINE----CK CODES--NONE---REMVD OIL PAN---WIP...	OPERATOR COMPLAINT
1900008	2	01/09/2019	783	NEEDS ROCKER ROLLERS ORDERED	OPERATOR COMPLAINT
1701646	1	01/31/2017	679	TROUBLESHOOT ENGINE---CODE P0520--ENGINE OIL PRESSURE--OIL LEVEL LOW--REFILL TO PROF	OPERATOR COMPLAINT
1911648	3	07/01/2019	783	OIL LEAK COMING FROM DRAIN PLUG NEEDS NEW PLUG AND OIL PAN	OPERATOR COMPLAINT
1807984	2	05/01/2018	783	NEEDS (3) ENGINE MOUNTS--POO	OPERATOR COMPLAINT
1702486	2	03/27/2017	823	TROUBLESHOOT ENGINE--BIG OIL LEAK--CLASS 3 FROM REAR MAIN SEAL--CK FRO WARRANTY---AC	OPERATOR COMPLAINT
PV1401	2803	NO START	Total Line Count for System Code 2803 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1508723	1	07/14/2015	746	NO START-CKD START SYSTEM-NEEDS NEW BATTERY	OPERATOR COMPLAINT
1612180	1	09/03/2016	746	NO START - S=CHECK START SYSTEM	OPERATOR COMPLAINT
1921161	1	11/14/2019	849	NO START--CK BATTERY SYSTEM--ALT GOOD-BATTERY DEAD--NEWS BATTERY	OPERATOR COMPLAINT
2113898	1	06/06/2021	833	NO START--CHARGE BATTERIES FOR 1/2 HOUR	OPERATOR COMPLAINT
PV1401	2810	AIR FILTER REPL	Total Line Count for System Code 2810 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1814766	17	11/28/2018	783	R/R CABIN FILTER	OPERATOR COMPLAINT
1810314	3	06/06/2018	746	A/R FILTER REPLACE	SCHEDULED SERVICE
1807984	3	05/01/2018	783	NEED CABIN FILTER---POO	OPERATOR COMPLAINT
1807984	5	05/01/2018	783	INSTALLED CABIN FILTER	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: **PV1401** to **PV1401**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	2813	ENGINE OIL LEAK	Total Line Count for System Code 2813 :		5
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1911648	4	07/01/2019	783	EN OIL PAN RR /OIL PAN	OPERATOR COMPLAINT
1702486	5	03/27/2017	823	OIL LEAK DIAGNOSTIC--OIL COMING FROM THE TOP--NEED TO REMOVE INTAKE	OPERATOR COMPLAINT
1702486	5	03/27/2017	746	OIL LEAK DIAGNOSTIC--OIL COMING FROM THE TOP--NEED TO REMOVE INTAKE	MANIFOLD GASKET OPERATOR COMPLAINT
1910905	3	06/13/2019	746	OIL PAN LEAK REPAIRED	MANIFOLD GASKET SCHEDULED SERVICE
1802580	2	03/12/2018	746	REPAIR ENGINE OIL LEAK	SCHEDULED SERVICE
PV1401	2816	ENGINE GASKETS/SEALS REPL	Total Line Count for System Code 2816 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1702486	6	03/27/2017	823	R/R INTAKE MANIFOLD & OIL -- COOLER--BASE DONE	OPERATOR COMPLAINT
1702486	6	03/27/2017	746	R/R INTAKE MANIFOLD & OIL -- COOLER--BASE DONE	OPERATOR COMPLAINT
PV1401	2818	ENGINE MOUNTS REPL	Total Line Count for System Code 2818 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1807984	7	05/01/2018	783	INSTALLED MOUNTS	OPERATOR COMPLAINT
PV1401	2819	ENGINE SWIT/SENS/THERM RE	Total Line Count for System Code 2819 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1807984	8	05/01/2018	783	R/R SENSOR FOR OIL PRESSURE & ACCESSORIES	OPERATOR COMPLAINT
PV1401	2842	ROCKER BOX R/R	Total Line Count for System Code 2842 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1900008	3	01/09/2019	783	DISMANTLE ENGINE INTAKE---R/R ROCKER ROLLERS--JOB COMPLETED	OPERATOR COMPLAINT
PV1401	2900	TRANSMISSION	Total Line Count for System Code 2900 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2006763	1	04/28/2020	29	TRANS -ARIGO DODGE	OUTSIDE REPAIR
PV1401	2901	TROUBLESHOOT TRANSMISSION	Total Line Count for System Code 2901 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2015573	1	08/17/2020	853	TROUBLESHOOT TRANSMISSION---REPAIR GROUND TO TCM---REPAIR AIR INTAKE LEAK	OPERATOR COMPLAINT
1923115	1	12/12/2019	820	TROUBLESHOOT TRANSMISSION---NO TRAN LIGHTON--CKD OIL LEVEL, LOW--ADDED OIL	OPERATOR COMPLAINT
PV1401	2905	TRANSMISSION R & R	Total Line Count for System Code 2905 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2006763	4	04/28/2020	29	TRANS RR UNDER WARANTY	WARRANTY

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021 System Code Range: **1100** to **9700**

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PV1401	2906	TRANSMISSION LEAKS REP	Total Line Count for System Code 2906 :			3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
1911648	5	07/01/2019	783	TRANS FLUID AND FILTER	OPERATOR COMPLAINT	
1721530	3	11/30/2017	746	REPAIR OIL LEAK @TRANSMISSION	SCHEDULED SERVICE	
1900362	2	01/10/2019	746	TRANSMISSION OIL LEAK REPAIR	SCHEDULED SERVICE	
PV1401	4000	TIRES	Total Line Count for System Code 4000 :			14
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
1900362	3	01/10/2019	746	ADJUSTED AIR PRESSURE ON ALL TIRES	SCHEDULED SERVICE	
1721530	4	11/30/2017	746	ROTATE ALL TIRES--ADUST AIR PRESSURE	SCHEDULED SERVICE	
1910978	1	06/14/2019	783	TIRES---REPAIRED	OPERATOR COMPLAINT	
1612180	3	09/03/2016	746	ROTATE ALL TIRES	OPERATOR COMPLAINT	
1814766	2	11/28/2018	746	CKD TIRES--NEED REPLACING	OPERATOR COMPLAINT	
1921353	1	12/03/2019	756	TIRES--NEEDS ALL NEW TIRES	OPERATOR COMPLAINT	
1921353	2	12/03/2019	29	TIRES--REPLACED ALL FOUR TIRES	OPERATOR COMPLAINT	
1615838	1	02/03/2017	679	TIRES	OPERATOR COMPLAINT	
1907680	1	04/24/2019	783	TIRES---REPAIRED	SCHEDULED SERVICE	
1903624	1	02/22/2019	854	TIRES---REPAIR	SCHEDULED SERVICE	
1906191	2	04/03/2019	783	TIRES	OPERATOR COMPLAINT	
1714373	1	08/11/2017	731	TIRES	OPERATOR COMPLAINT	
1912527	2	07/15/2019	849	TIRES--CHANGED ALL (4) TIRES	OPERATOR COMPLAINT	
1702486	1	03/27/2017	823	TIRES--FLAT TIRE--REAR LEFT TIRE FLAT	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: 1100 to 9700

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	4015	R/R/O TIRE REPLACEMENT	Total Line Count for System Code 4015 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1714373	2	08/11/2017	731	REPLCD TIRE	
PV1401	5001	CAMERAS	Total Line Count for System Code 5001 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1506870	1	05/02/2015	713	CAMERAS	
PV1401	5002	RADIOS	Total Line Count for System Code 5002 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1808067	1	04/25/2018	27	RADIOS	
1702069	1	02/06/2017	29	RADIOS	<u>OPERATOR COMPLAINT</u>
2126168	5	10/14/2021	809	DECOMISSION VEHICE FOR SURPLUS	<u>OPERATOR COMPLAINT</u>
2126168	5	10/14/2021	841	DECOMISSION VEHICE FOR SURPLUS	<u>OPERATOR COMPLAINT</u>
PV1401	5004	AVL -- Repairs	Total Line Count for System Code 5004 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1504535	1	03/25/2015	713	AVL-----REPAIRS	
PV1401	8060	DRIVE TO DEALER	Total Line Count for System Code 8060 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>TRANSPORT</u>
2006763	2	04/28/2020	809	DRIVE TO DEALER	
2006763	2	04/28/2020	827	DRIVE TO DEALER	<u>TRANSPORT</u>
2006763	3	04/28/2020	702	DRIVE TO DEALER	<u>TRANSPORT</u>
1814766	16	11/28/2018	783	TOOK VAN TO DEALER FOR RECALL	<u>OPERATOR COMPLAINT</u>
PV1401	9103	4,000 MILE PM CARS	Total Line Count for System Code 9103 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1900362	1	01/10/2019	746	4K MILE PM CARS ---COMPLETED--	
1616894	1	12/02/2016	746	4K MILE PM CARS	<u>SCHEDULED SERVICE</u>
1416659	1	11/14/2014	822	4K MILE PM CARS	<u>SCHEDULED SERVICE</u>

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: 1100 to 9700

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PV1401	9108	8,000 MILE PM CARS	Total Line Count for System Code 9108 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1906191	1	04/03/2019	859	8.000 PM CARS	SCHEDULED SERVICE
1707911	1	05/10/2017	679	8.000 MILE PM	SCHEDULED SERVICE
PV1401	9112	12,000 MILE PM CARS	Total Line Count for System Code 9112 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1910905	1	06/13/2019	746	12K MILE PM CARS---COMPLETED	SCHEDULED SERVICE
1715533	1	08/28/2017	746	12.000 MILE PM CARS	SCHEDULED SERVICE
PV1401	9116	16,000 MILE PM CARS	Total Line Count for System Code 9116 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2105877	1	05/15/2021	853	16K MILE PM CARS---COMPLETED	SCHEDULED SERVICE
1721530	1	11/30/2017	746	16K MILE PM CARS-----	SCHEDULED SERVICE
PV1401	9120	20,000 MILE PM CARS	Total Line Count for System Code 9120 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1802580	1	03/12/2018	746	20K MILE PM CARS--COMPLETED	SCHEDULED SERVICE
PV1401	9124	24,000 MILE PM CARS	Total Line Count for System Code 9124 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1810314	1	06/06/2018	746	24.000 MIL E PM CARS	SCHEDULED SERVICE
1611195	1	08/11/2016	746	24.000 MILE PM	SCHEDULED SERVICE
1611195	1	08/11/2016	679	24.000 MILE PM	SCHEDULED SERVICE
PV1401	9480	SAFETY CHECK	Total Line Count for System Code 9480 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2126168	1	10/14/2021	841	SAFETY INSPECTION COMPLETED	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 11/14/2014 to 10/14/2021

System Code Range: 1100 to 9700

Print Date: 10/16/2021

Asset# Range: PV1401 to PV1401

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Total Line Count for System Code 9700 :</u>	<u>18</u>	<u>Cause-Reason</u>
PV1401	9700	TEST RUN/ROAD TEST						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				
1601655	3	02/05/2016	823	ROAD TEST	OPERATOR COMPLAINT			
1701646	2	01/31/2017	679	ROAD TEST---TO DUPLICATE COMPLAINT	OPERATOR COMPLAINT			
1910905	4	06/13/2019	746	ROAD TEST	SCHEDULED SERVICE			
1702486	3	03/27/2017	823	ROAD TEST	OPERATOR COMPLAINT			
1616894	3	12/02/2016	746	ROAD TEST	SCHEDULED SERVICE			
1508723	5	07/14/2015	746	ROAD TEST	OPERATOR COMPLAINT			
1900008	4	01/09/2019	783	ROAD TEST---OK	OPERATOR COMPLAINT			
1900362	8	01/10/2019	746	ROAD TEST	SCHEDULED SERVICE			
1900362	4	01/10/2019	746	ROAD TEST---OK	SCHEDULED SERVICE			
1715533	2	08/28/2017	746	ROAD TEST	SCHEDULED SERVICE			
1802580	4	03/12/2018	746	ROAD TEST--FOUND --FRONT RIGHT BODY BROKEN--NEEDS BODY SHOP	SCHEDULED SERVICE			
1721530	5	11/30/2017	746	ROAD TEST	SCHEDULED SERVICE			
1810314	2	06/06/2018	746	ROAD TEST -OK -P.O.O 5/15/2018	OPERATOR COMPLAINT			
1814766	23	11/28/2018	783	ROAD TEST--OK	OPERATOR COMPLAINT			
1814766	13	11/28/2018	823	ROAD TEST---NEED TO REPLC BCM, NOT SENDING SIGNAL TO RELAY	OPERATOR COMPLAINT			
1814766	4	11/28/2018	746	ROAD TEST	OPERATOR COMPLAINT			
1923115	2	12/12/2019	820	ROAD TEST	OPERATOR COMPLAINT			
1814766	8	11/28/2018	823	ROAD TEST FOR FRONT LEFT TIRE VIBRATION---NEED TO REBALANCE FRONT TIRES & NEEDS WHE	OPERATOR COMPLAINT			