




WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 12



WorkOrder: 53766015
Invoice Number: 55345-53766015

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMC		VIN:	1FDFE4FS1EDB17173
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Sep 17, 2020	12:00 AM
Started	Sep 17, 2020	
Completed	Sep 17, 2020	6:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	257,637	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Sep-20	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 54573269
Invoice Number: 55345-54573269

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMC		VIN:	1FDFE4FS1EDB17173
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Jun 22, 2021	12:00 AM
Started	Jun 22, 2021	
Completed	Jun 23, 2021	12:19 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	283,162	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Gear Oil 80w90 qty 5 qts Air filter PA4075 Qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51044307
Invoice Number: 55345-51044307

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Mar 14, 2018	10:21 AM
Started	Mar 15, 2018	
Completed	Mar 15, 2018	4:50 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	139,870	DH
System	139,870	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service due by Mileage CORRECTION: Change Oil& Filter .Lube all Pivoting Points. check brakes.clean batteries L/R inner tire flat .swap tire with one 8/32 tread depth. Parts# B329 Qty (1) Oil5W20 Qty (7) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Mar-18	Arthurs,Durvin	2.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Mar-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51044307
Invoice Number: 55345-51044307

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FD4E4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Mar-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 0.42
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: **30** **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Mar-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.08
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51044307 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 2.50
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51426600	20-Jun-18	157,365	WO	PM A
51424717	14-Jun-18	152,369	WO	Clearance light, blood bourn pathogen kit, rear camera, wipers, adjust lift



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51044307
Invoice Number: 55345-51044307

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51347778	13-Jun-18	152,616	WO	PM C
51426461	13-Jun-18	152,616	WO	FTLMPMI_FOLLOWUP
51242518	15-May-18	148,439	WO	PM A
51099863	17-Apr-18	144,340	WO	PM A
51163880	2-Apr-18	142,017	WO	Wheel chair lift not working
51110549	20-Mar-18	140,517	WO	Replace Evap and orifice tube
51099825	15-Mar-18	139,870	WO	Front Tires& RearBrakes
51044307	15-Mar-18	139,870	WO	PM B
51000249	15-Feb-18	135,469	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 51044307 Desc: PM B**Equip: 4511-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS1EDB17173****LH: 10 Desc: Light Medium Duty PMI****Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 15-MAR-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Mar 15, 2018 4:24:12 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Mar 15, 2018 4:24:12 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Mar 15, 2018 4:24:12 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Mar 15, 2018 4:24:12 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Mar 15, 2018 4:24:13 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Mar 15, 2018 4:24:14 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Mar 15, 2018 4:24:14 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Mar 15, 2018 4:24:14 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Mar 15, 2018 4:24:14 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Mar 15, 2018 4:24:15 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Mar 15, 2018 4:24:15 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Mar 15, 2018 4:24:15 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Mar 15, 2018 4:24:15 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Mar 15, 2018 4:24:16 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Mar 15, 2018 4:24:16 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Mar 15, 2018 4:24:16 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Mar 15, 2018 4:24:16 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Mar 15, 2018 4:24:16 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Mar 15, 2018 4:24:16 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Mar 15, 2018 4:24:16 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Mar 15, 2018 4:24:17 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Mar 15, 2018 4:24:17 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Mar 15, 2018 4:24:17 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Mar 15, 2018 4:24:17 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Mar 15, 2018 4:24:17 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Mar 15, 2018 4:24:18 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Mar 15, 2018 4:24:19 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Mar 15, 2018 4:24:19 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Mar 15, 2018 4:24:19 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Mar 15, 2018 4:24:19 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Mar 15, 2018 4:24:20 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,420	Check Hood	Done		DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Mar 15, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:24:21 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Mar 15, 2018 4:24:21 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Mar 15, 2018 4:24:22 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Mar 15, 2018 4:24:22 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Mar 15, 2018 4:24:23 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Mar 15, 2018 4:24:23 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Mar 15, 2018 4:24:23 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Mar 15, 2018 4:24:23 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:24 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:25 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:25 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:25 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:25 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Mar 15, 2018 4:24:26 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Mar 15, 2018 4:24:26 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Mar 15, 2018 4:24:26 PM	No	
60,631	Tread Depth RF	4 32nds of an inch		DARTHURS	Mar 15, 2018 4:24:26 PM	No	
60,632	Tread Depth LF	4 32nds of an inch		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,634	Tread Depth RRI	9 32nds of an inch		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,635	Tread Depth LRI	9 32nds of an inch	L/R inner nail Swap With one 8/32 Tire	DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Mar 15, 2018 4:24:27 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Mar 15, 2018 4:24:28 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Mar 15, 2018 4:24:28 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Mar 15, 2018 4:24:28 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	Mar 15, 2018 4:24:28 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Mar 15, 2018 4:24:29 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
70,790	Check All Body Mounts and Chassis	Done		DARTHURS	Mar 15, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Frame				4:24:30 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Mar 15, 2018 4:24:30 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Mar 15, 2018 4:24:30 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,133	Brake Pad Thickness LR	4 Inch		DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,134	Brake Pad Thickness RR	4 Inch	rear brakes uneven wear	DARTHURS	Mar 15, 2018 4:24:31 PM	No	
77,135	Brake Rotor LF	1.554 Inch		DARTHURS	Mar 15, 2018 4:24:32 PM	No	
77,136	Brake Rotor RF	1.555 Inch		DARTHURS	Mar 15, 2018 4:24:32 PM	No	
77,137	Brake Rotor LR	1.641 Inch		DARTHURS	Mar 15, 2018 4:24:32 PM	No	
77,138	Brake Rotor RR	1.642 Inch		DARTHURS	Mar 15, 2018 4:24:32 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Mar 15, 2018 4:24:32 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Mar 15, 2018 4:24:33 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done	Repack front Wheel bearing	DARTHURS	Mar 15, 2018 4:24:33 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Mar 15, 2018 4:24:33 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Mar 15, 2018 4:24:33 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Mar 15, 2018 4:24:34 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Mar 15, 2018 4:24:34 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: DARTHURS Performed on: 15-MAR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 15, 2018 4:25:37 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Mar 15, 2018 4:25:37 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Mar 15, 2018 4:25:37 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Mar 15, 2018 4:25:38 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Mar 15, 2018 4:25:38 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Mar 15, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:25:38 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 15, 2018 4:25:38 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Mar 15, 2018 4:25:38 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Mar 15, 2018 4:25:39 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Mar 15, 2018 4:25:39 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	Mar 15, 2018 4:25:39 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Mar 15, 2018 4:25:39 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Mar 15, 2018 4:25:39 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-MAR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 15, 2018 4:26:03 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51099863
Invoice Number: 55345-51099863

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: DARTHURS

Status: 40

Created By: DARTHURS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Apr 13, 2018	12:39 PM
Started		
Completed	Apr 17, 2018	7:54 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	144,340	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: preventive maintenance CORRECTION: perform service lube all Pivoting Points cross rotate tires complete Part # B329 qty1 Oil5w20 Qts 6

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Apr-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51099863
Invoice Number: 55345-51099863

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
Activity 20 Sub Total				
Parts:				1.96
Labor:				0.00
Labor Hours: 0.00				
Sublet Parts:				0.00
Sublet Labor:				0.00
Activity Sub Total				1.96

Activity: 30 **999 TOTAL VEHICLE**
Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
Activity 30 Sub Total				
Parts:				0.00
Labor:				0.00
Labor Hours: 0.00				
Sublet Parts:				0.00
Sublet Labor:				0.00
Activity Sub Total				0.00

WorkOrder 51099863 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51426600	20-Jun-18	157,365	WO	PM A
51424717	14-Jun-18	152,369	WO	Clearance light, blood bourn pathogen kit, rear camera, wipers, adjust lift
51347778	13-Jun-18	152,616	WO	PM C
51426461	13-Jun-18	152,616	WO	FTLMPMI_FOLLOWUP



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51099863
Invoice Number: 55345-51099863

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51242518	15-May-18	148,439	WO	PM A
51099863	17-Apr-18	144,340	WO	PM A
51163880	2-Apr-18	142,017	WO	Wheel chair lift not working
51110549	20-Mar-18	140,517	WO	Replace Evap and orifice tube
51099825	15-Mar-18	139,870	WO	Front Tires& RearBrakes
51044307	15-Mar-18	139,870	WO	PM B

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 51099863 Desc: PM A

Equip: 4511-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS1EDB17173

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Apr 16, 2018 2:10:06 PM	No	
10,100	Safety Inspection	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 16, 2018 2:10:06 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		HPIERRE	Apr 16, 2018 2:10:06 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,140	Check Service Brakes	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,160	FRA Check Instruments and Horns	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
10,170	Check Fast Idle	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,180	Check Starter Protection Circuit	Done		HPIERRE	Apr 16, 2018 2:10:07 PM	No	
10,190	Check Reverse Warning System	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
11,100	Check Parking Brake	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		HPIERRE	Apr 16, 2018 2:10:08 PM	No	
11,140	Road Test: Check for Proper Operation	Done		HPIERRE	Apr 16, 2018 2:10:09 PM	No	
11,150	Perform Brake Test	Done		HPIERRE	Apr 16, 2018 2:10:09 PM	No	
11,152	Decelerometer Results Test 1	FEET	N/A	HPIERRE	Apr 16, 2018 2:10:09 PM	No	
11,154	Decelerometer Results Test 2	FEET	N/A	HPIERRE	Apr 16, 2018 2:10:09 PM	No	
11,156	Decelerometer Results Test 3	FEET	N/A	HPIERRE	Apr 16, 2018 2:10:10 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Apr 16, 2018 2:10:10 PM	No	
11,162	FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Apr 16, 2018 2:10:10 PM	No	
11,170	FRA Check Door Operation	Done		HPIERRE	Apr 16, 2018 2:10:10 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		HPIERRE	Apr 16, 2018 2:10:10 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		HPIERRE	Apr 16, 2018 2:10:10 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		HPIERRE	Apr 16, 2018 2:10:10 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		HPIERRE	Apr 16, 2018 2:10:10 PM	No	
20,230	FRA Check Wiring Under Dash	Done		HPIERRE	Apr 16, 2018 2:10:11 PM	No	
20,240	FRA Check Interior Lights	Done		HPIERRE	Apr 16, 2018 2:10:11 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		HPIERRE	Apr 16, 2018 2:10:11 PM	No	
20,260	Check Stop Request System	-	N/A	HPIERRE	Apr 16, 2018 2:10:11 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Apr 16, 2018 2:10:12 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Apr 16, 2018 2:10:12 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Apr 16, 2018 2:10:12 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		HPIERRE	Apr 16, 2018 2:10:12 PM	No	
22,110	Check Emergency Hatches	Done		HPIERRE	Apr 16, 2018 2:10:12 PM	No	
22,120	Check All Safety Equipment	Done		HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,310	Check Passenger Doors	Done		HPIERRE	Apr 16, 2018 2:10:12 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,330	Check Wheelchair Lift Operation	Done		HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		HPIERRE	Apr 16, 2018 2:10:13 PM	No	
30,360	Check for Physical Damage and Decals	Done		HPIERRE	Apr 16, 2018 2:10:14 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		HPIERRE	Apr 16, 2018 2:10:14 PM	No	
30,380	Check Exterior Compartment Doors	Done		HPIERRE	Apr 16, 2018 2:10:14 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		HPIERRE	Apr 16, 2018 2:10:14 PM	No	
33,100	Check Lights and Reflectors	Done		HPIERRE	Apr 16, 2018 2:10:15 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Apr 16, 2018 2:10:15 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Apr 16, 2018 2:10:15 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Apr 16, 2018 2:10:15 PM	No	
40,420	Check Hood	Done		HPIERRE	Apr 16, 2018 2:10:15 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		HPIERRE	Apr 16, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2:10:15 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Apr 16, 2018 2:10:15 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Apr 16, 2018 2:10:16 PM	No	
40,442	Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Apr 16, 2018 2:10:16 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Apr 16, 2018 2:10:16 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Apr 16, 2018 2:10:16 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Apr 16, 2018 2:10:17 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Apr 16, 2018 2:10:17 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		HPIERRE	Apr 16, 2018 2:10:17 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		HPIERRE	Apr 16, 2018 2:10:17 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,130	FRA Check Exhaust System	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,140	FRA Check Intake System	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,150	FRA Inspect Turbocharger	-	N/A	HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Apr 16, 2018 2:10:18 PM	No	
44,180	FRA Check for Leaks	Done		HPIERRE	Apr 16, 2018 2:10:19 PM	No	
44,190	FRA Perform Battery Inspection	Done		HPIERRE	Apr 16, 2018 2:10:19 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Apr 16, 2018 2:10:19 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		HPIERRE	Apr 16, 2018 2:10:19 PM	No	
50,510	Check Entire Steering System	Done		HPIERRE	Apr 16, 2018 2:10:20 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Apr 16, 2018 2:10:20 PM	No	
60,610	FRA Check and Record Air Pressure	Done		HPIERRE	Apr 16, 2018 2:10:20 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:20 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:21 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:22 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:22 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,620	Check Valve Stems and Caps	Done		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,630	Check and Record Tread Depth	Done		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,631	Tread Depth RF	10 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,632	Tread Depth LF	10 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,634	Tread Depth RRI	8 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,635	Tread Depth LRI	8 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:23 PM	No	
60,636	Tread Depth LRO	8 32nds of an inch		HPIERRE	Apr 16, 2018 2:10:24 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		HPIERRE	Apr 16, 2018 2:10:24 PM	No	
60,650	Check Sidewall Wear	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
60,660	Inspect for Cuts and Tears	Done		HPIERRE	Apr 16, 2018 2:10:24 PM	No	
60,670	Check Dual Mating With Square	-	N/A	HPIERRE	Apr 16, 2018 2:10:24 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
70,710	Check Vibration Damper	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
70,720	Check Engine and Transmission Mounts	Done		HPIERRE	Apr 16, 2018 2:10:25 PM	No	
70,730	FRA Check Starter	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,750	FRA Check Transmission for Leaks	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,770	FRA Check Exhaust System	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Apr 16, 2018 2:10:26 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		HPIERRE	Apr 16, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2:10:27 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Apr 16, 2018 2:10:27 PM	No	
77,110	FRA Check Fuel Tank	Done		HPIERRE	Apr 16, 2018 2:10:27 PM	No	
77,120	Check Suspension Components	Done		HPIERRE	Apr 16, 2018 2:10:27 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Apr 16, 2018 2:10:27 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		HPIERRE	Apr 16, 2018 2:10:27 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,133	Brake Pad Thickness LR	10 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,134	Brake Pad Thickness RR	10 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,135	Brake Rotor LF	1.6 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,136	Brake Rotor RF	1.6 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,137	Brake Rotor LR	1.7 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,138	Brake Rotor RR	1.7 Inch		HPIERRE	Apr 16, 2018 2:10:28 PM	No	
77,140	FRA Check Brake Hoses	Done		HPIERRE	Apr 16, 2018 2:10:29 PM	No	
77,150	Check King Pins	-	N/A	HPIERRE	Apr 16, 2018 2:10:29 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Apr 16, 2018 2:10:29 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		HPIERRE	Apr 16, 2018 2:10:29 PM	No	
80,810	Completion of PMI Report	Done		HPIERRE	Apr 16, 2018 2:10:30 PM	No	
90,000	SECTION 9 Completion of PMI	Done		HPIERRE	Apr 16, 2018 2:10:30 PM	No	
90,910	Vehicle Returned to predetermined location	Done		HPIERRE	Apr 16, 2018 2:10:30 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: HPIERRE Performed on: 17-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 17, 2018 7:53:12 AM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	Apr 17, 2018 7:53:12 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Apr 17, 2018 7:53:12 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Apr 17, 2018 7:53:12 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Apr 17, 2018 7:53:12 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Apr 17, 2018 7:53:13 AM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Apr 17, 2018 7:53:12 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Apr 17, 2018 7:53:13 AM	No	


LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-APR-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 16, 2018 2:10:54 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51242518
Invoice Number: 55345-51242518

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: HPIERRE

Status: 40

Created By: HPIERRE

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	May 14, 2018	10:53 AM
Started		
Completed	May 15, 2018	8:43 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	148,439	DH
System	148,644	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE: preventive maintenance CORRECTION: perform service lube all Pivoting Points cross rotate tires completed Parts # Oil5w20 Qts 6 Oil filter # B329 qty1

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
14-May-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
15-May-18	F75Z-6730-BA		PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51242518
Invoice Number: 55345-51242518

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: HPIERRE
Created By: HPIERRE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
Activity 20 Sub Total				
Parts:				8.62
Labor:				0.00
Labor Hours: 0.00				
Sublet Parts:				0.00
Sublet Labor:				0.00
Activity Sub Total				8.62

Activity: 30 **999 TOTAL VEHICLE**
Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
Activity 30 Sub Total				
Parts:				0.00
Labor:				0.00
Labor Hours: 0.00				
Sublet Parts:				0.00
Sublet Labor:				0.00
Activity Sub Total				0.00

WorkOrder 51242518 Grand Total

Parts: 8.62
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 8.62

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51242518	15-May-18	148,439	WO	PM A
51099863	17-Apr-18	144,340	WO	PM A

Scheduled Preventative Maintenance



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51242518
Invoice Number: 55345-51242518

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By: HPIERRE

Created By: HPIERRE

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4511-P

Ford E450 Champion Challenger

VIN: 1FDFE4FS1EDB17173

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	-------------------	----------------------	---------------------	------------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	------------------	------------	-------	-------------

PH: Work Order: 51242518 Desc: PM A**Equip: 4511-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS1EDB17173****LH: 10 Desc: Light Medium Duty PMI****Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 14-MAY-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	May 14, 2018 11:51:12 AM	No	
10,100	Safety Inspection	Done		HPIERRE	May 14, 2018 11:51:12 AM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	May 14, 2018 11:51:12 AM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		HPIERRE	May 14, 2018 11:51:12 AM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,140	Check Service Brakes	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,160	FRA Check Instruments and Horns	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,170	Check Fast Idle	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,180	Check Starter Protection Circuit	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
10,190	Check Reverse Warning System	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
11,100	Check Parking Brake	Done		HPIERRE	May 14, 2018 11:51:13 AM	No	
11,110	Check HVAC Switches and Other Controls	Done		HPIERRE	May 14, 2018 11:51:14 AM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	May 14, 2018 11:51:14 AM	No	
11,130	FRA Check Wiper and Washer Operation	Done		HPIERRE	May 14, 2018 11:51:14 AM	No	
11,140	Road Test: Check for Proper Operation	Done		HPIERRE	May 14, 2018 11:51:14 AM	No	
11,150	Perform Brake Test	Done		HPIERRE	May 14, 2018 11:51:14 AM	No	
11,152	Decelerometer Results Test 1	FEET	N/A	HPIERRE	May 14, 2018 11:51:14 AM	No	
11,154	Decelerometer Results Test 2	FEET	N/A	HPIERRE	May 14, 2018 11:51:14 AM	No	
11,156	Decelerometer Results Test 3	FEET	N/A	HPIERRE	May 14, 2018 11:51:14 AM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	May 14, 2018 11:51:15 AM	No	
11,162	FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	May 14, 2018 11:51:15 AM	No	
11,170	FRA Check Door Operation	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
11,180	FRA Check Operation of All Other Accessories	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
20,220	Check Accelerator and Brake Pedals	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
20,230	FRA Check Wiring Under Dash	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
20,240	FRA Check Interior Lights	Done		HPIERRE	May 14, 2018 11:51:15 AM	No	
20,250	FRA Check Interior Electrical Panels	Done		HPIERRE	May 14, 2018 11:51:16 AM	No	
20,260	Check Stop Request System	-	N/A	HPIERRE	May 14, 2018 11:51:16 AM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	May 14, 2018 11:51:16 AM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	May 14, 2018 11:51:16 AM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	May 14, 2018 11:51:16 AM	No	
22,100	Check Emergency Windows and Glass Condition	Done		HPIERRE	May 14, 2018 11:51:16 AM	No	
22,110	Check Emergency Hatches	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
22,120	Check All Safety Equipment	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
30,310	Check Passenger Doors	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
30,320	Inspect Step-well and Hand Rails	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
30,330	Check Wheelchair Lift Operation	Done		HPIERRE	May 14, 2018 11:51:17 AM	No	
30,340	FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	May 14, 2018 11:51:18 AM	No	
30,350	FRA Inspect Mirror and Mountings	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
30,360	Check for Physical Damage and Decals	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
30,370	Check Wiper Blade and Arm Condition	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
30,380	Check Exterior Compartment Doors	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
30,390	FRA Check Fuel Tank Cap	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
33,100	Check Lights and Reflectors	Done		HPIERRE	May 14, 2018 11:51:19 AM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	May 14, 2018 11:51:19 AM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		HPIERRE	May 14, 2018 11:51:18 AM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	May 14, 2018 11:51:19 AM	No	
40,420	Check Hood	Done		HPIERRE	May 14, 2018 11:51:19 AM	No	
40,430	Check Fan, Shroud and Radiator	Done		HPIERRE	May 14, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:51:19 AM		
40,440	Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	May 14, 2018 11:51:19 AM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	May 14, 2018 11:51:19 AM	No	
40,442	Freeze Point	Degree Fahrenheit	N/A	HPIERRE	May 14, 2018 11:51:19 AM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	May 14, 2018 11:51:20 AM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	May 14, 2018 11:51:20 AM	No	
40,461	Refractometer Reading	0 Degree Fahrenheit	N/A	HPIERRE	May 14, 2018 11:51:20 AM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	May 14, 2018 11:51:20 AM	No	
40,480	FRA Check Coolant Hose Condition	Done		HPIERRE	May 14, 2018 11:51:20 AM	No	
40,490	FRA Check Alternator Mount and Condition	Done		HPIERRE	May 14, 2018 11:51:20 AM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,130	FRA Check Exhaust System	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,140	FRA Check Intake System	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,150	FRA Inspect Turbocharger	-	N/A	HPIERRE	May 14, 2018 11:51:22 AM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		HPIERRE	May 14, 2018 11:51:21 AM	No	
44,180	FRA Check for Leaks	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
44,190	FRA Perform Battery Inspection	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
50,000	SECTION 5 Steering System Inspection	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
50,510	Check Entire Steering System	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
60,610	FRA Check and Record Air Pressure	Done		HPIERRE	May 14, 2018 11:51:22 AM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:22 AM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:22 AM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:23 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:23 AM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:23 AM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	May 14, 2018 11:51:23 AM	No	
60,620	Check Valve Stems and Caps	Done		HPIERRE	May 14, 2018 11:51:23 AM	No	
60,630	Check and Record Tread Depth	Done		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,631	Tread Depth RF	8 32nds of an inch		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,632	Tread Depth LF	8 32nds of an inch		HPIERRE	May 14, 2018 11:51:23 AM	No	
60,633	Tread Depth RRO	7 32nds of an inch		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,634	Tread Depth RRI	7 32nds of an inch		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,635	Tread Depth LRI	7 32nds of an inch		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,636	Tread Depth LRO	7 32nds of an inch		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		HPIERRE	May 14, 2018 11:51:24 AM	No	
60,650	Check Sidewall Wear	Done		HPIERRE	May 14, 2018 11:51:25 AM	No	
60,660	Inspect for Cuts and Tears	Done		HPIERRE	May 14, 2018 11:51:25 AM	No	
60,670	Check Dual Mating With Square	-	N/A	HPIERRE	May 14, 2018 11:51:25 AM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	May 14, 2018 11:51:25 AM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		HPIERRE	May 14, 2018 11:51:25 AM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,710	Check Vibration Damper	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,720	Check Engine and Transmission Mounts	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,730	FRA Check Starter	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,750	FRA Check Transmission for Leaks	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,760	FRA Check Differential Breather and Fluid	Done		HPIERRE	May 14, 2018 11:51:26 AM	No	
70,770	FRA Check Exhaust System	Done		HPIERRE	May 14, 2018 11:51:27 AM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	May 14, 2018 11:51:27 AM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		HPIERRE	May 14, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:51:27 AM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	May 14, 2018 11:51:27 AM	No	
77,110	FRA Check Fuel Tank	Done		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,120	Check Suspension Components	Done		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,131	Brake Pad Thickness LF	8 Inch		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,132	Brake Pad Thickness RF	8 Inch		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,133	Brake Pad Thickness LR	8 Inch		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,134	Brake Pad Thickness RR	8 Inch		HPIERRE	May 14, 2018 11:51:28 AM	No	
77,135	Brake Rotor LF	1.6 Inch		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,136	Brake Rotor RF	1.6 Inch		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,137	Brake Rotor LR	1.7 Inch		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,138	Brake Rotor RR	1.7 Inch		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,140	FRA Check Brake Hoses	Done		HPIERRE	May 14, 2018 11:51:29 AM	No	
77,150	Check King Pins	-	N/A	HPIERRE	May 14, 2018 11:51:30 AM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	May 14, 2018 11:51:30 AM	No	
80,000	SECTION 8 PMI Report Completion	Done		HPIERRE	May 14, 2018 11:51:30 AM	No	
80,810	Completion of PMI Report	Done		HPIERRE	May 14, 2018 11:51:30 AM	No	
90,000	SECTION 9 Completion of PMI	Done		HPIERRE	May 14, 2018 11:51:30 AM	No	
90,910	Vehicle Returned to predetermined location	Done		HPIERRE	May 14, 2018 11:51:30 AM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: HPIERRE Performed on: 14-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	May 14, 2018 2:30:08 PM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	May 14, 2018 2:30:08 PM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	May 14, 2018 2:30:08 PM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	May 14, 2018 2:30:08 PM	No	
104,000	Lubricate Chassis	Done		HPIERRE	May 14, 2018 2:30:09 PM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	May 14, 2018 2:30:08 PM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	May 14, 2018 2:30:08 PM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	May 14, 2018 2:30:09 PM	No	


LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 14, 2018 2:30:50 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51426600
Invoice Number: 55345-51426600

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By:

Created By:

Class:

Arrangement:

Potential Warranty:

TDELVA

TDELVA

WO

Unassigned

No

Equipment:

4511-P

Ford E450 Champion Challenger

1FDFE4FS1EDB17173

VIN:

Status:

40

Priority:

1

Driver:

Phone:

ETA:

**Reported
Started
Completed**

Chronology

Jun 19, 2018

12:00 AM

Jun 20, 2018

Jun 20, 2018

12:23 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	157,365	DH
System	153,108	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service due CORRECTION: Performed and completed PMA Changed engine oil and replaced engine oil filter Replaced rear A/C filter Added 6qts engine oil
20	MILEAGES ISSUES IN INFOR

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Jun-18	Delva, Terry	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51445421
Invoice Number: 55345-51445421

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By:

Created By:

Class:

Arrangement:

Potential Warranty:

TDELVA

TDELVA

WO

Unassigned

No

Equipment:

4511-P

Ford E450 Champion Challenger

1FD4E4FS1EDB17173

VIN:

Status:

40

Priority:

1

Driver:

Phone:

ETA:

Chronology		
Reported	Aug 23, 2018	1:21 PM
Started		
Completed	Aug 27, 2018	10:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	161,899	DH
System	161,721	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
24-Aug-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
24-Aug-18	PA4075	FILTER, AIR, PAPER SAME AS AF25590	1.00	5.23	5.23



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51776614
Invoice Number: 55345-51776614

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Oct 29, 2018	4:18 PM
Started	Oct 29, 2018	
Completed	Oct 29, 2018	11:54 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,414	DH
System	170,577	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Fixed right rear inside tire patched. Torque wheel 140 second torque wheel 140 lbs

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Oct-18	Gaspard,Ronald	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51858523
Invoice Number: 55345-51858523

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
1FDFE4FS1EDB17173
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 28, 2018	10:49 AM
Started	Nov 28, 2018	
Completed	Nov 28, 2018	3:59 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	174,737	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service due CORRECTION: Performed and completed PmA Changed engine oil and replaced engine oil filter Replaced rear AC filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Nov-18	Delva,Terry	1.12	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.12
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
28-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52061776
Invoice Number: 55345-52061776

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
1FDFE4FS1EDB17173
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 4, 2019	11:55 AM
Started	Feb 4, 2019	
Completed	Feb 5, 2019	7:17 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	182,719	DH
System	182,926	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Preventive Maintenance CORRECTION: Perform pmA Service lube all Pivoting Points cross rotate tires completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Feb-19	Pierre,Hubert J	6.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 6.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
04-Feb-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52140855
Invoice Number: 55345-52140855

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
PM A		VIN:	1FDFE4FS1EDB17173
Requested By:	CVERGARA	Status:	40
Created By:	CVERGARA	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Feb 28, 2019	11:20 AM
Started	Mar 1, 2019	
Completed	Mar 1, 2019	3:48 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	187,197	DH
System	187,197	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Performed and completed PMA SERVICE replaced drain plug

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Mar-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
01-Mar-19	B329	FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52291810

Invoice Number: 55345-52291810

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Apr 25, 2019	10:03 AM
Started	Apr 25, 2019	
Completed	Apr 26, 2019	12:13 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	195,770	DH
System	195,777	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Apr-19	Gaspard, Ronald	1.62	65.00	105.08

Activity 10 Sub Total

Parts: 0.00
Labor: 105.08
Labor Hours: 1.62
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 105.08

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
25-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52376497
Invoice Number: 55345-52376497

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	May 24, 2019	10:17 AM
Started		
Completed	May 29, 2019	9:32 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,207	DH
System	200,006	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA service CAUSE: preventive maintenance CORRECTION:PmA Service Performed
20	PMA Service Preventive maintenance PMA Service Perform

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
29-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52560086
Invoice Number: 55345-52560086

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DKNOTT
Created By: DKNOTT
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 1, 2019	12:00 AM
Started		
Completed	Aug 1, 2019	3:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,120	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA service CAUSE: preventive maintenance CORRECTION:PmA Service Performed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
01-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52654964
Invoice Number: 55345-52654964

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: DKNOTT

Status: 40

Created By: DKNOTT

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Aug 30, 2019	10:13 AM
Started		
Completed	Sep 4, 2019	9:17 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,490	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
30-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52873380
Invoice Number: 55345-52873380

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: VAMRITTEEMAL

Status: 40

Created By: VAMRITTEEMAL

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Nov 4, 2019	12:00 AM
Started	Nov 6, 2019	
Completed	Nov 6, 2019	9:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,015	DH
System	222,819	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service Due CORRECTION: Performed and completed PMA Lube all Pivoting Points

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Nov-19	Delva,Terry	1.33	65.00	86.67

Activity 10 Sub Total

Parts:	0.00
Labor:	86.67
Labor Hours: 1.33	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	86.67

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 52972753
Invoice Number: 55345-52972753

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFF4FS1EDB17173

Requested By:

RRENE

Status: 40

Created By:

RRENE

Priority: 1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology		
Reported	Dec 10, 2019	12:29 PM
Started	Dec 11, 2019	
Completed	Dec 11, 2019	10:34 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	227,532	DH
System	227,532	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: preventive maintenance CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Dec-19	Pierre,Hubert J	2.42	65.00	157.30

Activity 10 Sub Total

Parts: 0.00
Labor: 157.30
Labor Hours: 2.42
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 157.30

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
11-Dec-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53189515
Invoice Number: 55345-53189515

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: VAMRITTEEMAL

Status: 40

Created By: VAMRITTEEMAL

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Feb 14, 2020	11:00 AM
Started	Feb 16, 2020	
Completed	Feb 18, 2020	12:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	236,450	DH
System	236,292	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Feb-20	AMRIT TEEMAL,VISHNU	0.67	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Feb-20	B329(F)	FILTER, OIL, SPIN-ON	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53295410
Invoice Number: 55345-53295410

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FS1EDB17173

Requested By: VAMRITTEEMAL

Status: 40

Created By: VAMRITTEEMAL

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Mar 17, 2020	11:04 AM
Started	Mar 17, 2020	
Completed	Mar 18, 2020	12:21 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	240,363	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION: perform PMA service Oil filter B329 qty 1 Engine oil 10W30 qty 7 qts Replaced left front signal qty1

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Mar-20	Gaspard,Ronald	2.03	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A


Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 12



WorkOrder: 53656661
Invoice Number: 55345-53656661

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1DFE4FS1EDB17173
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 7, 2020	12:00 AM
Started	Aug 7, 2020	
Completed	Aug 7, 2020	9:21 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	253,204	DH
System	253,301	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points Check Brakes. Clean batteries. Replace Air Filter. Parts # B329 Qty (1) Parts # PA4075 Qty (1) Oil 10W30 Qty (7.0) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53883474
Invoice Number: 55345-53883474

Client Department:

MRC: 55345M

WO Desc:

55345-LIGHT DUTY PMA

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4511-P

Ford E450 Champion Challenger

VIN: 1FDFE4FS1EDB17173

Status: 40

Priority: 3

Driver:

Phone:

ETA:

Chronology

Reported	Oct 26, 2020	12:00 AM
Started	Oct 29, 2020	
Completed	Oct 29, 2020	10:30 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	261,932	DH

WorkOrder Notes

Line	Comment
10	PM. Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time. Parts. Engine oil filter part # B329 qty 1 engine oil. 5W20 Qty 6 qts

Activity: 5



999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54006774
Invoice Number: 55345-54006774

Client Department:

MRC: 55345M

WO Desc:

55345-LIGHT DUTY PMA

Requested By: RAUODRIGUEZ

Created By: RAUODRIGUEZ

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4511-P

Ford E450 Champion Challenger

VIN: 1FDFE4FS1EDB17173

Status: 40

Priority: 3

Driver:

Phone:

ETA:

Chronology

Reported	Jan 22, 2021	3:52 PM
Started	Jan 24, 2021	
Completed	Jan 24, 2021	6:22 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	266,009	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Replace. a/C Filter Parts # B329 Qty (1) Oil. 10W30 Qty (7.0) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: -

Part Failure: -

Activity Comments


Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54333603
Invoice Number: 55345-54333603

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		VIN:	1FDFE4FS1EDB17173
Requested By:	HPIERRE	Status:	40
Created By:	HPIERRE	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Apr 8, 2021	12:00 AM
Started	Apr 8, 2021	
Completed	Apr 9, 2021	12:12 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	274,559	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54452183
Invoice Number: 55345-54452183

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMA		VIN:	1FDFE4FS1EDB17173
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	May 17, 2021	3:29 PM
Started	May 17, 2021	
Completed	May 18, 2021	12:23 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	278,790	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 54673290
Invoice Number: 55345-54673290

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 2, 2021	12:00 AM
Started	Aug 2, 2021	
Completed	Aug 2, 2021	6:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	287,421	DH
System	287,529	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: Service by miles CORRECTION: Job complete also change oil filter part # B329 Now follow up for front and rear brakes off to complete

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Aug-21	Junior Hurst	0.03	0.00	0.00

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.03
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
02-Aug-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.98	1.98



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51660655
Invoice Number: 55345-51660655

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: CKARLENS
Created By: CKARLENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 2, 2018	9:19 PM
Started	Oct 2, 2018	
Completed	Oct 3, 2018	12:31 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	165,968	DH
System	166,167	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE:Service CORRECTION:Perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Replaced exhaust hanger and bracket

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Oct-18	Gaspard,Ronald	2.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52215680
Invoice Number: 55345-52215680

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:
PM B

Ford E450 Champion Challenger
1FDFE4FS1EDB17173

Requested By: VAMRITTEEMAL

VIN: 40

Created By: VAMRITTEEMAL

Status: 1

Class: WO

Priority: 1

Arrangement: Unassigned

Driver:

Potential Warranty: No

Phone:

ETA:

Chronology		
Reported	Mar 26, 2019	9:48 AM
Started	Mar 27, 2019	
Completed	Mar 28, 2019	12:19 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	191,485	DH
System	191,485	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION:Perform PMB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
27-Mar-19	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
27-Mar-19	B329	FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52754567
Invoice Number: 55345-52754567

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: DKNOTT

Created By: DKNOTT

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4511-P

Ford E450 Champion Challenger

1FDPE4FS1EDB17173

VIN: 40

Status: 1

Priority:

Driver:

Phone:

ETA:

Chronology		
Reported	Oct 7, 2019	12:00 AM
Started	Oct 7, 2019	
Completed	Oct 7, 2019	7:43 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	218,097	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE
	CAUSE: PREVENTIVE MAINTENANCE
	CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Oct-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	97.50

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
07-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
07-Oct-19	PA4456	FILTER, AIR, CARAVAN, '14 SAME AS WIX 49737	1.00	5.02	5.02

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 10

**WorkOrder: 53394710****Invoice Number: 55345-53394710****Client Department:****MRC:** 55345M**Equipment:** 4511-P**WO Desc:**

PM B

Ford E450 Champion Challenger

Requested By:

RGASPARD

VIN:

1FDFE4FS1EDB17173

Created By:

RGASPARD

Status:

40

Class:

WO

Priority:

1

Arrangement:

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:**

Chronology		
Reported	May 4, 2020	3:54 PM
Started	May 5, 2020	
Completed	May 5, 2020	10:15 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	244,563	DH
System	244,563	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE: preventive maintenance CORRECTION:perform pm service lube all pivoting point cross rotate tires completed

Activity: 10**999/999/999 TOTAL VEHICLE****Activity Note:**

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM B

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: B - PM Level B**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
05-May-20	B329(F)	FILTER, OIL, SPIN-ON SEE BALDWIN B329	1.00	1.96	1.96

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 54236032
Invoice Number: 55345-54236032

Client Department:

MRC:	55345M	Equipment:	4511-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		VIN:	1FDFE4FS1EDB17173
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Feb 25, 2021	3:01 PM
Started	Feb 26, 2021	
Completed	Feb 26, 2021	1:45 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	270,244	DH
System	270,244	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: preventive maintenance CORRECTION: Performed service lube all pivoting point cross tires completed

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **017 TIRES, TUBES, LINERS & VALVES**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51347778
Invoice Number: 55345-51347778

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology

Reported	Jun 13, 2018	8:41 AM
Started	Jun 13, 2018	
Completed	Jun 13, 2018	5:15 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	152,616	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM C CAUSE: Service due CORRECTION: Performed and completed PM C... Changed engine oil and replaced engine oil filter Replaced rear A/C filter Add 6qts Oil5w20 Drained and replaced differential fluid **Transmission's job done previously**

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
13-Jun-18	Delva, Terry	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51347778
Invoice Number: 55345-51347778

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
13-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
13-Jun-18	Delva,Terry	1.00	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: **30**  **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
13-Jun-18	Delva,Terry	0.45	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.45
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51347778 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 3.45
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51347778
Invoice Number: 55345-51347778

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE4FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51426600	20-Jun-18	157,365	WO	PM A
51424717	14-Jun-18	152,369	WO	Clearance light, blood bourn pathegen kit, rear camera, wipers, adjust lift
51426461	13-Jun-18	152,616	WO	FTLMPMI_FOLLOWUP
51347778	13-Jun-18	152,616	WO	PM C
51242518	15-May-18	148,439	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 51347778 Desc: PM C

Equip: 4511-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FS1EDB17173

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 13-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jun 13, 2018 4:07:13 PM	No	
10,100	Safety Inspection	Done		TDELVA	Jun 13, 2018 4:07:13 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,140	Check Service Brakes	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,160	FRA Check Instruments and Horns	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,170	Check Fast Idle	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,180	Check Starter Protection Circuit	Done		TDELVA	Jun 13, 2018 4:07:14 PM	No	
10,190	Check Reverse Warning System	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,100	Check Parking Brake	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,140	Road Test: Check for Proper Operation	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,150	Perform Brake Test	Done		TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	TDELVA	Jun 13, 2018 4:07:15 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	TDELVA	Jun 13, 2018 4:07:16 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	TDELVA	Jun 13, 2018 4:07:16 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Jun 13, 2018 4:07:16 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Jun 13, 2018 4:07:16 PM	No	
11,170	FRA Check Door Operation	Done		TDELVA	Jun 13, 2018 4:07:16 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		TDELVA	Jun 13, 2018 4:07:16 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		TDELVA	Jun 13, 2018 4:07:16 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		TDELVA	Jun 13, 2018 4:07:16 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		TDELVA	Jun 13, 2018 4:07:16 PM	No	
20,230	FRA Check Wiring Under Dash	Done		TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,240	FRA Check Interior Lights	Done		TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,260	Check Stop Request System	-	na	TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jun 13, 2018 4:07:17 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jun 13, 2018 4:07:17 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
22,110	Check Emergency Hatches	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
22,120	Check All Safety Equipment	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
30,310	Check Passenger Doors	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		TDELVA	Jun 13, 2018 4:07:18 PM	No	
30,330	Check Wheelchair Lift Operation	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,360	Check for Physical Damage and Decals	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,380	Check Exterior Compartment Doors	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
33,100	Check Lights and Reflectors	Done		TDELVA	Jun 13, 2018 4:07:19 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,420	Check Hood	Done		TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		TDELVA	Jun 13, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:07:20 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Jun 13, 2018 4:07:20 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	TDELVA	Jun 13, 2018 4:07:21 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jun 13, 2018 4:07:21 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,130	FRA Check Exhaust System	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,140	FRA Check Intake System	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,150	FRA Inspect Turbocharger	-	na	TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,180	FRA Check for Leaks	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,190	FRA Perform Battery Inspection	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jun 13, 2018 4:07:22 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		TDELVA	Jun 13, 2018 4:07:23 PM	No	
50,510	Check Entire Steering System	Done		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,610	FRA Check and Record Air Pressure	Done		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:23 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,620	Check Valve Stems and Caps	Done		TDELVA	Jun 13, 2018 4:07:23 PM	No	
60,630	Check and Record Tread Depth	Done		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,633	Tread Depth RRO	12 32nds of an inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,634	Tread Depth RRI	11 32nds of an inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,635	Tread Depth LRI	10 32nds of an inch		TDELVA	Jun 13, 2018 4:07:24 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,650	Check Sidewall Wear	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,660	Inspect for Cuts and Tears	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,670	Check Dual Mating With Square	-	na	TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
70,710	Check Vibration Damper	Done		TDELVA	Jun 13, 2018 4:07:25 PM	No	
70,720	Check Engine and Transmission Mounts	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,730	FRA Check Starter	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,750	FRA Check Transmission for Leaks	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,770	FRA Check Exhaust System	Done		TDELVA	Jun 13, 2018 4:07:26 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jun 13, 2018 4:07:27 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		TDELVA	Jun 13, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:07:26 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,110	FRA Check Fuel Tank	Done		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,120	Check Suspension Components	Done		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,131	Brake Pad Thickness LF	4 Inch		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,132	Brake Pad Thickness RF	4 Inch	Front Brakes	TDELVA	Jun 13, 2018 4:07:27 PM	Yes	51426461
77,133	Brake Pad Thickness LR	8 Inch		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,135	Brake Rotor LF	38.39 Inch		TDELVA	Jun 13, 2018 4:07:27 PM	No	
77,136	Brake Rotor RF	38.39 Inch		TDELVA	Jun 13, 2018 4:07:28 PM	No	
77,137	Brake Rotor LR	36.8 Inch		TDELVA	Jun 13, 2018 4:07:28 PM	No	
77,138	Brake Rotor RR	36.5 Inch		TDELVA	Jun 13, 2018 4:07:28 PM	No	
77,140	FRA Check Brake Hoses	Done		TDELVA	Jun 13, 2018 4:07:28 PM	No	
77,150	Check King Pins	-	na	TDELVA	Jun 13, 2018 4:07:28 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jun 13, 2018 4:07:28 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		TDELVA	Jun 13, 2018 4:07:28 PM	No	
80,810	Completion of PMI Report	Done		TDELVA	Jun 13, 2018 4:07:28 PM	No	
90,000	SECTION 9 Completion of PMI	Done		TDELVA	Jun 13, 2018 4:07:28 PM	No	
90,910	Vehicle Returned to predetermined location	Done		TDELVA	Jun 13, 2018 4:07:29 PM	No	

LH: 20 Desc: PM C

Task: PM C SERVICE Performed by: TDELVA Performed on: 13-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	Jun 13, 2018 3:59:34 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	Jun 13, 2018 3:59:34 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	Jun 13, 2018 3:59:34 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	Jun 13, 2018 3:59:34 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	Jun 13, 2018 3:59:35 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	Jun 13, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:59:35 PM		
107,000	FRA Change Primary Fuel Filter	-	na	TDELVA	Jun 13, 2018 3:59:35 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	Jun 13, 2018 3:59:35 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Jun 13, 2018 3:59:35 PM	No	
201,000	Service Crankcase Breather	Done		TDELVA	Jun 13, 2018 3:59:35 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		TDELVA	Jun 13, 2018 3:59:35 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		TDELVA	Jun 13, 2018 3:59:35 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Jun 13, 2018 3:59:35 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		TDELVA	Jun 13, 2018 3:59:36 PM	No	
301,000	Check and Lubricate Door Linkages	Done		TDELVA	Jun 13, 2018 3:59:36 PM	No	
302,000	Check Toe-In and Record Reading	-	na	TDELVA	Jun 13, 2018 3:59:36 PM	No	
302,001	Record Toe-In Reading	Inches, fraction-actual	na	TDELVA	Jun 13, 2018 3:59:36 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		TDELVA	Jun 13, 2018 3:59:36 PM	No	
305,000	FRA Change Differential Fluid	Yes		TDELVA	Jun 13, 2018 3:59:36 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 13-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 13, 2018 3:58:21 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51945337
Invoice Number: 55345-51945337

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: DKNOTT
Created By: DKNOTT
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4511-P
Ford E450 Champion Challenger
VIN: 1FDFE1FS1EDB17173
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 8, 2019	12:06 PM
Started	Jan 8, 2019	
Completed	Jan 9, 2019	12:20 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,607	DH
System	178,779	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 Qty1 Engine oil 5w20 qty7 Qts Transmission filter 20021 qty1 Transmission fluid 10 Qts Gear Oil 80w90 qty 5qts Air filter PA4075 Qty1

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jan-19	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52470311
Invoice Number: 55345-52470311

Client Department:

MRC: 55345M

WO Desc:

PM C

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4511-P

Ford E450 Champion Challenger

VIN: 1FDFE4FS1EDB17173

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Jun 27, 2019	9:35 AM
Started		
Completed	Jun 28, 2019	12:43 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	204,561	DH
System	204,561	DH

WorkOrder Notes

Line	Comment
10	PMC Service Preventive maintenance PMC Service Perform

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
28-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53085170
Invoice Number: 55345-53085170

Client Department:

MRC: 55345M

Equipment: 4511-P

WO Desc:

Ford E450 Champion Challenger

PM C

VIN: 1FDFE4FS1EDB17173

Requested By: DKNOTT

Status: 40

Created By: DKNOTT

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Jan 16, 2020	10:51 AM
Started	Jan 16, 2020	
Completed	Jan 16, 2020	6:48 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	231,824	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE ACCIDENTALLY RAN TIME FOR REAR RUBBER SPRING UNDER ACTIVITY 20

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Jan-20	AMRIT TEEMAL,VISHNU	0.72	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.72	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Jan-20	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96