Total Hours: 61.50 Labor: 4,144.50 Parts: 6,415.12			Comm: 90.40	Charged: 10650.02					
Work Order: Problem:		5 Pre Delivery Ins	Meter:	0		In Date:	09/11/2013	Closed:	09/11/2013
Work Com	npleted								
- Pre Deliv	very Inspe	ction							
		Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:			Meter:	0		In Date:	09/17/2014	Closed:	10/07/2014
Work Com	npleted				Parts Issued			Qı	uantity
- Pm					R/r Brake Cable				1.00
- R/r dama	aged righ	rear brake cab	le and a	djust both	Distilled Water 1gal				1.00
- Shop Sup	pplies			-	R/r Brake Cable Kit				1.00
					Shop Supplies				1.00
		Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 88.	06	Total:	388.06
Work Order: Problem:			Meter:	0		In Date:	11/19/2015	Closed:	11/30/2015
Work Com	npleted				Parts Issued			Qı	uantity
- Pm					Distilled Water 1gal				2.00
- Shop Sup	pplies				Shop Supplies				1.00
		Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 5.3	0	Total:	245.30
Work Order: Problem:			Meter:	0		In Date:	12/05/2016	Closed:	12/12/2016
Work Com	npleted				Parts Issued			Qı	uantity
- Pm					Distilled Water 1gal				1.00
- PIII					Non-chlor Brake Clnr	•			1.00
- Wash Eq	pt								
					Shop Supplies				1.00

## Palm Beach County Fleet Management Asset Maintenance History 10193050 2013 CLUB CAR VILLAGER 4 Utility Cart, Elec, Passenger

Nork Order: 1711637 Problem: pm service	Meter:	0		In Date:	11/28/2017	Closed:	12/12/2017
Work Completed			Parts Issued			Qı	uantity
- Pm			Battery Cable Lug				12.00
- R/r batteries and make new battery cables			Non-chlor Brake Clnr	•			1.00
- Shop Supplies			Battery 8v				6.00
			Bulk Battery Cable				5.00
			Shop Supplies				1.00
Hours: 8.00		Comm: 0.00	Labor: 480.00	Parts: 1,4	40.61	Total:	1,920.61
Vork Order: 1900401 Problem: pm service	Meter:	0		In Date:	01/10/2019	Closed:	01/15/2019
Work Completed			Parts Issued			Qı	uantity
- pm service			Mac Wite Lithium Gre	es			1.00
- replace 2 rear tires			Distilled Water 1gal				2.00
- Shop Supplies			Grease Cap				2.00
			18x8.50-8 W/rim Ken	nda			2.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
Hours: 5.50		Comm: 0.00	Labor: 368.50	Parts: 149	9.40	Total:	517.90

Meter: 0

## Work Order: 1911688 **Problem:** pm/ wont run/ see notes

## **In Date:** 11/12/2019 **Closed:** 02/12/2020

Work Completed		Parts Issued			Quantity	
- pm service		Resistor Assembly			2.00	
- diagnose . replace burned up motor, controller ar	nd solenoid. test run	Solenoid		1.00		
- replace all front and rear leaf and control arm bus		Outer Sleeve Rolled Sleeve				2.00
- Shop Supplies	5				2.00	
		Upper Sleeve				2.00
		Eye Mounts Sleeve				4.00
		Urethane Bushing				12.00
		Bushing				8.00
		48v 3.3hp Motor				1.00
		Controller				1.00
		Shop Supplies				1.00
		Freight Charge				1.00
Hours: 15.00	Comm: 0.00	Labor: 1,095.00	Parts: 1,8	58.73	Total:	2,953.73
ork Order: 2001881 M Problem: tires locked up/ rear end leak/ smell/ se	leter: 0 e notes		In Date:	02/25/2020	Closed:	04/20/202
Work Completed		Parts Issued			Qu	antity

Work Completed		Parts Issued		Quantity
- R&r potentiometer controller resister & ck. all wiring	j test run	48v 3.3hp Motor		1.00
- R&r all batteries		Controller		1.00
- Shop Supplies		Resistor Assembly	,	1.00
		Solenoid	1.00	
		Mcor 3 Switch		1.00
		Battery 8v Shop Supplies		6.00
				1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 2,637.72	Total: 2,929.72

Vork Order:		Meter: 0		In Date: 11/23/2020	Closed:	
Problem:	pm service/ tires					
Work Com	npleted					
- Preventiv	ve Maint. Service					
	Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 0.00	Total:	0.00
Vork Order:		Meter: 0		In Date: 11/23/2020	Closed:	12/04/2020
Problem:	pm/ Tires need to be replaced	I. They are bald. One is blown ou	t.			
Work Com	npleted		Parts Issued		Qı	uantity
- Preventiv	ve Maint. Service		Non-chlor Brake Clnr			1.00
- Replace	front tires		Distilled Water 1gal			2.00
- Align fro	nt end		18x850-8 Fairway Pro	)		2.00
- Wash cai	rt		Shop Supplies			1.00
- Clean an	d adjust rear brakes		Tire Disposal Fee			2.00
- Shop Su	pplies					
		0 0.00	Labor: 657.00	Parts: 224.44	Total <sup>.</sup>	881.44
	Hours: 9.00	Comm: 0.00	Labor. 057.00	1 4110. 224.44	rotan	
Vork Order:	2103388	Meter: 0		In Date: 03/25/2021	Closed:	03/29/2021
	2103388			In Date: 03/25/2021	Closed:	03/29/2021
	2103388 We were told that this was at	Meter: 0		In Date: 03/25/2021	<b>Closed:</b> hat they	03/29/2021 Jantity
Problem: Work Corr	2103388 We were told that this was at	<b>Meter:</b> 0 Fleet for pick up, but battery was	found dead when staff a	In Date: 03/25/2021	<b>Closed:</b> hat they	
Problem: Work Com - Batteries	2103388 We were told that this was at <b>ppleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte	<b>Meter:</b> 0 Fleet for pick up, but battery was e Each Battery To Get Main	found dead when staff a <b>Parts Issued</b>	In Date: 03/25/2021	<b>Closed:</b> hat they	uantity
Problem: Work Com - Batteries Charger To	2103388 We were told that this was at <b>ppleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte System	<b>Meter:</b> 0 Fleet for pick up, but battery was e Each Battery To Get Main	found dead when staff a <b>Parts Issued</b>	In Date: 03/25/2021	<b>Closed:</b> hat they	uantity
Problem: Work Com - Batteries Charger To Charging S	2103388 We were told that this was at <b>ppleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte System	<b>Meter:</b> 0 Fleet for pick up, but battery was e Each Battery To Get Main	found dead when staff a <b>Parts Issued</b>	In Date: 03/25/2021	i Closed: hat they Qเ	uantity
Problem: Work Com - Batteries Charger To Charging S - Shop Sup Vork Order:	2103388 We were told that this was at <b>ppleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte System pplies Hours: 2.00	<b>Meter:</b> 0 Fleet for pick up, but battery was e Each Battery To Get Main eries, And Test Batteries &	found dead when staff a <b>Parts Issued</b> Shop Supplies	In Date: 03/25/2021 arrived. They were told t Parts: 4.00	i Closed: hat they Qเ	<b>Jantity</b> 1.00 150.00
Problem: Work Com - Batteries Charger To Charging S - Shop Sup Vork Order:	2103388 We were told that this was at <b>a pleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte System pplies Hours: 2.00 2107241 Transition Prep Charge	Meter: 0 Fleet for pick up, but battery was e Each Battery To Get Main eries, And Test Batteries & Comm: 0.00	found dead when staff a <b>Parts Issued</b> Shop Supplies	In Date: 03/25/2021 arrived. They were told t Parts: 4.00	ו <b>Closed:</b> hat they <b>Qu</b> Total:	<b>Jantity</b> 1.00 150.00
Problem: Work Com - Batteries Charger To Charging S - Shop Sup Vork Order: Problem: Work Com	2103388 We were told that this was at <b>a pleted</b> Were Dead, Individually Charg Kick In, Fully Charge 6 8v Batte System pplies Hours: 2.00 2107241 Transition Prep Charge	Meter: 0 Fleet for pick up, but battery was e Each Battery To Get Main eries, And Test Batteries & Comm: 0.00	found dead when staff a <b>Parts Issued</b> Shop Supplies	In Date: 03/25/2021 arrived. They were told t Parts: 4.00	ו <b>Closed:</b> hat they <b>Qu</b> Total:	1.00

10/18/2021 3:21:49 PM	Palı 10193050	Palm Beach County Fleet Management Asset Maintenance History 10193050 2013 CLUB CAR VILLAGER 4 Utility Cart, Elec, Passenger							
Work Order: 2107	267 Meter:	0		In Date:	06/28/2021	Closed:	07/06/2021		
Problem: will no	ot start or run								
Work Completed	d								
- Tow From: Jpp	maint compound To: vist	a							
	Hours: 0.00	Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40		
Total Hours: 61.50	Total Labor: 4	,144.50	Total Comm: 90.40		Total Parts	: 6,415.12			