Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi, Trlr Mntd, Dual Reel

Total Hours: 74.80 Labor: 4,901.40 Parts: 4,795.71 Comm: 0.00 Charged: 9697.10

Work Order: 1404433 Meter: 0 In Date: 05/06/2014 Closed: 05/15/2014

Problem: valves

Work CompletedParts IssuedQuantity- Install shut off valves to pressure hoses3/8 Ball Valve2.00- Rewire traielr plug to county specs with Supplied hardwareShop Supplies1.00

- Shop Supplies

Hours: 2.50 Comm: 0.00 Labor: 150.00 Parts: 25.19 Total: 175.19

 Work Order:
 1404498
 Meter:
 0

 In Date:
 05/08/2014
 Closed:
 05/08/2014

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1508546 Meter: 0 In Date: 08/26/2015 Closed: 08/31/2015

Problem: pm service

Work Completed		Parts Issued		Quantity
 - Pm - Service trailer - replace trailer - Tool box lid was broken off. straighten hinge, drilled out rivets and holes. Rebolted back on - Shop Supplies 		Napa 10w30 Qt		2.00
		Napagold Oil Filte	er	1.00
		Napagold Fuel Filt	ter	1.00
		Napagold Fuel Filter		1.00
		Seal 1.719 2.561 .500		4.00
		Brake Cleaner		1.00
		Trailer Conn Plug		1.00
		Tank Lid		1.00
		Shop Supplies		1.00
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 86.41	Total: 596.41

Palm Beach County Fleet Management Asset Maintenance History 2 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi, Trlr Mntd, Dual Reel 10195552

Work Order: 1609013 Meter: 0 In Date: 08/30/2016 **Closed:** 09/12/2016

Hours: 11.00

Work Completed	Parts Issued	Quantity
- Pm	Napagold Oil Filter	1.00
- Service trailer	10w30 Motor Oil	2.00
- Replace 4 tires	Napagold Fuel Filter	1.00
- Replace trailer jack repalce tool box	Napagold Fuel Filter	1.00
- Service pump	Seal 1.719 2.561 .500	4.00
- Clean and adjust brake	Non-chlor Brake Clnr	1.00
- Shop Supplies	762171406 205-75r15	4.00
	Startron 8oz Fuel Trt	1.00
	Pump Oil	2.00
	Jack Trailer	1.00
	Front Trl Tool Box	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00

Labor: 660.00

Parts: 1,111.24

Total: 1,771.24

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi, Trlr Mntd, Dual Reel

Work Order: 1800824 Meter: 0 In Date: 01/23/2018 Closed: 02/26/2018

Problem: pm/ hose reel

Work Completed

- Pm

- Service Trailer
- R&r hose reel, valve and hoses
- R&r trailer plug
- R&r brakeaway battery
- Tank lid cover replace
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa 10w30 Qt	2.00
Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
Male Trailer Connector	1.00
12v5amp/hour Battery	1.00
3/8 Ball Valve	1.00
Pw Hose 100	2.00
hose 2sc06	24.00
bushing	1.00
insert 90 degree	1.00
Female Socket	2.00
female plug	2.00
3/8 Male Plug	2.00
Cham Plt Pwr Spark Pl	2.00
Tank Lid	1.00
Tank Cover Lid	1.00
Hose Reel	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00
Lalar 000 00 Davis 004 47	T-1-1 4 504

Hours: 10.00 Comm: 0.00 Labor: 600.00 Parts: 964.17 Total: 1,564.17

Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi , Trlr Mntd, Dual Reel

Work Order: 1812333 Meter: 0 In Date: 12/04/2018 Closed: 12/12/2018

Problem: battery needs replaced

Work Completed		Parts Issued		Quantity
- check and replace battery		Battery		1.00
- test. replace starter, ignition switch and install in	nline fuse	Ignition Switch		1.00
- Shop Supplies		Powersport Starte	r	1.00
		Fuse Holder		1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 325.49	Total: 593.49

Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi , Trlr Mntd, Dual Reel

Work Order: 1902980 Meter: 0 In Date: 03/18/2019 Closed: 03/29/2019

Problem: pm service

Work Completed		Parts Issued	Quantity
- pm service		Napagold Oil Filter	1.00
- service trailer		Napa 10w30 Qt	2.00
- service brakes		Napagold Fuel Filter	1.00
- replace trailer plug		Napagold Fuel Filter	1.00
- replace 3 V belts to pump		Spark Plug	2.00
- replace 2 safety chain hooks		Startron 8oz Fuel Trt	1.00
- service pto pump		Pm-22-a Additive Dies	1.00
- replace 1 tire		Seal 1.719 2.561 .500	4.00
- fab and install unloader bracketand replace hydro hoses		Grease Cap	4.00
- Shop Supplies		Non-chlor Brake Clnr	2.00
		Male Trailer Connector	1.00
		Clevis Slip Hook-bulk	2.00
		Pump Oi L	1.00
		St205/75r15 Lr D	1.00
		Air Filter	1.00
		Hoses & amp; Fittings	1.00
		Belt	3.00
		Fhp/belt	3.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours: 15.50 C	omm: 0.00	Labor: 1,038.50 Parts: 648.14	Total: 1,686.64

Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi, Trlr Mntd, Dual Reel

Work Order: 2003236 Meter: 0 In Date: 03/31/2020 Closed: 04/21/2020

Problem: pm/ slack adjuster/ pump leaking/ battery plate rusted

Work Completed	Parts Issued	Quantity
- pm service	Napagold Oil Filter	1.00
- service trailer	Napa 10w30 Qt	2.00
- R&r two tires	Napagold Fuel Filter	1.00
- service Pto pump	Napagold Fuel Filter	1.00
- fabercate and relocate battery box/ R&r hardware, cables, and battery.	Spark Plug	2.00
- R&r pump belts three in total.	Pm-22-a Additive Dies	1.00
R&r carb. and adjust	Startron 8oz Fuel Trt	1.00
- R&r fuel line / flush fuel sys.	Air Filter	1.00
R&r check valve & fittings	Grease Cap	4.00
Shop Supplies	Seal 1.719 2.561 .500	4.00
	St20575r15d Carlisle Trail Hd	2.00
	Battery	1.00
	30w Pump Oil 1 Ltr	1.00
	Break Away System	1.00
	Fuel Line Hose	3.00
	Battery Box	1.00
	Bulk Battery Cable	8.00
	Bulk Battery Cable	12.00
	Fhp/belt	3.00
	4ga Straight-pos	1.00
	Battery Cable Lug	2.00
	Batt/trm	1.00
	Carburetor	1.00
	Fittings (mako)	1.00
	Blue Monster Teflon Tape	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours: 16.30 Comm: 0.00 Labor: 1,189.90 Parts: 1,349.39 Total: 2,539.29

Palm Beach County Fleet Management Asset Maintenance History 10195552 2014 K-BAR 157597 Pressure Cleaner, 4,000 Psi, Trlr Mntd, Dual Reel

Work Order: 2010116 Meter: 0 In Date: 10/07/2020 Closed: 10/27/2020

Problem: eng drops cyl after warm, loses spark, pump leaking at head, ribbons mark spot, price before repairi

Work Completed Parts Issued Quantity

- Test run equip, pressure pump leaking, need to replace entire pump, could Shop Supplies 1.00

not diagnose engine complaint without pump replacement. Customer

declined all repairs.

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2112832 Meter: 0 In Date: 12/03/2021 Closed: 12/10/2021

Problem: flat tire

Quantity **Work Completed Parts Issued** St20575r15d Carlisle Trail Hd 3.00 - Replace Tire **Shop Supplies** 1.00 - Shop Supplies Tire Disposal Fee 1.00 Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 281.69 Total: 354.69

Work Order: 2113025 Meter: 0 In Date: 12/09/2021 Closed: 12/09/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 74.80 Total Labor: 4,901.40 Total Comm: 0.00 Total Parts: 4,795.71