Total Hours: 208.00	Labor: 13,198.75	Parts: 12,493.64	Comm: 336.34		Charged	: 26028.72	
Work Order: 84264 Problem: PRE-I	8 Meter DELIVERY INSPECTIO			In Date:	08/12/2008	Closed:	08/12/2008
Work Completed							
- Pre-delivery Ins	pection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 84486 Problem: KEY A	4 Meter ALIKE PAD LOCKS FOR			In Date:	09/30/2008	Closed:	10/02/2008
Work Completed			Parts Issued			Qı	uantity
- Supply Matchin	g Locks For Cargo Doors	Pick Up And Delivery	Shop Supplies				1.00
- Shop Supplies			Locks				2.00
	Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 134	1.00	Total:	164.00
Work Order: 84604	0 Meter	: 154		In Date:	10/22/2008	Closed:	10/31/2008
Problem: CUST	OMER REQUESTS ST	EPS					
Problem: CUST Work Completed		EPS	Parts Issued			Qı	uantity
Work Completed		EPS ont Door.install Trailer Hitch	Parts Issued Shop Supplies			Qı	Jantity 1.00
Work Completed						Qı	•
Work Completed			Shop Supplies	t		Qı	1.00
Work Completed - Fabricate And Ir Step.			Shop Supplies 2560 Hitch Pin/clip	t		Qu	1.00 1.00
Work Completed - Fabricate And Ir Step.			Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set	t Parts: 30'	.79		1.00 1.00 1.00
Work Completed - Fabricate And Ir Step. - Shop Supplies Work Order: 84728	nstall 2 Steps On Each Fr Hours: 2.00	ont Door.install Trailer Hitch Comm: 0.00	Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set Hitch Step		.79 11/19/2008	Total:	1.00 1.00 1.00 1.00 421.79
Work Completed - Fabricate And Ir Step. - Shop Supplies Work Order: 84728	Hours: 2.00 Bours: 2.00 Hours: 2.00 Bours: 2.000 Bours: 2.00 Bours: 2.00 Bours	ont Door.install Trailer Hitch Comm: 0.00	Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set Hitch Step	Parts: 30 ²		Total: Closed:	1.00 1.00 1.00 1.00
Work Completed - Fabricate And Ir Step. - Shop Supplies Work Order: 84728 Problem: TOWE Work Completed	Hours: 2.00 3 Meter ED IN - L/R FLAT TIRE	ont Door.install Trailer Hitch Comm: 0.00	Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set Hitch Step Labor: 120.00	Parts: 30 ²		Total: Closed:	1.00 1.00 1.00 1.00 421.79 11/25/2008
Work Completed - Fabricate And Ir Step. - Shop Supplies Work Order: 84728 Problem: TOWE Work Completed - C/s L/r Flat Tire;	Hours: 2.00 3 Meter ED IN - L/R FLAT TIRE	ont Door.install Trailer Hitch Comm: 0.00 : 982 dewall; Replace Spare Tire; Put	Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set Hitch Step Labor: 120.00 Parts Issued	Parts: 30 ²		Total: Closed:	1.00 1.00 1.00 1.00 421.79 11/25/2008
Work Completed - Fabricate And Ir Step. - Shop Supplies Work Order: 84728 Problem: TOWE Work Completed - C/s L/r Flat Tire;	Hours: 2.00 3 Meter ED IN - L/R FLAT TIRE	ont Door.install Trailer Hitch Comm: 0.00 : 982 dewall; Replace Spare Tire; Put	Shop Supplies 2560 Hitch Pin/clip Super Hoop Step Set Hitch Step Labor: 120.00 Parts Issued Shop Supplies	Parts: 30 ² In Date:	11/19/2008	Total: Closed: Qu	1.00 1.00 1.00 421.79 11/25/2008 Jantity 1.00

Work Order: Problem:	847306 SISTERS TOWING & TRANSP	Meter: ORTATON T		ON	In Date:	11/19/2008	Closed:	11/20/2008
Work Com	pleted							
- Sisters To Fleet	owing & Transportaton Tow Fron	n 345 S. Cong	ress - Tow To Sr					
	Hours: 0.00		Comm: 78.00	Labor: 0.00	Parts: 0.0	0	Total:	78.00
Nork Order: Problem:	848076 INSTALL DROP DOWN LADDE	Meter: ER RACK.	1308		In Date:	12/10/2008	Closed:	12/17/2008
Work Com	pleted			Parts Issued			Qı	antity
- Remove	Existing Ladder Rack & Install Til	t Down Rack.r	nove Step Fr Front	Shop Supplies				1.00
Right Door	To Center Cargo Doors.		·	Drop Down Ladder	Rack			1.00
- Shop Sup	oplies							
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 1,3	76.00	Total:	1,676.00
Vork Order: Problem:	936538 P.M.SERVICE	Meter:	2805		In Date:	04/15/2009	Closed:	04/17/2009
Work Com	pleted			Parts Issued			Qu	antity
- Pm Servi	ce			Shop Supplies				1.00
- Install Ne	ew Decal			1372 Oil Filter Frn	n Ph2 Wix 51	372		1.00
- Shop Sup	oplies			5w20 Engine Oil				7.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 38.	65	Total:	218.65
Nork Order: Problem:	944825 PM SERVICE	Meter:	6706		In Date:	10/20/2009	Closed:	10/23/2009
				Parts Issued			Qu	antity
Work Com	pieted							
Work Com - P.m.servi				Shop Supplies				1.00
- P.m.servi		adder Rack		Shop Supplies 1372 Oil Filter Frm	ו Ph2 Wix 51	372		1.00
- P.m.servi	ce .djust&lubricate Pivot Point On L	adder Rack						
- P.m.servi - Service A	ce .djust&lubricate Pivot Point On L	adder Rack		1372 Oil Filter Frn				1.00

Nork Order: 1003746 Problem: P. M. SERVICE	Meter: 9116		In Date:	04/12/2010	Closed:	04/15/2010
Work Completed		Parts Issued			Qı	uantity
- P. M.		Shop Supplies				1.00
- Install bumper stickers.		1372 Oil Filter Frr	m Ph2 Wix 51	372		1.00
- Service & adjust ladder rack. Test.		5w20 Engine Oil				7.00
- Remove plugs from lower ball joints. Install	grease fittings & lubricate.					
- Shop Supplies						
Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 38.	.65	Total:	338.65
Nork Order: 1010831 Problem: P. M. SERVICE	Meter: 11712		In Date:	10/01/2010	Closed:	10/13/2010
Work Completed		Parts Issued			Qı	uantity
- P. M.		Shop Supplies				1.00
- Service ladder rack.		Ca8039 Air Filter L	bf Af1615 Wix	46418		1.00
- Verify. Airbag malfunction light on. Scan tro to dealer for warranty repair.	ouble code V0151-60-1c. Bring	G8018 Fuel Filter L 1372 Oil Filter Frr				1.00
- Transport & pick up vehicle at dealer (defe	ctive air bag module).	5w20 Engine Oil				7.00
- Dealer to replace air bag module.	-	31-20 Wiper Blade	es 20" Blade			2.00
- Shop Supplies		•				
Hours: 6.75	Comm: 0.00	Labor: 405.00	Parts: 60.	.07	Total:	465.07
Nork Order: 1011329 Problem: flash canceiver	Meter: 11818		In Date:	10/14/2010	Closed:	10/18/2010
Work Completed		Parts Issued			Qı	uantity
- Reflash Canceiver		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Work Order: Problem:	1012965 CHECK BATTERY, C/S: HAD	Meter: TO JUMP STA		EPERATE DAYS.	In Date:	11/22/2010	Closed:	11/30/2010
Work Com	pleted							
	to jump start. Recharge battery Ind lights were on.	, check chargir	ng system, check fo	or				
	Hours: 0.75		Comm: 0.00	Labor: 45.00	Parts: 0.0	0	Total:	45.00
Work Order: Problem:	1100857 Check battery, hard to start for	Meter: several days	13136		In Date:	01/21/2011	Closed:	01/31/2011
Work Com	npleted			Parts Issued			Qı	uantity
	ery is dead, recharge battery, cho battery. Send to dealer for warr	0 0	heck for draw &	Shop Supplies				1.00
- Transpor	t & pick up vehicle at dealer (de	fective battery).					
- Dealer to	o replace defective battery.							
- Shop Su	pplies							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 2.0	0	Total:	122.00
Work Order: Problem:	1102080 SCREW IN TIRE	Meter:	13631		In Date:	02/23/2011	Closed:	02/28/2011
Work Com	pleted							
- Check &	remove screw in R/front tire.							
	Hours: 0.25		Comm: 0.00	Labor: 15.00	Parts: 0.0	0	Total:	15.00
Work Order: Problem:	1103491 P. M. SERVICE	Meter:	14540		In Date:	03/31/2011	Closed:	04/11/2011
Work Com	npleted			Parts Issued			Qı	uantity
- P. M. Ser	vice.			Shop Supplies				1.00
- Service la	adder rack, lube, etc.			1372 Oil Filter Frr	n Ph2 Wix 51	372		1.00
- Shop Su	pplies			5w20 Engine Oil				7.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 38.	63	Total:	263.63

Work Order: 1110340 Problem: P.M.SERVICE	Meter:	17588		In Date:	09/28/2011	Closed:	09/29/2011
Work Completed			Parts Issued			Qı	uantity
- P.m.service.			Shop Supplies				1.00
- Service Latt.rack.lubricate&test.			G8018 Fuel Filter L	bf G6593 Wix	33595		1.00
- Repair Nail In R/rear Tire.			1372 Oil Filter Frn	n Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-20 Wiper Blade	s 20" Blade			2.00
Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 51.	97	Total:	336.97
Work Order: 1202522 Problem: pm service	Meter:	21409		In Date:	03/14/2012	Closed:	03/19/2012
Work Completed			Parts Issued			Q	uantity
- pm service			Shop Supplies				1.00
- service ladder rack			1372 Oil Filter Frn	n Ph2 Wix 51	372		1.00
- Shop Supplies			G8018 Fuel Filter L	bf G6593 Wix	33595		1.00
			5w20 Engine Oil				7.00
Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 34.	13	Total:	259.13
Work Order: 1207712 Problem: sevice call	Meter:	24584		In Date:	08/14/2012	Closed:	08/15/2012
Work Completed							
- Tire Service I 95 Exit Ramp of Palm Beach	Lakes Blvd - s	evice call					
Hours: 0.00		Comm: 66.34	Labor: 0.00	Parts: 0.0	0	Total:	66.34
Work Order: 1207758 Problem: CHECK FRONR TIRES	Meter:	24836		In Date:	08/16/2012	Closed:	08/17/2012
Work Completed			Parts Issued			Qı	uantity
- replace feft front tire remove right front ti	re from rim a	nd switch with	Shop Supplies				1.00
spare tire balance tires			744395900 245/75	5r16 245/75r1	6 Wrangler H	t	1.00
- Shop Supplies			Tire Disposal Fee				1.00
Hours: 2.25		Comm: 0.00	Labor: 135.00	Parts: 199	9.17	Total:	334.17

Nork Order: Problem:		Meter:	26819		In Date:	01/18/2013	Closed:	01/30/2013
Work Com				Parts Issued			Qı	antity
- pm				Ca8039 Air Filter Lbf				1.00
	eds 3 new tires mount	balance add n2 rotate to	o front	1372 Oil Filter				1.00
		ry test multiple times ba		Napa Quart 5w20				7.00
ck charging	0	,		31-20 Wiper Blades 20				2.00
- operate s	service luvel and inspec	ert ladder rack		744395900 245-75r1	6			3.00
- Shop Sup	pplies			Battery 65				1.00
				Shop Supplies				1.00
				Tire Disposal Fee				3.00
	Hours: 6.50		Comm: 0.00	Labor: 390.00	Parts: 932	2.80	Total:	1,322.80
	1306086	Meter:						
	not running ck ac			Parts Issued			Qı	antity
Problem: Work Com	not running ck ac npleted e light was on scan and	l fund code po301 po31	•	Dg-508 Ignition Coil			Qı	2.00
Problem: Work Com - ck engine pinpoint te	not running ck ac npleted e light was on scan and est and 2 bad coils 1 &	l fund code po301 po31 2 replace coils clear cod	les and test drive				Qı	•
Problem: Work Com - ck engine pinpoint te - ck ac not	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing	l fund code po301 po31	les and test drive	Dg-508 Ignition Coil			Qı	2.00
Problem: Work Com - ck engine pinpoint te	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies	l fund code po301 po31 2 replace coils clear cod	les and test drive blem at this time	Dg-508 Ignition Coil Shop Supplies				2.00 1.00
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75	l fund code po301 po31 2 replace coils clear cod g test and found no pro	les and test drive blem at this time Comm: 0.00	Dg-508 Ignition Coil	Parts: 139		Total:	2.00 1.00 484.49
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171	l fund code po301 po31 2 replace coils clear cod	les and test drive blem at this time Comm: 0.00	Dg-508 Ignition Coil Shop Supplies	Parts: 139 In Date:	9.49 07/18/2013	Total:	2.00 1.00 484.49
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup /ork Order:	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm	l fund code po301 po31 2 replace coils clear cod g test and found no pro	les and test drive blem at this time Comm: 0.00	Dg-508 Ignition Coil Shop Supplies			Total: Closed:	2.00 1.00 484.49
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup /ork Order: Problem: Work Com	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm	l fund code po301 po31 2 replace coils clear cod g test and found no pro	les and test drive blem at this time Comm: 0.00	Dg-508 Ignition Coil Shop Supplies Labor: 345.00			Total: Closed:	2.00 1.00 484.49 07/25/201
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup /ork Order: Problem:	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm npleted	l fund code po301 po31 2 replace coils clear cod g test and found no pro	les and test drive blem at this time Comm: 0.00	Dg-508 Ignition Coil Shop Supplies Labor: 345.00 Parts Issued			Total: Closed:	2.00 1.00 484.49 07/25/201
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup /ork Order: Problem: Work Com - pm - svc ladde	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm npleted er rack	I fund code po301 po31 2 replace coils clear cod g test and found no pro Meter:	les and test drive blem at this time Comm: 0.00 28759	Dg-508 Ignition Coil Shop Supplies Labor: 345.00 Parts Issued Napagold Fuel Filter			Total: Closed:	2.00 1.00 484.49 07/25/201 aantity 1.00
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup /ork Order: Problem: Work Com - pm - svc ladde	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm npleted er rack	l fund code po301 po31 2 replace coils clear cod g test and found no pro	les and test drive blem at this time Comm: 0.00 28759	Dg-508 Ignition Coil Shop Supplies Labor: 345.00 Parts Issued Napagold Fuel Filter Napagold Oil Filter			Total: Closed:	2.00 1.00 484.49 07/25/201 antity 1.00 1.00
Problem: Work Com - ck engine pinpoint te - ck ac not - Shop Sup Vork Order: Problem: Work Com - pm - svc ladde - verify tpr	not running ck ac npleted e light was on scan and est and 2 bad coils 1 & t cold perform pinpoing pplies Hours: 5.75 1307171 pm npleted er rack ms light on found nail i	I fund code po301 po31 2 replace coils clear cod g test and found no pro Meter:	les and test drive blem at this time Comm: 0.00 28759	Dg-508 Ignition Coil Shop Supplies Labor: 345.00 Parts Issued Napagold Fuel Filter Napagold Oil Filter Napa Quart 5w20			Total: Closed:	2.00 1.00 484.49 07/25/2013 iantity 1.00 1.00 7.00

Nork Order: 140 [°] Problem: pm	1078	Meter:	32584		In Date:	01/31/2014	Closed:	02/10/2014
Work Complete	ed			Parts Issued			Q	uantity
- pm				Napagold Oil Filter				1.00
- svc ladder racl	<			Napa Quart 5w20				7.00
- repair rr tire				Wiper Blade				2.00
- Shop Supplies				Shop Supplies				1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 40.	88	Total:	325.88
Vork Order: 1404 Problem: ck a	1642 c blow cold but when weat		34661 hot		In Date:	05/13/2014	Closed:	05/19/2014
Work Complete	ed			Parts Issued			Q	uantity
	perform sys test and found evacuate and recharge sys	00	vap remove evap	Shop Supplies				1.00
- Shop Supplies								
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 2.0	0	Total:	302.00
/ork Order: 1409 Problem: PM		Meter:	37613		In Date:	09/23/2014	Closed:	09/30/2014
Work Complete	ed			Parts Issued			Q	uantity
- pm				Gm Steel Fuel Line				2.00
- verify needs tw	vo tires replace 2 tires mou	int blanance a	dd n2	Napagold Fuel Filter				1.00
- svc inspect lub	be ladder rack			Napagold Oil Filter				1.00
- Shop Supplies				Napa Quart 5w20				7.00
				744395900 245-75r	16			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 5.25		Comm: 0.00	Labor: 315.00	Parts: 526			841.43

Work Order: 1502806 Problem: pm	Meter: 40937		In Date:	03/18/2015	Closed:	03/27/201
Work Completed		Parts Issued			Q	uantity
- pm		Napagold Oil Filter				1.00
- svc inspect ladder rack		Napa Quart 5w20				7.00
- Shop Supplies		Wiper Blade				2.00
		Washer Fl				1.00
		Shop Supplies				1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 42.	.56	Total:	267.56
Nork Order: 1506304 Problem: ac not working all the time	Meter: 42589 on and off with cool		In Date:	06/23/2015	Closed:	06/30/201
Work Completed		Parts Issued			Q	uantity
- ck ac is nnot working properly perfo	m pinpoint test and found leaking	Valve Ai				1.00
vacuum reservior remove evap code re	place vacuum reservoir recharge sys	Vacuum Resevoir				1.00
and leak test		Disc Pad				1.00
 test drive for ac problem and found a pinpoint test and found warp front rote 	5	Disc Pad				1.00
calipers and replace pads	ors resurface front and rear rotors svc	B Fluid Dot 3-32oz				1.00

- test drive before and after repair

- Shop Supplies

Hours: 14.50

Comm: 0.00

Parts Issued		Quantity
Valve Ai		1.00
Vacuum Resevoir		1.00
Disc Pad		1.00
Disc Pad		1.00
B Fluid Dot 3-32oz		1.00
Brake Cleaner		2.00
Shop Supplies		1.00
Labor: 870.00	Parts: 154.81	Total: 1,024.81

Nork Order: 15 [°] Problem: p.m		Meter:	44010		In Date:	10/15/2015	Closed:	10/29/201
Work Complet	ted			Parts Issued			Qı	antity
- pm				Napagold Oil Filter				1.00
- 2 tires rr				Napa Quart 5w20				7.00
- install how m	ny driving decal			Wiper Blade				2.00
- svc ladder ra	ck			Washer Fluid Conce	entr			1.00
- fill all tires w	ith nitrogen			Napagold Air Filte	r			2.00
- Shop Supplie	25			Mac Wite Lithium C	Gres			1.00
				744395900 245-75	5r16			2.00
				Drain Plug				1.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 6.00		Comm: 0.00	Labor: 360.00	Parts: 516	6.12	Total:	876.12
Work Complet			- install during days	Parts Issued			Qı	antity
•	hicle to and from Kaufs no	rth palm beach t	o install drop down					
ladder rack.		- I	o install drop down					1.00
			o install drop down	Ez Down Ladder Ra				1.00
- Shop Supplie	۱S.		o install drop down	Ez Down Ladder Ra Labor				1.00 1.00
- Shop Supplie				Ez Down Ladder Ra Labor Shop Supplies	ack Ds			1.00 1.00 1.00
	Hours: 2.00		Comm: 0.00	Ez Down Ladder Ra Labor	ack Ds Parts: 2,7			1.00 1.00 1.00 2,918.75
- Shop Supplie Nork Order: 160 Problem: ac	Hours: 2.00	Meter:	Comm: 0.00	Ez Down Ladder Ra Labor Shop Supplies	ack Ds	98.75 02/17/2016		1.00 1.00 1.00 2,918.75
Nork Order: 160	Hours: 2.00 01663 blow warm		Comm: 0.00	Ez Down Ladder Ra Labor Shop Supplies	ack Ds Parts: 2,7		Closed:	1.00 1.00 1.00 2,918.75
Nork Order: 160 Problem: ac Work Complet	Hours: 2.00 01663 blow warm	Meter:	Comm: 0.00 45986	Ez Down Ladder Ra Labor Shop Supplies Labor: 120.00	Parts: 2,7 In Date:		Closed:	1.00 1.00 2,918.75 02/23/201
Nork Order: 160 Problem: ac Work Complet - ck ac blow w	Hours: 2.00 D1663 blow warm	Meter: test leak test and	Comm: 0.00 45986 I found leaking	Ez Down Ladder Ra Labor Shop Supplies Labor: 120.00 Parts Issued	Parts: 2,7 In Date:		Closed:	1.00 1.00 2,918.75 02/23/201
Nork Order: 160 Problem: ac Work Complet - ck ac blow w	Hours: 2.00 D1663 blow warm ted arm perfomr sys pressure t	Meter: test leak test and	Comm: 0.00 45986 I found leaking	Ez Down Ladder Ra Labor Shop Supplies Labor: 120.00 Parts Issued High Side Schrader	Parts: 2,7 In Date:		Closed:	1.00 1.00 2,918.75 02/23/201 antity 1.00
Nork Order: 160 Problem: ac Work Complet - ck ac blow w schrader valves	Hours: 2.00 D1663 blow warm ted arm perfomr sys pressure t	Meter: test leak test and	Comm: 0.00 45986 I found leaking	Ez Down Ladder Ra Labor Shop Supplies Labor: 120.00 Parts Issued High Side Schrader valve assy	Parts: 2,7 In Date: Valve		Closed:	1.00 1.00 2,918.75 02/23/201 antity 1.00 1.00
Nork Order: 160 Problem: ac Work Complet - ck ac blow w schrader valves	Hours: 2.00 D1663 blow warm ted arm perfomr sys pressure t	Meter: test leak test and	Comm: 0.00 45986 I found leaking	Ez Down Ladder Ra Labor Shop Supplies Labor: 120.00 Parts Issued High Side Schrader valve assy E8 A/c Oil Univ W E	Parts: 2,7 In Date: Valve		Closed:	1.00 1.00 2,918.75 02/23/201 antity 1.00 1.00 1.00

Work Order: Problem:	1603817 Pm service	Meter:	46676		In Date:	04/12/2016	Closed:	04/20/2016
Work Com	pleted			Parts Issued			Qu	uantity
- Pm servio	ce.			Napagold Oil Filter				1.00
- Operate	and service ladder rack.			Napa Quart 5w20				7.00
- Repair rig	ght rear tire.add N2.			Washer Fluid Concer	ntr			1.00
- Shop Sup	oplies			Wd40 16oz				1.00
				Shop Supplies				1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 39.	10	Total:	324.10
Work Order: Problem:	1609862 Have to jump start all the time.	Meter:	49432		In Date:	09/21/2016	Closed:	09/29/2016
Work Com	pleted			Parts Issued			Qı	uantity
- Test start	ing and charging system.replac	e bad battery.		Battery				1.00
- Shop Sup	oplies	-		Shop Supplies				1.00
	Hours: 0.75		Comm: 0.00	Labor: 45.00	Parts: 126	6.43	Total:	171.43
Work Order: Problem:	1612010 Pm service	Meter:	50164		In Date:	11/21/2016	Closed:	11/30/2016
Work Com	pleted			Parts Issued			Qı	uantity
- P.m.servi	ce.			Napagold Oil Filter				2.00
- Service L	adder Rack.			Napa Quart 5w20				14.00
- Rotate A	nd Balance Tires			Washer Fluid Concer	ntr			2.00
- Shop Sup	oplies			20" Wiper Blade				4.00
				Napagold Air Filter				2.00
				Shop Supplies				1.00
	Hours: 5.75		Comm: 0.00	Labor: 345.00	Parts: 95.	63	Total:	440.63

Work Order:1612981Meter:Problem:Step broken	50649		In Date:	12/20/2016	Closed:	12/27/2016
Work Completed		Parts Issued			Qu	uantity
- Fabricate and repair broken side step.		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 2.0	00	Total:	92.00
Work Order:1704868Meter:Problem:Pm Service	52574		In Date:	05/16/2017	Closed:	05/22/201
Work Completed		Parts Issued			Qı	uantity
- Pm Service.		Napagold Oil Filter				1.00
- Replace three tires and rotate right front to right rear.		Napa Quart 5w20				7.00
- Service ladder rack.		Washer Fluid Concer	ntr			1.00
- Shop Supplies		20" Wiper Blade				2.00
		Wd40 Spr				1.00
		744395900 245-75r	16			3.00
		Shop Supplies				1.00
		Tire Disposal Fee				3.00
Hours: 7.00	Comm: 0.00	Labor: 420.00	Parts: 653	3.42	Total:	1,073.42
Work Order:1712573Meter:Problem:Pm Service	56789		In Date:	12/20/2017	Closed:	12/28/201
Work Completed		Parts Issued			Qı	uantity
- Pm Service.		Napagold Oil Filter				1.00
- Rotate and balance four tires.		Napa Quart 5w20				7.00
- Service ladder rack.		Washer Fluid Concer	ntr			1.00
- Repair transmission cooler line at radiator leaking.		20" Wiper Blade				2.00
- Shop Supplies		Shop Supplies				1.00
Hours: 6.75	Comm: 0.00	Labor: 405.00	Parts: 40.	.64	Total:	445.64

02/09/2018 Closed: 02/26/2018

Total: 271.65

In Date:

Work Order:1801568Meter:57433Problem:Driver door lock and side door locks inop.

Parts Issued Quantity **Work Completed** Door Latch W/cable 1.00 - Repair left front door lock, both rear cargo door locks and right side cargo door lock. 1.00 latch - Shop Supplies latch 1.00 Door Handle W/cable 1.00 Door Remote 1.00 door latch remote control 1.00 Latch 1.00 1.00 retainer 1.00 Shop Supplies Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 655.00 Total: 955.00 Work Order: 1807342 Meter: 57870 In Date: 07/19/2018 Closed: 07/30/2018 Problem: PM Service Parts Issued Work Completed Quantity 7.00 Napa Quart 5w20 - Pm service. Napagold Oil Filter 1.00 - Service ladder rack. 20" Wiper Blade 2.00 - Shop Supplies Washer Fluid Concentr 1.00 Shop Supplies 1.00 Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 42.10 Total: 342.10 Work Order: 1811438 Meter: 58969 In Date: 11/06/2018 Closed: 11/13/2018 Problem: Towed in Left rear tire flat.Side walldamage. Parts Issued Quantity **Work Completed** 744395900 245-75r16 1.00 - Replace and balance left rear tire. Shop Supplies 1.00 - Shop Supplies Tire Disposal Fee 1.00

Hours: 1.00

Comm: 0.00

Labor: 67.00

Parts: 204.65

		6 2008 FOF				i ng		
Work Order: Problem:	1811760 Towed in for flat tire.Side wall o	Meter:	59118		In Date:	11/06/2018	Closed:	11/15/2018
		lanago						
Work Com	•							
- Tow Fror	m: 245 South Congress Ave Delra	ау То: 13026 Ја	0		_			
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order:		Meter:	59986		In Date:	01/16/2019	Closed:	01/28/2019
Problem:	PM Service and wiper blades							
Work Con	npleted			Parts Issued			Qı	antity
- Pm Servi	ice.			Napa Quart 5w20				7.00
- Rotate a	nd balance tires.correct N2.relea	rn Tpms.		Napagold Oil Filter				1.00
- Service la	adder rack.			20" Wiper Blade				2.00
- Wash ex	terior and vacume debris under	hood.		Shop Supplies				1.00
- Shop Su	pplies							
1	Hours: 7.00		Comm: 0.00	Labor: 469.00	Parts: 42.	15	Total:	511.15
Work Order:	1904557	Meter:	61984		In Date:	04/26/2019	Closed:	05/06/2019
Problem:	Runs rough and no power.Che	ck ac.						
	npleted			Parts Issued			Qı	antity
Work Com	- Replace three tires and balance all four.fill all tire with notrogen.test drive			i ai to iooaca				-
- Replace	three tires and balance all four fi	ll all tire with n	otrogen test drive	744395900 245-75r	16			3.00
- Replace	three tires and balance all four.fi d seperated caused heavy vibrati		otrogen.test drive	744395900 245-75r	16			3.00
- Replace prior found		on.	5	744395900 245-75r Freon Sr Shop				
- Replace prior found - Check a/ valves.evad	d seperated caused heavy vibrati	on. nspection foun	d leaking schrader	744395900 245-75r				2.00
 Replace prior found Check a/ valves.evad for leaks. 	d seperated caused heavy vibrati /c and found low freon.perform i cuate and replace both schrader	on. nspection foun valves.recharge	d leaking schrader e system and check	744395900 245-75r Freon Sr Shop E8 A/c Oil Univ W Dy	уe			2.00 1.00
 Replace prior found Check a/ valves.evad for leaks. C/s runs 	d seperated caused heavy vibrati /c and found low freon.perform i cuate and replace both schrader rough.test drive,scan and was u	on. nspection foun valves.recharge	d leaking schrader e system and check	744395900 245-75r Freon Sr Shop E8 A/c Oil Univ W Dy A/c Valve Core	уe			2.00 1.00 1.00
- Replace prior found - Check a/ valves.evad for leaks.	d seperated caused heavy vibrati /c and found low freon.perform i cuate and replace both schrader rough.test drive,scan and was un e.	on. nspection foun valves.recharge	d leaking schrader e system and check	744395900 245-75r Freon Sr Shop E8 A/c Oil Univ W Dy A/c Valve Core High Side Schrader V	уe			2.00 1.00 1.00 1.00

Work Order: Problem:	1911037 PM Service.	Meter:	66231		In Date:	10/25/2019	Closed:	10/31/2019
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servio	ce			Napagold Oil Filter				1.00
- Repaired	third brake light bulb.			Napa Quart 5w20				7.00
- Service la	adder rack.			Washer Fluid Concer	ntr			1.00
- Repaired	right rear tire.			20" Wiper Blade				2.00
- Shop Sup	oplies			Boxed Miniatures				2.00
				Shop Supplies				1.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 48.	40	Total:	559.40
Work Order:		Meter:	66381		In Date:	11/01/2019	Closed:	11/13/2019
Problem:	ROAD CALL, DEAD BATTER	ΥY						
Problem: Work Com	·	Ŷ		Parts Issued			Qı	uantity
Work Com	·	Y		Parts Issued Battery			Qu	Jantity 1.00
Work Com - C/k and r - Drive to I	pleted		e back to Sr Shop				Qı	•
Work Com - C/k and r - Drive to I	replace bad battery. Lantana and Jog to jump start v ng bad battery.		e back to Sr Shop	Battery			Qı	1.00
Work Com - C/k and r - Drive to l for replacin	replace bad battery. Lantana and Jog to jump start v ng bad battery.		e back to Sr Shop Comm: 0.00	Battery	Parts: 147	7.81		1.00
Work Com - C/k and r - Drive to I for replacin - Shop Sup Work Order:	replace bad battery. Lantana and Jog to jump start on g bad battery. oplies Hours: 2.25	vehicle and drive Meter:	Comm: 0.00	Battery Shop Supplies	Parts: 147 In Date:	7.81 02/12/2020	Total:	1.00 1.00 312.06
Work Com - C/k and r - Drive to I for replacin - Shop Sup Work Order:	replace bad battery. Lantana and Jog to jump start of bad battery. Oplies Hours: 2.25 2001515 Stuck in mud at Hagen Ranch	vehicle and drive Meter:	Comm: 0.00	Battery Shop Supplies		-	Total: Closed:	1.00 1.00 312.06
Work Com - C/k and r - Drive to I for replacin - Shop Sup Work Order: Problem: Work Com - Drive to a	replace bad battery. Lantana and Jog to jump start of bad battery. Oplies Hours: 2.25 2001515 Stuck in mud at Hagen Ranch	vehicle and drive Meter: h Library.	Comm: 0.00 68076	Battery Shop Supplies Labor: 164.25		-	Total: Closed:	1.00 1.00 312.06 02/18/2020
Work Com - C/k and r - Drive to I for replacin - Shop Sup Work Order: Problem: Work Com - Drive to a	apleted replace bad battery. Lantana and Jog to jump start with bad battery. Deplies Hours: 2.25 2001515 Stuck in mud at Hagen Ranch Apleted and from Hagen Ranch Library from stuck in mud.	vehicle and drive Meter: h Library.	Comm: 0.00 68076	Battery Shop Supplies Labor: 164.25 Parts Issued		-	Total: Closed:	1.00 1.00 312.06 02/18/2020

Work Order: 2004128 Problem: PM Service.	Meter:	69371		In Date:	04/24/2020	Closed:	05/26/2020
Work Completed			Parts Issued			Qı	uantity
- Pm Service.			Napa Quart 5w20				7.00
- Rotate and balance tires.			Napagold Oil Filte	r			1.00
- Service ladder rack.			20" Wiper Blade				2.00
- Shop Supplies			Washer Fluid Concentr				1.00
			Shop Supplies				1.00
Hours: 5.50		Comm: 0.00	Labor: 401.50	Parts: 46.	63	Total:	448.13
Work Order: 2007181 Problem: Transition Prep Charge	Meter:	69371		In Date:	07/22/2020	Closed:	07/22/2020
Work Completed							
- Transition Prep Charge							
Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 0.0	0	Total:	146.00

10174446

Palm Beach County Fleet Management Asset Maintenance History 2008 FORD E250 Van, Cargo, 3/4 Ton, W/Heavy Duty Tow Pkg

Work Order: 2100867 Meter: 69372 01/26/2021 Closed: 01/29/2021 In Date: Problem: pm service, get ready to transfer Parts Issued **Work Completed** Quantity Napa Quart 5w20 7.00 - Preventive Maint, Service 1.00 Napagold Oil Filter - Prep Vehicle For Reasignment Lt245/75r16/10 Mich Agilis 2.00 - Replaced Worn Upper And Lower Ball Joints, Replaced Worn Front Lower Shock Bushings. 1.00 Battery - Replaced 2 Worn Tires 20" Wiper Blade 2.00 - Performed Front End Alignment, Greased Front End Insulator Nut 2.00 - Load Test And Replace Bad Battery Ball Joint 2.00 - Replaced Frozen Front Brake Caliper Brackets **Ball Joint** 2.00 - Shop Supplies Shock 2.00 1.00 Caliper Bracket Hardware Kit 2.00 L/f Caliper Bracket 1.00 Shop Supplies 1.00 Tire Disposal Fee 2.00 Hours: 17.00 Comm: 0.00 Labor: 1,241.00 Parts: 1,754.17 Total: 2,995.17 Work Order: 2102225 02/25/2021 Closed: 02/25/2021 Meter: 69603 In Date: Problem: 1 - Detail Vehicle Wash Ticket(s) Issued **Work Completed** - 1 - Detail Vehicle Wash Ticket(s) Issued Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00 Work Order: 2104357 Meter: 70374 04/19/2021 Closed: 04/28/2021 In Date: Problem: ac and defrost not working Parts Issued Quantity Work Completed **Blower Resistor** 1.00 - Ck A/c Blower Inop, Replace Blower Motor Assembly & Resistor Blower Motor Assy 1.00 Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 85.86 Total: 231.86

Work Order:		Meter:	70423		In Date:	05/07/2021	Closed:	05/10/202
Problem:	needs fire x							
Work Com	pleted			Parts Issued			Qı	uantity
- replace f	ire x			Used Fire X Refurbis	shed			1.00
·	Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 13.	53	Total:	50.03
Work Order:		Meter:	71020		In Date:	07/20/2021	Closed:	08/10/202
Problem:	pm service							
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Napa Quart 5w20				7.00
				Napagold Oil Filter				1.00
				Napagold Air Filter				1.00
				Washer Fluid Conce	entr			1.00
				20" Wiper Blade				2.00
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 41.	55	Total:	333.55
Work Order:		Meter:	72494		In Date:	09/29/2021	Closed:	11/01/202
Problem:	head light out & horn not work	king						
Work Com	pleted			Parts Issued			Qı	uantity
- diagnose	e horn not working - test all fus	es n check for g	ood signal -	Set Horn Asy				1.00
replaced h	orn		U U	Halogen Sealed Bea	ams			2.00
 replace bassembly's 	ooth head lights - r&r front hea	d light grill - rep	blaced 2 bulb					
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 53.	96	Total:	272.96
Work Order: Problem:	2112449 check windshield for leaks	Meter:	72531		In Date:	11/22/2021	Closed:	12/14/202
Work Com	pleted							
- rust issue	es							

2/1/2022 2:18:30 PM		Palm Beach County Fleet Management Asset Maintenance History 10174446 2008 FORD E250 Van, Cargo, 3/4 Ton, W/Heavy Duty Tow Pkg						
Work Order: 2113263	Met	er: 72531		In Date:	12/15/2021	Closed:	12/15/2021	
Problem: Transition	Prep Charge							
Work Completed								
- Transition Prep Cha	rge							
F	lours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00)	Total:	146.00	
Total Hours: 208.00	Total Labor	: 13,198.75	Total Comm: 336.3	4	Total Parts	: 12,493.64	1	