

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 88.70 Labor: 5,836.10 Parts: 3,283.95 Comm: 126.89 Charged: 9246.94

Work Order: 1510077 **Meter:** 361 **In Date:** 10/05/2015 **Closed:** 10/05/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1600439 **Meter:** 2800 **In Date:** 01/13/2016 **Closed:** 01/20/2016
Problem: Trailer battery not charging message on dash.

Work Completed

- Diagnose trailer battery not charging message on dash.replace defective trailer connector.retest system.

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 14.20 Total: 104.20

Work Order: 1602565 **Meter:** 5238 **In Date:** 03/10/2016 **Closed:** 03/17/2016
Problem: Pm service.

Work Completed

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 36.52 Total: 216.52

Parts Issued	Quantity
Female Conn Socket	1.00
Fab Loom-split Poly	3.00
Shop Supplies	1.00
Labor: 90.00 Parts: 14.20 Total: 104.20	

Parts Issued	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00
Labor: 180.00 Parts: 36.52 Total: 216.52	

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1608037 **Meter:** 10415 **In Date:** 08/04/2016 **Closed:** 08/23/2016
Problem: P.M. Service.Install strobe lights.Remove printer shelf.

Work Completed

- P.m. Service.
- Install four corner strobe lights.fabricate and install wiring and switch.
- Remove printer stand per request.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Rocker Led Blk Ambe	1.00
Fuse Holder	1.00
Vtx609c Led Strobe Cl	2.00
Vtx609a Led Strobe Am	2.00
Fab Loom-split Poly	25.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 11.25

Comm: 0.00

Labor: 675.00

Parts: 526.00

Total: 1,201.00

Work Order: 1609852 **Meter:** 11582 **In Date:** 09/21/2016 **Closed:** 09/28/2016
Problem: Advance trac light on and no trottle response.

Work Completed

- Transport vehicle to dealer for defective throttle body.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 2.00

Total: 122.00

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1801344 **Meter:** 30855 **In Date:** 02/05/2018 **Closed:** 02/08/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Check battery and charging system.after charging battery fully ,battery failed load test.replace defective battery and cleaned terminals.
- Check and replace defective trailer plug connector and fabricate wire as needed.
- Replace two front tires.balance and rotate all four tires.
- Complete alignment and road test.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Silicone Spray 10oz	1.00
Battery Motorcraft	1.00
trailer plug	1.00
183114470 P245-70r17	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.75

Comm: 0.00

Labor: 525.00

Parts: 640.61

Total: 1,165.61

Work Order: 1803923 **Meter:** 34276 **In Date:** 04/16/2018 **Closed:** 04/19/2018
Problem: Right outside mirror fell off.

Work Completed

- Inspect and replace missing mirror glass .
- Shop Supplies

Parts Issued

Quantity

seal	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 48.29

Total: 78.29

Work Order: 1805120 **Meter:** 35729 **In Date:** 05/17/2018 **Closed:** 05/24/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 42.97

Total: 222.97

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1904834 **Meter:** 50117 **In Date:** 05/02/2019 **Closed:** 05/13/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Pressure test and inspect cooling system . Flush and refill coolant .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Anti Freeze Motorcraft	2.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 335.00 Parts: 94.98 Total: 429.98

Work Order: 1909772 **Meter:** 55125 **In Date:** 09/23/2019 **Closed:** 10/07/2019
Problem: P.M. service and left front tire going flat .

Work Completed

- P.m. service.
- Repair left front tire . Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Ford Triton Pvc Swc	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 53.32 Total: 345.32

Work Order: 2000947 **Meter:** 59884 **In Date:** 01/28/2020 **Closed:** 02/04/2020
Problem: PM Service

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 51.16 Total: 270.16

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2006548 **Meter:** 64892 **In Date:** 07/01/2020 **Closed:** 07/09/2020
Problem: Right front tire going flat . P.M. service.

Work Completed

- Repair right front tire and balance . Nitrofill all.
- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Inspect and service rear differential .
- Replace two tires . Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Cabin Air Filter	1.00
Px Grey Rtv Silicone	1.00
1qt Syngear Oil 75-90	3.00
245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 582.41

Total: 1,056.91

Work Order: 2101728 **Meter:** 69400 **In Date:** 02/16/2021 **Closed:** 02/17/2021
Problem: Right rear tire going flat .

Work Completed

- Tire Repair. Rr tire going flat. Locate leaking screw, remove and repair hole. Reinstall tire on wheel and balance. Reinstall wheel on vehicle.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

2/1/2022
2:40:24 PM

Palm Beach County Fleet Management Asset Maintenance History
10199061 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2200198 **Meter:** 72340 **In Date:** 01/06/2022 **Closed:** 01/11/2022
Problem: No start

Work Completed

Parts Issued

Quantity

- Computer diagnose no start . Code P06e9 . Test and replace defective starter relay . Clear codes and retest .

Relay 1.00

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 14.64 Total: 87.64

Work Order: 2200313 **Meter:** 72337 **In Date:** 01/10/2022 **Closed:** 01/10/2022
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

Work Order: 2200569 **Meter:** 72340 **In Date:** 01/18/2022 **Closed:** 01/18/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 88.70 Total Labor: 5,836.10 Total Comm: 126.89 Total Parts: 3,283.95