



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51450559
Invoice Number: 55345-51450559

Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: DARTHURS **VIN:** 2C7WDGBG7ER476551
Created By: DARTHURS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Jul 31, 2018	10:51 AM
Started		
Completed	Jul 31, 2018	11:30 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	169,211	DH

WorkOrder Notes

Line	Comment
10	Tech performed PM-A Part# P9600 Qty:1

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
31-Jul-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 8



WorkOrder: 51556816
Invoice Number: 55345-51556816

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By:

CKARLENS

Created By:

CKARLENS

Class:

WO

Arrangement:

Unassigned

Potential Warranty:

No

Equipment:

4817

Dodge Grand Caravan Braun Entervan SE

2C7WDGBG7ER476551

VIN:

Status:

40

Priority:

1

Driver:

Phone:

ETA:

Chronology	
Reported Started	Sep 13, 2018 2:14 PM
Completed	Sep 13, 2018 10:59 PM
Down Time	

Meter	Reading	UOM
WO		DH
Life	173,633	DH
System	1/3,686	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: CAUSE: CORRECTION:

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51888591
Invoice Number: 55345-51888591

Client Department:

MRC:	55345M	Equipment:	4817
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM A		VIN:	2C7WDGBG7ER476551
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Dec 21, 2018	1:04 PM
Started	Dec 21, 2018	
Completed	Dec 23, 2018	4:42 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	182,452	DH
System	182,532	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Perform and completed PMA Service Replaced air filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Dec-18	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-Dec-18	PA4456	FILTER, AIR, CARAVAN, '14 SAME AS WIX 49737	1.00	4.99	4.99



WorkOrder: 52020868
Invoice Number: 55345-52020868

Client Department:

MRC:	55345M	Equipment:	4817
WO Desc:			Dodge Grand Caravan Braun Entervan SE
	PM A	VIN:	2C7WDGBG7ER476551
Requested By:	VAMRITTEEMAL	Status:	40
Created By:	VAMRITTEEMAL	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Jan 22, 2019	10:05 AM
Started	Jan 22, 2019	
Completed	Jan 22, 2019	11:01 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	186,614	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service
	CAUSE: Preventive Maintenance
	CORRECTION: Perform and completed PMA Service

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Jan-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
22-Jan-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52346008

Invoice Number: 55345-52346008

Client Department:

MRC: 55345M

WO Desc:
PM A

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

VIN:
Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	May 20, 2019	12:00 AM
Started	May 21, 2019	
Completed	May 21, 2019	12:19 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	195,828	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes . Parts# P9600 Qty (1) Oil 5W20QTY (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-May-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	65.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-May-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52447042
Invoice Number: 55345-52447042

Client Department:

MRC: 55345M

WO Desc:
PM A

Requested By: DARTHURS

Created By: DARTHURS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

VIN:

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Jun 14, 2019	9:26 AM
Started		
Completed	Jun 14, 2019	4:30 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	199,630	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA Service
	CAUSE: preventive maintenance
	CORRECTION:PmA Service Performed

Activity: **10** 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: **20** 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A


Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
14-Jun-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted



WorkOrder: 52612887
Invoice Number: 55345-52612887

Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: DARTHURS **VIN:** 2C7WDGBG7ER476551
Created By: DARTHURS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Aug 16, 2019	12:53 PM
Started		
Completed	Aug 20, 2019	8:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	208,489	DH
System	208,489	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service
	CAUSE: preventive maintenance
	CORRECTION: perform PmA Service

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 0.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
19-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52705629
Invoice Number: 55345-52705629

Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM A **Status:** Dodge Grand Caravan Braun Entervan SE
Requested By: RRENE **VIN:** 2C7WDGBG7ER476551
Created By: RRENE **Priority:** 40
Class: WO **Driver:** 1
Arrangement: Unassigned **Phone:**
Potential Warranty: No **ETA:**

Chronology		
Reported	Sep 18, 2019	12:44 PM
Started	Sep 26, 2019	
Completed	Sep 27, 2019	11:17 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	212,837	DH
System	212,836	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service due CORRECTION: Performed and completed pma Changed engine oil and replaced engine oil filter

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Sep-19	Delva,Terry	0.83	65.00	54.17

Activity 10 Sub Total

Parts: 0.00
 Labor: 54.17
 Labor Hours: 0.83
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 54.17

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
26-Sep-19	PA4456	FILTER, AIR, CARAVAN, '14 SAME AS WIX 49737	1.00	5.02	5.02



Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: DARTHURS **VIN:** 2C7WDGGB7ER47655L
Created By: DARTHURS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Nov 22, 2019	4:27 PM
Started	Nov 22, 2019	
Completed	Nov 23, 2019	12:12 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	221,478	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter P9600 Engine oil 5w20 qty 5 qts Rotate tires torque wheels 100 lbs second torque 100 lbs

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Nov-19	Gaspard,Ronald	1.25	65.00	81.25

Activity 10 Sub Total

Parts:	0.00
Labor:	81.25
Labor Hours: 1.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	81.25

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53031077
Invoice Number: 55345-53031077

Client Department:

MRC: 55345M

Equipment: 4817

WO Desc:

Dodge Grand Caravan Braun Entervan SE

PM A

VIN: 2C7WDGBG7ER476551

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Dec 26, 2019	1:00 PM
Started	Dec 26, 2019	
Completed	Dec 27, 2019	4:25 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	225,989	DH
System	225,989	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter P9600 qty1 Engine oil 5w20 qty 6 Qts

Activity: **10** **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Dec-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts: 0.00
Labor: 104.00
Labor Hours: 1.60
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 104.00

Activity: **20** **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
27-Dec-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53226763
Invoice Number: 55345-53226763

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4817
VIN: Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 26, 2020	11:21 AM
Started	Feb 26, 2020	
Completed	Feb 27, 2020	12:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	234,070	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter P9600 qty1 Engine oil 10w30 qty 5 1/2 Qts

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Feb-20	Gaspard,Ronald	0.92	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 0.92
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
27-Feb-20	B329(F)	FILTER, OIL, SPIN-ON	1.00	1.96	1.96



Client Department:

MRC:	55345M	Equipment:	4817
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM A		VIN:	2C7WDGBG7ER476551
Requested By:	CVERGARA	Status:	40
Created By:	CVERGARA	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	May 21, 2018	12:53 PM
Started	May 21, 2018	
Completed	May 21, 2018	10:28 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	160,807	DH
System	160,953	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service due CORRECTION: Performed and completed PM A Changed engine oil and replaced engine oil filter..

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-May-18	Delva,Terry	0.92	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.92	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-May-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 2 of 9



WorkOrder: 51288308
Invoice Number: 55345-51288308

Client Department:

MRC: 55345M

WO Desc:
 PM A

Requested By: CVERGARA

Created By: CVERGARA

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

VIN: Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG7ER476551

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
21-May-18	Delva,Terry	1.50	0.00	0.00

Activity 20 Sub Total

Parts:	3.44
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.44

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-May-18	Delva,Terry	1.00	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51288308 Grand Total

Parts:	3.44
Labor:	0.00
Labor Hours: 3.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.44

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51288308	21-May-18	160,807	WO	PM A
51134269	25-Apr-18	156,575	WO	PM A



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 9



WorkOrder: 51288308
Invoice Number: 55345-51288308

Client Department:

MRC: 55345M

WO Desc:
PM A

Requested By: CVERGARA

Created By: CVERGARA

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

VIN: Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51363854	21-May-18	160,807	WO	FTLMPMI_FOLLOWUP

PH: Work Order: 51288308 Desc: PM A

Equip: 4817 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG7ER476551

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,100	Safety Inspection	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,140	Check Service Brakes	Done		TDELVA	May 21, 2018 9:06:36 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
10,160	FRA Check Instruments and Horns	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
10,170	Check Fast Idle	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
10,180	Check Starter Protection Circuit	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
10,190	Check Reverse Warning System	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
11,100	Check Parking Brake	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		TDELVA	May 21, 2018 9:06:37 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	May 21, 2018 9:06:38 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		TDELVA	May 21, 2018 9:06:38 PM	No	
11,140	Road Test: Check for Proper Operation	Done		TDELVA	May 21, 2018 9:06:38 PM	No	
11,150	Perform Brake Test	Done		TDELVA	May 21, 2018 9:06:38 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	TDELVA	May 21, 2018 9:06:38 PM	No	
11,154	Decelerometer Results Test 2	FEET	n/a	TDELVA	May 21, 2018 9:06:38 PM	No	
11,156	Decelerometer Results Test 3	FEET	n/a	TDELVA	May 21, 2018 9:06:38 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	TDELVA	May 21, 2018 9:06:38 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	TDELVA	May 21, 2018 9:06:38 PM	No	
11,170	FRA Check Door Operation	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		TDELVA	May 21, 2018 9:06:39 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,230	FRA Check Wiring Under Dash	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,240	FRA Check Interior Lights	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		TDELVA	May 21, 2018 9:06:39 PM	No	
20,260	Check Stop Request System	-	n/a	TDELVA	May 21, 2018 9:06:40 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	n/a	TDELVA	May 21, 2018 9:06:40 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	May 21, 2018 9:06:40 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	May 21, 2018 9:06:40 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		TDELVA	May 21, 2018 9:06:40 PM	No	
22,110	Check Emergency Hatches	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
22,120	Check All Safety Equipment	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
30,310	Check Passenger Doors	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
30,330	Check Wheelchair Lift Operation	Done		TDELVA	May 21, 2018 9:06:41 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	n/a	TDELVA	May 21, 2018 9:06:41 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		TDELVA	May 21, 2018 9:06:42 PM	No	
30,360	Check for Physical Damage and Decals	Done		TDELVA	May 21, 2018 9:06:42 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		TDELVA	May 21, 2018 9:06:42 PM	No	
30,380	Check Exterior Compartment Doors	Done		TDELVA	May 21, 2018 9:06:42 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		TDELVA	May 21, 2018 9:06:42 PM	No	
33,100	Check Lights and Reflectors	Done		TDELVA	May 21, 2018 9:06:43 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		TDELVA	May 21, 2018 9:06:43 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		TDELVA	May 21, 2018 9:06:43 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	May 21, 2018 9:06:43 PM	No	
40,420	Check Hood	Done		TDELVA	May 21, 2018 9:06:43 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		TDELVA	May 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:06:44 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	n/a	TDELVA	May 21, 2018 9:06:43 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	TDELVA	May 21, 2018 9:06:44 PM	No	
40,442	Freeze Point	Degree Fahrenheit	n/a	TDELVA	May 21, 2018 9:06:44 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	May 21, 2018 9:06:44 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	n/a	TDELVA	May 21, 2018 9:06:44 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	n/a	TDELVA	May 21, 2018 9:06:44 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	-	n/a	TDELVA	May 21, 2018 9:06:45 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		TDELVA	May 21, 2018 9:06:44 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,130	FRA Check Exhaust System	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,140	FRA Check Intake System	Done		TDELVA	May 21, 2018 9:06:45 PM	No	
44,150	FRA Inspect Turbocharger	-	n/a	TDELVA	May 21, 2018 9:06:45 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	May 21, 2018 9:06:46 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		TDELVA	May 21, 2018 9:06:46 PM	No	
44,180	FRA Check for Leaks	Done		TDELVA	May 21, 2018 9:06:46 PM	No	
44,190	FRA Perform Battery Inspection	Done		TDELVA	May 21, 2018 9:06:46 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done	Replaced Battery	TDELVA	May 21, 2018 9:06:46 PM	Yes	51363854
50,000	SECTION 5 Steering System Inspection	Done		TDELVA	May 21, 2018 9:06:46 PM	No	
50,510	Check Entire Steering System	Done		TDELVA	May 21, 2018 9:11:18 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		TDELVA	May 21, 2018 9:11:19 PM	No	
60,610	FRA Check and Record Air Pressure	Done		TDELVA	May 21, 2018 9:11:19 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		TDELVA	May 21, 2018 9:11:18 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		TDELVA	May 21, 2018 9:11:19 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		TDELVA	May 21, 2018 9:11:19 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	Pounds per Square Inch	n/a	TDELVA	May 21, 2018 9:11:19 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	n/a	TDELVA	May 21, 2018 9:11:19 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		TDELVA	May 21, 2018 9:11:19 PM	No	
60,620	Check Valve Stems and Caps	Done		TDELVA	May 21, 2018 9:11:19 PM	No	
60,630	Check and Record Tread Depth	Done		TDELVA	May 21, 2018 9:11:20 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		TDELVA	May 21, 2018 9:11:19 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		TDELVA	May 21, 2018 9:11:20 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		TDELVA	May 21, 2018 9:11:20 PM	No	
60,634	Tread Depth RRI	0 32nds of an inch	n/a	TDELVA	May 21, 2018 9:11:20 PM	No	
60,635	Tread Depth LRI	32nds of an inch	na	TDELVA	May 21, 2018 9:11:20 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		TDELVA	May 21, 2018 9:11:20 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		TDELVA	May 21, 2018 9:11:20 PM	No	
60,650	Check Sidewall Wear	Done		TDELVA	May 21, 2018 9:11:20 PM	No	
60,660	Inspect for Cuts and Tears	Done		TDELVA	May 21, 2018 9:11:20 PM	No	
60,670	Check Dual Mating With Square	-	n/a	TDELVA	May 21, 2018 9:11:21 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		TDELVA	May 21, 2018 9:11:20 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,710	Check Vibration Damper	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,720	Check Engine and Transmission Mounts	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,730	FRA Check Starter	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,750	FRA Check Transmission for Leaks	Done		TDELVA	May 21, 2018 9:11:21 PM	No	
70,760	FRA Check Differential Breather and Fluid	-	n/a	TDELVA	May 21, 2018 9:11:21 PM	No	
70,770	FRA Check Exhaust System	Done		TDELVA	May 21, 2018 10:26:22 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	-	n/a	TDELVA	May 21, 2018 9:11:21 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		TDELVA	May 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:11:22 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	May 21, 2018 9:11:22 PM	No	
77,110	FRA Check Fuel Tank	Done		TDELVA	May 21, 2018 9:11:22 PM	No	
77,120	Check Suspension Components	Done		TDELVA	May 21, 2018 9:11:22 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	May 21, 2018 9:11:22 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		TDELVA	May 21, 2018 9:11:22 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		TDELVA	May 21, 2018 9:11:22 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		TDELVA	May 21, 2018 9:11:22 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		TDELVA	May 21, 2018 9:11:22 PM	No	
77,135	Brake Rotor LF	26 Inch		TDELVA	May 21, 2018 9:11:23 PM	No	
77,136	Brake Rotor RF	26 Inch		TDELVA	May 21, 2018 9:11:23 PM	No	
77,137	Brake Rotor LR	16 Inch		TDELVA	May 21, 2018 9:11:23 PM	No	
77,138	Brake Rotor RR	16 Inch		TDELVA	May 21, 2018 9:11:23 PM	No	
77,140	FRA Check Brake Hoses	Done		TDELVA	May 21, 2018 9:11:24 PM	No	
77,150	Check King Pins	-	n/a	TDELVA	May 21, 2018 9:11:24 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	May 21, 2018 9:11:24 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		TDELVA	May 21, 2018 9:11:24 PM	No	
80,810	Completion of PMI Report	Done		TDELVA	May 21, 2018 9:11:24 PM	No	
90,000	SECTION 9 Completion of PMI	Done		TDELVA	May 21, 2018 9:11:24 PM	No	
90,910	Vehicle Returned to predetermined location	Done		TDELVA	May 21, 2018 9:11:24 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: TDELVA Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	May 21, 2018 9:12:06 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	May 21, 2018 9:12:05 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	May 21, 2018 9:12:06 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	May 21, 2018 9:12:06 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	May 21, 2018 9:12:06 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	May 21, 2018 9:12:06 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	TDELVA	May 21, 2018 9:12:06 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	May 21, 2018 9:12:06 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 21, 2018 9:12:28 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 53328354
Invoice Number: 55345-53328354

Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM A **Status:** Dodge Grand Caravan Braun Entervan SE
Requested By: RGASPARD **VIN:** 2C7WDGBG7ER476551
Created By: RGASPARD **Priority:** 40
Class: WO **Driver:** 1
Arrangement: Unassigned **Phone:**
Potential Warranty: No **ETA:**

Chronology		
Reported	Apr 14, 2020	3:46 PM
Started	Apr 14, 2020	
Completed	Apr 14, 2020	11:41 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	237,994	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter P9600 Qty1 Engine oil 10w30 qty 5 qts

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Apr-20	Gaspard,Ronald	1.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
14-Apr-20	P9600	FILTER, OIL	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51363936
Invoice Number: 55345-51363936

Client Department:

MRC: 55345M

Equipment: 4817

WO Desc:
 PM B

Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG7ER476551

Requested By: TDELVA

VIN:
Status: 40

Created By: TDELVA

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Jun 21, 2018	2:33 PM
Started	Jun 21, 2018	
Completed	Jun 21, 2018	11:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	164,907	DH
System	165,101	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service due by Mileage CORRECTION: Change Oil & Filter.lube all Pivoting Points.check brakes.rotate R/F tire to R/R& R/ R To front Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-Jun-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 2 of 9



WorkOrder: 51363936
Invoice Number: 55345-51363936

Client Department:

MRC: 55345M

WO Desc:
PM B

Requested By: TDELVA

Created By: TDELVA

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

VIN: Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	3.44
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.44

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51363936 Grand Total

Parts:	3.44
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.44

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51363936	21-Jun-18	164,907	WO	PM B

Scheduled Preventative Maintenance



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 9



WorkOrder: 51363936
Invoice Number: 55345-51363936

Client Department:

MRC: 55345M

WO Desc:
PM B

Requested By: TDELVA

Created By: TDELVA

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

VIN: Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51363854	21-May-18	160,807	WO	FTLMPMI_FOLLOWUP

PH: Work Order: 51363936 Desc: PM B

Equip: 4817 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG7ER476551

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 21-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jun 21, 2018 10:54:44 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 21, 2018 10:54:45 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jun 21, 2018 10:54:46 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 21, 2018 10:54:48 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 21, 2018 10:54:47 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 21, 2018 10:54:48 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jun 21, 2018 10:54:49 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,420	Check Hood	Done		DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:54:50 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 21, 2018 10:54:50 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 21, 2018 10:54:51 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 21, 2018 10:54:51 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 21, 2018 10:54:51 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jun 21, 2018 10:54:52 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		DARTHURS	Jun 21, 2018 10:54:53 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		DARTHURS	Jun 21, 2018 10:54:54 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	Pounds per Square Inch	NA	DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	NA	DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,632	Tread Depth LF	5 32nds of an inch		DARTHURS	Jun 21, 2018 10:54:54 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,634	Tread Depth RRI	32nds of an inch	NA	DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,635	Tread Depth LRI	32nds of an inch	NA	DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,636	Tread Depth LRO	5 32nds of an inch		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jun 21, 2018 10:54:55 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jun 21, 2018 10:54:56 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
66,100	FRA Check Outer Hubs for Leaks	-	NA	DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jun 21, 2018 10:54:56 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	-	NA	DARTHURS	Jun 21, 2018 10:54:57 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:54:57 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jun 21, 2018 10:54:57 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,131	Brake Pad Thickness LF	9 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,132	Brake Pad Thickness RF	9 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,133	Brake Pad Thickness LR	9 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,134	Brake Pad Thickness RR	9 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,135	Brake Rotor LF	1.1 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,136	Brake Rotor RF	1.099 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,137	Brake Rotor LR	.482 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,138	Brake Rotor RR	.483 Inch		DARTHURS	Jun 21, 2018 10:54:58 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jun 21, 2018 10:54:59 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jun 21, 2018 10:54:59 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: DARTHURS Performed on: 21-JUN-18


Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 21, 2018 10:56:11 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 21, 2018 10:56:11 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 21, 2018 10:56:11 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jun 21, 2018 10:56:11 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 21, 2018 10:56:12 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jun 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:56:12 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 21, 2018 10:56:12 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 21, 2018 10:56:12 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 21, 2018 10:56:12 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Jun 21, 2018 10:56:13 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	Jun 21, 2018 10:56:13 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 21, 2018 10:56:13 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 21, 2018 10:56:13 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 21-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 21, 2018 10:56:42 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52102586
Invoice Number: 55345-52102586

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4817

Dodge Grand Caravan Braun Entervan SE

VIN: 2C7WDGBG7ER476551

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Apr 15, 2019	12:00 AM
Started	Apr 15, 2019	
Completed	Apr 15, 2019	9:01 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	191,143	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB SERVICE
	CAUSE: PREVENTIVE MAINTENANCE
	CORRECTION: PERFORM AND COMPLETED PMB SERVICE

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Apr-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Apr-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52838981

Invoice Number: 55345-52838981

Client Department:

MRC: 55345M

Equipment: 4817

WO Desc:
PM B

Dodge Grand Caravan Braun Entervan SE
2C7WDGBG7ER476551

Requested By: RRENE

VIN:
Status: 40

Created By: RRENE

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Oct 25, 2019	2:26 PM
Started	Oct 25, 2019	
Completed	Oct 26, 2019	12:03 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	217,112	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter Lube all Pivoting Points. Check brakes. Parts # P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: **10** 999 TOTAL VEHICLE

Activity Note: Light Mediu Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Oct-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	97.50

Activity: **20** 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
28-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



Client Department:

MRC:	55345M	Equipment:	4817
WO Desc:			Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMB		VIN:	2C7WDG7ER476551
Requested By:	NSTOLFO	Status:	40
Created By:	NSTOLFO	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Jul 3, 2020	2:32 PM
Started	Jul 3, 2020	
Completed	Jul 3, 2020	7:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	242,232	DH
System	242,299	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Parts # P9600 Qty (1) Oil 5W20QTY (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 51718166

Invoice Number: 55345-51718166

Client Department:

MRC: 55345M **Equipment:** 4817
WO Desc: PM C **Dodge Grand Caravan Braun Entervan SE**
Requested By: CKARLENS **VIN:** 2C7WDGBG7ER476551
Created By: CKARLENS **Status:** 32
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Nov 7, 2018	11:37 AM
Started	Nov 7, 2018	
Completed	Nov 8, 2018	12:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,023	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil filter P9600 qty 1 Engine oil 5w20 qty 5 Qts AC filter PA10030 Qty1

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
07-Nov-18	Gaspard,Ronald	1.08	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 1.08
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
07-Nov-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder: 52519848
Invoice Number: 55345-52519848

Client Department:

MRC:	55345M	Equipment:	4817
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM C		VIN:	2C7WDGBG7ER476551
Requested By:	RRENE	Status:	40
Created By:	RRENE	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Jul 17, 2019	12:00 AM
Started	Jul 18, 2019	
Completed	Jul 18, 2019	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	204,188	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service Change Oil & Filter .Lube all Pivoting Points . check Brakes Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Jul-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	97.50

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Jul-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 53131885

Invoice Number: 55345-53131885

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4817
VIN: Dodge Grand Caravan Braun Entervan SE
Status: 2C7WDGBG7ER476551
Priority: 40
Driver: 1
Phone:
ETA:

Chronology		
Reported	Jan 28, 2020	9:56 AM
Started	Jan 28, 2020	
Completed	Jan 28, 2020	6:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	229,928	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC service Oil P9600 Qty1 Engine oil 5w20 qty 5 1/2 AC filter PA10030 Qty1

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
28-Jan-20	PA10030	FILTER, AIR, CABIN, CHRYSLER REPLACES 68127809AA	1.00	2.76	2.76

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Jan-20	Gaspard,Ronald	1.28	0.00	0.00

Activity 10 Sub Total

Parts: 2.76
 Labor: 0.00
 Labor Hours: 1.28
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 2.76

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued