

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Total Hours: 193.25 Labor: 12,228.50 Parts: 8,081.88 Comm: 2,303.38 Charged: 22613.76

Work Order: 839442 **Meter:** 0 **In Date:** 06/04/2008 **Closed:** 06/04/2008
Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 932500 **Meter:** 2173 **In Date:** 01/08/2009 **Closed:** 01/15/2009
Problem: P.M.SERVICE

Work Completed

- Pm Service

- Trailer Light Socket Not Secured To Vehicle; Fabricate Bracket & Attach To Truck

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 8.00

1066 White Lithium (crc 05037) 1.00

Nb-19 Wiper Blades 19" Anco 31-19 2.00

Hours: 3.25 Comm: 0.00 Labor: 195.00 Parts: 74.26 Total: 269.26

Work Order: 937506 **Meter:** 3100 **In Date:** 05/07/2009 **Closed:** 05/15/2009
Problem: CORRECT TIRES INFLATION LEVEL SPECIFIED/SEE NOTE

Work Completed

- Transport & Pick Up At Dealer; L/r Lower Hinge Bushing Broken-warranty

- Correct Tire Psi To Spec

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 2.25 Comm: 0.00 Labor: 135.00 Parts: 2.00 Total: 137.00

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1104139 **Meter:** 8514 **In Date:** 04/15/2011 **Closed:** 04/20/2011
Problem: P. M. Service, & low tire PSI lamp is lit

Work Completed

- P. M. Service.
- Repair right rear tire & reprogram T.p.m.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	8.00
Nb-19 Wiper Blades 19" Anco 31-19	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 74.11 Total: 314.11

Work Order: 1111049 **Meter:** 10940 **In Date:** 10/18/2011 **Closed:** 10/26/2011
Problem: P.M.SERVICE

Work Completed

- P. M. Service.
- Replace both rear tires & rotate to the front.
- Perform Tpm reset procedure.
- Install "how's my driving" decal.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	8.00
1066 White Lithium (crc 05037)	1.00
179636492 Lt245/75r17 Wrangler Sr-a E	2.00
Tire Disposal Fee	2.00

Hours: 5.00

Comm: 0.00

Labor: 300.00 Parts: 420.84 Total: 720.84

Work Order: 1111183 **Meter:** 10979 **In Date:** 10/21/2011 **Closed:** 10/24/2011
Problem: reflash canceiver

Work Completed

- Reflash Canceiver and Reprogram
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1204248 **Meter:** 13381 **In Date:** 05/04/2012 **Closed:** 05/09/2012
Problem: pm svc

Work Completed

- pm
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	8.00
Nb-19 Wiper Blades 19" Anco 31-19	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 2.75

Comm: 0.00

Labor: 165.00 Parts: 67.63 Total: 232.63

Work Order: 1208814 **Meter:** 15032 **In Date:** 09/17/2012 **Closed:** 10/04/2012
Problem: rr wheel smoking

Work Completed

- ck right rear wheel smoking perform pinpoint test and found frozen right rear caliper and brake hose replace caliper and test drive
- Shop Supplies

Parts Issued

Quantity

Reman Brake Caliper	1.00
Mkd1334 Rear Pads	1.00
Shop Supplies	1.00
R/rear Brake Hose	1.00

Hours: 2.50

Comm: 0.00

Labor: 150.00 Parts: 185.41 Total: 335.41

Work Order: 1212189 **Meter:** 15464 **In Date:** 12/19/2012 **Closed:** 12/27/2012
Problem: hard to start, pm

Work Completed

- pm
- ck battery was smoking and smell acid verified founq battery leaking acid rr battery
- Shop Supplies

Parts Issued

Quantity

Ph2 Oil Filter Lbf Ph	1.00
Napa Quart 5w20	8.00
Battery 65	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 210.00 Parts: 182.05 Total: 392.05

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1302308 **Meter:** 15864 **In Date:** 03/07/2013 **Closed:** 03/13/2013
Problem: driver side visor broke.

Work Completed

- repaired bracket for visor

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1310632 **Meter:** 18046 **In Date:** 10/23/2013 **Closed:** 10/30/2013
Problem: pm

Work Completed

- pm
- verify needs two fornt tires mountd balance add n2
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade	2.00
Washer Fl	1.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 547.01 Total: 802.01

Work Order: 1404364 **Meter:** 19680 **In Date:** 05/05/2014 **Closed:** 05/15/2014
Problem: install customers inverter

Work Completed

- Wire in and install Customer Inverter
- Pm
- R&r tire repair
- Shop Supplies

Parts Issued

Quantity

Bulk Battery Cable	25.00
Cs4l Cable 4	10.00
Cb185-100 Cir Brkr	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Shop Supplies	1.00

Hours: 7.75 Comm: 0.00 Labor: 465.00 Parts: 176.23 Total: 641.23

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1407446 **Meter:** 20703 **In Date:** 07/29/2014 **Closed:** 08/07/2014
Problem: gas cap light on,and off, engine light on,ck ac on off

Work Completed

- ck gas cap light and ck engine light on scan and found code po455 po457 perform pinpoint test and was unable to confirm evap leak at this time clear code
- ck ac work on and off ck sys pressure ck ac and found no problem with ac at this time
- test drive 46 miles before and after repair
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 2.00	Total: 212.00
-------------	------------	---------------	-------------	---------------

Work Order: 1408248 **Meter:** 20847 **In Date:** 08/20/2014 **Closed:** 08/25/2014
Problem: ac, wipers not working

Work Completed

- ck ac and wipers not working perform pinpoint test and found bad electrical part of ignition switch replace electrical part of ignition switch
- ck engine light was on scan and found code po455 per form pinpoint test on evap sys and found bad gas cap replace cap and clear codes
- Shop Supplies

Parts Issued

Quantity

Switch asm	1.00
Gas Cap Non-locking	1.00
Shop Supplies	1.00

Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 62.66	Total: 302.66
-------------	------------	---------------	--------------	---------------

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1410610 **Meter:** 21516 **In Date:** 10/23/2014 **Closed:** 10/30/2014
Problem: pm, ck engine light

Work Completed

- pm
- remove battery clean corrosion from battery tray ck battery and replace battery terminal
- ck engine light on scan code po455 po457 perform pinout test trace evap hose and found crack hose repair hose clear code
- test drive vehicle 50 miles before and after repair
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade	2.00
Washer Fl	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
05023 Battery Cleaner	1.00
Bat Term Protector	1.00
Shop Supplies	1.00

Hours: 8.25

Comm: 0.00

Labor: 495.00 Parts: 90.80 Total: 585.80

Work Order: 1411112 **Meter:** 21627 **In Date:** 11/05/2014 **Closed:** 11/19/2014
Problem: CK ENGINE LIGHT

Work Completed

- Ck Engine Ligh Is On Sca Fouind Po455 Diag Intermittent Evap Code Found Bad Evap Canister Replace Canister Purge Valve Clear Code And Reck System
- Test Drive Before And After Repair
- Shop Supplies

Parts Issued

Quantity

Ch Cannister Filter	1.00
Valve	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 270.00 Parts: 178.25 Total: 448.25

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1504333 **Meter:** 23008 **In Date:** 04/28/2015 **Closed:** 04/30/2015
Problem: P.M.SERVICE,TIRE PRESSURE ALARM.

Work Completed

Parts Issued

Quantity

- pm
- ck tpms light verify needs two rear tires rotate to front mount balance add n2
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 558.12 Total: 813.12

Work Order: 1509344 **Meter:** 24334 **In Date:** 09/16/2015 **Closed:** 09/18/2015
Problem: truck wont start battery draining

Work Completed

Parts Issued

Quantity

- ck and replace bad battery ck charging sys
- Shop Supplies

Battery 65	1.00
Shop Supplies	1.00

Hours: 0.75 Comm: 0.00 Labor: 45.00 Parts: 148.34 Total: 193.34

Work Order: 1510525 **Meter:** 24544 **In Date:** 10/19/2015 **Closed:** 10/27/2015
Problem: P.M.SERVICE

Work Completed

Parts Issued

Quantity

- pm
- ck and replace bad blower resistor replace leaking shraider valves recharge sys ck for leaks
- Shop Supplies

Napagold Oil Filter	2.00
Napa Quart 5w20	16.00
Washer Fluid Concentr	2.00
Wiper Blade	4.00
Napagold Fuel Filter	2.00
Ac Valve Core High	2.00
Core	2.00
South Region R134a	2.00
Used Fire X Refurbished	2.00
Blower Motor Resistor	2.00
Shop Supplies	1.00

Hours: 7.00 Comm: 0.00 Labor: 420.00 Parts: 236.57 Total: 656.57

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1511359 **Meter:** 24663 **In Date:** 11/05/2015 **Closed:** 11/17/2015
Problem: AC WORKS BUT ONLY ON HIGH #4

Work Completed

- ck ac only works on 4 replace defective blower motor resistor
- Shop Supplies

Parts Issued

Shop Supplies 1.00

Quantity

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1600711 **Meter:** 25192 **In Date:** 01/21/2016 **Closed:** 01/22/2016
Problem: need dun visor clip to hold visor in place

Work Completed

- ck sunvisor clip fabricate clip to hold visor and strobe
- Shop Supplies

Parts Issued

Shop Supplies 1.00

Quantity

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1605653 **Meter:** 25904 **In Date:** 06/01/2016 **Closed:** 06/14/2016
Problem: P.M.SERVICE

Work Completed

- Pm service.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Napagold Oil Filter 1.00

Napa Quart 5w20 8.00

Shop Supplies 1.00

Quantity

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 34.15 Total: 244.15

Work Order: 1606192 **Meter:** 25980 **In Date:** 06/16/2016 **Closed:** 06/27/2016
Problem: jump start every day

Work Completed

- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.
- Shop Supplies

Parts Issued

Battery 1.00

Shop Supplies 1.00

Quantity

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 120.41 Total: 180.41

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1608565 **Meter:** 26268 **In Date:** 08/17/2016 **Closed:** 08/30/2016
Problem: VEHICLE HOT ODOR

Work Completed

- C/s Veh. Hot Odor. C/k & Found Brake Caliper Locking Up.r/r Front And Rear Brake Calipers, Resurface Front&rear Rotors, R/r Front&rear Brake Pads,flush Brake System.
- R/r Steering Cover& Floor Mats.
- Test Drive Before&after Repair.
- Shop Supplies

Parts Issued

Quantity

Caliper w/ Hardware - Right Front (eclip	1.00
Caliper w/ Hardware - Left Front (eclips	1.00
Caliper w/ Hardware - Right Rear (eclips	1.00
Reman Brake Caliper	1.00
B Fluid Dot 3-32oz	2.00
Brake Cleaner	2.00
Disc Pad	1.00
Disc Pad	1.00
Floor Mat-2pc Rub Bk	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00

Hours: 12.75

Comm: 0.00

Labor: 765.00 Parts: 479.93 Total: 1,244.93

Work Order: 1701404 **Meter:** 27486 **In Date:** 02/09/2017 **Closed:** 02/21/2017
Problem: Pm Service.

Work Completed

- Pm Service
- Rotate and balance all tires.correct N2.relearntpms
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade Anco	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 65.26 Total: 290.26

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1704678 **Meter:** 28439 **In Date:** 05/10/2017 **Closed:** 05/15/2017
Problem: Broken fire extinguisher bracket

Work Completed

- Fabricate and replace fire extinguisher bracket.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1705660 **Meter:** 28584 **In Date:** 06/07/2017 **Closed:** 06/26/2017
Problem: Left rear tire flat.Trailer wiring fault.Wiper blades.

Work Completed

- Clean windshield and replace wiper blades.
- Replace left rear tire.
- Replace trailer socket.
- Shop Supplies

Parts Issued

Quantity

Wiper Blade Anco	2.00
179636492 Lt245-75r17	2.00
trailer plug	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 533.40 Total: 773.40

Work Order: 1706495 **Meter:** 28793 **In Date:** 06/30/2017 **Closed:** 07/17/2017
Problem: Right rear turnsignal light inop.

Work Completed

- Repair right tail light.

Parts Issued

Quantity

Bulb	1.00
------	------

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.78 Total: 30.78

Work Order: 1707228 **Meter:** 28866 **In Date:** 07/24/2017 **Closed:** 07/27/2017
Problem: Both headlights inop.

Work Completed

- Repair both headlights.
- Shop Supplies

Parts Issued

Quantity

Halogen Lamp	2.00
Shop Supplies	1.00

Hours: 1.75 Comm: 0.00 Labor: 105.00 Parts: 28.01 Total: 133.01

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1707767 **Meter:** 29005 **In Date:** 08/09/2017 **Closed:** 08/14/2017
Problem: Pm Service

Work Completed

- Pm Service.
- Mount three tires.rotate and balance all four.
- Trailer 6 way plug socket replaced.corroded and rusted from aux. water tank leaking water on connector.assembly
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade Anco	2.00
179636492 Lt245-75r17	3.00
trailer plug	1.00
Dielectric Grease	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 405.00 Parts: 838.49 Total: 1,243.49

Work Order: 1709346 **Meter:** 29157 **In Date:** 09/26/2017 **Closed:** 09/29/2017
Problem: Broken right side mirror and rear view mirror.

Work Completed

- Replace damage right side mirror and rear view mirror
- Shop Supplies

Parts Issued

Quantity

Mirror Assembly	1.00
Inside Real Mirror	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00 Parts: 252.44 Total: 372.44

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1800097 **Meter:** 29561 **In Date:** 01/03/2018 **Closed:** 01/19/2018
Problem: Pm service.Noise in front end.

Work Completed

- Pm Service.
- Replace both headlamps
- Replace all body mounts.
- Rotate and balance four tires.
- Clean and vacume crowel
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade Anco	2.00
Washer Fluid Concentr	1.00
Halogen Lamp	2.00
Body Mount Kit	2.00
Body Mount Kit	4.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 12.25

Comm: 0.00

Labor: 735.00

Parts: 586.73

Total: 1,321.73

Work Order: 1802046 **Meter:** 29561 **In Date:** 01/23/2018 **Closed:** 02/23/2018
Problem: Damage to right side of bed

Work Completed

- Damage to right side of bed

Hours: 0.00

Comm: 2,303.38

Labor: 0.00

Parts: 0.00

Total: 2,303.38

Work Order: 1806198 **Meter:** 30163 **In Date:** 06/18/2018 **Closed:** 06/26/2018
Problem: Left rear turnsignal out.

Work Completed

- Repair left rear turnsignal.

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 0.77

Total: 30.77

Parts Issued

Quantity

Boxed Miniatures	1.00
------------------	------

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 1808229 **Meter:** 30444 **In Date:** 08/10/2018 **Closed:** 08/27/2018
Problem: PM Service.

Work Completed

- Pm Service
- Replace third brake lamp bulbs.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade Anco	2.00
Used Fire X Refurbished	1.00
Boxed Miniatures	3.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 270.00 Parts: 62.86 Total: 332.86

Work Order: 1811955 **Meter:** 30747 **In Date:** 11/26/2018 **Closed:** 12/12/2018
Problem: Noise in rear over bumps.Trailer harness fault on dash.

Work Completed

- Replace front and rear shocks.
- Replace 6 way socket and replaced wiring harness.
- Shop Supplies

Parts Issued

Quantity

Gas Grande Shock	2.00
Gas Grande Shock	2.00
Wire Term 16-14 BlIt	20.00
Butt Connect	10.00
Primary Wire	6.00
trailer plug	1.00
Bulk Trailer Wire	6.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 268.00 Parts: 282.57 Total: 550.57

Work Order: 1813112 **Meter:** 30936 **In Date:** 12/31/2018 **Closed:** 01/14/2019
Problem: Left rear turnsignal inop.

Work Completed

- Test and replace bad turnsignal lamp bulb and repair socket.

Parts Issued

Quantity

Boxed Miniatures	1.00
------------------	------

Hours: 0.50

Comm: 0.00

Labor: 33.50 Parts: 0.77 Total: 34.27

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 2110372 **Meter:** 36091 **In Date:** 09/24/2021 **Closed:** 10/01/2021
Problem: Left front brakes smoking

Work Completed

- replaced both front calipers pads service rotors slides flush system
- Shop Supplies

Parts Issued

Quantity

B Fluid Dot 3-32oz	1.00
Non-chlor Brake Clnr	2.00
Brake Pads	1.00
Caliper w/ Hardware - Left Front (eclips	1.00
Caliper w/ Hardware - Right Front (eclip	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 190.32 Total: 482.32

Work Order: 2110808 **Meter:** 36091 **In Date:** 10/05/2021 **Closed:** 10/26/2021
Problem: Check brakes,pulls to one side.

Work Completed

- replaced both front brake flex hoses and flush system
- Test drive 40 miles to verify brakes are not pulling or making noise after repair. "break in" brake pads. Verify fluid level after test drive.
- Shop Supplies

Parts Issued

Quantity

Brake Hose	1.00
Brake Hose	1.00
Brake Caliper Kit	1.00
Wheel Seal - Front Wheel	1.00
Caliper Rebuild Kit	1.00
Brake Sohe	1.00
Brake Hose	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 173.48 Total: 465.48

Work Order: 2113325 **Meter:** 36446 **In Date:** 12/16/2021 **Closed:** 12/21/2021
Problem: Dead battery

Work Completed

- recharge test battery and test electrical system. replaced failed battery
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 111.79 Total: 184.79

3/1/2022
2:51:51 PM

Palm Beach County Fleet Management Asset Maintenance History
10174410 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Work Order: 2201385 **Meter:** 36490 **In Date:** 02/07/2022 **Closed:** 02/07/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 193.25

Total Labor: 12,228.50

Total Comm: 2,303.38

Total Parts: 8,081.88