

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Total Hours: 164.65 Labor: 10,909.20 Parts: 10,982.79 Comm: 570.40 Charged: 22462.39

Work Order: 1509630 **Meter:** 338 **In Date:** 09/23/2015 **Closed:** 09/23/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Minor weld repair or machining

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 0.00 Total: 300.00

Work Order: 1601162 **Meter:** 5451 **In Date:** 02/02/2016 **Closed:** 02/11/2016
Problem: Pm service.Right front bin door difficult to close.

Work Completed

- Pm service.
- Inspect and service power lift gate.
- Adjust right front bin door for utility body.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Wd40 16oz	1.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 7.00 Comm: 0.00 Labor: 420.00 Parts: 61.34 Total: 481.34

Work Order: 1605614 **Meter:** 10727 **In Date:** 06/01/2016 **Closed:** 06/15/2016
Problem: P.M. service and wiper/washers inop.

Work Completed

- P.m. Service.
- Diagnose inop windshield washer pump.replace defective pump.
- Repair one tire,rotate and balance all six.
- Inspect and service liftgate.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Washer Pump	1.00
Shop Supplies	1.00

Hours: 8.50 Comm: 0.00 Labor: 510.00 Parts: 88.63 Total: 598.63

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1607627 **Meter:** 12364 **In Date:** 07/26/2016 **Closed:** 07/29/2016
Problem: Install power inverter in left front utility bin.

Work Completed

- Install inverter in front bin of utility body.fabricate and install wiring.
- Shop Supplies

Parts Issued

Quantity

Cobra Inverter	1.00
Cb185-150 Cir Brkr	1.00
Terminal	2.00
Bat/cabl	16.00
Bulk Battery Cable	3.00
Fab/loom	20.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 393.02 Total: 633.02

Work Order: 1612326 **Meter:** 17840 **In Date:** 12/01/2016 **Closed:** 12/14/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace and balance six new tires.
- Inspect and service liftgate.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
179636492 Lt245-75r17	6.00
Napa Gear 80w-90 Qt	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 8.00

Comm: 0.00

Labor: 480.00 Parts: 1,547.53 Total: 2,027.53

Work Order: 1701867 **Meter:** 21160 **In Date:** 02/22/2017 **Closed:** 03/15/2017
Problem: Wiper blades broke.

Work Completed

- Replace defective rightside wiper blade.

Parts Issued

Quantity

22" Wiper Blade	1.00
-----------------	------

Hours: 0.25

Comm: 0.00

Labor: 15.00 Parts: 3.39 Total: 18.39

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1704841 **Meter:** 23697 **In Date:** 05/15/2017 **Closed:** 05/22/2017
Problem: P.M. service and had to jump start.

Work Completed

- P.m. service.
- Check battery, charging system .fully charge and recheck, failed load test .replace defective battery.
- Check and replace two tail lamps and one tag light bulbright side.
- Balance and rotate all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Battery 65	1.00
Led Sup Mdl 44 42 Dio	2.00
Bulb	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 7.30

Comm: 0.00

Labor: 438.00 Parts: 314.15 Total: 752.15

Work Order: 1705944 **Meter:** 24516 **In Date:** 06/15/2017 **Closed:** 06/21/2017
Problem: Left rear outter tire flat.

Work Completed

- Repair left rear outter tire flat.mount and balance .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1707590 **Meter:** 26087 **In Date:** 08/02/2017 **Closed:** 08/03/2017
Problem: Nail in drivers side tire, Pulls left

Work Completed

- Repair left front tire .test drive pulling was cause of low tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1711300 **Meter:** 30630 **In Date:** 11/16/2017 **Closed:** 11/29/2017
Problem: P.M. service and detal.

Work Completed

Parts Issued

Quantity

- P.m. service.	5w20 Engine Oil	8.00
- Check .resurface front brake rotors.replace pads and service calipers.bleed brakes.test drive.	Napagold Oil Filter	1.00
- Inspect and service power liftgate.	22" Wiper Blade	2.00
- Balance and rotate all six tires.	Non-chlor Brake Clnr	1.00
- Shop Supplies	Front Brake Pad	1.00
	lube	1.00
	Shop Supplies	1.00
Hours: 11.50 Comm: 0.00	Labor: 690.00 Parts: 150.40	Total: 840.40

Work Order: 1711645 **Meter:** 30542 **In Date:** 11/28/2017 **Closed:** 11/28/2017
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued		
Hours: 0.00 Comm: 96.00	Labor: 0.00 Parts: 0.00	Total: 96.00

Work Order: 1803727 **Meter:** 35860 **In Date:** 04/10/2018 **Closed:** 04/12/2018
Problem: P.M. service and check liftgate cable.Detail.

Work Completed

Parts Issued

Quantity

- P.m. service.	5w20 Engine Oil	7.00
- Test brake lights .replace both brake lights and retest.	Napagold Oil Filter	1.00
- Rotate and high speed balance all six tires.	22" Wiper Blade	2.00
- Inspect and service power liftgate .replace missing cotter pin in liftgate lock.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
	Pedal Pad	1.00
	Led Sup Mdl 44 42 Dio	2.00
	Shop Supplies	1.00
Hours: 7.00 Comm: 0.00	Labor: 420.00 Parts: 184.70	Total: 604.70

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1803834 **Meter:** 35860 **In Date:** 04/12/2018 **Closed:** 04/12/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1803969 **Meter:** 37561 **In Date:** 04/17/2018 **Closed:** 04/19/2018
Problem: Left front tire going flat.

Work Completed

- Repair left front tire and balance .nitrogen fill tires.

Parts Issued **Quantity**

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1805909 **Meter:** 38006 **In Date:** 06/11/2018 **Closed:** 06/12/2018
Problem: Bolt in left rear outter tire.

Work Completed

- Replace and balance left rear outter tire.check all tire pressures.

Parts Issued **Quantity**

179636492 Lt245-75r17 1.00

- Shop Supplies

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 223.45 Total: 283.45

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1809302 **Meter:** 41548 **In Date:** 09/11/2018 **Closed:** 09/18/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace five tires . Nitrogen fill tires and high speed balance all six tires.
- Complete front end alignment . Replace right side caster/camber adjusting bushing . Test drive.
- Service and inspect power liftgate.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
179636492 Lt245-75r17	5.00
Caster-camber Bushing	1.00
Shop Supplies	1.00
Tire Disposal Fee	5.00

Hours: 11.50

Comm: 0.00

Labor: 690.00 Parts: 1,181.13 Total: 1,871.13

Work Order: 1811708 **Meter:** 43181 **In Date:** 11/15/2018 **Closed:** 11/26/2018
Problem: No crank and wipers stay on .

Work Completed

- Perform starting and charging system test. Replace defective battery and retest all systems .
- Perform wiper pinpoint test . Scan tool pid monitoring . R&r defective wiper switch . Replace wiper blades .
- Fabricate and install new rear asset numbers .
- Shop Supplies

Parts Issued

Quantity

Battery 65	1.00
22" Wiper Blade	2.00
Switch Asy	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 167.50 Parts: 224.97 Total: 392.47

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1902750 **Meter:** 47363 **In Date:** 03/13/2019 **Closed:** 03/28/2019

Problem: P.M. service and detail .

Work Completed

- P.m. service.
- Perform air intake decarb cleaning . Clean throttle body . Flush injectors .
- Computer diagnose check engine light , code P0308 .perform complete tune up . Replace all sixteen spark plugs and eight wires and replace number eight coil and nuber two coil . Clear codes and retest .
- Rotate and balance all six tires . Nitrofill all .
- Inspect and service power liftgate .
- Diagnose noise from rear on turns . Add friction modifier and retest drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
oil auto	1.00
Used Fire X Refurbished	1.00
Ford Triton Pvc Swc	1.00
Intake Cleaner Kit	1.00
Throttle Body Cleaner	1.00
Injector Cleaner	1.00
Coil	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Friction Modifier	1.00
Clip	2.00
Coil	1.00
Shop Supplies	1.00

Hours: 14.60

Comm: 0.00

Labor: 978.20

Parts: 690.96

Total: 1,669.16

Work Order: 1903233 **Meter:** 47192 **In Date:** 03/25/2019 **Closed:** 03/25/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 1908391 **Meter:** 53637 **In Date:** 08/13/2019 **Closed:** 08/26/2019
Problem: P.M. service and detail.

Work Completed

- P.m. service.
- Test and replace left tag light bulb .
- Test and replace defective trailer plug connector and rewire as needed .
- Test strobe light switch and rewire and retest.
- Balance and rotate all six tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Wd40 Spr	1.00
Bulb	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 502.50

Parts: 56.37

Total: 558.87

Work Order: 1909573 **Meter:** 55268 **In Date:** 09/17/2019 **Closed:** 10/10/2019
Problem: Install arrow board .

Work Completed

- Fabricate and install and wire in new arrow board and controller .
- Test and replace burnt power inverter .
- Shop Supplies

Parts Issued

Quantity

Pawer Inverter	1.00
Fuse Holder	1.00
Primary Wire	5.00
Primary Wire	5.00
Fab Loom-split Poly	5.00
Large Led Arrow Board	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 2,463.83

Total: 3,011.33

Work Order: 1910134 **Meter:** 55031 **In Date:** 10/01/2019 **Closed:** 10/08/2019
Problem: fabricate light brks

Work Completed

- Fab/weld and install mounting frame for arrow board
- Shop Supplies

Parts Issued

Quantity

Gl. Blac	2.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 17.11

Total: 528.11

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 2002580 **Meter:** 60941 **In Date:** 03/12/2020 **Closed:** 03/19/2020

Problem: P.M. service and check engine light on .

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P0455 . Perform evap test. R&r defective purge valve . Clear code and retest .
- Test and replace both brake light assmblies . Replace right backup light assembly and both tag light bulbs .
- Replace two worn tires . Rotate and balance all six tires . Nitrofill all.
- Inspect and service transmission . Replace filter and flush transmission fluid .
- Diagnose engine misfire , code P0303 . Perform power balance test . R&r defective number three coil . Clear code and retest.
- Inspect and service power liftgate .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Purge Valve	1.00
Led Back-up Lamp Sys	1.00
Led Sup Mdl 44 42 Dio	2.00
Bulb	2.00
Tr416 Valve Stem	2.00
Lt245/75r17 Mich Defend Ltx	2.00
Transmission Filter	1.00
oil auto	16.00
Transmission Filter	1.00
Coil	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.50

Comm: 0.00

Labor: 1,058.50 Parts: 1,279.49 Total: 2,337.99

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 2008021 **Meter:** 67557 **In Date:** 08/12/2020 **Closed:** 08/20/2020
Problem: P.M. Service.Detail.

Work Completed

- P.m. service.
- Test and replace defective trailer plug connector and rewire as needed .
- Replace four tires . Rotate and balance all six tires . Nitrofill all.
- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Perfrom complete front end alignment and road test .
- Inspect and service power liftgate .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
trailer plug	1.00
Lt245/75r17 Mich Defend Ltx	4.00
Non-chlor Brake Clnr	1.00
Front Brake Pad	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 1,213.13

Total: 2,417.63

Work Order: 2008364 **Meter:** 67557 **In Date:** 08/21/2020 **Closed:** 08/21/2020
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 2102223 **Meter:** 72743 **In Date:** 02/25/2021 **Closed:** 03/10/2021
Problem: P.M. service , wiper will not shut off and detail .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Diagnose wipers staying on. Found to have bad wiper switch. R and R bad wiper switch
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Switch	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 169.60

Total: 680.60

Work Order: 2102596 **Meter:** 72660 **In Date:** 03/05/2021 **Closed:** 03/08/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 2105608 **Meter:** 74572 **In Date:** 05/20/2021 **Closed:** 05/26/2021
Problem: Brakes and power steering. (PM NOT DUE)

Work Completed

Parts Issued

Quantity

- Replace leaking hydra booster, Bleed power steering system.
- Shop Supplies

Brakr Booster	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 323.01

Total: 542.01

3/1/2022
2:57:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198309 2015 FORD F350 Utility Body, 1 Ton

Work Order: 2109078 **Meter:** 76913 **In Date:** 08/23/2021 **Closed:** 08/30/2021

Problem: P.M. service MUST BE JUMP STARTED, THEN WON'T RESTART Detail

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replaced 1 tire, repaired 1 tire. Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Charged battery fully and battery tested bad. R and R bad battery.
- Inspect and serviced power lift gate.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Lt245/75r17 Mich Defend Ltx	1.00
Mac Battery Protect	1.00
Battery	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 390.61

Total: 1,011.11

Work Order: 2109543 **Meter:** 76913 **In Date:** 08/31/2021 **Closed:** 08/31/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2201306 **Meter:** 81277 **In Date:** 02/04/2022 **Closed:** 02/04/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 164.65

Total Labor: 10,909.20

Total Comm: 570.40

Total Parts: 10,982.79