Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Total Hours: 155.60 Labor: 9,974.25 Parts: 10,598.04 Comm: 1,313.52 Charged: 21885.82

Work Order: 1107473 Meter: 1780 In Date: 07/18/2011 Closed: 09/30/2011

Problem: Install red emergency lights and siren.

Work Completed	Parts Issued	Quantity
- Transport vehicle to Evs for light and siren installatio	Installation At Evs Facility	1.00
- Shop Supplies	Shop Supplies	1.00
	Sound Off 4 Module (red/white) Front Windshield	2.00
	Sound Off Visor Mount Brackets	2.00
	Sound Off 8 Module (red/white) Rear Window	1.00
	Sound Off Windshield Shroud	2.00
	Code 3 Remote Siren Sys Handheld Cntrl	1.00
	Code 3 Speaker W/ Univ. Bracket	1.00
Hours: 2.00 Comm: 0.0	Labor: 120.00 Parts: 2,648.38	Total: 2,768.38

Work Order: 1107566 Meter: 0 In Date: 07/19/2011 Closed: 07/19/2011

Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1113105 Meter: 5158 In Date: 12/13/2011 Closed: 12/29/2011

Problem: P.M. service.

Work Complete	ed		Parts Issued	Quantity
- P.m. Service.			Shop Supplies	1.00
- Rotate and ba	lance all tires.		Ph10575 Oil Filter Mtc Fl500s Wix 57502	1.00
- Shop Supplies			5w20 Engine Oil	6.00
	Hours: 3.75	Comm: 0.00	Labor: 225.00 Parts: 20.53	Total: 245.53

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1113454 Meter: 4895 In Date: 12/27/2011 Closed: 12/29/2011

Problem: pick up fire ext

Work Completed		Parts Issued		Quantity
- pick up fire ext		Shop Supplies		1.00
- Shop Supplies		5lb Firex Abc Sto	ck# 340280001	1.00
		Custom5lb Brack	et Firex Stock #340060300	1.00
Hours: 0.30	Comm: 0.00	Labor: 18.00	Parts: 89.14	Total: 107.14

Work Order: 1203324 Meter: 10215 In Date: 04/09/2012 Closed: 04/18/2012

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Shop Supplies		1.00
- Rotate and balance all tires.		Ph10575 Oil Filter	Mtc Fl500s Wix 57502	1.00
- Shop Supplies		5w20 Engine Oil		6.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 19.80	Total: 244.80

Work Order: 1207600 Meter: 16065 In Date: 08/13/2012 Closed: 09/06/2012

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- Perform pm service.		Shop Supplies		1.00
- Rotate and balance all four tires.		Ph10575 Oil Filter	Mtc FI500s Wix 57502	1.00
- Transport vehicle to and from dealer for replacing failed	5w20 Engine Oil		6.00	
assembly with new under factory warranty Shop Supplies		Wiper Blade Wiper Blade		1.00
				1.00
		Rear Wiper Blade		1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 53.92	Total: 398.92

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1212133 Meter: 21635 In Date: 12/17/2012 Closed: 01/08/2013

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Perform pm service.- Rotate and balance all four tires.		5w20 Engine Oil		6.00
		Napagold Oil Filter		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 26.26	Total: 251.26

Work Order: 1307527 Meter: 27285 In Date: 07/29/2013 Closed: 08/08/2013

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Repair right rear tire,replace two and rotate and balance all four.		Napagold Oil Filte	r	1.00
- Complete wheel alignment.test drive.		Accufit Beam		1.00
- Shop Supplies		Exact Fit Blade Battery Cleaner		1.00
				1.00
		P245 65 Sr17		2.00
		Blade		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.75	Comm: 0.00	Labor: 465.00	Parts: 558.06	Total: 1,023.06

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: Problem:	1400183 Pm service and tire pressure wa	Meter: 31096 arning light on.		In Date:	01/07/2014	Closed:	01/24/2014
Work Com	pleted		Parts Issued			Qı	uantity
- P.m. Serv	ice.		5w20 Engine Oil				6.00
- Replace t	wo tires,rotate and balance all fo	our.	Napagold Oil Filter				1.00
- Shop Sup			Blade				1.00
			Accufit Beam				1.00
			Rear Wiper Blade				1.00
			Napagold Air Filter				1.00
			P245 65 Sr17				2.00
			Blade				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
	Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 592	2.52	Total:	877.52
	Pm service and low tire pressur	Meter: 35081 re warning light on.	Boots laws d	In Date:	07/14/2014		07/30/2014
Work Com	•		Parts Issued			Qı	uantity
- P.m. Serv			5w20 Engine Oil				6.00
	ttery and charging system.recha	rge and retest battery,fail load	Napagold Oil Filter				1.00
·	defective battery.		Group 59 Battery Mc				1.00
	nd balance all tires.		Shop Supplies				1.00
- Shop Sup	Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 160	s 10	Total	451.10
			Labor. 265.00				
Work Order: Problem:	Airbag light on and safety recall	Meter: 35767 I 14S06		In Date:	08/25/2014	Closea:	08/28/2014
Work Com	pleted		Parts Issued			Qı	uantity
- Transport vehicle to and from dealer for safety recall 14s06 and air bag light on reprogram power steering control module and repair C210 wiring barness connector with special electric grasse.		Shop Supplies				1.00	
	nnector with special electric grea	se.					
	nnector with special electric grea	se.					

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1409631 Meter: 36204 In Date: 09/25/2014 Closed: 09/30/2014

Problem: Charges for repairs not covered by warranty at dealer

Work Completed

- Charges not covered by warranty.

Hours: 0.00 Comm: 122.57 Labor: 0.00 Parts: 0.00 Total: 122.57

Work Order: 1500681 Meter: 38786 In Date: 01/20/2015 Closed: 01/30/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity	
- P.m. Service Rotate and balance tires.		5w20 Engine Oil		6.00	
		Napagold Oil Filte	Napagold Oil Filter		
- Shop Supplies		Accufit Beam		1.00	
		Accufit Beam		1.00	
		Brake Cleaner		1.00	
		Washer Fluid Concentr		1.00	
		Blade		1.00	
		Shop Supplies		1.00	
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 71.78	Total: 296.78	

Work Order: 1506714 Meter: 42294 In Date: 07/06/2015 Closed: 08/06/2015

Problem: Pm service.Recall.

Work Completed		Parts Issued	Quantity
- P.m. Service.		5w20 Engine Oil	6.00
- Rotate and balance all tires.		Napagold Oil Filter	1.00
- Transport vehicle to dealer for recall #15s11.		Accufit Beam	1.00
- Shop Supplies		Accufit Beam	1.00
		Blade	1.00
		Shop Supplies	1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00 Parts: 73.	12 Total: 418.12

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1513129 Meter: 46286 In Date: 12/30/2015 Closed: 12/31/2015

Problem: service

Work Completed

- Tire Service Break down location - service

Hours: 0.00 Comm: 19.93 Labor: 0.00 Parts: 0.00 Total: 19.93

Work Order: 1600314 Meter: 46491 In Date: 01/11/2016 Closed: 01/26/2016

Problem: Pm service.Dent on roof,left front.

Work Completed		Parts Issued		Quantity
- P.m. Service.	- P.m. Service.			6.00
Replace two tires,rotate and balance all four.Complete wheel alignment.test drive.Shop Supplies		Napagold Oil Filte	r	1.00
		Napagold Air Filte	er	1.00
		Washer Fluid Concentr		1.00
		Accufit Beam		1.00
		Blade		1.00
		Accufit Beam		1.00
		P245 65 Sr17		2.00
		Shop Supplies		1.00
	Tire Disposa	Tire Disposal Fee		2.00
Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 482.72	Total: 917.72

Work Order: 1601450 Meter: 46523 In Date: 01/20/2016 Closed: 02/10/2016

Problem: damage to roof

Work Completed

- damage to roof

Hours: 0.00 Comm: 354.00 Labor: 0.00 Parts: 0.00 Total: 354.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1606525 Meter: 51927 In Date: 06/27/2016 Closed: 07/14/2016

Problem: P.M. Service.check power steering.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Accufit Beam		1.00
- Inspect and service rear differential.	Blade		1.00	
- Pressure test and inspect cooling system.flush and	refill system.	Washer Fluid Cond	centr	1.00
- Rotate and balance all tires.	-	Ptex Ultra Grey 3o	Z	1.00
- Transport vehicle to dealer for steering gear replace	e(extended warranty)	Napa Gear 80w-90	0 Qt	1.00
- Shop Supplies		Ford Red Antifreez	ze	2.00
		Napagold Oil Filte	r	1.00
		5w20 Engine Oil		6.00
		Accufit Beam		1.00
		Shop Supplies		1.00
Hours: 8.75	Comm: 0.00	Labor: 525.00	Parts: 139.40	Total: 664.40

Work Order: 1612560 Meter: 55601 In Date: 12/07/2016 Closed: 01/03/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Test battery and charging system.replace bad battery.		Napagold Oil Filte	r	1.00
- Flush and refill transmission.		Accufit Beam		1.00
- Replace two tires,rotate and balance all four.		Accufit Beam		1.00
- Replace leaking rear shocks.		Wpr/blde		1.00
- Complete wheel alignment.test drive.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Battery		1.00
		Syn-atf Trans Fluid	I S	16.00
		P245 65 Sr17		2.00
		Real Shock		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 10.75 C	Comm: 0.00	Labor: 645.00	Parts: 817.13	Total: 1,462.1

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1704616 Meter: 58852 In Date: 05/09/2017 Closed: 05/09/2017

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1705773 Meter: 60025 In Date: 06/09/2017 Closed: 06/21/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service		L/f Door Panel		1.00
- Replace left front door trim panel.vinyl torn.		5w20 Engine Oil		12.00
- Rotate and balance four tires.nitrofill.		Napagold Oil Filte	r	2.00
- Shop Supplies		Accufit Beam		2.00
		Accufit Beam		2.00
		Shop Supplies		1.00
Hours: 4.55	Comm: 0.00	Labor: 273.00	Parts: 790.39	Total: 1,063.39

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1711634 Meter: 64301 In Date: 11/28/2017 Closed: 12/18/2017

Problem: P.M. service and Carbon monoxide concerns 17N03.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Inspect all brakes.r&i new rear brakes .replace both rea	r rotors and calipers	Napagold Oil Filte	r	1.00
and pads .flush and bleed brake system.road test.	·	Washer Fluid Cond	centr	1.00
- Rotate and high speed balance all four wheels.nitro fill	all.	26in Exactfit-beam	ı	1.00
- Transport to and from dealer for recall 17n03 carbon m	nonoxide concern.	22in Exactfit-beam	ı	1.00
- Shop Supplies		11in Exactfit-rear		1.00
		Brake Pad		1.00
		Rear Brake Rotor		2.00
		brake fluid		2.00
		Rear Caliper		1.00
		Brake Caliper		1.00
		Shop Supplies		1.00
Hours: 9.75	Comm: 0.00	Labor: 585.00	Parts: 399.77	Total: 984.77

Work Order: 1801752 Meter: 65778 In Date: 02/14/2018 Closed: 02/14/2018

Problem: Right rear tire going flat.

Work Completed		Parts Issued		Quantity
- Repair right rear tire and balance .nitrogen fill tires.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00

Hours: 2.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

	1805444 P.M. Service	Meter: 68227		In Date:	05/29/2018	Closed:	06/07/2018
Work Com	pleted		Parts Issued			Qı	uantity
- P.m. serv	ce.		Napagold Oil Filter				1.00
- Replace t	wo tires .rotate and high speed	balance all four tires. Nitrofill	5w20 Engine Oil				6.00
tires.			11in Exactfit-rear				1.00
- Perform	our wheel alignment. Road tes	t.	26in Exactfit-beam				1.00
- Shop Sup	pplies		22in Exactfit-beam				1.00
			P245 65 Sr17				2.00
			Mac Wite Lithium G	res			1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
	Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 46	3.91	Total:	898.91
Work Order: Problem:	1810358 remove emergency lights & si	Meter: 71249 ren to transfer		In Date:	10/05/2018	Closed:	10/29/2018
Work Com	pleted		Parts Issued			Qı	uantity
	mergency lights and siren		Shop Supplies				1.00
- Shop Sup	Hours: 2.00	Comm: 0.00	Labor: 134.00	Parts: 3.0	0	Total:	137.00
Work Order: Problem:	1810437 Transition Prep Charge	Meter: 71000		In Date:	10/10/2018	Closed:	10/10/2018
Work Com	pleted						
- Transitio	n Prep Charge						

Comm: 0.00

Labor: 134.00

Parts: 0.00

Total: 134.00

Hours: 4.25

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1811795 Meter: 71667 In Date: 11/16/2018 **Closed:** 11/21/2018 Problem: pm service **Parts Issued** Quantity **Work Completed** 6.00 Napa Quart 5w20 - pm service Napagold Oil Filter 1.00 11in Exactfit-rear 1.00 22in Exactfit-beam 1.00 26in Exactfit-beam 1.00 Hours: 2.75 Comm: 0.00 Labor: 184.25 Parts: 67.95 Total: 252.20 Work Order: 1812982 Meter: 72246 12/21/2018 Closed: 01/15/2019 In Date: **Problem:** wiper blades **Work Completed** - set up repairs & reasset Hours: 1.00 Comm: 400.46 Labor: 67.00 Parts: 0.00 Total: 467.46 Work Order: 1900812 Meter: 73594 In Date: 01/22/2019 Closed: 01/25/2019 Problem: horn inop **Work Completed** - trace down and repair broken wire under dash Hours: 1.50 Comm: 0.00 Labor: 100.50 Parts: 0.00 Total: 100.50 Work Order: 1904543 Meter: 76100 04/26/2019 Closed: 05/08/2019 In Date: Problem: pm service **Work Completed Parts Issued** Quantity Napa Quart 5w20 6.00 - Pm Service Napagold Oil Filter 1.00 - Mount and balance 2 tires and reset Tpm light Washer Fluid Concentr 1.00 26in Exactfit-beam 1.00 22in Exactfit-beam 1.00 2.00 245/65r17 Mic Defender Ltx Tire Disposal Fee 2.00

Comm: 0.00

Labor: 284.75

Parts: 503.08

Total: 787.83

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1905073 Meter: 76100 In Date: 05/09/2019 Closed: 05/09/2019

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1909111 Meter: 78603 In Date: 08/30/2019 Closed: 09/13/2019

Problem: recall 19S17

Work Completed

- to dealer for recall 19s17. rear toe linls

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 0.00 Total: 134.00

Work Order: 1910387 Meter: 79691 In Date: 10/07/2019 Closed: 10/21/2019

Problem: pm/ ABS light on

Work Completed		Parts Issued		Quantity
- Pm Service		Napagold Oil Filte	er	1.00
- Test & repl. battery; checked charging system		Napa Quart 5w20		6.00
- Check low tire light - traced to bad sensor-If tire-	-repl. sensor & retrain	22in Exactfit-beam	n	1.00
system		26in Exactfit-beam	n	1.00
	- Check for codes - U3000 Internal controller fault; R&r Hcu to replace Abs		Battery	
module, flash module and bleed brake system		Tpms12 Sensor Ti	re Pr	1.00
		Abs Module		1.00
		B Fluid Dot 3-32o	Z	1.00
Hours: 12.75	Comm: 0.00	Labor: 930.75	Parts: 706.91	Total: 1,637.66

Work Order: 1910723 Meter: 79814 In Date: 10/18/2019 Closed: 10/28/2019

Problem: tire light on

Work Completed		Parts Issued		Quantity
- Lr tire replacement; mount and balance		245/65r17 Mic De	efender Ltx	1.00
·		Tire Disposal Fee		1.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 222.88	Total: 295.8

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1910851 Meter: 79814 In Date: 10/22/2019 Closed: 10/22/2019

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 2004546 Meter: 85009 In Date: 05/06/2020 Closed: 05/13/2020

Problem: pm service

Work Completed		Parts Issued		Quantity	
- pm service		Napa Quart 5w20	6.00		
- replace tire & fill, balance	ce tire & fill, balance		Napagold Oil Filter		
- replace frt pads & rotors			22in Exactfit-beam		
		26in Exactfit-beam		1.00	
		245/65r17 Mic Defe	1.00		
		Non-chlor Brake Cli	nr	2.00	
		Brake Rotor		2.00	
		Front Brake Pad		1.00	
		Tire Disposal Fee		1.00	
Hours: 7.75	Comm: 0.00	Labor: 565.75	Parts: 524.69	Total: 1,090.44	

Work Order: 2007905 Meter: 86993 In Date: 08/11/2020 Closed: 08/11/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: Problem:	2012291 pm/ tire light/ no start	Meter:	91491		In Date:	12/10/2020	Closed:	12/18/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Napagold Oil Filter				1.00
- patch tire	e & nitro & balance			Napa Quart 5w20				6.00
·				Washer Fluid Concer	ntr			1.00
				22in Exactfit-beam				1.00
				26in Exactfit-beam				1.00
				11in Exactfit-rear				1.00
	Hours: 3.75		Comm: 0.00	Labor: 273.75	Parts: 69.	.09	Total:	342.84
Work Order:	2012645 1 - Detail Vehicle Wash Ticker	Meter:	91491		In Date:	12/18/2020	Closed:	12/18/2020
Work Com - 1 - Detai	I Vehicle Wash Ticket(s) Issued Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	10	Total	96.00
Work Order:		Meter:		Labor. 0.00	In Date:	03/04/2021		03/26/2021
	Check engine light on / Detail	weter:	93043		in Date:	03/04/2021	Ciosea:	03/20/2021
Work Com	npleted			Parts Issued			Qı	uantity
- Diag, airl	bag light, and replace driver sea	it beat buckle p	retensioner	Quick Strut				1.00
- Diag clur	nking noise. Replace left and rig	ht strut assemb	olies	Quick Strut				1.00
- Rotate a	nd nitro tires			Pretension				1.00
	Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 789	9.36	Total:	1,154.36
Work Order: Problem:	2103600 1 - Detail Vehicle Wash Ticket	Meter:	93843		In Date:	03/29/2021	Closed:	03/30/2021
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2106921 M Problem: pm service	leter: 95310		In Date:	06/24/2021	Closed:	07/01/2021
Work Completed		Parts Issued			Qı	uantity
- Preventive Maint. Service		Napa Quart 5w20				6.00
		Napagold Oil Filter				1.00
		Napagold Air Filter				1.00
		Washer Fluid Concer	ntr			1.00
		26in Exactfit-beam				1.00
		22in Exactfit-beam				1.00
		11in Exactfit-rear				1.00
Hours: 2.75	Comm: 0.00	Labor: 200.75	Parts: 79.	88	Total:	280.63
Work Order: 2109790 M Problem: check wipers	eter : 97341		In Date:	09/09/2021	Closed:	09/22/2021
Work Completed		Parts Issued			Qı	uantity
- Replace Front Wiper Blades		26in Exactfit-beam				1.00
- Replace Hollt Wipel blades		Zoiii Exactiit-beaiii				
- Replace Front Wiper blades		22in Exactfit-beam				1.00
Hours: 0.50	Comm: 0.00		Parts: 21.	15	Total:	1.00 57.65
Hours: 0.50	Comm: 0.00	22in Exactfit-beam	Parts: 21.	15 12/08/2021		
Hours: 0.50 Work Order: 2112982 M		22in Exactfit-beam			Closed:	57.65
Hours: 0.50 Work Order: 2112982 M Problem: pm service, NO START		22in Exactfit-beam Labor: 36.50			Closed:	57.65
Hours: 0.50 Work Order: 2112982 M Problem: pm service, NO START Work Completed	eter : 98437	22in Exactfit-beam Labor: 36.50 Parts Issued			Closed:	57.65 12/09/2021 uantity
Hours: 0.50 Work Order: 2112982 M Problem: pm service, NO START Work Completed - Preventive Maint. Service	eter : 98437	22in Exactfit-beam Labor: 36.50 Parts Issued Napa Quart 5w20			Closed:	57.65 12/09/2021 uantity 6.00
Hours: 0.50 Work Order: 2112982 M Problem: pm service, NO START Work Completed - Preventive Maint. Service	eter : 98437	22in Exactfit-beam Labor: 36.50 Parts Issued Napa Quart 5w20 Filter			Closed:	57.65 12/09/2021 uantity 6.00 1.00
Hours: 0.50 Work Order: 2112982 M Problem: pm service, NO START Work Completed - Preventive Maint. Service	eter : 98437	22in Exactfit-beam Labor: 36.50 Parts Issued Napa Quart 5w20 Filter 26in Exactfit-beam			Closed:	57.65 12/09/2021 uantity 6.00 1.00 1.00

Palm Beach County Fleet Management Asset Maintenance History 10185508 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2113103 Meter: 98446 In Date: 12/07/2021 Closed: 12/13/2021

Problem: NO START

Work Completed

- Tow From: 225 S Congress Ave, Delray Beach To: Se Shop

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2113701 Meter: 98448 In Date: 12/30/2021 Closed: 01/04/2022

Problem: headlight out

Work Completed Parts Issued Quantity

- Lights,headlites Boxed Capsules 1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 7.45 Total: 43.95

Work Order: 2201242 Meter: 99849 In Date: 02/03/2022 Closed: 03/03/2022

Problem: airbag light/ washer fluid/ shakes when stopping/ engine light

Work Completed

- Check over vehicle and clear code.

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Work Order: 2202466 Meter: 99849 In Date: 03/04/2022 Closed: 03/04/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 155.60 Total Labor: 9,974.25 Total Comm: 1,313.52 Total Parts: 10,598.04