

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 236.85 Labor: 15,692.50 Parts: 14,824.87 Comm: 3,810.84 Charged: 34328.21

Work Order: 1405983 **Meter:** 323 **In Date:** 06/18/2014 **Closed:** 06/18/2014
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1406679 **Meter:** 324 **In Date:** 07/08/2014 **Closed:** 07/31/2014
Problem: install and wire in saddle tank from previous truck

Work Completed

- install and wire in saddle tank in new truck. install correct fuel nozzle
- Shop Supplies

Parts Issued

Quantity

Fuel Nozzle	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 34.16 Total: 514.16

Work Order: 1408317 **Meter:** 1987 **In Date:** 08/21/2014 **Closed:** 08/27/2014
Problem: Request to equip truck with four off road tires.

Work Completed

- Replace and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Lt285 70 R17 Mt Tire	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 1,064.27 Total: 1,184.27

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1500174 **Meter:** 7613 **In Date:** 01/06/2015 **Closed:** 01/22/2015
Problem: Pm service.Safety recall #14C10

Work Completed

- Pm service.
- Replace rear brake pads and resurface both rear brake rotors.service calipers.flush and bleed hydraulic brake system.test drive.
- Inspect and service transfer fuel tank.
- Inspect and service winch.
- Rotate and balance all four tires.
- Transport vehicle to and from dealer for safety recall # 14c10
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Floor Mat-2pc Rub Bk	1.00
Stg Wheel Cov - Ford	2.00
Wiper Blade	2.00
Brake Pads	1.00
Brake Pads	1.00
Cl3z2200c Brake Pads	1.00
Brk Fluid Dot 4-12oz	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 11.75

Comm: 0.00

Labor: 705.00

Parts: 359.14

Total: 1,064.14

Work Order: 1503049 **Meter:** 9683 **In Date:** 03/24/2015 **Closed:** 03/31/2015
Problem: Noise in four wheel drive.

Work Completed

- Diagnose for clicking noise in four wheel drive on turns.replace defective left front axle shaft assembly.retest.
- Inspect and replace broken winch fair lead assembly.
- Shop Supplies

Parts Issued

Quantity

Front Axleshaft	1.00
Shop Supplies	1.00

Hours: 2.40

Comm: 0.00

Labor: 144.00

Parts: 242.87

Total: 386.87

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1603479 **Meter:** 21558 **In Date:** 04/01/2016 **Closed:** 04/19/2016
Problem: Pm service.

Work Completed

- P.m. Service.
- Inspect and service aux. fuel system.
- Resurface both rear brake rotors,replace rear pads.service and lube calipers,flush and bleed system.
- Inspect and service winch.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
B Fluid Dot 3-32oz	1.00
Brake Cleaner	1.00
Brake Pad Motorcraft	1.00
Braket Real Caliper	1.00
Shop Supplies	1.00

Hours: 9.75

Comm: 0.00

Labor: 585.00

Parts: 200.53

Total: 785.53

Work Order: 1610147 **Meter:** 27512 **In Date:** 09/28/2016 **Closed:** 10/20/2016
Problem: P.M. service and install tool box.

Work Completed

- P.m. Service.
- Test battery and charging system.recharge and retest battery,failed load test.replace defective battery.
- Replace and rewire corroded trailer plug.
- Replace front brake rotors and brake pads.service and lube caliper.flush and bleed system.
- Inspect and service aux. fuel system.
- Replace and balance four new tires.
- Install toolbox on truck bed.
- Inspect and service winch.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Battery 65	1.00
trailer plug	1.00
Front Rotor	2.00
Brake Pad	1.00
Napagold Fuel Filter	1.00
Tire Lt/285/70/r17	4.00
Shop Supplies	1.00
Toolbox	1.00
Tire Disposal Fee	4.00

Hours: 16.50

Comm: 0.00

Labor: 990.00

Parts: 1,990.36

Total: 2,980.36

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1709453 **Meter:** 38248 **In Date:** 09/28/2017 **Closed:** 10/17/2017
Problem: PM Service, Check fire extinguisher.

Work Completed

- P.m. service.
- Rear shocks failed .r&r with new.
- Inspect and service auxilary fuel tank.
- Inspect and service winch.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shock Absorber	2.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 405.00

Parts: 154.75

Total: 559.75

Work Order: 1712661 **Meter:** 40597 **In Date:** 12/22/2017 **Closed:** 12/28/2017
Problem: Tire light on.

Work Completed

- Repair left rear tire and balance .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1802657 **Meter:** 42962 **In Date:** 03/12/2018 **Closed:** 03/15/2018
Problem: P.M. Service.Rattling noise,especially when turning.

Work Completed

- P.m. service . Test drive for noise .only rattle heard was tool in side pocket. Unable to duplicate any other rattle at this time.
- Rotated and balanced all four tires. Nitrogen fill all tires.
- Inspect and service auxilary fuel pump and tank.
- Inspect and service winch.
- Inspect and service transfer case .drain and refill.
- Resurface both rear rotors .inspect and service calipers and replace brake pads .flush and bleed brake system and test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Mac Wite Lithium Gres	1.00
Napagold Fuel Filter	1.00
Ford Transfer Case Fluid	2.00
Rear Brake Pad	1.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00

Hours: 10.75

Comm: 0.00

Labor: 645.00

Parts: 139.93

Total: 784.93

Work Order: 1803989 **Meter:** 44043 **In Date:** 04/17/2018 **Closed:** 04/19/2018
Problem: Left outside mirror cracked.

Work Completed

- Remove left front door panel to replace broken outside mirror assembly.
- Shop Supplies

Parts Issued

Quantity

Mirror Asy	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 277.54

Total: 337.54

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1808549

Meter: 48506

In Date: 08/20/2018 **Closed:** 09/04/2018

Problem: P.M. service.

Work Completed

- P.m. service.
- Inspect and service aux fuel tank .
- Test and replace blower resistor due to low speed inop.
- Resurface both front rotors . Replace front pads and calipers . Flush and bleed brake system . Road test. Replace missing center cap.
- Inspect and service winch.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Blower Resistor	1.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-12oz	2.00
Caliper Washer	4.00
Caliper	1.00
Caliper	1.00
Center Cap	1.00
Shop Supplies	1.00

Hours: 10.55

Comm: 0.00

Labor: 633.00

Parts: 414.52

Total: 1,047.52

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1900836 **Meter:** 53619 **In Date:** 01/23/2019 **Closed:** 02/07/2019
Problem: P.M. service and right front tire going flat.

Work Completed

- P.m. service.
- Pressure test and inspect cooling system . Flush and refill coolant .
- Check battery and charging system . Battery failed load test . R&r defective battery .
- Resurface rear rotors. Replace rear calipers and brake pads . Flush and bleed brake system . Road test.
- Replace two tires . Rotate and high speed balance all four tires. Nitrofill all.
- Inspect and service auxiliary fuel system .
- Inspect and service winch .
- Complete front end alignment . Road test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Anti Freeze Motorcraft	2.00
Battery 65	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Pad	1.00
Housing	1.00
Housing	1.00
Kit Braket Busching	1.00
Lt285/70/17tire	2.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 15.75

Comm: 0.00

Labor: 1,055.25

Parts: 1,364.35

Total: 2,419.60

Work Order: 1901620 **Meter:** 53821 **In Date:** 02/12/2019 **Closed:** 02/14/2019
Problem: Install air compressor and hose rail.

Work Completed

- Fabricate and mount air compressor and hose reel .pipe together and supply tool quick connect couplers.
- Shop Supplies

Parts Issued

Quantity

Adapter	6.00
Coupler	2.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 268.00

Parts: 27.90

Total: 295.90

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1903860 **Meter:** 55953 **In Date:** 04/09/2019 **Closed:** 04/16/2019
Problem: P.M. service and noise from engine .

Work Completed

- P.m. service.
- Diagnose noise from belt area.r&r defective belt tensionor and belt . Retest .
- Inspect and service auxilary fuel tank .
- Inspect and service winch .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
V Belt	1.00
Tensioner Assy	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 6.85

Comm: 0.00

Labor: 458.95

Parts: 194.78

Total: 653.73

Work Order: 1908111 **Meter:** 59766 **In Date:** 08/06/2019 **Closed:** 08/07/2019
Problem: Saddle tank pumping very slow.

Work Completed

- Saddle tank pumping very slow.replace filter.

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Labor: 33.50	Parts: 5.36
Total: 38.86	

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1909026

Meter: 60723

In Date: 08/28/2019 **Closed:** 09/11/2019

Problem: P.M. service , remove aux fuel tank and compressor .

Work Completed

- P.m. service.
- Diagnose noise from left front . Replace left front wheel bearing assembly and vacuum hub actuator assembly . Road test .
- Resurface all four rotors and service calipers . Replace brakes ,front and rear . Flush and bleed brake system . Road test .
- Inspect and service aux fule tank . Remove fuel tank and tool box and air compressor . Install tool box from asset 10202080 .
- Inspect and service winch .
- Test and replace defective trailer plug connector and rewire as needed.
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Actuator	1.00
Hub Assembly	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Brake Pad	1.00
Brake Pad	1.00
Napagold Fuel Filter	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 19.35

Comm: 0.00

Labor: 1,296.45

Parts: 671.36

Total: 1,967.81

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2001039

Meter: 65940

In Date: 01/30/2020 **Closed:** 02/10/2020

Problem: P.M. service.

Work Completed

- P.m. service.
- Replace two tires . Rotate and balance all four tires . Nitrofill all and reset Tpms .
- Computer diagnose misfire . Perform tune up . Remove intake to replace all six spark plugs . Retest .
- Perform complete air intake decarb and cleaning . Flush injectors . Clean throttle body .
- Inspect and service rear differential .
- Inspect and service front differential .
- Perform complete front end alignment and road test .
- Inspect and service winch .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Dielect Silicone Comp	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Px Grey Rtv Silicone	1.00
75w140 Ford Axle Lube	3.00
1qt Syngear Oil 75-90	2.00
Non-chlor Brake Clnr	2.00
Lt285/70/17tire	2.00
Spark Plugs	6.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 15.85

Comm: 0.00

Labor: 1,157.05

Parts: 1,123.67

Total: 2,280.72

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2004999 **Meter:** 71205 **In Date:** 05/18/2020 **Closed:** 06/04/2020
Problem: P.M. service and noise in front end on turns .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Diagnose noise . R&r defective right front axle and wheel bearing and locking actulators on both sides . Road test .
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.
- Replace both rear brake rotors and pads . Service calipers . Flush and bleed brake system . Road test .
- Inspect rear parking brakes . R&r worn out parking brake shoes and adjust .
- Perform complete front end alignment and road test .
- Inspect and service winch .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Mac Wite Lithium Gres	1.00
Non-chlor Brake Clnr	1.00
Actuator	2.00
Hub Assembly	1.00
Lt285/70/17tire	2.00
Rotor Assy	2.00
Fron Brake Pad	1.00
Parking Brake Shoe	1.00
Rotor Assy	2.00
Shaft	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 18.25

Comm: 0.00

Labor: 1,332.25

Parts: 2,314.39

Total: 3,646.64

Work Order: 2009012 **Meter:** 75912 **In Date:** 09/08/2020 **Closed:** 09/10/2020
Problem: Left rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Nitrofill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2009329 **Meter:** 76361 **In Date:** 09/17/2020 **Closed:** 09/24/2020
Problem: PM Service, Wheel well platic comming off.

Work Completed

Parts Issued

Quantity

- P.m. service . Secure front valance hanging down .
- Inspect and service winch .
- Remove stuck debris from under side of chassis and brakes .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.75 Comm: 0.00 Labor: 419.75 Parts: 33.85 Total: 453.60

Work Order: 2010951 **Meter:** 76361 **In Date:** 09/24/2020 **Closed:** 10/30/2020
Problem: damage to tail gate, rear bumper & bumper needs repainted

Work Completed

- damage to tail gate, rear bumper & bumper needs repainted

Hours: 0.00 Comm: 1,656.00 Labor: 0.00 Parts: 0.00 Total: 1,656.00

Work Order: 2100430 **Meter:** 79148 **In Date:** 01/13/2021 **Closed:** 01/21/2021
Problem: Hard to start after fueling , debris from A/C vents and smells bad .

Work Completed

Parts Issued

Quantity

- Computer diagnose long crank after fueling .codes P1450 ,p2198 and P2196 . Perform Evap test . R&r stuck open purge valve and retest and clear codes .
- Clean A/c vents and evaporator . Flush evaporator and deodorize . Retest . Replace worn out steering wheel cover .
- Shop Supplies

Purge Valve	1.00
Whl/cvr	1.00
Evap Odor Elinitator	1.00
Shop Supplies	1.00

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 82.15 Total: 337.65

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2102645 **Meter:** 80351 **In Date:** 03/09/2021 **Closed:** 03/23/2021
Problem: P.M. service and four wheel drive inop .

Work Completed

- Preventive Maint. Service
- check ,pin point test and replaced defective l/h tag light socket and bulb
- verify need brakes,replace 2 front brakes rotors,pads front and rear,resurfaced both rear brakes rotors,flush,bleed service calipers,road test to verify noemal operation
- Pressure test and inspect cooling system ,found leaking water Pump and heater hose, replace defective water pump , thermostat housing , hose from heater core,drive & a/c belts ,, o ring , flush and refill , verify normal operation
- check,replace defective blower resistor
- verify complaint ,pin point test vacuum and electrical systems,, replaced both defective front auto lock actuator and front drive shaft by R&r all necessary parts . verify normal operation
- balance and rotate all 4 tires . Nitro fill all.
- inspect and service winch
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Tag Lamp	1.00
Brake Rotor	2.00
Brake Pad	1.00
Brake Pad	1.00
Gasket	1.00
Heater Hose	1.00
V Belt	1.00
V Belt	1.00
Tmermostat Housing	1.00
Water Pump	1.00
Anti Freeze Motorcraft	2.00
Blower Motor Resistor	1.00
Actuator	2.00
Shaft Assy	1.00
Shop Supplies	1.00

Hours: 23.10

Comm: 0.00

Labor: 1,686.30

Parts: 1,673.11

Total: 3,359.41

Work Order: 2106809 **Meter:** 83361 **In Date:** 06/22/2021 **Closed:** 06/23/2021
Problem: Towed in for No Start

Work Completed

- Charge battery fully . Test battery and charging system . R&r defective battery .
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 147.81

Total: 220.81

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2107060 **Meter:** 83361 **In Date:** 06/22/2021 **Closed:** 06/28/2021
Problem: No Start

Work Completed

- Tow From: 2300 Jog Rd (parking garage A15-5th floor) To: 2601 Vista Parkway

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2109387 **Meter:** 85835 **In Date:** 08/30/2021 **Closed:** 09/09/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose winch inop. Found to have bad solenoid. R and R solenoid. Inspect and serviced winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
22" Wiper Blade	2.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Repl Solenoid Term Up	1.00
Shop Supplies	1.00

Hours: 6.25 Comm: 0.00 Labor: 456.25 Parts: 57.53 Total: 513.78

Work Order: 2202204 **Meter:** 91542 **In Date:** 02/25/2022 **Closed:** 03/07/2022
Problem: PM Service. passenger windshield wiper

Work Completed

- Preventive Maint. Service
- replaced two tires, balance and rotate all 4 Nitro fill all.
- check ,verify needs rear brakes,replaced both rear rotors,pads,service calipers,flush and bleed fluid then road test
- competed front end alignment and road test
- inspect and service winch
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brk Fluid Dot 4-32oz	1.00
Brake Pads	1.00
Brake Rotor	2.00
Lt285/70/17tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 12.25 Comm: 0.00 Labor: 894.25 Parts: 1,098.86 Total: 1,993.11

5/2/2022
10:42:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195215 2014 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2203896 **Meter:** 92518 **In Date:** 04/12/2022 **Closed:** 04/12/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 236.85

Total Labor: 15,692.50

Total Comm: 3,810.84

Total Parts: 14,824.87