

5/2/2022
11:42:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10210072 2019 JACOBSON GROOM MASTER II Ballfield Groomer, Diesel

Total Hours: 43.00 Labor: 3,127.00 Parts: 2,220.45 Comm: 0.00 Charged: 5347.45

Work Order: 1903567 **Meter:** 1 **In Date:** 04/02/2019 **Closed:** 05/31/2019
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- missing scarifire
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 2000868 **Meter:** 212 **In Date:** 01/27/2020 **Closed:** 02/06/2020
Problem: pm/ stalls with acceloration/ see notes

Work Completed

Parts Issued

Quantity

- pm service
- hydraulic service
- diagnose and adjust rod on accellorator pedal and replace brake prox switch
- Shop Supplies

Napa Qt 15w40 3.00
Napagold Oil Filter 1.00
Napagold Fuel Filter 1.00
Napagold Air Filter 1.00
Non-chlor Brake Clnr 1.00
Napa Trans Filter 1.00
Aw68 Hydro Fluid Hydr 4.00
Switch, Prox 1.00
Shop Supplies 1.00

Hours: 7.00 Comm: 0.00 Labor: 511.00 Parts: 179.62 Total: 690.62

Work Order: 2006856 **Meter:** 270 **In Date:** 07/14/2020 **Closed:** 07/24/2020
Problem: needs new tire (tire only)

Work Completed

Parts Issued

Quantity

- replace tire
- Shop Supplies

20x11.00-10 4ply Carl Turf Tamer 1.00
Shop Supplies 1.00
Tire Disposal Fee 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 171.95 Total: 244.95

5/2/2022
11:42:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10210072 2019 JACOBSON GROOM MASTER II Ballfield Groomer, Diesel

Work Order: 2009248 **Meter:** 270 **In Date:** 09/15/2020 **Closed:** 10/21/2020
Problem: wont stay running long/ see notes

Work Completed

- service
- readjust pedal & brake rod
- replace relays
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Atf Plus 4	1.00
Pm-22-a Additive Dies	1.00
Napagold Air Filter	1.00
Relay	3.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00 Parts: 96.22 Total: 461.22

Work Order: 2103568 **Meter:** 552 **In Date:** 03/29/2021 **Closed:** 04/26/2021
Problem: The bracket for the fuel intake is broken. PM service

Work Completed

- Preventive Maint. Service
- fabricate fuel bracket - replace fuel solenoid readjust rod
- replace 2 rear tires
- repair blow relays - clean wiring
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	3.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
Pm-22-a Additive Dies	1.00
20x11.00-10 4ply Carl Turf Tamer	2.00
Solenoid Fuel	1.00
Qd Electronic Cleaner	1.00
Threaded Rod	1.00
Relay	3.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 817.01 Total: 1,547.01

5/2/2022
11:42:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10210072 2019 JACOBSON GROOM MASTER II Ballfield Groomer, Diesel

Work Order: 2106363 **Meter:** 575 **In Date:** 06/11/2021 **Closed:** 06/28/2021

Problem: broken fuel shut off. P brake wont hold

Work Completed

- replace fuel shut off solenoid n rod bracket - readjust shut off n on
- readjust parking brake - test
- Shop Supplies

Parts Issued

Quantity

Solenoid Rod	1.00
Solenoid Fuel	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 353.53

Total: 609.03

Work Order: 2112591 **Meter:** 879 **In Date:** 11/29/2021 **Closed:** 12/16/2021

Problem: Key broken off in ignition

Work Completed

- Removed Ignition Switch, Disassembled To Removed Broken Key
- Removed Fuel Solenoid And Bracket, Weld On Extra Suport, Re-installed And Adjusted Fuel Solenoid
- Load Test And Replaced Battery, Test Charging System
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 102.32

Total: 576.82

Work Order: 2200780 **Meter:** 882 **In Date:** 01/24/2022 **Closed:** 03/28/2022

Problem: will not start

Work Completed

- Ck Wont Start. Charge Battery And Test Electrical System. Replace Ignition Key Switch W/ Keys, And Starter (2x's)
- Shop Supplies

Parts Issued

Quantity

Starter	1.00
Keyswitch	1.00
Starter	1.00
Powersport Starter	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 494.16

Total: 859.16

5/2/2022
11:42:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10210072 2019 JACOBSON GROOM MASTER II Ballfield Groomer, Diesel

Work Order: 2203549 **Meter:** 890 **In Date:** 03/31/2022 **Closed:** 04/22/2022
Problem: Bald Front Tire/ pm

Work Completed

Parts Issued

Quantity

- Ck No Start. Remove Panels To Charge Battery. New Replacement Was Delivered

Shop Supplies

1.00

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Work Order: 2204382 **Meter:** 890 **In Date:** 04/26/2022 **Closed:** 04/26/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 43.00

Total Labor: 3,127.00

Total Comm: 0.00

Total Parts: 2,220.45