

5/5/2022  
1:49:47 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

---

<b>Total Hours: 89.75</b>	<b>Labor: 6,116.75</b>	<b>Parts: 4,100.63</b>	<b>Comm: 0.00</b>	<b>Charged: 10217.38</b>
---------------------------	------------------------	------------------------	-------------------	--------------------------

---

<b>Work Order:</b> 1500500	<b>Meter:</b> 1	<b>In Date:</b> 01/14/2015	<b>Closed:</b> 01/14/2015
<b>Problem:</b> 1061 - Pre Delivery Inspection			

**Work Completed**

- Pre Delivery Inspection

Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
-------------	------------	---------------	-------------	---------------

---

<b>Work Order:</b> 1601042	<b>Meter:</b> 128	<b>In Date:</b> 01/29/2016	<b>Closed:</b> 02/04/2016
<b>Problem:</b> P.M.SERVICE			

**Work Completed**

- pm  
- svc hyd sys  
- wash eq  
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00	
Fuel Fil	1.00	
Napagold Fuel Filter	1.00	
Napagold Oil Filter	1.00	
15w40 Bulk South Reg	4.00	
Shop Supplies	1.00	
Labor: 360.00	Parts: 38.11	Total: 398.11

Hours: 6.00	Comm: 0.00
-------------	------------

5/5/2022  
1:49:47 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 1702041

**Meter:** 299

**In Date:** 02/28/2017 **Closed:** 03/20/2017

**Problem:** P.M.SERVICE DEAD BATTERY

**Work Completed**

- Pm service.
- C/c Battery.test battery bad.replace battery.check charging system
- Service Hyd.system.inspect lines,hoses,replace filter.correct fluid level.
- C/c rollers.verify needs all rollers.r/r rollers and hardware.
- Wash equipment.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Fuel Fil	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Group 26 Delco	1.00
Napa Trans Filter	1.00
Napa 20w50 Qt	2.00
Anti-scalp Wheel	4.00
Carriage Bolt	4.00
Lug Nut	4.00
Anti Scalp Wheel	3.00
Roller Shaft	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00

Parts: 340.63

Total: 880.63

5/5/2022  
1:49:47 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 1802272 **Meter:** 450 **In Date:** 02/28/2018 **Closed:** 03/12/2018  
**Problem:** PM Service.Missing spring in back.

**Work Completed**

- Pm Service.
- Replace broken spring on pump drive.service hydraulic system.replace filter,inspect lines,hoses etc.correct fluid level.
- Replace chute,front rollers,scalp wheels,etc.
- Wash equipment.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Fuel Fil	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napa Trans Filter	1.00
Napa 20w50 Qt	2.00
deck chutes	1.00
Carriage Bolt	2.00
Lug Nut	2.00
Pump Drive Spring	1.00
Anti Scalp Wheel	3.00
Roller Shaft	1.00
Anti-scalp Wheel	2.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 570.00

Parts: 309.11

Total: 879.11

**Work Order:** 1807219 **Meter:** 490 **In Date:** 07/16/2018 **Closed:** 07/23/2018  
**Problem:** Belt broken.Will not start.

**Work Completed**

- C/c wont start.verified belt jammed up crank.replace two belts.pto and Hyd.drive.
- Verify R/h hyd. motor blocked.remove bypass valve clear,clean and reinstall.
- Shop Supplies

**Parts Issued**

**Quantity**

481460 Clutch Belt Sc	1.00
Belt	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 210.00

Parts: 125.20

Total: 335.20

5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 1902255      **Meter:** 525      **In Date:** 02/28/2019      **Closed:** 03/11/2019  
**Problem:** PM Service.

**Work Completed**

- Pm Service.
- Service Hyd. system.replace hyd. filter
- Replace four anti-scalp wheels and hardware.
- Wash equipment.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Fuel Fil	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napa Trans Filter	1.00
Napa 20w50 Qt	2.00
Lug Nut	4.00
Carriage Bolt	4.00
Anti-scalp Wheel	4.00
Oil Filter	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 502.50      Parts: 222.29      Total: 724.79

5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 1909442      **Meter:** 563      **In Date:** 09/13/2019      **Closed:** 10/15/2019  
**Problem:** NEEDS CHUTE,PULLEY MAKING NOISE.

**Work Completed**

- C/c pulley.verify center spindle assm.bad.replace center spindle assm.blades,hardware and chute.test mow.
- Replace bad battery.check charging system.
- Verify clutch housing broken.replace electronic Pto clutch.
- Shop Supplies

**Parts Issued**

**Quantity**

Chute Spring	1.00
deck chutes	1.00
Battery	1.00
Locknut	3.00
Bolt	2.00
Hh Bolt	3.00
Washer	3.00
Nut	3.00
Spindle Assy	1.00
Bolt	2.00
Blades	3.00
Wing Nut	4.00
U Nut	4.00
Tapered Hub	1.00
Electric Clutch Assy	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 1,233.73

Total: 1,890.73

5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 2003898 **Meter:** 596 **In Date:** 04/20/2020 **Closed:** 04/30/2020  
**Problem:** PM Service

**Work Completed**

- Pm Service.
- Service Hyd.system.inspect all.change filter.correct fluid level.
- Replace antiscalp wheels Replace bearings on tensioner.
- Wash equipment.clean out radiator fins.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Fuel Fil	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napa 20w50 Qt	2.00
Oil Filter	1.00
Pulley	1.00
Bearing	2.00
Carriage Bolt	2.00
Lug Nut	2.00
Anti-scalp Wheel	2.00
Deck Wheel	3.00
Shop Supplies	1.00

Hours: 8.75

Comm: 0.00

Labor: 638.75

Parts: 274.14

Total: 912.89

**Work Order:** 2005141 **Meter:** 600 **In Date:** 05/21/2020 **Closed:** 05/29/2020  
**Problem:** Check battery.Wont start.

**Work Completed**

- Replace battery.battery tested bad.check charging system.
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Shop Supplies	1.00

Hours: 0.75

Comm: 0.00

Labor: 54.75

Parts: 135.33

Total: 190.08

5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

---

**Work Order:** 2005826      **Meter:** 604      **In Date:** 06/11/2020      **Closed:** 06/30/2020  
**Problem:** Broken belt.

**Work Completed**

- C/c broken belt.level spindle pulleys.lube all.r/r belt.test mow.
- Verify wont start.found ground wire on battery bad.r/r ground wire.
- Shop Supplies

Hours: 4.25

Comm: 0.00

**Parts Issued**

**Quantity**

Cutter Deck Belt	1.00
Neg Bat Cable	1.00
Shop Supplies	1.00

Labor: 310.25

Parts: 145.36

Total: 455.61

---

**Work Order:** 2009257      **Meter:** 629      **In Date:** 09/15/2020      **Closed:** 09/28/2020  
**Problem:** Check no crank no start and battery.

**Work Completed**

- Replace battery.
- Verify blown fuse.repair worn area in wire harness.unable to duplicate problem.
- Bolt for seat fell out.repair and reinstall.
- Replace two rear tires.
- Shop Supplies

Hours: 5.50

Comm: 0.00

**Parts Issued**

**Quantity**

Battery	1.00
Atc-20 Fuse	1.00
Cable Tie	1.00
24x12.00-12/4 Turf Master	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 401.50

Parts: 431.92

Total: 833.42

5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 2104669  
**Problem:** PM

**Meter:** 675

**In Date:** 04/27/2021 **Closed:** 05/05/2021

**Work Completed**

- Preventive Maint. Service
- Service hydraulic system, replace filter correct fluid level
- Replace bearings in front left wheel.
- Replace all rollers anti scalp wheels and brackets, wing nuts etc..
- Wash unit for service and repairs.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Fuel Fil	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napa 20w50 Qt	1.00
Oil Filter	1.00
43583 Sleeve Scag	1.00
Seal	2.00
Tappered Bearing Set	2.00
U Nut	3.00
Carriage Bolt	4.00
Anti-scalp Wheel Bracket	4.00
Lug Nut	4.00
Anti-scalp Wheel	4.00
Wheel Deck	3.00
Roller Shaft	1.00
Wing Nut	3.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 508.17

Total: 1,274.67



5/5/2022  
1:49:48 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10198090 2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Work Order:** 2113298      **Meter:** 712      **In Date:** 12/16/2021      **Closed:** 01/06/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level and inspect all.
- Replace 3 blades and cut out two seized spindle bolts.
- Verify left rear scalp wheel bracket broke off, Fabricate and weld back onto the deck. Replace all anti scalp wheels/rollers and hardware.
- Shop Supplies

**Parts Issued**

**Quantity**

15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Oil Filter	1.00
Napa 20w50 Qt	2.00
Hh Bolt	2.00
Roller Shaft	3.00
Deck Wheel	3.00
Lug Nut	4.00
Carriage Bolt	4.00
Anti-scalp Wheel	4.00
Nut	2.00
Blades	3.00
Shop Supplies	1.00

Hours: 11.50      Comm: 0.00

Labor: 839.50      Parts: 336.68      Total: 1,176.18

**Work Order:** 2204386      **Meter:** 720      **In Date:** 04/26/2022      **Closed:** 04/26/2022  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00

Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 89.75**

**Total Labor: 6,116.75**

**Total Comm: 0.00**

**Total Parts: 4,100.63**