

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 118.30 Labor: 8,047.60 Parts: 5,171.33 Comm: 105.54 Charged: 13324.47

Work Order: 1600975 **Meter:** 299 **In Date:** 01/28/2016 **Closed:** 01/29/2016
Problem: TRAILER PLUG

Work Completed

- Replace Trailer Plug
- Shop Supplies

Hours: 1.50 Comm: 0.00

Parts Issued

	Quantity
Female Conn Socket	1.00
Shop Supplies	1.00

Labor: 90.00 Parts: 13.12 Total: 103.12

Work Order: 1601076 **Meter:** 300 **In Date:** 02/01/2016 **Closed:** 02/01/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00

Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1608457 **Meter:** 4572 **In Date:** 08/16/2016 **Closed:** 08/30/2016
Problem: P.M. service and install strobe lights.

Work Completed

- P.m. Service.
- Install four corner strobe lights.fabricate and install wiring and switch.
- Rotate and balance all tires.
- Shop Supplies

Hours: 11.00 Comm: 0.00

Parts Issued

	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Vtx609a Led Strobe Am	2.00
Vtx609c Led Strobe Cl	2.00
Fuse Holder	1.00
Rocker Led Blk Ambe	1.00
Clr Rtv Silcn Sealant	1.00
Fab Loom-split Poly	25.00
Shop Supplies	1.00

Labor: 660.00 Parts: 526.48 Total: 1,186.48

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1611221 **Meter:** 5972 **In Date:** 10/28/2016 **Closed:** 10/28/2016
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1700618 **Meter:** 9760 **In Date:** 01/20/2017 **Closed:** 01/31/2017
Problem: Right rear tire going flat.

Work Completed

- Repair and balance right rear tire.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1701111 **Meter:** 10254 **In Date:** 02/02/2017 **Closed:** 02/22/2017
Problem: P.M. Service.Pulls right and recall.

Work Completed

- P.m. Service.

- Complete wheel alignment.test drive.

- Rotate and balance tires.

- Transport vehicle to dealer for recall #16b32.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Shop Supplies 1.00

Hours: 7.50 Comm: 0.00 Labor: 450.00 Parts: 18.22 Total: 468.22

Work Order: 1705389 **Meter:** 15265 **In Date:** 05/31/2017 **Closed:** 06/06/2017
Problem: P.M. Service.

Work Completed

- P.m. service.

- High speed balanced all four tires.nitro filled .

- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00

5w20 Engine Oil 7.00

22" Wiper Blade 2.00

Washer Fluid Concentr 1.00

Used Fire X Refurbished 1.00

Shop Supplies 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 43.37 Total: 223.37

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1710737 **Meter:** 20269 **In Date:** 10/31/2017 **Closed:** 11/16/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace cracked left rear tail lamp lens assembly with new.fabricate lens to install Led strobe lamp.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Clr Rtv Silcn Sealant	1.00
Lamp Assy	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 114.91 Total: 354.91

Work Order: 1802307 **Meter:** 25975 **In Date:** 03/01/2018 **Closed:** 03/23/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace all four tires .nitrogen fill and balance all four tires.
- Perform front end alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
183114470 P245-70r17	4.00
Napagold Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 877.45 Total: 1,267.45

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1908057 **Meter:** 35049 **In Date:** 08/05/2019 **Closed:** 08/13/2019
Problem: PM Service, Computer stand will not stay in place, Detail.

Work Completed

Parts Issued

Quantity

- P.m. service
- Resurface both rear brake rotors and service calipers . Replace brake pads .
Flush and bleed brake system . Road test.
- Rotate and balance all four tires . Nitrofill all.
- Readjust and tighten computer stand .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 7.30 Comm: 0.00 Labor: 489.10 Parts: 134.03 Total: 623.13

Work Order: 1908444 **Meter:** 35049 **In Date:** 08/13/2019 **Closed:** 08/13/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1911958 **Meter:** 39963 **In Date:** 11/19/2019 **Closed:** 11/27/2019
Problem: P.M. Service.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Replace two tires,rotate and balance all four.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Mac Battery Protect	1.00
Wd40 Spr	1.00
245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 518.06 Total: 810.06

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2001879 **Meter:** 44830 **In Date:** 02/25/2020 **Closed:** 03/05/2020
Problem: P.M. service , power outlets inop and spare key .

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.
- Test power outlets and replace burnt fuses . Retest .
- Program new spare key with scan tool .
- Perform complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Ford Triton Pvc Swc	1.00
Cabin Air Filter	1.00
245/70/17 Tire Mich	2.00
Mcase Ctg Fuse-20 Amp	2.00
ford side key	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 654.07

Total: 1,274.57

Work Order: 2005383 **Meter:** 51063 **In Date:** 05/29/2020 **Closed:** 06/11/2020
Problem: P.M. service and recalls 17S33 and 18S27 .

Work Completed

- P.m. service.
- Pressure test and inspect cooling system . Flush and refill .
- Resurface both front brake rotors and service calipers . Replace brake pads .
- Flush and bleed brake system . Road test .
- Balance and rotate all four tires . Nitrofill all .
- Transport to and from dealer for recall 17s33 and 18s27 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Anti Freeze Motorcraft	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 124.26

Total: 890.76

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2012952 **Meter:** 62842 **In Date:** 12/29/2020 **Closed:** 01/06/2021
Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Replaced cabin filter. Clean debris from fresh air intake.
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Filter	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50 Parts: 75.51 Total: 331.01

Work Order: 2104245 **Meter:** 68325 **In Date:** 04/15/2021 **Closed:** 04/27/2021
Problem: P.M. Service right side inverter smells burnt when on .

Work Completed

- Preventive Maint. Service
- Mount Two New Tires; Nitrogen Fill All, Rotate And Balance Four.
- Inspect Power Inverters And Verify Complaint. Found Inverters To Be Dirty And Sticky From Spilled Drink. R&r Two Faulty Inverters And Shorted 50 Amp Fuses.
- Removed Trans Pan And R&r Filter; Perform Automatic Transmission Fluid Exchange And Road Test.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
245/70/17 Tire Mich	2.00
400w Inverter Cobra	2.00
Tram Filter	1.00
oil auto	16.00
Max-50 Fuse	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.00

Comm: 0.00

Labor: 584.00 Parts: 905.80 Total: 1,489.80

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2105627 **Meter:** 69087 **In Date:** 05/20/2021 **Closed:** 05/20/2021

Problem: leak rear driver side tire

Work Completed

- Repair left rear tire, balance and nitro service
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00
-------------	------------	--------------	-------------	--------------

Work Order: 2106128 **Meter:** 69900 **In Date:** 06/04/2021 **Closed:** 06/07/2021

Problem: Please check GPS connections. GPS reported not working.

Work Completed

- Gps plug disconnected, reconnect.

Hours: 0.30	Comm: 0.00	Labor: 21.90	Parts: 0.00	Total: 21.90
-------------	------------	--------------	-------------	--------------

Work Order: 2109333 **Meter:** 74454 **In Date:** 08/27/2021 **Closed:** 09/08/2021

Problem: P.M. Service

Work Completed

- Performed P.m. Service & Inspection.
- Mount 2 Tire's Then Balance And Rotate All 4 Wheels, Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle.
- Performed Fuel Induction Service & Fuel Injecton Flush.
- Computer Diagnose Engine Misfire .performed Tune Up, Removed And Replaced All 6 Spark Plugs.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
245/70/17 Tire Mich	2.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Throttle Body Cleaner	1.00
Gasket	1.00
Gasket	1.00
Spark Plugs	6.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 12.20	Comm: 0.00	Labor: 890.60	Parts: 529.73	Total: 1,420.33
--------------	------------	---------------	---------------	-----------------

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2113546 **Meter:** 80166 **In Date:** 12/22/2021 **Closed:** 01/03/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance. nitro fill
- Perform Ids Sir diagnostic, scan air bag system, code #b1413 -93- 8b Impact sensor front left side, open circuit, Perform pin out and resistance testing, open circuit from right side lower dash to impact sensor, install circuit from Rig left side
- Shop Supplies

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Primary Wire	15.00
Primary Wire	15.00
Electrical Tape	1.00
Fab Loom-split Poly	15.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 53.34

Total: 637.34

Work Order: 2201372 **Meter:** 82039 **In Date:** 02/07/2022 **Closed:** 02/07/2022
Problem: screw in rear passenger tire

Work Completed

- Tire Repair
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Work Order: 2201491 **Meter:** 82359 **In Date:** 02/09/2022 **Closed:** 02/14/2022
Problem: check engine light

Work Completed

- Scan diagnose Cel, Code P1450, Smoke test evap system, no leaks found, Evap tests prove purge valve stuck open, replace purge valve retest. Pass
- Shop Supplies

Parts Issued

Quantity

Valva Asy	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 48.33

Total: 194.33

6/6/2022
9:23:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10199064 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2204890 **Meter:** 86057 **In Date:** 05/05/2022 **Closed:** 05/05/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 118.30

Total Labor: 8,047.60

Total Comm: 105.54

Total Parts: 5,171.33