Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 88.75	Labor: 6,048.00	Parts: 4,902.05	Comm: 5,999.51		Charged: 16949.56	
Work Order: 160868	30 Meter:	332	Ir	n Date:	08/22/2016 Closed:	08/22/2016

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1700408 Meter: 6611 In Date: 01/12/2017 Closed: 01/25/2017

Problem: P.M.SERVICE

Work Completed		Parts Issued		Quantity
- Pm Service		Napa Quart 5w20	Napa Quart 5w20	
- Rotate and balance tires.		Napagold Oil Filte	er	1.00
- Shop Supplies		Washer Fluid Con	Washer Fluid Concentr	
		Shop Supplies		1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 32.50	Total: 197.50

Work Order: 1702938 Meter: 9954 In Date: 03/22/2017 Closed: 03/31/2017

Problem: PM Service

Work Complete	d		Parts Issued	Quantity
- Pm service.			Napagold Oil Filter	1.00
- Replace left tai	l/brake lamp bulb.		Napa Quart 5w20	7.00
- Rotate and bala	ance all tires.		Washer Fluid Concentr	1.00
- Shop Supplies			Bulb	1.00
			Shop Supplies	1.00
	Hours: 3.00	Comm: 0.00	Labor: 180.00 Parts: 3	3.28 Total: 213.28

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

 Work Order:
 1706979
 Meter:
 15211
 In Date:
 07/17/2017
 Closed:
 07/27/2017

 Problem:
 PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Used Fire X Refurb	oished	1.00
- Rotate and balance 4 tires.		Napa Quart 5w20		7.00
- Service spare tire and nitro service.		Napagold Oil Filte	er	1.00
- R/r trailer plug,service and clean corroded w	rires and lube connector.	Napagold Air Filt	er	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Con	centr	1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 63.26	Total: 348.26

Work Order: 1710546 Meter: 17812 In Date: 10/25/2017 Closed: 10/30/2017

Problem: Left rear tire flat

Work Completed
Parts Issued
Quantity
Shop Supplies
1.00
Shop Supplies
Hours: 1.00
Comm: 0.00
Labor: 60.00
Parts: 2.00
Total: 62.00

Work Order: 1800911 Meter: 19444 In Date: 01/25/2018 Closed: 01/31/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filte	er	1.00
- Replace four tires.		Napa Quart 5w20		7.00
- Shop Supplies		Washer Fluid Con	centr	1.00
		Wd40 Spr		1.00
		22" Wiper Blade		2.00
		183114470 P245-	70r17	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 876.69	Total: 1,116.69

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1805202 Meter: 21815 In Date: 05/21/2018 Closed: 05/30/2018

Problem: Left rear tire flat.

Work CompletedParts IssuedQuantity- Patch and balance left rear tire .reset air pressure and tire lamp off.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1807160 Meter: 24758 In Date: 07/13/2018 Closed: 07/23/2018

Problem: PM Service.

Work Completed		Parts Issued	Quantity
- Pm Service.		Napa Quart 5w20	7.00
- Rotate and balance tires.		Napagold Oil Filter	1.00
- Shop Supplies		Used Fire X Refurbished	1.00
		22" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Napagold Air Filter	1.00
		Shop Supplies	1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00 Parts: 65	.21 Total: 230.21

Work Order: 1807389 Meter: 24758 In Date: 07/18/2018 Closed: 07/19/2018

Problem: accident/undrivable

Work Completed

- Tow From: Ne corner Lyons/clintmore To: vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1808261 Meter: 24758 In Date: 07/19/2018 Closed: 08/13/2018

Problem: Damage to right front fender, hood, front bumper, grille & possible steering

Work Completed

- Damage to right front fender, hood, front bumper, grille & possible steering

Hours: 0.00 Comm: 4,585.91 Labor: 0.00 Parts: 0.00 Total: 4,585.91

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1811327 Meter: 29725 In Date: 11/01/2018 Closed: 11/19/2018

Problem: PM Service.Check engine light on.

Work Completed	Parts Issued	Quantity
- Pm Service.	Napa Quart 5w20	7.00
- Check engine light is on.scan and found code P1450.send to dealer for	Napagold Oil Filter	1.00
warranty.	Washer Fluid Concentr	1.00
- Jump start vehicle, check charging system and found bad battery. send to dealer to replace battery under warranty.	Shop Supplies	1.00

- Transport vehicle to and from dealer for replacing battery and safety recall #17s33f Door lock shield.

- Shop Supplies

Hours: 5.50 Comm: 0.00 Labor: 368.50 Parts: 37.05 Total: 405.55

Work Order: 1812953 Meter: 31281 In Date: 12/20/2018 Closed: 12/26/2018

Problem: Rear tire flat.

Work Completed		Parts Issued		Quantity
- Repair and balance left rear tire.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 3.00	Total: 70.00

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1903128 Meter: 36192 In Date: 03/21/2019 Closed: 03/29/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filter		1.00
- Resurface front rotors.replace front brake pads.service caliper	rs.remove	Napa Quart 5w20		7.00
drive shaft to resurface rear rotors.replace rear brake pads.service	ce calipers.	22" Wiper Blade		2.00
- Replace four tires.		Washer Fluid Conc	entr	1.00
- Shop Supplies		Napagold Air Filte	r	1.00
		Ceramic Brake Lub	e	1.00
		Non-chlor Brake C	Inr	1.00
		Brake Pad		1.00
		Brake Pad Set		1.00
		245/70/17 Tire Mic	h	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 14.00 Comr	m: 0.00	Labor: 938.00	Parts: 1,216.49	Total: 2,154.49

Work Order: 1907042 Meter: 41496 In Date: 07/08/2019 Closed: 07/22/2019

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Used Fire X Refurb	ished	1.00
- Install steering wheel cover and custom fit floor mats.		Napagold Oil Filter	ſ	1.00
- Adjust tool box lid to open and close properly.		Napa Quart 5w20		6.00
- Balance and rotate 4 tires.		Washer Fluid Conc	entr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		2pc Hd Mat Set Bl	<	1.00
		Ford Triton Pvc Sw	С	1.00
		Shop Supplies		1.00
Hours: 4.25	Comm: 0.00	Labor: 284.75	Parts: 109.94	Total: 394.69

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1909198 Meter: 42781 In Date: 09/06/2019 Closed: 09/16/2019

Problem: Right side mirror broken.

Work CompletedParts IssuedQuantity- Replace right side mirror assembly.(broken)Mirror Assey1.00- Shop SuppliesShop Supplies1.00Hours: 1.00Comm: 0.00Labor: 67.00Parts: 181.13Total: 248.13

Work Order: 1912001 Meter: 42847 In Date: 11/20/2019 Closed: 11/25/2019

Problem: Dead battery at meter shop parking lot.

Work CompletedParts IssuedQuantity- Jump start vehicle in Wud parking lot.fully recharge and test battery andShop Supplies1.00

charging system.all tested ok.

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 1912888 Meter: 42883 In Date: 12/17/2019 Closed: 12/31/2019

Problem: PM Service.Check tires.

Work Completed		Parts Issued	Quantity
- Pm Service.		Napagold Oil Filter	1.00
- Balance and rotate four tires.		Napa Quart 5w20	7.00
- Repaired right front tire.		Washer Fluid Concentr	1.00
- Clean engine compartment.		22" Wiper Blade	2.00
- Service tool box and adjust latches.		Napagold Air Filter	1.00
- Shop Supplies		Shop Supplies	1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50 Parts: 56.77	Total: 458.27

Work Order: 2004390 Meter: 44790 In Date: 03/31/2020 Closed: 05/01/2020

Problem: damage to rear bumper & tail gate

Work Completed

- damage to rear bumper & tail gate

Hours: 0.00 Comm: 1,317.60 Labor: 0.00 Parts: 0.00 Total: 1,317.60

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2005959 Meter: 46774 In Date: 06/16/2020 Closed: 06/23/2020

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napa Quart 5w20		6.00
- Replace cabin air filter.		Napagold Oil Filte	er	1.00
- R/r bumper trim to prep and paint front bumper.		Washer Fluid Con	centr	1.00
- Rotate and balance 4 tires.		22" Wiper Blade		2.00
- Repaired right rear tire.		Cabin Air Filter		1.00
- Service tool box.lube and adjust latches.		Red Oxide Primer		1.00
- Relocate fire extinguisher and adjust computer star	nd.	Gl. Blac		1.00
- Wash engine compartment.		Shop Supplies		1.00
- Shop Supplies				
Hours: 9.25	Comm: 0.00	Labor: 675.25	Parts: 69.54	Total: 744.79

Work Order: 2012751 Meter: 52149 In Date: 12/21/2020 Closed: 01/07/2021

Problem: PM Service and TPMS light.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w20		7.00
- R & R cabin air filter.		Napagold Oil Filte	r	1.00
- replace 2 tires. rotate and balance all 4		Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	oished	1.00
		Cabin Filter		1.00
		245/70/17 Tire Mi	ch	2.00
		Shop Supplies Tire Disposal Fee		1.00
				2.00
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 806.06	Total: 1,134.5

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2102300 Meter: 52310 In Date: 03/01/2021 Closed: 03/03/2021

Problem: Bad battery and left rear tire flat.

Work Completed		Parts Issued		Quantity
- Test starting and charging system.battery failed loadtest.replace bad		Battery		1.00
battery.		Battery		1.00
- Repair and balance left rear tire.		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 292.66	Total: 438.66

Work Order: 2102709 Meter: 52420 In Date: 03/10/2021 Closed: 03/12/2021

Problem: TPMS light on.Washer inop.Binding drive shaft.Noise after stop.

Work Completed		Parts Issued		Quantity
- R&r Washer Fluid Pump To Clean Clogged Screen And Flush L		Tire Pressure Monitoring System Sensor (1.00
Work Properly	ork Properly		Tpms Sens Kit	
- R&r Noisy Drive Shaft To Lube Slip Joint		Shop Supplies		1.00
- Road Test To Verify Repairs				
- Patched Repaired Left Rear Tire And Replaced I reset Tpms System	Damaged Tpms Sensor			
- Shop Supplies				
Hours: 4.25	Comm: 0.00	Labor: 310.25	Parts: 83.50	Total: 393.75

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2107842 Meter: 53721 In Date: 07/19/2021 Closed: 07/28/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
 - Preventive Maint. Service - Service rear calipers, replace rotors & rear brake pads. - Remove left front seat & replace seat cushion. - Clean A/c air intake & replace cabin air filter. 		Napagold Oil Filter		1.00
		Napa Quart 5w20 Napagold Air Filter Washer Fluid Concentr		7.00
				1.00
		Brake Rotor-dih Parki Brake Pad Cabin Air Filter		2.00
				1.00
				1.00
		Pad Seat Brake Rotor		1.00
				2.00
		Shop Supplies		1.00
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 501.39	Total: 1,048.89

Work Order: 2201719 Meter: 58640 In Date: 02/15/2022 Closed: 02/18/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service			Napagold Oil Filter	
- mount 2 tires rotate balanced 4 tires			Napa Quart 5w20	
- Shop Supplies		Washer Fluid Con	centr	1.00
		22" Wiper Blade		2.00
		Used Fire X Refurb	oished	1.00
		245/70/17 Tire Mich		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 461.84	Total: 808.59

Palm Beach County Fleet Management Asset Maintenance History 10202143 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2204270 Meter: 60550 In Date: 04/22/2022 Closed: 04/26/2022

Problem: driver side tail light out

 Work Completed
 Parts Issued
 Quantity

 - Lighting, Other replaced both brake lamp bulbs
 Boxed Miniatures
 2.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 1.00
 Comm: 0.00
 Labor: 73.00
 Parts: 3.77
 Total: 76.77

Work Order: 2205604 Meter: 62084 In Date: 05/26/2022 Closed: 05/26/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 88.75 Total Labor: 6,048.00 Total Comm: 5,999.51 Total Parts: 4,902.05