## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Total Hours: 216.60 Labor: 14,114.05 Parts: 14,107.29 Comm: 1,140.00 Charged: 29361.34

Work Order: 1303454 Meter: 326 In Date: 04/09/2013 Closed: 04/09/2013

Problem: 1061 - Pre Delivery Inspection

**Work Completed** 

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1305807 Meter: 2556 In Date: 06/11/2013 Closed: 06/24/2013

Problem: Right front wheel bearing dust cap lost.

Work CompletedParts IssuedQuantity- Inspect and replace missing right front wheel bearing dust cap with<br/>new.clean and repack same wheel bearing.install new floor mats to protect<br/>carpet.Cap1.00- Shop SuppliesFloor Mat-2pc Rub Bk1.00Shop Supplies1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 42.31 Total: 72.31

Work Order: 1311242 Meter: 8023 In Date: 11/05/2013 Closed: 11/19/2013

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace two tires,rotate and balance	all six.	Napagold Oil Filte	er	1.00
- Replace missing pintle pin.		Washer Fl		1.00
- Complete wheel alignment.		179636492 Lt245-	-75r17	2.00
- Shop Supplies		Tr416 Valve Stem		2.00
		Used Fire X Refurb	oished	1.00
		Pintle Pin W/chair	ı	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 9.25	Comm: 0.00	Labor: 555.00	Parts: 541.23	Total: 1,096.23

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1400855 Meter: 10737 In Date: 01/27/2014 Closed: 01/31/2014

**Problem:** Install customer supplied computer stand.

Work CompletedParts IssuedQuantity- Assemble and install costomer supplied computer stand.Shop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1401938 Meter: 11857 In Date: 02/27/2014 Closed: 03/11/2014

**Problem:** Right rear tire going flat and pulls to the right.

Hours: 7.50

Work Completed Parts Issued Quantity

- Repair and balance right rear outter tire.

Shop Supplies 1.00

- Complete wheel alignment.test drive.

- Shop Supplies

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 2.00 Total: 212.00

Labor: 450.00

Parts: 539.55

Total: 989.55

Work Order: 1405806 Meter: 15921 In Date: 06/12/2014 Closed: 06/30/2014

Problem: P.M. Service.

Work Completed	Parts Issued	Quantity
- Perform pm service.	5w20 Engine Oil	7.00
- Fabricate and replace broken hitch pindle pin with new.	Napagold Oil Filter	1.00
- Repair flat right front tire.install two new tires.nitrogen fill and balance all	Napagold Air Filter	1.00
six.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Pintle Pin W/chain	1.00
	179636492 Lt245-75r17	2.00
	Tr416 Valve Stem	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Comm: 0.00

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1406397 Meter: 16153 In Date: 06/30/2014 Closed: 07/08/2014

Problem: Dead battery

Work Completed	Parts Issued	Quantity
- Test starting and charging system.battery failed loadtest after	Battery 65	1.00
recharge.replace failed battery with new.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 146.92 Total: 206.92

Work Order: 1412879 Meter: 21592 In Date: 12/30/2014 Closed: 01/29/2015

**Problem:** Pm service. Check back up alarm.need, copies of keys for spare.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace four tires,roate and balance all six.		Napagold Oil Filte	r	1.00
- Check back-up malarm.repair wiring.		Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	pished	1.00
		179636492 Lt245-	75r17	4.00
		Stg Wheel Cov - F	ord	1.00
		J211 Key		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 7.50	Comm: 0.00	Labor: 450.00	Parts: 1,137.07	Total: 1,587.0

### Palm Beach County Fleet Management Asset Maintenance History 0189844 2013 FORD F350 Utility Body, 1 Ton, Gas 10189844

Work Order: 1504488	Meter: 26477		In Date:	05/01/2015 <b>Closed:</b>	05/07/2015
<b>Problem:</b> Pm service.Check wiring for light bar	r and toggle switch.				
Work Completed		Parts Issued		Q	uantity
- P.m. Service.		5w20 Engine Oil			7.00
- Resurface front brake rotors, replace front brak	e pads.service and lube	Napagold Oil Filter			1.00
calipers.flush and bleed system.		Wiper Blade			2.00
- Replace two tires, rotate and balance all six.		Napagold Air Filter	•		1.00
- Complete wheel alignment.test drive.		Brake Pads			1.00
- Check and repair wiring to light bar.		kit brake			1.00
- Shop Supplies		179636492 Lt245-7	5r17		2.00
		Shop Supplies			1.00
		Tire Disposal Fee			2.00
Hours: 14.50	Comm: 0.00	Labor: 870.00	Parts: 750	).14 Total	1,620.14
Work Order: 1506130	Meter: 28417		In Date:	06/18/2015 <b>Closed:</b>	06/23/2015

Problem: Won't start.

Work Completed		Parts Issued		Quantity
- Battery failed load test. Replace battery.		Battery 65		1.00
- Test drive.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 148.34	Total: 238.34

# Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1512584 Meter: 32696 In Date: 12/14/2015 Closed: 12/31/2015

Problem: Pm service.Check brakes.

Work Completed		Parts Issued		Qua	antity
- Pm service.		5w20 Engine Oil			7.00
- Replace missing hitch pintle pin.		Napagold Oil Filter			1.00
- Resurface both rear brake rotors.lube caliper slides and re	eplace rear brake	Napagold Air Filte	r		1.00
pads.bleed brake system and road test.		Used Fire X Refurb	ished		1.00
- Rotate and balance all six tires.		22" Wiper Blade			2.00
- Shop Supplies		Pintle Pin W/chain			1.00
		Brake Pad			1.00
		B Fluid Dot 3-32oz			1.00
		Brake Cleaner			1.00
		Real Brake Pad			1.00
		Shop Supplies			1.00
Hours: 11.00 C	Comm: 0.00	Labor: 660.00	Parts: 228.46	Total:	888.46

# Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1605705 Meter: 36795 In Date: 06/02/2016 Closed: 06/20/2016

**Problem:** P.M. service and A/C inop blows warm.

Work Completed	Parts Issued	Quantity
- P.m. Service.	Napagold Oil Filter	1.00
- Check a/c system.r&r dashboard and replace leaking	5w20 Engine Oil	7.00
evaporator,accumulator and orifice tube.flush system,vacuum and recaharge	Washer Fluid Concentr	1.00
to specs.	22" Wiper Blade	2.00
- Inspect and service rear differential.	Used Fire X Refurbished	1.00
- Rotate and balance all tires.	Evaporator Core	1.00
- Shop Supplies	Accumulator	1.00
	E8 A/c Oil Univ W Dye	1.00
	Kit O	1.00
	Seal Kits	2.00
	Friction Modifier	2.00
	75w140 Ford Axle Lube	3.00
	R134a Lv Shop 2	2.00
	Shop Supplies	1.00
Hours: 18.50 Comm: 0.00	Labor: 1,110.00 Parts: 560.54	Total: 1,670.54

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1612491 Meter: 41574 In Date: 12/06/2016 Closed: 12/27/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace and balance six new tires.		Napagold Oil Filter	r	1.00
- Flush and refill transmission system.		22" Wiper Blade		2.00
- Complete wheel alignment.test drive.		Napagold Air Filte	er	1.00
- Shop Supplies		Used Fire X Refurb	ished	1.00
		Stg Wheel Cov - Fo	ord	1.00
		Wd40 Spr		1.00
		179636492 Lt245-7	75r17	6.00
		Tr416 Valve Stem		6.00
		Syn-atf Trans Fluid	S	11.00
		Shop Supplies		1.00
		Tire Disposal Fee		6.00
Hours: 11.00	Comm: 0.00	Labor: 660.00	Parts: 1,644.88	Total: 2,304.88

Work Order: 1703805 Meter: 43875 In Date: 04/14/2017 Closed: 04/27/2017

**Problem:** Left front tire going flat and light bar inop.

Work Comple	eted		Parts Issued		Quantity
- Diagnose in	nop lightbar.r&r left kick panel ar	nd repair damaged power wire.	Shop Supplies		1.00
- Repair and	balance left front tire.				
- Shop Suppl	ies				
	Hours: 2.50	Comm: 0.00	Labor: 150.00	Parts: 2.00	Total: 152.00

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1706219 Meter: 45335 In Date: 06/23/2017 Closed: 06/30/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Test battery and charging system.replace bad b	pattery	Napagold Oil Filte	r	1.00
- Replace pintle pin.	•	22" Wiper Blade		2.00
- Rotate and balance tires.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Battery 65		1.00
		Pintle Pin W/clip		1.00
		Shop Supplies		1.00
Hours: 6.25	Comm: 0.00	Labor: 375.00	Parts: 200.20	Total: 575.20

Work Order: 1707351 Meter: 45335 In Date: 06/30/2017 Closed: 07/27/2017

**Problem:** damage to rgt side rear of body

#### **Work Completed**

- damage to rgt side rear of body

Hours: 0.00 Comm: 948.00 Labor: 0.00 Parts: 0.00 Total: 948.00

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1712592 Meter: 49460 In Date: 12/20/2017 Closed: 12/28/2017

**Problem:** PM Service, Check brakes - sqeak at low speed, Replace broken vise.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Replace three faulty dome lamp bulbs with new.		Napagold Oil Filter		1.00
- Replace broken vise with new .had to drill holes to	mount base to fit.	Used Fire X Refurbished		1.00
- Resurface both front rotors on truck .replace failed	front calipers stuck and	Washer Fluid Concen	tr	1.00
brake pads with new .flush and bleed brake system a	nd road test.	Ford Triton Pvc Swc		1.00
- Rotate and balance six tires.		22" Wiper Blade		2.00
- Shop Supplies		Bulb		3.00
		Hd Workshop Vise		1.00
		Brake Pads		1.00
		Reman/ca Reman/ca		1.00
				1.00
		B Fluid Dot 3-32oz		1.00
		lube		1.00
		Non-chlor Brake Clnr		1.00
		Brake Pad Motorcraft		1.00
		Vise		1.00
		Shop Supplies		1.00
Hours: 12.00	Comm: 0.00	Labor: 720.00	Parts: 804.43	Total: 1,524.4

Work Order: 1807236 Meter: 52941 In Date: 07/17/2018 Closed: 07/23/2018

**Problem:** TIRE REPAIR

Work Completed		Parts Issued		Quantity
- Repair and balance right rear inner tire.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00

# Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1807568 Meter: 53135 In Date: 07/25/2018 Closed: 08/20/2018

Problem: P.M.SERVICE, BAD BATTERY

Hours: 13.75

Work Completed	Parts Issued	Quantity
- Pm Service.	Napagold Air Filter	1.00
- Recharge and test battery(failed)jump start in Wud parking lot.replace	Napagold Oil Filter	1.00
motorcraft battery under warranty.	Napa Quart 5w20	7.00
- Mount and balance six tires	Washer Fluid Concentr	1.00
- Replace both led brake lamps and drill out rivets to replace 3 lamp light	22" Wiper Blade	2.00
par at rear bumper	179636492 Lt245-75r17	6.00
- Replace 6 way connector and harness and secure wiring.	Led Id Bar 6 Ctrs	1.00
- Dissamble vise to clean rust and lube moving parts to work properly.	Dielect Silicone Comp	1.00
- Adjust tail gate to open and close properly	Vinyl Electrical Tape	1.00
- Shop Supplies	Terminal 12-10 Stud	10.00
	trailer plug	1.00
	Battery 65	1.00
	Led S T T 12v Grom	2.00
	Wire Term 16-14 Bllt	10.00
	Shop Supplies	1.00

Comm: 0.00

Tire Disposal Fee

Parts: 1,664.66

Labor: 825.00

6.00

Total: 2,489.66

- Tow From: 8100 Forest Hill Blvd To: Lv shop

Hours: 0.00

### Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1903293 Problem: PM Service.	Meter:	57890		In Date:	03/26/2019	Closed:	04/15/2019
Work Completed			Parts Issued			Qı	uantity
- Pm Service.			Napagold Air Filter				1.00
- Rotate and balance 6 tires.			Napa Quart 5w20				7.00
- Clean debris from radiator core to cool prope	rly.		Napagold Oil Filter				1.00
- Shop Supplies			22" Wiper Blade				2.00
			Washer Fluid Concen	ntr			1.00
			Used Fire X Refurbish	ned			1.00
			Ford Triton Pvc Swc				1.00
			Shop Supplies				1.00
Hours: 6.25		Comm: 0.00	Labor: 418.75	Parts: 85.	73	Total:	504.48
Work Order: 1906203  Problem: Towed in for no start.	Meter:	59813		In Date:	06/12/2019	Closed:	06/13/2019
Work Completed			Parts Issued			Qı	uantity
- Charge battery fully . Test battery and charging	ng system	. R&r battery for	Battery				1.00
bad cell with new.	,	Ţ	Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 14	1.90	Total:	208.90
Work Order: 1906208  Problem: No start	Meter:	59736		In Date:	06/12/2019	Closed:	06/12/2019

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

### Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1910041 Meter: 63726 In Date: 09/30/2019 Closed: 10/24/2019

**Problem:** P.M. service and right front door ajar stays on .

### **Work Completed**

- P.m. service.
- Resurface both rear rotors . Replace calipers ,brake hoses and pads .flush and bleed brake system . Road test .
- Computer diagnose air bag light ,code B0021 . Perform pinpoint test . Replace bosy harness , remove all seats and floor mat and dash to replace body harness . Remove right front door panel to replace ajsr switch . Clear codes and retest .
- Computer diagnose misfire , code P0308 . Perform tune up . Replace all sixteen spark plugs and wires . Clear code and road test .
- Perform complete air intake decarb and cleaning . Flush injectors .
- R&i left front seat to be repaired .replace center A/c register .
- Rotate and high speed balance all six tires . Nitrofill all.
- Remove vise to free up and replace missing C clip .
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Pedal Pad	1.00
B Fluid Dot 3-32oz	1.00
Brake Hose	1.00
Brake Hose	1.00
Real Brake Pad	1.00
Switch	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Caliper Washer	4.00
Brake Caliper	1.00
Brake Caliper	1.00
Throttle Body Cleaner	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Seat R And R	1.00
A/c Vent	1.00
Wiring Asy	1.00
Shop Supplies	1.00
Labor: 2,065.90 Parts: 1,450.57	Total: 3,516.47

Hours: 28.30 Comm: 0.00

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1911040 Meter: 63726 In Date: 10/25/2019 Closed: 10/29/2019

**Problem:** Replace broken cup holder.

### **Work Completed**

- Repair cup holder.

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50

Work Order: 2003171 Meter: 68828 In Date: 03/30/2020 Closed: 04/06/2020

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	7.00
- Test washers . Replace both washer jets and clear and clear hoses of	of Napagold Oil Filter	1.00
plastic . Fill washer tank and retest .	22" Wiper Blade	2.00
- Test and replace corroded trailer plug connector and rewire as nee	ded. Napagold Air Filter	1.00
- Replace two tires . Roptate and balance all six tires . Nitrofill all.	Ford Triton Pvc Swc	1.00
- Perform complete front end alignment and road test .	Washer Nozzle	2.00
- Shop Supplies	trailer plug	1.00
	Lt245/75r17 Mich Defend Ltx	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 10.80 Comm: 0.0	00 Labor: 788.40 Parts: 596.59	Total: 1,384.99

Work Order: 2008251 Meter: 71535 In Date: 08/18/2020 Closed: 08/20/2020

Problem: Had to jump start.

Work Completed	Parts Issued		Quantity
- Charge battery fully . Test battery and charging system . Battery failed l	oad Battery		1.00
test . R&r defective battery .	<b>Shop Supplies</b>		1.00
- Shop Supplies			
Hours: 1.00 Comm: 0.00	Labor: 73.00	Parts: 147.81	Total: 220.81

### Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 2010876 Meter: 72978 In Date: 10/29/2020 Closed: 11/05/2020
Problem: PM Service

Work Completed Parts Issued Orain Plug

Drain Plug

1.00

- check verify needs front brakes,replaced front brakes pads ,rotors due to rotors below spec after resurfaced,service calipers ,service @ pack front hub brearing then road test

- check,replaced 4 tires balance and rotate all 6 . Nitrofill all.

- check ,replaced all 6 defective body mounts

- Shop Supplies

Parts Issued		Quantity
Drain Plug		1.00
Napagold Oil Fi	lter	1.00
5w20 Engine Oi		7.00
Used Fire X Refu	urbished	1.00
22" Wiper Blade	2	2.00
Brk Fluid Dot 4-	32oz	1.00
Brake Rotor		2.00
Front Brake Pac	b	1.00
Lt245/75r17 Mid	ch Defend Ltx	4.00
Body Mount Kit		4.00
Body Mount Kit		2.00
Wheel Seal - Fro	ont Wheel	2.00
Shop Supplies		1.00
Tire Disposal Fe	e	4.00
Labor: 1,314.00	Parts: 2,532.14	Total: 3,846.14

Work Order: 2101416 Meter: 73455 In Date: 02/08/2021 Closed: 02/09/2021

Comm: 0.00

**Problem:** Towed in right front tire flat .

Hours: 18.00

Parts Issued	Quantity
all. Lt245/75r17 Mich Defend Ltx	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Labor: 36.50 Parts: 305.64	Total: 342.14
	II all. Lt245/75r17 Mich Defend Ltx Shop Supplies Tire Disposal Fee

Work Order: 2101553 Meter: 73544 In Date: 02/05/2021 Closed: 02/10/2021

Problem: FLAT TIRE TOWED TO FLEET

#### **Work Completed**

- Tow From: 4654 Summit Blvd To:

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 2104918 Meter: 75496 In Date: 05/03/2021 Closed: 05/10/2021

**Problem:** P.M. service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		22" Wiper Blade		2.00
- Balance and Rotate All Six Tires With Nitro Fill		Napagold Oil Filte	r	1.00
- Shop Supplies		5w20 Engine Oil		7.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 36.93	Total: 438.43

Work Order: 2109076 Meter: 77342 In Date: 08/23/2021 Closed: 08/30/2021

**Problem:** PM Service. Battery going dead and left front going flat .

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection		5w20 Engine Oil		8.00
- Performed Flat Repair On R/r Tire, Then Balance And F	Rotate All 6 Tires.	Napagold Oil Filte	r	1.00
- Load Test Battery, Test Recommend Charge, Charged	e, Charged Battery And Retest, Washer Fluid Concentr		entr	1.00
Battery Failed Recommend To Replace, Removed & Rep	placed Then Reset To	22" Wiper Blade		2.00
Basic Settings.		Used Fire X Refurb	ished	1.00
·	tack Up Alarm Inop, Check Power & Ground. Power & Ground Ok. Alarm		Napagold Air Filter	
Defective, Removed & Replaced Then Check. Working A	9	Steering Wheel Co	ver Large	1.00
- Storage Bin Shock Strut Damaged, Removed & Replace Strut For Driver Front Storage Bin And Leaking Strut For	•	Battery		1.00
- Shop Supplies	J	Alarm		1.00
		Support		2.00
		Shop Supplies		1.00
Hours: 9.00	Comm: 0.00	Labor: 657.00	Parts: 242.47	Total: 899.47

## Palm Beach County Fleet Management Asset Maintenance History 10189844 2013 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 2202203 Meter: 81477 In Date: 02/25/2022 Closed: 03/24/2022

Problem: PM Service. New truck ordered

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	r	1.00
- Rotate and speed balance all six, nitro	o fill	5w20 Engine Oil		8.00
- Check and replace both Red stop ligh	nt, Repair & replace both wiring	Washer Fluid Con-	centr	1.00
connector		22" Wiper Blade		2.00
- Shop Supplies		Led Adapter Plug		2.00
		Led Sup Mdl 44 47	2 Dio	2.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 150.84	Total: 625.34

Work Order: 2206196 Meter: 84001 In Date: 06/13/2022 Closed: 06/13/2022

Problem: Transition Prep Charge

#### **Work Completed**

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 216.60 Total Labor: 14,114.05 Total Comm: 1,140.00 Total Parts: 14,107.29