Hours: 0.00

Comm: 19.46

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Total Hours: 122.70 Labor: 7,925.00	Parts: 5,379.94	Comm: 4,308.05	Charged: 17612.99			
Work Order: 1306849 Meter: Problem: 1061 - Pre Delivery Inspection	7		In Date:	07/10/2013	Closed:	07/10/2013
Work Completed						
- Pre Delivery Inspection						
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1306967 Meter: Problem: window tint	293		In Date:	07/12/2013	Closed:	07/24/2013
Work Completed		Parts Issued			Qı	ıantity
- Commercial Window Tint		Shop Supplies				1.00
- Travel Time To Drop Off And Pick Up At \	/endor					
- Shop Supplies						
Hours: 2.00	Comm: 144.00	Labor: 120.00	Parts: 2.0	0	Total:	266.00
Work Order: 1306986 Meter: Problem: 1 - Wash ticket(s) issued	8		In Date:	07/12/2013	Closed:	07/12/2013
Work Completed						
- 1 - Wash ticket(s) issued						
Hours: 0.00	Comm: 9.73	Labor: 0.00	Parts: 0.0	0	Total:	9.73
Work Order: 1307823 Meter: Problem: 2 - Wash ticket(s) issued	293		In Date:	08/06/2013	Closed:	08/06/2013
Work Completed						
- 2 - Wash ticket(s) issued						

Labor: 0.00

Parts: 0.00

Total: 19.46

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1400492 Meter: 5205 In Date: 01/15/2014 Closed: 01/24/2014 Problem: Pm service and request for detail vehicle.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Rotate and balance all tires.		Napagold Oil Filter		1.00
- Shop Supplies		Washer Fl		1.00
		Bigg Degreaser		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 30.56	Total: 210.56

Work Order: 1400569 Meter: 4719 In Date: 01/16/2014 Closed: 01/16/2014

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 97.92 Labor: 0.00 Parts: 0.00 Total: 97.92

Work Order: 1405414 Meter: 11845 In Date: 06/03/2014 Closed: 06/11/2014

Problem: P.M. Service.Detail

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil	6.00	
- Rotate and balance all tires.		Napagold Oil Filter	r	1.00
- Shop Supplies		Accufit Beam		1.00
		Accufit Beam		1.00
		Blade		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 66.25	Total: 246.25

Work Order: 1405512 Meter: 11368 In Date: 06/04/2014 Closed: 06/04/2014

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 97.92 Labor: 0.00 Parts: 0.00 Total: 97.92

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1407949 Meter: 12806 In Date: 08/12/2014 **Closed:** 08/12/2014

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

In Date:

Work Order: 1412495 Meter: 18328 In Date: 12/15/2014 Closed: 12/29/2014

Problem: Pm service.

Work Completed Parts Issued Quantity Napagold Oil Filter 1.00 - Pm service. 5w20 Engine Oil 6.00 - Rotate and balance all four tires. **Shop Supplies** 1.00 - Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 21.19 Total: 201.19

Work Order: 1502057 Meter: 18328 **In Date:** 02/26/2015 **Closed:** 02/26/2015

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70 Work Order: 1502148 Meter: 20917 02/27/2015 **Closed**: 02/28/2015

Problem: Wiper blades not clearing windsheild.

Work Completed Quantity **Parts Issued** Accufit Beam 1.00 - Inspect and replace both front wiper blades. Accufit Beam 1.00 Hours: 0.30 Comm: 0.00 Labor: 18.00 Parts: 26.40 Total: 44.40

Hours: 6.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: Problem:	1504455 Pm service.	Meter:	25000		In Date:	04/30/2015	Closed:	05/07/2015
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm servic	ce.			5w20 Engine Oil				6.00
- Rotate ar	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	oplies			Wd40 16oz				1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 29.	92	Total:	209.92
Vork Order: Problem:	1508284 Left rear tire flat.	Meter:	28940		In Date:	08/18/2015	Closed:	08/19/2015
Work Com	pleted			Parts Issued			Qı	ıantity
- Repair ar	nd balance left rear tire.			Shop Supplies				1.00
- Shop Sup								
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Vork Order: Problem:	1508435 1 - Wash ticket(s) issued	Meter:	28940		In Date:	08/21/2015	Closed:	08/21/2015
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Vork Order: Problem:	1511315 Pm service.	Meter:	31673		In Date:	11/04/2015	Closed:	11/16/2015
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm servic	ce.			5w20 Engine Oil				6.00
- Battery fa	ailed load test after recharge.alto	ernator output	at specs.no	Napagold Oil Filter				1.00
•	ce defective battery.	·	·	Accufit Beam				1.00
- Rotate ar	nd balance all four tires.			Accufit Beam				1.00
- Transpor	t vehicle to and from dealer for	oil leak.,rear m	ain seal.	Blade				1.00
- Shop Sup	oplies			Group 59 Battery Mc				1.00
				Shop Supplies				1.00

Comm: 0.00

Labor: 360.00

Parts: 219.46

Total: 579.46

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1601778 Meter: 36142 In Date: 02/19/2016 Closed: 02/24/2016

Problem: Battery for key fob.

Work CompletedParts IssuedQuantity- Test and replace key fob battery.Enr Elect Battery1.00Napagold Air Filter1.00Hours: 0.25Comm: 0.00Labor: 15.00Parts: 10.07Total: 25.07

Work Order: 1601779 Meter: 31673 In Date: 02/19/2016 Closed: 02/26/2016

Problem: needs spare key

Work CompletedParts IssuedQuantity- Make and program 1 keyFord Ignition Key Blank1.00- Shop SuppliesShop Supplies1.00Hours: 1.00Comm: 0.00Labor: 60.00Parts: 28.61Total: 88.61

Work Order: 1601823 Meter: 36142 In Date: 02/22/2016 Closed: 02/22/2016

Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 95.40 Labor: 0.00 Parts: 0.00 Total: 95.40

rder: 1604593 Meter: 39018 In Date: 05/02/2016 Closed: 05/05/2016

Work Order: 1604593 Meter: 39018

Problem: P.M. service.

Hours: 6.50

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	6.00
- Replace and balance all four tires.	Napagold Oil Filter	1.00
- Complete wheel alignment.test drive.	Accufit Beam	1.00
- Shop Supplies	Accufit Beam	1.00
	Blade	1.00
	Washer Fluid Concentr	1.00
	245/60/18 Tire Gdy	4.00
	Shop Supplies	1.00

Comm: 0.00

Tire Disposal Fee

Parts: 977.67

Labor: 390.00

4.00

Total: 1,367.67

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1610230 Meter: 45319 In Date: 09/29/2016 Closed: 10/18/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Fflush and refill transmission system.		Napagold Oil Filte	r	1.00
- Rotate and balance tires.		Accufit Beam		1.00
- Shop Supplies		Accufit Beam		1.00
		Wpr/blde		1.00
		Washer Fluid Cond	centr	1.00
		Syn-atf Trans Fluid	I S	13.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 114.34	Total: 384.34

Work Order: 1701924 Meter: 51803 In Date: 02/24/2017 Closed: 03/15/2017

Problem: P.M. service and Towed in for no start.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Scan system for no start concern.c1137.replace shiter a	ssemble per	5w20 Engine Oil		6.00
Tsb.clear code.		Washer Fluid Cond	centr	1.00
- Rotate and balance tires.		Accufit Beam		1.00
- Shop Supplies		Accufit Beam		1.00
		Wpr/blde		1.00
		Shift Lever Assy		1.00
		Enr Elect Battery		1.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 330.00	Parts: 247.36	Total: 577.36

Work Order: 1701949 Meter: 45319 In Date: 02/23/2017 Closed: 02/27/2017

Problem: No start

Work Completed

- Tow From: Belvedere and Lake (marathon Gas Stn) To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: Problem:	1702813 Tow on,right tire flat.	Meter:	53574		In Date:	03/21/2017	Closed:	03/29/2017
Work Com	pleted			Parts Issued			Qι	antity
- Replace a	and balance right front tire.			245/60/18 Tire Gdy				1.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 228	3.49	Total:	258.49
Work Order: Problem:		Meter:	51803		In Date:	03/20/2017	Closed:	03/21/2017
Work Com	pleted							
- Tire Servi	ce 10651 Southern Blvd, Royal Palm E	Beach - F	lat tire					
	Hours: 0.00		Comm: 51.56	Labor: 0.00	Parts: 0.0	0	Total:	51.56
Work Order: Problem:	1702834 Flat tire	Meter:	51803		In Date:	03/20/2017	Closed:	03/21/2017
Work Com	pleted							
- Tow Fron	n: 10651 Southern Blvd To: Lv shop							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	1705321 Replace key fob battery.	Meter:	53574		In Date:	05/30/2017	Closed:	05/31/2017
Work Com	pleted			Parts Issued			Qı	antity
- Test and	replace keyfob battery.			Enr Elect Battery				1.00

Labor: 15.00

Comm: 0.00

Hours: 0.25

Parts: 7.07

Total: 22.07

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1705997 Meter: 57463 In Date: 06/16/2017 **Closed:** 06/29/2017 Problem: P.M. service. **Parts Issued** Quantity **Work Completed** 5w20 Engine Oil 6.00 - P.m. Service. Napagold Oil Filter 1.00 - Pressure test and inspect cooling system.flush and refill system. Napagold Air Filter 1.00 - Rotate and balance tires. Accufit Beam 1.00 - Shop Supplies Accufit Beam 1.00 Washer Fluid Concentr 1.00 Anti Freeze Motorcraft 1.00 **Shop Supplies** 1.00 Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 82.46 Total: 382.46 Work Order: 1706338 Meter: 53574 In Date: 06/27/2017 Closed: 06/27/2017 Problem: 6 - Wash ticket(s) issued **Work Completed** - 6 - Wash ticket(s) issued Hours: 0.00 Comm: 57.24 Labor: 0.00 Parts: 0.00 Total: 57.24 Work Order: 1706827 Meter: 57463 In Date: 06/21/2017 **Closed**: 07/12/2017 Problem: damage to rgt doors **Work Completed** - damage to rgt doors Hours: 0.00 Comm: 2,351.98 Parts: 0.00 Labor: 0.00 Total: 2,351.98 Work Order: 1706974 Meter: 57698 **In Date:** 07/17/2017 **Closed:** 07/20/2017 **Problem:** Had to jump start. **Parts Issued** Quantity **Work Completed** 1.00 Battery - Charge battery fully.test battery and charging system.battery failed load test.r&r defective battery. **Shop Supplies** 1.00 - Shop Supplies

Comm: 0.00

Labor: 60.00

Parts: 156.59

Total: 216.59

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1707116 Meter: 57698 In Date: 07/20/2017 Closed: 07/20/2017

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1707120 Meter: 57698 In Date: 07/20/2017 Closed: 07/20/2017

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Work Order: 1710855 Meter: 63507 In Date: 11/02/2017 Closed: 11/08/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Rotate and high speed balance all four tires.		Napagold Oil Filte	er	1.00
- Inspect body and body plugs for leaks .reprog	gram Hvac module to latest	26in Exactfit-bean	n	1.00
calibration per Tsb 16-0166.		22in Exactfit-bean	n	1.00
- Shop Supplies		Wpr/blde		1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 56.71	Total: 296.71

Work Order: 1711352 Meter: 63507 In Date: 11/17/2017 Closed: 11/17/2017

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1800852 Meter: 67956 In Date: 01/24/2018 Closed: 01/29/2018

Problem: No start.

Work CompletedParts IssuedQuantity- Diagnoise no start.test battery good .scan computer Pats codes .replace
and program new Pats key.clear codes ,retest.Key W/ Remote1.00Shop Supplies1.00

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 152.99 Total: 242.99

Work Order: 1800883 Meter: 63507 In Date: 01/24/2018 Closed: 01/24/2018

Problem: key pad wouldnt open vehicle and when finally did the car lights went crazy, then vehicle wont start like dead battery

Work Completed

- Tow From: 7653 Oakmont Dr. Lake Worth To: vista center

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1802384 Meter: 69436 In Date: 03/02/2018 Closed: 03/06/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity	
- P.m. service.	. service. Napagold Oil Filter				
- Balance and rotate all four wheels .nitro fill a	and reset Tpms.	Napagold Oil Filter 5w20 Engine Oil 26in Exactfit-beam 22in Exactfit-beam 11in Exactfit-rear Shop Supplies	6.00		
- Shop Supplies		26in Exactfit-bear	1.00		
		22in Exactfit-bear	n	1.00	
		11in Exactfit-rear		1.00	
		Shop Supplies		1.00	
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 56.71	Total: 236.71	

Work Order: 1802689 Meter: 69436 In Date: 03/12/2018 Closed: 03/12/2018

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1802901 Meter: 70505 In Date: 03/19/2018 Closed: 03/22/2018

Problem: Wipers not clearing windshield

 Work Completed
 Parts Issued
 Quantity

 - Test and replace both front wiper blades and retest.
 26in Exactfit-beam
 1.00

 22in Exactfit-beam
 1.00

 Hours: 0.20
 Comm: 0.00
 Labor: 12.00
 Parts: 26.84
 Total: 38.84

Work Order: 1804430 Meter: 73104 In Date: 04/27/2018 Closed: 05/04/2018

Problem: P.M. service.Recall 17N03

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Rotate and balance all four tires.nitrogen fill tires.		Napagold Oil Filte	r	1.00
- Transport to and from dealer for recall 17n03.		26in Exactfit-beam)	1.00
- Shop Supplies		22in Exactfit-beam)	1.00
		11in Exactfit-rear		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 56.71	Total: 356.71

Work Order: 1805005 Meter: 73104 In Date: 05/14/2018 Closed: 05/14/2018

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1808554 Problem: P.M. service.	Meter:	78537		In Date:	08/20/2018	Closed:	08/23/2018
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter	r			1.00
- R&r broken left front outter door handle.			5w20 Engine Oil				6.00
- Perform tune up . Replace all six spark plu	gs and replac	e upper intake	Washer Fluid Cond	entr			1.00
gaskets .			Wd40 Spr				1.00
- Perform air intake decarb and flush injecto	ors .		Mac Wite Lithium	Gres			1.00
- Rotate and balance all four tires.			Door Handle				1.00
- Shop Supplies			Gasket				1.00
			Spark Plugs				6.00
			Injector Cleaner				1.00
			Intake Cleaner Kit				1.00
			Shop Supplies				1.00
Hours: 8.20		Comm: 0.00	Labor: 492.00	Parts: 209	9.87	Total:	701.87
Work Order: 1809203 Problem: 5 - Wash ticket(s) issued	Meter:	78537		In Date:	09/07/2018	Closed:	09/07/2018
Work Completed							
- 5 - Wash ticket(s) issued							
Hours: 0.00		Comm: 47.70	Labor: 0.00	Parts: 0.0	0	Total:	47.70
Work Order: 1812296 Problem: Left rear tire has nail.	Meter:	78537		In Date:	12/03/2018	Closed:	12/05/2018
Work Completed			Parts Issued			Qı	uantity
- Repair and balance left front tire.			Shop Supplies				1.00
- Shop Supplies							

Comm: 0.00

Labor: 67.00

Parts: 3.00

Total: 70.00

Work Order: Problem:	1900290 P.M. service.	Meter:	83665		In Date:	01/08/2019	Closed:	01/10/2019
Work Com	pleted			Parts Issued			Qu	antity
- P.m. serv	rice.			Napagold Oil Filter				1.00
- Replace 1	four tires . Balance and nitrogen f	fill all tires .		Napa Quart 5w20				6.00
- Perform	complete four wheel alignment a	ind road test .		11in Exactfit-rear				1.00
- Shop Sup				22in Exactfit-beam				1.00
	•			26in Exactfit-beam				1.00
				P245/60/18 Tire Mic				4.00
				Shop Supplies				1.00
				Tire Disposal Fee				4.00
	Hours: 6.50		Comm: 0.00	Labor: 435.50	Parts: 1,29	98.51	Total:	1,734.01
Work Order:		Meter:	86589		In Date:	04/18/2019	Closed:	04/19/2015
Problem:	remove lights & siren for surplus		86589	Parts Issued	In Date:	04/18/2019		
Problem: Work Com	remove lights & siren for surplus		86589	Parts Issued Shop Supplies	In Date:	04/18/2019		antity
Problem: Work Com - Remove	remove lights & siren for surplus pleted lights & sirens for surplus		86589	Parts Issued Shop Supplies	In Date:	04/18/2019		
Problem: Work Com	remove lights & siren for surplus pleted lights & sirens for surplus		86589 Comm: 0.00		In Date:		Qu	antity
Problem: Work Com - Remove - Shop Sup	remove lights & siren for surplus npleted lights & sirens for surplus pplies Hours: 2.50		Comm: 0.00	Shop Supplies			Q u Total:	1.00 170.50
Problem: Work Com - Remove - Shop Sup	remove lights & siren for surplus npleted lights & sirens for surplus pplies Hours: 2.50	S	Comm: 0.00	Shop Supplies	Parts: 3.00)	Q u Total:	1.00 170.50
Problem: Work Com - Remove - Shop Sup	remove lights & siren for surplus npleted lights & sirens for surplus pplies Hours: 2.50 1904268 Transition Prep Charge	S	Comm: 0.00	Shop Supplies	Parts: 3.00)	Q u Total:	1.00 170.50
Problem: Work Com - Remove - Shop Sup Work Order: Problem: Work Com	remove lights & siren for surplus npleted lights & sirens for surplus pplies Hours: 2.50 1904268 Transition Prep Charge	S	Comm: 0.00	Shop Supplies	Parts: 3.00)	Q u Total:	1.00 170.50
Problem: Work Com - Remove - Shop Sup Work Order: Problem: Work Com	remove lights & siren for surplus ppleted lights & sirens for surplus pplies Hours: 2.50 1904268 Transition Prep Charge ppleted	S	Comm: 0.00	Shop Supplies	Parts: 3.00	04/18/2019	Qu Total: Closed:	1.00 170.50
Problem: Work Com - Remove - Shop Sup Work Order: Problem: Work Com - Transition	remove lights & siren for surplus ppleted lights & sirens for surplus pplies	Meter:	Comm: 0.00 86588 Comm: 0.00	Shop Supplies Labor: 167.50	Parts: 3.00 In Date:	04/18/2019	Total: Closed: Total:	1.00 170.50 04/18/2019
Problem: Work Com - Remove - Shop Sup Work Order: Problem: Work Com - Transition	remove lights & siren for surplus ppleted lights & sirens for surplus pplies Hours: 2.50 1904268 Transition Prep Charge ppleted n Prep Charge Hours: 2.00 1904411 1 - Detail Vehicle Wash Ticket(s	Meter:	Comm: 0.00 86588 Comm: 0.00	Shop Supplies Labor: 167.50	Parts: 3.00 In Date: Parts: 0.00	O 04/18/2019	Total: Closed: Total:	1.00 170.50 04/18/2019
Problem: Work Com - Remove - Shop Sup Work Order: Problem: Work Com - Transition Work Order: Problem: Work Order: Problem:	remove lights & siren for surplus ppleted lights & sirens for surplus pplies Hours: 2.50 1904268 Transition Prep Charge ppleted n Prep Charge Hours: 2.00 1904411 1 - Detail Vehicle Wash Ticket(s	Meter:	Comm: 0.00 86588 Comm: 0.00	Shop Supplies Labor: 167.50	Parts: 3.00 In Date: Parts: 0.00	O 04/18/2019	Total: Closed: Total:	1.00 170.50 04/18/2019

- 1 - Wash ticket(s) issued

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

	1905301 pm service	Meter:	87746		In Date:	05/16/2019	Closed:	05/22/2019
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servi	ce			Napagold Oil Filter				1.00
- Repl. fror	nt asset #			Napa Quart 5w20				6.00
- Repl. fror	nt pads; service calipers & resurfac	e rotors		26in Exactfit-beam				1.00
				22in Exactfit-beam				1.00
				Brake Shoe, Kit				1.00
				Brake Shoe, Kit				1.00
	Hours: 6.00		Comm: 0.00	Labor: 402.00	Parts: 222	2.48	Total:	624.48
Work Order: Problem:	1907993 recall 19S17	Meter:	88720		In Date:	08/01/2019	Closed:	08/07/2019
Work Com	pleted							
- to dealer	for recall 19s17. rear toe links							
- look over	full suspension							
	Hours: 3.00		Comm: 0.00	Labor: 201.00	Parts: 0.0	0	Total:	201.00
Work Order: Problem: Work Com	1909889 1 - Wash ticket(s) issued	Meter:	89450		In Date:	09/25/2019	Closed:	09/25/2019

Comm: 9.54

Labor: 0.00

Parts: 0.00

Total: 9.54

Work Order: Problem:	1909953 towed in for no start	Meter:	89518		In Date:	09/26/2019	Closed:	10/03/2019
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servi	ce			Napagold Oil Filter				1.00
- Test and	R/r weak battery			Napa Quart 5w20				6.00
	igh speed balance & nitro 4 tires			Washer Fluid Concer	ntr			1.00
				11in Exactfit-rear				1.00
				22in Exactfit-beam				1.00
				26in Exactfit-beam				1.00
				Battery				1.00
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 246	6.72	Total:	538.72
	wont start/ tow after 9;00 am 9/26	Meter:	89450		In Date:	09/25/2019	Closed:	09/26/2019
Work Com	pleted							
- Tow Fron	m: 401 n dixie To: 2601 vista parkway							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	1911503 1 - Wash ticket(s) issued	Meter:	90494		In Date:	11/05/2019	Closed:	11/05/2019
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Work Order: Problem:	2001111 1 - Detail Vehicle Wash Ticket(s) Iss		91936		In Date:	01/31/2020	Closed:	01/31/2020
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00

Work Order: 2002605 Problem: pm service	Meter:	93420		In Date:	03/13/2020	Closed:	03/20/2020
Work Completed			Parts Issued			Qı	uantity
- pm service			Napagold Oil Filter				1.00
- rotate and balance all 4 tires			Napa Quart 5w20				6.00
			Washer Fluid Concer	ntr			1.00
			26in Exactfit-beam				1.00
			22in Exactfit-beam				1.00
			11in Exactfit-rear				1.00
Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 70.	04	Total:	289.04
Work Order: 2004711 Problem: check engine light on	Meter:	95105		In Date:	05/11/2020	Closed:	05/15/2020
Work Completed							
- reset oil change light							
Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 0.0	0	Total:	36.50
Work Order: 2009188 Problem: pm service	Meter:	97760		In Date:	09/14/2020	Closed:	10/05/2020
Work Completed			Parts Issued			Qı	uantity
- pm service			Napa Quart 5w20				6.00
·			Napagold Oil Filter				1.00
			Washer Fluid Concer	ntr			1.00
			22in Exactfit-beam				1.00
			26in Exactfit-beam				1.00
Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 57.	00	Total:	203.00
Work Order: 2012246 Problem: LF headlight/ turning on ac ma	Meter: akes engine wa			In Date:	12/09/2020	Closed:	12/21/2020
Work Completed			Parts Issued			Qı	uantity
- replaced left headlight bulb			Boxed Capsules				1.00
- road test vehicle & turned ac on & off, n	o problem fou	nd					
,							
Hours: 1.50		Comm: 0.00	Labor: 109.50	Parts: 10.	16	Total:	119.66

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 2012266 Meter: 99360 In Date: 12/09/2020 Closed: 12/09/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

In Date: 01/27/2021 Closed: 01/28/2021

Work Order: 2100592 Meter: 100009 In Date: 01/15/2021 Closed: 01/27/2021

Problem: Power Steering went out, eng light on

Work Completed	Parts Issued	Quantity
- test battery n charging system - replace battery	Fuse	2.00
- diagnose check engine light - p0442 evap code - found broken evap line -	Bp Fmx-lp F Mx Fuse	2.00
check over electrical power steering system no prob found - vehicle did have	Battery	1.00
a weak battery		

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 207.66 Total: 426.66

Work Order: 2101064 Meter: 100079

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2105171 Meter: 104791 In Date: 05/10/2021 Closed: 05/14/2021

Problem: pm service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		26in Exactfit-bear	1.00	
- Repaired 1 Tire, Rset Pressure With Nitrogen	, Re-balanced Tire	22in Exactfit-bear	1.00	
- Replaced Rear Brake Pads, Machined Rotors,	, Serviced Calipers	Napa Quart 5w20	6.00	
		Napagold Oil Filte	er	1.00
		Brake Pads		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 141.33	Total: 615.83

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

			ZOIS I OND EXI	, 0				
Work Order: Problem:	2108885 wheel bearing noise/ possibly L		105920		In Date:	08/17/2021	Closed:	08/19/2021
Work Comp	pleted			Parts Issued			Qı	uantity
	noise - r&r hub asm remove n 2 lb-ft - road test	install new lr	wheel bearing tq	Hub Asm				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 163	3.35	Total:	382.35
Work Order: Problem:	-	Meter:	106769		In Date:	10/25/2021	Closed:	10/27/2021
Work Com	pleted			Parts Issued			Qı	uantity
- Preventive Maint. Service			Napa Quart 5w20				6.00	
				Napagold Oil Filter				1.00
				Napagold Air Filter				1.00
				26in Exactfit-beam				1.00
				22in Exactfit-beam				1.00
	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 50.	01	Total:	196.01
Work Order: Problem:	2200464 check engine light on	Meter:	107457		In Date:	01/13/2022	Closed:	01/27/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Checked [Otc P0125,replaced Thermostat,	Bleed Coolant	t And Test Drove	Thermostat				1.00
	, ,			Anti Freeze Motorcra	aft			1.00
	Hours: 2.50		Comm: 0.00	Labor: 182.50	Parts: 33.	50	Total:	216.00
Work Order: Problem:	2202991 1 - Detail Vehicle Wash Ticket(108628		In Date:	03/17/2022	Closed:	03/17/2022
Work Comp	pleted							
- 1 - Detail	Vehicle Wash Ticket(s) Issued							

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2204813	Meter:	111453		In Date:	05/04/2022	Closed:	05/05/2022
Problem: pm service							
Work Completed			Parts Issued			Qı	ıantity
- Preventive Maint. Service			Napa Quart 5w20				6.00
			Napagold Oil Filter				1.00
			Washer Fluid Concen	tr			1.00
			11in Exactfit-rear				1.00
			22in Exactfit-beam				1.00
			26in Exactfit-beam				1.00
			Non-chlor Brake Clnr				1.00
Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 63.	00	Total:	209.00
Problem: 1 - Detail Vehicle Wash Ticket(s) Work Completed	Issued						
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40
Work Order: 2205212 Problem: 1 - Detail Vehicle Wash Ticket(s)		111727		In Date:	05/13/2022	Closed:	05/16/2022
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40
Work Order: 2206797 Problem: department states trans slipping	Meter:	112002		In Date:	06/28/2022	Closed:	
Work Completed							
- Check Over Vehicle							

Palm Beach County Fleet Management Asset Maintenance History 10192665 2013 FORD EXPLORER Suv, Lg Mid Size

Work Order: 2207380 Meter: 112002 In Date: 07/14/2022 Closed: 07/14/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 122.70 Total Labor: 7,925.00 Total Comm: 4,308.05 Total Parts: 5,379.94