



Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: 55345-LIGHT DUTY PMB Dodge Grand Caravan Braun Entervan SE
Requested By: JUHURST **VIN:** 2C7WDG6G6ER476545
Created By: JUHURST **Status:** 40
Class: WO **Priority:** 3
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
 ETA:

Chronology		
Reported	Jul 21, 2021	12:00 AM
Started	Jul 21, 2021	
Completed	Jul 22, 2021	12:08 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	244,067	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE:Service CORRECTION:Perform PMB Service Oil filter P9600 qty1 Engine oil 10w30 qty 5 1/2 qts Replaced right rear tire

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 54470178
Invoice Number: 55345-54470178

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: 55345-LIGHT DUTY PMA **VIN:** Dodge Grand Caravan Braun Entervan SE
 2C7WDG6G6ER476545
Requested By: RGASPARD **Status:** 40
Created By: RGASPARD **Priority:** 3
Class: WO **Driver:**
Arrangement: Unassigned **Phone:**
Potential Warranty: No **ETA:**

Chronology		
Reported	Jun 16, 2021	12:00 AM
Started	Jun 16, 2021	
Completed	Jun 16, 2021	9:26 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	239,736	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: unit came in for service CAUSE: Time for service CORRECTION: Job complete also replace one new tire to left front of unit size 225/65 R17 and oil filter # p9600. Please charge out for me showing zero in stock

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Jun-21	Junior Hurst	0.03	0.00	0.00

Activity 5 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 0.03
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10
Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Jun-21	P9600	FILTER, OIL	1.00	3.49	3.49



Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:			Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		VIN:	2C7WDG6G6ER476545
Requested By:	JUHURST	Status:	40
Created By:	JUHURST	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Apr 13, 2021	12:00 AM
Started	Apr 13, 2021	
Completed	Apr 15, 2021	12:05 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	235,478	DH
System	235,478	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter P9600 qty1 Engine oil 10w30 qty 6 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: 55345-LIGHT DUTY PMC **Dodge Grand Caravan Braun Entervan SE**
Requested By: JUHURST **VIN:** 2C7WDGBG6ER476545
Created By: JUHURST **Status:** 40
Class: WO **Priority:** 3
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Feb 18, 2021	12:00 AM
Started	Feb 19, 2021	
Completed	Feb 19, 2021	6:45 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	230,906	DH
System	230,906	DH

WorkOrder Notes

Line	Comment
------	---------

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Feb-21	Junior Hurst	0.03	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10
Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Feb-21	Junior Hurst	1.90	0.00	0.00

Activity 10 Sub Total



Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:		VIN:	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		Status:	2C7WDG6G6ER476545
Requested By:	DARTHURS	Priority:	40
Created By:	DARTHURS	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Dec 21, 2020	12:00 AM
Started	Dec 21, 2020	
Completed	Dec 21, 2020	6:23 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	226,508	DH
System	226,508	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: CAUSE: CORRECTION: PM service complete. 12/21/2020

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Dec-20	Junior Hurst	0.02	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.02	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **011RTD SUSPENSION**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **WO Desc:** Dodge Grand Caravan Braun Entervan SE
Requested By: VAMRITTEEMAL **VIN:** 2C7WDGBG6ER476545
Created By: VAMRITTEEMAL **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Mar 11, 2020	10:13 AM
Started	Mar 11, 2020	
Completed	Mar 11, 2020	11:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,703	DH
System	213,896	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points Check Brakes. Rotate . L/F To L/R & R/R ToR/F Swap R/F & Replace On R/R. Replace cabin Air Filter. Parts# P9600 Qty (1) Parts #PA10030 Qty (1) Oil 10W30 Qty (5.5) Qt

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Mar-20	Arthurs,Durvin	1.65	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.65	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: 55345-LIGHT DUTY PMA **VIN:** Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG6ER476545
Requested By: RGASPARD **Status:** 40
Created By: RGASPARD **Priority:** 3
Class: WO **Driver:**
Arrangement: Unassigned **Phone:**
Potential Warranty: No **ETA:**

Chronology		
Reported	Sep 15, 2020	12:00 AM
Started	Sep 15, 2020	
Completed	Sep 15, 2020	11:08 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	222,250	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: change Oil & Filter ,Check Brakes. Lube all Pivoting Points Clean Batteries. Parts # B329 Qty (1) Oil 10W20 Qty (5.5:) Qt.

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53558510
Invoice Number: 55345-53558510

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: NSTOI FO
Created By: NSTOLFO
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4811
Dodge Grand Caravan Braun Entervan SE
VIN: 2C7WDGBG6ER476545
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 24, 2020	12:02 PM
Started	Jun 24, 2020	
Completed	Jun 25, 2020	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	217,936	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: service CORRECTION:perform PMB service Oil filter P9600 qty 1 Engine oil 10w30 qty 5 1/2 qts

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 0.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 53111044
Invoice Number: 55345-53111044

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: EARJOHNSON **VIN:** 2C7WDGBG6ER476545
Created By: EARJOHNSON **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Jan 17, 2020	10:44 AM
Started	Jan 20, 2020	
Completed	Jan 20, 2020	6:27 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,581	DH
System	209,339	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Jan-20	AMRIT TEEMAL,VISHNU	0.63	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.63
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
20-Jan-20	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53003308
Invoice Number: 55345-53003308

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4811
VIN: Dodge Grand Caravan Braun Entervan SE
Status: 2C7WDGBG6ER476545
Priority: 40
Driver: 1
Phone:
ETA:

Chronology		
Reported	Dec 16, 2019	12:00 AM
Started	Dec 18, 2019	
Completed	Dec 18, 2019	8:50 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	205,098	DH
System	204,878	DH

WorkOrder Notes

Line Comment

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Dec-19	Earl Johnson	1.68	65.00	109.20

Activity 10 Sub Total

Parts: 0.00
Labor: 109.20
Labor Hours: 1.68
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 109.20

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Dec-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Dec-19	Earl Johnson	0.15	65.00	9.75



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52888567
Invoice Number: 55345-52888567

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: DARTHURS **VIN:** 2C7WDGBG6ER476545
Created By: DARTHURS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Nov 14, 2019	12:00 AM
Started	Nov 15, 2019	
Completed	Nov 15, 2019	12:31 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,197	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter P9600 qty1 Engine oil 5w20 qty 6 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Nov-19	Gaspard,Ronald	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 65.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Nov-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52780671
Invoice Number: 55345-52780671

Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM A		VIN:	2C7WDGBG6ER476545
Requested By:	RRENE	Status:	40
Created By:	RRENE	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Oct 11, 2019	11:15 AM
Started	Oct 11, 2019	
Completed	Oct 11, 2019	9:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	195,603	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes Parts # B329 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Oct-19	Arthurs, Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
11-Oct-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52648487

Invoice Number: 55345-52648487

Client Department:

MRC: 55345M

Equipment: 4811

WO Desc:

Dodge Grand Caravan Braun Entervan SE

PM B

VIN: 2C7WDGBG6ER476545

Requested By: VAMRITTEEMAL

Status: 40

Created By: VAMRITTEEMAL

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Sep 9, 2019	3:57 PM
Started	Sep 11, 2019	
Completed	Sep 11, 2019	12:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	191,546	DH
System	191,535	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmB CAUSE: Service due CORRECTION: Performed and completed pmB Changed engine oil and replaced engine oil filter

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Sep-19	Delva, Terry	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	102.92

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
11-Sep-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52551231
Invoice Number: 55345-52551231

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: AOWENS **VIN:** 2C7WDG6G6ER476545
Created By: AOWENS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Jul 30, 2019	2:54 PM
Started	Jul 30, 2019	
Completed	Jul 30, 2019	10:02 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	186,904	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Jul-19	AMRIT TEEMAL,VISHNU	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 65.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
30-Jul-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52455005

Invoice Number: 55345-52455005

Client Department:

MRC: 55345M

WO Desc:
PM A

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

Dodge Grand Caravan Braun Entervan SE

VIN: 2C7WDGBG6ER476545

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Jun 25, 2019	4:12 PM
Started	Jun 25, 2019	
Completed	Jun 26, 2019	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	182,552	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE
	CAUSE: PREVENTIVE MAINTENANCE
	CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jun-19	AMRIT TEEMAL,VISHNU	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	65.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
25-Jun-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52368954

Invoice Number: 55345-52368954

Client Department:

MRC: 55345M

WO Desc:
PM C

Requested By: RGASPARD

Created By: RGASPARD

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

Dodge Grand Caravan Braun Entervan SE
2C7WDGBG6ER476545

VIN: 40

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	May 22, 2019	11:05 AM
Started	May 22, 2019	
Completed	May 23, 2019	12:06 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,390	DH

WorkOrder Notes

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE REPLACED CABIN FILTER

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-May-19	AMRIT TEEMAL,VISHNU	2.00	65.00	130.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 130.00
 Labor Hours: 2.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 130.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
22-May-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52267774
Invoice Number: 55345-52267774

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A Dodge Grand Caravan Braun Entervan SE
Requested By: RGASPARD **VIN:** 2C7WDGBG6ER476545
Created By: RGASPARD **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Apr 23, 2019	1:33 PM
Started	Apr 23, 2019	
Completed	Apr 24, 2019	12:03 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	173,990	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter P9600 Qty1 Engine oil 5w20 qty 6 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Apr-19	Gaspard, Ronald	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 65.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
23-Apr-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder: 52004446
Invoice Number: 55345-52004446

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: RGASPARD **VIN:** 2C7WDGBG6ER476545
Created By: RGASPARD **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Mar 19, 2019	3:46 PM
Started	Mar 19, 2019	
Completed	Mar 20, 2019	12:28 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	169,741	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter P9600 Qty1 Engine oil 5w20 qty 6 Qts Air filter PA4456 qty 1

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Mar-19	Gaspard, Ronald	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51910566
Invoice Number: 55345-51910566

Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM B		VIN:	2C7WDGBG6ER476545
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Dec 17, 2018	5:05 PM
Started	Dec 17, 2018	
Completed	Dec 17, 2018	11:51 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	165,488	DH
System	165,647	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE: Service CORRECTION:Perform pmB Service Oil filter P9600 Qty1 Engine oil 5w20 qty 6 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Dec-18	Gaspard,Ronald	1.07	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Dec-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A Dodge Grand Caravan Braun Entervan SE
Requested By: RGASPARD **VIN:** 2C7WDGBG6ER476545
Created By: RGASPARD **Status:** 32
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Nov 14, 2018	11:36 AM
Started	Nov 14, 2018	
Completed	Nov 15, 2018	12:02 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	161,269	DH
System	161,359	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter P9600 Qty1 Engine oil 5w20 qty 5 Qts Rotate tires Torque wheels 100 lbs second torque wheels 100 lbs

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Nov-18	Gaspard,Ronald	1.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51714511
Invoice Number: 55345-51714511

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A **Dodge Grand Caravan Braun Entervan SE**
Requested By: RGASPARD **VIN:** 2C7WDGBG6ER476545
Created By: RGASPARD **Status:** 32
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
ETA:

Chronology		
Reported	Oct 16, 2018	3:25 PM
Started	Oct 16, 2018	
Completed	Oct 17, 2018	12:05 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	157,282	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter P9600 Qty1 Engine oil 5w20 qty 5 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Oct-18	Gaspard,Ronald	1.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Oct-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51561387
Invoice Number: 55345-51561387

Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:	PM C		Dodge Grand Caravan Braun Entervan SE
Requested By:	DKNOTT	VIN:	2C7WDGBG6ER476545
Created By:	DKNOTT	Status:	32
Class:	WO	Priority:	1
Arrangement:	Unassigned	Driver:	
Potential Warranty:	No	Phone:	
		ETA:	

Chronology		
Reported	Sep 12, 2018	1:56 PM
Started	Sep 12, 2018	
Completed	Sep 13, 2018	12:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	153,078	DH
System	153,078	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter P9600 Qty1 Engine oil 5w20 qty 6 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Sep-18	Gaspard,Ronald	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Sep-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51474396
Invoice Number: 55345-51474396

Client Department:

MRC: 55345M **Equipment:** 4811
WO Desc: PM A Dodge Grand Caravan Braun Entervan SE
Requested By: CKARLENS **VIN:** 2C7WDGBG6ER476545
Created By: CKARLENS **Status:** 40
Class: WO **Priority:** 1
Arrangement: Unassigned **Driver:**
Potential Warranty: No **Phone:**
 ETA:

Chronology		
Reported	Aug 1, 2018	11:41 AM
Started	Aug 1, 2018	
Completed	Aug 2, 2018	9:47 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	148,736	DH
System	148,736	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter P9600 qty1 Engine Oil 5w20 qty 6 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Aug-18	Gaspard,Ronald	1.08	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 1.08
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
01-Aug-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:	PM A	VIN:	Dodge Grand Caravan Braun Entervan SE 2C7WDGBG6ER476545
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Jun 29, 2018	2:42 PM
Started	Jun 29, 2018	
Completed	Jul 1, 2018	8:59 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	144,343	DH
System	144,660	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform pmA CAUSE:Preventive Maintenance CORRECTION: Tech Performed PM-A Parts used Oil filter Qty:1 part#P9600 Oil Qty:5.5

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Jun-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder: 51352810
Invoice Number: 55345-51352810

Client Department:

MRC: 55345M

WO Desc:
 PM A

Requested By: DARTHURS

Created By: DARTHURS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

VIN: Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG6ER476545

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Date	Part Number	Description	Qty.	Each	Extended
29-Jun-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Jun-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 20 Sub Total

Parts:	3.44
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.44

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Jun-18	KARLENS,Cyrius	0.33	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.33	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51352810 Grand Total

Parts:	3.44
Labor:	0.00
Labor Hours: 4.33	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.44

Recent Repair History



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 9



WorkOrder: 51352810
Invoice Number: 55345-51352810

Client Department:

MRC: 55345M

WO Desc:
 PM A

Requested By: DARTHURS

Created By: DARTHURS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

VIN: Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG6ER476545

Status: 40

Priority: 1

Driver:

Phone:

ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51352810	1-Jul-18	144,343	WO	PM A
51399508	5-Jun-18	140,960	WO	Passenger-side rear door harness is broken and ramp is out of adjustment

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51485671	6-Jul-18	145,014	WO	Engine is making noise

PH: Work Order: 51352810 Desc: PM A

Equip: 4811 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG6ER476545

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 29-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,100	Safety Inspection	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 29, 2018 4:03:05 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	Jun 29, 2018 4:03:06 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Jun 29, 2018 4:03:07 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:03:08 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 29, 2018 4:03:09 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	Jun 29, 2018 4:03:09 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 29, 2018 4:03:08 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	Jun 29, 2018 4:03:09 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Jun 29, 2018 4:04:02 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 29, 2018 4:04:02 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	Jun 29, 2018 4:04:03 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 29, 2018 4:04:04 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 29, 2018 4:04:04 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 29, 2018 4:09:08 PM	No	
40,420	Check Hood	Done		CKARLENS	Jun 29, 2018 4:09:08 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:09:08 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jun 29, 2018 4:09:08 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 29, 2018 4:09:09 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:09:09 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 29, 2018 4:09:09 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Jun 29, 2018 4:09:09 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jun 29, 2018 4:09:09 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	Jun 29, 2018 4:09:10 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	Jun 29, 2018 4:09:11 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 29, 2018 4:09:11 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 29, 2018 4:09:11 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	Jun 29, 2018 4:09:11 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	Jun 29, 2018 4:09:12 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:09:13 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	0 Pounds per Square Inch	na	CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	na	CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	Jun 29, 2018 4:09:13 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,632	Tread Depth LF	6 32nds of an inch		CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,634	Tread Depth RRI	32nds of an inch	na	CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,635	Tread Depth LRI	32nds of an inch	na	CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,636	Tread Depth LRO	6 32nds of an inch		CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 29, 2018 4:09:14 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 29, 2018 4:09:15 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 29, 2018 4:09:16 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:09:17 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
77,131	Brake Pad Thickness LF	9 Inch		CKARLENS	Jun 29, 2018 4:09:17 PM	No	
77,132	Brake Pad Thickness RF	9 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,135	Brake Rotor LF	27.8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,136	Brake Rotor RF	27.8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,137	Brake Rotor LR	11.8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,138	Brake Rotor RR	11.8 Inch		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	Jun 29, 2018 4:09:18 PM	No	
77,150	Check King Pins	-	na	CKARLENS	Jun 29, 2018 4:09:19 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 29, 2018 4:09:19 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 29, 2018 4:09:19 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	Jun 29, 2018 4:09:19 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	Jun 29, 2018 4:09:19 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	Jun 29, 2018 4:09:19 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: CKARLENS Performed on: 29-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 29, 2018 3:59:50 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Jun 29, 2018 3:59:51 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Jun 29, 2018 3:59:50 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Jun 29, 2018 3:59:50 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Jun 29, 2018 3:59:51 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Jun 29, 2018 3:59:51 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	Jun 29, 2018 3:59:51 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Jun 29, 2018 3:59:51 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 29-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 29, 2018 3:58:53 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 51248398
Invoice Number: 55345-51248398

Client Department:

MRC:	55345M	Equipment:	4811
WO Desc:			Dodge Grand Caravan Braun Entervan SE
PM B		VIN:	2C7WDGBG6ER476545
Requested By:	RAURODRIGUEZ	Status:	40
Created By:	RAURODRIGUEZ	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	May 16, 2018	12:01 PM
Started	May 16, 2018	
Completed	May 16, 2018	11:22 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	140,030	DH
System	140,192	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil& Filter. Lube all Pivoting Points. check brakes.motor leaking oil / Motor tapping.Swap L/R Tire With one 5/32 Parts# P9600 Qty (1) Oil 5 W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-May-18	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-May-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44



WorkOrder: 51248398
Invoice Number: 55345-51248398

Client Department:

MRC: 55345M

WO Desc:
PM B

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG6ER476545

VIN:

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
16-May-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	3.44
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.44

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-May-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 51248398 Grand Total

Parts:	3.44
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.44

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51399508	5-Jun-18	140,960	WO	Passenger-side rear door harness is broken and ramp is out of adjustment
51248398	16-May-18	140,030	WO	PM B



WorkOrder: 51248398
Invoice Number: 55345-51248398

Client Department:

MRC: 55345M

WO Desc:
PM B

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4811

Dodge Grand Caravan Braun Entervan SE
 2C7WDGBG6ER476545

VIN:
Status: 40

Priority: 1

Driver:

Phone:

ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51110706	18-Apr-18	136,087	WO PM A	

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51248398 Desc: PM B

Equip: 4811 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG6ER476545

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 16-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,100	Safety Inspection	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 16, 2018 8:55:06 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	May 16, 2018 8:55:07 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	May 16, 2018 8:55:09 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	May 16, 2018 8:55:08 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	May 16, 2018 8:55:08 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	May 16, 2018 8:55:09 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	May 16, 2018 8:55:09 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 16, 2018 8:55:09 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 16, 2018 8:55:09 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	May 16, 2018 8:55:09 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	May 16, 2018 8:55:09 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 16, 2018 8:55:09 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	May 16, 2018 8:55:09 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	May 16, 2018 8:55:10 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	May 16, 2018 8:55:10 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	May 16, 2018 8:55:10 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	May 16, 2018 8:55:10 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	May 16, 2018 8:55:10 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 16, 2018 8:55:11 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 16, 2018 8:55:11 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 16, 2018 8:55:11 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	May 16, 2018 8:55:11 PM	No	
22,110	Check Emergency Hatches	-	NA	DARTHURS	May 16, 2018 8:55:11 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	May 16, 2018 8:55:11 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 16, 2018 8:55:12 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	May 16, 2018 8:55:11 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	May 16, 2018 8:55:12 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	May 16, 2018 8:55:12 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 16, 2018 8:55:12 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	May 16, 2018 8:55:12 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	May 16, 2018 8:55:12 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
40,420	Check Hood	Done		DARTHURS	May 16, 2018 8:55:13 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	May 16, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:55:13 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 16, 2018 8:55:14 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 16, 2018 8:55:14 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 16, 2018 8:55:14 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 16, 2018 8:55:14 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 16, 2018 8:55:14 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 16, 2018 8:55:14 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 16, 2018 8:55:14 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	May 16, 2018 8:55:14 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	May 16, 2018 8:55:15 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	May 16, 2018 8:55:16 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 16, 2018 8:55:16 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 16, 2018 8:55:16 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	May 16, 2018 8:55:16 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	May 16, 2018 8:55:16 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 16, 2018 8:55:16 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	May 16, 2018 8:55:17 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	May 16, 2018 8:55:17 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 16, 2018 8:55:17 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	May 16, 2018 8:55:17 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		DARTHURS	May 16, 2018 8:55:17 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		DARTHURS	May 16, 2018 8:55:17 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		DARTHURS	May 16, 2018 8:55:17 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	Pounds per Square Inch	NA	DARTHURS	May 16, 2018 8:55:18 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	NA	DARTHURS	May 16, 2018 8:55:18 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,631	Tread Depth RF	5 32nds of an inch		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,632	Tread Depth LF	5 32nds of an inch		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,633	Tread Depth RRO	5 32nds of an inch		DARTHURS	May 16, 2018 8:55:18 PM	No	
60,634	Tread Depth RRI	32nds of an inch	NA	DARTHURS	May 16, 2018 8:55:18 PM	No	
60,635	Tread Depth LRI	32nds of an inch	NA	DARTHURS	May 16, 2018 8:55:19 PM	No	
60,636	Tread Depth LRO	2 32nds of an inch	swap L/R tire with one 5/32	DARTHURS	May 16, 2018 8:55:19 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	May 16, 2018 8:55:19 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
66,100	FRA Check Outer Hubs for Leaks	-	NA	DARTHURS	May 16, 2018 8:55:20 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 16, 2018 8:55:19 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	May 16, 2018 8:55:20 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	-	NA	DARTHURS	May 16, 2018 8:55:20 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 16, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:55:21 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		DARTHURS	May 16, 2018 8:55:22 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		DARTHURS	May 16, 2018 8:55:21 PM	No	
77,135	Brake Rotor LF	1.1 Inch		DARTHURS	May 16, 2018 8:55:22 PM	No	
77,136	Brake Rotor RF	1.101 Inch		DARTHURS	May 16, 2018 8:55:22 PM	No	
77,137	Brake Rotor LR	.499 Inch		DARTHURS	May 16, 2018 8:55:22 PM	No	
77,138	Brake Rotor RR	.498 Inch		DARTHURS	May 16, 2018 8:55:22 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	May 16, 2018 8:55:23 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	May 16, 2018 8:55:23 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 16, 2018 8:55:23 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	May 16, 2018 8:55:22 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	May 16, 2018 8:55:23 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	May 16, 2018 8:55:23 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	May 16, 2018 8:55:23 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: DARTHURS Performed on: 16-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	May 16, 2018 8:56:49 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	May 16, 2018 8:56:50 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	May 16, 2018 8:56:50 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	May 16, 2018 8:56:50 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	May 16, 2018 8:56:50 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	May 16, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:56:50 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 16, 2018 8:56:50 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	May 16, 2018 8:56:50 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	May 16, 2018 8:56:50 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	May 16, 2018 8:56:50 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	May 16, 2018 8:56:51 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	May 16, 2018 8:56:51 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done	check engine light on & Motor tapping	DARTHURS	May 16, 2018 8:57:35 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 16-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 16, 2018 8:58:10 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	