Total Hours: 91.05 La	abor: 5,975.85	Parts: 3,524.19	Comm: 192.00		Chargeo	1: 9692.04	
Work Order: 1005806 Problem: Pre Deliver	Meter: ry Inspection	11		In Date:	06/03/2010	Closed:	06/03/2010
Work Completed							
- Pre Delivery Inspection	on						
H	ours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1012877 Problem: P. M. SER	Meter: VICE	2224		In Date:	11/18/2010	Closed:	11/30/2010
Work Completed			Parts Issued			Qı	uantity
- P. M.			Shop Supplies				1.00
- Shop Supplies			1372 Oil Filter Frm	Ph2 Wix 51	372		1.00
			5w20 Engine Oil				7.00
H	ours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 38.	59	Total:	158.59
Work Order: 1105515 Problem: P. M. SER	Meter: VICE	4860		In Date:	05/25/2011	Closed:	05/27/2011
Work Completed			Parts Issued			Qı	uantity
- Performed P.m.			Shop Supplies				1.00
- Tightened tool box.			1372 Oil Filter Frm	Ph2 Wix 51	372		1.00
- Shop Supplies			5w20 Engine Oil				7.00
			1066 White Lithiun	n (crc 05037)			1.00
			Used Firex Refurbed	d Fire Extings	hers		1.00
H	ours: 2.50	Comm: 0.00	Labor: 150.00	Parts: 55.	26	Total:	205.26
Work Order: 1200168 Problem: P. M. SER	Meter: VICE	7322		In Date:	01/05/2012	Closed:	01/12/2012
Work Completed			Parts Issued			Qı	uantity
- P. M. Service.			Shop Supplies				1.00
- Shop Supplies			1372 Oil Filter Frm	Ph2 Wix 51	372		1.00
			5w20 Engine Oil				7.00
							150.34

Nork Order: 1200370 Problem: needs 2 extra keys	Meter:	7385		In Date:	01/11/2012	Closed:	01/19/2012
Work Completed			Parts Issued			Qı	uantity
- Make and program 2 extra keys			164-r8040 Ignition K	(ey 2011- N	ewer (ford)		2.00
- Flash Coneceiver and reprogram			Shop Supplies				1.00
- Shop Supplies							
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 48.	.50	Total:	168.50
Work Order: 1401335 Problem: pm	Meter:	13961		In Date:	02/10/2014	Closed:	02/19/2014
Work Completed			Parts Issued			Qı	uantity
- pm			Napagold Oil Filter				1.00
- Shop Supplies			Napa Quart 5w20				7.00
			Wiper Blade				2.00
			Washer Fl				1.00
			Shop Supplies				1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 43.	.10	Total:	163.10
Work Order: 1403849 Problem: FRONT LEFT TIRE SCREW IN IT	Meter:	14390		In Date:	04/21/2014	Closed:	04/25/2014
Work Completed			Parts Issued			Qı	uantity
- - ck screw in lf tire dismount mount patach bala	ance add	n2	Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: 1408183 Problem: PM	Meter:	15538		In Date:	08/18/2014	Closed:	08/25/2014
Work Completed			Parts Issued			Qı	uantity
- pm			Napagold Oil Filter				1.00
- Shop Supplies			Napa Quart 5w20				7.00
			Shop Supplies				1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 32.	.39	Total:	152.39

Work Order: Problem:		Meter:	17355		In Date:	02/18/2015 Closed:	02/26/2015
Work Com	npleted			Parts Issued		C	uantity
- pm				Napagold Oil Filter			1.00
-	t rear tail light assm damage	ed replace assembly	V	Napa Quart 5w20			7.00
- Shop Su	5 5		,	Wiper Blade			2.00
				Washer Fl			1.00
				Lamp Assembly			1.00
				Shop Supplies			1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 20	1.95 Total	: 381.95
Work Order: Problem:	1509205 pm, not cooling	Meter:	19950		In Date:	09/14/2015 Closed:	09/18/2015
Work Com	npleted			Parts Issued		c	uantity
- pm				Napagold Oil Filter			1.00
-	t cooling ck sys pressure and	d found low freon e	evac recharge add	Napa Quart 5w20			7.00
	ind no leaks at this time		U U	Washer Fluid Concen	tr		1.00
- repair da	amage left front rear view ho	busing		Napagold Air Filter			1.00
- Shop Su	pplies			Used Fire X Refurbish	ned		1.00
				South Region R134a			2.00
				South Region R134a			2.00
				Ptex Superbond Sm			1.00
				Shop Supplies			1.00
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 92.	.35 Total	: 392.35
Work Order: Problem:	1511604 no start towed in	Meter:	20595		In Date:	11/12/2015 Closed:	11/30/2015
Work Com	npleted			Parts Issued		c	uantity
- recharge	e ck and replace bad battery			Battery			1.00
- Shop Su	pplies			Shop Supplies			1.00
	Hours: 0.75		Comm: 0.00	Labor: 45.00	Parts: 120		: 165.41

ork Order: Problem:		Meter:	20436		In Date:	11/12/2015	Closed:	11/18/2015
Work Com	pleted							
- Tow Fror	m: 22543 sw 65 ave boca To: sr	shop delray						
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.00)	Total:	96.00
ork Order:		Meter:	20831		In Date:	12/07/2015	Closed:	12/09/2015
Problem:	wont fuel							
Work Com	pleted			Parts Issued			Qu	antity
- Test and	remove Cancever issue fuel car	d		Shop Supplies				1.00
- Shop Suj	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.00)	Total:	62.00
	1000200	Meter:	21004		In Date:	03/28/2016	Closed:	04/05/2016
ork Order: Problem: Work Com	pm	inclei.	21004	Parts Issued	in Date:	03/28/2016		04/05/2016
Problem: Work Com	pm apleted	meter.	21004	Parts Issued Napagold Oil Filter	In Date:	03/28/2016		
Problem: Work Com - Pm servio	pm apleted ce.				In Date:	03/28/2016		lantity
Problem: Work Com - Pm servio	pm apleted ce. reds for tires.r&r 4 tires.mount a			Napagold Oil Filter	In Date:	03/28/2016		iantity 1.00
Problem: Work Com - Pm servio - Verify ne Tpms sense	pm apleted ce. reds for tires.r&r 4 tires.mount a			Napagold Oil Filter Napa Quart 5w20		03/28/2016		iantity 1.00 7.00
Problem: Work Com - Pm servio - Verify ne Tpms sense	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade	2			1.00 7.00 2.00
Problem: Work Com - Pm servio - Verify ne Tpms sense - Check ac	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade 235 75r17 Adventure	e oring System			1.00 7.00 2.00 4.00
Problem: Work Com - Pm servio - Verify ne Tpms sense - Check ac	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade 235 75r17 Adventure Tire Pressure Monito	e pring System or			1.00 7.00 2.00 4.00 1.00
Problem: Work Com - Pm servio - Verify ne Tpms sense - Check ac	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade 235 75r17 Adventure Tire Pressure Monito Blower Motor Resisto	e pring System or			1.00 7.00 2.00 4.00 1.00
Problem: Work Com - Pm servio - Verify ne Tpms sense - Check ac	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade 235 75r17 Adventure Tire Pressure Monito Blower Motor Resiste Tpms12 Sensor Tire I	e pring System or			1.00 7.00 2.00 4.00 1.00 1.00
Problem: Work Com - Pm servio - Verify ne Tpms sense - Check ac	pm apleted ce. reds for tires.r&r 4 tires.mount a pr. conly blows on #3			Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade 235 75r17 Adventure Tire Pressure Monito Blower Motor Resistor Tpms12 Sensor Tire I Blower Resistor	e pring System or			1.00 7.00 2.00 4.00 1.00 1.00 1.00 1.00

Work Order:1702122Meter:25276Problem:P.M.SERVICE/ LOW PRESSURE TIRE INDICATOR ON.

In Date: 03/01/2017 Closed: 03/13/2017

Work Completed		Parts Issued			Qı	uantity	
- Pm Service.		Napa Quart 5w20				7.00	
- Repair F/l tire.rotate and balance all.corre	ect N2 levels.relearn Tpms.	22" Wiper Blade				2.00	
- Shop Supplies	•	Washer Fluid Conce	entr		1.00		
		Used Fire X Refurbi	shed		1.0		
		Napagold Oil Filter				1.00	
		Shop Supplies				1.00	
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 54.	92	Total:	279.92	
ork Order: 1708962 Problem: PM Service	Meter: 26548		In Date:	09/18/2017	Closed:	09/27/2	
Work Completed		Parts Issued			Qı	uantity	
- Pm Service		Napa Quart 5w20				7.00	
- Rotate and balance tires.		Napagold Oil Filter				1.00	
- Shop Supplies		Washer Fluid Conce	entr			1.00	
		22" Wiper Blade				2.00	
		Napagold Air Filter	r			1.00	
		Shop Supplies				1.00	
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 49.	87	Total	214.87	

Nork Order:		Meter: 27788		In Date:	03/29/2018 CI	osed:	04/12/2018		
Problem:	PM Service.Steering wheel	cover.							
Work Com	pleted		Parts Issued			Qı	uantity		
- Pm Servio	ce		Lamp Assembly				1.00		
- Replace k	oroken left tail lamp with new	assembly.fabricate and install	Napa Quart 5w20 7.0						
strobe light	t to new lamp.		Napagold Oil Filter	1.00					
- Rotate ar	nd balance 4 tires		22" Wiper Blade				2.00		
- Shop Sup	oplies		Ford Triton Pvc Swc				1.00		
			Clr Rtv Silcn Sealant				1.00		
			Non-chlor Brake Cln	r			1.00		
			Shop Supplies				1.00		
	Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 227	7.00	Total:	512.00		
ork Order: Problem:	1808967 Ac not cold	Meter: 28874		In Date:	08/30/2018 CI	osed:	09/18/2018		
Work Com	pleted		Parts Issued			Qı	uantity		
- C/s ac no	ot blowing cold.check system	pressure found low pressure	E8 A/c Oil Univ W Dy	/e			1.00		
.evacuate,re	echarge, check for leaks and f	ound no leaks at this time.	Freon Sr Shop				2.00		
- Shop Sup	oplies		Shop Supplies				1.00		
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 21.	89	Total:	201.89		

Vork Order: 1812796 Problem: P.M. Service.Detail.	Meter: 29250		In Date:	12/17/2018 Clo	sed:	12/27/2018
Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filte	r			1.00
- Inspect all brakes . Resurface front and rear ro	otors and service calipers .	Napa Quart 5w20				7.00
Replace front and rear brake pads . Flush and bl	eed brake system . Road test.	Washer Fluid Cond	centr			1.00
- Replace left front seat side trim panel .		20" Wiper Blade				2.00
- Shop Supplies		Used Fire X Refurb	oished			1.00
		brake fluid				1.00
		Non-chlor Brake C	Inr			1.00
		Brake Pad				1.00
		Brake Pad				1.00
		Housing				1.00
		Shield Asy				1.00
		Shop Supplies				1.00
Hours: 9.30	Comm: 0.00	Labor: 623.10	Parts: 330	.72	Total:	953.82
/ork Order: 1813061 Problem: 1 - Detail Vehicle Wash Ticket(s) Is	Meter: 29250 sued		In Date:	12/27/2018 Clo	sed:	12/27/2018
Work Completed						
- 1 - Detail Vehicle Wash Ticket(s) Issued						
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	D	Total:	96.00

Nork Order: 1906525 Problem: PM Service	Meter: 30462		In Date:	06/20/2019 Clo	osed:	07/08/201
Work Completed		Parts Issued			Qu	antity
- Pm Service.		Napa Quart 5w20				7.00
- Replace third brake lamp bulbs.		Napagold Oil Filte	r			1.00
- Rotate and balance 4 tires.mount and disr	mount 1 tire to index and	20" Wiper Blade				2.00
balance on right rear.		Washer Fluid Cond	entr			1.00
- Vacume debris from engine compartment		Boxed Miniatures				3.00
- Install how is my driving sticker and resec	ure strobe lamp harness.	Shop Supplies				1.00
- Shop Supplies						
Hours: 5.00	Comm: 0.00	Labor: 335.00	Parts: 46	.17	Total:	381.17
<i>Iork Order</i> : 1913220 Problem: PM Service	Meter: 32098		In Date:	12/31/2019 Clc		01/13/202
Work Completed		Parts Issued			Qu	antity
- Pm Service.		Used Fire X Refurb	ished			1.00
- Rotate and balance four tires.		Napagold Air Filte	er			1.00
- Service tool box and adjust to close prope	erly.	Napagold Oil Filte	r			1.00
- Clean engine compartment.		Napa Quart 5w20				7.00
- Shop Supplies		Washer Fluid Cond	entr			1.00
		20" Wiper Blade				2.00
		Non-chlor Brake C	Inr			1.00
		Shop Supplies				1.00
Hours: 4.25	Comm: 0.00	Labor: 310.25	Parts: 75	58	Total:	385.83

Work Order: 2007820 Meter: 33658 08/07/2020 **Closed:** 08/25/2020 In Date: Problem: PM Service.No power. **Work Completed** Parts Issued Quantity Napa Quart 5w20 7.00 - Pm Service. Napagold Oil Filter 1.00 - Check and replace bad battery. Washer Fluid Concentr 1.00 - C/s no power.test drive and found front brakes locking up.replace both front brake calipers, pads both hoses and rotors. flush brake fluid. Brake Pad Set 1.00 - Test drive before and after repairs. 1.00 Non-chlor Brake Clnr - Rotate and balance tires. B Fluid Dot 3-32oz 1.00 - Shop Supplies Permatex 1.00 1.00 Battery 2.00 Center Cap Front Rotor Motorcraft 2.00 1.00 Brake Hose F/r Brake Hose F/I 1.00 Caliper F/I 1.00 Caliper F/r 1.00 20" Wiper Blade 2.00 Shop Supplies 1.00 Hours: 9.50 Comm: 0.00 Labor: 693.50 Parts: 803.67 Total: 1,497.17

Vork Order: 2102440 Meter: Problem: PM Service.	34894		In Date:	03/03/2021	Closed:	03/15/202
Work Completed		Parts Issued			Qı	uantity
- Preventive Maint. Service		22" Wiper Blade				2.00
- Rotate Balanced 4 Tires		Napagold Oil Filter				1.00
- Replaced Worn Decal		Napa Quart 5w20				7.00
- Top Off Rear Diff Fluid		75w140 Ford Axle Lu	ıbe			1.00
- Wash Vehicle		Shop Supplies				1.00
 R&r Tailgate Service Panle To Adjust And Service Latch Close Properly Shop Supplies 		Lobor 101 50	Dorto: 76	74	Totalı	470.04
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 76.			478.21
Vork Order: 2108090 Meter: Problem: Check engine light on Image: Check engine light on	35824		In Date:	07/27/2021	Closed:	08/02/202
Work Completed		Parts Issued			Qı	uantity
Work Completed - Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs.		Parts Issued Shop Supplies			Qı	Jantity 1.00
- Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with la					Qı	-
- Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs.			Parts: 2.6	5		-
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 	test update.test	Shop Supplies	Parts: 2.6 In Date:	5 09/03/2021	Total:	1.00
Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 /ork Order: 2109647 Meter:	comm: 0.00	Shop Supplies			Total: Closed:	1.00
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 Vork Order: 2109647 Problem: PM Service.Lost ignition keys 	comm: 0.00	Shop Supplies Labor: 146.00			Total: Closed:	1.00 148.65 09/24/202
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 York Order: 2109647 Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued			Total: Closed:	1.00 148.65 09/24/202
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 York Order: 2109647 Meter: Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service replaced asset numbers and how's my driving sticker 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued Napa Quart 5w20	In Date:		Total: Closed:	1.00 148.65 09/24/202 Jantity 7.00
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 York Order: 2109647 Meter: Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued Napa Quart 5w20 Napagold Oil Filter	In Date:		Total: Closed:	1.00 148.65 09/24/202 Jantity 7.00 1.00
 Diagnose for check engine light on codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 York Order: 2109647 Meter: Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service replaced asset numbers and how's my driving sticker rotate/balanced 4 tires replace and reprogram all keys. 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concer	In Date:		Total: Closed:	1.00 148.65 09/24/202 Jantity 7.00 1.00 1.00
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 York Order: 2109647 Meter: Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service replaced asset numbers and how's my driving sticker rotate/balanced 4 tires 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concer 22" Wiper Blade	In Date:		Total: Closed:	1.00 148.65 09/24/202 Jantity 7.00 1.00 1.00 2.00
 Diagnose for check engine light on.codes P0130 and P 13-03-05 asper Dtc with Tsb and reprogram Pcm with lat drive vehicle before and after repairs. Shop Supplies Hours: 2.00 Vork Order: 2109647 Meter: Problem: PM Service.Lost ignition keys Work Completed Preventive Maint. Service replaced asset numbers and how's my driving sticker rotate/balanced 4 tires replace and reprogram all keys. 	comm: 0.00	Shop Supplies Labor: 146.00 Parts Issued Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concer 22" Wiper Blade Used Fire X Refurbis	In Date:		Total: Closed:	1.00 148.65 09/24/202 Jantity 7.00 1.00 2.00 1.00

10/24/2022 4:38:45 PM		Palm Beach 10181121		/ Fleet Managem ORD F150 Picku	ent Asset Maintenan ıp, 1/2 Ton	ice History			
Work Order: 220 Problem: PM	3085	Meter: 37483				In Date:	03/22/2022	Closed:	03/24/2022
Work Complete	ed				Parts Issued			Qı	uantity
- Preventive Ma	aint. Service				Napagold Oil Filter				1.00
- Rotate Balanc	ed 4 Tires				Napa Quart 5w20				7.00
- R&r Both Wip	er Arms To Clean O	off Rust And Pain	t Them		22" Wiper Blade				2.00
- Shop Supplies	5				Napagold Air Filter				1.00
					Shop Supplies				1.00
	Hours: 4.00	Comm:	0.00		Labor: 292.00	Parts: 46.	46	Total:	338.46
Nork Order: 220 Problem: Trar	8833 nsition Prep Charge	Meter: 38283				In Date:	08/23/2022	Closed:	08/23/2022
Work Complete	ed								
- Transition Pre	p Charge								
	Hours: 2.00	Comm:	0.00		Labor: 146.00	Parts: 0.0	0	Total:	146.00
Total Hours: 91.05	5 Total L	abor: 5,975.85			Total Comm: 192.0	0	Total Parts	: 3,524.19	