10/24/2022 4:43:44 PM			Paln 1020	n Beach County Fleet Manag 2136 2016 FORD F150 Pic		ice History			
Total Hours: 7	6.90 L	.abor: 5,302	.20	Parts: 4,408.08	Comm: 893.89		Charged	: 10604.17	
Work Order: Problem:		e Delivery Ins	Meter: spection	322		In Date:	12/14/2016	Closed:	12/14/2016
Work Comp	oleted								
- Pre Delive	ery Inspect	ion							
	F	lours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:		9.	Meter:	1336		In Date:	12/30/2016	Closed:	02/13/2017
Work Comp	pleted				Parts Issued			Qı	uantity
- Parts only	(radio sho	p).			Micro Add A Circuit				1.00
-	F	lours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 21.	11	Total:	21.11
Work Order: Problem:		ice.	Meter:	4568		In Date:	06/22/2017	Closed:	06/30/2017
Work Comp	pleted				Parts Issued			Qı	uantity
- P.m. Servi	ce.				5w20 Engine Oil				7.00
- Windshiel	d washer i	nop.diagnos	se and re	place defective washer pump.	Napagold Oil Filter				1.00
- Rotate and	d balance	tires.			Washer Fluid Concer	ntr			1.00
- Shop Sup	plies				Used Fire X Refurbish	hed			1.00
					Washer Pump				1.00
					Shop Supplies				1.00
	F	lours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 66.	95	Total:	306.95

Palm Beach County Fleet Management Asset Maintenance History102021362016 FORD F150 Pickup, 1/2 Ton

Work Order: 1800427 Problem: P.M. service.	Meter:	9846		In Date:	01/11/2018	Closed:	01/19/2018
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			5w20 Engine Oil				6.00
- Rotate and high speed balance all four tires.			Napagold Oil Filter				1.00
- Shop Supplies			22" Wiper Blade				2.00
			Floor Mat-2pc Rub I	Bk			1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 52.	87	Total:	232.87
Nork Order: 1807357 Problem: P.M. service and request new key.	Meter:	15129		In Date:	07/19/2018	Closed:	07/25/201
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter				1.00
- Program new key to vehicle.			5w20 Engine Oil				6.00
- Replace two tires . Rotate and balance all four	r tires . Nit	rogen fill tires.	22" Wiper Blade				2.00
- Complete front end alignment and road test.		U U	Washer Fluid Conce	ntr			1.00
- Shop Supplies			Ford Triton Pvc Swc				1.00
			Used Fire X Refurbis	shed			1.00
			183114470 P245-70	Dr17			2.00
			ford side key				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
Hours: 7.30		Comm: 0.00	Labor: 438.00	Parts: 554	4.90	Total:	992.90
Nork Order: 1812733 Problem: Right rear tire repair.	Meter:	18706		In Date:	12/14/2018	Closed:	12/18/2018
Work Completed			Parts Issued			Qı	uantity
- Repair right rear tire and balance . Nitrofill all.			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00

Nork Order: 1901258 Problem: PM Service, Driver side mirror is de	Meter: etached.	19576		In Date:	02/01/2019	Closed:	02/20/2019
Work Completed			Parts Issued			Qu	uantity
- P.m. service.			Napagold Oil Filter	r			1.00
- Replace two tires . Rotate and high speed ba	lance all fo	ur tires . Nitrogen	5w20 Engine Oil				6.00
fill all.		-	Washer Fluid Conc	entr			1.00
- Test and replace right rear turn signal bulb .			22" Wiper Blade				2.00
- Resurface rear brake rotors and service calipe	ers . Replac	e brake pads and	Used Fire X Refurb	ished			1.00
flush and bleed brake system . Test drive .			245/70/17 Tire Mic	ch			2.00
- Replace broken left outside mirror assembly.			Boxed Miniatures				1.00
- Shop Supplies			lube				1.00
			Brake Pad				1.00
			Mirror				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
Hours: 9.00		Comm: 0.00	Labor: 603.00	Parts: 797	7.26	Total:	1,400.26
Vork Order: 1903121 Problem: Damage to right rear fender	Meter:	19726		In Date:	02/14/2019	Closed:	03/21/201
Work Completed							
- Damage to right rear fender							
Hours: 0.00		Comm: 580.56	Labor: 0.00	Parts: 0.0	0	Total:	580.56
Work Order:1906377Problem:Flat tire on Rear drivers' side tire.	Meter:	21813		In Date:	06/17/2019	Closed:	06/18/2019
Work Completed							
- Tire Service Dubois Park – 19075 Dubois Rd, Rear drivers' side tire.	Jupiter, Fl 3	33477 - Flat tire on					
Hours: 0.00		Comm: 70.25	Labor: 0.00	Parts: 0.0	0	Total:	70.25

10/24/2022 4:43:45 PM

Palm Beach County Fleet Management Asset Maintenance History102021362016 FORD F150 Pickup, 1/2 Ton

Work Com								
	npleted			Parts Issued			Qı	antity
- Replace	right front tire.repair left rear abd bal	ance both	l.	183114470 P245-70	r17			1.00
- Shop Su				Shop Supplies				1.00
				Tire Disposal Fee				1.00
	Hours: 1.50		Comm: 0.00	Labor: 100.50	Parts: 201	.38	Total:	301.88
Work Order: Problem:	1908562 P.M. service and airbag light on .	Meter:	23288		In Date:	08/15/2019	Closed:	08/28/2019
Work Con	npleted			Parts Issued			Qı	antity
- P.m. serv	vice.			Napagold Oil Filter				1.00
- Charge b	pattery fully . Test battery and chargin	g system	. Battery failed load	5w20 Engine Oil				7.00
test . R&r o	defective battery .			22" Wiper Blade				2.00
- Replace	broken glove box stop .			Washer Fluid Concen	ıtr			1.00
•	er diagnose complaint . Scan for code		•	Ford Triton Pvc Swc				1.00
	mal operation . Passager off light on t	till seat oc	cupied .	Battry Motorcraft				1.00
	nd balance all four tires . Nitrofill all.			Retainer Glove				1.00
- Shop Su	pplies			Shop Supplies				1.00
	Hours: 5.10		Comm: 0.00	Labor: 341.70	Parts: 261	.38	Total:	603.08
Work Order: Problem:	1909449 Flat tire on Passenger Front tire	Meter:	23502		In Date:	07/25/2019	Closed:	09/13/2019
Work Con	pleted							
- Tire Serv	ice Loggerhead Park - Flat tire on Pas	senger Fr	ont tire					
	Hours: 0.00		Comm: 70.25	Labor: 0.00	Parts: 0.0	C	Total:	70.25
Work Order: Problem:	1911325 Flat tire on F/D (Change out)	Meter:	24779		In Date:	10/29/2019	Closed:	10/31/2019
Work Con	pleted							
- Tow From	m: loggerhead park-14200 Us hwy 1, .	Juno bead	:h Fl					
	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	C	Total:	0.00

10/24/2022 4:43:45 PM			nty Fleet Manage 6 FORD F150 Pic	ment Asset Maintena kup, 1/2 Ton	nce History			
Nork Order:	1913223	Meter:	26194		In Date:	12/29/2019	Closed:	01/02/2020
Problem:	corrected from old inv#2	20-140955 from 117.0	00 to 64.03					
Work Com	pleted							
	ce Loggerhead Park - Fla from old inv#20-140955							
	Hours: 0.00		Comm: 76.84	Labor: 0.00	Parts: 0.0	0	Total:	76.84
Nork Order: Problem:		Meter:	26194		In Date:	01/02/2020	Closed:	01/06/2020
Work Com	pleted			Parts Issued			Qı	uantity
- parts only	y			Lt245/70r17 Fstone	Transforce H	l/t2 10p		1.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				1.00
	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 143	3.47	Total:	143.47
Nork Order: Problem:	2000177 Tire light on . spare on v		26419		In Date:	01/07/2020	Closed:	01/08/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Repair let	ft front tire and balance	. Nitrofill all.		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0		Total:	

10/24/2022	
4:43:45 PM	

Palm Beach County Fleet Management Asset Maintenance History102021362016 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	2002861 PM Service	Meter:	27998		In Date:	03/20/2020	Closed:	03/30/2020
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			Napagold Oil Filte	r			1.00
- Replace o	cabin air filter and clean fresh a	air intake .		5w20 Engine Oil				6.00
- Repair le	ft rear tire and replace two wo	rn tires . Balance	and nitrofill all	22" Wiper Blade				2.00
four tires .				Mac Wite Lithium	Gres			1.00
- Perform	complete front end alignment	and road test .		Used Fire X Refurb	ished			1.00
- Shop Sup	oplies			Ford Triton Pvc Sw	C			1.00
				Cabin Air Filter				1.00
				245/70/17 Tire Mid	ch			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 554	4.81	Total:	1,065.81
/ork Order: Problem:	2005190 Drivers side rear tire.	Meter:	29154		In Date:	05/22/2020	Closed:	05/27/2020
Work Com	pleted			Parts Issued			Qu	uantity
- Repair le	ft rear tire and balance . Nitrof	ill all.		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00

Work Order: 2008975	Meter: 31750		In Date: 09/08/2020	Closed:	09/30/2020
Problem: P.M. service , recalls 17S33 , 18S2	27 and towed in for coolant lea	k .			
Work Completed		Parts Issued		Q	uantity
- P.m. service.		Napagold Oil Filter			1.00
- Replace cabin air filter and clean fresh air int	ake .	5w20 Engine Oil			6.00
- Rotate and balance all four tires . Nitrofill all	and reset Tpms .	22" Wiper Blade			2.00
- Top off coolant and pressure test and inspec	t . Hook up Ids to scan for	Washer Fluid Conce	entr		1.00
codes and test fan operation . Road test for ter	n miles . Could not dupicate at	Cabin Filter			1.00
this time .		Purge Valve			1.00
- Computer diagnose check engine light , code evap test . R&r defective stuck open purge valv		Shop Supplies			1.00
- Transport to and from dealer for recalls 17s3	3 and 18s27 .				
- Shop Supplies					
Hours: 8.00	Comm: 0.00	Labor: 584.00	Parts: 112.39	Total:	696.39
Work Order: 2009003 Problem: Pump failer, Liquid sprayed everyv	Meter: 31748 vhere		In Date: 09/05/2020	Closed:	09/08/2020
Work Completed					
- Tow From: Burt Reynalds Park-east Side To:	Lv shop				
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	Total:	96.00

Palm Beach County Fleet Management Asset Maintenance History 10202136 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2103616 Meter: 35949 03/30/2021 Closed: 04/08/2021 In Date: Problem: P.M. service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 6.00 - Check all. R & I two new tires on front, rotate and speed balance all ,nitro fill 22" Wiper Blade 2.00 - Check brakes, R & I front and rear brakes, Resurface all four rotors, service Washer Fluid Concentr 1.00 caliper slide pins, bleed brakes and road test Mac Wite Lithium Gres 1.00 - Pressure test cooling system leaking water pump, R & I new water pump Used Fire X Refurbished 1.00 asm, R & I new thermostat asm and o ring, flush cooling system 245/70/17 Tire Mich 2.00 - Perform complete front end alignment, road test Non-chlor Brake Clnr 1.00 - Shop Supplies 1.00 Brk Fluid Dot 4-12oz Brake Pad 1.00 Brake Pad 1.00 Anti Freeze Motorcraft 2.00 Gasket 1.00 **Tmermostat Housing** 1.00 Water Pump 1.00 Shop Supplies 1.00 2.00 **Tire Disposal Fee** Comm: 0.00 Hours: 18.50 Labor: 1,350.50 Parts: 1,318.66 Total: 2,669.16 Work Order: 2105639 Meter: 37058 05/21/2021 Closed: 05/24/2021 In Date: Problem: Battery Died. Had to be jumped to start. Will bring in 05.21.21 Parts Issued Work Completed Quantity Battry Motorcraft 1.00 - Batterycheck battery, charging system, after fully charge it fails load test, replaced defective battery and reset bms Shop Supplies 1.00 - Shop Supplies

Comm: 0.00

Labor: 109.50 Parts: 192.82

Total: 302.32

Vork Order: Problem:	2111135 PM Service.	Meter:	40430		In Date:	10/15/2021	Closed:	10/26/2021
Work Com	pleted			Parts Issued			Qı	antity
- Preventiv	e Maint. Service			22" Wiper Blade				2.00
- rotate an	d balance al 4 tires ni	tro fill all		5w20 Engine Oil				6.00
- Shop Sup	oplies			Napagold Oil Filter				1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 25.	82	Total:	244.82
Vork Order: Problem:		Meter: nt out, cam	41541 he back on but the radio is not wor	king	In Date:	12/08/2021	Closed:	12/13/2021
							0	
Work Com	pleted			Parts Issued			Q	antity
- Diagnose Reset Batte Inoperation	e Dash Lites And Radio ry Monitor System Ar n Following Tsb Ssm 4	nd Reprogr	n Tool For Codes But No Codes. am Fcim Due To Intermittent st And Ok At This Time.	Parts Issued Shop Supplies			Q	1.00
- Diagnose Reset Batte	e Dash Lites And Radio ry Monitor System Ar n Following Tsb Ssm 4	id Reprogr 7045. Rete	am Fcim Due To Intermittent		Parts: 2.6	5		-
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order:	e Dash Lites And Radio ry Monitor System Ar Following Tsb Ssm 4 oplies Hours: 1.50	nd Reprogr 7045. Rete Meter:	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784	Shop Supplies	Parts: 2.6 In Date:	5 02/03/2022	Total:	1.00
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order:	2 Dash Lites And Radio ry Monitor System Ar Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h	nd Reprogr 7045. Rete Meter:	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784	Shop Supplies			Total: Closed:	1.00
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order: Problem: Work Com	e Dash Lites And Radio ry Monitor System Ar Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted	nd Reprogr 7045. Rete Meter: nas nail in i	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784 t	Shop Supplies			Total: Closed:	1.00 112.15 02/08/2022
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order: Problem: Work Com - Replace r	e Dash Lites And Radio ry Monitor System Ar of Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted ight rear tire , due to	nd Reprogr 7045. Rete Meter: nas nail in i	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784	Shop Supplies Labor: 109.50 Parts Issued			Total: Closed:	1.00 112.15 02/08/2022
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order: Problem: Work Com	e Dash Lites And Radio ry Monitor System Ar of Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted ight rear tire , due to	nd Reprogr 7045. Rete Meter: n as nail in i sidewall da	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784 t	Shop Supplies Labor: 109.50 Parts Issued Shop Supplies		02/03/2022	Total: Closed: Qu	1.00 112.15 02/08/2022 uantity 1.00
 Diagnose Reset Batte Inoperation Shop Sup Vork Order: Problem: Work Com Replace r Shop Sup Vork Order: 	e Dash Lites And Radio ry Monitor System Ar of Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted right rear tire , due to oplies Hours: 0.50	nd Reprogr 7045. Rete Meter: nas nail in i sidewall da Meter:	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784 t amage, balance and nitro service Comm: 0.00	Shop Supplies Labor: 109.50 Parts Issued Shop Supplies Lt245/75r17 Tire	In Date:	02/03/2022	Total: Closed: Qu Total:	1.00 112.15 02/08/2022 Jantity 1.00 1.00
 Diagnose Reset Batte Inoperation Shop Sup Vork Order: Problem: Work Com Replace r Shop Sup Vork Order: 	e Dash Lites And Radio ry Monitor System Ar o Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted ight rear tire , due to oplies Hours: 0.50 2206894 Transition Prep Char	nd Reprogr 7045. Rete Meter: nas nail in i sidewall da Meter:	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784 t amage, balance and nitro service Comm: 0.00	Shop Supplies Labor: 109.50 Parts Issued Shop Supplies Lt245/75r17 Tire	In Date: Parts: 90.	02/03/2022	Total: Closed: Qu Total:	1.00 112.15 02/08/2022 uantity 1.00 1.00 127.14
- Diagnose Reset Batte Inoperation - Shop Sup Vork Order: Problem: - Replace r - Shop Sup Vork Order: Problem: Work Com	e Dash Lites And Radio ry Monitor System Ar o Following Tsb Ssm 4 oplies Hours: 1.50 2201262 rear passenger tire h pleted ight rear tire , due to oplies Hours: 0.50 2206894 Transition Prep Char	nd Reprogr 7045. Rete Meter: nas nail in i sidewall da Meter:	am Fcim Due To Intermittent st And Ok At This Time. Comm: 0.00 42784 t amage, balance and nitro service Comm: 0.00	Shop Supplies Labor: 109.50 Parts Issued Shop Supplies Lt245/75r17 Tire	In Date: Parts: 90.	02/03/2022	Total: Closed: Qu Total:	1.00 112.15 02/08/2022 uantity 1.00 1.00 127.14