Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Total Hours: 114.50 Labor: 7,920.70 Parts: 6,490.43 Comm: 166.25 Charged: 14577.38

Work Order: 1700649 Meter: 326 In Date: 01/23/2017 Closed: 01/23/2017

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1703349 Meter: 4503 In Date: 04/04/2017 Closed: 04/28/2017

Problem: Install DMI unit

Work Completed		Parts Issued		Quantity
- Install new D.m.i unit in truck and ro	n truck and route cable behind center stereo control			7.00
unit.r & R 6 pin round trailer socket du	Napagold Oil Filte	r	1.00	
- P.m. service.		Used Fire X Refurb	oished	1.00
- Replace broken glove box stop asser	mbly with new.(defective part)	trailer plug		1.00
- Rotate and balance four tires.	Strbrt Liq Elec Tap	1.00		
- Shop Supplies		Washer Fluid Con-	1.00	
		Gloved Box Stop Rac 1 Obdk Distance		1.00
				1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 8.25	Comm: 0.00	Labor: 495.00	Parts: 1,556.55	Total: 2,051.55

Work Order: 1708043 Meter: 11160 In Date: 08/16/2017 Closed: 08/24/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity		
- P.m. service.	- P.m. service.			7.00		
- Rotate and high speed balance all four tires.		Napagold Oil Filter		1.00		
- Shop Supplies		Used Fire X Refurbi	ished	1.00		
		Washer Fluid Conce	entr	1.00		
		Stg Wheel Cov - Fo	ord	1.00		
		Shop Supplies		1.00		
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 52.96	Total: 277.96		

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 17127 Problem: P.M.		Meter:	17432		In Date:	12/27/2017	Closed:	12/30/2017
Work Completed	i			Parts Issued			Qı	uantity
- P.m. service.				5w20 Engine Oil				6.00
- Rotate and high	n speed balance all four tires.			Napagold Oil Filter				1.00
- Shop Supplies	·			22" Wiper Blade				2.00
				Mac Wite Lithium Gr	es			1.00
				Napagold Air Filter				1.00
				Shop Supplies				1.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 39.	.62	Total:	264.62
Work Order: 18049 Problem: P.M.	985 service and right front going	Meter: flat.	24964		In Date:	05/14/2018	Closed:	05/21/2018
Work Completed	d			Parts Issued			Qı	uantity
- P.m. service.				Napagold Oil Filter				1.00
- Charge battery	fully .load test battery .failed	load test .r	&r defective	5w20 Engine Oil				7.00
battery .test charg	ging system ,ok.			22" Wiper Blade				2.00
- Balance and rot	tate all four tires. Nitrofill and	reset Tpm:	S.	Washer Fluid Concer	ntr			1.00
- Shop Supplies				Used Fire X Refurbis	hed			1.00
				Battry Motorcraft				1.00
				Shop Supplies				1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 216	6.73	Total:	501.73
Work Order: 18068 Problem: Right	522 front tire going flat.	Meter:	27306		In Date:	06/26/2018	Closed:	06/28/2018
Work Completed	d			Parts Issued			Qı	uantity
- Repair right fro	nt tire and balance .nitrogen	fill tires.		Shop Supplies				1.00
- Shop Supplies	J							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: Problem:	1809939 P.M. service.	Meter:	32353		In Date:	09/26/2018	Closed:	10/04/2018
Work Com	pleted			Parts Issued			Qı	ıantity
- P.m. serv	ice.			22" Wiper Blade				2.00
- Replace t	two tires. Balance and rotate al	l four tires. Nitro	fill.	Napagold Oil Filter				1.00
- Complete	e front end alignment. Road te	est.		5w20 Engine Oil				6.00
- Shop Sup	oplies			265 / 70 / 17 SI / Tii	re Gdy			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 7.25		Comm: 0.00	Labor: 485.75	Parts: 529	9.90	Total:	1,015.65
Work Order: Problem:	1811748 Left rear tire going flat.	Meter:	34552		In Date:	11/15/2018	Closed:	11/19/2018
Work Com	pleted			Parts Issued			Qı	ıantity
- Repair le	ft rear tire and balance . Nitrof	ill all.		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00
Work Order: Problem:	1812896 service call	Meter:	36247		In Date:	12/17/2018	Closed:	12/19/2018
Work Com	pleted							
- Tire Servi	ice 7301 Truck and Trailer way	off Southern Blv	d - service call					
	Hours: 0.00		Comm: 70.25	Labor: 0.00	Parts: 0.0	0	Total:	70.25
Work Order: Problem:	1812969 Right rear tire flat.	Meter:	36480		In Date:	12/21/2018	Closed:	12/26/2018
Work Com	pleted			Parts Issued			Qı	ıantity
- Repair ric	ght rear tire and balance . Nitro	gen fill tires.		Shop Supplies				1.00
- Shop Sup	oplies	-						
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1902031 Meter: 39497 In Date: 02/22/2019 Closed: 03/04/2019

Problem: P.M. service and vibration at highway speeds .

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Inspect brakes . Resurface both front rotors and service calipers . Replace	5w20 Engine Oil	7.00
fronrt brake pads .flush and bleed system . Road test .	Used Fire X Refurbished	1.00
- Inspect all tire . Replace two tires . Rotate and high speed balance all four	22" Wiper Blade	2.00
tires . Nitrofill all .	Washer Fluid Concentr	1.00
- Shop Supplies	265 70 R17 Tire	2.00
	Non-chlor Brake Clnr	1.00
	Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 8.75 Comm: 0.00	Labor: 586.25 Parts:	590.55 Total: 1,176.80

Work Order: 1907479 Meter: 46914 In Date: 07/19/2019 Closed: 07/25/2019

Problem: P.M. service.

Work Completed		Parts Issued	Quantity	
- P.m. service.		5w20 Engine Oil		7.00
- Replace brokem glove box stop .	Napagold Oil Filte	er	1.00	
- Rotate and balance all four tires . Nitrofill all.		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Con-	centr	1.00
		Retainer Glove		1.00
		Shop Supplies		1.00
Hours: 4.05	Comm: 0.00	Labor: 271.35	Parts: 63.71	Total: 335.06

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2000014 Meter: 54497 In Date: 01/02/2020 Closed: 01/13/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace broken left tail light lens and mount strobe b	bulb .	5w20 Engine Oil		6.00
- Resurface both front rotors and service calipers . Rep	olace brake pads .	Napagold Air Filte	er	1.00
Flush and bleed brake system . Road test .		Used Fire X Refurb	ished	1.00
- Rotate and high speed balance all four tires . Nitrofill	22" Wiper Blade	2.00		
- Remove left seat assembly to remove lowwer seat co	2pc Hd Mat Set Blk		1.00	
defective seat cushion .		Brk Fluid Dot 4-32oz Non-chlor Brake Clnr Brake Pad Brake Pad Pad Seat		1.00
- Shop Supplies				1.00
				1.00
				1.00
				1.00
		Lamp Assy		1.00
		Shop Supplies		1.00
Hours: 10.75	Comm: 0.00	Labor: 784.75	Parts: 444.03	Total: 1,228.7

Work Order: 2002524 Meter: 58376 In Date: 03/12/2020 Closed: 03/17/2020

Problem: Left rear tire going flat .

Work Completed		Parts Issued		Quantity
- Repair Left rear tire and balance . Nitrofill all.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00

- Shop Supplies

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: Problem:	2003900 Left rear tire flat .P.M. service, reca		60432		In Date:	04/20/2020	Closed:	05/05/2020
Work Com	·			Parts Issued			Oı	uantity
- P.m. serv	•			Napagold Oil Filter				1.00
	pattery fully . Test battery and charging	na system	Rattery failed load	5w20 Engine Oil				6.00
	defective battery. Hook up Ids to res	0 ,	. Dattery failed load	22" Wiper Blade				2.00
- Repair le	ft rear tire . Rotate and balance all fo	ur tires . N	litrofill all.	Battry Motorcraft				1.00
- Transpor	t to and from dealer for recall 17s33			Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 8.25		Comm: 0.00	Labor: 602.25	Parts: 208	3.57	Total:	810.82
Work Order:	2004023	Meter:	60106		In Date:	04/20/2020	Closed:	04/22/2020
Problem:	Flat Tire on L/R							
Work Com	pleted							
- Tow Fron	n: Sr7 South of Saturnia Isle							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	2006615 Left rear tire going flat .	Meter:	63555		In Date:	07/06/2020	Closed:	07/07/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Repair le	ft rear tire and balance . nitrofill all.			Shop Supplies				1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2008899 Meter: 67402 In Date: 09/03/2020 Closed: 09/15/2020

Problem: P.M. service, wipers noisey and pulls to the left.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Clean fresh air intake and replace cabin air filter .	5w20 Engine Oil	6.00
- Inspect and service transfer case . Drain and refill .	Used Fire X Refurbished	1.00
- Inspect and service transmission . Replace filter and flush and refill .	22" Wiper Blade	2.00
- Rotate and high speed balance all four tires . Nitrofill all.	Cabin Air Filter	1.00
- Perform complete front end alignment to correct pulling condition . Road	oil auto	2.00
test.	Tram Filter	1.00
- Shop Supplies	oil auto	16.00
	Shop Supplies	1.00
Hours: 10.25 Comm: 0.00	Labor: 748.25 Parts: 241.6	6 Total: 989.91

Work Order: 2102464 Meter: 76931 In Date: 03/04/2021 Closed: 03/11/2021

Problem: P.M. service.

Work Completed		Parts Issued	Quantity	
- Preventive Maint. Service		Napagold Oil Filte	1.00	
- Inspect and replace four new on front , speed balance	5w20 Engine Oil		6.00	
- Perform complete alignment, road test		Washer Fluid Cond	1.00	
- Shop Supplies		22" Wiper Blade		2.00
		265/70/17 Tire Grappler		4.00
		Shop Supplies	1.00	
		Tire Disposal Fee	4.00	
Hours: 7.25	Comm: 0.00	Labor: 529.25	Parts: 1,013.70	Total: 1,542.95

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2107578 Meter: 85450 In Date: 07/13/2021 Closed: 07/19/2021

Problem: PM Service.

Work Completed		Parts Issued	Quantity	
- Preventive Maint. Service	22" Wiper Blade		2.00	
- Rotated and balanced all 4 tires. Nitrogen filled a	Napagold Oil Filte	r	1.00	
- Shop Supplies	5w20 Engine Oil Used Fire X Refurbished		6.00	
			1.00	
		Napagold Air Filter		1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 40.69	Total: 314.44

Work Order: 2112386 Meter: 92439 In Date: 11/19/2021 Closed: 11/30/2021

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	22" Wiper Blade	2.00
 Rotate and speed balance, nitro fill all Check and replace cabin filter and clean fresh air intake. Check circuit to strobe light switch, R & I new switch 	Washer Fluid Concentr	1.00
	Filter	1.00
	Cabin Filter	1.00
 Check all brakes, R & I front and rear brakes, Resurface all rotors, R & I Refurbish front calipers, service caliper slide pins, Flush brake system, road test Check Rusty side step, R & I New side steps Rusty Shop Supplies 	Universal Switch	1.00
	ad Non-chlor Brake Clnr	1.00
	Brk Fluid Dot 4-32oz	1.00
	Reman/ca	3.00
	Reman/ca	1.00
	Brake Pad	1.00
	Brake Pad	1.00
	Step Assy	1.00
	Step Assy	1.00
	5w20 Engine Oil	6.00
	Shop Supplies	1.00
Hours: 14.25 Comm: 0.00	Labor: 1,040.25 Parts: 1,367.07	Total: 2,407.32

Palm Beach County Fleet Management Asset Maintenance History 10202402 2017 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2204971 Meter: 102201 In Date: 05/09/2022 Closed: 05/12/2022

Problem: PM Service and left front running light out .

Work Completed	Parts Issued	Qı	uantity
- Preventive Maint. Service	Napagold Oil Filter		1.00
- Rotate and speed balance, nitro fill	5w20 Engine Oil		6.00
- Diagnose engine misfire . Perform engine tune/up replace all six spark	Washer Fluid Concentr		1.00
plugs . Retest	22" Wiper Blade		2.00
- Perform Injector cleaning, Perform engine decarb	Used Fire X Refurbished	d	1.00
- Check circuit to left side turn signal inop. R & I new bulb	Spark Plug		6.00
- Shop Supplies	Motor Tune-up 16oz		1.00
	Throttle Body Cleaner		1.00
	Intake Cleaner Kit		1.00
	Boxed Miniatures		1.00
	Shop Supplies		1.00
Hours: 10.45 Comm: 0.00	Labor: 762.85	Parts: 108.72 Total:	871.57

Work Order: 2207868 Meter: 105472 In Date: 07/28/2022 Closed: 07/28/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 114.50 Total Labor: 7,920.70 Total Comm: 166.25 Total Parts: 6,490.43