	Laban 40 470 40	Dorto: 40.040.00	Comm. 4.404.04						
Fotal Hours: 190.90 Labor: 12,472.10 Parts: 12,949.8		Parts: 12,949.88	Comm: 1,431.84		Charged: 26853.82				
Nork Order: 120671 Problem: 1061 -	2 Me Pre Delivery Inspec	ter: 315 tion		In Date:	07/18/2012 Closed:	07/18/2012			
Work Completed									
- Pre Delivery Inspe	ection								
	Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 0.0	00 Total:	240.00			
Nork Order: 130150 Problem: Pm ser		ter: 5219		In Date:	02/12/2013 Closed:	02/27/2013			
Work Completed			Parts Issued		Q	uantity			
- P.m. Service.			5w20 Engine Oil			7.00			
- Replace broken r	oof mounted marke	er light.	1372 Oil Filter			1.00			
- Rotate and balan	ce all tires		Wd40 Spray Lube S	tock		1.00			
- Shop Supplies			Lamp			1.00			
			Washer Fl			1.00			
			Shop Supplies			1.00			
	Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 61	.18 Total:	451.18			
Nork Order: 130849 Problem: P.M. se		ter: 9842		In Date:	08/22/2013 Closed:	09/20/2013			
Work Completed			Parts Issued		Q	uantity			
- P.m. Service.			5w20 Engine Oil			7.00			
- Replace two clea	rance lamp on right	side of utility bed.	Napagold Oil Filter			1.00			
- Rotate and balan	ce all six tires.		Used Fire X Refurbis	shed		1.00			
- Complete wheel	alignment.test drive		Floor Mat-2pc Rub	Bk		1.00			
- Shop Supplies			Marker Lamp			1.00			
			Grommet Mount Ki	t		1.00			
			Shop Supplies			1.00			
	Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 89	.80 Total:	599.80			

Palm Beach County Fleet Management Asset Maintenance History 10186231 2012 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1402501 Meter: 13889 03/14/2014 **Closed:** 04/07/2014 In Date: Problem: P.m. service. **Work Completed** Parts Issued Quantity 5w20 Engine Oil 8.00 - P.m. Service. Napagold Oil Filter 1.00 - Replace and balance six new tires. Wiper Blade 2.00 - Replace left side clearance lamps.fabricate and rewire both. Brake Cleaner 1.00 - Shop Supplies Washer Fluid Concentr 1.00 Napagold Air Filter 1.00 179636492 Lt245-75r17 6.00 Tr416 Valve Stem 6.00 Grommet Mount Kit 1.00 Marker Lamp 1.00 Shop Supplies 1.00 Tire Disposal Fee 6.00 Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 1,561.51 Total: 2,041.51 02/05/2015 **Closed:** 02/19/2015 Work Order: 1501381 Meter: 21469 In Date: Problem: Pm service. **Work Completed** Parts Issued Quantity 5w20 Engine Oil 8.00 - Pm service. Napagold Oil Filter 1.00 - Rotate and balance all six tires. Wiper Blade 2.00 - Perform complete front end alignment. - Shop Supplies Pintle Pin W/chain 1.00 Washer Fluid Concentr 1.00 Used Fire X Refurbished 1.00 Shop Supplies 1.00 Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 57.25 Total: 537.25

rk Order: 1508569 Problem: Pm service.	Mete	r: 26187		In Date:	08/26/2015 Closed:	09/11/2015		
Work Completed			Parts Issued		q	uantity		
- Pm service.			5w20 Engine Oil			7.00		
 Test battery and charging system.battery failed load test after recharge.replace defective battery. Replace two tires.rotate and balance all six. 		Napagold Oil Filter			1.00			
		Wiper Blade			2.00			
		Battery			1.00			
- Shop Supplies			179636492 Lt245-75	r17		2.00		
			Battery 65			1.00		
			Shop Supplies			1.00		
			Tire Disposal Fee			2.00		
Hours: 7.	50	Comm: 0.00	Labor: 450.00	Parts: 817	.26 Total	: 1,267.26		
rk Order: 1604758 Problem: P.M. Service.	Mete	er: 32526		In Date:	05/05/2016 Closed:	05/19/2016		
rk Order: 1604758 Problem: P.M. Service. Work Completed	Mete	r: 32526	Parts Issued	In Date:		05/19/2016 wantity		
Problem: P.M. Service.	Mete	r: 32526	Parts Issued 5w20 Engine Oil	In Date:				
Problem: P.M. Service. Work Completed - P.m. Service.				In Date:		uantity		
Problem: P.M. Service. Work Completed	s,replace rear brake pads.		5w20 Engine Oil	In Date:		uantity 7.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors	s,replace rear brake pads. n.		5w20 Engine Oil Napagold Oil Filter	In Date:		uantity 7.00 1.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade	In Date:		7.00 1.00 2.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights,	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter	In Date:		uantity 7.00 1.00 2.00 1.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights, - Replace four tires,rotate and	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter Rear Pads			uantity 7.00 1.00 2.00 1.00 1.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights, - Replace four tires,rotate and	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter Rear Pads B U 6 Dio Grmt Kit			Auantity 7.00 1.00 2.00 1.00 2.00 2.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights, - Replace four tires,rotate and	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter Rear Pads B U 6 Dio Grmt Kit 179636492 Lt245-75	r17		Quantity 7.00 1.00 2.00 1.00 2.00 4.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights, - Replace four tires,rotate and	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter Rear Pads B U 6 Dio Grmt Kit 179636492 Lt245-750 Brake Pad	r17		Provide 7.00 1.00 2.00 1.00 2.00 4.00 1.00		
Problem: P.M. Service. Work Completed - P.m. Service. - Resurface rear brake 5rotors calipers.flush and bleed system - Replace both back up lights, - Replace four tires,rotate and	s,replace rear brake pads. n. ,had water in them.		5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Napagold Air Filter Rear Pads B U 6 Dio Grmt Kit 179636492 Lt245-75 Brake Pad Used Fire X Refurbish	r17		Provide 7.00 1.00 2.00 1.00 2.00 4.00 1.00 1.00		

Work Order: 1612782 Meter: 37578 12/14/2016 Closed: 01/02/2017 In Date: Problem: P.M. service. Parts Issued Quantity **Work Completed** 5w20 Engine Oil 7.00 - P.m. Service. 1.00 Napagold Oil Filter - Replace two tires, rotate and balance all four. 20" Wiper Blade 2.00 - Complete wheel alignment.test drive. Used Fire X Refurbished 1.00 - Shop Supplies Pintle Pin W/clip 1.00 179636492 Lt245-75r17 2.00 Tr416 Valve Stem 2.00 1.00 Stg Wheel Cov - Ford Shop Supplies 1.00 Tire Disposal Fee 2.00 Hours: 8.50 Comm: 0.00 Labor: 510.00 Parts: 569.51 Total: 1.079.51 Work Order: 1707613 Meter: 42942 08/03/2017 Closed: 08/22/2017 In Date: Problem: P.M. service. Parts Issued Quantity Work Completed 2.00 Caster-camber Bushing - P.m. Service. 5w20 Engine Oil 7.00 - Test battery and charging system.replace bad battery. Napagold Oil Filter 1.00 - Replace and rewire corroded trailer plug. Used Fire X Refurbished 1.00 - Replace for tires, rotate and balance all six. 22" Wiper Blade 2.00 - Flush and refill transmission system. Battery 1.00 - Shop Supplies 1.00 trailer plug 179636492 Lt245-75r17 4.00

Tr416 Valve Stem

Shop Supplies

Labor: 645.00

Tire Disposal Fee

Syn-atf Trans Fluid S

Parts: 1.361.98

4.00

16.00

1.00

4.00

Total: 2,006.98

Nork Order: 1802624 Problem: PM Service, Right & left side cabi	Meter: 47770 net doors have trouble openir	ng and closing.	In Date:	03/09/2018	Closed:	03/15/2018	
Work Completed		Parts Issued			Q	uantity	
- P.m. service. Replace both washer nozzles.		Washer Nozzle				2.00	
- Inspect all brakes .r&i front brake pads .serv	ice both front calipers and	5w20 Engine Oil	5w20 Engine Oil			7.00	
resurface both front rotors.bleed brakes and r	oad test.	Napagold Oil Filte	er		1.00 2.00		
- Inspect trailer plug and wiring inop.r&i new	rtrailer plug connector .retest	. 22" Wiper Blade					
- Check and align and adjust both side utilty	n Washer Fluid Con	centr		1.00 1.00			
doors .replace missing pintle pin.	Brake Pads						
 Check and replace two worn tires on front .r all six wheels.nitrofill all. 	^{ce} Non-chlor Brake (Non-chlor Brake Clnr			1.00		
- Shop Supplies	brake fluid			1.00			
- Shop Supplies		trailer plug				1.00	
		Pintle Pin W/clip				1.00	
		179636492 Lt245-	75r17			2.00	
		Shop Supplies				1.00	
		Tire Disposal Fee				2.00	
Hours: 13.25	Comm: 0.00	Labor: 795.00	Parts: 591	.53	Total:	1,386.53	
/ork Order: 1807116 Problem: Towed in for no start.	Meter: 50872		In Date:	07/12/2018	Closed:	07/18/201	
Work Completed		Parts Issued			Q	uantity	
- Perform battery charging and load analying	test .battery failed test with	Battery				1.00	
bad cell .r&r defective battery.	,	Shop Supplies				1.00	
- Shop Supplies							
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 130).64	Total:	190.64	
Vork Order: 1807129 Problem: wont run	Meter: 50860		In Date:	07/12/2018	Closed:	07/12/201	
Work Completed							
- Tow From: bert winters park To: vista							
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00	

Palm Beach County Fleet Management Asset Maintenance History 10186231 2012 FORD F350 Utility Body, 1 Ton, Gas

Work Order: 1809714 Meter: 52647 09/20/2018 **Closed:** 10/04/2018 In Date: Problem: P.M. Service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - P.m. service. 5w20 Engine Oil 7.00 - Replace two tires and rotate and high speed balance all six wheels . Nitrofill all. 22" Wiper Blade 2.00 - A/c performance test . Leak test . Replace seal on liquid line at condensor . Washer Fluid Concentr 1.00 Recover , evacuate and full recharge to factory spec . Retest. Used Fire X Refurbished 1.00 - Perform complete front end alignment. Road test. 179636492 Lt245-75r17 2.00 - Shop Supplies Freon Lv Shop 1 2.00 A/c Seal Kit 1.00 Over Flow Hose 1.00 Shop Supplies 1.00 Tire Disposal Fee 2.00 Hours: 12.00 Comm: 0.00 Labor: 804.00 Parts: 549.70 Total: 1,353.70 Work Order: 1901340 Meter: 55653 In Date: 02/04/2019 **Closed:** 02/14/2019

Problem: Check engine light on and A/C blows warm .

Work Completed

- Computer diagnose check engine light ,code P0455 .perform evap test . R&r stuck open purge valve . Clear codes and retest.

- A/c performance test . Leak test . Recover freon . Replace leaking evaporator core . Evcuate system and complete filler to factory spec. .retest A/c performance .

- Shop Supplies

Hours: 12.10

Comm: 0.00

Quantity Parts Issued Purge Valve 1.00 E8 A/c Oil Univ W Dye 1.00 Freon Lv Shop 1 2.00 **Evaporator Core** 1.00 Valve Asy 1.00 Shop Supplies 1.00 Labor: 810.70 Parts: 424.22 Total: 1,234.92 **Meter:** 57405

Work Order: 1904336

In Date: 04/22/2019 Closed: 04/29/2019

Problem: P.M. service and towed in diesal poured in gas tank .

Work Completed		Parts Issued	Quantity			
- P.m. service.		Napagold Oil Filter			1.00	
- Test and replace clearance light bulb .		5w20 Engine Oil			7.00	
- Replace four tires . Balance and rotate all six tire	es . Nitrofill all .	22" Wiper Blade			2.00	
- Computer diagnose misfire . Replace all sixteen	spark plugs and wires .	Boxed Miniatures			1.00	
Clear codes and retest .	ear codes and retest .				4.00	
- Perform complete air intake decarb and cleanin	g . Flush injectors .	Tr416 Valve Stem			4.00	
- Check and replace all six cab body mounts . tim	Spark Plug			16.00		
- Inspect and test fuel sample ,found to be mixed	l with diesal . Remove fuel	Espak Plug Wire			4.00	
ank to drain and clean out . Flush fuel lines . Refil	Espak Plug Wire			4.00		
- Remove vise to replace defective rusty adjusting	g bolts . Retest operation of	Throttle Body Cleane	r		1.00	
vise .		Injector Cleaner	1.00			
- Shop Supplies		Intake Cleaner Kit			1.00	
		Body Mount Kit			4.00	
		Body Mount Kit			2.00	
		Motor Tune-up 16oz			1.00	
		Ford Triton Pvc Swc			1.00	
		Shop Supplies			1.00	
		Tire Disposal Fee			4.00	
Hours: 26.00	Comm: 0.00	Labor: 1,742.00	Parts: 1,9	30.37	Total: 3,672.37	
rk Order: 1904353 Problem: Pumped Diesel instead of unleaded	Meter: 57187		In Date:	04/22/2019	Closed: 04/22/20	

- Tow From: Loggerhead park, 14200 Us1, Juno beach To: vista

Hours: 0.00

Labor: 0.00 Parts: 0.00

Nork Order:	1905577	Meter:	57405		In Date:	04/26/2019	Closed:	05/28/2019
	damage to rear bumper	motor	01100		in Dato.	0 1/20/2010	0.0000	00/20/2010
Work Comp	bleted							
- damage to	o rear bumper							
_	Hours: 0.00		Comm: 1,143.84	Labor: 0.00	Parts: 0.00)	Total:	1,143.84
Vork Order: Problem:	1908504 Missing fuel cap	Meter:	59310		In Date:	08/14/2019	Closed:	08/15/2019
Work Comp	pleted			Parts Issued			Qı	uantity
- Replace m	issing fuel cap and scan and cl	ear evap codes	for loose cap.	Cap Asy				1.00
- Shop Supp	olies	·		Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 22.9	94	Total:	89.94
Vork Order: Problem:		Meter:	62376		In Date:	11/08/2019	Closed:	11/18/2019
Work Comp	bleted			Parts Issued			Qı	uantity
- P.m. servio	ce.			Napagold Oil Filter				1.00
- Replace tv	vo tires . Rotate and high speed	l balance all si	k tires . Nitrofill all.	5w20 Engine Oil				7.00
- Shop Supp	olies			Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
				Used Fire X Refurbish	ned			1.00
				Lt245/75r17 Mich De	efend Ltx			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 6.50		Comm: 0.00	Labor: 474.50	Parts: 562	.19	Total:	1,036.69
Vork Order: 2 Problem:	2001009 Towed in for no start.	Meter:	64325		In Date:	01/29/2020	Closed:	02/04/2020
Work Comp	bleted			Parts Issued			Qı	uantity
- Test batte	ry . failed load test . Perform sta	arting and cha	rging sytem tests .	Battery 65				1.00
Ok . Replace	defective battery .	-		Shop Supplies				1.00
- Shop Supp	olies							

10/24/2022 5:17:14 PM				ment Asset Maintenan y Body, 1 Ton, Gas	ce History			
Work Order: Problem:		Meter:	64133		In Date:	01/29/2020	Closed:	01/30/2020
Work Com	npleted							
- Tow Fror	m: Cabana Colony Park ·	-3855 Holiday Rd Pbg,	To: Lv shop					
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	2005596 P.M. service.	Meter:	67140		In Date:	06/04/2020	Closed:	06/18/2020
Work Com	npleted			Parts Issued			Qı	uantity
- P.m. Serv	vice			Napagold Oil Filter				1.00
- Replace	broken roof marker ligh	t.		5w20 Engine Oil				7.00
- Replace	worn out hood struts.re	place broken driver sid	e sun visor.	Washer Fluid Concer	ntr			1.00
- Rotate a	nd balance all six tires.			22" Wiper Blade				2.00
- Shop Suj	pplies			Ford Triton Pvc Swc				1.00
				Grommet Mount Kit				1.00
				Boxed Miniatures				1.00
				Lamp				1.00
				Retainer				1.00
				Sun Visor				1.00
				Lift Support				2.00
				Shop Supplies				1.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 316	6.29	Total:	827.29

Hours: 2.50

Palm Beach County Fleet Management Asset Maintenance History 10186231 2012 FORD F350 Utility Body, 1 Ton, Gas

2.00

1.00

8.00

1.00

1.00

6.00

1.00

1.00

6.00

1.00

1.00

1.00

Total: 433.70

Work Order: 2100372 Meter: 73010 01/12/2021 **Closed:** 01/20/2021 In Date: Problem: P.M. service. **Work Completed** Parts Issued Quantity 22" Wiper Blade - Preventive Maint, Service Washer Fluid Concentr - Replace all 6 worn down tires below 4/32nds min. Install and balance all 6 new tires. Reinstall tires on truck. 5w20 Engine Oil - Alignment. Use alignment machine to preform complete 4 wheel Napagold Oil Filter alignment. Adjust front toe and camber/caster. Center steering wheel. Test Used Fire X Refurbished drive to verify alignment. Lt245/75r17 Mich Defend Ltx - Pintle Pin missing. Remove broken chain and replace with new pintle pin. Pintle Pin W/clip - Shop Supplies Shop Supplies Tire Disposal Fee Hours: 9.80 Comm: 0.00 Labor: 715.40 Parts: 1,581.57 Total: 2,296.97 Work Order: 2104394 Meter: 75299 In Date: 04/20/2021 Closed: 04/22/2021 Problem: Wipers inop. Rear center marker light loose. Quantity Parts Issued Work Completed Arm And Assy - test and replace defective wiper transmission and motor assembly . Retest . Motor Asy - Reattach center tail light assembly. Shop Supplies - Shop Supplies

Comm: 0.00

Labor: 182.50

Parts: 251.20

Palm Beach County Fleet Management Asset Maintenance History 10186231 2012 FORD F350 Utility Body, 1 Ton, Gas

Meter: 77655

Work Order: 2108721 Problem: PM Service.

In Date: 08/11/2021 Closed: 09/10/2021

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	5w20 Engine Oil	7.00
- Charge battery fully . Test battery and charging system . Battery failed load	Napagold Oil Filter	1.00
test . R&r defective battery .	22" Wiper Blade	2.00
- Remove left rear bin door latch cover to replace Bin Door Lock Cylinder	Steering Wheel Cover Large	1.00
Damage	Mac Wite Lithium Gres	1.00
- Resurface both rear brake rotors . Replace brake pads . Service calipers .	Battery	1.00
Flush and bleed brake system . Road test .	Brk Fluid Dot 4-32oz	1.00
- Rotate And Balance Six Tires. Nitro Fill All	Brake Pad	1.00
- Shop Supplies	Lock Cylinder	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours: 11.80 Comm: 0.00	Labor: 861.40 Parts: 299.42	Total: 1,160.82

 Work Order:
 2202251
 Meter:
 81901
 In Date:
 02/28/2022
 Closed:
 03/10/2022

Problem: P.M service and washers inop and hood will not close ,ABS light on . New truck ordered

Work Completed			Parts Issued		Q	uantity
- Performed P.m. Serv	vice & Inspection.		Napagold Oil Filter		1.00	
- Performed Tire Rota	ition And Balance On	All 6 Tires. Reset Tire Pressure	5w20 Engine Oil		7.00	
And Fill With Nitro Fill	And Fill With Nitro Fill.					1.00
	- Hood Will Not Close Due To Rust & Corrosion On Latch Spring Assembly. Removed Latch Assembly Then Install New.					2.00
		Ground. 12v Signal & Ground Was	Used Fire X Refurbish	ed		1.00
	0	nd Replaced Then Check Working	Napagold Alf Filter			1.00
As Design.	As Design.			Washer Pump		
- Removed And Repla	- Removed And Replaced All 4 Leaking Gas Shock Strut For The Utility Bin Door.					4.00
Door.						1.00
5 5		m Diagnosis, Found 2 Fault	Abs Sensor			1.00
	0	Speed Sensor Input Missing	Shop Supplies			1.00
& Test Drove Vehicle		Defective R & R, Then Clear Faults				
- Shop Supplies						
F	lours: 10.20	Comm: 0.00	Labor: 744.60	Parts: 256	.51 Total	1,001.11
Work Order: 2207558 Problem: Transition		84703		In Date:	07/19/2022 Closed:	07/19/2022
Work Completed						
- Transition Prep Cha	rge					
F	lours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00) Total	146.00
Total Hours: 190.90	Total Labor: 1	2,472.10	Total Comm: 1,431.8	34	Total Parts: 12,949.8	8