

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Total Hours: 128.25 Labor: 8,268.75 Parts: 5,929.82 Comm: 1,413.59 Charged: 15612.16

Work Order: 1303173 **Meter:** 195 **In Date:** 04/02/2013 **Closed:** 04/02/2013
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1303804 **Meter:** 390 **In Date:** 04/17/2013 **Closed:** 04/19/2013
Problem: Left rear tire going flat.

Work Completed

- Repair flat left rear tire.nitrogen fill and balance same.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1304819 **Meter:** 2051 **In Date:** 05/14/2013 **Closed:** 05/14/2013
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.46 Labor: 0.00 Parts: 0.00 Total: 19.46

Work Order: 1307252 **Meter:** 7422 **In Date:** 07/19/2013 **Closed:** 07/25/2013
Problem: Pm service and request for detail vehicle.

Work Completed

- P.m. Service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued	Quantity
5w20 Engine Oil	6.00
Ph10575 Oil Filter Mt	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 26.68 Total: 251.68

Work Order: 1307391 **Meter:** 7422 **In Date:** 07/24/2013 **Closed:** 07/24/2013
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 97.92 Labor: 0.00 Parts: 0.00 Total: 97.92

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1407343 **Meter:** 27700 **In Date:** 07/25/2014 **Closed:** 07/29/2014
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 47.59 Total: 272.59

Work Order: 1412150 **Meter:** 32829 **In Date:** 12/04/2014 **Closed:** 12/09/2014
Problem: Pm service.

Work Completed

- Pm service.
- Replace and balance all four tires.
- Complete four wheel alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
P245 65 Sr17	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.25 Comm: 0.00 Labor: 435.00 Parts: 922.68 Total: 1,357.68

Work Order: 1503691 **Meter:** 36583 **In Date:** 04/09/2015 **Closed:** 04/09/2015
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1511415 **Meter:** 44615 **In Date:** 11/06/2015 **Closed:** 11/09/2015
Problem: Pm service.

Work Completed

- Pm service.
- Test starting and charging system.battery failed load test after recharge.replace defective battery.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Group 59 Battery Mc	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00 Parts: 219.46 Total: 504.46

Work Order: 1601499 **Meter:** 48295 **In Date:** 02/11/2016 **Closed:** 02/18/2016
Problem: Right front tire flat.

Work Completed

- Repair and balance right front tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1602754 **Meter:** 49417 **In Date:** 03/16/2016 **Closed:** 03/17/2016
Problem: Pm service.

Work Completed

- Pm service.
- Transmission flush.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Napagold Air Filter	1.00
Syn-atf Trans Fluid S	13.00
Shop Supplies	1.00

Hours: 5.25

Comm: 0.00

Labor: 315.00 Parts: 132.76 Total: 447.76

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1606746 **Meter:** 53825 **In Date:** 07/01/2016 **Closed:** 07/12/2016
Problem: Check door,hard to close.

Work Completed

- Diagnose door latch assemble.replace defective latch assemble.
- Shop Supplies

Parts Issued

Quantity

Door Lock Clip Assy	1.00
latch	1.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 210.77 Total: 300.77

Work Order: 1608279 **Meter:** 54547 **In Date:** 08/11/2016 **Closed:** 08/23/2016
Problem: P.M. Service.Detail.

Work Completed

- P.m. Service.
- Pressure test and inspect cooling system.flush and refill system.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Wd40 8oz Spray Aerosl	1.00
Ford Red Antifreeze	2.00
Shop Supplies	1.00

Hours: 5.75 Comm: 0.00 Labor: 345.00 Parts: 132.29 Total: 477.29

Work Order: 1608409 **Meter:** 54403 **In Date:** 08/15/2016 **Closed:** 08/15/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1700288 **Meter:** 59898 **In Date:** 01/10/2017 **Closed:** 01/23/2017
Problem: P.M. service and detail.

Work Completed

- P.m. Service.
- Replace and balance four new tires.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Washer Fluid Concentr	1.00
P245 65 Sr17	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.25

Comm: 0.00

Labor: 435.00

Parts: 813.64

Total: 1,248.64

Work Order: 1700424 **Meter:** 59644 **In Date:** 01/13/2017 **Closed:** 01/13/2017
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1704672 **Meter:** 65538 **In Date:** 05/10/2017 **Closed:** 05/11/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Mac Wite Lithium Gres	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Wpr/blde	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 60.67

Total: 285.67

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1707998 **Meter:** 68953 **In Date:** 08/15/2017 **Closed:** 08/24/2017

Problem: Inspect for holes in cab that would allow exhaust in cab.

Work Completed

Parts Issued

Quantity

- Inspect and perform Tsb 16-0166 procedure one.inspect for air leaks in body seams and plugs Reprogram Hvac to latest calibration.

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1709901 **Meter:** 70946 **In Date:** 10/11/2017 **Closed:** 10/17/2017

Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.

5w20 Engine Oil 6.00

- Balance and rotate all four tires.

Napagold Oil Filter 1.00

- Shop Supplies

Accufit Beam 1.00

Accufit Beam 1.00

Wpr/blde 1.00

Shop Supplies 1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 55.45 Total: 280.45

Work Order: 1709996 **Meter:** 70945 **In Date:** 10/12/2017 **Closed:** 10/12/2017

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1806942 **Meter:** 79509 **In Date:** 07/09/2018 **Closed:** 07/12/2018
Problem: pm service

Work Completed

- pm service
- replace left front a pillar trim

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
22in Exactfit-beam	1.00
24in Exactfit-beam	1.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Moulding	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 666.23 Total: 891.23

Work Order: 1808349 **Meter:** 79936 **In Date:** 08/14/2018 **Closed:** 08/14/2018
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1812283 **Meter:** 82765 **In Date:** 12/03/2018 **Closed:** 01/04/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 1907538 **Meter:** 87478 **In Date:** 07/22/2019 **Closed:** 07/25/2019
Problem: pm service

Work Completed

- Pm Service

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
24in Exactfit-beam	1.00

Hours: 2.75 Comm: 0.00 Labor: 184.25 Parts: 66.27 Total: 250.52

Work Order: 1908520 **Meter:** 87858 **In Date:** 08/14/2019 **Closed:** 08/22/2019
Problem: recall 19S17 rear toe links

Work Completed

- To dealer for recall 19S17: rear toe links

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 0.00 Total: 134.00

Work Order: 1912069 **Meter:** 92267 **In Date:** 11/21/2019 **Closed:** 12/06/2019
Problem: pm/ check fuel fill inlet

Work Completed

- pm service
- fuel filler message. scan, evap test. replace purge valve. clear code p0457
- rotate and balance tires

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
24in Exactfit-beam	1.00
22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Purge Valve	1.00

Hours: 5.75 Comm: 0.00 Labor: 419.75 Parts: 123.57 Total: 543.32

Work Order: 1912467 **Meter:** 92266 **In Date:** 12/05/2019 **Closed:** 12/05/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 2000343 **Meter:** 93719 **In Date:** 01/10/2020 **Closed:** 01/10/2020
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2005469 **Meter:** 96185 **In Date:** 06/01/2020 **Closed:** 06/11/2020
Problem: pm service

Work Completed

- pm service

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	5.00
22in Exactfit-beam	1.00
24in Exactfit-beam	1.00

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 50.70 Total: 251.45

Work Order: 2011303 **Meter:** 101280 **In Date:** 11/10/2020 **Closed:** 11/13/2020
Problem: pm service/ jump start in Roads lot

Work Completed

- Preventive Maint. Service
- Travel to Roads to jump start vehicle
- test & replace battery & check charging system
- top off fuel in loaner

Parts Issued

Quantity

Napa Quart 5w20	5.00
Napagold Oil Filter	1.00
Blade	1.00
24in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Battery	1.00

Hours: 5.25 Comm: 0.00 Labor: 383.25 Parts: 201.68 Total: 584.93

Work Order: 2101624 **Meter:** 102022 **In Date:** 02/02/2021 **Closed:** 02/11/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 2102932 **Meter:** 102740 **In Date:** 03/16/2021 **Closed:** 05/13/2021
Problem: missing windshield molding & foot rest pad

Work Completed

- replace right side windshield molding

Parts Issued

Quantity

Window Molding	1.00
Pedal Cover Pad	1.00
Moulding	1.00
Moulding	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 412.68

Total: 485.68

Work Order: 2105341 **Meter:** 103751 **In Date:** 05/12/2021 **Closed:** 05/21/2021
Problem: pm service

Work Completed

- Preventive Maint. Service
- replaced front and rear pads & resurface all rotors, service calipers

Parts Issued

Quantity

Napa Quart 5w20	5.00
Napagold Oil Filter	1.00
Blade	1.00
24in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Front Brake Pads	1.00
Rear Brake Pads	1.00

Hours: 9.75

Comm: 0.00

Labor: 711.75

Parts: 182.22

Total: 893.97

Work Order: 2106737 **Meter:** 104228 **In Date:** 06/21/2021 **Closed:** 06/22/2021
Problem: needs foot rest

Work Completed

- parts only

Parts Issued

Quantity

Foot Rest Pad	1.00
---------------	------

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 14.40

Total: 14.40

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 2111747 **Meter:** 106088 **In Date:** 10/29/2021 **Closed:** 11/15/2021
Problem: pm/ dead battery

Work Completed

- Preventive Maint. Service
- Test Charging System Replaced Battery (warranty)

Parts Issued

Quantity

Battery	1.00
Napa Quart 5w20	5.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 123.85 Total: 397.60

Work Order: 2113264 **Meter:** 106999 **In Date:** 12/15/2021 **Closed:** 12/20/2021
Problem: head light out

Work Completed

- Replaced Blown Head Light Bulb

Parts Issued

Quantity

Boxed Capsules	1.00
----------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 7.45 Total: 80.45

Work Order: 2203398 **Meter:** 113576 **In Date:** 03/29/2022 **Closed:** 03/31/2022
Problem: pm service

Work Completed

- Preventive Maint. Service

Parts Issued

Quantity

Napa Quart 5w20	5.00
Napagold Oil Filter	1.00
24in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Washer Fluid Concentr	1.00

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 43.70 Total: 244.45

Work Order: 2209130 **Meter:** 116402 **In Date:** 08/30/2022 **Closed:** 08/30/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: Fleet loaner

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Fleet loaner

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

1/9/2023
4:49:16 PM

Palm Beach County Fleet Management Asset Maintenance History
10187846 2013 FORD EXPLORER Suv, Large Mid Size, 4X4

Work Order: 2209401 **Meter:** 116458 **In Date:** 09/09/2022 **Closed:** 09/13/2022
Problem: pm service

Work Completed

- Preventive Maint. Service

Parts Issued

Quantity

Napa Quart 5w20	5.00
Napagold Oil Filter	1.00
24in Exactfit-beam	1.00
22in Exactfit-beam	1.00

Hours: 2.75 Comm: 0.00

Labor: 200.75 Parts: 45.54 Total: 246.29

Work Order: 2211582 **Meter:** 117341 **In Date:** 11/16/2022 **Closed:** 12/06/2022
Problem: several warning lights on in dash

Work Completed

- Check Abs/trac Warning Lights Are On, Codes C0034, C0037 Stored,
Replaced Both R/f And L/r Wheel Speed Sensors

Parts Issued

Quantity

Speed Sensor	1.00
Speed Sensor	1.00

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 97.12 Total: 243.12

Work Order: 2212225 **Meter:** 117314 **In Date:** 12/06/2022 **Closed:** 12/06/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 128.25 Total Labor: 8,268.75 Total Comm: 1,413.59 Total Parts: 5,929.82