WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

Print Date: 1/31/2023 Asset# Range: PT1400 to PT1400

BUS# SY	'S Code	SYS Co	ode Description			
PT1400	1100		OR CLEAN	Total Line Count for System Code 1100 :	1	Cause-Reason
Work Order #		Close Date	Employee#	Description of Work	<u> </u>	SCHEDULED SERVICE
1813970	1	07/02/2018	627	INTERIOR CLEAN		
PT1400	1332		TER REPLACE	Total Line Count for System Code 1332 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work	•	SCHEDULED SERVICE
1812116	2	06/12/2018	<u>⊏πρισγεе#</u> 837	RR CABIN FILTER		3323322 3232
PT1400	1400		RICAL SYSTEM	Total Line Count for System Code 1400 :	3	<u>Cause-Reason</u>
				-	<u> </u>	SCHEDULED SERVICE
Work Order #	Line#		Employee#	Description of Work		SCHEDULED SERVICE
1316968	2	01/09/2014	786	ELECTRICAL SYSTEM-INSTAL EJ WARD SYSTEM		
						SCHEDULED SERVICE
1316968	4	01/09/2014	786	FINISHED INSTALLING EJ WARD SYSTEM		
						MANUFACTURER'S RECALL
1410042	3	07/17/2014	713	ELECTRICAL SYSTEM-RECAL # 14504-REPROGRAM RESTRAIN	T CONTROL MO	ODULE
PT1400	1408	BATTE	RIES REPLACE	Total Line Count for System Code 1408 :	2	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		WARRANTY
1505059	3	04/08/2015	705	battery r/r by dealer		
				•		OPERATOR COMPLAINT
2126799	2	10/07/2021	787	REPLCD BATTERY		
PT1400	1409	EXTER	IOR LIGHTING	Total Line Count for System Code 1409 :	4	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
2118546	2	07/22/2021	753	SIGNAL LIGHT FRONT OUT		
						OPERATOR COMPLAINT
1907949	1	04/30/2019	752	INSTALL BRAKE LAMP		or Eravior Comm Ermit
1301343	'	0-7/00/2013	102	HO I LE DIVANE LAWI		ODERATOR COMPLAINT
1005000	0	02/20/2040	040	DEDI CD DATTEDY		OPERATOR COMPLAINT
1905296	2	03/20/2019	849	REPLCD BATTERY		
						OPERATOR COMPLAINT
2118546	5	07/22/2021	753	INSTALL SIGNAL LIGHT BULB		
PT1400	1410	INTERI	OR LIGHTING	Total Line Count for System Code 1410 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		OPERATOR COMPLAINT
1908121	1	05/02/2019	822	REMVD LIGHTS FROM 1301 INSTALL INTO PT1400NEED TO IN	STALL HEADLI	GHTS/BUMPER
						OPERATOR COMPLAINT
1908121	2	05/02/2019	822	COMPLETED INSTALLING LIGHTS/WIRING ON 1400		
.000.2.	-	2 2. 02. 20 10	V			OPERATOR COMPLAINT
1908121	3	05/02/2019	822	INSTALLED FRONT LIGHT & BUMPER & INTERIOR PANELSCHA	ADCED DATTE	
1900121	3	03/02/2019	٥∠∠	INSTALLED FRONT LIGHT & DUMPER & INTERIOR PANELSCH/	AUGED BALLE	TIESVVOIVI HULD CHAP

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

Nork Order # Line# Close Date Employee# B37	
Nork Order # Line# Close Date Employee# Bascription of Work R/R WIPER BLADES SCHEDULED SERVIF 1803050 2 02/21/2018 837 R/R WIPER BLADES SCHEDULED SERVIF 1803050 2 02/21/2018 837 BODY-HAVE SPARE KEY MADE SCHEDULED SERVIF 1803050 2504 BUS DECALS INSTALL Total Line Count for System Code 2504 : 1	3US# SYS
1803050	T1400
SCHEDULED SERVIOR 1316968 3 01/09/2014 813 BODY-HAVE SPARE KEY MADE	Vork Order #
1316968 3 01/09/2014 813 BODY-HAVE SPARE KEY MADE	1803050
PT1400 2504 BUS DECALS INSTALL Total Line Count for System Code 2504 : 1 Cause-Reason	
Work Order # 1316968	1316968
1316968	T1400
PT1400 2505 WIPERS Total Line Count for System Code 2505 : 4 Cause-Reason	/ork Order #
Work Order # Line# Close Date Employee# Description of Work WIPERSREPLCD SCHEDULED SERVICE	1316968
1908310	T1400
SCHEDULED SERVICE 2	Vork Order #
2121072 2 08/18/2021 753 R&R BOTH WIPER BLADE AND ARM INSTALL SCHEDULED SERVICE	1908310
2121072 2 08/18/2021 823 R&R BOTH WIPER BLADE AND ARM INSTALL OPERATOR COMPLA	
2121072 2	2121072
1924289 3 01/14/2020 866 R/R REAR WIPER ARM	
1924289 3 01/14/2020 866 R/R REAR WIPER ARM	2121072
PT1400 2506 DOORS	
Manufacturer's Reside Line# 1410042 Line	1924289
Total Line Close Date Employee# Description of Work 2 2 2 2 2 2 2 2 2	T1400
PT1400 2603 FRONT RELINE Total Line Count for System Code 2603 : 1 Cause-Reason Work Order # 2023156 Line# 2 Close Date 12/03/2020 Employee# 833 Description of Work RELCD FRONT BRAKE PADSROAD TEST NORMAL WEAR PT1400 2604 REAR RELINE Total Line Count for System Code 2604 : 1 Cause-Reason Work Order # 2121072 Line# 4 08/18/2021 Close Date Employee# 823 Description of Work RAR REAR ROTORS AND REAR PADS SCHEDULED SERVICE PT1400 2800 ENGINE Total Line Count for System Code 2800 : 1 Cause-Reason Work Order # Line# Line# Close Date Employee# Description of Work OPERATOR COMPLA	
Work Order # 2023156Line# 2Close Date 12/03/2020Employee# 833Description of Work RELCD FRONT BRAKE PADSROAD TESTNORMAL WEAR RELCD FRONT BRAKE PADSROAD TESTPT14002604REAR RELINETotal Line Count for System Code 2604 :1Cause-ReasonWork Order # 2121072Line# 4Close Date 08/18/2021Employee# 823Description of Work R&R REAR ROTORS AND REAR PADSSCHEDULED SERVICE SCHEDULED SERVICEPT14002800ENGINETotal Line Count for System Code 2800 :1Cause-ReasonWork Order #Line#Close DateEmployee#Description of WorkOPERATOR COMPLA	1410042
2023156 2 12/03/2020 833 RELCD FRONT BRAKE PADSROAD TEST	T1400
PT14002604REAR RELINETotal Line Count for System Code 2604 :1Cause-ReasonWork Order # 2121072Line# 08/18/2021Employee# 823Description of Work R&R REAR ROTORS AND REAR PADSSCHEDULED SERVICE SCHEDULED SERVICE STATE SCHEDULED SERVICE SERVICE SCHEDULED SCHEDULED SERVICE SCHEDULED SCHEDU	/ork Order #
Work Order # 2121072 Line# 4 08/18/2021 Close Date 823 Employee# R&R REAR ROTORS AND REAR PADS SCHEDULED SERVICE PT1400 2800 ENGINE Total Line Count for System Code 2800 : 1 1 Cause-Reason OPERATOR COMPLATOR COMPLATO	2023156
2121072 4 08/18/2021 823 R&R REAR ROTORS AND REAR PADS PT1400 2800 ENGINE Total Line Count for System Code 2800 : 1 Cause-Reason Work Order # Line# Close Date Employee# Description of Work OPERATOR COMPLA	T1400
2121072 4 08/18/2021 823 R&R REAR ROTORS AND REAR PADS PT1400 2800 ENGINE Total Line Count for System Code 2800 : 1 1 Cause-Reason Work Order # Line# Close Date Employee# Description of Work OPERATOR COMPLA	Vork Order#
Work Order # Line# Close Date Employee# Description of Work Order	2121072
Tronk Grading Close Bate Employees	T1400
	Vork Order #
PT1400 2801 TROUBLESHOOT ENGINE Total Line Count for System Code 2801 : 3 Cause-Reason	T1400
Work Order # Line# Close Date Employee# Description of Work Order	/ork Order#
1924289 1 01/14/2020 866 TROUBLESHOOT ENGINEPARTS ORDERED 12/30	
OPERATOR COMPLA	
2122288 1 08/28/2021 753 TROUBLESHOOT ENGINEFRONT MOTPOR MOUNT BAD	2122288
OPERATOR COMPLA	
2126799 1 10/07/2021 787 TROUBLESHOOT ENGINETEST BATTERYFAILED	2126799
Page 2 of 7	

Page 2 of 7

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

Print Date: 1/31/2023 Asset# Range: PT1400 to PT1400

BUS# SY	S Code	SYS Code I	<u>Description</u>				
PT1400	2803	NO START			Total Line Count for System Code 2803 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description	of Work		OPERATOR COMPLAINT
1905296	1	03/20/2019	756	NO START			
PT1400	2809	AIR INTAKE	SYSTEM REPAI	R	Total Line Count for System Code 2809 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description	of Work		SCHEDULED SERVICE
1600401	3	02/11/2016	823	R/R AIR FILTER			
PT1400	2816	ENGINE GA	ASKETS/SEALS R	REPL	Total Line Count for System Code 2816 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	<u>Description</u>	of Work		OPERATOR COMPLAINT
1924289	4	01/14/2020	866	R/R COVER GAS	SKET		
PT1400	2818	ENGINE MO	OUNTS REPL		Total Line Count for System Code 2818 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description	of Work		OPERATOR COMPLAINT
2122288	2	08/28/2021	753	R/R MOTOR MO	UNT		
PT1400	2854	150,000 MIL	E ENGINE TUNE	UP	Total Line Count for System Code 2854 :	1	Cause-Reason
Work Order #	Line#	Close Date	Employee#	<u>Description</u>	of Work		NORMAL WEAR
1924289	2	01/14/2020	866	R/R COIL PACKS	& SPARK PLUGS		
PT1400	2918	TRANS MO	UNT REPLACE		Total Line Count for System Code 2918 :	2	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description	of Work		OPERATOR COMPLAINT
2122288	3	08/28/2021	753	R/R LOWER TRA	NS MOUNT		
							OPERATOR COMPLAINT
2122288	4	08/28/2021	753	STARTED REMOV	/AL OF UPPER TRANS MOUNTCOMPLETE	:D	

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

BUS# S	YS Code	SYS C	ode Description			
PT1400	4000	TIRES		Total Line Count for System Code 4000:	8	<u>Cause-Reason</u>
Work Order #	Line#		Employee#	Description of Work		OPERATOR COMPLAINT
2118546	3	07/22/2021	753	INSTALL (2) NEW TIRESRESET TPMSWAIT FOR LUG NUTS		
0440540		07/00/0004	750	NOTAL NEW COLUMNITO		OPERATOR COMPLAINT
2118546	4	07/22/2021	753	INSTALL NEW 12 LUG NUTS		OPERATOR COMPLAINT
1924289	5	01/14/2020	27	R/R TIRESTIRE TECH		OPERATOR COMPLAINT
102 1200	Ü	01/11/2020	21	TWY TINES TIME FESTI		SCHEDULED SERVICE
1702244	2	03/15/2017	679	TRIP TO DEALERR/R ALL TIRESRETURN TO PTC		
						SCHEDULED SERVICE
1912768	2	07/12/2019	746	ADJUSTED AIR PRESSURE ON ALL TIRES		
4440074		00/47/0044	75.4	TIDES DEPAID LEST DEAD TIDE		OPERATOR COMPLAINT
1413374	1	09/17/2014	751	TIRES-REPAIR LEFT REAR TIRE		OPERATOR COMPLAINT
1507749	1	05/22/2015	746	checked all tires		OPERATOR COMPLAINT
10077 10	•	00/22/2010	7 10	ononce an area		NORMAL WEAR
1600401	2	02/11/2016	823	TIRES ROTATED		
PT1400	4001	TIRE F	REPAIR	Total Line Count for System Code 4001 :	2	<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
2005251	2	03/24/2020	864	REPAIRED TIRE RL		
						SCHEDULED SERVICE
1921909	2	11/27/2019	747	REPAIRED R/F TIRE		
PT1400	4007	LUGS	MISSING OR LOOSE	Total Line Count for System Code 4007:	1	<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1803050	3	02/21/2018	837	R/R LUGNUTS		
PT1400	4011	L/F TI	RE REPLACEMENT	Total Line Count for System Code 4011:	1	<u>Cause-Reason</u>
Work Order #	Line#	Close Date	Employee#	Description of Work	T 011 41 60	OPERATOR COMPLAINT
2118546	1	07/22/2021	753	LEFT TIRE REPLACEMENTTWO TIRES WORN/FLATTPMS LIGH	I ONALSO	12 LUG NUTS BAD
PT1400	4013		TIRE REPLACEMENT	Total Line Count for System Code 4013 :	1	<u>Cause-Reason</u>
Work Order #		Close Date	Employee#	Description of Work		SCHEDULED SERVICE
2121072	3	08/18/2021	753	R&R LEFT REAR TIRE AND RESET TPMS		

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

Print Date: 1/31/2023 <u>Asset# Range:</u> PT1400 to PT1400

BUS# SY	/S Code	SYS C	ode Description			
PT1400	8020	MISCE	LLANEOUS Travel Ti	me Total Line Count for System Code 8020 :	4	Cause-Reason
Work Order #	Line#		Employee#	Description of Work		TRANSPORT
1418292	2	01/08/2015	642	pick up at al packer		
						TRANSPORT
1418292	2	01/08/2015	808	pick up at al packer		
						MANUFACTURER'S RECALL
1410042	4	07/17/2014	731	PICKUP FROM DEALERSHIP		
	•	0.,,_0				MANUFACTURER'S RECALL
1410042	4	07/17/2014	817	PICKUP FROM DEALERSHIP		WANDI ADTONERO REDALE
1410042		07/17/2014	017	FIGROF FROM DEALERSHIF		
PT1400	8060	DRIVE	TO DEALER	Total Line Count for System Code 8060:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		MANUFACTURER'S RECALL
1410042	1	07/17/2014	747	DRIVE TO DEALER-AL PACKER FORD		
						TRANSPORT
1505059	2	04/08/2015	770	drove car dealer, and picked car up from the dealer		
				, 1		WARRANTY
1418292	1	01/08/2015	611	drop off at al packer		
1410232	'					
PT1400	9100	IN SR	C GOLF/CAR/TRUC/		1	<u>Cause-Reason</u>
Work Order #	Line#		Employee#	Description of Work		SCHEDULED SERVICE
1316968	1	01/09/2014	813	IN SERVICE GOLF/CAR/TRUCK/VAN P.M		
PT1400	9103	4,000	MILE PM CARS	Total Line Count for System Code 9103 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1413113	1	09/12/2014	786	4K MILE PM CARS		
						SCHEDULED SERVICE
1912768	1	07/12/2019	746	4K MILE PM CARSCOMPLETED		
1012700	•	017 12/2010	7 10	TO WILL THE OF THE OCUMENTS		SCHEDULED SERVICE
1700044	4	02/45/2017	670	AL MILE DM CADS COMPLETED		SCHEDOLED SERVICE
1702244	1	03/15/2017	679	4K MILE PM CARSCOMPLETED		
PT1400	9108	8,000	MILE PM CARS	Total Line Count for System Code 9108:	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1921909	1	11/27/2019	747	8.000 MILE PM CARS		
						SCHEDULED SERVICE
1505461	1	04/02/2015	746	8000 MILE PM CARS- COMPLETED		
	-					SCHEDULED SERVICE
1711130	1	06/27/2017	752	8.000 MILE PM CARS		CO. LEGELE CLIVIOL
17 11130	1	00/21/2017	132	0.000 MILL I M CARS		

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

Print Date: 1/31/2023 <u>Asset# Range:</u> PT1400 to PT1400

BUS# SY	S Code	SYS Co	de Description			
PT1400	9112	12,000 I	MILE PM CARS	Total Line Count for System Code 9112 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
2005251	1	03/24/2020	864	12K MILE PM CARSCOMPLETED		
						SCHEDULED SERVICE
1511407	1	08/12/2015	746	12K MI8LE PM CARS		
						OPERATOR COMPLAINT
1718358	1	10/13/2017	756	12K MILE PM CARSCOMPLETE		
PT1400	9116	16,000 I	MILE PM CARS	Total Line Count for System Code 9116 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
2023156	1	12/03/2020	833	16K MILE PM CARSCOMPLETED		
						SCHEDULED SERVICE
1803050	1	02/21/2018	837	16K MILE PM CARSCOMPLETED		
						SCHEDULED SERVICE
1600401	1	02/11/2016	823	16K MILE PM CARS		
PT1400	9120	20,000 I	MILE PM CARS	Total Line Count for System Code 9120 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1812116	1	06/12/2018	837	20.000 mile pm cars		
						SCHEDULED SERVICE
1606889	1	05/17/2016	746	20K MILE PM CARS		
						SCHEDULED SERVICE
2107172	1	03/31/2021	753	20K MILE PM CARSCOMPLETED		
PT1400	9124	4 24,000 MILE PM CARS		Total Line Count for System Code 9124 :	3	Cause-Reason
Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
1901182	1	01/21/2019	762	24.000 MILE PM CARS -NO OIL IN ENGINE		
						SCHEDULED SERVICE
1614131	1	10/08/2016	679	24K MILE PM CARSCOMPLETED		
						SCHEDULED SERVICE
2121072	1	08/18/2021	753	24.000 MILE PM CARS		

WO Close Date Range: 01/09/2014 to 10/07/2021 System Code Range: 1100 to 9700

_	BUS# S	YS Code	SYS (Code Description			
	PT1400	9700	TEST	RUN/ROAD TEST	Total Line Count for System Code 9700:	8	Cause-Reason
	Work Order #	Line#	Close Date	Employee#	Description of Work		SCHEDULED SERVICE
	2121072	5	08/18/2021	823	RUN / DRIVE TEST READY TO GO BACK ON SERVICE		OPERATOR COMPLAINT
	2122288	5	08/28/2021	753	ROAD TESTOK		
							SCHEDULED SERVICE
	1912768	3	07/12/2019	746	ROAD TEST		
							SCHEDULED SERVICE
	1606889	2	05/17/2016	746	ROAD TEST-OK		
							SCHEDULED SERVICE
	1316968	5	01/09/2014	813	INSPECT & ROAD TEST		
							SCHEDULED SERVICE
	1511407	2	08/12/2015	746	ROAD TEST-OK		
							SCHEDULED SERVICE
	1505461	2	04/02/2015	746	ROADTEST		
							OPERATOR COMPLAINT
	1507749	21	05/22/2015	746	road test		