



**WorkOrder: 51226631**  
**Invoice Number: 55345-51226631**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>	PM A	<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE 2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Status:</b>	40
<b>Created By:</b>	DARTHURS	<b>Priority:</b>	1
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Chronology		
<b>Reported</b>	May 29, 2018	12:54 PM
<b>Started</b>	May 29, 2018	
<b>Completed</b>	May 29, 2018	10:57 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	143,029	DH
System	143,207	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:Perform pmA  CAUSE: Preventive Maintenance  CORRECTION: Tech Perform pmA  Parts used Oil filter Qty:1 part#P9600 Oil Qty: 5.5

**Activity:** 10 **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
29-May-18	KARLENS,Cyrius	2.00	0.00	0.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity:** 20 **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**



**WorkOrder: 51226631**  
**Invoice Number: 55345-51226631**

**Client Department:**

**MRC:** 55345M

**WO Desc:**  
 PM A

**Requested By:** DARTHURS

**Created By:** DARTHURS

**Class:** WO

**Arrangement:** Unassigned

**Potential Warranty:** No

**Equipment:** 4814

**VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDGBG1ER476548

**Status:** 40

**Priority:** 1

**Driver:**

**Phone:**

**ETA:**

Date	Part Number	Description	Qty.	Each	Extended
29-May-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44

**Labor Posted**

Date	Technician	Hours	Rate	Extended
29-May-18	KARLENS,Cyrius	1.00	0.00	0.00

**Activity 20 Sub Total**

Parts:	3.44
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>3.44</b>

**Activity:** 30 **999 TOTAL VEHICLE**

**Activity Note:** PRAMETER

**Reason for Repair:** 05 - Inspection, Routine

**Work Accomplished:** 06 - Inspect

**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
29-May-18	KARLENS,Cyrius	0.47	0.00	0.00

**Activity 30 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.47	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**WorkOrder 51226631 Grand Total**

Parts:	3.44
Labor:	0.00
Labor Hours: 3.47	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>WorkOrder Grand Total</b>	<b>3.44</b>

**Recent Repair History**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 3 of 9



**WorkOrder: 51226631**  
**Invoice Number: 55345-51226631**

**Client Department:**

**MRC:** 55345M

**WO Desc:**  
PM A

**Requested By:** DARTHURS

**Created By:** DARTHURS

**Class:** WO

**Arrangement:** Unassigned

**Potential Warranty:** No

**Equipment:** 4814

**VIN:** Dodge Grand Caravan Braun Entervan SE  
2C7WDGBG1ER476548

**Status:** 40

**Priority:** 1

**Driver:**

**Phone:**

**ETA:**

WorkOrder	Date Completed	Life Meter	Class	Description
51226631	29-May-18	143,029	WO PM A	

**Scheduled Preventative Maintenance**

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

**Other Open Repairs**

WorkOrder8	Date Reported	Life Meter	Class	Description

**PH: Work Order: 51226631 Desc: PM A**

**Equip: 4814 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG1ER476548**

**LH: 10 Desc: Light Medium Duty PMI**

**Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 29-MAY-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,100	Safety Inspection	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	May 29, 2018 10:25:30 PM	No	
10,170	Check Fast Idle	-	na	CKARLENS	May 29, 2018 10:25:31 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	May 29, 2018 10:25:31 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	May 29, 2018 10:25:32 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	May 29, 2018 10:25:32 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	May 29, 2018 10:25:32 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	May 29, 2018 10:25:32 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	May 29, 2018 10:25:32 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 29, 2018 10:25:32 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 29, 2018 10:25:32 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	May 29, 2018 10:25:33 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	May 29, 2018 10:25:33 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 29, 2018 10:25:33 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	May 29, 2018 10:25:33 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	May 29, 2018 10:25:34 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 29, 2018 10:25:34 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	May 29, 2018 10:25:34 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	May 29, 2018 10:25:35 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	May 29, 2018 10:25:35 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 29, 2018 10:25:35 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	May 29, 2018 10:25:35 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	May 29, 2018 10:25:35 PM	No	
30,330	Check Wheelchair Lift Operation	-	na	CKARLENS	May 29, 2018 10:25:36 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 29, 2018 10:25:35 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 29, 2018 10:25:36 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 29, 2018 10:25:37 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 29, 2018 10:25:37 PM	No	
40,420	Check Hood	Done		CKARLENS	May 29, 2018 10:25:37 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	May 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:25:37 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-		CKARLENS	May 29, 2018 10:25:37 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 29, 2018 10:25:37 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	May 29, 2018 10:25:37 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 29, 2018 10:29:40 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 29, 2018 10:29:40 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 29, 2018 10:29:40 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 29, 2018 10:29:40 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	May 29, 2018 10:29:41 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	May 29, 2018 10:29:41 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 29, 2018 10:29:41 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 29, 2018 10:29:41 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	May 29, 2018 10:29:41 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	May 29, 2018 10:29:42 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 29, 2018 10:29:42 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	May 29, 2018 10:29:43 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	May 29, 2018 10:29:43 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 29, 2018 10:29:43 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	May 29, 2018 10:29:43 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		CKARLENS	May 29, 2018 10:29:43 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		CKARLENS	May 29, 2018 10:29:43 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		CKARLENS	May 29, 2018 10:29:44 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	Pounds per Square Inch	na	CKARLENS	May 29, 2018 10:29:43 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	na	CKARLENS	May 29, 2018 10:29:44 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		CKARLENS	May 29, 2018 10:29:44 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	May 29, 2018 10:29:44 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	May 29, 2018 10:29:44 PM	No	
60,631	Tread Depth RF	6 32nds of an inch		CKARLENS	May 29, 2018 10:29:44 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,634	Tread Depth RRI	32nds of an inch	na	CKARLENS	May 29, 2018 10:29:45 PM	No	
60,635	Tread Depth LRI	32nds of an inch	na	CKARLENS	May 29, 2018 10:29:45 PM	No	
60,636	Tread Depth LRO	8 32nds of an inch		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	May 29, 2018 10:29:45 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	May 29, 2018 10:29:46 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 29, 2018 10:29:47 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	May 29, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:29:47 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 29, 2018 10:29:48 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	May 29, 2018 10:29:48 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	May 29, 2018 10:29:48 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 29, 2018 10:29:48 PM	No	
77,131	Brake Pad Thickness LF	11 Inch		CKARLENS	May 29, 2018 10:29:48 PM	No	
77,132	Brake Pad Thickness RF	11 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,133	Brake Pad Thickness LR	8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,134	Brake Pad Thickness RR	8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,135	Brake Rotor LF	27.8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,136	Brake Rotor RF	27.8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,137	Brake Rotor LR	11.8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,138	Brake Rotor RR	11.8 Inch		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	May 29, 2018 10:29:49 PM	No	
77,150	Check King Pins	-	na	CKARLENS	May 29, 2018 10:29:50 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 29, 2018 10:29:50 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	May 29, 2018 10:29:50 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	May 29, 2018 10:29:50 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	May 29, 2018 10:29:50 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	May 29, 2018 10:29:51 PM	No	

**LH: 20 Desc: PM A**

**Task: PM A SERVICE Performed by: CKARLENS Performed on: 29-MAY-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	May 29, 2018 9:52:38 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	May 29, 2018 9:52:38 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	May 29, 2018 9:52:38 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	May 29, 2018 9:52:38 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	May 29, 2018 9:52:39 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	May 29, 2018 9:52:39 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	May 29, 2018 9:52:39 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	May 29, 2018 9:52:39 PM	No	

**LH: 30 Desc: PRAMETER**



**Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 29-MAY-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 29, 2018 9:51:33 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 51541275**  
**Invoice Number: 55345-51541275**

**Client Department:** 55345M      **Equipment:** 4814  
**MRC:**      Dodge Grand Caravan Braun Entervan SE  
**WO Desc:** PM A      **VIN:** 2C7WDGBG1ER476548  
**Requested By:** CKARLENS      **Status:** 40  
**Created By:** CKARLENS      **Priority:** 1  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported Started</b>	Aug 31, 2018	11:34 AM
<b>Completed</b>	Aug 31, 2018	11:06 PM

Meter	Reading	UOM
WO		DH
Life	155,721	DH

**Down Time**      **WorkOrder Notes**

Line	Comment
10	COMPLAINT:Perform pmA CAUSE: Preventive Maintenance CORRECTION: Performed pmA

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

<b>Activity 10 Sub Total</b>		
Parts:		0.00
Labor:		0.00
Labor Hours: 0.00		0.00
Sublet Parts:		0.00
Sublet Labor:		0.00
<b>Activity Sub Total</b>		<b>0.00</b>

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
31-Aug-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**

55345 Palm Tran Connection  
v 2.2  
Page 1 of 9



**WorkOrder: 51797651**  
**Invoice Number: 55345-51797651**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM A      Dodge Grand Caravan Braun Entervan SE  
**Requested By:** AOWENS      **VIN:** 2C7WDGBG1ER476548  
**Created By:** AOWENS      **Status:** 32  
**Class:** WO      **Priority:** 1  
**Arrangement:** Unassigned      **Driver:**  
**Potential Warranty:** No      **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Nov 1, 2018	1:05 PM
<b>Started</b>	Nov 1, 2018	
<b>Completed</b>	Nov 2, 2018	8:54 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	164,475	DH
System	164,475	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA Service  CAUSE: preventive maintenance  CORRECTION: Performed and completed PMA Service Part# P9600 Qty1

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
01-Nov-18	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
Labor: 0.00  
Labor Hours: 1.00  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
01-Nov-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**Client Department:**  
**MRC:** 55345M **Equipment:** 4814  
**WO Desc:** PM A **Dodge Grand Caravan Braun Entervan SE**  
**Requested By:** CVERGARA **VIN:** 2C7WDGGB1ER476548  
**Created By:** CVERGARA **Status:** 40  
**Class:** WO **Priority:** 1  
**Arrangement:** Unassigned **Driver:**  
**Potential Warranty:** No **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Dec 14, 2018	1:42 PM
<b>Started</b>		
<b>Completed</b>	Dec 14, 2018	11:36 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	168,783	DH
System	169,007	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

<b>Activity 10 Sub Total</b>		
Parts:		0.00
Labor:		0.00
Labor Hours: 0.00		
Sublet Parts:		0.00
Sublet Labor:		0.00
<b>Activity Sub Total</b>		<b>0.00</b>

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------



**WorkOrder**

55345 Palm Tran Connection  
v 2.2

Page 1 of 9



**WorkOrder: 52176736**  
**Invoice Number: 55345-52176736**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM A      **Dodge Grand Caravan Braun Entervan SE**  
**Requested By:** RGASPARD      **VIN:** 2C7WDG1ER476548  
**Created By:** RGASPARD      **Status:** 40  
**Class:** WO      **Priority:** 1  
**Arrangement:** Unassigned      **Driver:**  
**Potential Warranty:** No      **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Mar 14, 2019	11:58 AM
<b>Started</b>	Mar 14, 2019	
<b>Completed</b>	Mar 14, 2019	11:59 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	177,072	DH
System	177,282	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:pmA  CAUSE:Service  CORRECTION: Perform pmA Service Oil filter P9600 Qty1 Engine oil 5 Qts

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
14-Mar-19	Gaspard,Ronald	1.00	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
Labor: 0.00  
Labor Hours: 1.00  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -


**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
14-Mar-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 52255044**  
**Invoice Number: 55345-52255044**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM A      **Dodge Grand Caravan Braun Entervan SE**  
**Requested By:** RGASPARD      **VIN:** 2C7WDGBG1ER476548  
**Created By:** RGASPARD      **Status:** 40  
**Class:** WO      **Priority:** 1  
**Arrangement:** Unassigned      **Driver:**  
**Potential Warranty:** No      **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Apr 8, 2019	2:35 PM
<b>Started</b>	Apr 8, 2019	
<b>Completed</b>	Apr 8, 2019	11:23 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	181,359	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA SERVICE
	CAUSE: PREVENTIVE MAINTENANCE
	CORRECTION: PERFORM AND COMPLETED PMA SERVICE

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
08-Apr-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
 Labor: 0.00  
 Labor Hours: 1.00  
 Sublet Parts: 0.00  
 Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
08-Apr-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
PM A		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	VAMRITTEEMAL	<b>Status:</b>	40
<b>Created By:</b>	VAMRITTEEMAL	<b>Priority:</b>	1
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Chronology		
<b>Reported</b>	Jul 18, 2019	11:32 AM
<b>Started</b>	Jul 18, 2019	
<b>Completed</b>	Jul 19, 2019	7:04 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	190,108	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA Service  CAUSE: Service due By Mileage.  CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
18-Jul-19	Arthurs,Durvin	1.00	65.00	65.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>65.00</b>

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
18-Jul-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
PM A		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	RRENE	<b>Status:</b>	40
<b>Created By:</b>	RRENE	<b>Priority:</b>	1
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Chronology		
<b>Reported</b>	Aug 20, 2019	3:36 PM
<b>Started</b>	Aug 20, 2019	
<b>Completed</b>	Aug 20, 2019	10:09 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	194,215	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Perform PMA Service  CAUSE: Service due by Mileage.  CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Parts# P9600 Qty (1) Oil 5W20 Qty. (5.5) Qt

**Activity:** 10 999 TOTAL VEHICLE  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
20-Aug-19	Arthurs,Durvin	1.00	65.00	65.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>65.00</b>

**Activity:** 20 999 TOTAL VEHICLE  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
20-Aug-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45





**WorkOrder**

55345 Palm Tran Connection  
v 2.2  
Page 1 of 9



**WorkOrder: 52825429**  
**Invoice Number: 55345-52825429**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
PM A		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	AOWENS	<b>Status:</b>	40
<b>Created By:</b>	AOWENS	<b>Priority:</b>	1
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Chronology		
<b>Reported</b>	Oct 16, 2019	10:34 AM
<b>Started</b>	Oct 16, 2019	
<b>Completed</b>	Oct 17, 2019	12:11 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	203,093	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Perform PMA Service  CAUSE: Service due by Mileage.  CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check Brakes.Patch & Balance R/R tire. Parts # P9600 Qty (1) Oil 5W20 Qty (5,5) Qts

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
16-Oct-19	Arthurs,Durvin	1.50	65.00	97.50

**Activity 10 Sub Total**

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>97.50</b>

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
16-Oct-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**

55345 Palm Tran Connection  
v 2.2

Page 1 of 9



**WorkOrder: 52903609**

**Invoice Number: 55345-52903609**

**Client Department:**

**MRC:** 55345M

**Equipment:** 4814

**WO Desc:**

Dodge Grand Caravan Braun Entervan SE

PM A

**VIN:** 2C7WDGBG1ER476548

**Requested By:** DARTHURS

**Status:** 40

**Created By:** DARTHURS

**Priority:** 1

**Class:** WO

**Driver:**

**Arrangement:** Unassigned

**Phone:**

**Potential Warranty:** No

**ETA:**

Chronology		
<b>Reported</b>	Nov 11, 2019	12:00 AM
<b>Started</b>	Nov 12, 2019	
<b>Completed</b>	Nov 13, 2019	12:26 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	207,818	DH
System	207,818	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: pmA  CAUSE: Service  CORRECTION: perform pmA service Oil filter P9600 qty1 Engine oil 5w20 qty 6 Qts Fixed left front tire patched and balanced

Activity: **10** **999 TOTAL VEHICLE**

**Activity Note:** Light Medium Duty PMI

**Reason for Repair:** 08 - Preventive Maintenance

**Work Accomplished:** A - PM Level A

**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
12-Nov-19	Gaspard,Ronald	1.50	65.00	97.50

**Activity 10 Sub Total**

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>97.50</b>

Activity: **20** **999 TOTAL VEHICLE**

**Activity Note:** PM A

**Reason for Repair:** 08 - Preventive Maintenance

**Work Accomplished:** A - PM Level A

**Part Failure:** -

**Activity Comments**

**Parts Issued**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 53095204**  
**Invoice Number: 55345-53095204**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM A      **Status:** Dodge Grand Caravan Braun Entervan SE  
**Requested By:** DARTHURS      **VIN:** 2C7WDGBG1ER476548  
**Created By:** DARTHURS      **Priority:** 40  
**Class:** WO      **Driver:** 1  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported</b>	Jan 21, 2020	10:41 AM
<b>Started</b>	Jan 22, 2020	
<b>Completed</b>	Jan 22, 2020	12:49 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	216,580	DH
System	216,580	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:PM A  CAUSE: preventive maintenance by Mllege  CORRECTION:perform pmA,Change Oil and Filter,

**Activity: 10** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
22-Jan-20	Rodriguez,Raul	1.23	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
 Labor: 0.00  
 Labor Hours: 1.23  
 Sublet Parts: 0.00  
 Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
22-Jan-20	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** 55345-LIGHT DUTY PMA      **VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDG1ER476548  
**Requested By:** NSTOLFO      **Status:** 40  
**Created By:** NSTOLFO      **Priority:** 3  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported</b>	Jul 24, 2020	10:20 AM
<b>Started</b>	Jul 24, 2020	
<b>Completed</b>	Jul 25, 2020	12:16 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	229,009	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:pmA  CAUSE: Service  CORRECTION:Perform pmA Service Oil filter P9600 qty1 Engine oil 10w30 qty 5 Qts

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**



**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** 55345-LIGHT DUTY PMA      **VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDGGB1ER476548  
**Requested By:** RGASPARD      **Status:** 40  
**Created By:** RGASPARD      **Priority:** 3  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

**Chronology**

<b>Reported</b>	Sep 29, 2020	12:00 AM
<b>Started</b>	Sep 29, 2020	
<b>Completed</b>	Sep 29, 2020	11:31 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	233,322	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA Service.  CAUSE: Service Due by Mileage.  CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Check batteries. Replace cabin air filter. Parts # P9600 Qty (1) Parts # 90228P Qty (1) Oil 10W30 Qty(5.5) Qt

**Activity:** 5 **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity:** 10 **999/999/999 TOTAL VEHICLE**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** 55345-LIGHT DUTY PMA      **VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDG1ER476548  
**Requested By:** RGASPARD      **Status:** 40  
**Created By:** RGASPARD      **Priority:** 3  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported</b>	Feb 19, 2021	12:00 AM
<b>Started</b>	Feb 19, 2021	
<b>Completed</b>	Feb 20, 2021	12:59 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	242,040	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: pmA  CAUSE: Service  CORRECTION:Perform pmA Service Oil filter P9600 qty1 Engine oil 10w30 qty 5 qts

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **079 DEVICES, SAFETY/STABILITY, TRAILER**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**



**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	RGASPARD	<b>Status:</b>	40
<b>Created By:</b>	RGASPARD	<b>Priority:</b>	3
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Chronology		
<b>Reported</b>	Apr 6, 2021	12:00 AM
<b>Started</b>	Apr 6, 2021	
<b>Completed</b>	Apr 7, 2021	7:42 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	246,312	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Unit came in for service  CAUSE: Time for service  CORRECTION: Job complete this Vehicle need a oil cooler on the center of the engine. Oil filter replaced part # P9600
20	noted for repair

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
06-Apr-21	Junior Hurst	0.03	0.00	0.00

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **020 GROUP, DRIVETRAIN**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 11 - Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------







**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>Status:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Chronology		
<b>Reported</b>	Sep 9, 2021	12:00 AM
<b>Started</b>	Sep 9, 2021	
<b>Completed</b>	Sep 9, 2021	11:28 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	259,062	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Perform PMA Service  CAUSE: Service Due by Mileage.  CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Van Major Oil Leak.  Parts# P9600 Qty (1) Oi l 5W30;Qty (5.5) Qt

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **079 DEVICES, SAFETY/STABILITY, TRAILER**

**Activity Note:** Light Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------


**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>Status:</b>	2C7WDG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Chronology		
<b>Reported</b>	Aug 31, 2022	12:00 AM
<b>Started</b>	Sep 2, 2022	
<b>Completed</b>	Sep 2, 2022	6:22 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	268,781	DH
System	268,545	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Vehicle came in for service
	CAUSE: service by mileage
	CORRECTION: service job complete also change Oil filter part # p9600

**Activity: 5**  **999/999/999 TOTAL VEHICLE**

**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**
**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** 

**Activity Note:** Light Duty PMI  
**Reason for Repair:** -  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**
**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
02-Sep-22	P9600	FILTER, OIL	1.00	3.49	3.49

**Labor Posted**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 2 of 10



**WorkOrder: 55741254**  
**Invoice Number: 55345-55741254**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>Status:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Date	Technician	Hours	Rate	Extended
02-Sep-22	Junior Hurst	4.05	0.00	0.00

**Activity 10 Sub Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 4.05	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>3.49</b>

**Activity: 20** **999 TOTAL VEHICLE**

**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
02-Sep-22	Junior Hurst	0.48	0.00	0.00

**Activity 20 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.48	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**WorkOrder 55741254 Grand Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 4.53	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>WorkOrder Grand Total</b>	<b>3.49</b>

**Recent Repair History**

WorkOrder	Date Completed	Life Meter	Class	Description
55741254	2-Sep-22	268,781	WO	55345-LIGHT DUTY PMA

**Scheduled Preventative Maintenance**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 3 of 10



**WorkOrder: 55741254**  
**Invoice Number: 55345-55741254**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>Status:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

**Other Open Repairs**

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

**PH: Work Order: 55741254 Desc: 55345-LIGHT DUTY PMA  
 Equip: 4814 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG1ER476548**

**LH: 10 Desc: Light Duty PMI**

**Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 02-SEP-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Sep 2, 2022 2:20:05 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Sep 2, 2022 2:20:00 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Sep 2, 2022 3:18:20 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Sep 2, 2022 3:18:24 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Sep 2, 2022 3:18:29 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Sep 2, 2022 3:18:48 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Sep 2, 2022 3:18:58 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Sep 2, 2022 3:19:12 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Sep 2, 2022 3:19:30 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Sep 2, 2022 3:19:38 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Sep 2, 2022 3:20:02 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Sep 2, 2022 3:20:11 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Sep 2, 2022 3:20:17 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Sep 2, 2022 3:20:22 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Sep 2, 2022 3:20:30 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Sep 2, 2022 3:20:52 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Sep 2, 2022 3:20:59 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Sep 2, 2022 3:21:19 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Sep 2, 2022 3:21:28 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Sep 2, 2022 3:21:41 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Sep 2, 2022 3:21:54 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Sep 2, 2022 3:22:17 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Sep 2, 2022 3:22:24 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Sep 2, 2022 3:22:32 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles,	Done		JUHURST	Sep 2, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Controls and Panels				3:22:40 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Sep 2, 2022 3:22:56 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Sep 2, 2022 3:23:05 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Sep 2, 2022 3:23:14 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Sep 2, 2022 3:23:26 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Sep 2, 2022 3:23:36 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Sep 2, 2022 3:23:46 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 2, 2022 3:23:52 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 2, 2022 3:24:02 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 2, 2022 6:17:34 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 2, 2022 3:28:47 PM	No	
32,000	Engine Inspection	Done		JUHURST	Sep 2, 2022 3:29:08 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Sep 2, 2022 3:29:23 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Sep 2, 2022 4:35:46 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Sep 2, 2022 3:29:57 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Sep 2, 2022 3:30:27 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Sep 2, 2022 3:30:35 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Sep 2, 2022 3:30:54 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Sep 2, 2022 3:31:09 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Sep 2, 2022 3:31:37 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Sep 2, 2022 3:32:27 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Sep 2, 2022 3:32:33 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Sep 2, 2022 3:33:23 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Sep 2, 2022 3:42:26 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 2, 2022 3:44:32 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 2, 2022 3:44:54 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 2, 2022 4:01:18 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 2, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:01:29 PM		
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Sep 2, 2022 4:01:42 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Sep 2, 2022 4:01:59 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Sep 2, 2022 4:02:27 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Sep 2, 2022 4:02:34 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Sep 2, 2022 4:02:44 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Sep 2, 2022 4:02:51 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Sep 2, 2022 4:03:00 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Sep 2, 2022 4:03:23 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Sep 2, 2022 4:03:31 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Sep 2, 2022 4:03:41 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Sep 2, 2022 4:03:52 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Sep 2, 2022 4:04:01 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Sep 2, 2022 4:26:59 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Sep 2, 2022 4:27:04 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Sep 2, 2022 4:27:09 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Sep 2, 2022 4:27:14 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Sep 2, 2022 4:27:19 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Sep 2, 2022 4:27:23 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Sep 2, 2022 4:27:31 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Sep 2, 2022 4:27:36 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Sep 2, 2022 4:27:44 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Sep 2, 2022 4:27:49 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Sep 2, 2022 4:27:54 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 2, 2022 4:28:07 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 2, 2022 4:39:44 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch	front tires need rotate	JUHURST	Sep 2, 2022 4:48:17 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per		JUHURST	Sep 2, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		Square Inch			4:48:29 PM		
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 2, 2022 6:16:24 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 2, 2022 4:49:19 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Sep 2, 2022 4:49:24 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Sep 2, 2022 4:49:34 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Sep 2, 2022 4:50:04 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Sep 2, 2022 4:51:26 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 2, 2022 4:51:47 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Sep 2, 2022 6:15:55 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Sep 2, 2022 6:15:35 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Sep 2, 2022 4:52:16 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Sep 2, 2022 4:52:34 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		JUHURST	Sep 2, 2022 4:52:38 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Sep 2, 2022 4:53:08 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Sep 2, 2022 4:53:16 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Sep 2, 2022 4:53:25 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Sep 2, 2022 4:53:32 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Sep 2, 2022 6:14:30 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Sep 2, 2022 4:54:01 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Sep 2, 2022 4:54:23 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Sep 2, 2022 4:54:33 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Sep 2, 2022 4:54:55 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Sep 2, 2022 4:55:12 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Sep 2, 2022 4:55:19 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 2, 2022 5:16:22 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Sep 2, 2022 5:16:17 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Sep 2, 2022 5:50:20 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 2, 2022 5:50:25 PM	No	



Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 2, 2022 5:50:30 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 2, 2022 5:51:14 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 2, 2022 5:51:25 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 2, 2022 5:51:32 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 2, 2022 5:51:41 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Sep 2, 2022 5:51:48 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Sep 2, 2022 5:51:55 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Sep 2, 2022 5:52:01 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 2, 2022 5:52:19 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 2, 2022 5:52:30 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Sep 2, 2022 5:52:42 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Sep 2, 2022 5:53:00 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Sep 2, 2022 5:53:05 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Sep 2, 2022 5:53:10 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Sep 2, 2022 5:53:16 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Sep 2, 2022 5:53:21 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		JUHURST	Sep 2, 2022 5:53:43 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Sep 2, 2022 5:53:48 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Sep 2, 2022 5:53:54 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Sep 2, 2022 5:53:59 PM	No	
60,500	INSPECT_Bridgeplate Operation	Done		JUHURST	Sep 2, 2022 5:54:04 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Sep 2, 2022 5:54:11 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Sep 2, 2022 5:54:15 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Sep 2, 2022 5:54:20 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Sep 2, 2022 5:54:25 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Sep 2, 2022 5:54:29 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Sep 2, 2022 5:54:34 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Sep 2, 2022 5:54:38 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Sep 2, 2022 5:54:43 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Sep 2, 2022 5:54:48 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Sep 2, 2022 5:54:52 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Sep 2, 2022 5:54:57 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Sep 2, 2022 5:55:02 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Sep 2, 2022 5:55:07 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Sep 2, 2022 5:55:11 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Sep 2, 2022 5:55:16 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Sep 2, 2022 5:55:21 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Sep 2, 2022 5:55:25 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Sep 2, 2022 5:55:30 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Sep 2, 2022 5:55:34 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Sep 2, 2022 5:55:39 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Sep 2, 2022 5:55:44 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Sep 2, 2022 5:55:48 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Sep 2, 2022 5:55:53 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Sep 2, 2022 5:55:58 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Sep 2, 2022 5:56:04 PM	No	

**LH: 20 Desc: PM A**

**Task: PM A SERVICE Performed by: JUHURST Performed on: 02-SEP-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Sep 2, 2022 1:48:46 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Sep 2, 2022 1:48:57 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Sep 2, 2022 1:49:13 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Sep 2, 2022 1:49:21 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Sep 2, 2022 1:49:28 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Sep 2, 2022 1:49:40 PM	No	
107,000	FRA Change Primary Fuel Filter	No		JUHURST	Sep 2, 2022 1:50:02 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Sep 2, 2022 1:50:13 PM	No	

**LH: 5 Desc: PERSONAL RISK ASSESSMENT**

**Task: PRA and Meter Readings Performed by: JUHURST Performed on: 02-SEP-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Sep 2, 2022 1:45:46 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 2, 2022 1:45:41 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Sep 2, 2022 1:45:53 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Sep 2, 2022 1:45:59 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 2, 2022 1:46:10 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 2, 2022 1:46:19 PM	No	



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 10



**WorkOrder: 55911689**  
**Invoice Number: 55345-55911689**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** 55345-LIGHT DUTY PMA      **VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDGBG1ER476548  
**Requested By:** JUHURST      **Status:** 40  
**Created By:** JUHURST      **Priority:** 3  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported</b>	Nov 29, 2022	12:00 AM
<b>Started</b>	Dec 6, 2022	
<b>Completed</b>	Dec 6, 2022	8:41 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	273,624	DH
System	273,173	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA  CAUSE: preventive maintenance  CORRECTION:performed PMA Service completed

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **017 TIRES, TUBES, LINERS & VALVES**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 2 of 10



**WorkOrder: 55911689**  
**Invoice Number: 55345-55911689**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	JUHURST	<b>Status:</b>	40
<b>Created By:</b>	JUHURST	<b>Priority:</b>	3
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

Date	Technician	Hours	Rate	Extended
06-Dec-22	Pierre,Hubert J	1.67	0.00	0.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 1.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
06-Dec-22	P9600	FILTER, OIL	1.00	3.49	3.49

**Labor Posted**

Date	Technician	Hours	Rate	Extended
06-Dec-22	Pierre,Hubert J	0.25	0.00	0.00

**Activity 20 Sub Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 0.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>3.49</b>

**WorkOrder 55911689 Grand Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 1.92	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>WorkOrder Grand Total</b>	<b>3.49</b>

**Recent Repair History**

WorkOrder	Date Completed	Life Meter	Class	Description
55911689	6-Dec-22	273,624	WO	55345-LIGHT DUTY PMA
56179636	30-Nov-22	273,173	WO	Sliding door came off track.



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 3 of 10



**WorkOrder: 55911689**  
**Invoice Number: 55345-55911689**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>			Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMA		<b>VIN:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	JUHURST	<b>Status:</b>	40
<b>Created By:</b>	JUHURST	<b>Priority:</b>	3
<b>Class:</b>	WO	<b>Driver:</b>	
<b>Arrangement:</b>	Unassigned	<b>Phone:</b>	
<b>Potential Warranty:</b>	No	<b>ETA:</b>	

WorkOrder	Date Completed	Life Meter	Class	Description
56175729	30-Nov-22	273,063	WO	55345 PER DVIR ( Check Engine Light On )
56135130	14-Nov-22	272,646	WO	radiator issue
56133191	14-Nov-22	272,646	WO	check for oil leaks

**Scheduled Preventative Maintenance**

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

**Other Open Repairs**

WorkOrder8	Date Reported	Life Meter	Class	Description

**PH: Work Order: 55911689 Desc: 55345-LIGHT DUTY PMA  
 Equip: 4814 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG1ER476548**

**LH: 10 Desc: Light Duty PMI  
 Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 06-DEC-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		HPIERRE	Dec 6, 2022 8:21:23 AM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Dec 6, 2022 8:21:24 AM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		HPIERRE	Dec 6, 2022 8:21:25 AM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Dec 6, 2022 8:21:25 AM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Dec 6, 2022 8:21:26 AM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Dec 6, 2022 8:21:26 AM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 6, 2022 8:21:27 AM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Dec 6, 2022 8:21:28 AM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Dec 6, 2022 8:25:48 AM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Dec 6, 2022 8:25:53 AM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Dec 6, 2022 8:21:29 AM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Dec 6, 2022 8:21:30 AM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Dec 6, 2022 8:21:30 AM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Dec 6, 2022 8:21:31 AM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Dec 6, 2022 8:21:31 AM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Dec 6, 2022 7:33:17 AM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Dec 6, 2022 8:21:32 AM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Dec 6, 2022 7:33:27 AM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Dec 6, 2022 7:33:57 AM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Dec 6, 2022 8:21:33 AM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Dec 6, 2022 7:34:07 AM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Dec 6, 2022 7:34:16 AM	No	
21,100	INSPECT_Parking Brake Operation	Done		HPIERRE	Dec 6, 2022 8:21:33 AM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Dec 6, 2022 8:21:34 AM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Dec 6, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:21:34 AM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Dec 6, 2022 7:34:53 AM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Dec 6, 2022 8:21:35 AM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Dec 6, 2022 8:21:36 AM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Dec 6, 2022 7:35:08 AM	No	
21,700	INSPECT_Engine Fault Codes	Done		HPIERRE	Dec 6, 2022 8:21:36 AM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Dec 6, 2022 8:21:37 AM	No	
31,000	SSF (Street Side Front)	Done		HPIERRE	Dec 6, 2022 8:21:38 AM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 6, 2022 7:35:21 AM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 6, 2022 7:35:32 AM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 6, 2022 7:35:39 AM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 6, 2022 8:21:38 AM	No	
32,000	Engine Inspection	Done		HPIERRE	Dec 6, 2022 8:21:39 AM	No	
32,010	INSPECT_Hood, Springs and Props	Done		HPIERRE	Dec 6, 2022 8:21:39 AM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Dec 6, 2022 8:21:40 AM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Dec 6, 2022 8:21:41 AM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Dec 6, 2022 8:21:41 AM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Dec 6, 2022 8:21:42 AM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Dec 6, 2022 8:21:43 AM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Dec 6, 2022 7:36:31 AM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Dec 6, 2022 7:36:36 AM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Dec 6, 2022 7:36:43 AM	No	
32,100	INSPECT_Intake System	Done		HPIERRE	Dec 6, 2022 8:21:43 AM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Dec 6, 2022 7:36:53 AM	No	
33,010	CSF (Curb Side Front)	Done		HPIERRE	Dec 6, 2022 8:21:44 AM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Dec 6, 2022 8:14:20 AM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Dec 6, 2022 8:14:27 AM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 6, 2022	No	



Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					8:21:44 AM		
33,050	INSPECT_Wiper Blades, Arms	Done		HPIERRE	Dec 6, 2022 8:21:45 AM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	-	passenger side fall off the track	HPIERRE	Dec 6, 2022 8:21:45 AM	Yes	56194161
40,000	SECTION 4 - Interior Inspection	Done		HPIERRE	Dec 6, 2022 8:21:46 AM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Dec 6, 2022 8:16:47 AM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Dec 6, 2022 8:21:46 AM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Dec 6, 2022 8:21:47 AM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Dec 6, 2022 8:21:47 AM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Dec 6, 2022 8:21:48 AM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Dec 6, 2022 8:21:48 AM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Dec 6, 2022 8:16:59 AM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Dec 6, 2022 8:17:04 AM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Dec 6, 2022 8:21:49 AM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Dec 6, 2022 8:21:50 AM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		HPIERRE	Dec 6, 2022 8:21:50 AM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Dec 6, 2022 8:21:51 AM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Dec 6, 2022 8:17:13 AM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Dec 6, 2022 8:17:18 AM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Dec 6, 2022 8:21:52 AM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Dec 6, 2022 8:17:25 AM	No	
50,200	INSPECT_Ball Joint Play	Done		HPIERRE	Dec 6, 2022 8:21:52 AM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Dec 6, 2022 8:21:53 AM	No	
50,400	LUBE_All Chassis Components	Done		HPIERRE	Dec 6, 2022 8:21:54 AM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Dec 6, 2022 8:21:54 AM	No	
50,700	INSPECT_Tire Condition	Done		HPIERRE	Dec 6, 2022 8:21:55 AM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 6, 2022 8:21:55 AM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 6, 2022 8:21:56 AM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an		HPIERRE	Dec 6, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		inch			8:21:56 AM		
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per Square Inch		HPIERRE	Dec 6, 2022 8:21:57 AM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Dec 6, 2022 8:21:57 AM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		HPIERRE	Dec 6, 2022 8:21:58 AM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Dec 6, 2022 8:21:58 AM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Dec 6, 2022 8:21:59 AM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Dec 6, 2022 8:22:00 AM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:00 AM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:01 AM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	18 Inch		HPIERRE	Dec 6, 2022 8:22:01 AM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	18 Inch		HPIERRE	Dec 6, 2022 8:22:02 AM	No	
52,100	INSPECT_Vibration Damper	Done		HPIERRE	Dec 6, 2022 8:22:03 AM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Dec 6, 2022 8:22:03 AM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Dec 6, 2022 8:22:04 AM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Dec 6, 2022 8:22:05 AM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Dec 6, 2022 8:22:05 AM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Dec 6, 2022 8:22:06 AM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Dec 6, 2022 8:22:06 AM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Dec 6, 2022 8:22:07 AM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Dec 6, 2022 8:18:39 AM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Dec 6, 2022 8:18:44 AM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Dec 6, 2022 8:18:49 AM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Dec 6, 2022 8:18:54 AM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Dec 6, 2022 8:22:08 AM	No	
53,600	INSPECT_Tire Condition	Done		HPIERRE	Dec 6, 2022 8:22:08 AM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Dec 6, 2022 8:22:09 AM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Dec 6, 2022 8:22:09 AM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Dec 6, 2022 8:22:10 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Dec 6, 2022 8:22:10 AM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Dec 6, 2022 8:22:11 AM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:11 AM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		HPIERRE	Dec 6, 2022 8:22:12 AM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:12 AM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		HPIERRE	Dec 6, 2022 8:22:13 AM	No	
55,000	!FRA!INSPECT_REAR Brake Assemblies	Done		HPIERRE	Dec 6, 2022 8:22:14 AM	No	
55,100	!FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Dec 6, 2022 8:22:14 AM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Dec 6, 2022 8:22:15 AM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:15 AM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Dec 6, 2022 8:22:16 AM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Dec 6, 2022 8:22:16 AM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	18 Inch		HPIERRE	Dec 6, 2022 8:22:17 AM	No	
55,700	!FRA!INSPECT_Under Body Exhaust System	Done		HPIERRE	Dec 6, 2022 8:22:17 AM	No	
55,800	*RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Dec 6, 2022 8:19:54 AM	No	
55,900	*RPT*INSPECT_REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Dec 6, 2022 8:19:58 AM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Dec 6, 2022 8:22:18 AM	No	
60,100	RECORD_Wheelchair Cycle Count	Cycles	N/A	HPIERRE	Dec 6, 2022 8:22:18 AM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Dec 6, 2022 8:22:19 AM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Dec 6, 2022 8:22:20 AM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Dec 6, 2022 8:22:20 AM	No	
60,500	INSPECT_Bridgeplate Operation	Done		HPIERRE	Dec 6, 2022 8:22:21 AM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Dec 6, 2022 8:22:21 AM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Dec 6, 2022 8:22:22 AM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Dec 6, 2022 8:22:22 AM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Dec 6, 2022 8:22:23 AM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Dec 6, 2022 8:22:24 AM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Dec 6, 2022 8:22:24 AM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Dec 6, 2022 8:22:25 AM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Dec 6, 2022 8:22:26 AM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Dec 6, 2022 8:22:26 AM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Dec 6, 2022 8:22:27 AM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		HPIERRE	Dec 6, 2022 8:22:27 AM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Dec 6, 2022 8:22:28 AM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Dec 6, 2022 8:22:28 AM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		HPIERRE	Dec 6, 2022 8:22:29 AM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Dec 6, 2022 8:22:29 AM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Dec 6, 2022 8:22:30 AM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Dec 6, 2022 8:22:30 AM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		HPIERRE	Dec 6, 2022 8:22:31 AM	No	
62,400	INSPECT_All Pivot Points	Done		HPIERRE	Dec 6, 2022 8:22:31 AM	No	
62,500	INSPECT_Cams and Slots	Done		HPIERRE	Dec 6, 2022 8:22:32 AM	No	
62,600	INSPECT_Rollers	Done		HPIERRE	Dec 6, 2022 8:22:33 AM	No	
62,700	INSPECT_All Linkages	Done		HPIERRE	Dec 6, 2022 8:22:33 AM	No	
80,000	SECTION 8 - PMI Report Completion	Done		HPIERRE	Dec 6, 2022 8:22:34 AM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Dec 6, 2022 8:22:35 AM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Dec 6, 2022 8:22:35 AM	No	

**LH: 20 Desc: PM A**

**Task: PM A SERVICE Performed by: HPIERRE Performed on: 06-DEC-22**


Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 6, 2022 8:27:35 AM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	Dec 6, 2022 8:27:36 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Dec 6, 2022 8:27:37 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Dec 6, 2022 8:27:38 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Dec 6, 2022 8:27:38 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Dec 6, 2022 8:27:39 AM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Dec 6, 2022 8:27:39 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Dec 6, 2022 8:27:40 AM	No	

**LH: 5 Desc: PERSONAL RISK ASSESSMENT****Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-DEC-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		HPIERRE	Dec 6, 2022 8:28:33 AM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 6, 2022 8:28:34 AM	No	
4	Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 6, 2022 8:28:35 AM	No	
7	Have you performed the proper LOTO?	Done		HPIERRE	Dec 6, 2022 8:28:35 AM	No	
10	Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 6, 2022 8:28:36 AM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 6, 2022 8:28:37 AM	No	



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 53204518**  
**Invoice Number: 55345-53204518**

**Client Department:**

**MRC:** 55345M

**Equipment:** 4814

**WO Desc:**  
 PM A

Dodge Grand Caravan Braun Entervan SE  
 2C7WDGBG1ER476548

**Requested By:** RAUODRIGUEZ

**VIN:**

**Created By:** RAUODRIGUEZ

**Status:** 40

**Class:** WO

**Priority:** 1

**Arrangement:** Unassigned

**Driver:**

**Potential Warranty:** No

**Phone:**

**ETA:**

Chronology		
<b>Reported</b>	Feb 19, 2020	10:08 AM
<b>Started</b>	Feb 20, 2020	
<b>Completed</b>	Feb 20, 2020	7:07 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	220,838	DH
System	220,838	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMA SERVICE  CAUSE: PREVENTIVE MAINTENANCE  CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

**Activity: 10** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
20-Feb-20	AMRIT TEEMAL,VISHNU	0.63	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
 Labor: 0.00  
 Labor Hours: 0.63  
 Sublet Parts: 0.00  
 Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM A  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** A - PM Level A  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
20-Feb-20	P9600	FILTER, OIL	1.00	3.45	3.45



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 51678175**  
**Invoice Number: 55345-51678175**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM B      Dodge Grand Caravan Braun Entervan SE  
**Requested By:** AOWENS      **VIN:** 2C7WDGBG1ER476548  
**Created By:** AOWENS      **Status:** 40  
**Class:** WO      **Priority:** 1  
**Arrangement:** Unassigned      **Driver:**  
**Potential Warranty:** No      **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Oct 9, 2018	12:49 PM
<b>Started</b>	Oct 9, 2018	
<b>Completed</b>	Oct 9, 2018	10:49 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	160,072	DH
System	160,214	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMB Service  CAUSE: preventive maintenance  CORRECTION: performed and completed PMB Service Part# P9600 Qty1

**Activity: 10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Mediu Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
09-Oct-18	Owens, Arthur	1.00	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
 Labor: 0.00  
 Labor Hours: 1.00  
 Sublet Parts: 0.00  
 Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM B  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** B - PM Level B  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
09-Oct-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**

55345 Palm Tran Connection  
v 2.2  
Page 1 of 9



**WorkOrder: 52325531**  
**Invoice Number: 55345-52325531**

**Client Department:**

**MRC:** 55345M

**Equipment:** 4814

**WO Desc:**

Dodge Grand Caravan Braun Entervan SE

PM B

**VIN:** 2C7WDGBG1ER476548

**Requested By:** VAMRITTEEMAL

**Status:** 40

**Created By:** VAMRITTEEMAL

**Priority:** 1

**Class:** WO

**Driver:**

**Arrangement:** Unassigned

**Phone:**

**Potential Warranty:** No

**ETA:**

Chronology		
Reported	Jun 14, 2019	11:16 AM
Started	Jun 14, 2019	
Completed	Jun 14, 2019	10:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	185,637	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMB SERVICE  CAUSE: PREVENTIVE MAINTENANCE  CORRECTION: PERFORM AND COMPLETED PMB SERVICE REPLACED AIR FILTER

**Activity: 10**



999 TOTAL VEHICLE

**Activity Note:** Light Medium Duty PMI

**Reason for Repair:** 08 - Preventive Maintenance

**Work Accomplished:** 06 - Inspect

**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
14-Jun-19	AMRIT TEEMAL,VISHNU	1.00	65.00	65.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>65.00</b>

**Activity: 20**



999 TOTAL VEHICLE

**Activity Note:** PM B

**Reason for Repair:** 08 - Preventive Maintenance

**Work Accomplished:** B - PM Level B

**Part Failure:** -

**Activity Comments**


**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
14-Jun-19	PA4456	FILTER, AIR, CARAVAN, '14 SAME AS WIX 49737	1.00	5.02	5.02





**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 1 of 9



**WorkOrder: 52995149**  
**Invoice Number: 55345-52995149**

**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** PM B      **Dodge Grand Caravan Braun Entervan SE**  
**Requested By:** RGASPARD      **VIN:** 2C7WDGBG1ER476548  
**Created By:** RGASPARD      **Status:** 40  
**Class:** WO      **Priority:** 1  
**Arrangement:** Unassigned      **Driver:**  
**Potential Warranty:** No      **Phone:**  
**ETA:**

Chronology		
<b>Reported</b>	Dec 13, 2019	12:00 AM
<b>Started</b>	Dec 13, 2019	
<b>Completed</b>	Dec 13, 2019	11:16 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	212,379	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMB Service  CAUSE: Service due by Mileage.  CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Check batteries. Parts# B329 Qty (1) Oil 5W20. Qty (5.5) Qt

**Activity: 10** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
13-Dec-19	Arthurs,Durvin	1.20	65.00	78.00

**Activity 10 Sub Total**

Parts: 0.00  
 Labor: 78.00  
 Labor Hours: 1.20  
 Sublet Parts: 0.00  
 Sublet Labor: 0.00  
**Activity Sub Total 78.00**

**Activity: 20** **999 TOTAL VEHICLE**  
**Activity Note:** PM B  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** B - PM Level B  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
13-Dec-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE 2C7WDGBG1ER476548
55345-LIGHT DUTY PMB		<b>Status:</b>	40
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	3
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Chronology		
<b>Reported</b>	Dec 15, 2020	12:51 PM
<b>Started</b>	Dec 16, 2020	
<b>Completed</b>	Dec 17, 2020	12:18 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	237,728	DH
System	237,728	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT:PMB  CAUSE: service  CORRECTION: perform PMB service Oil filter P9600 qty1 Engine oil 10w30 qty 5 1/2 qts

**Activity: 5** **999/999/999 TOTAL VEHICLE**  
**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **079 DEVICES, SAFETY/STABILITY, TRAILER**  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**


**Client Department:**


<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMB		<b>Status:</b>	2C7WDG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Chronology		
<b>Reported</b>	Jun 27, 2022	12:00 AM
<b>Started</b>	Jun 30, 2022	
<b>Completed</b>	Jun 30, 2022	6:52 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	264,007	DH
System	263,680	DH

**WorkOrder Notes**

Line	Comment
10	COMPLAINT: Perform PMB Service.  CAUSE: Service due by Mileage.  CORRECTION: Change Oil & Filter. Lube all apivoting Points. Check Brakes. parts # P9600 Qty (1) Oil 5W30 Qty (5,5) Qts

**Activity: 5**  **999/999/999 TOTAL VEHICLE**

**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**
**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10**  **079 DEVICES, SAFETY/STABILITY, TRAILER**

**Activity Note:** Light Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**
**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 2 of 10



**WorkOrder: 54885341**  
**Invoice Number: 55345-54885341**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMB		<b>Status:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

Date	Technician	Hours	Rate	Extended
30-Jun-22	Arthurs,Durvin	1.85	0.00	0.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 1.85	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

Activity: **20** **999 TOTAL VEHICLE**

**Activity Note:** PM B  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** B - PM Level B  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
30-Jun-22	P9600	FILTER, OIL	1.00	3.49	3.49

**Labor Posted**

Date	Technician	Hours	Rate	Extended
30-Jun-22	Arthurs,Durvin	0.40	0.00	0.00

**Activity 20 Sub Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 0.40	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>3.49</b>

**WorkOrder 54885341 Grand Total**

Parts:	3.49
Labor:	0.00
Labor Hours: 2.25	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>WorkOrder Grand Total</b>	<b>3.49</b>

**Recent Repair History**

WorkOrder	Date Completed	Life Meter	Class	Description
54885341	30-Jun-22	264,007	WO	55345-LIGHT DUTY PMB
55717099	24-Jun-22	263,175	WO	55345 PER DVIR ( Check Front Left Tire )



**WorkOrder**  
 55345 Palm Tran Connection  
 v 2.2  
 Page 3 of 10



**WorkOrder: 54885341**  
**Invoice Number: 55345-54885341**

**Client Department:**

<b>MRC:</b>	55345M	<b>Equipment:</b>	4814
<b>WO Desc:</b>		<b>VIN:</b>	Dodge Grand Caravan Braun Entervan SE
55345-LIGHT DUTY PMB		<b>Status:</b>	2C7WDGBG1ER476548
<b>Requested By:</b>	DARTHURS	<b>Priority:</b>	40
<b>Created By:</b>	DARTHURS	<b>Driver:</b>	3
<b>Class:</b>	WO	<b>Phone:</b>	
<b>Arrangement:</b>	Unassigned	<b>ETA:</b>	
<b>Potential Warranty:</b>	No		

WorkOrder	Date Completed	Life Meter	Class	Description
55690024	15-Jun-22	262,469	WO	air conditioning not working
55670932	7-Jun-22	262,287	WO	check engine light on
55647733	31-May-22	261,546	WO	Flat tire.

**Scheduled Preventative Maintenance**

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

**Other Open Repairs**

WorkOrder8	Date Reported	Life Meter	Class	Description
55717099	23-Jun-22	263,175	WO	55345 PER DVIR ( Check Front Left Tire )

**PH: Work Order: 54885341 Desc: 55345-LIGHT DUTY PMB  
 Equip: 4814 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG1ER476548**

**LH: 10 Desc: Light Duty PMI  
 Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 30-JUN-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		DARTHURS	Jun 30, 2022 6:03:02 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jun 30, 2022 6:03:07 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		DARTHURS	Jun 30, 2022 6:03:13 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jun 30, 2022 6:03:17 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jun 30, 2022 6:03:21 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jun 30, 2022 6:03:29 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 30, 2022 6:03:35 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jun 30, 2022 6:03:41 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jun 30, 2022 6:03:47 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jun 30, 2022 6:03:53 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jun 30, 2022 6:03:58 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jun 30, 2022 6:04:06 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jun 30, 2022 6:04:17 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jun 30, 2022 6:04:22 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jun 30, 2022 6:04:32 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jun 30, 2022 6:04:40 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Jun 30, 2022 6:04:45 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jun 30, 2022 6:04:52 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Jun 30, 2022 6:05:00 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jun 30, 2022 6:05:13 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jun 30, 2022 6:05:25 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		DARTHURS	Jun 30, 2022 6:05:34 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jun 30, 2022 6:05:41 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jun 30, 2022 6:05:47 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles,	Done		DARTHURS	Jun 30, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Controls and Panels				6:05:54 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jun 30, 2022 6:06:00 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jun 30, 2022 6:06:10 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jun 30, 2022 6:06:17 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		DARTHURS	Jun 30, 2022 6:06:22 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jun 30, 2022 6:06:27 PM	No	
31,000	SSF (Street Side Front)	Done		DARTHURS	Jun 30, 2022 6:06:32 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 30, 2022 6:06:40 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 30, 2022 6:06:46 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 30, 2022 6:06:51 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jun 30, 2022 6:07:03 PM	No	
32,000	Engine Inspection	Done		DARTHURS	Jun 30, 2022 6:07:09 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		DARTHURS	Jun 30, 2022 6:07:14 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jun 30, 2022 6:07:19 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jun 30, 2022 6:07:25 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Jun 30, 2022 6:07:36 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jun 30, 2022 6:08:16 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jun 30, 2022 6:07:44 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jun 30, 2022 6:08:24 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Jun 30, 2022 6:08:31 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jun 30, 2022 6:08:42 PM	No	
32,100	INSPECT_Intake System	Done		DARTHURS	Jun 30, 2022 6:08:50 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		DARTHURS	Jun 30, 2022 6:09:06 PM	No	
33,010	CSF (Curb Side Front)	Done		DARTHURS	Jun 30, 2022 6:09:15 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jun 30, 2022 6:09:20 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jun 30, 2022 6:09:26 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 30, 2022 6:09:30 PM	No	
33,050	INSPECT_Wiper Blades, Arms	-	Rear	DARTHURS	Jun 30, 2022	Yes	55741205

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
			Wiper Blade		6:09:59 PM		
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jun 30, 2022 6:10:07 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		DARTHURS	Jun 30, 2022 6:10:12 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jun 30, 2022 6:10:21 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jun 30, 2022 6:10:27 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jun 30, 2022 6:10:34 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Jun 30, 2022 6:10:51 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jun 30, 2022 6:11:03 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jun 30, 2022 6:11:10 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jun 30, 2022 6:11:17 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jun 30, 2022 6:11:23 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jun 30, 2022 6:11:28 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jun 30, 2022 6:11:34 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jun 30, 2022 6:11:40 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jun 30, 2022 6:11:45 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jun 30, 2022 6:11:51 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jun 30, 2022 6:11:58 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jun 30, 2022 6:12:03 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jun 30, 2022 6:12:09 PM	No	
50,200	INSPECT_Ball Joint Play	Done		DARTHURS	Jun 30, 2022 6:12:14 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jun 30, 2022 6:12:19 PM	No	
50,400	LUBE_All Chassis Components	Done		DARTHURS	Jun 30, 2022 6:12:24 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jun 30, 2022 6:12:29 PM	No	
50,700	INSPECT_Tire Condition	Done		DARTHURS	Jun 30, 2022 6:12:34 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 30, 2022 6:12:40 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jun 30, 2022 6:12:47 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 30, 2022 6:12:58 PM	No	



Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Jun 30, 2022 6:13:03 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		DARTHURS	Jun 30, 2022 6:13:12 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Jun 30, 2022 6:13:20 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jun 30, 2022 6:13:25 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jun 30, 2022 6:13:29 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		DARTHURS	Jun 30, 2022 6:13:34 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Jun 30, 2022 6:13:45 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		DARTHURS	Jun 30, 2022 6:13:51 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.099 Inch		DARTHURS	Jun 30, 2022 6:14:15 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.099 Inch		DARTHURS	Jun 30, 2022 6:14:28 PM	No	
52,100	INSPECT_Vibration Damper	Done		DARTHURS	Jun 30, 2022 6:14:38 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jun 30, 2022 6:14:43 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		DARTHURS	Jun 30, 2022 6:14:48 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jun 30, 2022 6:14:52 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		DARTHURS	Jun 30, 2022 6:14:57 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jun 30, 2022 6:15:03 PM	No	
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jun 30, 2022 6:15:07 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done		DARTHURS	Jun 30, 2022 6:15:12 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jun 30, 2022 6:15:26 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jun 30, 2022 6:15:38 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jun 30, 2022 6:15:47 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jun 30, 2022 6:15:53 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jun 30, 2022 6:15:57 PM	No	
53,600	INSPECT_Tire Condition	Done		DARTHURS	Jun 30, 2022 6:16:02 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jun 30, 2022 6:16:10 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jun 30, 2022 6:16:15 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jun 30, 2022 6:16:21 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose	Done		DARTHURS	Jun 30, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Lugs/Indicators, Outer Hub Leaks				6:16:27 PM		
54,100	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jun 30, 2022 6:16:32 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jun 30, 2022 6:16:42 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Jun 30, 2022 6:17:16 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Jun 30, 2022 6:17:30 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Jun 30, 2022 6:17:39 PM	No	
55,000	!FRA!INSPECT_REAR Brake Assemblies	Done		DARTHURS	Jun 30, 2022 6:17:44 PM	No	
55,100	!FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jun 30, 2022 6:17:49 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jun 30, 2022 6:17:53 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jun 30, 2022 6:18:07 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jun 30, 2022 6:18:14 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.473 Inch		DARTHURS	Jun 30, 2022 6:18:31 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.473 Inch		DARTHURS	Jun 30, 2022 6:18:40 PM	No	
55,700	!FRA!INSPECT_Under Body Exhaust System	Done		DARTHURS	Jun 30, 2022 6:18:45 PM	No	
55,800	*RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jun 30, 2022 6:18:50 PM	No	
55,900	*RPT*INSPECT_REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jun 30, 2022 6:18:54 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jun 30, 2022 6:18:59 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		DARTHURS	Jun 30, 2022 6:19:16 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jun 30, 2022 6:19:20 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jun 30, 2022 6:19:25 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jun 30, 2022 6:19:31 PM	No	
60,500	INSPECT_Bridgeplate Operation	Done		DARTHURS	Jun 30, 2022 6:19:35 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jun 30, 2022 6:19:40 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jun 30, 2022 6:19:44 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Jun 30, 2022 6:19:49 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jun 30, 2022 6:19:53 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jun 30, 2022 6:19:58 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or	Done		DARTHURS	Jun 30, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Cracks				6:20:04 PM		
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jun 30, 2022 6:20:09 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jun 30, 2022 6:20:14 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jun 30, 2022 6:20:19 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jun 30, 2022 6:20:24 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		DARTHURS	Jun 30, 2022 6:20:29 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jun 30, 2022 6:20:34 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jun 30, 2022 6:20:38 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jun 30, 2022 6:20:43 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jun 30, 2022 6:20:47 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jun 30, 2022 6:20:52 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jun 30, 2022 6:20:59 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jun 30, 2022 6:21:03 PM	No	
62,400	INSPECT_All Pivot Points	Done		DARTHURS	Jun 30, 2022 6:21:08 PM	No	
62,500	INSPECT_Cams and Slots	Done		DARTHURS	Jun 30, 2022 6:21:12 PM	No	
62,600	INSPECT_Rollers	Done		DARTHURS	Jun 30, 2022 6:21:17 PM	No	
62,700	INSPECT_All Linkages	Done		DARTHURS	Jun 30, 2022 6:21:22 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		DARTHURS	Jun 30, 2022 6:21:26 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jun 30, 2022 6:21:31 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jun 30, 2022 6:21:35 PM	No	

**LH: 20 Desc: PM B**

**Task: PM B SERVICE Performed by: DARTHURS Performed on: 30-JUN-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 30, 2022 6:22:25 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 30, 2022 6:22:48 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 30, 2022 6:22:53 PM	No	
103,000	FRA Check Transmission Fluid	-	NA	DARTHURS	Jun 30, 2022 6:23:06 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 30, 2022 6:23:12 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jun 30, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:23:18 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 30, 2022 6:23:32 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 30, 2022 6:23:39 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 30, 2022 6:23:43 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Jun 30, 2022 6:24:00 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	Jun 30, 2022 6:24:15 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 30, 2022 6:24:20 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 30, 2022 6:24:27 PM	No	


**LH: 5 Desc: PERSONAL RISK ASSESSMENT**

**Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-JUN-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		DARTHURS	Jun 30, 2022 6:25:15 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 30, 2022 6:25:19 PM	No	
4	Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 30, 2022 6:25:24 PM	No	
7	Have you performed the proper LOTO?	Done		DARTHURS	Jun 30, 2022 6:25:29 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 30, 2022 6:25:33 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 30, 2022 6:25:38 PM	No	



**WorkOrder**  
55345 Palm Tran Connection  
v 2.2



WorkOrder: 51379464  
Invoice Number: 55345-51379464

Page 1 of 9

**Client Department:**

**MRC:** 55345M

**WO Desc:** 4814  
PM C

**Equipment:** 4814

Dodge Grand Caravan Braun Entervan SE  
2C7WDGBG1ER476548

**Requested By:** CKARLENS

**VIN:** CKARLENS

**Status:** CKARLENS

**Created By:** WO

**Priority:** Unassigned

**Class:** No

**Driver:** Unassigned

**Arrangement:** No

**Phone:** No

**ETA:** No

Chronology		Down Time	
Reported	Jun 26, 2018		10:53 AM
Started	Jun 27, 2018		
Completed	Jun 27, 2018		11:02 PM

Meter	Reading	UOM
WO		DH
Life	147,414	DH
System	147,414	DH

**WorkOrder Notes**

Line	Comment
10	Performed PM-C
	Parts used
	Oil filter Qty:1 part#P9600
	Oil Qty:5.50
	Oil drain plug Qty:1 part#6506214AA

**Activity: 10**  
**Activity Note:** 999 TOTAL VEHICLE  
Light Medium Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** 06 - Inspect  
**Part Failure:**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
27-Jun-18	KARLENS,Cyrus	2.00	0.00	0.00

**Activity 10 Sub Total**  
Parts: 0.00  
Labor: 0.00  
Labor Hours: 2.00  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total** 0.00


**Activity: 20**  
**Activity Note:** 999 TOTAL VEHICLE  
PM C  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** C - PM Level C  
**Part Failure:**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
27-Jun-18	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.44	3.44



**WorkOrder**  
55345 Palm Tran Connection  
v 2.2



**WorkOrder: 51379464**  
**Invoice Number: 55345-51379464**

Page 2 of 9

**Client Department:**

**MRC:** 55345M  
**WO Desc:** 4814  
PM C Dodge Grand Caravan Braun Entervan SE  
**Requested By:** CKARLENS  
**Created By:** CKARLENS  
**Class:** WO  
**Arrangement:** Unassigned  
**Potential Warranty:** No

**Equipment:** 4814  
Dodge Grand Caravan Braun Entervan SE  
**VIN:** 2C7WDGBG1ER476548  
**Status:** 40  
**Priority:** 1  
**Driver:** 1  
**Phone:**  
**ETA:**

Date	Part Number	Description	Qty.	Each	Extended
27-Jun-18	PA10030	FILTER, AIR, CABIN, CHRYSLER REPLACES 68127809AA	1.00	2.75	2.75
27-Jun-18	6801855AA	FILTER, TRANSMISSION, DODGE	1.00	22.39	22.39

**Labor Posted**

Date	Technician	Hours	Rate	Extended
27-Jun-18	KARLENS,Cyrus	2.00	0.00	0.00

**Activity 20 Sub Total**

Parts: 28.58  
Labor: 0.00  
Labor Hours: 2.00  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 28.58**

**Activity: 30**

**Activity Note:** 999 TOTAL VEHICLE PRAMETER  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** 06 - Inspect  
**Part Failure:**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
27-Jun-18	KARLENS,Cyrus	0.33	0.00	0.00

**Activity 30 Sub Total**


Parts: 0.00  
Labor: 0.00  
Labor Hours: 0.33  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**WorkOrder 51379464 Grand Total**

Parts: 28.58  
Labor: 0.00  
Labor Hours: 4.33  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**WorkOrder Grand Total 28.58**



**WorkOrder**  
55345 Palm Tran Connection  
v 2.2



**WorkOrder: 51379464**  
**Invoice Number: 55345-51379464**

Page 3 of 9

**Client Department:**

**MRC:** 55345M

**WO Desc:** 4814  
PM C

**Equipment:** Dodge Grand Caravan Braun Entervan SE

**VIN:** 2C7WDGGB1ER476548

**Requested By:** CKARLENS

**Status:** 40

**Created By:** CKARLENS

**Priority:** 1

**Class:** WO

**Driver:** Unassigned

**Arrangement:** No

**Phone:** No

**Potential Warranty:** No

**ETA:**

**Recent Repair History**

WorkOrder	Date Completed	Life Meter	Class	Description
51379464	27-Jun-18	147,414	WO	PM C
51226631	29-May-18	143,029	WO	PM A

**Scheduled Preventative Maintenance**

Next	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

**Other Open Repairs**

WorkOrder	Date Reported	Life Meter	Class	Description
51492756	9-Jul-18	149,177	WO	Nail on driver rear tire
51466915	27-Jun-18	147,414	WO	FOLLOWUP--replace rear tires

PH: Work Order: 51379464 Desc: PM C

Equip: 4814 Desc: Dodge Grand Caravan Braun Entervan SE VIN: 2C7WDGBG1ER476548

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 27-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,100	Safety Inspection	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 27, 2018 4:18:49 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,170	Check Fast Idle	-	na	CKARLENS	Jun 27, 2018 4:18:50 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	Jun 27, 2018 4:18:50 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	Jun 27, 2018 4:18:51 PM	No	
11,152	Decelerometer Results Test 1	FEET		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,154	Decelerometer Results Test 2	FEET		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,156	Decelerometer Results Test 3	FEET		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 27, 2018 4:18:53 PM	No	



Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 27, 2018 4:18:52 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 27, 2018 4:18:53 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 27, 2018 4:18:54 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 27, 2018 4:18:54 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	Jun 27, 2018 4:22:36 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	Jun 27, 2018 4:22:36 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 27, 2018 4:22:36 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	Jun 27, 2018 4:22:36 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 27, 2018 4:22:36 PM	No	
30,330	Check Wheelchair Lift Operation	-	na	CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	Jun 27, 2018 4:22:37 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 27, 2018 4:22:37 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	
40,420	Check Hood	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 27, 2018 4:22:38 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jun 27, 2018 4:22:38 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 27, 2018 4:22:39 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	Jun 27, 2018 4:22:40 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	Jun 27, 2018 4:22:42 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 27, 2018 4:22:41 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 27, 2018 4:22:43 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	Jun 27, 2018 4:22:41 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	Jun 27, 2018 4:22:43 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
60,611	Air Pressure RF	40 Pounds per Square Inch		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
60,612	Air Pressure LF	40 Pounds per Square Inch		CKARLENS	Jun 27, 2018 4:34:03 PM	No	
60,613	Air Pressure RRO	40 Pounds per Square Inch		CKARLENS	Jun 27, 2018 4:34:04 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	0 Pounds per Square Inch	na	CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,615	Air Pressure LRI	Pounds per Square Inch	na	CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,616	Air Pressure LRO	40 Pounds per Square Inch		CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		CKARLENS	Jun 27, 2018 4:34:04 PM	No	
60,633	Tread Depth RRO	4 32nds of an inch		CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,634	Tread Depth RRI	0 32nds of an inch	na	CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,635	Tread Depth LRI	0 32nds of an inch	na	CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,636	Tread Depth LRO	4 32nds of an inch	REPLACE REAR TIRES	CKARLENS	Jun 27, 2018 4:34:05 PM	Yes	51466915
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	Jun 27, 2018 4:34:05 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	Jun 27, 2018 4:34:06 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 27, 2018 4:34:07 PM	No	
77,131	Brake Pad Thickness LF	11 Inch		CKARLENS	Jun 27, 2018 4:34:08 PM	No	
77,132	Brake Pad Thickness RF	11 Inch		CKARLENS	Jun 27, 2018 4:34:08 PM	No	
77,133	Brake Pad Thickness LR	9 Inch		CKARLENS	Jun 27, 2018 4:34:21 PM	No	
77,134	Brake Pad Thickness RR	9 Inch		CKARLENS	Jun 27, 2018 4:34:21 PM	No	
77,135	Brake Rotor LF	27.8 Inch		CKARLENS	Jun 27, 2018 4:45:04 PM	No	
77,136	Brake Rotor RF	27.8 Inch		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
77,137	Brake Rotor LR	11.8 Inch		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
77,138	Brake Rotor RR	11.8 Inch		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
77,150	Check King Pins	-	na	CKARLENS	Jun 27, 2018 4:45:05 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	Jun 27, 2018 4:45:05 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	Jun 27, 2018 4:45:07 PM	No	

**LH: 20 Desc: PM C**

**Task: PM C SERVICE Performed by: CKARLENS Performed on: 27-JUN-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 27, 2018 5:29:37 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	Jun 27, 2018 5:29:37 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
107,000	FRA Change Primary Fuel Filter	-	na	CKARLENS	Jun 27, 2018 5:29:38 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
201,000	Service Crankcase Breather	Done		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Jun 27, 2018 5:29:38 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
301,000	Check and Lubricate Door Linkages	Done		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
302,000	Check Toe-In and Record Reading	-	na	CKARLENS	Jun 27, 2018 5:29:39 PM	No	
302,001	Record Toe-In Reading	Inches, fraction-actual		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		CKARLENS	Jun 27, 2018 5:29:39 PM	No	
305,000	FRA Change Differential Fluid	Yes		CKARLENS	Jun 27, 2018 5:29:39 PM	No	

**LH: 30 Desc: PRAMETER**

**Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 27-JUN-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 27, 2018 5:28:12 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



**WorkOrder**

55345 Palm Tran Connection  
v 2.2

Page 1 of 9



WorkOrder: 51998697

Invoice Number: 55345-51998697

**Client Department:**

**MRC:** 55345M

**WO Desc:**  
PM C

**Requested By:** VAMRITTEEMAL

**Created By:** VAMRITTEEMAL

**Class:** WO

**Arrangement:** Unassigned

**Potential Warranty:** No

**Equipment:** 4814

Dodge Grand Caravan Braun Entervan SE

**VIN:** 2C7WDGBG1ER476548

**Status:** 40

**Priority:** 1

**Driver:**

**Phone:**

**ETA:**

Chronology		
<b>Reported</b>	Feb 15, 2019	1:04 PM
<b>Started</b>	Feb 16, 2019	
<b>Completed</b>	Feb 16, 2019	12:01 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	172,802	DH

**WorkOrder Notes**

Line	Comment
10	PMC Service Perform PMC service Oil filter P9600 Qty1 Engine oil 5w20 qty 6 Qts Rotate tires torque wheels 100 lbs second torque 100 lbs

Activity: **10** **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
16-Feb-19	Gaspard,Ronald	1.42	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
Labor: 0.00  
Labor Hours: 1.42  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 0.00**

Activity: **20** **999 TOTAL VEHICLE**  
**Activity Note:** PM C  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** C - PM Level C  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
16-Feb-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**

55345 Palm Tran Connection  
v 2.2

Page 1 of 9



WorkOrder: 52708913

Invoice Number: 55345-52708913

**Client Department:**

**MRC:** 55345M

**WO Desc:**  
PM C

**Requested By:** DARTHURS

**Created By:** DARTHURS

**Class:** WO

**Arrangement:** Unassigned

**Potential Warranty:** No

**Equipment:** 4814

Dodge Grand Caravan Braun Entervan SE  
2C7WDGBG1ER476548

**VIN:**

**Status:** 40

**Priority:** 1

**Driver:**

**Phone:**

**ETA:**

Chronology		
<b>Reported Started</b>	Sep 23, 2019	12:00 AM
<b>Completed</b>	Sep 23, 2019	10:04 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	198,875	DH

**WorkOrder Notes**

Line	Comment
10	PMC SERVICE PREVENTIVE MAINTENANCE PERFORM AND COMPLETED PMC SERVICE

**Activity:** 10 **999 TOTAL VEHICLE**  
**Activity Note:** Light Medium Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
23-Sep-19	AMRIT TEEMAL,VISHNU	2.00	65.00	130.00

**Activity 10 Sub Total**

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>130.00</b>

**Activity:** 20 **999 TOTAL VEHICLE**  
**Activity Note:** PM C  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** C - PM Level C  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
23-Sep-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
23-Sep-19	B329(F)	FILTER, OIL SAME AS LF3681	-1.00	1.96	-1.96
23-Sep-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



**WorkOrder**

55345 Palm Tran Connection  
v 2.2  
Page 1 of 9



**WorkOrder: 53306988**  
**Invoice Number: 55345-53306988**

**Client Department:**

**MRC:** 55345M

**Equipment:** 4814

**WO Desc:**

Dodge Grand Caravan Braun Entervan SE

PM C

**VIN:** 2C7WDGBG1ER476548

**Requested By:** AOWENS

**Status:** 40

**Created By:** AOWENS

**Priority:** 1

**Class:** WO

**Driver:**

**Arrangement:** Unassigned

**Phone:**

**Potential Warranty:** No

**ETA:**

Chronology		
<b>Reported</b>	Apr 7, 2020	11:02 AM
<b>Started</b>	Apr 7, 2020	
<b>Completed</b>	Apr 8, 2020	12:17 AM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	224,851	DH

**WorkOrder Notes**

Line	Comment
10	PMC Service Perform PMC service Oil filter P9600 qty1 Engine oil 10w30 qty 5 qts

**Activity:** 10 999/999/999 TOTAL VEHICLE  
**Activity Note:** Light Duty PMI  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
07-Apr-20	Gaspard,Ronald	1.25	0.00	0.00

**Activity 10 Sub Total**

Parts: 0.00  
Labor: 0.00  
Labor Hours: 1.25  
Sublet Parts: 0.00  
Sublet Labor: 0.00  
**Activity Sub Total 0.00**

**Activity:** 20 999 TOTAL VEHICLE  
**Activity Note:** PM C  
**Reason for Repair:** 08 - Preventive Maintenance  
**Work Accomplished:** C - PM Level C  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
08-Apr-20	P9600	FILTER, OIL	1.00	3.45	3.45





**Client Department:**

**MRC:** 55345M      **Equipment:** 4814  
**WO Desc:** 55345-LIGHT DUTY PMC      **VIN:** Dodge Grand Caravan Braun Entervan SE  
 2C7WDGBG1ER476548  
**Requested By:** CVERGARA      **Status:** 40  
**Created By:** CVERGARA      **Priority:** 3  
**Class:** WO      **Driver:**  
**Arrangement:** Unassigned      **Phone:**  
**Potential Warranty:** No      **ETA:**

Chronology		
<b>Reported</b>	May 18, 2021	12:00 AM
<b>Started</b>	May 18, 2021	
<b>Completed</b>	May 18, 2021	8:01 PM
<b>Down Time</b>		

Meter	Reading	UOM
WO		DH
Life	250,565	DH

**WorkOrder Notes**

Line	Comment
10	Perform PMC Service Change Oil & Filter Lube all Pivoting Points. Check brakes Check batteries.. filter housing leaking. Parts # B329 Qty (1) Oil 10W30 Qty (5.5) Qt

**Activity: 5** **999/999/999 TOTAL VEHICLE**

**Activity Note:** PERSONAL RISK ASSESSMENT  
**Reason for Repair:** SW - Shop Work Order  
**Work Accomplished:** 06 - Inspect  
**Part Failure:** 00 - No Failure

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

**Activity 5 Sub Total**

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
<b>Activity Sub Total</b>	<b>0.00</b>

**Activity: 10** **079 DEVICES, SAFETY/STABILITY, TRAILER**

**Activity Note:** Light Duty PMI  
**Reason for Repair:** 05 - Inspection, Routine  
**Work Accomplished:** -  
**Part Failure:** -

**Activity Comments**

**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

**Labor Posted**

Date	Technician	Hours	Rate	Extended
18-May-21	Arthurs,Durvin	2.15	0.00	0.00