



Work Order

LaShundra Crowder : 9/26/2018 10:03:12 AM

4831



Work Order # 2978 [PM A/ MILES 140223]	Status NEW	
Entity Name West Palm Beach	Budget OPERATIONS	Created 9/26/2018
Priority 2-Standard	Assigned HALL, JOESPH	Due 9/25/2018
Work Type PREVENTIVE-A	Customer	Completed 9/25/2018

Services

Service Code	Service Description	Estimated Hours
PM-A		
[] PMI-002A	WALK AROUND INSPECTION	0.80
[] PMI-003A	TURN ON VEHICLES/PARKING BRAKE SET/LIGHTS ON A/C SYSTEM ON HIGHT	0.80
[] PMI-004	check body damage (note any damage)	0.00
[] PMI-005	Inspect window glass	0.00
[] PMI-006	Inspect mirrors and replaced the mirror that are missing	0.00
[] PMI-007	Inspect wiper blades	0.00
[] PMI-008	Inspect decals/number & body tape	0.00
[] PMI-009	Inspect reflectors	0.00
[] PMI-010	Inspect exterior lights	0.00
[] PMI-012	inspect Windshield crack	0.00
[] PMI-013	inspect head light high and low beam	0.15
[] PMI-014	license Plate/Valid sticker	0.00
[] PMI-015	Inspect Back-Up Lights/Alarm	0.00
[] PMI-016	Inspect clearance/ Taxi Light (If Applicable)	0.00
[] PMI-017	inspect all turn signals	0.00
[] PMI-018	check hazard	0.00
[] PMI-019	inspect breaks	0.00
[] PMI-020	inspect stairwell/ wheelchair lift lights	0.00
[] PMI-021	Inspect tire overall condition	0.00
[] PMI-022	inspect driver and transit door operation/condition	0.00
[] PMI-023	Inspect bumpers	0.00
[] PMI-024	Inspect all exterior cleanliness	0.00
[] PMI-024A	SYSTEM INSPECTION PRE-POST SERVICE ROAD TEST	0.20
[] PMI-025	Inspect engine Starting System	0.00



Work Order

LaShundra Crowder : 9/26/2018 10:03:12 AM

[]	PMI-026	Inspect instrument gages and warning lights	0.00
[]	PMI-027	Inspection Of horn operation	0.00
[]	PMI-028	inspection of wiper/washer operation	0.00
[]	PMI-029	inspection of parking brake operation/ pedal movement	0.00
[]	PMI-030	inspection of brake petal pads	0.00
[]	PMI-031	inspection of a/c heat system operation	0.00
[]	PMI-032	inspection of defrost system	0.00
[]	PMI-033	inspect brake system pulsation/stopping	0.00
[]	PMI-034	inspect vehicle pulling from side to side	0.00
[]	PMI-035	inspect tire vibration	0.00
[]	PMI-035A	VEHICLE INTERIOR	0.00
[]	PMI-036	registration, insurance and accident pack	0.00
[]	PMI-038	inspect interior lighting	0.00
[]	PMI-039	inspect rear view mirror	0.00
[]	PMI-040	inspect interior signage	0.00
[]	PMI-041	A) No Smoking	0.00
[]	PMI-042	B) Emergency Exit	0.00
[]	PMI-043	C) Complaint Information	0.00
[]	PMI-044	inspect W/C securement pouch/ Container	0.00
[]	PMI-045	inspect driver seat	0.00
[]	PMI-046	inspect transit seat	0.00
[]	PMI-046A	inspect all the seatbelt	0.00
[]	PMI-047	inspect interior finishes and trim	0.00
[]	PMI-048	inspect interior floor and step-well	0.00
[]	PMI-049	inspect handles and sanctions	0.00
[]	PMI-050	inspect cleanness/trunk- Compartment (if applicable)	0.00
[]	PMI-051	inspect cooling system- hoses for leaks	0.00
[]	PMI-051A	A/C & HEATING SYSTEM	0.00
[]	PMI-052	clean- inspect A/C Filter and outside vents front/ rear	0.00
[]	PMI-053	Ambient Temperature Outside_____F	0.00
[]	PMI-054	Ambient Temperature Inside_____F	0.00
[]	PMI-055	Outlet Temperature Front_____F	0.00
[]	PMI-056	Outlet Temperature Rear_____F	0.00



Work Order

LaShundra Crowder : 9/26/2018 10:03:12 AM

<input type="checkbox"/>	PMI-057	Fan Speed Front & Rear _____	0.00
<input type="checkbox"/>	PMI-057A	LIFT/ RAMP	0.00
<input type="checkbox"/>	PMI-058	Inspect General Operation	0.00
<input type="checkbox"/>	PMI-059	inspect abnormal noises	0.00
<input type="checkbox"/>	PMI-060	inspect lubricate Pivot points guides and latches	0.00
<input type="checkbox"/>	PMI-061	inspect hand rails	0.00
<input type="checkbox"/>	PMI-062	Inspect Inner/Outer Barrier stops	0.00
<input type="checkbox"/>	PMI-063	inspect interlock operations	0.00
<input type="checkbox"/>	PMI-064	inspect hydraulic oil ? level Condition contamination	0.00
<input type="checkbox"/>	PMI-065	inspect platforms light	0.00
<input type="checkbox"/>	PMI-066	inspection of damaged or bent Mechanism	0.00
<input type="checkbox"/>	PMI-067	inspect control operation and condition	0.00
<input type="checkbox"/>	PMI-068	inspect electrical harnesses/ exposed wires	0.00
<input type="checkbox"/>	PMI-069	inspect threshold warning plate	0.00
<input type="checkbox"/>	PMI-070	inspect all lift-tight latches & Rollers for wear	0.00
<input type="checkbox"/>	PMI-071	inspect external snap rings.. lift cycle# _____	0.00
<input type="checkbox"/>	PMI-071A	ELECTRICAL SYSTEM	0.00
<input type="checkbox"/>	PMI-072	inspect alternator-battery for loose/ broken wires	0.00
<input type="checkbox"/>	PMI-074A	ENGINE DIAGNOSTICS	0.00
<input type="checkbox"/>	PMI-075	change engine oil & filter	0.00
<input type="checkbox"/>	PMI-076	Inspect air filter	0.00
<input type="checkbox"/>	PMI-077	Inspect for fluid and leaks	0.00
<input type="checkbox"/>	PMI-078	inspect & Fill all fluid levels	0.00
<input type="checkbox"/>	PMI-079	inspect engine electrical wiring and fittings	0.00
<input type="checkbox"/>	PMI-080	computer code diagnostic as needed _____	0.50
<input type="checkbox"/>	PMI-080A	TIRE CONDITION/ WEAR PATTERN	0.00
<input type="checkbox"/>	PMI-081	torque all lug nuts/check spare tire and jack (if applicable)	0.00
<input type="checkbox"/>	PMI-082	check pressure of front tires bus 65psi, mini 36psi	0.00
<input type="checkbox"/>	PMI-083	check pressure of rear tire bus 70psi mini 36psi	0.00
<input type="checkbox"/>	PMI-084	Visual Inspection of front/ rear tire alignment	0.00
<input type="checkbox"/>	PMI-085	front end alignment as needed	0.00
<input type="checkbox"/>	PMI-087	inspect fire extinguisher expiration date DATE _____	0.00
<input type="checkbox"/>	PMI-088	inspect first aid kit	0.00



Work Order

LaShundra Crowder : 9/26/2018 10:03:12 AM

[]	PMI-089	Inspect safety triangles	0.00
[]	PMI-090	Inspect blood born kit	0.00
[]	PMI-091	inspect all securement belts and W/C tie downs	0.00
[]	PMI-092	Inspect clean and lubricate all latch systems	0.00
[]	PMI-093	inspect interlock system	0.00
[]	PMI-094	Inspect window/ door Emergency exits latches	0.00
[]	PMI-095	inspect Emergency Belt Cutter	0.00
[]	PMI-095A	FUELED VEHICLES	0.00
[]	PMI-096	inspect tank for damages	0.00

Notes

Note Date	Note Type	Service Code	Modified By
9/26/2018	GENERAL		LaShundra Crowder
<p><i>PM A SERVICE PERFORMED</i></p> <p><i>REPLACED ENGINE OIL</i></p> <p><i>REPLACED OIL FILTER</i></p> <p><i>REPLACED AIR FILTER</i></p> <p><i>REPLACED WASHER FLUID</i></p>			

Parts

Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
E-001	ENGINE OIL	WAREHOUSE []	QUART	\$1.648	6.00	\$9.89
E002-V	FILTER, OIL, VAN	WAREHOUSE []	EACH	\$2.690	1.00	\$2.69
69737	FILTER, AIR, VAN	WAREHOUSE []	EACH	\$11.000	1.00	\$11.00
WSH001	WASHER FLUID	WAREHOUSE []	QUART	\$1.690	1.00	\$1.69



Work Order

LaShundra Crowder : 9/26/2018 10:03:12 AM

Mini Van

Preventive Maintenance Inspection Vehicles

Type P.M. Performed @ 5000mil/30 Days (Circle One) A 5000 mil B 20000 C-60000

Symbols / ok Mechanic Name Joe Hall
X Repairs Needed In Red Lift Make Capacity Lb


Date 9/25/18 Not Applicable Lift Serial #
Vehicle# 4831 Lift Cycles Mileage 140223

A	B	C	A) Walk Around Inspection	A	B	C	D) Maintenance Performed
			With Vehicle Running/Parking Brake set/Lights on/A/C System On High				C) Engine Compartment/Drive train
✓			1) Body Damage (Note any Damage)	✓			1) Change Engine Oil & Filter
✓			2) Tires	✓			2) Inspect Air Filter
✓			3) Window Glass	✓			3) Inspect Drive Belts/Pulleys
✓			4) Mirrors	✓			4) Fluid Leaks
✓			5) Wiper Blades	✓			5) Fill All all Fluid Levels
✓			6) Decals/Numbers List On Separate Sheet				
✓			7) Reflectors				E) Brakes Measure:
✓			8) Lights				L/F Pads M.M.
			A) Parking				L/F Rotors M.M.
✓			B) Headlights High and Low Beam				R/F Pads M.M.
✓			C) License Plate				R/F Rotors M.M.
✓			D) Back-Up				R/R Pads/Shoes M.M.
✓			E) Clearance				R/R Rotors/Drums M.M.
✓			F) Turn Signals				L/R Pads/Shoes M.M.
✓			G Hazard				L/R Rotors/Drums M.M.
✓			H) Brake				Parking Brake Pads/Shoes M.M.
✓			I) Back-Up/Alarm				F) Air Condition Performance
✓			J) Stairwell lights	✓			1) Ambient Temperature Outside 89
✓			9) Compartment Door Operation/Condition	✓			2) Ambient temperature Inside 79
✓			10) Bumpers	✓			3) Outlet temperature Front 84
✓			B) System Inspected	✓			4) Outlet Temperature Rear 84
✓			A) Pre Service Road Test	✓			5) Record System Pressure
✓			1) Interior Cleanness				A) Suction/Low Side PSI
✓			2) Interior Condition/Seats				B) Discharge/High Side PSI
✓			3) Engine Starting System	✓			6) Fan Speeds Front & Rear 1800
✓			4) Instrument Gauges and Warning Lights				G) Air Condition System Inspection
✓			5) Horn Operation				1) Hoses Fittings For Leaks
✓			6) Wiper/Washer Operation				2) Clean Evaporator/Condenser Coils F/R
✓			7) Parking Brake Operation/Pedal Movement				4) Rear Condenser Cooling Fans
✓			8) Brake Pedal Pads				5) High/Low Pressure Switches
✓			9) Seat Belt Operation & Condition				6) Securement of Hoses and Lines
✓			10) A/C/Heaf System Operation				8) Inspect Mounting Hardware
✓			11) Defrost				9) Clean Evaporator Drains F/R
✓			12) Brake System Pulsation/Stopping				
✓			13) Vehicle Pulling from Side To Side				H) Lift/Ramp
✓			14) Tire Vibration				1) Operation/Abnormal Noises
✓			15) Cooling System Service	✓			2) Lubricate Pivot Points & Guides
✓			Vehicle Interior	✓			3) Inspect Mounting Bolts/Welds
✓			Valid FL	✓			6) Interlock Operation
✓			A) Registration	✓			11) Damaged Or Bent Mechanism
✓			B) Insurance Card	✓			12) Control Operation and Condition
✓			C) Accident Form	✓			13) Electrical Harnesses/Exposed Wiring
✓			2-Way Radio	✓			15) Inspect all Lift-Tite Latches & rollers for Wear
✓			Seat Condition	✓			16) Micro switches For adjustments
✓			Interior Signage	✓			C) Safety Equipment
✓			A) No Smoking	✓			1) Fire Extinguisher Date: 4/18
✓			B) Emergency Exit	✓			2) First Aid Kit
✓			C) Complaint Information	✓			3) Safety Triangles
✓			W/C Securement Pouch/Container	✓			4) Blood Born Kit
✓			Tires	✓			5) Wheel Chair Tie Downs/Securment Belts
✓			L/F				
✓			R/F				
✓			L/R				
✓			R/R				
✓			Wheel Alignment				

A	B	C	C) Safety Equipment			A	B	C	Annual Inspections
✓	✓	✓	1) Fire Extinguisher	Date:	4/18			Complete Annual Vehicle Inspection Form	
✓	✓	✓	2) First Aid Kit					Clean all Evaporators/Condensing Units	
✓	✓	✓	3) Safety Triangles					Recycle Recharge A/C System	
✓	✓	✓	4) Blood Born Kit					Engine Tune-Up	
			5) Wheel Chair Tie Downs/Securement Belts						
			6) Inter Lock System						
			Electrical System						
✓	✓	✓	Inspect Alt/Batteries for loose/broken Wires						
✓	✓	✓	Inspect @ Clean Battery Terminals						
✓	✓	✓	Test Alt And Record Output		14.1				
			Test Battery and record Output		12.5				
Signature Of A.S.E Certified Mechanic								Date	

Comments

pm A performed
 Replace Oil filter & O-ring
 Add 6 qts Engine Oil
 Add 1 qt Washer Fluid
 Replace Air Filter

Mechanic Name	Vehicle NO	Mileage	Job Order #	QTY	Description	Total Cost	Issued by	Labor Hrs
Joe Hall	4831	140223	2978					
				1	Oil Filter & O'ring (WL610010)			
				6 qts	Engine Oil (5W-30)			
				1 qt	Washer Fluid			
				1	Air Filter (69737)			
Mechanic's signature						Date		
						9-25-18		
Supervisor's approval						Date		
Manager's approval						Date		



Work Order

LaShundra Crowder : 1/3/2019 11:44:02 AM

1831



Work Order # 3262 [P.M.A / MILES 1444743]	Status NEW
Entity Name West Palm Beach	Budget OPERATIONS
Priority 2-Standard	Assigned HALL, JOESPH
Work Type PREVENTIVE-A	Customer
	Created 1/3/2019
	Due 1/2/2019
	Completed 1/2/2019

Services

Service Code	Service Description	Estimated Hours
M-A		
<input type="checkbox"/> PMI-002A	WALK AROUND INSPECTION	0.80
<input type="checkbox"/> PMI-003A	TURN ON VEHICLES/PARKING BRAKE SET/LIGHTS ON A/C SYSTEM ON HIGHT	0.80
<input type="checkbox"/> PMI-004	check body damage (note any damage)	0.00
<input type="checkbox"/> PMI-005	Inspect window glass	0.00
<input type="checkbox"/> PMI-006	Inspect mirrors and replaced the mirror that are missing	0.00
<input type="checkbox"/> PMI-007	Inspect wiper blades	0.00
<input type="checkbox"/> PMI-008	Inspect decals/number & body tape	0.00
<input type="checkbox"/> PMI-009	Inspect reflectors	0.00
<input type="checkbox"/> PMI-010	Inspect exterior lights	0.00
<input type="checkbox"/> PMI-012	inspect Windshield crack	0.00
<input type="checkbox"/> PMI-013	inspect head light high and low beam	0.15
<input type="checkbox"/> PMI-014	license Plate/Valid sticker	0.00
<input type="checkbox"/> PMI-015	Inspect Back-Up Lights/Alarm	0.00
<input type="checkbox"/> PMI-016	Inspect clearance/ Taxi Light (If Applicable)	0.00
<input type="checkbox"/> PMI-017	inspect all turn signals	0.00
<input type="checkbox"/> PMI-018	check hazard	0.00
<input type="checkbox"/> PMI-019	inspect breaks	0.00
<input type="checkbox"/> PMI-020	inspect stairwell/ wheelchair lift lights	0.00
<input type="checkbox"/> PMI-021	Inspect tire overall condition	0.00
<input type="checkbox"/> PMI-022	inspect driver and transit door operation/condition	0.00
<input type="checkbox"/> PMI-023	Inspect bumpers	0.00
<input type="checkbox"/> PMI-024	Inspect all exterior cleanliness	0.00
<input type="checkbox"/> PMI-024A	SYSTEM INSPECTION PRE-POST SERVICE ROAD TEST	0.20
<input type="checkbox"/> PMI-025	Inspect engine Starting System	0.00



Work Order

LaShundra Crowder : 1/3/2019 11:44:02 AM

97.	<input type="checkbox"/>	PMI-026	Inspect instrument gages and warning lights	0.00
	<input type="checkbox"/>	PMI-027	Inspection Of horn operation	0.00
	<input type="checkbox"/>	PMI-028	inspection of wiper/washer operation	0.00
	<input type="checkbox"/>	PMI-029	inspection of parking brake operation/ pedal movement	0.00
	<input type="checkbox"/>	PMI-030	inspection of brake petal pads	0.00
	<input type="checkbox"/>	PMI-031	inspection of a/c heat system operation	0.00
	<input type="checkbox"/>	PMI-032	inspection of defrost system	0.00
	<input type="checkbox"/>	PMI-033	inspect brake system pulsation/stopping	0.00
	<input type="checkbox"/>	PMI-034	inspect vehicle pulling from side to side	0.00
	<input type="checkbox"/>	PMI-035	inspect tire vibration	0.00
	<input type="checkbox"/>	PMI-035A	VEHICLE INTERIOR	0.00
	<input type="checkbox"/>	PMI-036	registration, insurance and accident pack	0.00
	<input type="checkbox"/>	PMI-038	inspect interior lighting	0.00
	<input type="checkbox"/>	PMI-039	inspect rear view mirror	0.00
	<input type="checkbox"/>	PMI-040	inspect interior signage	0.00
	<input type="checkbox"/>	PMI-041	A) No Smoking	0.00
	<input type="checkbox"/>	PMI-042	B) Emergency Exit	0.00
	<input type="checkbox"/>	PMI-043	C) Complaint Information	0.00
	<input type="checkbox"/>	PMI-044	inspect W/C securement pouch/ Container	0.00
	<input type="checkbox"/>	PMI-045	inspect driver seat	0.00
	<input type="checkbox"/>	PMI-046	inspect transit seat	0.00
	<input type="checkbox"/>	PMI-046A	inspect all the seatbelt	0.00
	<input type="checkbox"/>	PMI-047	inspect interior finishes and trim	0.00
	<input type="checkbox"/>	PMI-048	inspect interior floor and step-well	0.00
	<input type="checkbox"/>	PMI-049	inspect handles and sanctions	0.00
	<input type="checkbox"/>	PMI-050	inspect cleanness/trunk- Compartment (if applicable)	0.00
	<input type="checkbox"/>	PMI-051	inspect cooling system- hoses for leaks	0.00
	<input type="checkbox"/>	PMI-051A	A/C & HEATING SYSTEM	0.00
	<input type="checkbox"/>	PMI-052	clean- inspect A/C Filter and outside vents front/ rear	0.00
	<input type="checkbox"/>	PMI-053	Ambient Temperature Outside _____ F	0.00
	<input type="checkbox"/>	PMI-054	Ambient Temperature Inside _____ F	0.00
	<input type="checkbox"/>	PMI-055	Outlet Temperature Front _____ F	0.00
	<input type="checkbox"/>	PMI-056	Outlet Temperature Rear _____ F	0.00



Work Order

LaShundra Crowder : 1/3/2019 11:44:02 AM

<input type="checkbox"/>	PMI-057	Fan Speed Front & Rear _____	0.00
<input type="checkbox"/>	PMI-057A	LIFT/ RAMP	0.00
<input type="checkbox"/>	PMI-058	Inspect General Operation	0.00
<input type="checkbox"/>	PMI-059	inspect abnormal noises	0.00
<input type="checkbox"/>	PMI-060	inspect lubricate Pivot points guides and latches	0.00
<input type="checkbox"/>	PMI-061	inspect hand rails	0.00
<input type="checkbox"/>	PMI-062	Inspect Inner/Outer Barrier stops	0.00
<input type="checkbox"/>	PMI-063	inspect interlock operations	0.00
<input type="checkbox"/>	PMI-064	inspect hydraulic oil ? level Condition contamination	0.00
<input type="checkbox"/>	PMI-065	inspect platforms light	0.00
<input type="checkbox"/>	PMI-066	inspection of damaged or bent Mechanism	0.00
<input type="checkbox"/>	PMI-067	inspect control operation and condition	0.00
<input type="checkbox"/>	PMI-068	inspect electrical harnesses/ exposed wires	0.00
<input type="checkbox"/>	PMI-069	inspect threshold warning plate	0.00
<input type="checkbox"/>	PMI-070	inspect all lift-tight latches & Rollers for wear	0.00
<input type="checkbox"/>	PMI-071	inspect external snap rings.. lift cycle# _____	0.00
<input type="checkbox"/>	PMI-071A	ELECTRICAL SYSTEM	0.00
<input type="checkbox"/>	PMI-072	inspect alternator-battery for loose/ broken wires	0.00
<input type="checkbox"/>	PMI-074A	ENGINE DIAGNOSTICS	0.00
<input type="checkbox"/>	PMI-075	change engine oil & filter	0.00
<input type="checkbox"/>	PMI-076	Inspect air filter	0.00
<input type="checkbox"/>	PMI-077	Inspect for fluid and leaks	0.00
<input type="checkbox"/>	PMI-078	inspect & Fill all fluid levels	0.00
<input type="checkbox"/>	PMI-079	inspect engine electrical wiring and fittings	0.00
<input type="checkbox"/>	PMI-080	computer code diagnostic as needed _____	0.50
<input type="checkbox"/>	PMI-080A	TIRE CONDITION/ WEAR PATTERN	0.00
<input type="checkbox"/>	PMI-081	torque all lug nuts/check spare tire and jack (if applicable)	0.00
<input type="checkbox"/>	PMI-082	check pressure of front tires bus 65psi, mini 36psi	0.00
<input type="checkbox"/>	PMI-083	check pressure of rear tire bus 70psi mini 36psi	0.00
<input type="checkbox"/>	PMI-084	Visual Inspection of front/ rear tire alignment	0.00
<input type="checkbox"/>	PMI-085	front end alignment as needed	0.00
<input type="checkbox"/>	PMI-087	inspect fire extinguisher expiration date DATE _____	0.00
<input type="checkbox"/>	PMI-088	inspect first aid kit	0.00



Work Order

LaShundra Crowder : 1/3/2019 11:44:02 AM

[]	PMI-089	Inspect safety triangles	0.00
[]	PMI-090	Inspect blood born kit	0.00
[]	PMI-091	inspect all securement belts and W/C tie downs	0.00
[]	PMI-092	Inspect clean and lubricate all latch systems	0.00
[]	PMI-093	inspect interlock system	0.00
[]	PMI-094	Inspect window/ door Emergency exits latches	0.00
[]	PMI-095	inspect Emergency Belt Cutter	0.00
[]	PMI-095A	FUELED VEHICLES	0.00
[]	PMI-096	inspect tank for damages	0.00

Notes

Note Date	Note Type	Service Code	Modified By
1/3/2019	GENERAL		LaShundra Crowder
<i>PM A SERVICE PERFORMED</i>			
<i>REPLACED ENGINE OIL</i>			
<i>REPLACED OIL FILTER</i>			
<i>REPLACED WASHER FLUID</i>			

Parts

Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
E-C01	ENGINE OIL	WAREHOUSE []	QUART	\$1.691	6.00	\$10.14
WL610010	Mini Van Oil Filter	WAREHOUSE []	EACH	\$5.000	1.00	\$5.00
WSH001	WASHER FLUID	WAREHOUSE []	QUART	\$1.690	1.00	\$1.69



Work Order

LaShundra Crowder : 1/3/2019 11:44:02 AM

Totals	
Est. Parts Total:	\$8.38
Est. Labor Total:	\$0.00
Total	\$8.38

Mini Van

Preventive Maintenance Inspection Vehicles

Type P.M. Performed @ 5000mi/30 Days (Circle One) A 5000 mil B 20000 C-60000

Symbols	/ ok	Mechanic Name Joe Hall	
	X Repairs Needed In Red	Lift Make	Capacity
	O Not Applicable	Lift Serial #	Lb

Date **1/2/19** Vehicle# **4831** Lift Cycles _____ Mileage **144743**

A	B	C	A) Walk Around Inspection	A	B	C	D) Maintenance Performed
			With Vehicle Running/Parking Brake set/Lights on/A/C System On High				C) Engine Compartment/Drive train
✓			1) Body Damage (Note any Damage)	✓			1) Change Engine Oil & Filter
✓			2) Tires	✓			2) Inspect Air Filter
✓			3) Window Glass	✓			3) Inspect Drive Belts/Pulleys
✓			4) Mirrors	✓			4) Fluid Leaks
✓			5) Wiper Blades	✓			5) Fill All all Fluid Levels
✓			6) Decals/Numbers List On Separate Sheet				
✓			7) Reflectors				E) Brakes Measure:
✓			8) Lights				L/F Pads M.M.
✓			A) Parking				L/F Rotors M.M.
✓			B) Headlights High and Low Beam				R/F Pads M.M.
✓			C) License Plate				R/F Rotors M.M.
✓			D) Back-Up				R/R Pads/Shoes M.M.
✓			E) Clearance				R/R Rotors/Drums M.M.
✓			F) Turn Signals				L/R Pads/Shoes M.M.
✓			G) Hazard				L/R Rotors/Drums M.M.
✓			H) Brake				Parking Brake Pads/Shoes M.M.
✓			I) Back-Up/Alarm				
✓			J) Stairwell lights				F) Air Condition Performance
✓			9) Compartment Door Operation/Condition	✓			1) Ambient Temperature Outside
✓			10) Bumpers	✓			2) Ambient temperature Inside
✓			B) System Inspected	✓			3) Outlet temperature Front
✓			A) Pre Service Road Test	✓			4) Outlet Temperature Rear
✓			1) Interior Cleanness	✓			5) Record System Pressure
✓			2) Interior Condition/Seats	✓			A) Suction/Low Side PSI
✓			3) Engine Starting System	✓			B) Discharge/High Side PSI
✓			4) Instrument Gauges and Warning Lights				6) Fan Speeds Front & Rear
✓			5) Horn Operation				G) Air Condition System Inspection
✓			6) Wiper/Washer Operation				1) Hoses Fittings For Leaks
✓			7) Parking Brake Operation/Pedal Movement				2) Clean Evaporator/Condenser Coils F/R
✓			8) Brake Pedal Pads				4) Rear Condenser Cooling Fans
✓			9) Seat Belt Operation & Condition				5) High/Low Pressure Switches
✓			10) A/C/Heaf System Operation				6) Securement of Hoses and Lines
✓			11) Defrost				8) Inspect Mounting Hardware
✓			12) Brake System Pulsation/Stopping				9) Clean Evaporator Drains F/R
✓			13) Vehicle Pulling from Side To Side				
✓			14) Tire Vibration				H) Lift/Ramp
✓			15) Cooling System Service	✓			1) Operation/Abnormal Noises
✓			Vehicle Interior	✓			2) Lubricate Pivot Points & Guides
✓			Valid FL	✓			3) Inspect Mounting Bolts/Welds
✓			A) Registration	✓			6) Interlock Operation
✓			B) Insurance Card	✓			11) Damaged Or Bent Mechanism
✓			C) Accident Form	✓			12) Control Operation and Condition
✓			2-Way Radio	✓			13) Electrical Harnesses/Exposed Wiring
✓			Seat Condition	✓			15) Inspect all Lift-Tite Latches & rollers for Wear
✓			Interior Signage	✓			16) Micro switches For adjustments
✓			A) No Smoking	✓			C) Safety Equipment
✓			B) Emergency Exit	✓			1) Fire Extinguisher Date: 4/18
✓			C) Complaint Information	✓			2) First Aid Kit
✓			W/C Securement Pouch/Container	✓			3) Safety Triangles
✓			Tires	✓			4) Blood Born Kit
✓			L/F	✓			5) Wheel Chair Tie Downs/Securment Belts
✓			R/F	✓			
✓			L/R	✓			
✓			R/R	✓			
✓			Wheel Alignment	✓			

A	B	C	C) Safety Equipment			A	B	C	Annual Inspections
✓	✓	✓	1) Fire Extinguisher	Date:	4/18			Complete Annual Vehicle Inspection Form	
✓	✓	✓	2) First Aid Kit					Clean all Evaporators/Condensing Units	
✓	✓	✓	3) Safety Triangles					Recycle Recharge A/C System	
✓	✓	✓	4) Blood Bom Kit					Engine Tune-Up	
✓	✓	✓	5) Wheel Chair Tie Downs/Securement Belts						
✓	✓	✓	6) Inter Lock System						
			Electrical System						
✓	✓	✓	Inspect All/Batteries for loose/broken Wires						
✓	✓	✓	Inspect @ Clean Battery Terminals						
✓	✓	✓	Test Alt And Record Output		14.2				
✓	✓	✓	Test Battery and record Output		12.5				

Signature Of A.S.E Certified Mechanic

Date

Comments

pm A performed

Replace Oil Filter & O'ring
 Add 6qt Engine Oil
 Add 1qt Washer Fluid

Mechanic Name: Joe Hull
Vehicle NO: 4831
Mileage: 144743
Work Order #: 3262
QTY: 1
Description: Oil Filter (WLG10010)
Total Cost: [blank]
Issued by: [blank]
Labor Hrs: [blank]

1 Oil Filter (WLG10010)

6qt Engine Oil (5W-30)

1qt Washer Fluid

Mechanic's signature
Supervisor's approval
Manager's approval



Date
Date
Date

12/19



Work Order

LaShundra Crowder : 2/19/2019 3:27:26 PM

4831



Work Order # 3406 [PM A / MILES 149886]	Status NEW	
Entity Name West Palm Beach	Budget OPERATIONS	Created 2/19/2019
Priority 2-Standard	Assigned HALL, JOESPH	Due 2/15/2019
Work Type PREVENTIVE-A	Customer	Completed 2/15/2019

Services

Service Code	Service Description	Estimated Hours
PM-A		
<input type="checkbox"/> PMI-002A	WALK AROUND INSPECTION	0.80
<input type="checkbox"/> PMI-003A	TURN ON VEHICLES/PARKING BRAKE SET/LIGHTS ON A/C SYSTEM ON HIGHT	0.80
<input type="checkbox"/> PMI-004	check body damage (note any damage)	0.00
<input type="checkbox"/> PMI-005	Inspect window glass	0.00
<input type="checkbox"/> PMI-006	Inspect mirrors and replaced the mirror that are missing	0.00
<input type="checkbox"/> PMI-007	Inspect wiper blades	0.00
<input type="checkbox"/> PMI-008	Inspect decals/number & body tape	0.00
<input type="checkbox"/> PMI-009	Inspect reflectors	0.00
<input type="checkbox"/> PMI-010	Inspect exterior lights	0.00
<input type="checkbox"/> PMI-012	inspect Windshield crack	0.00
<input type="checkbox"/> PMI-013	inspect head light high and low beam	0.15
<input type="checkbox"/> PMI-014	license Plate/Valid sticker	0.00
<input type="checkbox"/> PMI-015	Inspect Back-Up Lights/Alarm	0.00
<input type="checkbox"/> PMI-016	Inspect clearance/ Taxi Light (If Applicable)	0.00
<input type="checkbox"/> PMI-017	inspect all turn signals	0.00
<input type="checkbox"/> PMI-018	check hazard	0.00
<input type="checkbox"/> PMI-019	inspect breaks	0.00
<input type="checkbox"/> PMI-020	inspect stairwell/ wheelchair lift lights	0.00
<input type="checkbox"/> PMI-021	Inspect tire overall condition	0.00
<input type="checkbox"/> PMI-022	inspect driver and transit door operation/condition	0.00
<input type="checkbox"/> PMI-023	Inspect bumpers	0.00
<input type="checkbox"/> PMI-024	Inspect all exterior cleanliness	0.00
<input type="checkbox"/> PMI-024A	SYSTEM INSPECTION PRE-POST SERVICE ROAD TEST	0.20
<input type="checkbox"/> PMI-025	Inspect engine Starting System	0.00



Work Order

LaShundra Crowder : 2/19/2019 3:27:26 PM

<input type="checkbox"/>	PMI-026	Inspect instrument gages and warning lights	0.00
<input type="checkbox"/>	PMI-027	Inspection Of horn operation	0.00
<input type="checkbox"/>	PMI-028	inspection of wiper/washer operation	0.00
<input type="checkbox"/>	PMI-029	inspection of parking brake operation/ pedal movement	0.00
<input type="checkbox"/>	PMI-030	inspection of brake petal pads	0.00
<input type="checkbox"/>	PMI-031	inspection of a/c heat system operation	0.00
<input type="checkbox"/>	PMI-032	inspection of defrost system	0.00
<input type="checkbox"/>	PMI-033	inspect brake system pulsation/stopping	0.00
<input type="checkbox"/>	PMI-034	inspect vehicle pulling from side to side	0.00
<input type="checkbox"/>	PMI-035	inspect tire vibration	0.00
<input type="checkbox"/>	PMI-035A	VEHICLE INTERIOR	0.00
<input type="checkbox"/>	PMI-036	registration, insurance and accident pack	0.00
<input type="checkbox"/>	PMI-038	inspect interior lighting	0.00
<input type="checkbox"/>	PMI-039	inspect rear view mirror	0.00
<input type="checkbox"/>	PMI-040	inspect interior signage	0.00
<input type="checkbox"/>	PMI-041	A) No Smoking	0.00
<input type="checkbox"/>	PMI-042	B) Emergency Exit	0.00
<input type="checkbox"/>	PMI-043	C) Complaint Information	0.00
<input type="checkbox"/>	PMI-044	inspect W/C securement pouch/ Container	0.00
<input type="checkbox"/>	PMI-045	inspect driver seat	0.00
<input type="checkbox"/>	PMI-046	inspect transit seat	0.00
<input type="checkbox"/>	PMI-046A	inspect all the seatbelt	0.00
<input type="checkbox"/>	PMI-047	inspect interior finishes and trim	0.00
<input type="checkbox"/>	PMI-048	inspect interior floor and step-well	0.00
<input type="checkbox"/>	PMI-049	inspect handles and sanctions	0.00
<input type="checkbox"/>	PMI-050	inspect cleanness/trunk- Compartment (if applicable)	0.00
<input type="checkbox"/>	PMI-051	inspect cooling system- hoses for leaks	0.00
<input type="checkbox"/>	PMI-051A	A/C & HEATING SYSTEM	0.00
<input type="checkbox"/>	PMI-052	clean- inspect A/C Filter and outside vents front/ rear	0.00
<input type="checkbox"/>	PMI-053	Ambient Temperature Outside_____F	0.00
<input type="checkbox"/>	PMI-054	Ambient Temperature Inside_____F	0.00
<input type="checkbox"/>	PMI-055	Outlet Temperature Front_____F	0.00
<input type="checkbox"/>	PMI-056	Outlet Temperature Rear_____F	0.00



Work Order

LaShundra Crowder : 2/19/2019 3:27:26 PM

[]	PMI-057	Fan Speed Front & Rear _____	0.00
[]	PMI-057A	When lowering lift platform, the platform stops half way down.	2.00
[]	PMI-058	Inspect General Operation	0.00
[]	PMI-059	inspect abnormal noises	0.00
[]	PMI-060	inspect lubricate Pivot points guides and latches	0.00
[]	PMI-061	inspect hand rails	0.00
[]	PMI-062	Inspect Inner/Outer Barrier stops	0.00
[]	PMI-063	inspect interlock operations	0.00
[]	PMI-064	inspect hydraulic oil ? level Condition contamination	0.00
[]	PMI-065	inspect platforms light	0.00
[]	PMI-066	inspection of damaged or bent Mechanism	0.00
[]	PMI-067	inspect control operation and condition	0.00
[]	PMI-068	inspect electrical harnesses/ exposed wires	0.00
[]	PMI-069	inspect threshold warning plate	0.00
[]	PMI-070	inspect all lift-tight latches & Rollers for wear	0.00
[]	PMI-071	inspect external snap rings.. lift cycle# _____	0.00
[]	PMI-071A	ELECTRICAL SYSTEM	0.00
[]	PMI-072	inspect alternator-battery for loose/ broken wires	0.00
[]	PMI-074A	ENGINE DIAGNOSTICS	0.00
[]	PMI-075	change engine oil & filter Mileage 212283	1.00
[]	PMI-076	Inspect air filter	0.00
[]	PMI-077	Inspect for fluid and leaks	0.00
[]	PMI-078	inspect & Fill all fluid levels	0.00
[]	PMI-079	inspect engine electrical wiring and fittings	0.00
[]	PMI-080	computer code diagnostic as needed _____	0.50
[]	PMI-080A	TIRE CONDITION/ WEAR PATTERN	0.00
[]	PMI-081	torque all lug nuts/check spare tire and jack (if applicable)	0.00
[]	PMI-082	check pressure of front tires bus 65psi, mini 36psi	0.00
[]	PMI-083	check pressure of rear tire bus 70psi mini 36psi	0.00
[]	PMI-084	Visual Inspection of front/ rear tire alignment	0.00
[]	PMI-085	front end alignment as needed	0.00
[]	PMI-087	inspect fire extinguisher expiration date DATE _____	0.00
[]	PMI-088	inspect first aid kit	0.00



Work Order

LaShundra Crowder : 2/19/2019 3:27:26 PM

[]	PMI-089	Inspect safety triangles	0.00
[]	PMI-090	Inspect blood born kit	0.00
[]	PMI-091	inspect all securement belts and W/C tie downs	0.00
[]	PMI-092	Inspect clean and lubricate all latch systems	0.00
[]	PMI-093	inspect interlock system	0.00
[]	PMI-094	Inspect window/ door Emergency exits latches	0.00
[]	PMI-095	inspect Emergency Belt Cutter	0.00
[]	PMI-095A	FUELED VEHICLES	0.00
[]	PMI-096	inspect tank for damages	0.00

Notes

Note Date	Note Type	Service Code	Modified By
2/19/2019	GENERAL		LaShundra Crowder

*PM A SERVICE PERFORMED
 REPLACED ENGINE OIL
 REPLACED OIL FILTER
 REPLACED WASHER FLUID*

Parts

Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
--------	-------------	----------	-----------------	-----------	----------	-------

Mini Van

Preventive Maintenance Inspection Vehicles:

Type P.M. Performed @ 5000mil/30 Days (Circle One) A 5000 mil B 20000 C-60000

Symbols	/ ok X Repairs Needed In Red O Not Applicable	Mechanic Name Joe Hall	Lift Make Capacity
Date: 2/5/19	Vehicle#: 4831	Lift Serial #	Mileage: 149886

A) Walk Around Inspection			D) Maintenance Performed		
A	B	C	A	B	C
With Vehicle Running/Parking Brake set/Lights on/A/C System On High			C) Engine Compartment/Drive train		
1) Body Damage (Note any Damage)			1) Change Engine Oil & Filter		
2) Tires			2) Inspect Air Filter		
3) Window Glass			3) Inspect Drive Belts/Pulleys		
4) Mirrors			4) Fluid Leaks		
5) Wiper Blades			5) Fill All all Fluid Levels		
6) Decals/Numbers List On Separate Sheet			E) Brakes Measure:		
7) Reflectors			L/F Pads M.M.		
8) Lights			L/F Rotors M.M.		
A) Parking			R/F Pads M.M.		
B) Headlights High and Low Beam			R/F Rotors M.M.		
C) License Plate			R/R Pads/Shoes M.M.		
D) Back Up			R/R Rotors/Drums M.M.		
E) Clearance			L/R Pads/Shoes M.M.		
F) Turn Signals			L/R Rotors/Drums M.M.		
G) Hazard			Parking Brake Pads/Shoes M.M.		
H) Brake			F) Air Condition Performance		
I) Back-Up/Alarm			1) Ambient Temperature Outside		
J) Stairwell lights			2) Ambient temperature Inside		
9) Compartment Door Operation/Condition			3) Outlet temperature Front		
10) Bumpers			4) Outlet Temperature Rear		
B) System Inspected			5) Record System Pressure		
A) Pre Service Road Test			A) Suction/Low Side PSI		
1) Interior Cleanness			B) Discharge/High Side PSI		
2) Interior Condition/Seats			6) Fan Speeds Front & Rear		
3) Engine Starting System			G) Air Condition System Inspection		
4) Instrument Gauges and Warning Lights			1) Hoses Fittings For Leaks		
5) Horn Operation			2) Clean Evaporator/Condenser Coils F/R		
6) Wiper/Washer Operation			4) Rear Condenser Cooling Fans		
7) Parking Brake Operation/Pedal Movement			5) High/Low Pressure Switches		
8) Brake Pedal Pads			6) Securement of Hoses and Lines		
9) Seat Belt Operation & Condition			8) Inspect Mounting Hardware		
10) A/C/Heat System Operation			9) Clean Evaporator Drains F/R		
11) Defrost			H) Lift/Ramp		
12) Brake System Pulsation/Stopping			1) Operation/Abnormal Noises		
13) Vehicle Pulling from Side To Side			2) Lubricate Pivot Points & Guides		
14) Tire Vibration			3) Inspect Mounting Bolts/Welds		
15) Cooling System Service			6) Interlock Operation		
Vehicle Interior			11) Damaged Or Bent Mechanism		
Valid FL			12) Control Operation and Condition		
A) Registration			13) Electrical Harnesses/Exposed Wiring		
B) Insurance Card			15) Inspect all Lift-Tile Latches & rollers for Wear		
C) Accident Form			16) Micro switches For adjustments		
2-Way Radio			C) Safety Equipment		
Seat Condition			1) Fire Extinguisher Date: 4/18		
Interior Signage			2) First Aid Kit		
A) No Smoking			3) Safety Triangles		
B) Emergency Exit			4) Blood Born Kit		
C) Complaint Information			5) Wheel Chair Tie Downs/Securement Belts		
W/C Securement Pouch/Container					
Tires					
L/F					
R/F					
L/R					
R/R					
Wheel Alignment					

A	B	C		A	B	C
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	C) Safety Equipment			Annual Inspections
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	1) Fire Extinguisher			Complete Annual Vehicle Inspection Form
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2) First Aid Kit			Clear all Evaporators/Condensing Units
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3) Safety Triangles			Recycle Recharge A/C System
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4) Blood Bombs			Engine Tune-Up
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	5) Wheel Chai Tie Down/Securement Balls			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	6) Inter Lock System			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Electrical System			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Inspect All Batteries for loose/broken Wires			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Inspect @ Clean Battery Terminals			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Test Alt And Record Output	14.1		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Test Battery and record Output	12.5		

Date: 4/18

Signature Of A.S.E Certified Mechanic


Date

Comments

pm A performed
 Replace Oil Filter & Oil
 Add 6qt Engine Oil
 Add 1qt Washer Fluid

Mechanic Name Joe Hall	Vehicle Number 4831	Mileage 149886	Work Order # 3104
---------------------------	------------------------	-------------------	----------------------

DESCRIPTION	
Oil Filter	
6qt Engine Oil (5W-30)	
1qt Washer Fluid	

Mechanic Signature 	Date: 2/15/19
Supervisor Approval	Date:
Manager Approval	Date:



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52305726
Invoice Number: 55345-52305726

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
 GRAND CARAVAN SE
VIN: 2C7WDGBG1ER476565
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 1, 2019	3:51 PM
Started	May 1, 2019	
Completed	May 1, 2019	11:03 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	157,866	DH
System	158,058	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points .check Brakes . Parts#P9600 Qty (1) Oil 5W20QTY Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-May-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
 Labor: 65.00
 Labor Hours: 1.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
01-May-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52393433

Invoice Number: 55345-52393433

Client Department:

MRC: 55345M

WO Desc:
PM A

Requested By: DARTHURS

Created By: DARTHURS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4831

GRAND CARAVAN SE
2C7WDGBG1ER476565

VIN:
Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	May 29, 2019	3:27 PM
Started	May 29, 2019	
Completed	May 29, 2019	10:29 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	162,113	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter . lube all Pivoting Points , Check Brakes Parts#P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
29-May-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
29-May-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52551232
Invoice Number: 55345-52551232

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:			GRAND CARAVAN SE
PM A		VIN:	2C7WDGBG1ER476565
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Aug 1, 2019	3:23 PM
Started	Aug 1, 2019	
Completed	Aug 1, 2019	9:11 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,553	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. check brakes. Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Aug-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
02-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 9



WorkOrder: 52655642
Invoice Number: 55345-52655642

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:			GRAND CARAVAN SE
PM A		VIN:	2C7WDGBG1ER476565
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology			
Reported	Sep 16, 2019		12:00 AM
Started	Sep 16, 2019		
Completed	Sep 16, 2019		8:32 PM
Down Time			

Meter	Reading	UOM
WO		DH
Life	175,335	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Sep-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	97.50

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
16-Sep-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder: 53597638
Invoice Number: 55345-53597638

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGGB1ER476565
Requested By:	DARTHURS	Priority:	40
Created By:	DARTHURS	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Aug 11, 2020	12:00 AM
Started	Aug 11, 2020	
Completed	Aug 12, 2020	12:01 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	184,013	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: CAUSE: CORRECTION:
20	Perform PMC Service.Change Oil & Filter. Lube all Pivoting Points. Check Brakes.Check Battery. transmission Pan Leaking R/F Strut Making Noise. Parts # P9600 Qty (1) Oil 10W30 Qty (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder: 53773927
Invoice Number: 55345-53773927

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	DARTHURS	Priority:	40
Created By:	DARTHURS	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Nov 13, 2020	12:00 AM
Started	Nov 13, 2020	
Completed	Nov 14, 2020	12:17 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	188,336	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: Service CORRECTION:perform PmA Service Oil P9600 Qty1 Engine oil 10w30 qty 5 1/2 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 54210481
Invoice Number: 55345-54210481

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Mar 23, 2021	2:25 PM
Started	Mar 23, 2021	
Completed	Mar 24, 2021	12:14 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	196,555	DH
System	196,556	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter P9600 qty1 Engine oil 10w30 qty 6 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder: 54407080
Invoice Number: 55345-54407080

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	May 7, 2021	12:00 AM
Started	May 7, 2021	
Completed	May 7, 2021	7:09 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,978	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter Lube all Pivoting. Check brakes. Check batteries. Parts # P 9600 Qty (1) Oil 10W30 Qty (5.5) Qt.

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder: 54680037
Invoice Number: 55345-54680037

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Aug 26, 2021	9:16 AM
Started	Aug 26, 2021	
Completed	Aug 26, 2021	11:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	209,524	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA
	CAUSE: preventive maintenance
	CORRECTION: Performed service PMA completed

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 54845464
Invoice Number: 55345-54845464

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	HPIERRE	Priority:	40
Created By:	HPIERRE	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Sep 28, 2021	12:00 AM
Started	Sep 28, 2021	
Completed	Sep 29, 2021	12:23 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,824	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA
	CAUSE:Service
	CORRECTION:Perform pmA Service
	Oil filter P9600 qty1
	Engine oil 10w30 qty 5 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 12



WorkOrder: 55717276
Invoice Number: 55345-55717276

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDG1ER476565
Requested By:	JUHURST	Priority:	40
Created By:	JUHURST	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Aug 17, 2022	12:00 AM
Started	Aug 18, 2022	
Completed	Aug 18, 2022	8:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,194	DH
System	223,194	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: vehicle came in for service
	CAUSE: Service due by Mileage
	CORRECTION: Service job complete also change oil filter part p9600

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Aug-22	P9600	FILTER, OIL	1.00	3.49	3.49

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 2 of 12



WorkOrder: 55717276
Invoice Number: 55345-55717276

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG1ER476565
Requested By:	JUHURST	Priority:	40
Created By:	JUHURST	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Date	Technician	Hours	Rate	Extended
18-Aug-22	Junior Hurst	1.88	0.00	0.00

Activity 10 Sub Total

Parts:	3.49
Labor:	0.00
Labor Hours: 1.88	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.49

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Aug-22	Junior Hurst	0.67	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.67	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 55717276 Grand Total

Parts:	3.49
Labor:	0.00
Labor Hours: 2.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.49

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55717276	18-Aug-22	223,194	WO	55345-LIGHT DUTY PMA
55792147	21-Jul-22	219,396	WO	VAN OVERHEATING CONDITION

Scheduled Preventative Maintenance



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 12



WorkOrder: 55717276
Invoice Number: 55345-55717276

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
 GRAND CARAVAN SE
VIN: 2C7WDGBG1ER476565
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 55717276 Desc: 55345-LIGHT DUTY PMA
Equip: 4831 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG1ER476565

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 18-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Aug 18, 2022 6:13:42 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Aug 18, 2022 6:13:38 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Aug 18, 2022 7:20:53 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Aug 18, 2022 7:21:06 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Aug 18, 2022 7:21:12 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Aug 18, 2022 7:21:16 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Aug 18, 2022 7:21:25 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Aug 18, 2022 7:21:30 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Aug 18, 2022 7:25:35 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Aug 18, 2022 7:25:39 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Aug 18, 2022 7:26:09 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Aug 18, 2022 7:26:15 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Aug 18, 2022 7:26:21 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Aug 18, 2022 7:26:25 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Aug 18, 2022 7:26:30 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Aug 18, 2022 7:30:31 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Aug 18, 2022 7:30:49 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Aug 18,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2022 7:30:57 PM		
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Aug 18, 2022 7:31:03 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Aug 18, 2022 7:31:08 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Aug 18, 2022 7:31:13 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Aug 18, 2022 7:31:21 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Aug 18, 2022 7:31:28 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Aug 18, 2022 7:31:33 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Aug 18, 2022 7:31:38 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Aug 18, 2022 7:31:47 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Aug 18, 2022 7:31:58 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Aug 18, 2022 7:32:03 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Aug 18, 2022 7:32:08 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Aug 18, 2022 7:32:39 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Aug 18, 2022 7:32:44 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Aug 18, 2022 7:32:51 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Aug 18, 2022 7:32:59 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 18, 2022 7:33:13 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Aug 18, 2022 7:33:21 PM	No	
32,000	Engine Inspection	Done		JUHURST	Aug 18, 2022 7:33:29 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Aug 18, 2022 7:33:33 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Aug 18, 2022 7:33:38 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Aug 18, 2022 7:33:45 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Aug 18, 2022 7:34:01 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Aug 18, 2022 7:34:42 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Aug 18, 2022 7:34:53 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Aug 18, 2022 7:35:01 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Aug 18, 2022 7:35:11 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Aug 18, 2022 7:35:19 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Aug 18, 2022 7:35:33 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Aug 18, 2022 7:35:44 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Aug 18, 2022 7:35:49 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Aug 18, 2022 7:35:58 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Aug 18, 2022 7:36:14 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 18, 2022 7:36:22 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Aug 18, 2022 7:36:26 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Aug 18, 2022 7:36:31 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Aug 18, 2022 7:37:04 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Aug 18, 2022 7:37:13 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Aug 18, 2022 7:37:47 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Aug 18, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:37:55 PM		
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Aug 18, 2022 7:38:00 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Aug 18, 2022 7:38:05 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Aug 18, 2022 7:39:36 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Aug 18, 2022 7:40:09 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Aug 18, 2022 7:40:17 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Aug 18, 2022 7:40:26 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Aug 18, 2022 7:40:45 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Aug 18, 2022 7:41:48 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Aug 18, 2022 7:42:17 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Aug 18, 2022 7:42:24 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Aug 18, 2022 7:42:33 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Aug 18, 2022 7:42:37 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Aug 18, 2022 7:42:52 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Aug 18, 2022 7:43:00 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Aug 18, 2022 7:43:09 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Aug 18, 2022 7:43:16 PM	No	
50,500	!FRA!CHANGE_Engine oil, filters	Done		JUHURST	Aug 18, 2022 7:43:26 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Aug 18, 2022 7:43:32 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Aug 18, 2022 7:43:40 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose	Done		JUHURST	Aug 18,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Lugs/Indicators, Outer Hub Leaks				2022 7:43:45 PM		
51,000	RECORD_LF-Tire Tread Depth (32nds)	0 32nds of an inch		JUHURST	Aug 18, 2022 7:44:20 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Aug 18, 2022 7:44:27 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch	this. vehicle need two tires in the front worn out	JUHURST	Aug 18, 2022 7:46:46 PM	Yes	55868954
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Aug 18, 2022 7:47:09 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Aug 18, 2022 7:47:13 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Aug 18, 2022 7:47:22 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Aug 18, 2022 7:47:27 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 18, 2022 7:48:11 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 18, 2022 7:48:27 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.269 Inch		JUHURST	Aug 18, 2022 7:49:10 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.269 Inch		JUHURST	Aug 18, 2022 7:49:22 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Aug 18, 2022 7:49:27 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Aug 18, 2022 7:49:40 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		JUHURST	Aug 18, 2022 7:49:46 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Aug 18, 2022 7:49:51 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Aug 18, 2022 7:50:04 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Aug 18, 2022 7:50:09 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Aug 18, 2022 7:50:15 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Aug 18, 2022 7:50:20 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Aug 18, 2022 7:50:29 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Aug 18, 2022 7:50:34 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Aug 18, 2022 7:50:47 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Aug 18, 2022 7:50:43 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Aug 18, 2022 7:50:53 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Aug 18, 2022 7:51:02 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Aug 18, 2022 7:51:06 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Aug 18, 2022 7:51:11 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Aug 18, 2022 7:51:16 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Aug 18, 2022 7:51:20 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 18, 2022 7:51:25 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Aug 18, 2022 7:51:46 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Aug 18, 2022 7:52:04 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Aug 18, 2022 7:52:12 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Aug 18, 2022 7:52:19 PM	No	
55,000	!FRA!INSPECT_REAR Brake Assemblies	Done		JUHURST	Aug 18, 2022 7:52:24 PM	No	
55,100	!FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Aug 18, 2022 7:52:30 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Aug 18, 2022 7:52:35 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 18, 2022 7:52:49 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 18, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					7:52:58 PM		
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Aug 18, 2022 7:53:16 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Aug 18, 2022 7:53:25 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Aug 18, 2022 7:53:30 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Aug 18, 2022 7:53:36 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Aug 18, 2022 7:53:51 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Aug 18, 2022 7:53:47 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		JUHURST	Aug 18, 2022 7:54:14 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Aug 18, 2022 7:54:20 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Aug 18, 2022 7:54:41 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Aug 18, 2022 7:54:47 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Aug 18, 2022 7:57:29 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Aug 18, 2022 7:57:51 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Aug 18, 2022 7:58:02 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Aug 18, 2022 7:58:07 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Aug 18, 2022 7:58:12 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Aug 18, 2022 7:58:19 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Aug 18, 2022 7:59:59 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Aug 18, 2022 8:00:21 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Aug 18, 2022 8:00:38 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for	Done		JUHURST	Aug 18,	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Loose Bolts Broken Welds, etc.				2022 8:00:43 PM		
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Aug 18, 2022 8:00:47 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Aug 18, 2022 8:00:52 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Aug 18, 2022 8:00:57 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Aug 18, 2022 8:01:01 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Aug 18, 2022 8:01:06 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Aug 18, 2022 8:01:11 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Aug 18, 2022 8:01:16 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Aug 18, 2022 8:01:20 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Aug 18, 2022 8:01:25 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Aug 18, 2022 8:01:30 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Aug 18, 2022 8:01:34 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Aug 18, 2022 8:01:43 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Aug 18, 2022 8:01:48 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Aug 18, 2022 8:01:53 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Aug 18, 2022 8:01:58 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Aug 18, 2022 8:02:03 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: JUHURST Performed on: 18-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Aug 18, 2022 5:30:26 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Aug 18, 2022 6:12:11 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Aug 18, 2022 6:12:03 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
103,000	FRA Check Transmission Fluid	Done		JUHURST	Aug 18, 2022 6:12:18 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Aug 18, 2022 6:12:22 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Aug 18, 2022 6:12:27 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Aug 18, 2022 6:12:32 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Aug 18, 2022 6:12:37 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 18-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Aug 18, 2022 5:28:58 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Aug 18, 2022 5:28:54 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Aug 18, 2022 5:29:04 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Aug 18, 2022 5:29:09 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 18, 2022 5:29:13 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 18, 2022 5:29:18 PM	No	



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 55868960
Invoice Number: 55345-55868960

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGGB1ER476565
Requested By:	JUHURST	Priority:	40
Created By:	JUHURST	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Sep 16, 2022	12:00 AM
Started	Sep 21, 2022	
Completed	Sep 21, 2022	8:13 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	228,066	DH
System	227,690	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: VEHICLE CAME IN FOR SERVICE CAUSE: SERVICE DUE BY MILEAGE CORRECTION: SERVICE JOB COMPLETE ALSO CHANGE OIL FILTER P9600 RETURN VEHICLE BACK TO WORK

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10
Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-Sep-22	P9600	FILTER, OIL	1.00	3.49	3.49

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 2 of 10



WorkOrder: 55868960
Invoice Number: 55345-55868960

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:			GRAND CARAVAN SE
55345-LIGHT DUTY PMA		VIN:	2C7WDGBG1ER476565
Requested By:	JUHURST	Status:	40
Created By:	JUHURST	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Date	Technician	Hours	Rate	Extended
21-Sep-22	Junior Hurst	2.18	0.00	0.00

Activity 10 Sub Total

Parts:	3.49
Labor:	0.00
Labor Hours: 2.18	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.49

Activity: **20** **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Sep-22	Junior Hurst	0.38	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.38	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 55868960 Grand Total

Parts:	3.49
Labor:	0.00
Labor Hours: 2.56	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.49

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55868960	21-Sep-22	228,066	WO	55345-LIGHT DUTY PMA
55969129	21-Sep-22	227,693	WO	55345 PER DVIR (Replace Wiper Blades)
55717276	18-Aug-22	223,194	WO	55345-LIGHT DUTY PMA



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 10



WorkOrder: 55868960
Invoice Number: 55345-55868960

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
VIN: GRAND CARAVAN SE
 2C7WDGBG1ER476565
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

**PH: Work Order: 55868960 Desc: 55345-LIGHT DUTY PMA
 Equip: 4831 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG1ER476565**

**LH: 10 Desc: Light Duty PMI
 Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 21-SEP-22**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Sep 21, 2022 6:05:34 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Sep 21, 2022 6:05:29 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Sep 21, 2022 6:41:43 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Sep 21, 2022 6:41:48 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Sep 21, 2022 6:43:42 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Sep 21, 2022 6:58:04 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Sep 21, 2022 6:58:09 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Sep 21, 2022 6:59:04 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Sep 21, 2022 6:59:11 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Sep 21, 2022 7:00:25 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Sep 21, 2022 7:00:40 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Sep 21, 2022 7:00:45 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Sep 21, 2022 7:00:53 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Sep 21, 2022 7:01:13 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Sep 21, 2022 7:01:21 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Sep 21, 2022 7:01:28 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Sep 21, 2022 7:02:20 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Sep 21, 2022 7:02:24 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Sep 21, 2022 7:02:30 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Sep 21, 2022 7:02:45 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Sep 21, 2022 7:03:00 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Sep 21, 2022 7:03:09 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Sep 21, 2022 7:03:22 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Sep 21, 2022 7:03:27 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls	Done		JUHURST	Sep 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	and Panels				7:03:32 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Sep 21, 2022 7:03:48 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Sep 21, 2022 7:04:14 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Sep 21, 2022 7:04:28 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Sep 21, 2022 7:04:38 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Sep 21, 2022 7:04:52 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Sep 21, 2022 7:04:56 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 21, 2022 7:05:01 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 21, 2022 7:05:07 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 21, 2022 7:05:14 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 21, 2022 7:05:19 PM	No	
32,000	Engine Inspection	Done		JUHURST	Sep 21, 2022 7:05:30 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Sep 21, 2022 7:05:34 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Sep 21, 2022 7:05:51 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Sep 21, 2022 7:06:05 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Sep 21, 2022 7:06:12 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Sep 21, 2022 7:06:18 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Sep 21, 2022 7:06:32 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Sep 21, 2022 7:06:53 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Sep 21, 2022 7:08:20 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Sep 21, 2022 7:08:29 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Sep 21, 2022 7:08:36 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Sep 21, 2022 7:08:48 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Sep 21, 2022 7:57:19 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Sep 21, 2022 7:08:54 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Sep 21, 2022 7:09:04 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Sep 21, 2022 7:09:10 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 21, 2022 7:09:16 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Sep 21, 2022 7:09:23 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Sep 21, 2022 7:09:30 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Sep 21, 2022 7:09:36 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Sep 21, 2022 7:09:41 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Sep 21, 2022 7:09:50 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Sep 21, 2022 7:09:54 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Sep 21, 2022 7:09:59 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Sep 21, 2022 7:10:06 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Sep 21, 2022 7:10:11 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Sep 21, 2022 7:10:15 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Sep 21, 2022 7:10:52 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Sep 21, 2022 7:11:00 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Sep 21, 2022 7:11:10 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Sep 21, 2022 7:11:27 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Sep 21, 2022 7:11:38 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Sep 21, 2022 7:11:50 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Sep 21, 2022 7:12:19 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Sep 21, 2022 7:12:29 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Sep 21, 2022 7:12:41 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Sep 21, 2022 7:12:56 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Sep 21, 2022 7:13:02 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Sep 21, 2022 7:13:43 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Sep 21, 2022 7:14:03 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Sep 21, 2022 7:14:19 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 21, 2022 7:14:59 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 21, 2022 7:15:04 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Sep 21, 2022 7:28:16 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per		JUHURST	Sep 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		Square Inch			7:29:08 PM		
51,200	RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Sep 21, 2022 7:31:26 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 21, 2022 7:31:42 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Sep 21, 2022 7:32:21 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Sep 21, 2022 7:32:27 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Sep 21, 2022 7:32:44 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 21, 2022 7:33:38 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Sep 21, 2022 7:37:48 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Sep 21, 2022 7:38:44 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Sep 21, 2022 7:39:00 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Sep 21, 2022 7:39:14 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Sep 21, 2022 7:40:06 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		JUHURST	Sep 21, 2022 7:40:12 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Sep 21, 2022 7:40:30 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		JUHURST	Sep 21, 2022 7:40:58 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Sep 21, 2022 7:41:06 PM	No	
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Sep 21, 2022 7:41:16 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Sep 21, 2022 7:41:32 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Sep 21, 2022 7:41:40 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Sep 21, 2022 7:42:41 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Sep 21, 2022 7:42:50 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Sep 21, 2022 7:42:56 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Sep 21, 2022 7:43:03 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Sep 21, 2022 7:43:11 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Sep 21, 2022 7:43:15 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Sep 21, 2022 7:43:44 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Sep 21, 2022 7:43:51 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Sep 21, 2022 7:43:57 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Sep 21, 2022 7:44:04 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 21, 2022 7:45:10 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 21, 2022 7:45:41 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Sep 21, 2022 7:46:15 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Sep 21, 2022 7:46:26 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Sep 21, 2022 7:46:31 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Sep 21, 2022 7:46:38 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Sep 21, 2022 7:46:43 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Sep 21, 2022 7:47:27 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Sep 21, 2022 7:47:37 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Sep 21, 2022 8:00:37 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Sep 21, 2022 8:02:14 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Sep 21, 2022 8:02:19 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Sep 21, 2022 8:02:33 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Sep 21, 2022 8:02:39 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Sep 21, 2022 8:02:44 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		JUHURST	Sep 21, 2022 8:02:57 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Sep 21, 2022 8:03:01 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Sep 21, 2022 8:03:06 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Sep 21, 2022 8:03:14 PM	No	
60,500	INSPECT_Bridgeplate Operation	Done		JUHURST	Sep 21, 2022 8:03:20 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Sep 21, 2022 8:03:25 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Sep 21, 2022 8:03:30 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Sep 21, 2022 8:03:37 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Sep 21, 2022 8:04:14 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Sep 21, 2022 8:04:19 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Sep 21, 2022 8:04:24 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires	Done		JUHURST	Sep 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	and Cables				8:04:28 PM		
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Sep 21, 2022 8:04:33 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Sep 21, 2022 8:04:38 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Sep 21, 2022 8:04:42 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Sep 21, 2022 8:04:47 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Sep 21, 2022 8:04:52 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Sep 21, 2022 8:04:57 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Sep 21, 2022 8:05:01 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Sep 21, 2022 8:05:06 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Sep 21, 2022 8:05:11 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Sep 21, 2022 8:05:41 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Sep 21, 2022 8:05:37 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Sep 21, 2022 8:05:49 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Sep 21, 2022 8:05:54 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Sep 21, 2022 8:05:59 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Sep 21, 2022 8:06:07 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Sep 21, 2022 8:06:11 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Sep 21, 2022 8:06:16 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Sep 21, 2022 8:06:20 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: JUHURST Performed on: 21-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Sep 21, 2022 5:38:58 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Sep 21, 2022 5:39:02 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Sep 21, 2022 5:39:22 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Sep 21, 2022 5:39:26 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Sep 21, 2022 5:39:34 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Sep 21, 2022 5:39:38 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Sep 21, 2022 5:39:46 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Sep 21, 2022 5:39:54 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-SEP-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Sep 21, 2022 5:37:01 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 21, 2022 5:36:56 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Sep 21, 2022 5:37:07 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Sep 21, 2022 5:37:11 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 21, 2022 5:37:16 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 21, 2022 5:37:21 PM	No	



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52472980

Invoice Number: 55345-52472980

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
VIN: GRAND CARAVAN SE
 2C7WDGBG1ER476565
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 25, 2019	4:12 PM
Started	Jun 25, 2019	
Completed	Jun 26, 2019	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	166,160	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check Brakes. Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Jun-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts: 0.00
 Labor: 97.50
 Labor Hours: 1.50
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 97.50

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
25-Jun-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder: 54053656
Invoice Number: 55345-54053656

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMB		Status:	2C7WDG1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Jan 14, 2021	12:06 PM
Started	Jan 14, 2021	
Completed	Jan 15, 2021	12:05 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	192,489	DH
System	192,561	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: service CORRECTION:perform PMB service Oil filter P9600 qty1 Engine oil 10w30 qty 5 1/2 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 54942346
Invoice Number: 55345-54942346

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMB		Status:	2C7WDGGB1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Jun 20, 2022	12:00 AM
Started	Jun 23, 2022	
Completed	Jun 23, 2022	8:53 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	218,533	DH
System	218,414	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: vehicle came in for service
	CAUSE: Service due by Mileage
	CORRECTION: job complete also change oil filter part # p9600

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
23-Jun-22	P9600	FILTER, OIL	1.00	3.49	3.49

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 2 of 10



WorkOrder: 54942346
Invoice Number: 55345-54942346

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMB		Status:	2C7WDGGB1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Date	Technician	Hours	Rate	Extended
23-Jun-22	Junior Hurst	3.20	0.00	0.00

Activity 10 Sub Total

Parts:	3.49
Labor:	0.00
Labor Hours: 3.20	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.49

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Jun-22	Junior Hurst	2.15	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.15	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

WorkOrder 54942346 Grand Total

Parts:	3.49
Labor:	0.00
Labor Hours: 5.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	3.49

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
54942346	23-Jun-22	218,533	WO	55345-LIGHT DUTY PMB
55710960	22-Jun-22	218,414	WO	55345 PER DVIR (Window Goes Down Some Times)
55642456	27-May-22	216,350	WO	check engine light on



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 10



WorkOrder: 54942346
Invoice Number: 55345-54942346

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMB		Status:	2C7WDGBG1ER476565
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55710960	21-Jun-22	218,414	WO	55345 PER DVIR (Window Goes Down Some Times)

PH: Work Order: 54942346 Desc: 55345-LIGHT DUTY PMB
Equip: 4831 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG1ER476565

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 23-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Jun 23, 2022 3:34:13 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jun 23, 2022 3:34:07 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Jun 23, 2022 5:41:09 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jun 23, 2022 5:44:42 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jun 23, 2022 5:44:46 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jun 23, 2022 5:44:53 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jun 23, 2022 5:46:38 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jun 23, 2022 5:46:47 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jun 23, 2022 5:51:19 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jun 23, 2022 5:54:35 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jun 23, 2022 5:54:40 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jun 23, 2022 5:54:44 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jun 23, 2022 5:54:49 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jun 23, 2022 5:54:55 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Jun 23, 2022 5:55:18 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jun 23, 2022 5:55:23 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jun 23, 2022 5:55:36 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jun 23, 2022 5:55:42 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jun 23, 2022 5:55:52 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jun 23, 2022 5:55:58 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jun 23, 2022 6:05:01 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Jun 23, 2022 5:56:27 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jun 23, 2022 5:56:41 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jun 23, 2022 6:05:01 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles,	Done		JUHURST	Jun 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Controls and Panels				5:57:29 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jun 23, 2022 5:57:34 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Jun 23, 2022 5:57:41 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jun 23, 2022 5:57:50 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Jun 23, 2022 5:58:01 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Jun 23, 2022 5:58:14 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Jun 23, 2022 5:58:19 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jun 23, 2022 5:58:28 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jun 23, 2022 5:58:34 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2022 5:58:45 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Jun 23, 2022 5:58:52 PM	No	
32,000	Engine Inspection	Done		JUHURST	Jun 23, 2022 5:59:51 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Jun 23, 2022 6:00:00 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jun 23, 2022 6:00:04 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jun 23, 2022 6:00:09 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jun 23, 2022 6:00:14 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jun 23, 2022 6:00:21 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jun 23, 2022 6:00:26 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jun 23, 2022 6:00:33 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jun 23, 2022 6:00:38 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jun 23, 2022 6:00:47 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Jun 23, 2022 6:00:53 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jun 23, 2022 6:01:14 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Jun 23, 2022 6:01:18 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jun 23, 2022 6:01:37 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jun 23, 2022 6:01:42 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2022 6:01:49 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Jun 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:01:54 PM		
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jun 23, 2022 6:02:04 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Jun 23, 2022 6:01:59 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jun 23, 2022 6:02:14 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jun 23, 2022 6:02:19 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jun 23, 2022 6:02:29 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jun 23, 2022 6:02:24 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jun 23, 2022 6:02:42 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jun 23, 2022 6:02:46 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jun 23, 2022 6:02:51 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jun 23, 2022 6:03:03 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jun 23, 2022 6:03:07 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jun 23, 2022 6:03:12 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Jun 23, 2022 6:03:16 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Jun 23, 2022 6:03:22 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jun 23, 2022 6:03:27 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done	ramp working perfect	JUHURST	Jun 23, 2022 6:05:02 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jun 23, 2022 6:03:39 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jun 23, 2022 6:03:44 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Jun 23, 2022 6:03:53 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jun 23, 2022 6:04:00 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Jun 23, 2022 6:05:32 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jun 23, 2022 6:05:27 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Jun 23, 2022 6:05:37 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jun 23, 2022 6:05:41 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jun 23, 2022 6:05:46 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2022 6:06:09 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per		JUHURST	Jun 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		Square Inch			6:06:26 PM		
51,200	RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jun 23, 2022 6:06:38 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Jun 23, 2022 6:06:46 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jun 23, 2022 6:06:51 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jun 23, 2022 6:06:59 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Jun 23, 2022 6:07:03 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2022 6:07:21 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2022 6:07:49 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.526 Inch		JUHURST	Jun 23, 2022 6:08:08 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.526 Inch		JUHURST	Jun 23, 2022 6:09:00 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Jun 23, 2022 6:09:06 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jun 23, 2022 6:09:13 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		JUHURST	Jun 23, 2022 6:09:18 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jun 23, 2022 6:09:25 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		JUHURST	Jun 23, 2022 6:09:30 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jun 23, 2022 6:09:53 PM	No	
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jun 23, 2022 6:09:58 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Jun 23, 2022 6:10:03 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jun 23, 2022 6:10:11 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jun 23, 2022 6:10:22 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jun 23, 2022 6:10:27 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jun 23, 2022 6:10:33 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jun 23, 2022 6:10:37 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Jun 23, 2022 6:10:49 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jun 23, 2022 6:10:53 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Jun 23, 2022 6:11:02 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jun 23, 2022 6:12:09 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jun 23, 2022 6:12:20 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jun 23, 2022 6:12:32 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch	right rear leaking nail in tire	JUHURST	Jun 23, 2022 6:14:39 PM	Yes	55717139
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Jun 23, 2022 6:14:59 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Jun 23, 2022 6:15:10 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Jun 23, 2022 6:15:18 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jun 23, 2022 6:15:26 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jun 23, 2022 6:15:32 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jun 23, 2022 6:15:43 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2022 6:16:00 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jun 23, 2022 6:16:12 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.5 Inch		JUHURST	Jun 23, 2022 6:16:49 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.5 Inch		JUHURST	Jun 23, 2022 6:17:11 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jun 23, 2022 6:17:15 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jun 23, 2022 6:17:25 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jun 23, 2022 6:17:30 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jun 23, 2022 6:17:36 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		JUHURST	Jun 23, 2022 6:17:58 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jun 23, 2022 6:18:02 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jun 23, 2022 6:18:13 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jun 23, 2022 6:18:30 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Jun 23, 2022 6:18:55 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jun 23, 2022 6:19:01 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jun 23, 2022 6:19:07 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jun 23, 2022 6:19:14 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jun 23, 2022 6:19:19 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jun 23, 2022 6:19:25 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jun 23, 2022 6:19:30 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jun 23, 2022 6:19:48 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jun 23, 2022 6:19:41 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jun 23, 2022 6:20:01 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jun 23, 2022 6:19:57 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Jun 23, 2022 6:20:08 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jun 23, 2022 6:20:12 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jun 23, 2022 6:20:17 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Jun 23, 2022 6:20:21 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jun 23, 2022 6:20:26 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jun 23, 2022 6:20:31 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jun 23, 2022 6:20:37 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Jun 23, 2022 6:20:42 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Jun 23, 2022 6:20:46 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Jun 23, 2022 6:20:51 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Jun 23, 2022 6:20:56 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Jun 23, 2022 6:21:00 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Jun 23, 2022 6:21:05 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jun 23, 2022 6:21:09 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jun 23, 2022 6:21:14 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: JUHURST Performed on: 23-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Jun 23, 2022 8:11:43 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Jun 23, 2022 8:11:39 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Jun 23, 2022 8:11:54 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Jun 23, 2022 8:11:58 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Jun 23, 2022 8:12:03 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Jun 23, 2022 8:12:12 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Jun 23, 2022 8:12:16 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Jun 23, 2022 8:12:21 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Jun 23, 2022 8:12:26 PM	No	
201,000	Service Crankcase Breather	Done		JUHURST	Jun 23, 2022 8:12:48 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		JUHURST	Jun 23, 2022 8:13:27 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		JUHURST	Jun 23, 2022 8:13:36 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Jun 23, 2022 8:13:44 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 23-JUN-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Jun 23, 2022 3:06:56 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 23, 2022 3:07:47 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Jun 23, 2022 3:07:53 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Jun 23, 2022 3:07:58 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 23, 2022 3:08:04 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 23, 2022 3:09:33 PM	No	



Key, Shacoya: 5/10/2018 12:32:33 PM

Work Order



4831

Work Order # 2348 [PM-C SERVICE MILES 133872] Status COMPLETED

Entity Name West Palm Beach Budget OPERATIONS Created 5/10/2018
 Priority 2-Standard Assigned HALL, JOSEPH Due 5/7/2018
 Work Type PREVENTATIVE-C Customer Completed 5/7/2018

Custom Fields

Asset

Asset ID 4831 Schedule
 Group Tree WEST PALM BEACH Manufacturer DODGE Model CARAVAN
 Category VEHICLES Serial # 2C7WDBG1ER476565
 Type VAN

Asset Custom Fields

ENGINE SIZE: LENGTH: 16 LICENSE PLATE #: LOCATION: West Palm Beach
 LICENSE PLATE: LIFT MANUFACTURER: MANUFACTURER: YEAR: 2014
 EXPIRATION: Alliance Bus WARRANTY EXPIRATION: SALES
 VENDOR: EXPIRATION: EXPIRATION:

Services

Service Code	Service Description	Estimated Hours
MP1-104	torque all lug nuts/check spare tire and jack (if applicable)	0.00
PM1-0	WALK AROUND INSPECTION	0.00
PM1-01	TURN ON VEHICLE/PARKING BRAKE SET/LIGHTS ON A/C SYSTEM ON HIGH	0.00
PM1-0102	replace fuel filter	0.00
PM1-0103	flush/change trans fluid as needed	0.00
PM1-0149	inspect slack adjusters and chambers	0.00
PM1-02	inspect body damage (note any damage)	0.00
PM1-03	inspect window glass	0.00
PM1-04	inspect mirrors	0.00
PM1-05	inspect wiper blades	0.00
PM1-06	inspect decal numbers	0.00
PM1-07	inspect reflectors	0.00
PM1-08	inspect all lights	0.00

PM-B

000000





Work Order

Key, Shacoya: 5/10/2018 12:32:33 PM

0.00	[N]	PMI-09	Inspect parking light
0.00	[N]	PMI-10	Inspect headlights high and low beam
0.00	[N]	PMI-103A	TIRE CONDITION/ WEAR PATTERN
0.00	[N]	PMI-105	check pressure of front tires bus 65 psi van 36 psi
0.00	[N]	PMI-106	check pressure of rear tires
0.00	[N]	PMI-107	visual inspection of front/ rear alignment
0.00	[N]	PMI-108	balance all tires and brake inspection
0.00	[N]	PMI-109	front end alignment as needed
0.00	[N]	PMI-11	inspect license plate valid sticker
0.00	[N]	PMI-110	Record thread Depth Rotate Replaced L/F _____/32 _____psi R/F _____/32 _____psi L/R/O _____/32 _____psi L/R/I _____/32 _____psi R/R/O _____/32 _____psi R/R/I _____/32 _____psi
0.00	[N]	PMI-111	fire extinguisher expiration date _____
0.00	[N]	PMI-112	inspect first aid kit
0.00	[N]	PMI-113	inspect safety triangles (3)
0.00	[N]	PMI-114	inspect blood born kit
0.00	[N]	PMI-115	inspect securement belts and w/c tie downs
0.00	[N]	PMI-116	inspect fire suppression system for low pressure/ leak/ hose kink expiration date _____ serial # _____
0.00	[N]	PMI-117	inspect all securement belts- w/c tie downs
0.00	[N]	PMI-118	inspect inter-lock system
0.00	[N]	PMI-119	inspect window/ door emergency exit latches
0.00	[N]	PMI-12	inspect back up lights and alarm
0.00	[N]	PMI-120	inspect emergency belt cutter
0.00	[N]	PMI-120A	FUELED VEHICLES
0.00	[N]	PMI-121	inspect tank for damage
0.00	[N]	PMI-122	inspect all components (including hoses) are properly fastened
0.00	[N]	PMI-123	inspect all hoses for rubbing & possible leaks
0.00	[N]	PMI-124	inspect all electrical harnesses and power connections including grounds
0.00	[N]	PMI-125	road test vehicle on both fuels
0.00	[N]	PMI-126	inspect leak test the following with liquid soap
0.00	[N]	PMI-127	inspect filter unit
0.00	[N]	PMI-128	inspect injector rails





Key, Shacoya: 5/10/2018 12:32:33 PM

Work Order

0.00	[N]	PMI-129	inspect corresponding hoses/ tubing connections
0.00	[N]	PMI-13	inspect clearance/ taxi light if applicable
0.00	[N]	PMI-130	inspect injector hoses
0.00	[N]	PMI-131	inspect vacuum leak test following
0.00	[N]	PMI-132	inspect intake manifold
0.00	[N]	PMI-133	inspect manifold nipples
0.00	[N]	PMI-134	inspect all vacuum hoses
0.00	[N]	PMI-135	perform engine code test
0.00	[N]	PMI-136	inspect tubing connections
0.00	[N]	PMI-137	verify system pressure and correction 4.0 bar reading
0.00	[N]	PMI-138	replace filters
0.00	[N]	PMI-138A	*****
0.00	[N]	PMI-139	*****
0.00	[N]	PMI-139A	BRAKES
0.00	[N]	PMI-14	inspect turn signals
0.00	[N]	PMI-140	L/F PADS MM
0.00	[N]	PMI-141	L/F ROTOR MM
0.00	[N]	PMI-142	R/F PADS MM
0.00	[N]	PMI-143	R/F ROTOR MM
0.00	[N]	PMI-144	R/R PADS MM
0.00	[N]	PMI-145	R/R ROTOR MM
0.00	[N]	PMI-146	L/R PAD MM
0.00	[N]	PMI-147	L/R ROTOR MM
0.00	[N]	PMI-148	inspect parking brakes
0.00	[N]	PMI-15	inspect hazard
0.00	[N]	PMI-150	inspect brake hoses and lines
0.00	[N]	PMI-151	check wheel cylinders for leaks
0.00	[N]	PMI-152	inspect callipers/ slides/ mounting bolts
0.00	[N]	PMI-16	inspection of the brakes
0.00	[N]	PMI-17	inspect stairwell/ wheelchair lift light
0.00	[N]	PMI-18	inspect overall condition
0.00	[N]	PMI-19	inspect driver and transit door operation/ condition





Work Order

PMI-20	inspect bumpers	[N]	0.00
PMI-200	inspect exhaust system	[N]	0.00
PMI-201	replace serpentine belt as needed	[N]	0.00
PMI-21	inspect exterior cleanliness	[N]	0.00
PMI-21A	SYSTEM INSPECTION	[N]	0.00
PMI-22	inspect engine starting system	[N]	0.00
PMI-23	inspect instrument gages and warning lights	[N]	0.00
PMI-24	inspect horn operation	[N]	0.00
PMI-25	inspect wiper/washer operation	[N]	0.00
PMI-26	inspect parking brake operation/ pedal movement	[N]	0.00
PMI-27	inspect brake pedal pads	[N]	0.00
PMI-28	inspect a/c heat system operation	[N]	0.00
PMI-29	inspect defrost	[N]	0.00
PMI-30	inspect brake system pulsation/stopping	[N]	0.00
PMI-31	inspect vehicle pulling from side to side	[N]	0.00
PMI-32	inspect the tire vibration	[N]	0.00
PMI-32A	VEHICLE INTERIOR	[N]	0.00
PMI-33	inspect vehicle registration, insurance and accident pack	[N]	0.00
PMI-34	inspect all the seatbelt and tie down, pull and re-track proper. Blue belt _____ Tie down _____ Extension belt _____ Belt securment _____ Shoulder belt Male _____ Female _____ Belt adapter _____ Floor adapter _____	[N]	0.00
PMI-35	inspect interior lighting	[N]	0.00
PMI-36	inspect rear view mirror	[N]	0.00
PMI-37	inspect interior storage bag	[N]	0.00
PMI-38	A) no smoking	[N]	0.00
PMI-39	B) Emergency Exit	[N]	0.00
PMI-40	C) complaint information	[N]	0.00
PMI-41	inspect W/C securment pouch/ container	[N]	0.00
PMI-42	inspect driver seat	[N]	0.00
PMI-43	inspect transit seat	[N]	0.00
PMI-44	inspect interior finishes and trim	[N]	0.00
PMI-45	inspect interior flood and step-well	[N]	0.00





Work Order

Key, Shacoya: 5/10/2018 12:32:33 PM

PMI-46	[Y]	inspect handles and sanctions	0.00
PMI-47	[Y]	inspect interior cleanliness/trunk-compartment	0.00
PMI-47A	[Y]	COOLING SYSTEM	0.00
PMI-48	[Y]	inspect cooling system- hoses for leaks	0.00
PMI-49	[Y]	inspect radiator/cap fans,pump and clamps REPLACED RADIATOR	2.00
PMI-50	[Y]	pressure test and cooling system _____ psi	0.00
PMI-51	[Y]	inspect upper and lower control arms and ball joints	0.00
PMI-52	[Y]	inspect steering linkage- lubricate	0.00
PMI-53	[Y]	inspect steering hoses, links, arms and rods	0.00
PMI-54	[Y]	inspect shocks-struts front/rear	0.00
PMI-55	[Y]	inspect rear hub and axle seals	0.00
PMI-56	[Y]	inspect lubricate all grease fitting	0.00
PMI-57	[Y]	inspect rear leaf springs/bushing/u-bolts	0.00
PMI-57A	[Y]	AIR CONDITIONING PERFORMANCE	0.00
PMI-58	[Y]	clean-inspect A/C filter and outside vents front/rear	0.00
PMI-59	[Y]	Ambient Temperature outside _____61 _____ F	0.00
PMI-60	[Y]	Ambient temperature inside _____ F	0.00
PMI-61	[Y]	outlet temperature front _____ F	0.00
PMI-62	[Y]	outlet temperature rear _____ F	0.00
PMI-63	[Y]	inspect fan speed front and rear _____	0.00
PMI-63A	[Y]	AIR CONDITION SYSTEM INSPECTION	0.00
PMI-64	[Y]	inspect hoses fittings for leaks	0.00
PMI-65	[Y]	inspect & clean evaporator/condenser coils F/R	0.00
PMI-66	[Y]	inspect front and rear condenser cooling fans	0.00
PMI-67	[Y]	inspect high/low pressure switches	0.00
PMI-68	[Y]	securement hoses and lines	0.00
PMI-69	[Y]	inspect mounting hardware	0.00
PMI-69A	[Y]	LIFT/RAMP	0.00
PMI-70	[Y]	inspect general operation	0.00
PMI-71	[Y]	inspect abnormal noise	0.00
PMI-72	[Y]	inspect lubricate pivot points, guides and latches	0.00
PMI-73	[Y]	inspect hand rails	0.00



Notes

0.00	PMI-74	inspect inner/outer barrier stops	[N]
0.00	PMI-75	inspect interlock operation	[N]
0.00	PMI-76	inspect hydraulic oil level/ condition contamination	[N]
0.00	PMI-77	inspect platform lights	[N]
0.00	PMI-78	inspect damage or bent mechanism	[N]
0.00	PMI-79	inspect control operation and condition	[N]
0.00	PMI-80	inspect electrical harnesses/ exposed wiring	[N]
0.00	PMI-81	inspect threshold warning plate	[N]
0.00	PMI-82	inspect all lift-tight latches & rollers for wear	[N]
0.00	PMI-83	inspect external snap rings	[N]
0.00	PMI-84	inspect hydraulic oil leaks hoses cylinder	[N]
0.00	PMI-85	inspect hoses for rubbing	[N]
0.00	PMI-86	inspect micro and power switches, control board and circuits	[N]
0.00	PMI-87	inspect-lubricate barriers on platform pivot pin, inner roll stop,rotating side-arm, parallel arm, hand rail pins.	[N]
0.00	PMI-88	inspect alternator-battery for loose/ broken wires	[N]
0.00	PMI-89	inspect and clean battery terminals	[N]
0.00	PMI-90	Test battery and record	[N]
0.00	PMI-91	inspect test alternator and record	[N]
0.00	PMI-91A	ENGINE DIAGNOSTIC	[N]
0.00	PMI-92	change engine oil filter	[N]
0.00	PMI-93	inspect air filter	[N]
0.00	PMI-94	inspect for fluid leaks	[N]
0.00	PMI-95	inspect and fill fluids leaks	[N]
0.00	PMI-96	inspect engine electrical wiring and fitting	[N]
0.00	PMI-97	check computer code diagnostic as needed	[N]
0.00	PMI-98	inspect drive belt tensioner	[N]
0.00	PMI-99	inspect drive belt pulleys	[N]
0.00	PMI-999	TECHNICIAN SIGNATURE	[N]
0.00		DATE	[N]







Work Order

Key, Shacoya: 5/10/2018 12:32:33 PM

Note Date

Note Type

Service Code

Modified By

5/10/2018

GENERAL

Key, Shacoya

**PM-C SERVICE WAS PERFORMED
BUT PM-B SERVICE WAS USED.**

5/10/2018

GENERAL

Key, Shacoya

PM-C SERVICE

ADDED 7 QTS ENGINE OIL

ADDED 6 QTS OF TRANSMISSION FLUID

REPLACED TRANSMISSION FILTER

ADDED 1 QT WASHER FLUID

REPLACED AIR FILTER

REPLACED FRONT BRAKE PADS

NOTE: SCAN CODE CATALYST SYSTEM LOW EFFIENECY BANK 2
RIGHT REAR WHEEL STUD & LUG NUT MISSING.

Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
E-001	ENGINE OIL	WAREHOUSE []	QUART	\$1,500	6.00	\$9,00
E002-V	FILTER, OIL, VAN	WAREHOUSE []	EACH	\$12,690	1.00	\$12,69
WSH001	WASHER FLUID	WAREHOUSE []	EACH	\$0,660	1.00	\$0,66
BR002-V	BRAKE-PADS, REAR, VAN	WAREHOUSE []	EACH	\$35,090	1.00	\$35,09

Parts



Contact Name	Equipment Used	Labor Date	Labor	Hours	Labor Rate	Labor Total
Totals						
			Act. Labor Total:			\$0.00
			Act. Parts Total:			\$92.51
			Total			\$92.51


WAREHOUSE []	EAC	QU/RT	EAC	Hours	Labor Rate	Labor Total
WAREHOUSE []	EAC	QU/RT	H	1.00	\$13.990	\$13.99
WAREHOUSE []	EAC	QU/RT	RT	6.00	\$1.680	\$10.08
WAREHOUSE []	EAC	QU/RT	H	1.00	\$11.000	\$11.00

FILTER, AIR, VAN
 FLUID, TRANSMISSION, VAN
 FILTER, TRANSMISSION, VAN

Key, Shacoya: 5/10/2018 12:32:33 PM

Work Order





Preventive Maintenance Inspection Vehicles

Type P.M. Performed @ 5000mi/30 Days (Circle One) A 5000 mi B 20000 C 50000

Symbols / ok
 X Repairs Needed In Red
 O Not Applicable
 Vehicle# 4831
 Lift Serial #
 Lift Make
 Mechanic Name
 Capacity
 Lb
 Mileage 133872

Date: 5/7/18

(A) Walk Around Inspection (B) C A

With Vehicle Running/Parking Brake

Test Lights on/A/C System On High

(1) Body Damage (Note any Damage)

(2) Tires

(3) Window Glass

(4) Mirrors

(5) Wiper Blades

(6) Decals/Numbers List On Separate Sheet

(7) Reflectors

(8) Lights

(A) Parking

(B) Headlights High and Low Beam

(C) License Plate

(D) Back-Up

(E) Clearance

(F) Turn Signals

(G) Hazard

(H) Brake

(I) Back-Up/Alarm

(J) Stairwell lights

(9) Compartment Door Operation/Condition

(10) Bumpers

(B) System Inspected

(A) Fire Service Road Test

(1) Interior Cleaness

(2) Interior Condition/Seats

(3) Engine Starting System

(4) Instrument Gauges and Warning Lights

(5) Horn Operation

(6) Wiper/Washer Operation

(7) Parking Brake Operation/Pedal Movement

(8) Brake Pedal Pads

(9) Seat Belt Operation & Condition

(10) A/C/Heat System Operation

(11) Defrost

(12) Brake System Pulsator/Stopping

(13) Vehicle Pulling from Side To Side

(14) Tire Vibration

(15) Cooling System Service

Vehicle Interior

Valid FL

(A) Registration

(B) Insurance Card

(2) Accident Form

(2-Way Radio

Seat Condition

Interior Signage

(4) No Smoking

(B) Emergency Exit

(C) Complaint Information

(W/C Securement Pouch/Container

Tires

(L/F

(R/F

(L/R

(R/R

Wheel Alignment

(5) Wheel Chair Tie Downs/Securement Belts

(4) Blood Bom Kit

(3) Safety Triangles

(2) First Aid Kit

(1) Fire Extinguisher

Date: 4/18

(1) Safety Equipment

(18) Micro switches For adjustments

(18) Inspect all Lift-Tie Latches & rollers for Wear

(18) Electrical Harnesses/Exposed Wiring

(12) Control Operation and Condition

(11) Damaged Or Bent Mechanism

(8) Interlock Operation

(2) Inspect Mounting Bolts/Welds

(2) Lubricate Pivot Points & Guides

(1) Operation/Abnormal Noises

H/Lift/Ramp

(9) Clean Evaporator Drains F/R

(8) Inspect Mounting Hardware

(7) Securement of Hoses and Lines

(5) High/Low Pressure Switches

(4) Rear Condenser/Cooling Fans

(2) Clean Evaporator/Condenser Coils F/R

(1) Hoses Fittings For Leaks

(1) Air Condition System Inspection

(6) Fan Speeds Front & Rear

(B) Discharge/High Side

(A) Suction/Low Side

(5) Record System Pressure

(4) Outlet Temperature Rear

(3) Outlet temperature Front

(2) Ambient temperature Inside

(1) Ambient Temperature Outside

(F) Air Condition Performance

(M.M. Parking Brake Pads/Shoes

(M.M. L/R Rotors/Drums

(M.M. L/R Pads/Shoes

(M.M. R/R Rotors/Drums

(M.M. R/R Pads/Shoes

(M.M. L/R Rotors

(M.M. L/R Pads

(M.M. L/R Rotors

(M.M. L/R Pads

(E) Brakes Measure:

(5) Fill All all Fluid Levels

(4) Fluid Leaks

(3) Inspect Drive Belts/Pulleys

(2) Inspect Air Filter

(1) Change Engine Oil & Filter

(C) Engine Compartment/Drive train

(D) Maintenance Performed

(C) A B A

(A) Walk Around Inspection

(Lift Cycles

Mileage 133872

Mini Van

A	B	C	Date:	4/18
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	1) Fire Extinguisher	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2) First Aid Kit	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3) Safety Triangles	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4) Blood Bom Kit	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	5) Wheel Chair Tie Downs/Securement Belts	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	6) Inter Lock System	
			Electrical System	
			Inspect AH/Batteries for loose/broken Wires	
			Inspect @ Clean Battery Terminals	
			Test Alt And Record Output	13.84
			Test Battery and record Output	12.90
			Annual Inspections	
			Complete Annual Vehicle Inspection Form	
			Hear all Evaporators/Condensing Units	
			Recycle Recharge A/C System	
			Engine Tune-Up	

Signature Of A.S.E Certified Mechanic

Comments

Date

PMC Service

Replace Oil Filter

ADD 20W5 Engine Oil

ADD 6 QTS Transmission Fluid

Replace Transmission Fluid

ADD 1QT Washer Fluid

Replace Air Filter

Replace front brake pads

note: Scan code catalyst system low efficiency bank 2

Right rear wheel stud & lug nut missing

Mechanic Name	Vehicle NO	Mileage	Work Order #	QTY	Description	Total Cost	Issued by	Labor Hrs
Joe Hall	4831	135872		1	Oil Filter (WLG10010)			
					6qt Engine Oil (5W-30)			
				1	Trans Filter (B-350)			
				6qt	Trans Fluid			
				1qt	Washer Fluid			
				1	Air Filter			
				1	Brake pads (PC1589)			
Mechanic's signature								
Supervisor's approval								
Manager's approval								
Date	5/7/18							





Work Order

LaShundra Crowder : 7/14/2018 2:09:34 PM

4831



Work Order # 2615 [PM C/ MILES 137985]	Status NEW	
Entity Name West Palm Beach	Budget OPERATIONS	Created 7/14/2018
Priority 2-Standard	Assigned Carnes Masse	Due 7/14/2018
Work Type PREVENTATIVE-C	Customer	Completed 7/14/2018

Services

	Service Code	Service Description	Estimated Hours
PM-C			
[√]	001	Walk Around Vehicle WUTH VEHICLE RUNNING/PARKING BRAKES SET/LIGHTS ON/A/C SYSTEM ON HIGH	0.00
[√]	002	1.) Body Damage (note any damage)	0.25
[√]	003	2.) Tires looked low when I checked 2 tires needed to be replaced	0.00
[√]	004	3) Window Glass	0.00
[√]	006	4.) Wiper Blades	0.00
[√]	PM - 98C	INSPECT MOUNTING BLOTS / WELDS	0.00
[√]	PM- 05C	Inspect Mirrors	0.00
[√]	PM -06C	INSPECT WIPER BLADES	0.00
[√]	PM- 07C	INSPECT DECALS/NUMBERS	0.00
[√]	PM -08C	INSPECT REFLECTORS	0.00
[√]	PM -09C	INSPECT LIGHTS	0.00
[√]	PM- 100C	INSPECT FOR GAS SPRINGS (CYLINDERS) FOR DAMAGE, SECUREMENT	0.00
[√]	PM- 101	Inspect lower cable	0.00
[√]	PM- 101C	INSPECT LOWER CABLE	0.00
[√]	PM- 102C	INSPECT VERTICAL ARM PLATE COVERS	0.00
[√]	PM- 103	Inspect vertical arm plate covers	0.00
[√]	PM- 104C	INSPECT ALTERNATOR-BATTERY(S) FOR LOOSE / BROKEN WIRES	0.00
[√]	PM- 105C	INSPECT AND CLEAN BATTERY TERMINALS	0.00
[√]	PM- 106C	TEST BATTERY AND RECORD OUTPUT	0.00
[√]	PM- 107C	TEST ALTERNATOR AND RECORD OUTPUT	0.00
[√]	PM- 109C	CHANGE ENGINE OIL AND FILTER	0.00
[√]	PM -10C	INSPECT PARKING	0.00
[√]	PM- 110C	INSPECT AIR FILTER	0.00
[√]	PM- 111C	INSPECT FOR FLUID LEAKS	0.00



Work Order

LaShundra Crowder : 7/14/2018 2:09:34 PM

[√]	PM- 112C	FILL ALL FLUID LEAKS	0.00
[√]	PM- 113C	INSPECT ENGINE ELECTRICAL WIRING AND FITTINGS	0.00
[√]	PM- 114C	COMPUTER CODE DIAGNOSTIC AS NEEDED	0.00
[√]	PM- 115C	INSPECT DRIVE BELT TENSIONER	0.00
[√]	PM- 116C	INSPECT DRIVE BELT PULLEYS	0.00
[√]	PM- 117C	INSPECT EXHAUST SYSTEM	0.00
[√]	PM- 118C	REPLACE SERPENTINE BELT AS NEEDED	0.00
[√]	PM- 119C	REPLACE FUEL FILTER (IF APPLICABLE)	0.00
[√]	PM -11C	INSPECT HEADLIGHTS HIGH AND LOW BEAM	0.00
[√]	PM- 120C	REPLACE PCV VALVE AS NEEDED	0.00
[√]	PM- 121C	REPLACE SPARK PLUGS AS NEEDED	0.00
[√]	PM- 122C	FLUSH/CHANGE TRANS FLUID AS NEEDED	0.00
[√]	PM- 124C	TORQUE ALL LUG NUTS/CHECK SPARE TIRE AND JACK (IF APPLICABLE)	0.00
[√]	PM- 125C	CHECK PRESSURE OF FRONT TIRES	0.00
[√]	PM- 126C	CHECK PRESSURE OF REAR TIRES	0.00
[√]	PM- 127C	VISUAL INSPECTION OF FRONT / REAR TIRE ALIGNMENT	0.00
[√]	PM- 128C	BALANCE ALL TIRES AND BRAKE INSPECTION	0.00
[√]	PM- 129C	FRONT END ALIGNMENT AS NEEDED	0.00
[√]	PM -12C	INSPECT BACK UP LIGHTS / ALARM	0.00
[√]	PM -13C	INSPECT LICENSE PLATE	0.00
[√]	PM -14C	INSPECT CLEARANCE / TAXI LIGHT	0.00
[√]	PM -15C	INSPECT TURN SIGNALS	0.00
[√]	PM- 16C	INSPECT HAZARD	0.00
[√]	PM- 17C	INSPECT BRAKE	0.00
[√]	PM- 18C	INSPECT STAIRWELL / WHEELCHAIR LIFT LIGHTS	0.00
[√]	PM- 19C	INSPECT TIRE OVERALL CONDITION	0.00
[√]	PM- 20C	INSPECT DRIVER AND TRANSIT DOOR OPERATION/CONDITION	0.00
[√]	PM- 21C	INSPECT BUMPERS	0.00
[√]	PM- 22C	INSPECT EXTERIOR CLEANLINESS	0.00
[√]	PM- 25	INSPECT ENGINE STARTING SYSTEM	0.00
[√]	PM- 26C	INSPECT INSTRUMENT GAUGES AND WARNING LIGHTS	0.00
[√]	PM- 27C	INSPECT HORN OPERATION	0.00
[√]	PM- 28C	INSPECT WIPER / WASHER OPERATION	0.00



Work Order

LaShundra Crowder : 7/14/2018 2:09:34 PM

[√]	PM- 29C	INSPECT PARKING BREAK OPERATION / PEDAL MOVEMENT	0.00
[√]	PM- 30C	INSPECT BRAKE PEDAL PADS	0.00
[√]	PM- 31C	INSPECT A/C / HEAT SYSTEM OPERATION	0.00
[√]	PM- 32C	INSPECT DEFROST	0.00
[√]	PM- 33C	INSPECT BRAKE SYSTEM PULSATION / STOPPING	0.00
[√]	PM- 34C	INSPECT VEHICLE PULLING FROM SIDE TO SIDE	0.00
[√]	PM- 35C	INSPECT TIRE VIBRATION	0.00
[√]	PM- 37C	MAKE SURE REGISTRATION, INSURANCE, AND ACCIDENT PACK IN VEHICLE.	0.00
[√]	PM- 38C	MAKE SURE 2-WAY RADIO WORKS (MDT)	0.00
[√]	PM- 39C	INSPECT INTERIOR LIGHTING	0.00
[√]	PM- 40C	INSPECT REAR VIEW MIRROR	0.00
[√]	PM- 41C	INSPECT INTERIOR SIGNAGE	0.00
[√]	PM- 42-44C	NO SMOKING EMERGENCY EXIT COMPLAINT INFORMATION	0.00
[√]	PM- 45C	INSPECT W/C SECUREMENT POUCH / CONTAINER	0.00
[√]	PM- 46C	INSPECT DRIVER SEAT	0.00
[√]	PM- 47C	INSPECT TRANSIT SEATS	0.00
[√]	PM -48C	INSPECT INTERIOR FINISHES AND TRIM	0.00
[√]	PM- 49C	INSPECT INTERIOR FLOOR AND STEP-WELL	0.00
[√]	PM- 50C	INSPECT HANDLES AND SANCTIONS	0.00
[√]	PM- 51C	INSPECT INTERIOR CLEANNESS/ TRUNK COMPARTMENT	0.00
[√]	PM- 53C	INSPECT COOLING SYSTEM - HOSES FOR LEAKS	0.00
[√]	PM- 54C	INSPECT RADIATOR/CAP, FANS, PUMP, AND CLAMPS	0.00
[√]	PM- 55C	PRESSURE TEST THE COOLING SYSTEM	0.00
[√]	PM- 57C	INSPECT UPPER AND LOWER CONTROL ARMS AND BALL JOINTS	0.00
[√]	PM- 58C	INSPECT STEERING LINKAGE - LUBRICATE	0.00
[√]	PM- 59C	INSPECT STEERING HOSES, LINKS, ARMS, AND RODS	0.00
[√]	PM- 60C	INSPECT SHOCKS - STRUTS FRONT/REAR	0.00
[√]	PM -61C	INSPECT REAR HUB AND AXLE SEALS	0.00
[√]	PM- 62C	LUBRICATE ALL GREASE FITTINGS	0.00
[√]	PM- 63C	INSPECT REAR LEAF SPRINGS/BUSHINGS/U-BOLTS	0.00
[√]	PM- 65C	CLEAN - INSPECT A/C FILTER AND OUTSIDE VENTS FRONT/REAR	0.00
[√]	PM- 66C	AMBIENT TEMPERATURE OUTSIDE	0.00



Work Order

LaShundra Crowder : 7/14/2018 2:09:34 PM

[√]	PM- 67C	AMBIENT TEMPERATURE INSIDE	0.00
[√]	PM- 68C	OUTLET TEMPERATURE FRONT	0.00
[√]	PM- 69C	OUTLET TEMPERATURE REAR	0.00
[√]	PM- 70C	FAN SPEEDS FRONT & REAR	0.00
[√]	PM- 72C	INSPECT HOSES FITTINGS FOR LEAKS	0.00
[√]	PM- 73C	CLEAN EVAPORATOR/ CONDENSER COILS F/R	0.00
[√]	PM- 74C	FRONT AND REAR CONDENSER COOLING FANS	0.00
[√]	PM- 75C	HIGH/LOW PRESSURE SWITCHES	0.00
[√]	PM- 76C	SECUREMENT OF HOSES AND LINES	0.00
[√]	PM- 77C	INSPECT MOUNTING HARDWARE	0.00
[√]	PM- 78C	CLEAN EVAPORATER DRAINS FRONT / REAR	0.00
[√]	PM- 80C	GENERAL OPERATION	0.00
[√]	PM- 81C	ABNORMAL NOISES	0.00
[√]	PM- 82C	LUBRICATE PIVOT POINTS; GUIDES AND LATCHES	0.00
[√]	PM- 83C	INSPECT HAND RAILS	0.00
[√]	PM- 84	INSPECT INNER / OUTER BARRIER STOPS	0.00
[√]	PM- 85	INTERLOCK OPERATION	0.00
[√]	PM- 86C	HYDRAULIC OIL LEVEL / CONDITION CONTAMINATION	0.00
[√]	PM- 87C	PLATFORM LIGHTS	0.00
[√]	PM- 88C	DAMAGE OR BENT MECHANISM	0.00
[√]	PM- 89C	CONTROL OPERATION AND CONDITION	0.00
[√]	PM- 90C	ELECTRICAL HARNESES/ EXPOSED WIRING	0.00
[√]	PM- 91C	THRESHOLD WARNING PLATE	0.00
[√]	PM- 92C	INSPECT ALL LIFT TIGHT LATCHES & ROLLERS FOR WEAR	0.00
[√]	PM- 93C	INSPECT EXTERNAL SNAP RINGS	0.00
[√]	PM- 94C	HYDRAULIC OIL LEAKS / HOSES / CYLINDERS	0.00
[√]	PM- 95C	INSPECT HOSES FOR RUBBING	0.00
[√]	PM- 96C	INSPECT MICRO AND POWER SWITCHES, CONTROL BOARD AND CIRCUITS	0.00
[√]	PM- 97C	INSPECT LUBRICATE BARRIERS ON PLATFORM PIVOT PINS, INNER ROLL STOP, ROTATING SIDE ARM, PARALLEL ARM, HAND RAIL PINS	0.00
[√]	PM- 99C	INSPECT COTTER PINS ON PLATFORM PIVOT PIN	0.00
[√]	PM-100	Inspect gas springs (cylinders) for damage, securement.	0.00
[√]	PMI- 78	Clean evaporator drains front / rear	0.00
[√]	PMI- 98	Inspecting mounting bolts / welds	0.00



Work Order

LaShundra Crowder : 7/14/2018 2:09:34 PM

Notes

Note Date	Note Type	Service Code	Modified By
7/14/2018	GENERAL		LaShundra Crowder
<i>PM C PERFORMED</i>			
<i>REPLACED ENGINE OIL AND OIL FILTER</i>			
<i>REPLACED TRANSMISSION FLUID AND AIR FILTER</i>			
<i>CHECKED TIRES AND BRAKES</i>			

Parts

Part #	Description	Location	Unit of Measure	Unit Cost	Quantity	Total
E-001	ENGINE OIL	WAREHOUSE []	QUART	\$1.669	6.00	\$10.02
TRAN001-V	FLUID, TRANSMISSION, VAN	WAREHOUSE []	QUART	\$11.000	6.00	\$66.00
TRAN002-V	FILTER, TRANSMISSION, VAN	WAREHOUSE []	EACH	\$13.990	1.00	\$13.99
WSH001	WASHER FLUID	WAREHOUSE []	QUART	\$1.690	1.00	\$1.69
E019-V	COOLANT, VAN	WAREHOUSE []	QUART	\$0.440	2.00	\$0.88

Mini Van

Preventive Maintenance Inspection Vehicles

Type P.M. Performed @ 5000mil/30 Days (Circle One) A 5000 mil B 20000 C-60000

Symbols	/ ok	Mechanic Name Carnes Massi
	X Repairs Needed In Red	Lift Make Capacity
	O Not Applicable	Lift Serial #

Date **07-14-11** Vehicle# **4831** Lift Cycles _____ Mileage **137985**

A	B	C	A) Walk Around Inspection	A	B	C	D) Maintenance Performed
			With Vehicle Running/Parking Brake set/Lights on/A/C System On High				C) Engine Compartment/Drive train
			1) Body Damage (Note any Damage)				1) Change Engine Oil & Filter
			2) Tires				2) Inspect Air Filter
			3) Window Glass				3) Inspect Drive Belts/Pulleys
			4) Mirrors				4) Fluid Leaks
			5) Wiper Blades				5) Fill All all Fluid Levels
			6) Decals/Numbers List On Separate Sheet				
			7) Reflectors				E) Brakes Measure:
			8) Lights				U/F Pads
			A) Parking				U/F Rotors
			B) Headlights High and Low Beam				R/F Pads
			C) License Plate				R/F Rotors
			D) Back-Up				R/R Pads/Shoes
			E) Clearance				R/R Rotors/Drums
			F) Turn Signals				L/R Pads/Shoes
			G Hazard				L/R Rotors/Drums
			H) Brake				Parking Brake Pads/Shoes
			I) Back-Up/Alarm				F) Air Condition Performance
			J) Stairwell lights				1) Ambient Temperature Outside
			9) Compartment Door Operation/Condition				2) Ambient temperature Inside
			10) Bumpers				3) Outlet temperature Front
			B) System Inspected				4) Outlet Temperature Rear
			A) Pre Service Road Test				5) Record System Pressure
			1) Interior Cleanness				A) Suction/Low Side
			2) Interior Condition/Seats				B) Discharge/High Side
			3) Engine Starting System				6) Fan Speeds Front & Rear
			4) Instrument Gauges and Warning Lights				G) Air Condition System Inspection
			5) Horn Operation				1) Hoses Fittings For Leaks
			6) Wiper/Washer Operation				2) Clean Evaporator/Condenser Coils F/R
			7) Parking Brake Operation/Pedal Movement				4) Rear Condenser Cooling Fans
			8) Brake Pedal Pads				5) High/Low Pressure Switches
			9) Seat Belt Operation & Condition				6) Securement of Hoses and Lines
			10) A/C/Heaf System Operation				8) Inspect Mounting Hardware
			11) Defrost				9) Clean Evaporator Drains F/R
			12) Brake System Pulsation/Stopping				
			13) Vehicle Pulling from Side To Side				H) Lift/Ramp
			14) Tire Vibration				1) Operation/Abnormal Noises
			15) Cooling System Service				2) Lubricate Pivot Points & Guides
			Vehicle Interior				3) Inspect Mounting Bolts/Welds
			Valid FL:				6) Interlock Operation
			A) Registration				11) Damaged Or Bent Mechanism
			B) Insurance Card				12) Control Operation and Condition
			C) Accident Form				13) Electrical Harnesses/Exposed Wiring
			2-Way Radio				15) Inspect all Lift-Tite Latches & rollers for Wear
			Seat Condition				16) Micro switches For adjustments
			Interior Signage				C) Safety Equipment
			A) No Smoking				1) Fire Extinguisher
			B) Emergency Exit				2) First Aid Kit
			C) Complaint Information				3) Safety Triangles
			W/C Securement Pouch/Container				4) Blood Born Kit
			Tires				5) Wheel Chair Tie Downs/Securement Belts
			L/F				
			R/F				
			L/R				
			R/R				
			Wheel Alignment				

95
80
75
70

PSI
PSI

1800

Date: 04-11

8828

A	B	C		A	B	C	
			C) Safety Equipment				Annual Inspections
		/	1) Fire Extinguisher			/	Complete Annual Vehicle Inspection Form
		/	2) First Aid Kit			/	Clean all Evaporators/Condensing Units
		/	3) Safety Triangles			/	Recycle Recharge A/C System
		/	4) Blood Bom Kit			/	Engine Tune-Up
		/	5) Wheel Chair Tie Downs/Securement Belts				
		/	6) Inter Lock System				
			Electrical System				
			Inspect All/Batteries for loose/broken Wires				
		/	Inspect @ Clean Battery Terminals				
		/	Test Alt And Record Output				
		/	Test Battery and record Output				

Signature Of A.S.E Certified Mechanic Caruso M. S. M. Date 07-14-18

Comments

PMI C SERVICE performed

Replaced motor oil

Replaced oil filter

Replaced ATF fluid

Replaced ATF filter

Checked tires and brakes

Mechanic Name	Vehicle NO	Mileage	Work Order #		
Carnes Master	4231	137 985	2415		
QTY	Description	Total Cost	Issued by	Labor Hrs	
6.0 qts	5W30 Motor oil				
1	oil filter				
6.0 qts	ATF fluid				
1	ATF Filter				
1.0 gallon	washer fluid				
2.0 qts	Antifreeze/Coolant.				
Mechanic's signature	Carnes Master		Date	07-14-15	
Supervisor's approval			Date		
Manager's approval			Date		



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53558520
Invoice Number: 55345-53558520

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMC
Requested By: NSTOLFO
Created By: NSTOLFO
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
VIN: GRAND CARAVAN SE
Status: 2C7WDGBG1ER476565
Priority: 40
Driver: 3
Phone:
ETA:

Chronology		
Reported	Jun 3, 2020	12:00 AM
Started	Jun 3, 2020	
Completed	Jun 3, 2020	6:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	179,630	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter Lube all Pivoting Points. Check brakes. Check batteries..replace cabin Air Filter. Parts #P9600 Qty (1) Parts # PA10030 Qty (1) Oil 10W30 Qty Qty (5.5) Qt

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty	Each	Extended
------	-------------	-------------	-----	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
 Labor: 0.00
 Labor Hours: 0.00
 Sublet Parts: 0.00
 Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty	Each	Extended
------	-------------	-------------	-----	------	----------

Labor Posted



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 54537431
Invoice Number: 55345-54537431

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMC		Status:	2C7WDGBG1ER476565
Requested By:	DARTHURS	Priority:	40
Created By:	DARTHURS	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology

Reported	Jun 24, 2021	12:00 AM
Started	Jun 24, 2021	
Completed	Jun 25, 2021	12:24 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	205,324	DH

WorkOrder Notes

Line	Comment
10	Vehicle came in for service. Change engine oil. And filter only Next technician will take all of them to complete the job
20	PMC Service Perform pmc Service Oil filter P9600 Engine oil 10w30 qty 5 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Jun-21	Junior Hurst	0.07	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 1 of 10



WorkOrder: 55972551
Invoice Number: 55345-55972551

Client Department:

MRC:	55345M	Equipment:	4831
WO Desc:			GRAND CARAVAN SE
55345-LIGHT DUTY PMC		VIN:	2C7WDGBG1ER476565
Requested By:	JUHURST	Status:	40
Created By:	JUHURST	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Oct 26, 2022	12:00 AM
Started	Oct 28, 2022	
Completed	Oct 28, 2022	6:48 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	232,683	DH
System	232,555	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter. lube all Pivoting Points. Check brakes. Engine Major Oil Leaks. Parts # P9600 Qty (1) Oil 10W30 Qty (5,5) Qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
28-Oct-22	Arthurs,Durvin	1.92	0.00	0.00



WorkOrder
 55345 Palm Tran Connection
 v 2.2
 Page 3 of 10



WorkOrder: 55972551
Invoice Number: 55345-55972551

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4831
VIN: GRAND CARAVAN SE
 2C7WDGBG1ER476565
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
56036725	13-Oct-22	230,635	WORC	Road Call (Flat Tire)
56012517	5-Oct-22	229,585	WO	FLAT TIRE ROAD CALL

PH: Work Order: 55972551 Desc: 55345-LIGHT DUTY PMC
Equip: 4831 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG1ER476565

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 28-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		DARTHURS	Oct 28, 2022 5:05:10 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Oct 28, 2022 5:05:15 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		DARTHURS	Oct 28, 2022 5:05:21 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Oct 28, 2022 5:05:28 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Oct 28, 2022 5:05:33 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Oct 28, 2022 5:05:40 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 28, 2022 5:05:45 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Oct 28, 2022 5:05:51 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Oct 28, 2022 5:06:01 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Oct 28, 2022 5:06:08 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Oct 28, 2022 5:06:14 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Oct 28, 2022 5:06:21 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Oct 28, 2022 5:06:27 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Oct 28, 2022 5:06:36 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancellation	Done		DARTHURS	Oct 28, 2022 5:06:46 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Oct 28, 2022 5:06:53 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		DARTHURS	Oct 28, 2022 5:07:00 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Oct 28, 2022 5:07:07 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		DARTHURS	Oct 28, 2022 5:07:16 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Oct 28, 2022 5:07:23 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Oct 28, 2022 5:07:34 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		DARTHURS	Oct 28, 2022 5:07:40 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Oct 28, 2022 5:07:45 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Oct 28, 2022 5:07:51 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles,	Done		DARTHURS	Oct 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Controls and Panels				5:07:58 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Oct 28, 2022 5:08:05 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Oct 28, 2022 5:08:11 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Oct 28, 2022 5:08:16 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		DARTHURS	Oct 28, 2022 5:08:21 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Oct 28, 2022 5:08:26 PM	No	
31,000	SSF (Street Side Front)	Done		DARTHURS	Oct 28, 2022 5:08:31 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Oct 28, 2022 5:08:39 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Oct 28, 2022 5:09:00 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 28, 2022 5:09:08 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Oct 28, 2022 5:09:13 PM	No	
32,000	Engine Inspection	Done		DARTHURS	Oct 28, 2022 5:09:19 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		DARTHURS	Oct 28, 2022 5:09:25 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Oct 28, 2022 5:09:32 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Oct 28, 2022 5:09:38 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		DARTHURS	Oct 28, 2022 5:09:45 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Oct 28, 2022 5:10:04 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Oct 28, 2022 5:10:12 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Oct 28, 2022 5:10:26 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Oct 28, 2022 5:10:34 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Oct 28, 2022 5:10:43 PM	No	
32,100	INSPECT_Intake System	Done		DARTHURS	Oct 28, 2022 5:10:57 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		DARTHURS	Oct 28, 2022 5:11:15 PM	No	
33,010	CSF (Curb Side Front)	Done		DARTHURS	Oct 28, 2022 5:11:21 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Oct 28, 2022 5:11:28 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Oct 28, 2022 5:11:36 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 28, 2022 5:11:40 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Oct 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					5:11:45 PM		
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Oct 28, 2022 5:11:53 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		DARTHURS	Oct 28, 2022 5:11:58 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Oct 28, 2022 5:12:06 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Oct 28, 2022 5:12:11 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Oct 28, 2022 5:12:17 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Oct 28, 2022 5:12:22 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Oct 28, 2022 5:12:27 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Oct 28, 2022 5:12:32 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Oct 28, 2022 5:12:38 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Oct 28, 2022 5:12:44 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Oct 28, 2022 5:12:51 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Oct 28, 2022 5:12:55 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		DARTHURS	Oct 28, 2022 5:13:00 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Oct 28, 2022 5:13:07 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Oct 28, 2022 5:13:13 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Oct 28, 2022 5:13:20 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Oct 28, 2022 5:13:25 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Oct 28, 2022 5:13:31 PM	No	
50,200	INSPECT_Ball Joint Play	Done		DARTHURS	Oct 28, 2022 5:13:36 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Oct 28, 2022 5:13:44 PM	No	
50,400	LUBE_All Chassis Components	Done		DARTHURS	Oct 28, 2022 5:13:49 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Oct 28, 2022 5:13:53 PM	No	
50,700	INSPECT_Tire Condition	-	TPMS Light on	DARTHURS	Oct 28, 2022 5:15:17 PM	Yes	56083259
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Oct 28, 2022 5:14:05 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Oct 28, 2022 5:14:12 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Oct 28, 2022 5:14:22 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per		DARTHURS	Oct 28, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		Square Inch			5:14:41 PM		
51,200	RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Oct 28, 2022 5:15:29 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Oct 28, 2022 5:15:37 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Oct 28, 2022 5:15:42 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Oct 28, 2022 5:15:47 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		DARTHURS	Oct 28, 2022 5:15:52 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 28, 2022 5:16:02 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 28, 2022 5:16:07 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.099 Inch		DARTHURS	Oct 28, 2022 5:16:19 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.099 Inch		DARTHURS	Oct 28, 2022 5:16:26 PM	No	
52,100	INSPECT_Vibration Damper	Done		DARTHURS	Oct 28, 2022 5:16:32 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Oct 28, 2022 5:16:36 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		DARTHURS	Oct 28, 2022 5:16:42 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Oct 28, 2022 5:16:46 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		DARTHURS	Oct 28, 2022 5:16:51 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	-	Major Oil leaks	DARTHURS	Oct 28, 2022 5:17:54 PM	Yes	56083259
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Oct 28, 2022 5:17:59 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done		DARTHURS	Oct 28, 2022 5:18:05 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Oct 28, 2022 5:18:12 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Oct 28, 2022 5:18:18 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Oct 28, 2022 5:18:25 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Oct 28, 2022 5:18:32 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Oct 28, 2022 5:18:38 PM	No	
53,600	INSPECT_Tire Condition	Done		DARTHURS	Oct 28, 2022 5:18:43 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Oct 28, 2022 5:18:49 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		DARTHURS	Oct 28, 2022 5:18:54 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Oct 28, 2022 5:19:39 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Oct 28, 2022 5:19:46 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,100	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Oct 28, 2022 5:19:55 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		DARTHURS	Oct 28, 2022 5:20:06 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Oct 28, 2022 5:20:15 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		DARTHURS	Oct 28, 2022 5:20:29 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		DARTHURS	Oct 28, 2022 5:20:41 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Oct 28, 2022 5:20:47 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Oct 28, 2022 5:20:55 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Oct 28, 2022 5:21:00 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 28, 2022 5:21:13 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Oct 28, 2022 5:22:00 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.473 Inch		DARTHURS	Oct 28, 2022 5:21:36 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.473 Inch		DARTHURS	Oct 28, 2022 5:22:22 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Oct 28, 2022 5:22:29 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Oct 28, 2022 5:22:37 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Oct 28, 2022 5:22:43 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Oct 28, 2022 5:22:48 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		DARTHURS	Oct 28, 2022 5:22:54 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Oct 28, 2022 5:23:00 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Oct 28, 2022 5:23:05 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Oct 28, 2022 5:23:09 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		DARTHURS	Oct 28, 2022 5:23:14 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Oct 28, 2022 5:23:18 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Oct 28, 2022 5:23:24 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Oct 28, 2022 5:23:29 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Oct 28, 2022 5:23:33 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Oct 28, 2022 5:23:38 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Oct 28, 2022 5:23:42 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Oct 28, 2022 5:23:47 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Oct 28, 2022 5:23:52 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Oct 28, 2022 5:23:57 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Oct 28, 2022 5:24:01 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		DARTHURS	Oct 28, 2022 5:24:06 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Oct 28, 2022 5:24:11 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Oct 28, 2022 5:24:17 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		DARTHURS	Oct 28, 2022 5:24:21 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Oct 28, 2022 5:24:26 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Oct 28, 2022 5:24:30 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Oct 28, 2022 5:24:35 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		DARTHURS	Oct 28, 2022 5:24:40 PM	No	
62,400	INSPECT_All Pivot Points	Done		DARTHURS	Oct 28, 2022 5:24:44 PM	No	
62,500	INSPECT_Cams and Slots	Done		DARTHURS	Oct 28, 2022 5:24:49 PM	No	
62,600	INSPECT_Rollers	Done		DARTHURS	Oct 28, 2022 5:24:53 PM	No	
62,700	INSPECT_All Linkages	Done		DARTHURS	Oct 28, 2022 5:24:58 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		DARTHURS	Oct 28, 2022 5:25:03 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Oct 28, 2022 5:25:07 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Oct 28, 2022 5:25:16 PM	No	

LH: 20 Desc: PM C

Task: PM C SERVICE Performed by: DARTHURS Performed on: 28-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 28, 2022 5:26:57 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Oct 28, 2022 5:27:02 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Oct 28, 2022 5:27:08 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Oct 28, 2022 5:27:12 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Oct 28, 2022 5:27:17 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Oct 28, 2022 5:27:22 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
107,000	FRA Change Primary Fuel Filter	-	NA	DARTHURS	Oct 28, 2022 5:27:33 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Oct 28, 2022 5:27:39 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Oct 28, 2022 5:27:44 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Oct 28, 2022 5:28:00 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		DARTHURS	Oct 28, 2022 5:28:09 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Oct 28, 2022 5:28:14 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Oct 28, 2022 5:28:21 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Oct 28, 2022 5:28:26 PM	No	
301,000	Check and Lubricate Door Linkages	Done		DARTHURS	Oct 28, 2022 5:28:31 PM	No	
302,000	Check Toe-In and Record Reading	-	NA	DARTHURS	Oct 28, 2022 5:28:46 PM	No	
302,001	Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Oct 28, 2022 5:28:58 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Oct 28, 2022 5:29:05 PM	No	
305,000	FRA Change Differential Fluid	No		DARTHURS	Oct 28, 2022 5:29:10 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 28-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		DARTHURS	Oct 28, 2022 5:29:46 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 28, 2022 5:29:50 PM	No	
4	Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 28, 2022 5:29:55 PM	No	
7	Have you performed the proper LOTO?	Done		DARTHURS	Oct 28, 2022 5:29:59 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 28, 2022 5:30:03 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 28, 2022 5:30:08 PM	No	