Total Hours:	368.00	Labor: 23,139.50	Parts: 23,841.48	Comm: 3,080.25		Charged	50061.24	
Work Order: Problem:		Meter: ELIVERY INSPECTION			In Date:	05/02/2006	Closed:	05/02/2006
Work Com	pleted							
- Pre-deliv	very Inspe	ction						
		Hours: 2.00	Comm: 0.00	Labor: 100.00	Parts: 0.0	0	Total:	100.00
Work Order: Problem:		Meter: GHT POST	8		In Date:	05/05/2006	Closed:	05/31/2006
Work Com	pleted			Parts Issued			Qı	uantity
- Fab Light	t Post			Shop Supplies				1.00
- Fab Spra	y Frame			T-1 Black Paint Glos	SS			2.00
- Shop Sup	pplies			1/4x2x20 Alum Flat	Bar 6063			1.00
				2x2x1/4x20 Alum A	ngle Archited	ctual		1.00
				1-1/4x20 Alum Pipe	e Sch 80			3.00
				1/4x2x20 Angle Ste	el			1.00
				3"x 20 Steel Channe	el 5.0 Thick			16.00
				66060 Lock Pin 3/8	"x2-1/2"			2.00
		Hours: 19.00	Comm: 0.00	Labor: 950.00	Parts: 103	3.47	Total:	1,053.47
Work Order: Problem:		Meter: L STROBE LIGHT	8		In Date:	05/09/2006	Closed:	05/10/2006
Work Com	pleted			Parts Issued			Qı	uantity
- Fabricate	e & Install	Strobe Light Sys.		Shop Supplies				1.00
- Shop Sup				06133 3m Electric T	ape Stock #8	32260101		1.00
				84842 Rocker Switc	h			1.00
		Hours: 3.50	Comm: 0.00	Labor: 175.00	Parts: 12.	40	Total [.]	187.40

Work Order: Problem:	734087 P.M SERVICE	Meter: 3451		In Date:	02/09/2007	Closed:	02/13/200
Work Com	npleted		Parts Issued			Q	uantity
- Pm Servi	ice		Shop Supplies				1.00
- Nitrogen	n Fill Tires.		Ph16 Oil Filter Lbf	f Ph253 Wix 51	307		1.00
- Shop Su	pplies		5w20 Engine Oil				7.00
	Hours: 3.75	Comm: 0.00	Labor: 206.25	Parts: 34	.16	Total:	240.41
Work Order: Problem:	741693 CHECK BRAKE LIGHTS	Meter: 5539		In Date:	07/19/2007	Closed:	07/24/200
Work Com	npleted		Parts Issued			Q	uantity
	ed Left Rear Brake Light Was No nd Bad Bulb.replace With New B		3057 Bulb				1.00
	Hours: 0.50	Comm: 0.00	Labor: 27.50	Parts: 0.8	30	Total:	28.30
Work Order: Problem:	743282 P.M SERVICE	Meter: 6066		In Date:	08/28/2007	Closed:	09/13/200
Work Com	npleted		Parts Issued			Q	uantity
- Pm Servi	ice		Shop Supplies				1.00
- Balance	4 Tires		Ca9401 Air Filter I	Lbf Af3590 Wix	x 42725		1.00
- Transpor	rt To Dealer For Warranty Driver	Seat Repair P/u When Done	Ph16 Oil Filter Lbf	Ph16 Oil Filter Lbf Ph253 Wix 51307			1.00
- Shop Su	pplies		5w20 Engine Oil				7.00
			Wd40 Spray Lube	Stock# 40554	0002		1.00
			10020 Injector Cle	eaner Don't Re	order		1.00
			31-24 Wiper Blac	les 24" Blade			2.00

2/10/2023	
7:35:56 AM	

Meter: 8734

Work Order: 835454 Problem: P.M SERVICE

In Date: 03/13/2008 Closed: 03/17/2008

Work Completed		Parts Issued		Quantity
- Pm Service		Shop Supplies		1.00
- Repair L/front R/front Tires.rotate And Balan	nce All 4 Tires	Ca9401 Air Filter L	bf Af3590 Wix 427	725 1.00
- Remove And Replace Broken Trailer Hitch Pi	in.	Ph16 Oil Filter Lbf	1.00	
- Shop Supplies		5w20 Engine Oil	7.00	
		31-24 Wiper Blade	es 24" Blade	2.00
		Used Firex Refurbe	ed Fire Extingshers	5 1.00
		18410 Pintle Pin		1.00
Hours: 5.25	Comm: 0.00	Labor: 315.00	Parts: 59.08	Total: 374.08
ork Order: 845405	Meter: 11641		In Date: 10	0/08/2008 Closed: 10/27/20
Problem: P.M SERVICE, CHECK A/C & TIR		Parts Issued	In Date: 10	
		Parts Issued Shop Supplies	In Date: 10	0/08/2008 Closed: 10/27/20 Quantity 1.00
Problem: P.M SERVICE,CHECK A/C & TIR Work Completed - Pm Service	ES	Shop Supplies		Quantity
Problem: P.M SERVICE,CHECK A/C & TIR Work Completed - Pm Service - Replace 2 Tires.mount New Tires On Front.b.	ES alance All 4 Tiresnitro Fill Tires.	Shop Supplies		Quantity 1.00
Problem: P.M SERVICE,CHECK A/C & TIR Work Completed - Pm Service	ES alance All 4 Tiresnitro Fill Tires.	Shop Supplies Ph16 Oil Filter Lbf	Ph253 Wix 51307	Quantity 1.00 1.00
Problem: P.M SERVICE,CHECK A/C & TIR Work Completed - Pm Service - Replace 2 Tires.mount New Tires On Front.bu - Diagnose Ac Concern.send To Dealer For Co	ES alance All 4 Tiresnitro Fill Tires.	Shop Supplies Ph16 Oil Filter Lbf 5w20 Engine Oil	Ph253 Wix 51307	Quantity 1.00 1.00 7.00
 Problem: P.M SERVICE, CHECK A/C & TIR Work Completed Pm Service Replace 2 Tires.mount New Tires On Front.b. Diagnose Ac Concern.send To Dealer For Co Replacement. Complete Front End Alignment.test Drive. To/fr Dealer For Warranty A/c Condener Fan 	ES Palance All 4 Tiresnitro Fill Tires. Ondenser Fan Motor	Shop Supplies Ph16 Oil Filter Lbf 5w20 Engine Oil 31-24 Wiper Blade	Ph253 Wix 51307	Quantity 1.00 1.00 7.00 2.00
 Problem: P.M SERVICE, CHECK A/C & TIR Work Completed Pm Service Replace 2 Tires.mount New Tires On Front.b. Diagnose Ac Concern.send To Dealer For Co Replacement. Complete Front End Alignment.test Drive. 	ES Palance All 4 Tiresnitro Fill Tires. Ondenser Fan Motor	Shop Supplies Ph16 Oil Filter Lbf 5w20 Engine Oil 31-24 Wiper Blade Tire Disposal Fee	Ph253 Wix 51307 es 24" Blade	Quantity 1.00 1.00 7.00 2.00 2.00 2.00

Vork Order: 937775 Problem: P.M SERVI	CE	Meter: 13949		In Date:	05/14/2009	Closed:	05/18/2009
Work Completed			Parts Issued			Qı	antity
- Pm Service			Shop Supplies				1.00
- Service Trans, Flush A	nd Refill.		Ph16 Oil Filter Lbf	Ph253 Wix 513	307		1.00
- Test And Replace Left	Rear Tag Light And Ri	ight Front Parkinglight Bulb.	5w20 Engine Oil				7.00
- Repair 1 Tire Mount C	On Right Rear High Spe	eed Balance All 4 Tires. Nitro	1066 White Lithiu	m (crc 05037)			1.00
Fill Tires.			Syn/atf Trans Fluic	l Synthetic			12.00
- Shop Supplies							
Но	urs: 7.05	Comm: 0.00	Labor: 423.00	Parts: 83.5	58	Total:	506.58
	OTATIO IN TIMO MAIN						
Problem: CHECK ON Work Completed	STATIC IN TWO WA	Y RADIO,SEE NOTES.	Parts Issued			Qı	antity
Work Completed		Y RADIO,SEE NOTES. arrow Problem To 2-way	Parts Issued Shop Supplies			Qı	iantity 1.00
Work Completed - Scan Test Engine Ontr						Qı	•
Work Completed - Scan Test Engine Ontr Radio Sys. - Shop Supplies				Parts: 2.00)		•
Work Completed - Scan Test Engine Ontr Radio Sys. - Shop Supplies	rols & Test Electrical.na ours: 1.00	arrow Problem To 2-way	Shop Supplies	Parts: 2.00 In Date:) 11/04/2009	Total:	1.00
Work Completed - Scan Test Engine Ontr Radio Sys. - Shop Supplies Ho York Order: 945653	rols & Test Electrical.na ours: 1.00	arrow Problem To 2-way Comm: 0.00	Shop Supplies			Total: Closed:	1.00 62.00
Work Completed - Scan Test Engine Ontr Radio Sys. - Shop Supplies Ho /ork Order: 945653 Problem: Recall #H46	rols & Test Electrical.na ours: 1.00 S(steering linkage)	comm: 0.00 Meter: 15760	Shop Supplies			Total: Closed:	1.00 62.00 11/06/2009
Work Completed - Scan Test Engine Ontr Radio Sys. - Shop Supplies Ho York Order: 945653 Problem: Recall #H46 Work Completed	rols & Test Electrical.na ours: 1.00 S(steering linkage)	comm: 0.00 Meter: 15760	Shop Supplies Labor: 60.00 Parts Issued			Total: Closed:	1.00 62.00 11/06/2009

2/10/2023 7:35:56 AM

Palm Beach County Fleet Management Asset Maintenance History K11735 2006 DODGE 2500 Pickup, 3/4 Ton, 4X4

Work Order: 945820 Meter: 15764 11/09/2009 **Closed:** 11/13/2009 In Date: Problem: pm service Parts Issued Quantity **Work Completed** Shop Supplies 1.00 - P.m service. Ph16 Oil Filter Lbf Ph253 Wix 51307 1.00 - Mount two new tires, rotate & balance all four tires. 5w20 Engine Oil 7.00 - Test starting & charging system. Batter failed load test, replace defective battery. 2.00 31-24 Wiper Blades 24" Blade - Replace missing pintle safety pin. Used Firex Refurbed Fire Extingshers 1.00 - Alignment. Group 65 Battery (mtc Bxt-65-850) 1.00 - Shop Supplies 179469492 Lt245/70r17 Wrangler Sr-a E 2.00 Tr416 Valve Stem 2.00 2.00 Tire Disposal Fee 18410 Pintle Pin 1.00 Hours: 8.75 Comm: 0.00 Labor: 525.00 Parts: 510.70 Total: 1.035.70 Work Order: 1001040 Meter: 16596 In Date: 01/28/2010 Closed: 01/28/2010 **Problem:** Check turn signals. Quantity Work Completed Parts Issued 3057 Bulb 2.00 - Test & replace two turn signal bulbs on L/r. Hours: 0.50 Comm: 0.00 Parts: 1.59 Total: 31.59 Labor: 30.00 Work Order: 1002640 **Meter:** 17477 **In Date:** 03/15/2010 **Closed:** 03/18/2010 Problem: Brake light comes on. **Work Completed** Parts Issued Quantity 1.00 Shop Supplies - Test & diagnose brake warning light circuit, trace problem to failed brake fluid resevior switch, replace master cylinder resevior, bleed system & test Master Cyl Resivour / 68054878aa 1.00 drive. 1401 Brake Fluid Brake Fluid 2.00 - Shop Supplies Hours: 2.50 Comm: 0.00 Labor: 150.00 Parts: 59.52 Total: 209.52

Work Order: 1004966 Meter: 17811 05/12/2010 Closed: 05/19/2010 In Date: Problem: P.M service, check tires for nails. Parts Issued **Work Completed** Quantity Shop Supplies 1.00 - P.m service. Ph16 Oil Filter Lbf Ph253 Wix 51307 1.00 - Inspect A/c for low air flow, R&i dash, replace broken recirculation door & housing, install new door actuator, R&i 2way radios for access. 5w20 Engine Oil 7.00 - Test & replace failed strobe lamp switch. 84863 Rocker Switch (motormite) 1.00 - Shop Supplies Rec Door Assy / 68004226ac 1.00 Actuator / 4885206ab 1.00 Hours: 8.75 Comm: 0.00 Labor: 525.00 Parts: 94.95 Total: 619.95 Work Order: 1012785 Meter: 19912 In Date: 11/16/2010 Closed: 12/03/2010 Problem: P.M. service and repair seat and see notes. Work Completed Parts Issued Quantity Shop Supplies 1.00 - Perform pm service. Ph16 Oil Filter Lbf Ph253 Wix 51307 1.00 - Transmission pan gasket leaking.service transmission and install new filter and gasket.flush and renew fluid. B196 Trans Filter Lbf T766 Wix 58843 1.00 - Install two new tires to the front wheels and balance all four. 5w20 Engine Oil 7.00 - Remove driver seat for repairs to damage cushion and fabric and install Syn/atf Trans Fluid Synthetic 8.00 after done. 31-24 Wiper Blades 24" Blade 2.00 - Transport driver seat to and from central auto trim shop for repairing Tire Disposal Fee 2.00 damage cushion and fabric. 179469492 Lt245/70r17 Wrangler Sr-a E 2.00 - Shop Supplies Hours: 9.25 Comm: 128.30 Labor: 555.00 Parts: 468.12 Total: 1,151.43 Work Order: 1013437 Meter: 19912 **In Date:** 11/16/2010 **Closed:** 12/07/2010 Problem: damage to frt & rear bumper & lft rear fender **Work Completed** - damage to frt & rear bumper & lft rear fender

Hours: 0.00

Comm: 1,542.00 Labor: 0.00

Parts: 0.00

Total: 1,542.00

Work Order: 1100429 Problem: Left front trun signal in	Meter:	20227		In Date:	01/11/2011	Closed:	01/13/2011
Work Completed			Parts Issued			Qı	uantity
- Replace front turn signal bulb.			3157na Amber Bulb				2.00
Hours: 0.25		Comm: 0.00	Labor: 15.00	Parts: 2.6	4	Total:	17.64
Work Order: 1103621	Meter:	21080		In Date:	04/04/2011	Closed:	04/07/2011
Problem: Left rear brake light ou	ıt.						
Work Completed	Work Completed					Qı	uantity
- Test and replace failed left brake	e lamp bulb with new.		Shop Supplies				1.00
- Shop Supplies			3157 Tail Light Bulbs				1.00
Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 3.2	0	Total:	33.20
Work Order: 1103966	Meter:	21117		In Date:	04/12/2011	Closed:	04/25/2011
Problem: Pm service also li8nka	age for four wheel drive	seperated					
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Shop Supplies				1.00
- Replace 4x4 shift linkage and bu	ishings.adjust linkage.		Ph16 Oil Filter Lbf Ph	253 Wix 51	307		1.00
- Rotate and balance all tires.			Ca9401 Air Filter Lbf Af3590 Wix 42725				1.00
- Shop Supplies			5w20 Engine Oil				7.00
			31-24 Wiper Blades	24" Blade			2.00
			Used Firex Refurbed	Fire Extings	hers		1.00
			Bushing				2.00
			Linkage Rod				1.00
Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 78.	99	Total:	363.99
Work Order: 1107540 Problem: Screw in right rear tire	Meter: and left rear turn signa			In Date:	07/19/2011	Closed:	07/20/2011
Work Completed			Parts Issued			Qı	uantity
- Test and replace failed left turn	signal lamp bulb with n	ew.	Shop Supplies				1.00
- Repair flat right rear tire.nitroge	n fill and balance same.		3157 Tail Light Bulbs				1.00
- Shop Supplies							
Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 3.2	<u>^</u>	Total:	00.00

Work Order: Problem:	1109706 Front right turn signal lamp ir	Meter: 22732		In Date:	09/12/2011	Closed:	09/14/2011
Work Com	npleted		Parts Issued			Qı	antity
- Remove bulb with r	0	replace failed right turn signal lamp	3157na Amber Bulb				1.00
	Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 1.32	2	Total:	31.32
Work Order: Problem:	1112277 Pm service and ac blows hot	Meter: 23378 t air.		In Date:	11/16/2011	Closed:	11/29/2017
Work Com	npleted		Parts Issued			Qu	antity
- Perform	pm service.		Shop Supplies				1.00
- Diagnose	e ac concern.recover freon,rem	nove condenser and replace failed	Ph16 Oil Filter Lbf Pl	h253 Wix 513	307		1.00
fan motor	with new.vacume and recharge	e system.ac performance test.	5w20 Engine Oil				7.00
- Rotate a	nd balance all four tires.		31-24 Wiper Blades	24" Blade			2.00
- Shop Su	pplies		Condenser Fan Mote	or			1.00
	Hours: 6.25	Comm: 0.00	Labor: 375.00	Parts: 156	6.80	Total:	531.80
Work Order: Problem:	1112649 trailer plug	Meter: 23384		In Date:	11/30/2011	Closed:	11/30/201
Work Com	npleted						
- repair tra	ailer plug connection						
	Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 0.00	0	Total:	30.00
Work Order: Problem:	1113193 Bolt in left rear tire and nail ir	Meter: 23596 n right rear tire.		In Date:	12/15/2011	Closed:	12/15/2011
Work Com	npleted		Parts Issued			Qı	antity
- Repair tv	vo flat tires right rear and left i	rear.nitrogen fill and balance both.	Shop Supplies				1.00
- Shop Su	pplies						
Shop Sal							

Work Order: 1202973 Mete Problem: Left front tire has holein side wall.	r: 24458		In Date:	03/28/2012	Closed:	03/29/2012
Work Completed		Parts Issued			Qu	uantity
- Replace and balance left front tire.		Shop Supplies				1.00
- Shop Supplies		179469492 Lt245/7	0r17 Wrangl	er Sr-a E		1.00
		Tire Disposal Fee				1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 17	1.32	Total:	231.32
Work Order:1205434MeteProblem:P.M. Service.	r: 24803		In Date:	06/11/2012	Closed:	06/21/2012
Work Completed		Parts Issued			Q	uantity
- P.m. Service.		Shop Supplies				1.00
- Replace one tire, rotate and balance all four.		Ph16 Oil Filter Lbf F	Ph253 Wix 51	307		1.00
- Shop Supplies		5w20 Engine Oil				7.00
		31-24 Wiper Blade	es 24" Blade			2.00
		179469492 Lt245/7	0r17 Wrangl	er Sr-a E		1.00
		Tire Disposal Fee				1.00
Hours: 4.25	Comm: 0.00	Labor: 255.00	Parts: 202	2.07	Total:	457.07
Work Order:1209017MeteProblem:Battery has to be jumped to start engine.	r: 25534		In Date:	09/20/2012	Closed:	09/20/2012
Work Completed		Parts Issued			Qı	uantity
- Test starting and charging system.battery failed load	test after	Shop Supplies				1.00
recharge.replace failed battery with new.		Group 65 Battery (r	ntc Bxt-65-85	50)		1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 132	2.26	Total:	192.26
Work Order:1210919MeteProblem:Left rear tire flat.	r: 26049		In Date:	11/08/2012	Closed:	11/15/2012
Work Completed		Parts Issued			Qı	uantity
- Repair and balance left rear tire.		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total	62.00

Work Order: Problem:	1301612 Pm service.Right front tire flat.	Meter:	27336		In Date:	02/14/2013	Closed:	03/21/2013
Work Com	-			Parts Issued			Qı	antity
- P.m. Serv	vice.			5w20 Engine Oil				7.00
- Replace	two tires,repair right front,rotate	e and balance a	II four.	Ph16 Oil Filter Lbf P				1.00
-	test and inspect cooling system			31-24 Wiper Blades	2			2.00
	ooling system.			179469492 Lt245-70	r17			2.00
- Complet	e wheel alignment.test drive.			Peak Global Antifrz				2.00
- Shop Su	pplies			Radiator Caps				1.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 9.75		Comm: 0.00	Labor: 585.00	Parts: 537	7.42	Total:	1,122.42
Work Order: Problem:	1303538 replace rusred tail gate	Meter:	27336		In Date:	03/15/2013	Closed:	04/11/2013
Work Com	npleted							
- replace r	rusred tail gate							
	Hours: 0.00		Comm: 520.80	Labor: 0.00	Parts: 0.0	0	Total:	520.80
Work Order: Problem:	1304467 Check engine light on.	Meter:	27594		In Date:	05/06/2013	Closed:	05/22/2013
Work Com	npleted			Parts Issued			Qu	antity
- Diagnos	e check engine light.p0456.test a	and replace fail	ed fuel cap.clear	Gas Cap Non-locking)			1.00
codes.		·	•	Shop Supplies				1.00
- Shop Suj	pplies							

Vork Order: 13 Problem: Pr		Meter: 28962		In Date:	10/01/2013	Closed:	10/22/2013
Work Comple	eted		Parts Issued			Q	uantity
- P.m. Service).		5w20 Engine Oil				7.00
- Replace tag	lamp and dome light bulbs.		Napagold Oil Filter				1.00
- Replace hoc	od props.		31-24 Wiper Blade	s 2			2.00
- Rotate and	balance all tires.		Hood Lift Support				2.00
- Shop Suppli	ies		Shop Supplies				1.00
	Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 84.	.29	Total:	369.29
Vork Order: 14 Problem: Re		Meter: 29851 e lights installed.Check becon ,tur	nsignal light and trail	In Date: ler harness.	02/21/2014	Closed:	02/28/201
Work Comple	eted		Parts Issued			Q	uantity
- Replace roof mounted beacon light.fabricate and install four corner strobe			Vtx609c Led Strobe	e Cl			2.00
, per request	5		Vtx609a Led Strobe	e Am			2.00
- Check traile	r connector.install new conne	ctor,fabricated and install wiring.	Clr Rtv Silcn Sealan	t			1.00
- Shop Suppli	ies		Bulb				2.00
			Trailer Conn Socket	t			1.00
			Shop Supplies				1.00
	Hours: 10.50	Comm: 0.00	Labor: 630.00	Parts: 470	0.86	Total:	1,100.86
Vork Order: 14 Problem: P.	104920 M. service and Tie rod recall	Meter: 31041 n62.		In Date:	05/20/2014	Closed:	06/11/201
Work Comple	eted		Parts Issued			Q	uantity
- P.m. Service).		Washer Pump				1.00
- Resurface fr	ont brake rotors, replace brak	es pads.service and lube	Brake Pads				1.00
calipers.flush a	and bleed system.		Seat R And R				1.00
- Diagnose in	op windshield washer.replace	e defective pump.	5w20 Engine Oil				7.00
- R&r driver s	eat for upholstery repairs.		Napagold Oil Filter				1.00
- Transport ve	ehicle to dealer for recall#n62		31-24 Wiper Blade	s 2			2.00
- Shop Suppli	ies		Shop Supplies				1.00
	Hours: 10.75	Comm: 0.00	Labor: 645.00	Parts: 538	8 58	Total	1,183.58

Work Order: 1411902 Meter: 32374 11/25/2014 Closed: 12/12/2014 In Date: Problem: Pm service.Flat tire and right side mirror loose. Parts Issued Quantity **Work Completed** 5w20 Engine Oil 7.00 - Pm service. Napagold Oil Filter 1.00 - Check battery and charging system.battery failed loadtest..replace defective battery. Used Fire X Refurbished 1.00 - Secure loose right side mirror assembly. 31-24 Wiper Blades 2 2.00 - Replace one tire.rotate and balance all four. 179469492 Lt245-70r17 1.00 - Shop Supplies Battery 65 1.00 Cap Wheel 1.00 Stg Wheel Cov - Chevy 1.00 Shop Supplies 1.00 Tire Disposal Fee 1.00 Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 599.89 Total: 929.89 Work Order: 1412743 Meter: 32434 In Date: 12/22/2014 Closed: 12/31/2014 Problem: Towed in.No start. Parts Issued Quantity Work Completed Fuel Module 1.00 - Test fuel pressure.r&r fuel tank and replace fuel pump.clean and refill fuel tank. Shop Supplies 1.00 - Shop Supplies Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 238.87 Total: 448.87 Work Order: 1412834 Meter: 32404 **In Date:** 12/19/2014 **Closed:** 12/29/2014 Problem: No start **Work Completed**

- Tow From: 3700 Belvedere Rd, To: Lv Shop

Hours: 0.00

Comm: 104.15

Labor: 0.00

Parts: 0.00

Total: 104.15

Work Order:	1504062	Meter: 33727		In Date:	04/20/2015	Closed:	04/28/2015
Problem:	Four wheel drive inop.						
Work Com	pleted		Parts Issued			Qu	antity
- Inspect a	and replace both defective training	nsfer case shifter shaft bushings.	Grommet				2.00
- Shop Supplies		Shop Supplies				1.00	
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 29	.90	Total:	89.90
Nork Order: Problem:	1509061 Pm service.	Meter: 34996		In Date:	09/09/2015	Closed:	09/28/2015
Work Com	pleted		Parts Issued			Qı	antity
- Pm servi	ce.		5w20 Engine Oil				7.00
- Replace	and balance all four tires.		Napagold Oil Filter				1.00
- Test and	replace defective left tail lam	p socket and bulb.also secure	Wiper Blade				2.00
headliner.			Washer Fluid Conce	entr			1.00
- Perform	complete front end alignmen	t.	Napagold Air Filter				1.00
- Shop Su	oplies		1qt Syngearoil 75w	140			1.00
			Lt245/70r17/10				4.00
			Tr416 Valve Stem				4.00
			Tail Light Socket				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
	Hours: 8.00	Comm: 0.00	Labor: 480.00	Parts: 1,1	76.76	Total:	1,656.76

Work Order:1603678Meter:35825Problem:P.M. service and right front tire goin g flat and recall r25.

In Date: 04/07/2016 **Closed:** 04/26/2016

Work Com	pleted		Parts Issued		Quantity
- P.m. Serv	<i>v</i> ice.		5w20 Engine Oil		7.00
- Test batt	ery and charging system.replac	e bad battery.	Napagold Oil Filte	1.00	
- Repair rig	- Repair right front tire, rotate and balance all four.				2.00
- Transport vehicle to dealer for recall #r25. - Replace and re-key worn-out ignition cylinder.			Washer Fluid Con	1.00	
			Battery	1.00	
- Shop Su	oplies		Ignition	1.00	
			Shop Supplies		1.00
	Hours: 9.50	Comm: 0.00	Labor: 570.00	Parts: 414.53	Total: 984.53
Vork Order: Problem:	1604067 Key will not turn in Ignition	Meter: 35770		In Date: 04/18/201	6 Closed: 04/18/201
Work Com	pleted				
- Tow Fror	m: 3700 Belvedere Rd (airport N	Naint) Behind Bldg E To: Lv Shop			
	Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	Total: 96.00

Work Order:	1608745	Meter: 37412	In Date:	08/23/2016 Closed:	09/12/2016
Problem:	Braks hard to stop and move tool bo	ox to front and tool box locks, struts and check A/C,	recall.		

Work Completed		Parts Issued		Quantity
- Diagnose brakes for hard pedal concern.rep	place defective booster and	R134a Lv Shop 2		2.00
master cylinder.flush and bleed system.		Reman Brake Boos	ster	1.00
- Relocate tool box to front of truck bed.repla	3	Brake Master Cylir	nder	1.00
and four lid props.relocate beacon light to lef	t side of bed ande	B Fluid Dot 3-32oz	Z	1.00
rewire.replace bad stop lamp switch.	and look chack	Brake Cleaner		1.00
 A/c performance test.recover freon.vacuum system.recharge to specs. 		Support		4.00
- Shop Supplies		Pedal Pad	1.00	
		Tool Lock Cylinder	r	1.00
		Latch Assy		1.00
		Brake Stop Switch		1.00
		Shop Supplies		1.00
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 712.43	Total: 1,222.43
Nork Order: 1610146	Motor: 27929		In Data: 00/28/20/	16 Closed: 11/02/2016

Work Order: 1610146

Meter: 37838

In Date: 09/28/2016 Closed: 11/03/2016

Problem: P.M. service and A/C clutch hot and discolored.

Work Completed

- Pm Service

- Ck a/c operation for odor. Coolant leaking, repl failed water pump. Replace Thermostat, serp belt, & tensioner. Flush & refill coolant.

- perform transfer case service
- Rotate & balance 4 tires, nitro fill.
- Shop Supplies

Parts Issued		Qua	ntity
5w20 Engine Oil			7.00
Napagold Oil Filter			1.00
Wiper Blades 24"			2.00
Washer Fluid Concen	tr		1.00
Bulb			1.00
New Water Pump			1.00
Belt - Serpentine			1.00
Peak Global Antifrz			2.00
Syn-atf Trans Fluid S			2.00
Thermostat			1.00
Tensioner Assy			1.00
Shop Supplies			1.00
Labor: 585.00	Parts: 300.79	Total: 8	385.79

Work Order: 1610148	Meter: 37507		In Date:	09/28/2016	Closed:	09/28/2016
Problem: 1 - Key(s) issued						
Work Completed		Parts Issued			Qı	uantity
- 1 - Key(s) issued		Duplicate Vehicle Key	/S			1.00
Hours: 0.30	Comm: 0.00	Labor: 18.00	Parts: 3.0	0	Total:	21.00
Work Order: 1612121 Problem: Check engine light runs rough a	Meter: 38261 nd install inverter under drivers	seat.	In Date:	11/28/2016	Closed:	12/13/2016
Work Completed		Parts Issued			Qı	uantity
- Diagnose check engine light.p0302.perfor	m tune-up.replace spark plugs	Champ Copper Spark	C PI			16.00
and #3 coil.clear codes.		Ing Coil On Plug				1.00
- Service and clean throttle body and induct	tion system.flush injectors.	Intake Cleaner Kit				1.00
- Install power inverter.fabricate and install	wiring.	Injector Cleaner				1.00
- Shop Supplies		Bat/cabl				15.00
		Bulk Battery Cable				15.00
		Fab/loom				15.00
		Cb185-150 Cir Brkr				1.00
		Shop Supplies				1.00
Hours: 10.50	Comm: 0.00	Labor: 630.00	Parts: 290).35	Total:	920.35
Work Order: 1700041 Problem: Left rear tire going flat.	Meter: 38664		In Date:	01/03/2017	Closed:	01/11/2017
Work Completed		Parts Issued			Qı	uantity
- Repair and balance left rear tire.		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: 1701158 Problem: Right rear tire going flat.	Meter: 38989		In Date:	02/03/2017	Closed:	02/08/2017
Work Completed		Parts Issued			Qu	uantity
- Repair and balance right rear tgire.		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00				62.00

Work Order: 1705873 Meter: 400 Problem: P.M. service ,coolant leak,brake lights blow out,n		front seat.	In Date:	06/13/2017	Closed:	06/23/2017
Work Completed		Parts Issued			Qı	antity
- P.m. Service.		Seat R And R				1.00
- Replace damaged pintle pin.		5w20 Engine Oil				7.00
- R&r driver seat for upholstery repair.		Napagold Oil Filter				1.00
- Pressure test and inspect cooling system.replace leaking ra	diator.flush and	Wiper Blades 24"				2.00
refill system.		Washer Fluid Concent	tr			1.00
- Check brake lights.replace left side socket.		Used Fire X Refurbish	ed			1.00
- Shop Supplies		Napa Radiator				1.00
		Peak Global Antifrz				2.00
		Pintle Pin W/clip	•		1.00 1.00	
		Tail Lamp Circuit Boar				
		Rad Cap				1.00
		Hose Clamp				1.00
		1 2 Ss Hose Clamp				1.00
		Bulb				1.00
		Shop Supplies				1.00
Hours: 7.00 Co	mm: 0.00	Labor: 420.00	Parts: 527	7.29	Total:	947.29
Vork Order: 1708074 Meter: 413	358		In Date:	08/16/2017	Closed:	08/24/2017

Vork Order:1708074Meter:41358In Date:Problem:A/C blower inop and A/C not cold ,left mirror glass cracked and check rear bumper damage.

Work Completed				Quantity
- Diagnoise blower inop.blower motor and resistor	bad .replace	Ac Condenser Ass	у	1.00
th.diagnoise A/c not cooling .condensor fan motor not working .replace	Blower Motor Asse	embly	1.00	
fan assembly.recover and recharge A/c system.chec	fan assembly.recover and recharge A/c system.check for leaks.			1.00
 Replace drivers door mirror. Bumper damage not receiver. 	t effecting hitch or	Mirror Asy		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 4.90	Comm: 0.00	Labor: 294.00	Parts: 691.21	Total: 985.21

Nork Order: 1	1708566	Meter: 41457		In Date:	08/30/2017	Closed:	08/31/201
Problem: A	AC Leaking inside cab.						
Work Comp	pleted		Parts Issued			Qı	uantity
- Dry out an operators co	nd clean and weld plastic evap l poler.	pox.due to damage from	Shop Supplies				1.00
- Shop Supp	plies						
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Nork Order: 7 Problem: F		Meter: 43376 ing flat and washer hose broken.		In Date:	01/26/2018	Closed:	02/05/2018
Work Completed			Parts Issued			Qu	uantity
- P.m. service.		5w20 Engine Oil				7.00	
- Replace all four tires.nitrogen fill tires and high speed balance all four.		Napagold Oil Filter				1.00	
- Test and replace left rear tail light assembly mount new strobe light in lens			Wiper Blades 24"				2.00
.replace brok	ken tag light .repair broken was	sher hose.	Used Fire X Refurbis	hed			1.00
- Perform co	omplete front end alignment.		Tire Lt 245/70/17				4.00
- Shop Supp	plies		Tr416 Valve Stem				4.00
			Tail Lamp				1.00
			Lic Lamp Assy				1.00
			Tail Light Socket				1.00
			Lamp Socket				1.00
			Mnt Conc Led Clear				1.00
			Vtx609a Led Strobe	Am			1.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
	Hours: 9.25	Comm: 0.00	Labor: 555.00	Parts: 1,6	90.02	Total:	2,245.02

Work Order: Problem:	1803015 inspect trailer plug	Meter: 43724		In Date:	03/21/2018	Closed:	03/28/2018
Work Com	pleted		Parts Issued			Qı	uantity
- install tra	iler brake controller and run wi	ring to trailer plug	Adapter				1.00
- Shop Sup		5 1 5	Brake Control				1.00
			Shop Supplies				1.00
	Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 84.	56	Total:	324.56
Work Order: Problem:	1804749 trailer plug problem	Meter: 44217		In Date:	05/07/2018	Closed:	05/09/2018
Work Com	pleted		Parts Issued			Qı	uantity
- replace tr	ailer plug		trailer plug				1.00
- Shop Sup			Shop Supplies				1.00
	Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 13.	10	Total:	103.10
Work Order: Problem:	1805560 Towed in for no start.	Meter: 44398		In Date:	05/31/2018	Closed:	06/05/2018
Work Com	pleted		Parts Issued			Qı	uantity
- Check an	d inspect charging system .alte	rnator failed .r&r defective	Alternator				1.00
alternator.	Charge battery fully.		Shop Supplies				1.00
- Shop Sup	oplies						
	Hours: 1.40	Comm: 0.00	Labor: 84.00	Parts: 268	3.60	Total:	352.60
Work Order: Problem:		Meter: 44380		In Date:	05/31/2018	Closed:	06/01/2018
Work Com	pleted						
- Tow From	n: 3700 Belvedere rd Bldg #e T	o: Lv shop					
	Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00

2/10/2023 7:35:56 AM

Vork Order: Problem:	1805879 Check engine light.	Meter: 44464		In Date:	06/08/2018	Closed:	06/25/2018	
Work Com	pleted		Parts Issued			Q	uantity	
- Diagnose	e check engine light-p0420. Cat	alytic converter efficiency	U-bolt				1.00	
low.replace	both upstream catalytic conver	ters.clear codes.	U-bolt				1.00	
- Shop Sup	oplies		Pipe				1.00	
			Cat Conv				1.00	
			Shop Supplies				1.00	
	Hours: 4.00 Comm: 0.00		Labor: 240.00	Parts: 420.01 Tota			al: 660.01	
Vork Order: Problem:	1807728 P.M. service and A/C inop at ti	Meter: 45087 mes.		In Date:	07/30/2018	Closed:	08/06/2018	
Work Completed			Parts Issued			Q	uantity	
- P.m. service.			5w20 Engine Oil				6.00	
- Diagnose noise from belt area . Replace idler pully and retest.			Napagold Oil Filter				1.00	
- Replace le	eft and right worn out motor m	ounts .	Washer Fluid Concentr				1.00	
- Rotate an	nd balance all four tires. Nitroge	n fill tires.	Wiper Blades 24"				2.00	
- A/c perfo	ormance test . Scan for codes ,no	o codes present . Check pressure	Used Fire X Refurbished				1.00	
and temp a	t vents 42 degrees. Could not d	upicate concern.	Drivebelt Idler Pulley	/			1.00	
- Shop Sup	oplies		Bracket Motor Mour	nt			2.00	
			Shop Supplies				1.00	
	Hours: 9.35	Comm: 0.00	Labor: 561.00	Parts: 337	1.28	Total:	892.28	
Vork Order: Problem:	1809160 A/C blows warm at times.	Meter: 45513		In Date:	09/06/2018	Closed:	09/13/2018	
Work Com	pleted		Parts Issued			Q	uantity	
- A/c performance test . Vents blowing 40 degrees. Test drive . Scan for codes no codes . Test condensor fan operation ok .evac and recharge system ,not low . Could not dupicate complaint at this time.			Shop Supplies				1.00	
- Shop Sup	oplies							
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00	

Vork Order: Problem:	1810070 Dead battery, Keep jump starting	Meter: 45690		In Date:	09/28/2018 Closed	: 10/01/2018
Work Com			Parts Issued			Quantity
	ery and charging system.replace ba	ad battery	Battery 65			1.00
- Shop Sup		a sattery.	Shop Supplies			1.00
	Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 17	2.77 Tota	al: 239.77
Vork Order: Problem:	1900980 P.M. service and four wheel drive	Meter: 47178 inop.		In Date:	01/25/2019 Closed	: 02/13/2019
Work Com	pleted		Parts Issued			Quantity
- P.m. serv	vice.		Napagold Oil Filte	r		1.00
- Compute	er diagnose check engine light . co	le P0300 . Perform tune up .	5w20 Engine Oil			7.00
Replace all sixteen spark plugs . Clear codes and road test.			Wiper Blades 24"			2.00
- Inspect transfer case . Replace missing shifter bushings and adjust shifter .			r . Washer Fluid Con	centr		1.00
- Perform	complete air intake decarb and flue	h injectors . Clean trottle bo	dy Macs Chain Cable	Lube		1.00
•			Spark Plugs			16.00
- Rotate ar	nd high speed balance all four tires	. Nitrofill all.	Grommet			2.00
- Shop Sup	oplies		Injector Cleaner			1.00
			Throttle Body Clea	aner		1.00
			Intake Cleaner Kit			1.00
			Shop Supplies			1.00
	Hours: 10.45	Comm: 0.00	Labor: 700.15	Parts: 33	8.28 Tota	al: 1,038.43
Vork Order: Problem:	1903637 Brake controller inop.	Meter: 47683		In Date:	04/03/2019 Closed	: 04/08/2019
Work Com	pleted		Parts Issued			Quantity
- Diagnose	e brake control locking up trailer bi	akes . R&r defective trailer	trailer plug			1.00
0	roller and defective trailer plug cor		Brake Control			1.00
- Shop Sup	oplies		Shop Supplies			1.00
	Hours: 1.50	Comm: 0.00	Labor: 100.50	Parts: 88	.05 Tota	al: 188.55

2/10/2023 7:35:56 AM

Work Order:	1903845	Meter:	47725		In Date:	04/09/2019	Closed:	04/10/2019
Problem:	Right rear tire going flat .							
Work Com	pleted			Parts Issued			Qı	antity
- Repair ri	ght rear tire and balance . Nitrog	en fill tires .		Shop Supplies				1.00
- Shop Su	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00
Nork Order:	1906730	Meter:	48955		In Date:	06/26/2019	Closed:	07/09/2019
Problem.	A/C stops blowing intermittenly							
r robieni.	A/C stops blowing intermittenity							
Work Com				Parts Issued			Qı	antity
Work Com			R&r defective	Parts Issued Blower Motor			Qu	a ntity 1.00
Work Com - A/c perfo	pleted		R&r defective				Qı	•
Work Com - A/c perfo	opleted prmance test . Inspect and test bl tor and resister.retest .		R&r defective	Blower Motor			Qı	1.00

Meter: 49388

Work Order: 1908359

In Date: 08/12/2019 Closed: 08/26/2019

Problem: P.M. service and A/C inop.

Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filter				1.00
- Test and replace high mount stop light bulbs		5w20 Engine Oil Wiper Blades 24"				7.00
- Check battery and charging system after fully	charging battery . Battery					2.00
failed load test . R&r defective battery .		Used Fire X Refurbi	shed			1.00
- Perform A/c performance test . Replace defec		Whl/cvr				1.00
,condensor, accumulator and fixed orfice line . I complete recharge to factory specs . Retest .	Boxed Miniatures				2.00	
- Balance and rotate all four tires . Nitrofill all.	Battery				1.00	
- Shop Supplies	A/c Gadket Kit Freon Lv Shop 1				1.00	
- Shop Supplies					2.00	
		Hose Liquid A/c				1.00
		Aa/c Accumulat			1.00	
		Fan A/c Condenser				1.00
		A/c Condenser				1.00
		Shop Supplies				1.00
Hours: 11.75	Comm: 0.00	Labor: 787.25	Parts: 690	0.56	Total:	1,477.81
Problem: 2000178 Problem: Two tires going flat .	Meter: 51100		In Date:	01/07/2020	Closed:	01/08/2020
Work Completed		Parts Issued			Qı	uantity
- Repair right rear tire and right front tire . Bala	nce both . Nitrofill all.	Shop Supplies				1.00
- Shop Supplies						
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 4.0	0	Total:	150.00

Nork Order: Problem:	2002802 Right and left rear tires going	Meter: 52045 flat.		In Date:	03/19/2020	Closed:	03/19/2020
Work Com	pleted		Parts Issued			Q	uantity
- Replace t	two rear tires and balance . Nit	rofill all .	Shop Supplies				1.00
- Shop Sup			Lt245/70r17 Tire				2.00
			Tire Disposal Fee				2.00
	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 307	7.97	Total:	380.97
Nork Order: Problem:	2002851 PM Service, Power steering in	Meter: 52074 nop.		In Date:	03/20/2020	Closed:	03/31/2020
Work Com	pleted		Parts Issued			Q	uantity
- P.m. serv	ice.		Napagold Oil Filter				1.00
- Diagnose	e no power assist on steering .	R&r defective power steering	5w20 Engine Oil				7.00
5	sh and bleed power steering sy	1 5	Washer Fluid Concentr 22" Wiper Blade				1.00
- Perform	headlight restoration .						2.00
- Replace t	two tires . Rotate and balance a	all four tires . Nitrofill all.	Pawer Sterring Pum	1.00			
- Shop Sup	oplies		3m Tm Headlight L	ens			1.00
			Tran Flu Qt Dexron	3i			2.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
			Lt245/70r16				2.00
	Hours: 8.25	Comm: 0.00	Labor: 602.25	Parts: 403	3.57	Total:	1,005.82
Vork Order: Problem:	2003328 Had to jump start .	Meter: 52147		In Date:	04/02/2020	Closed:	04/06/2020
Work Com	pleted		Parts Issued			Q	uantity
- Battery fa	ailed load test . R&r defective b	pattery and retest charging system .	Battery 65				1.00
- Shop Sup	oplies		Shop Supplies				1.00
	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 180	0.69	Total:	253.69

Vork Order: 2004254 Problem: Towed in for no start	Meter: 52409		In Date: 04/28/2020	0 Closed:	05/05/2020
Work Completed		Parts Issued		0	iantity
•				QL	•
	ode P127a . Perform pinpoint test and	Starter			1.00
starter circuit test . R&r defective	starter assembly and retest . Clear code .	Shop Supplies			1.00
- Shop Supplies					
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 194.61	Total:	340.61
Vork Order: 2004274 Problem: seems like starter we	Meter: 52368 nt bad. been acting up		In Date: 04/28/2020	0 Closed:	04/29/2020
Work Completed					
work completed					
- Tow From: 8100 belvedere, mee	et jose at 711 To: vista				

Meter: 53888

Work Order: 2008949

In Date: 09/04/2020 **Closed:** 09/22/2020

Problem: PM Service, Replace tool box locks. Drivers rear tire has a nial in it.

Work Completed			Parts Issued			Qı	antity
- P.m. service.			White Shepherd S	Stp Lk			1.00
- Test and replace defe	ctive trailer plug cor	nector and rewire as needed .	Napagold Oil Filte	er			1.00
- Replace front brake re	otors , calipers , hose	es and pads . Flush and bleed	5w20 Engine Oil				7.00
brake system and Road	test .		Used Fire X Refure	bished			1.00
- Force entry into right assembly and retest .	side tool box . Repla	ace broken tool box latch	Napagold Air Filte	er			1.00
,	Léourtines Nitrafill		trailer plug				1.00
- Balance and rotate all puncture it .	i tour tires . Nitrotili a	all.remove nail from tire did not	Brk Fluid Dot 4-32	2oz			1.00
- Shop Supplies			Reman Brake Cali	per			1.00
			Reman Brake Cali	per			1.00
			Brake Rotor Only	,			2.00
			Brake Pads				1.00
			Brake Hose				1.00
			Brake Hose				1.00
			Latch & Strik	er Kit			1.00
			Shop Supplies				1.00
Hc	ours: 10.25	Comm: 0.00	Labor: 748.25	Parts: 750.	76	Total:	1,499.01
Vork Order: 2010912 Problem: Towed in fo	or no start .	Meter: 54385		In Date:	10/29/2020	Closed:	11/24/2020
Work Completed			Parts Issued			Qı	antity
3		nator test ok. Found excessive inal at starter. Replace connector	Shop Supplies				1.00
- Shop Supplies							
Hc	ours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00		Total:	77.00

7:35:56 AN	Λ		6 DODGE 2500 Picku		,			
Work Order: Problem:		Mete	er: 54362		In Date:	10/29/2020	Closed:	10/30/2020
Work Com	pleted							
- Tow Fron	n: 3700 Belvedere Rd-	Near Fuel Island To: 2	2601 Vista Parkwary					
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	00	Total:	96.00
Work Order: Problem:	2100644 Towed in Will not shi		er: 55262 ight on .		In Date:	01/19/2021	Closed:	01/28/2021
Work Com	pleted			Parts Issued			Qı	antity
- Diagnose	e transmission, Codes I	P0932, P0733, P0734,	P1790, P0869,	Sensor Transducer				1.00
Remove pa	n full of clutch debris,	Replace transmission	, Replace engine rear	Big G Degreaser 1 Ga	il			1.00
main seal, S trans verific	Service transfer case. R	eplace oil cooler, Clea	ar codes, Perform	Bars Leak Hd Conc				1.00
- Shop Sup				Rear Main Seal Set				1.00
- Shoh Sh	phes			Napa Oil Seal				1.00
				Rebuilt Transmission	Assy			1.00
				Tram Oil Atf 4				12.00
				Tram Oil Cooler				1.00
				Shop Supplies				1.00
	Hours: 8.00		Comm: 0.00	Labor: 584.00	Parts: 4,1	76.12	Total:	4,760.12
Work Order: Problem:	2101754 tranny issues	Mete	er: 55530		In Date:	01/19/2021	Closed:	02/16/2021
Work Com	pleted							
- Tow Fron	n: Pbia To: Lv shop							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	00	Total:	96.00

Palm Beach County Fleet Management Asset Maintenance History

2/10/2023

Meter: 55840

Work Order: 2102862

In Date: 03/12/2021 **Closed:** 03/25/2021

Problem: PM Service No Start (keys in truck)

Hours: 0.00

Work Completed		Parts Issued			Qı	uantity
- Preventive Maint. Service		Relay				1.00
- Diagnose no start, Scan no related codes, I	ound intermittent starter	5w20 Engine Oil				7.00
solenoid bad, Replace starter, relay and servi	ce all connections.	Napagold Oil Filter				1.00
- Replace right rear license plate light, R&r r		22" Wiper Blade				2.00
Strobe bulb and reseal. Rewire front strobe c	,	Relay				1.00
- Replace front track bar, Due to drivers side	0	Mnt Conc Led Clear				1.00
- Diagnose excessive steering play, Replace hydraulic system.	bad steering gear. Flush	Permatex				1.00
- Perform alignment, straighten steering wh	eel Road test	Lamp				1.00
- Shop Supplies		New Starter				1.00
- Shop Supplies		Tram Oil Atf 4				3.00
		Steering Gear				1.00
		Track Bar				1.00
		Shop Supplies				1.00
Hours: 12.95	Comm: 0.00	Labor: 945.35	Parts: 1,2	17.95	Total:	2,163.30
/ork Order: 2103960	Meter: 56100		In Date:	04/08/2021	Closed:	04/20/2021
Problem: Towed in for wont start						
Work Completed		Parts Issued			Qu	antity
- Diagnose bad starter, Replace starter, Perfe	orm voltage drop tests on	New Starter				2.00
starting and charging system circuits. All goo	od.	Shop Supplies				1.00
- Shop Supplies						
Hours: 1.60	Comm: 0.00	Labor: 116.80	Parts: 393	3.25	Total:	510.05
Vork Order: 2104055 Problem: wont start	Meter: 55962		In Date:	04/08/2021	Closed:	04/12/2021
Work Completed						
- Tow From: Doa maint comp To: 2601 vista						

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Nork Order: Problem:	2104632 No Start (keys in truck)	Meter: 56176			In Date:	03/12/2021	Closed:	04/26/202
Work Com	pleted							
- Tow Fron	m: Pbia Maint3700 Belvedere r	d To: Lv shop						
	Hours: 0.00	Comm: 96.00		Labor: 0.00	Parts: 0.0	0	Total:	96.00
Vork Order: Problem:	2106150 AC works intermittently. AC bl	Meter: 56861 ows cold on start up, but soor	n stops	blowing cold- Na		06/04/2021 Check engine		06/29/202
Work Com	npleted			Parts Issued			Qı	uantity
- Low Side	e Vapor Line Freazing Up Perfor	med A/c Performace Test Four	nd	Red Angel Ac Sto	p Lk			1.00
Low On Fre	eon Parts Unavaliable Injected L	eak Sealant, Remove Dash An	d	E8 A/c Oil Univ W	Dye			1.00
•	ode Doors And Actuators Reter	st system . Evac and complete	-	Freon Lv Shop 1				4.00
recharge sy	Up Snapon Scanned Code P042	10 Increasted Park 1 Catalityic	_	Oxygen Sensor Oxygen Sensor Cat Conv Cap And Valve Kit Sensor - Heater Temp Camper Foam Tape				1.00
	No Visual Defects Seen Data R8		Clear					1.00
	Retest . Replace Stuck On Brak	, 3						1.00
- Shop Sup	pplies		-				1	1.00
								1.00
			_					1.00
			_	Evaporator Core				1.00
				Air Door Actuator				1.00
				Air Door Actuator				3.00
				Door				1.00
				Blower Motor Res	istor			1.00
				Mode Door Repai	r Kit			1.00
				Marine Adh Seal I	3lk			1.00
			-	Brake Light Switc	h			1.00
				Shop Supplies				1.00
	Hours: 11.90	Comm: 0.00		Labor: 868.70	Parts: 1,4	35.84	Total:	2,304.54

Vork Order: Problem:	2109023 Front passenger tire has nail in i	Meter: 57842 t.		In Date:	08/19/2021	Closed:	08/19/202
Work Com			Parts Issued			Qı	uantity
	, ht front tire and balance . Nitro f	ill all	Shop Supplies				1.00
- Shop Sup	-						
Shop Sup	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.6	5	Total:	75.65
/ork Order: Problem:	2110006 PM Service and A/C warm at idl	Meter: 57940 e send to SE for spray rig servic	e	In Date:	09/15/2021	Closed:	09/30/202
Work Com	pleted		Parts Issued			Q	uantity
- Preventiv	e Maint. Service		5w20 Engine Oil				7.00
- Rotated a	and balanced all 4 tires. Nitrogen	filled all tires.	Napagold Oil Filter				1.00
	e both back up lights inop. Found		22" Wiper Blade				2.00
-	up light bulbs.		Boxed Miniatures				2.00
- Diagnose	e ignition hard to turn. Found to h	ave worn out key. Replaced key	Non-chlor Brake Clnr				1.00
9	e power steering fluid leak. Found	5 1 5	Socket				1.00
	vitch. Replaced pressure switch ar		Power Steering Press		1.00		
	e A/c not working at idle. Found to		A/c Fan Motor Assy				1.00
-	Replaced fan assembly and conne	CLOF.	Key Blank				1.00
- Shop Sup	phies		Shop Supplies			1.00	
	Hours: 8.55	Comm: 0.00	Labor: 624.15	Parts: 143	3.63	Total:	767.78
Vork Order: Problem:	2110846 A/c condenser keeps shutting of	Meter: 58065 f making it blow hot air. Left rear	tire going flat .	In Date:	10/06/2021	Closed:	10/28/202
Work Com	pleted		Parts Issued			Qı	uantity
- Scan for	codes , no codes . Perform A/c pe	rformance test . blows 39	Switch - Ignition				1.00
0	vents . Test drove serval times an	d let idle . Could not duplicate .	Tire Lt 245/70/17				2.00
•	s . R&r defective ignition switch .		Shop Supplies				1.00
- Replace b Nitro fill all	both rear tires and balance . Due t	to worn out and large hole .	Tire Disposal Fee				2.00
- Shop Sup	oplies						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 433	3.99	Total:	579.99

Nork Order: Problem:	2112988 both front tires have puntures, (n	Meter: ails)	58496		In Date:	12/08/2021	Closed:	12/09/2021
Work Com	pleted			Parts Issued			Qı	uantity
- repair lef right front.	t front tire, balance and nitro servi	ce, removed	short screw from	Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 2.6	5	Total:	75.65
Nork Order: Problem:	2203190 PM Service. A/C inop , no blow	Meter:	59481		In Date:	03/24/2022	Closed:	03/31/2022
Work Com	pleted			Parts Issued			Q	uantity
- Preventiv	ve Maint. Service			Napagold Oil Filter				1.00
- rotate an	d balance all 4 tire nitro fill all			5w20 Engine Oil				7.00
- vehicle a	c system was not blowing and ho	t . Tipm four	id at fault after	22" Wiper Blade				2.00
	Install jumper wire and fuse . Rete	•		Fuse Holder				1.00
- Shop Sup	oplies			Shop Supplies				1.00
	Hours: 8.75		Comm: 0.00	Labor: 638.75	Parts: 33.	31	Total:	672.06
Work Order: Problem:	2204650 Passenger Rear tire damage	Meter:	59956		In Date:	04/29/2022	Closed:	05/03/2022
Work Com	pleted			Parts Issued			Q	uantity
- Replace k	both rear tire and balance . Nitro f	ill all.		Lt 245/70/17 Tire Bf	g			2.00
- Shop Sup				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 348	3.13	Total:	421.13
Work Order: Problem:	2206967 Had to jump start. RPM running	Meter: high. No thro		lowning hot.	In Date:	06/30/2022	Closed:	07/06/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Compute	er diagnose ,only low voltage code	s . Check sta	rting and charging	Battery				1.00
system. Fou	und intermittent short in battery. F		0 0 0	Battery				1.00
cables. Rete				Shop Supplies				1.00
- Shop Sup	oplies							

2/10/2023 7:35:56 AN		Palm B K11735		lanagement Asset Maintena 00 Pickup, 3/4 Ton, 4X4	ance History			
Work Order: Problem:	2206995 RUNNING ROUGH	Meter: 60	0793		In Date:	06/30/2022	Closed:	07/01/2022
Work Com	pleted							
- Tow From	n: 3700 Belvedere Rd W	pb To: 260 ⁻	1 Vista Pkwy					
	Hours: 0.00	C	omm: 113.00	Labor: 0.00	Parts: 0.0	0	Total:	113.00
					In Date:	10/28/2022	Closed:	11/23/2022
Work Order:	2211141	Meter: 62	2284		in Date.			
			-	specialized equip to PM L00				
	PM Service. Engine lig		-	o specialized equip to PM L00 Parts Issued			Qı	lantity
Problem: Work Com	PM Service. Engine lig		-		0701 sprayer i		Qu	Jantity 1.00
Problem: Work Com - Preventiv	PM Service. Engine lig	ht is on. Or	-	Parts Issued	0701 sprayer i		Qı	•
Problem: Work Com - Preventiv - rotate and	PM Service. Engine lig pleted e Maint. Service	ht is on. Or	-	Parts Issued Napagold Oil Filter	0701 sprayer i		Qı	1.00
Problem: Work Com - Preventiv - rotate and - Test and	PM Service. Engine lig pleted e Maint. Service d balance all 4 tires nitro replace relay .	ht is on. Or	-	Parts Issued Napagold Oil Filter 5w20 Engine Oil	9701 sprayer i		Qı	1.00 7.00
Work Com - Preventiv - rotate and	PM Service. Engine lig pleted e Maint. Service d balance all 4 tires nitro replace relay .	ht is on. Or	-	Parts Issued Napagold Oil Filter 5w20 Engine Oil 22'' Wiper Blade	9701 sprayer i		Qı	1.00 7.00 2.00
Problem: Work Com - Preventiv - rotate and - Test and	PM Service. Engine lig pleted e Maint. Service d balance all 4 tires nitro replace relay .	ht is on. Or	-	Parts Issued Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Px 101br Copper Si	9701 sprayer i		Qı	1.00 7.00 2.00 1.00