

3/6/2023  
3:59:16 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10206695 2017 SCAG STT72V25KBD Mower, 72in Zero Turn Radius**

---

**Total Hours: 44.50    Labor: 3,154.50    Parts: 2,188.75    Comm: 0.00    Charged: 5343.25**

---

**Work Order:** 1711810      **Meter:** 1      **In Date:** 12/01/2017    **Closed:** 12/01/2017  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 2.00      Comm: 0.00      Labor: 120.00      Parts: 0.00      Total: 120.00

---

**Work Order:** 1803470      **Meter:** 77      **In Date:** 04/03/2018    **Closed:** 04/17/2018  
**Problem:** Replace blades.

**Work Completed**

- Replace blades.

- Shop Supplies

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 81.74      Total: 141.74

---

**Parts Issued      Quantity**

Mower Blade      3.00

Shop Supplies      1.00

---

**Work Order:** 1806605      **Meter:** 163      **In Date:** 06/27/2018    **Closed:** 07/12/2018  
**Problem:** Replace blades

**Work Completed**

- Replace worn blades.

- Shop Supplies

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 81.74      Total: 141.74

---

**Parts Issued      Quantity**

Mower Blade      3.00

Shop Supplies      1.00

---

**Work Order:** 1810883      **Meter:** 306      **In Date:** 10/23/2018    **Closed:** 10/29/2018  
**Problem:** Replace blades

**Work Completed**

- Replace blades.

- Shop Supplies

Hours: 1.00      Comm: 0.00      Labor: 67.00      Parts: 82.74      Total: 149.74

---

**Parts Issued      Quantity**

Mower Blade      3.00

Shop Supplies      1.00

---





3/6/2023  
3:59:16 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10206695 2017 SCAG STT72V25KBD Mower, 72in Zero Turn Radius**

**Work Order:** 2100755

**Meter:** 720

**In Date:** 01/22/2021 **Closed:** 02/17/2021

**Problem:** Staff will deliver this asset to Pahokee Fleet this morning for PM service.

**Work Completed**

- Preventive Maint. Service
- Replace damaged blades, blade bolts and nuts
- Replace worn out front deck rollers, damaged front roller shaft and outer rear deck rollers.
- Replace worn pump drive belt, Pto drive belt and tensioner springs
- Replace damage warning decal on instrument panel
- Shop Supplies

**Parts Issued**

**Quantity**

15w40 Bulk Tank Pahokee	4.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Aw68 Hyd Fluid Tank Pahokee	3.00
Oil Filter	1.00
Hh Bolt	3.00
Nut	3.00
Mower Blade	3.00
Carriage Bolt	4.00
Roller Shaft	1.00
Deck Wheel	3.00
Pto Spring	1.00
Anti-scalp Wheel	4.00
Belt	1.00
Pump Drive Spring	1.00
Belt	1.00
Decal Inst Panel	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 650.29

Total: 1,270.79

3/6/2023  
3:59:16 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10206695 2017 SCAG STT72V25KBD Mower, 72in Zero Turn Radius**

---

**Work Order:** 2204472      **Meter:** 905      **In Date:** 04/26/2022    **Closed:** 05/04/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- replaced bent worn blades
- serviced hydraulic system changed filter and drained tank and wheel motors and refilled
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
15w40 Bulk Tank Pahokee	4.00
Napagold Fuel Filter	1.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Blade	3.00
Napa Hydraulic Filtr	1.00
Aw68 Hyd Fluid Tank Pahokee	4.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 112.58

Total: 550.58

---

**Work Order:** 2207958      **Meter:** 957      **In Date:** 08/01/2022    **Closed:**  
**Problem:** left side anti-scalping tire needs to be replaced

**Work Completed**

- Accessories / Attachments

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

---

**Work Order:** 2207981      **Meter:** 957      **In Date:** 08/02/2022    **Closed:** 08/22/2022  
**Problem:** Replace left-side anti-scalp tire

**Work Completed**

- Cut out damaged left front anti-scalp wheel mounting plate. Install new left anti-scalp mounting plate, wheel and bolt. Replaced worn right front anti-scalp wheel and bolt. Replaced damaged air cleaner assembly.
- Shop Supplies

**Parts Issued**

**Quantity**

Anti-scalp Wheel	2.00
Carriage Bolt	2.00
Anti-scalp Wheel Bracket	1.00
Air Filter Assy	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 401.22

Total: 547.22

3/6/2023  
3:59:16 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10206695 2017 SCAG STT72V25KBD Mower, 72in Zero Turn Radius**

---

**Work Order:** 2210638      **Meter:** 980      **In Date:** 10/18/2022      **Closed:** 10/20/2022  
**Problem:** Won't start.

**Work Completed**

**Parts Issued**

**Quantity**

- Charged and load test, it failed. Install new battery
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 111.76      Total: 184.76

---

**Work Order:** 2301650      **Meter:** 998      **In Date:** 02/17/2023      **Closed:** 02/17/2023  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 44.50      Total Labor: 3,154.50      Total Comm: 0.00      Total Parts: 2,188.75**