

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Total Hours: 80.00 Labor: 5,376.25 Parts: 3,785.12 Comm: 270.00 Charged: 9431.37

Work Order: 1500287 **Meter:** 1 **In Date:** 01/08/2015 **Closed:** 01/08/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1512684 **Meter:** 69 **In Date:** 12/16/2015 **Closed:** 12/31/2015
Problem: pm

Work Completed

- pm
- wash eq
- svc hyd sys inspect lines hoses fittings etc correct fluid level
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|------|
| Air Filter | 1.00 |
| Air Filter | 1.00 |
| Spin On Filter | 1.00 |
| Fuel Filter | 1.00 |
| Oil Filter | 1.00 |
| 15w40 Bulk South Reg | 6.00 |
| Shop Supplies | 1.00 |

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 164.39 Total: 524.39

Work Order: 1605076 **Meter:** 83 **In Date:** 05/16/2016 **Closed:** 05/25/2016
Problem: RECALL

Work Completed

- Prep. equipment ready for Hector to complete recall # 03-09.unsecure wire harness contact engine block.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 1608787 **Meter:** 181 **In Date:** 08/24/2016 **Closed:** 08/31/2016
Problem: Road call.Due for DPF Regen.

Work Completed

Parts Issued

Quantity

- C/cdpf Regen. Travel To West Boyton To Regen Dpf.test Run To Heat Up Dpf. Unable To Perform Regen. Communicationissue W/display.contact Dealer F/warranty Repair.
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1700192 **Meter:** 344 **In Date:** 01/06/2017 **Closed:** 01/12/2017
Problem: pm service

Work Completed

Parts Issued

Quantity

- Pm
- Service hyd sys
- Wash out mower and rad and motor
- Shop Supplies

15w40 Oil Qt 6.00

Air Filter 1.00

Air Filter 1.00

Oil Filter 1.00

Fuel Filter 1.00

Fuel Filter 1.00

Non-chlor Brake Clnr 2.00

Napa Hydraulic Filtr 1.00

Aw68 Hydro Fluid Hydr 6.00

Shop Supplies 1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 298.34 Total: 658.34

Work Order: 1705179 **Meter:** 478 **In Date:** 05/25/2017 **Closed:** 06/21/2017
Problem: needs regen/ someone changed code

Work Completed

Parts Issued

Quantity

- reset pin code (1,2,3,4) repalce opf pressure sensor, and perform regeneration
- Shop Supplies

Pressure Sensor 1.00

Shop Supplies 1.00

Freight Charge 1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 747.12 Total: 987.12

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 1707364 **Meter:** 529 **In Date:** 07/27/2017 **Closed:** 08/08/2017
Problem: wont go into regen mode

Work Completed

- Hector turf to fleet for software update

Hours: 0.00 Comm: 270.00 Labor: 0.00 Parts: 0.00 Total: 270.00

Work Order: 1802051 **Meter:** 739 **In Date:** 02/23/2018 **Closed:** 03/12/2018
Problem: P.M.SERVICE

Work Completed

- Pm Service.
- Replace right headlamp assembly.
- Service hydraulic system.
- Wash equipment.
- Contact dealer to enter pin to reset info. center.replace up and down switch.r/r 10 grease fittings.
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|-------|
| Air Filter | 1.00 |
| head light assmby | 1.00 |
| Air Filter | 1.00 |
| Fuel Filter | 1.00 |
| Fuel Filter | 1.00 |
| Oil Filter | 1.00 |
| 15w40 Bulk South Reg | 6.00 |
| screw grease roller | 10.00 |
| Grease Zerk | 10.00 |
| Switch | 1.00 |
| Switch | 1.00 |
| Shop Supplies | 1.00 |

Hours: 9.75 Comm: 0.00 Labor: 585.00 Parts: 621.53 Total: 1,206.53

Work Order: 1900886 **Meter:** 1070 **In Date:** 01/24/2019 **Closed:** 01/31/2019
Problem: Called for no start.Had to drive to Park Vista to diag. no start.

Work Completed

- C/c wont start.replace bad starter relay.replace three other relays due to corroded terminals.clean connections.reassemble and test run.
- Travel to park vista to diagnose.return to park vista to install new parts.
- Shop Supplies

Parts Issued

Quantity

| | |
|---------------|------|
| Relay | 2.00 |
| Relay | 2.00 |
| Shop Supplies | 1.00 |

Hours: 4.25 Comm: 0.00 Labor: 284.75 Parts: 118.56 Total: 403.31

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 1902978 **Meter:** 1111 **In Date:** 03/18/2019 **Closed:** 03/29/2019
Problem: PM Service.

Work Completed

- Pm Service.
- Service hyd. system.inspect lines,hoses,etc...
- Secure roof hardware.replace grease fittings on rollers.
- Wash equipment.
- Plug multiple holes in rear tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|------|
| Air Filter | 1.00 |
| Air Filter | 1.00 |
| Napa Fuel Filter | 1.00 |
| Fuel Filter | 1.00 |
| 15w40 Bulk South Reg | 6.00 |
| Oil Filter | 1.00 |
| Aw68 Bulk Sr | 3.00 |
| Hyd Filter | 1.00 |
| screw grease roller | 6.00 |
| Shop Supplies | 1.00 |

Hours: 7.50

Comm: 0.00

Labor: 502.50

Parts: 266.81

Total: 769.31

Work Order: 2002768 **Meter:** 1215 **In Date:** 03/18/2020 **Closed:** 03/30/2020
Problem: P.M.SERVICE

Work Completed

- Pm Service.
- Service Hyd.system.inspect all. Replace hyd. filters.correct fluid levels.
- Wash equipment.vacume grass and debris.clean radiator fins.
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|------|
| Fuel Filter | 1.00 |
| Fuel Filter | 1.00 |
| 15w40 Bulk South Reg | 6.00 |
| Napagold Oil Filter | 1.00 |
| Aw68 Bulk Sr | 4.00 |
| Hyd Filter | 1.00 |
| Hyd Filter | 1.00 |
| Shop Supplies | 1.00 |

Hours: 6.75

Comm: 0.00

Labor: 492.75

Parts: 286.95

Total: 779.70

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 2004401 **Meter:** 1246 **In Date:** 05/01/2020 **Closed:** 05/11/2020
Problem: Check engine light on.

Work Completed

- C/c Check engine light on.found Spn 522574,spn 3719.test run to operating temp.initiate Parked Regen.verify codes gone after regen.reset service light.

- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

Shop Supplies

Quantity

1.00

Labor: 146.00

Parts: 4.00

Total: 150.00

Work Order: 2103762 **Meter:** 1337 **In Date:** 04/01/2021 **Closed:** 04/14/2021
Problem: PM

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filters, correct fluid level.
- Test run for 1 hour to clear regen light from dash, initiate stationary regeneration.
- vacuum grass and debris, wash equipment for service and repairs.
- Verify front right pin is bent, replace pin and lubricate all.
- Repair Left rear tire.
- Shop Supplies

Hours: 10.75

Comm: 0.00

Parts Issued

Napagold Air Filter

Napagold Air Filter

Fuel Filter

Napa Fuel Filter

15w40 Bulk South Reg

Napagold Oil Filter

Aw68 Bulk Sr

Hyd Filter

Hyd Filter

Wd40 Spr

Pivot Carrier Shaft

Shop Supplies

Labor: 784.75

Parts: 356.19

Total: 1,140.94

Quantity

1.00

1.00

1.00

1.00

6.00

1.00

3.00

1.00

1.00

1.00

1.00

1.00

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 2105999 **Meter:** 1371 **In Date:** 06/01/2021 **Closed:** 06/08/2021

Problem: Oil is leaking from the right side deck. Bent pin on left side deck.

Work Completed

- Customers complaint front right deck is leaking fluid. Replace o ring and reassemble, tighten all fittings. check Hydraulic fluid level.

- Verify front left pin is bent and seized. Replace pin.

- Wash unit for repairs.

- Shop Supplies

Parts Issued

Quantity

| | |
|---------------------|------|
| Shaft Pivot Carrier | 1.00 |
| Shop Supplies | 1.00 |

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 76.65 Total: 478.15

Work Order: 2204781 **Meter:** 1610 **In Date:** 05/03/2022 **Closed:** 05/19/2022

Problem: PM Service. Check Engine message on display.

Work Completed

- Preventive Maint. Service

- Service hydraulic system, replace two filters, correct fluid level.

- Verify front left and right deck pins are bent. remove and replace pins.

- Verify engine v- belt it cracked up. Replace engine v-belt.

- C/c check engine light on. Verify Spn: 412 Fmi: 3. Replace 2 exhaust gas temp sensors. test run to verify code is cleared and not present.

- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------|------|
| Napagold Air Filter | 1.00 |
| Napagold Air Filter | 1.00 |
| Fuel Filter | 1.00 |
| Napa Fuel Filter | 1.00 |
| 15w40 Bulk South Reg | 6.00 |
| Napagold Oil Filter | 1.00 |
| Aw68 Bulk Sr | 3.00 |
| Hyd Filter | 1.00 |
| Hyd Filter | 1.00 |
| Shaft Pivot Carrier | 2.00 |
| V-belt | 1.00 |
| Sensor Exh Temp | 1.00 |
| Sensor Exh Temp | 1.00 |
| Shop Supplies | 1.00 |
| Freight Charge | 1.00 |
| Freight Charge | 1.00 |
| Freight Charge | 1.00 |

Hours: 11.00 Comm: 0.00 Labor: 803.00 Parts: 842.60 Total: 1,645.60

3/6/2023
4:00:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10198086 2015 TORO GRNDSMSTR 4500D Mower, Rotary, 5 Gang

Work Order: 2301259 **Meter:** 1628 **In Date:** 02/08/2023 **Closed:** 02/08/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 80.00

Total Labor: 5,376.25

Total Comm: 270.00

Total Parts: 3,785.12